

# Site Photographs



**Photo 1** View of damaged building and temporary fencing | Facing south | June 28, 2022



**Photo 2** View of the damaged guard rail and suspected hydrocarbon impacted area on the south east edge of State Route 20. | Facing east | June 28, 2022



**Photo 3** *View of suspected hydrocarbon staining on asphalt on the south side of Penn Cove Road | Facing south | June 28, 2022*



**Photo 4** *View of suspected contaminated soil along the shoulder of State Route 20 | Facing west | June 28, 2022*



**Photo 5** *View of soil screening locations along the shoulder of State Route 20 | Facing west | June 28, 2022*