


INITIAL INVESTIGATION



#2280

SITE NAME: Signal Equipment Inc
ADDRESS: 838 Poplar Pl S, Seattle
INSP. DATE: 1/7/92
INSP. NAME: John Stormon

An initial investigation was conducted at Signal Equipment Inc on 1/7/92 by John Stormon. The tank has been closed in place. Gary Lane , of Signal Equipment Inc, told me that several soil borings have been drilled to characterize the site. Signal is waiting for their insurance to help in the cost of the cleanup. Mr. Lane will send the reports which have been prepared on the site characterization.

Robert Bartlett, of Pacific Testing Lab, told me that a number of soil boring were installed at the site and that the contamination was found to extend beyond the back of the building and to a utility backfill. The contamination then follows the utility backfill. The contamination was only traced to Signal's property boundary. Off site contamination may be present.

STATUS: Obstructed