SHARP

SHARP Report — Part 1 of 2

Go to site contamination history

• SHARP first SHARP		v2024.04.29	Ecology I	nfo
SHARP rating	Low		ERTS	645213
 SHARP date 	08/15/2024		CSID	12378
EJFlagged?	✓ – No Override		FSID	10851
 LD confidence level 	low		VCP	NW2987
 Cleanup milestone 	cleanup completion/NFA		UST ID	620096
• SHARPster	Kim Vik		LUST ID	6823

This section is	s blank	if this is	the first	SHARP
-----------------	---------	------------	-----------	-------

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	medium	multiple chemical types	\Diamond
Groundwater	C3	medium	risk to off-site people	\bigcirc
Surface water	D4	medium	climate change impacts	\Diamond
Sediment	D4	medium	plant/animal tissue data	\bigcirc
Soil	C2	medium		

Location and land use info

401 Central Ave, Bellingham, Whatcom County, 98225

Primary parcel 380330114260
Land use commercial
Responsible unit NWRO

Sources reviewed	
8/3/22 - MW Installation Rpt and NFA Request	
10/19/21 - ECY Opinion Letter	
6/16/20 - MW Installation Rpt and NFA Request	
5/14/19 - ECY Opinion Letter	
10/11/18 - Response to ECY Comments and Work Plan	
12/29/17 - ECY Opinion Letter	
3/31/17 - Independent Remedial Action Report	
(see two additional in Overflow below)	



Primary census tract	Associated census tracts
53073000600	none

53073000600	none
Local demographics co	omments
no comments	
Source/source area de	
	as caused by the release from a 300-gallon gasoline UST, a 1,000-gallon gasoline
UST, and a 1,300-gallon gaso	line UST. The USTs were associated with former fueling operations.

Soil comments

Contaminated soil has been removed from the property, but remains off the property in the street right of way. An NFA was issued for the Property on 1/19/23.

Groundwater comments

GW beneath the property does not have contaminants above the cleanup levels. The off-property extent of GW contamination has not been fully defined (in the street right of way).



SHARF
Surface water comments
no comments
Sediment comments
no comments
Indoor air comments
The vapor intrusion assessment showed that no VOCs were detected in sub-slab soil gas above the Method B
screening levels.
Additional factors comments
no comments



Site history Go to top The property and adjacent properties were utilized from about the 1940s into the 1980s as an operating base for fueling and repairing garbage trucks that provided services to the City of Bellingham. Vehicle repairs were also suscpected to have occurred on the property; however, historical documentation could not confirm this. The building on the property was built around 1912 and was used for retail commercial purposes. The building was remodeled in 2000 from retain to office space (current usage). Note: The Site is located approximately 140 feet west of the east boundary of the Bellingham Maritime Heritage Park (former Holly Street Landfill).



Overflow - Site contamination and cleanup history
Additional Documents:
5/24/16 - ECY Opinion Letter
9/30/13 - UST Site Assessment and PCS Removal Action Report

12378 401 Central Ave USTs 20240815

First SHARP

SHARP rating — Low

SHARP Report — Part 2 of 2

Conceptual site model 08/15/2024



