

SHARP Report — Part 1 of 2

Go to site contamination history

SHARP first SHARP		v2024.04.29	Ecology	/ Info
SHARP rating	Low		ERTS	SHARP it
 SHARP date 	02/19/2025		CSID	5677
EJFlagged?	✓ – No Override		FSID	21186636
 LD confidence level 	high		VCP	CE0239
 Cleanup milestone 	cleanup completion/NFA		UST ID	12476
• SHARPster	Chelsea Wisotzkey		LUST ID	46

This section is blank if this is the first SHARP

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	high	multiple chemical types	0
Groundwater	D4	high	risk to off-site people	\Diamond
Surface water	D4	high	climate change impacts	\Diamond
Sediment	D4	high	plant/animal tissue data	\Diamond
Soil	D4	high		

Location and land use info

1891 N 1st St, Yakima, Yakima County, 98901

Primary parcel 181312-44015

Land use commercial

Responsible unit CRO

Sources reviewed

GeoEngineers, Inc. 2024. "Site Assessment Bekins Northwest Moving & Storage." April 29. 2024."

Washington State Department of Ecology. 2006. "Partial Sufficiency and Further Action Determination Under WAC 173-340-515(5) for the Following Hazardous Waste Site: Bekins Moving & Storage,

1891 North 1st Street Yakima, Washington 98901." May 22, 2006.

Foss Environmental & Infrastructure. 1999. "Draft – Summary of Soil Sampling Activities." January 5, 1999.

Burlington Environmental Chempro Division. 1991. "Burlington Environmental, Site

Characterization/Interim Action Report, Bekins Northwest, Yakima, Washington." June 1991.



Primary census tract	Associated census tracts
0	N/A

Local demographics co	mments
no comments	
0	
Source/source area des	
The source of contamination \	was a leaking 1000 gallon unleaded gasoline tank, which was removed in 1990.

Soil comments

Contaminated soil was remediated using landfarming; Ecology issued a letter of Partial Sufficiency for the soil remediation in 2006.

Groundwater comments

Groundwater was evaluated during a November 2023 Ecology-led Site Assessment; no contaminants greater than MTCA Method A cleanup levels present at the site.



Surface water comments	
Not a surface water site.	
Sediment comments	
No sediment at this site.	
NO Seulifierit at tills site.	
Indoor air comments	
no comments	
A delta de la facta de la companya de	
Additional factors comments	
no comments	



Site history <u>Go to top</u>
Bekins was listed in 1990 following the removal of one 1,000 gallon gasoline tank. Soil and groundwater samples
collected near the UST indicated that benzene, total xylenes, gasoline and lead were present at concentrations
greater than state cleanup levels. Approximately 250 cubic yards of contaminated soil was excavated and land-
farmed on site. In 1998, soil was retested and all contaminants were below cleanup levels, resulting in a letter of
partial sufficiency from Ecology. However, insufficient groundwater data had prevented this site from obtaining
an NFA determination. In November 2023 groundwater was tested for gasoline, diesel, and related constituents.
Contaminants were either not detected or detected below cleanup levels.



Overtiow -	- Site contamination and cleanup history
N/A	

5677 Bekins Moving & Storage Company 20250219

First SHARP

SHARP rating — Low

SHARP Report — Part 2 of 2

Conceptual site model



02/19/2025

