

• SHARP first SHARP		v2024.04.29	Ecology Info	
• SHARP rating	Low		ERTS	C524350
• SHARP date	09/29/2025		CSID	6660
• EJFlagged?	SHARP it		FSID	77751227, 30169, 7
• LD confidence level	low		VCP	NA
• Cleanup milestone	feasibility study		UST ID	5215, 620469, 6204
• SHARPster	John Mefford		LUST ID	5, 8131, 8130

This section is blank if this is the first SHARP

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	high	multiple chemical types	✓
Groundwater	C2	high	risk to off-site people	⊗
Surface water	D4	high	climate change impacts	✓
Sediment	D4	high	plant/animal tissue data	⊗
Soil	C2	high		

Location and land use info

232 E. Woodin Avenue, Chelan, Chelan County, 98816

Primary parcel	multiple parcels (greater than 10)
Land use	commercial
Responsible unit	CRO

Sources reviewed

Comprehensive Supplemental Remedial Investigation, Leidos, August 5, 2025

2024 Annual Groundwater Monitoring Summary Report, Leidos, June 11, 2025

Primary census tract	Associated census tracts
53007960303	53007960302

Local demographics comments

no comments

Source/source area description

Multiple releases occurred throughout the site, forming a commingled groundwater petroleum hydrocarbon plume. Three major source areas are associated with Chevron-related entities including Unocal and Standard Oil. Other sources may exist including heating oil USTs and USTs associated with now-defunct business entities. The soil and groundwater media is impacted but the data shows that vapor intrusion and the groundwater to surface water pathway are incomplete. The contaminants of concern are gasoline-range, diesel-range, and oil-range organics plus their constituents.

Soil comments

no comments

Groundwater comments

no comments

Surface water comments

no comments

Sediment comments

no comments

Indoor air comments

no comments

Additional factors comments

no comments

Site history[Go to top](#)

Gasoline service stations were established as early as 1921 in the site vicinity. By 1929, at least six businesses were providing gasoline and oil or offered vehicle maintenance services along Woodin Avenue between Columbia Street and the east side of Saunders Street. The site is named for the Chelan Chevron Service Station which has existed since 1931 and is major source area prior to remediation. The other two major source areas are the former Unocal Service Station which appears to have existed as early as 1910 and until the 1970s. The third major source area is the former Standard Oil Service Station which appears to have operated from 1922 until the 1950s. Other potential source areas are described in the Comprehensive SRI report.

Overflow - Site contamination and cleanup history

No overflow

Chelan Chevron

6660 Chelan Chevron 20250929

First SHARP

SHARP rating — Low

SHARP Report — Part 2 of 2

Conceptual site model

09/29/2025



Assessment scores by environmental medium

