



### What's happening in your neighborhood?

Ecology's contractor, Wyser Construction, Inc. began cleanup work at the 10 homes located on the east side of Bridgeway in Everett, WA on May 21, 2007. The cleanup will remove and dispose of accessible soil contaminated with arsenic and lead. Soil is accessible if it is not under the house, paved driveways and walkways, or patios. All accessible contaminated soil with arsenic levels above 20 mg/Kg that is within one foot of the surface will be removed and replaced with clean topsoil. Below one foot, all accessible contaminated soil that has arsenic above certain specified levels will be removed and replaced with clean backfill (see page 2 for definition) and topsoil. The yard restoration will include sod lawns, landscape plant replacements, building or reconstructing walls, and restoring fences.

### How long will this cleanup last?

This cleanup is expected to last for 3-5 months. The cleanup work will take place during the **daytime from 7:30 a.m. – 4:30 p.m. on weekdays.**

### Cleanup Activities for Sept. 4- Sept. 14, 2007



#### Cleanup work for September 4 - 14, 2007

- Complete topsoil and sod replacement work at 207, 209 and 215 Bridgeway.
- Continue backyard excavation work at 205 Bridgeway. As final excavation depths are reached, geofabric (see page 2 for definition) will be placed, and restoration will begin immediately. The front yard of this property will be the new stockpile area for the next several cleanup properties.
- Mobilize and prepare for excavation work at 115 and 201 Bridgeway. The backyards will be excavated first, followed by the front yards.

#### Status Update-Cleanup at 209, 215, 223, 225, and 229 Bridgeway

- 205 Bridgeway – Excavation in the backyard and under the deck is in progress.
- 207 Bridgeway –Excavation work in the backyard and side yards has been completed, geofabric has been placed, and restoration work is in progress.
- 209 Bridgeway –Excavation and backfilling work is finished. Restoration work is in progress.
- 215 Bridgeway – Restoration work is nearly complete in the backyard and work continues in the front and side yards.
- 223 Bridgeway – Retaining walls have been restored. Sod has been installed in the back and front yards. Plants and bark are left to be installed.
- 225 Bridgeway – Replacement plants have been planted. A few finishing details remain to be completed.
- 229 Bridgeway – Replacement plants have been planted. A few finishing details remain to be completed.

## What's the truck route?



## Will there be someone to answer my immediate concerns?

Yes, Ecology has contracted Glen Vadera with Science Applications International Corporation (SAIC) to be the on-site coordinator. He will represent Ecology during the daily field activities. Any immediate concerns may be presented to Glen Vadera, who will then communicate them to Jerome Cruz.

**Contact information for the on-site  
Field Coordinator**  
Glen Vadera  
SAIC Coordinator  
(206) 271-4691

## Ecology keeping you informed

This is the eight in a series of newsletters Ecology will produce. Ecology will update this newsletter regularly to inform the neighborhood about the current status of the soil cleanup along the east side of Bridgeway in Everett, Washington. Ecology will contact the next set of homeowners before cleanup work begins on their property.

## Definitions

**Geofabric:** A textile that is placed in the excavation which underlies the clean sandy fill. The geofabric acts as a warning that contaminated soil remains underneath it. The geofabric allows water to drain through it.

**Backfill:** Clean sandy material used to fill in the excavation. For most of these yards, a layer of topsoil is placed above it to allow for the installation of lawns or planting strips.



**The truck route for the dump trucks carrying away contaminated soil will be:**

- South on Skyline Drive.
- Follow Skyline Drive south.
- Then east to Medora Way.
- Head east to Bridgeway.
- Left onto Bridgeway to 229, the loading site.



**After the trucks are loaded:**

- The trucks will proceed north on Bridgeway.
- Turn right onto Skyline Drive.
- Then turn right onto Marine View Drive.

**\* Trucks carrying clean backfill and topsoil will proceed along the same route, but in the opposite direction.**

**For more information about  
Ecology's cleanup, please contact:**

Department of Ecology  
Attn: Jerome Cruz  
Toxics Cleanup Program  
3190 160<sup>th</sup> Ave SE  
Bellevue, WA 98008  
(425) 649-7094  
Email: [jcru461@ecy.wa.gov](mailto:jcru461@ecy.wa.gov)