

January 4, 2011 Project 101.00173.00010

Mr. Tom Middleton Washington Department of Ecology P.O. Box 47775 Olympia, Washington 98504-7775

Re: Quarterly Groundwater Sampling Report – December 2010 Event Former Arco Service Station #0855, Longview, Washington

Dear Mr. Middleton:

On behalf of Wakefield Family LLC (property owner), SLR International Corp (SLR) has prepared this report to present the results of the quarterly groundwater sampling activities conducted in December 2010 at the above-referenced site. The former Arco Service Station #0855 property (the property) is located at 4603 Ocean Beach Highway, near the western end of Longview, Washington (see Figure 1). The purposes of the groundwater sampling program are to assess the effectiveness of the current deep groundwater recovery operations and the 2007 site remedial action (soil excavation and shallow groundwater extraction), and to monitor the migration and attenuation of the petroleum hydrocarbon concentrations in the shallow groundwater-bearing unit and the deep aquifer over time.

#### BACKGROUND

After completing the 2007 remedial action at the property, quarterly groundwater sampling results in 2007 and 2008 showed that the samples from all of the shallow groundwater monitoring wells, except MW-10, and from all of the deep groundwater monitoring wells, except DMW-4, DMW-5, DMW-9, and DMW-10, contained petroleum hydrocarbon concentrations below the Model Toxics Control Act (MTCA) Method A groundwater cleanup levels for four consecutive quarters (SLR, 2008a; SLR, 2008b; and SLR, 2008c). To remediate the remaining impacted groundwater in the deep aquifer, a deep groundwater recovery well (RW-1) was installed and a recovery/treatment system has been operating since June 2009 (SLR, 2009). After activating the system, the current groundwater sampling program has consisted of conducting annual sampling events (collect samples from all of the shallow and deep monitoring wells) in September, and conducting quarterly sampling events (collect samples from shallow well MW-10 and from deep wells DMW-5, DMW-9, and DMW-10) in December, March, and June. groundwater sampling results in September and December 2009 and March and June 2010, the samples from shallow monitoring well MW-10 contained petroleum hydrocarbon concentrations below the Method A cleanup levels for four consecutive quarters (SLR, 2009; SLR, 2010a; SLR, 2010b; and SLR, 2010c). Therefore, MW-10 was eliminated from the future quarterly groundwater sampling events.



#### **DECEMBER 2010 SAMPLING EVENT**

SLR personnel conducted the groundwater sampling activities on December 14, 2010. On December 13<sup>th</sup>, SLR deactivated the deep groundwater recovery/treatment system so that the deep aquifer would be under non-pumping static conditions at the time of sampling.

Immediately prior to sampling, SLR measured the depths to groundwater in all of the shallow groundwater monitoring wells (MW-5, MW-8, MW-9, MW-10, MW-11, MW-12, MW-13, and MW-14), all of the deep groundwater monitoring wells (DMW-3, DMW-4, DMW-5, DMW-6, DMW-7, DMW-8, DMW-9, and DMW-10), and the deep groundwater recovery well (RW-1) by using an electronic water level probe. The depth to groundwater measurements were converted to groundwater elevations by using the results of previous well elevation surveys conducted by Gibbs and Olson, Inc., of Longview, Washington. The depths to groundwater in the shallow wells ranged from 1.37 to 4.66 feet below the tops of the well casings. The groundwater elevations in the shallow wells ranged from 3.75 to 7.55 feet above the NAVD 88 datum. The depths to groundwater in the deep wells ranged from 4.36 to 6.52 feet below the tops of the well casings. The groundwater elevations in the deep wells ranged from 2.30 to 3.38 feet above the NAVD 88 datum. The groundwater elevations in the shallow and deep wells were inconsistent and could not be used to determine general shallow or deep groundwater flow directions beneath the site area. The groundwater monitoring data from the December 2010 sampling event, as well as from the previous groundwater sampling events, are presented in Table 1. groundwater elevations in the shallow and deep wells on December 14, 2010, are shown on Figures 2 and 3, respectively.

SLR personnel collected groundwater samples from deep wells DMW-5, DMW-9, and DMW-10 for laboratory analysis. SLR purged the wells by using a peristaltic pump with dedicated tubing at a flow rate of approximately 0.33 liters per minute. During purging, field parameters of temperature, conductivity, dissolved oxygen (DO), pH, and oxidation-reduction potential were measured every three to five minutes. Each groundwater sample was collected following the stabilization of the field parameter measurements. The purge water was pumped through the groundwater treatment system at the site.

The groundwater samples were submitted to Friedman & Bruya, Inc. (F&B) in Seattle, Washington, for analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX) by EPA Method 8021B, and gasoline-range organics (GRO) by Ecology Method NWTPH-Gx. The analytical results indicated that the samples from wells DMW-5 and DMW-10 contained benzene concentrations [9 and 32 micrograms per liter (µg/L), respectively] that exceeded the MTCA Method A cleanup level (5 µg/L). The groundwater sample from well DMW-9 did not contain analyte concentrations greater than the MTCA Method A cleanup levels. The groundwater sample analytical results from the December 2010 event, as well as from the previous sampling events, are presented in

Table 2. The benzene and GRO concentrations in the December 2010 samples from the deep wells are shown on Figure 3. A copy of the laboratory analytical report is attached.

#### CONCLUSIONS

The 2008 groundwater sampling results from the shallow wells indicated that the 2007 remediation activities effectively removed the source of the shallow groundwater contamination and extracted most of the impacted shallow groundwater (SLR, 2008a; SLR, 2008b; and SLR, 2008c). In October 2008, the remaining petroleum hydrocarbon concentrations in the shallow groundwater that exceeded the MTCA Method A cleanup levels only occurred in one localized area (near well MW-10). Based on the quarterly groundwater sampling results from September 2009 through September 2010 (SLR, 2009; SLR, 2010a; SLR, 2010b; SLR, 2010c; and SLR, 2010d), the hydrocarbon concentrations near MW-10 have decreased to below the Method A cleanup levels due to natural attenuation.

The 2008 groundwater sampling results from the deep wells showed that the 2007 remediation activities had limited short-term affects on the deep groundwater concentrations (SLR, 2008a; SLR, 2008b; and SLR, 2008c). However, the petroleum hydrocarbon concentrations are decreasing with distance away from the primary source area (the former dispenser island area) due to natural attenuation. To actively remediate the impacted deep groundwater, a deep groundwater recovery/treatment system has been operating since June 2009. Based on the groundwater sampling results from December 2009 through September 2010 sampling results (SLR, 2010a; SLR, 2010b; SLR, 2010c; SLR, 2010d), as well as the December 2010 sampling results, the benzene and GRO concentrations in the deep groundwater are decreasing due to the operation of the system. At the source area well (DMW-9), the benzene and GRO concentrations in December 2010 were 3,297 and 8,280  $\mu$ g/L, respectively, less than the concentrations in October 2008 (the last sampling event prior to activating the deep groundwater recovery/treatment system). In December 2010, the benzene and GRO concentrations (3.3 and 320  $\mu$ g/L, respectively) at DMW-9 were below the MTCA Method A cleanup levels.

If you have any questions, please contact me at (425) 471-0479 or mstaton@slrcorp.com.

Sincerely,

**SLR International Corp** 

Michael D. Staton, L.G. Principal Geologist

Mr. Tom Middleton Page 4

Attachments: Limitations

References Tables 1 and 2 Figures 1 through 3

Laboratory Analytical Report

ce: Kurt Peterson, Cascadia Law Group PLLC (4 copies)

## LIMITATIONS

The services reflected in this report were performed consistent with generally accepted professional consulting principals and practices. No other warranty, express or implied, is made. These services were performed consistent with our agreement with our client. This information is solely for the use of our client unless otherwise noted. Any reliance on this information by a third party is at such party's sole risk.

Opinions and recommendations contained herein apply to conditions existing when services were performed and are intended only for the client, purposes, location, timeframes, and project parameters indicated. We are not responsible for the impacts of any changes in environmental standards, practices, or regulations subsequent to performance of services. We do not warrant the accuracy of information supplied by others, nor the use of segregated portions of this report.

## REFERENCES

- SLR. 2008a. Remedial Action Report, Former Arco Service Station #0855, 4603 Ocean Beach Highway, Longview, Washington. July 21.
- SLR. 2008b. Quarterly Groundwater Sampling Report July 2008 Event, Former Arco Service Station #0855, Longview, Washington. August 29.
- SLR. 2008c. Quarterly Groundwater Sampling Report September/October 2008 Event, Former Arco Service Station #0855, Longview, Washington. October 29.
- SLR. 2009. Deep Groundwater Remediation System Installation and Performance Report, Former Arco Service Station #0855, Longview, Washington. November 4.
- SLR. 2010a. Quarterly Groundwater Sampling Report December 2009 Event, Former Arco Service Station #0855, Longview, Washington. January 9.
- SLR. 2010b. Quarterly Groundwater Sampling Report March 2010 Event, Former Arco Service Station #0855, Longview, Washington. April 5.
- SLR. 2010c. Quarterly Groundwater Sampling Report June 2010 Event, Former Arco Service Station #0855, Longview, Washington. July 20.
- SLR. 2010d. Groundwater Sampling Report September 2010 Event, Former Arco Service Station #0855, Longview, Washington. October 25.

Table 1 Groundwater Monitoring Data Former Arco Service Station #0855 Longview Washington

Well Number	Top of Casing Elevation <sup>a</sup> (feet)	Date Measured	Depth to Groundwater <sup>b</sup> (feet)	Free Product Thickness (feet)	Groundwater Elevation (feet)
Shallow Mo	nitoring Wells				
MW-1	8.34	03/27/00	4.36	NP	3.98
		05/23/00	5.20	NP	3.14
		07/20/00	5.55	NP	2.79
		10/18/00	5.41	NP	2.93
		01/18/01	4.81	NP	3.53
		04/18/01	4.58	NP	3.76
		07/17/01	5.54	NP	2.80
		10/18/01	5.26	NP	3.08
		01/16/02	4.45	NP	3.89
		07/09/03	5.80	NP	2.54
	8.25°	05/25/05	4.12	NP	4.13
		12/07/05	3.77	NP	4.48
		08/16/06	6.58	NP	1.67
*			Well abandoned is	n September 2007.	
MW-2	8.76	03/27/00	3.61	NP	5.15
		05/23/00	4.64	NP	4.12
		07/20/00	5.06	NP	3.70
	<u> </u>	10/18/00	5.19	NP	3.57
		01/18/00	3.96	· NP	4.80
		04/18/01	3.83	NP	4.93
		07/17/01	5.08	NP	3.68
		10/18/01	4.83	NP	3.93
		01/16/02	3.71	NP	5.05
		07/09/03	5.36	NP	3.40
	8.89°	05/25/05	4.15	NP	4.74
		12/07/05	4.09	NP	4.80
		08/16/06	5.96	NP	2.93
			Well abandoned i	n September 2007.	
MW-3	8.78	03/27/00	5.61	NP	3.17
		05/23/00	6.46	NP	2.32
		07/20/00	7.05	NP	1.73
		10/18/00	6.84	NP	1.94
		01/18/01	6.37	NP	2.41
		04/18/01	5.46	NP	3.32
		07/17/01	6.93	NP	1.85
		10/18/01	6.47	NP	2.31
		01/16/01	4.83	NP	3.95
		07/09/03	6.72	0.02	2.08*
	8.58°	05/25/05	4.65	Film	3.93
		12/07/05	4.45	0.01	4.14*
		08/16/06	6.91	0.24	1.86*
			<del>'</del>	n September 2007.	

Table 1 Groundwater Monitoring Data Former Arco Service Station #0855 Longview Washington

Well Number	Top of Casing Elevation <sup>a</sup> (feet)	Date Measured	Depth to Groundwater <sup>b</sup> (feet)	Free Product Thickness (feet)	Groundwater Elevation (feet)
Shallow Mo	nitoring Wells (continued)				
MW-4	8.78	11/15/00	6.88	NP	1.90
		01/18/01	6.78	NP	2.00
		04/18/01	6.90	NP	1.88
		07/17/01	7.50	NP	1.28
		10/18/01	6.92	NP	1.86
		01/16/02	6.15	NP	2.63
		07/09/03	7.04	NP	1.74
	8.69°	05/25/05	6.24	NP	2.45
	0.09	12/07/05	5.70	NP	2.99
		08/16/06	6.84	NP	1.85
	-	00/10/00		n September 2007.	1.00
MW-5	8.78	11/15/00	6.54	NP	2.24
1,1,1,1,5	0.70	01/18/01	6.07	NP	2.71
		04/18/01	5.46	NP	3.32
		07/17/01	6.79	NP	1.99
		10/18/01	6.50	NP	2.28
		01/16/02	5.49	NP	3.29
		07/09/03	6.86	NP	1.92
	8.67°	05/25/05	5.64	NP	3.03
	8.67	12/07/05	5.53	NP NP	3.14
					2.39
		08/16/06	6.28 4.64	NP	
		12/11/07	4.04	NP	4.03
		03/11/08		NP	3.77
		07/01/08	5.33	NP	3.34
		09/30/08 09/02/09	6.17 7.08	NP	2.50 1.59
				NP	4.04
		12/15/09	4.63	NP	
		03/18/10	4.85	NP NB	3.82
		06/15/10	4.84	NP ND	3.83
		09/14/10	6.87	NP	1.80
MANUE	8.21	12/14/10 11/15/00	3.03 6.15	NP NP	5.64 2.06
MW-6	0.21	01/18/01	5.85	NP NP	2.36
		04/18/01	5.85	NP NP	2.51
		07/17/01	6.02	NP NP	2.51
		10/18/01	6.02	NP	2.19
		01/16/02	5.80	NP NP	2.18 2.41
		07/09/03	6.16	NP NP	2.41
	8.11°	05/25/05	4.00	NP	4.11
		12/07/05	5.70	NP	2.41
		08/16/06	6.40	NP	1.71
			Well destroyed in	November 2007.	

Table 1 Groundwater Monitoring Data Former Arco Service Station #0855 Longview Washington

Well	Top of Casing Elevation <sup>a</sup>		Depth to Groundwater <sup>b</sup>	Free Product Thickness	Groundwater
Number	(feet)	Date Measured	(feet)	(feet)	Elevation (feet)
Shallow Mo	nitoring Wells (continued)				
MW-7	8.45	11/15/00	6.52	NP	1.93
		01/18/01	6.24	NP	2.21
		04/18/01	5.98	NP	2.47
		07/17/01	6.44	NP	2.01
		10/18/01	6.39	NP	2.06
		01/16/02	6.31	NP	2.14
		07/09/03	7.00	NP	1.45
	8.26°	05/25/05	5.61	NP	2.65
		12/07/05	6.36 <sup>d</sup>	NP	1.90
		08/16/06	6.40	NP	1.86
			Well abandoned i	n September 2007.	
MW-8	6.45	05/25/05	4.50	NP	1.95
		12/07/05	3.69	NP	2.76
		08/16/06	4.67	NP	1.78
		12/11/07	3.55	NP	2.90
		03/11/08	3.51	NP	2.94
		07/01/08	4.03	NP	2.42
		09/30/08	4.19	NP	2.26
	. 1	09/02/09	4.55	NP	1.90
		12/15/09	3.31	NP	3.14
		03/18/10	3.05	NP	3.40
		06/15/10	2.48	NP	3.97
		09/14/10	4.32	NP	2.13
		12/14/10	2.70	NP	3.75
MW-9	9.43	05/25/05	4.66	NP	4.77
		12/07/05	4.59	NP	4.84
		08/16/06	5.23	NP	4.20
		12/11/07	4.52	NP	4.91
		03/11/08	4.65	NP	4.78
		07/01/08	5.06	NP	4.37
		09/30/08	5.08	NP	4.35
		09/02/09	5.20	NP	4.23
		12/15/09	4.51	NP	4.92
		03/18/10	4.64 4.72	NP NP	4.79 4.71
	,	06/15/10		1	4.71 4.49
		09/14/10 12/14/10	4.94 4.66	NP NP	4.49
MW-10	9.52	05/25/05	10.30	NP NP	-0.78
1v1 vv -10	9.32	12/07/05	5.90	NP NP	3.62
		08/16/06	7.18	NP	2.34
	,	12/11/07	4.22	NP	5.30
		03/11/08	6.02	NP NP	3.50
		07/01/08	6.53	NP	2.99
		09/30/08	4.51	NP	5.01
		09/02/09	7.76	NP	1.76
		12/15/09	5.97	NP	3.55
		03/18/10	8.14	NP	1.38
		06/15/10	5.15	NP	4.37
		09/14/10	7.88	NP	1.64
		12/14/10	3.42	NP	6.10

Table 1 Groundwater Monitoring Data Former Arco Service Station #0855 Longview Washington

Well Number	Top of Casing Elevation <sup>a</sup> (feet)	Date Measured	Depth to Groundwater <sup>b</sup> (feet)	Free Product Thickness (feet)	Groundwater Elevation (feet)
Shallow Mor	nitoring Wells (continued)			l l	
MW-11	8.16	12/07/05	3.87	NP	4.29
		08/16/06	6.10	NP	2.06
		12/11/07	3.51	NP	4.65
		03/11/08	4.86	NP	3.30
		07/01/08	5.61	NP	2.55
		09/30/08	6.56	NP	1.60
		09/02/09	7.52	NP	0.64
		12/15/09	4.35	NP	3.81
		03/18/10	4.17	NP	3.99
		06/15/10	4.22	NP NP	3.94
	·	09/14/10	6.28	NP	1.88
		12/14/10	1.86	NP	6.30
MW-12	8.21	12/11/07	2.69	NP	5.52
111,11 12	0.21	03/11/08	4.25	NP	3.96
		07/01/08	5.20	NP	3.01
		09/30/08	5.85	NP	2.36
	· ·	09/02/09	6.33	NP	1.88
		12/15/09	3.09	NP	5.12
		03/18/10	3.46	NP	4.75
		06/15/10	3.65	NP	4.56
		09/14/10	5.65	NP	2.56
l		12/14/10	1.45	NP NP	6.76
MW-13	9.03	12/11/07	1.10	NP NP	7.93
W W - 13	9.03	03/11/08	1.53	NP NP	
		07/01/08	3.53	NP NP	7.50 5.50
		09/30/08	4.73	l l	
				NP	4.30
		09/02/09	7.04	NP	1.99
		12/15/09	2.24	NP	6.79
		03/18/10	1.48	NP	7.55
		06/15/10	1.65	NP	7.38
		09/14/10	5.80	NP	3.23
1 677 1 4	0.20	12/14/10	1.48	NP	7.55
MW-14	8.39	12/11/07	1.50	NP	6.89
		03/11/08	3.85	NP	4.54
		07/01/08	4.27	NP	4.12
		09/30/08	6.44	NP	1.95
		09/02/09	6.93	NP	1.46
		12/15/09	1.77	NP	6.62
		03/18/10	1.65	NP	6.74
		06/15/10	1.78	NP	6.61
		09/14/10	6.23	NP	2.16
D 18 (F * *)		12/14/10	1.37	NP	7.02
Deep Monito	lane.	10/07/05	6.73	NTD I	1.00
DMW-1	8.55	12/07/05	6.73	NP	1.82
	-	08/16/06	6.28	NP 1 2007	2.27
~~~~	0.72	10 (0 = 10 =		n September 2007.	
DMW-2	8.29	12/07/05	6.10	NP	2.19
		08/16/06	6.71	′ NP	1.58

Table 1 Groundwater Monitoring Data Former Arco Service Station #0855 Longview Washington

Well Number	Top of Casing Elevation <sup>a</sup> (feet)	Date Measured	Depth to Groundwater <sup>b</sup> (feet)	Free Product Thickness (feet)	Groundwater Elevation (feet)
Deep Monit	oring Wells (continued)				
DMW-3	6.66	12/07/05	12.15 <sup>d</sup>	NP	-5.49
		08/16/06	4.55	NP	2.11
		12/11/07	4.60	NP	2.06
		03/11/08	5.68	NP	0.98
		07/01/08	5.52	NP	1.14
		09/30/08	5.03	NP	1.63
		09/02/09	5.19	NP	1.47
		12/15/09	4.71	NP	1.95
		03/18/10	4.55	NP	2.11
		06/15/10	4.42	NP	2.24
		09/14/10	5.01	NP	1.65
		12/14/10	4.36	NP	2.30
DMW-4	8.55	12/07/05	6.30	NP	2.25
ì		08/16/06	7.12	NP	1.43
		12/11/07	6.08	NP	2.47
		03/11/08	6.54	NP	2.01
		07/01/08	6.41	NP	2.14
		09/30/08	6.91	NP	1.64
		09/02/09	7.13	NP	1.42
		12/15/09	6.26	NP	2.29
		03/18/10	6.43	NP	2.12
	l	06/15/10	6.11	NP	2.44
		09/14/10	6.97	NP	1.58
		12/14/10	5.18	NP	3.37
DMW-5	8.14	12/07/05	5.88	NP	2.26
		08/16/06	6.57	NP	1.57
		12/11/07	5.75	NP	2.39
		03/11/08	6.14	NP	2.00
		07/01/08	5.01	NP	3.13
		09/30/08	6.52	NP	1.62
		09/02/09	6.75	NP	1.39
		12/15/09	5.87	NP	2.27
		03/18/10	6.03	NP	2.11
		06/15/10	5.68	NP	2.46
		09/14/10	6.55	NP	1.59
		12/14/10	4.80	NP	3.34
DMW-6	9.15	08/16/06	7.74	NP	1.41
		12/11/07	6.68	NP	2.47
		03/11/08	7.15	NP	2.00
		07/01/08	7.04	NP	2.11
		09/30/08	7.53	NP	1.62
		09/02/09	7.79	NP	1.36
		12/15/09	6.89	NP	2.26
		03/18/10	7.06	NP	2.09
		06/15/10	6.74	NP	2.41
		09/14/10	7.59	NP	1.56
		12/14/10	5.79	NP	3.36

Table 1 Groundwater Monitoring Data Former Arco Service Station #0855 Longview Washington

Well Number	Top of Casing Elevation <sup>a</sup> (feet)	Date Measured	Depth to Groundwater <sup>b</sup> (feet)	Free Product Thickness (feet)	Groundwater Elevation (feet)
Deep Monito	oring Wells (continued)				
DMW-7	8.12	08/16/06	6.68	NP	1.44
		12/11/07	5.68	NP	2.44
		03/11/08	6.11	NP	2.01
		07/01/08	6.02	NP	2.10
		09/30/08	6.61	NP	1.51
		09/02/09	6.74	NP	1.38
		12/15/09	5.85	NP	2.27
		03/18/10	5.93	NP	2.19
		06/15/10	5.82	NP	2.30
		09/14/10	6.55	NP	1.57
		12/14/10	5.27	NP	2.85
DMW-8	9.09	08/16/06	7.65	NP	1.44
		12/11/07	6.60	NP	2.49
		03/11/08	7.06	NP	2.03
		07/01/08	6.97	NP	2.12
		09/30/08	7.48	NP	1.61
		09/02/09	7.69	NP	1.40
	-	12/15/09	6.80	NP	2.29
		03/18/10	6.81	NP	2.28
		06/15/10	6.55	NP	2.54
		09/14/10	7.50	, NP	1.59
		12/14/10	6.52	NP	2.57
DMW-9	8.86	12/11/07	5.39	NP	3.47
		03/11/08	6.84	NP	2.02
		07/01/08	6.85	NP	2.01
		09/30/08	7.20	NP	1.66
		09/02/09	7.44	NP	1.42
		12/15/09	6.54	NP	2.32
		03/18/10	6.69	NP	2.17
		06/15/10	6.39	NP	2.47
		09/14/10	7.23	NP	1.63
		12/14/10	5.66	NP	3.20
DMW-10	8.38	12/11/07	4.91	NP	3.47
		03/11/08	6.35	NP	2.03
		07/01/08	6.24	NP	2.14
		09/30/08	6.75	NP	1.63
		09/02/09	6.99	NP	1.39
		12/15/09	6.09	NP	2.29
		03/18/10	6.25	NP	2.13
		06/15/10	5.91	NP	2.47
		09/14/10	6.77	NP	1.61
		12/14/10	5.02	NP	3.36
Deep Recove	ry Well				
RW-1	8.08	09/02/09	6.69	NP	1.39
		12/15/09	5.78	NP	2.30
		03/18/10	5.96	NP	2.12
		06/15/10	5.60	NP	2.48
		12/14/10	4.70	NP	3.38

#### NOTES:

NP = Free prroduct was not present.

<sup>&</sup>lt;sup>a</sup> Top of well casing elevations were surveyed relative to NAVD 88 datum.

b Measurements in feet below top of well casing.

<sup>&</sup>lt;sup>c</sup> Top of casing (TOC) elevation was re-surveyed in May 2005.

d Water in well was under pressure and rising when the cap was removed. The water level was recorded after the well cap was off for over 2 hours.

<sup>\*</sup> Groundwater elevation corrected for product thickness by using the equation: Groundwater elevation = TOC elevation - depth to groundwater + (product thickness x 0.80).

Table 2
Groundwater Sample Analytical Results - Petroleum Hydrocarbons
Former Arco Service Station #0855
Longview, Washington

						h	
******		Benzene <sup>a</sup>	Toluenea	Ethylbenzene <sup>a</sup>	Total Xylenes <sup>a</sup>	GRO <sup>b</sup>	DROc
Well Number	Sample Date	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)
MTCA Method A Cleanu		5	1,000	700	1,000	800	500
Shallow Monitoring Well					<u> </u>		
MW-1	03/27/00	ND	ND	ND	ND	ND	ND
	05/23/00	ND	ND	ND	ND	ND	NA
	07/20/00	ND	ND	ND	ND	ND	NA
	10/18/00	ND	ND	1.61	ND	404	NA
	01/18/01	ND	ND	ND	ND	95.6	NA
	04/18/01	ND	ND	ND	ND	NA	NA
	07/17/01	ND	2.63	1.46	ND	386	NA
	10/18/01	ND	ND	ND	ND	ND	NA
	01/16/02	ND	ND	ND	ND	104	NA
	.07/09/03	< 0.50	< 0.50	< 0.50	<1.0	<50	<250
	05/25/05	<1.0	<1.0	<1.0	<2.0	<100	< 50
	11/30/05	<1.0	<1.0	<1.0	<3.0	<100	< 50
				Vell abandoned in	September 2007		
MW-2	03/27/00	6.89	49.5	599	2,490	17,100	ND
	05/23/00	26.2	16.2	614	1,770	13,200	NA
	07/20/00	11.9	11.8	304	330	7,220	NA
	10/18/00	3.67	1.23	13.9	7.55	743	NA
	01/18/00	ND	ND	41.1	5.62	691	NA
	04/18/01	ND	ND	8.73	ND	NA	NA
	07/17/01	ND	1.26	14	ND	430	NA
	10/18/01	2.11	ND	3.64	ND	304	NA
	01/16/02	1.16	0.81	37.1	6.71	370	NA
	07/09/03	0.86	< 0.50	6.43	1.28	131	<250
	05/30/05	<1.0	<1.0	<1.0	<2.0	<100	52
	12/01/05	<1.0	<1.0	<1.0	<3.0	120	< 50
			V	Vell abandoned in	September 2007	<u>'</u>	
MW-3	03/07/00	7,520	12,900	2,780	14,500	93,700	ND
	05/23/00	4,710	8,330	2,280	11,200	65,200	NA
	07/20/00	10,700	22,600	3,160	17,400	145,000	NA
	10/18/00	12,900	33,000	4,890	26,700	179,000	NA
	01/18/01	9,380	17,200	3,940	20,230	121,000	NA
	04/18/01	7,700	15,300	3,430	16,990	NA	NA
	07/17/01	10,100	21,400	4,120	20,900	940,000	NA
	10/18/01	7,200	19,700	3,340	17,300	139,000	NA
	01/16/02	13,600	26,600	3,920	20,800	177,000	NA
	07/09/03	11,800	20,100	4,560	21,200	124,000	3,750
	05/25/05			ampled due to pre			
	11/28/05			ampled due to pre			
			V	Vell abandoned in	September 2007	1.	

Table 2
Groundwater Sample Analytical Results - Petroleum Hydrocarbons
Former Arco Service Station #0855
Longview, Washington

		Benzene <sup>a</sup>	Toluene <sup>a</sup>	Ethylbenzene <sup>a</sup>	Total Xylenes <sup>a</sup>	GRO <sup>b</sup>	DRO°
Well Number	Sample Date	(µg/L)	(µg/L)	(μg/L)	(μg/L)	(µg/L)	(µg/L)
MTCA Method A Cleanu	p Levels <sup>d</sup>	5	1,000	700	1,000	800	500
Shallow Monitoring Well	s (continued)		,		,		
MW-4	11/15/00	1,310	53.6	2,430	7,250	45,500	NA
	01/18/01	1,130	ND	2,030	2,764	29,400	NA
	04/18/01	1,280	ND	1,700	2,591	ŇA	NA
	07/17/01	1,610	35	2,870	1,870	34,900	. NA
	10/18/01	1,040	ND	2,300	1,320	33,000	NA
	01/16/02	733	ND	920	948	19,300	NA
	07/09/03	906	39.1	1,350	156	14,100	798
	05/24/05	310	2.90	410	185 <sup>e</sup>	9,600	2,300
	12/01/05	990	140	1,100	1,353 <sup>e</sup>	11,000	2,900 <sup>f</sup>
		AND THE PROPERTY OF THE PROPER		Vell abandoned in			
MW-5	11/15/00	ND	ND	ND	ND	ND	NA
	01/18/01	ND	ND	ND	ND	786	NA
	04/18/01	9.42	ND	6.76	10.1	NA	NA
	07/17/01	1.83	1.16	1.90	3.28	694	NA
	10/18/01	3.05	1.39	1.48	1.45	647	NA
	01/16/02	52.3	3.82	48	24.9	2,800	NA
	07/09/03	1.26	0.99	1.54	4.64	615	<250
	05/24/05	<1.0	<1.0	<1.0	<2.0	460	120
	11/28/05	<1.0	<1.0	<1.0	<3.0	420	230 <sup>f</sup>
	12/11/07	<1.0	<1.0	<1.0	<3.0	140	< 50
	03/11/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	07/02/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	10/02/08	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/14/10	<1.0	. <1.0	<1.0	<3.0	<100	NA
MW-6	11/15/00	ND	ND	ND	ND	131	NA
	01/18/01	ND	ND	ND	ND	732	NA
	04/18/01	ND	ND	ND	ND	NA	NA
	07/17/01	ND	1.35	1.33	5.79	892	NA
	10/18/01	ND	ND	2.60	5.48	1,000	NA
	01/16/02	ND	0.72	1.58	2.78	810	NA
	07/09/03	< 0.50	0.53	1.15	4.84	462	958
	05/25/05	<1.0	<1.0	<1.0	<2.0	370	270
	11/28/05	<1.0	<1.0	<1.0	<1.0	NA	<1.0
				Well destroyed in			
MW-7	11/15/00	ND	ND	ND	1.35	113	NA
	01/18/01	ND	ND	ND	ND	242	NA
	04/18/01	ND	ND	ND	ND	NA	NA
	07/17/01	ND	ND	ND	ND	275	NA
	10/18/01	ND	ND	ND	ND	286	NA
	01/16/02	ND	ND	ND	ND	362	NA
	07/09/03	< 0.50	< 0.50	<0.50	1.48	232	2,050
	05/25/05	<1.0	<1.0	<1.0	<2.0	<100	220
	11/30/05	<1.0	<1.0	<1.0	<3.0	<100	140
			<u> </u>	Vell abandoned in	September 2007	•	

Table 2
Groundwater Sample Analytical Results - Petroleum Hydrocarbons
Former Arco Service Station #0855
Longview, Washington

		D a	To a	T-(1 11 a	m , i xz i a	GRO <sup>b</sup>	DROc
Well Number	Sample Date	Benzene <sup>a</sup> (μg/L)	Toluene <sup>a</sup> (µg/L)	Ethylbenzene <sup>a</sup> (µg/L)	Total Xylenes <sup>a</sup> (μg/L)	GRO (μg/L)	DRO (μg/L)
MTCA Method A Cleanu		<u>(μg/L)</u> 5	1,000	700	1,000	800	500
Shallow Monitoring Well		5	1,000	700	1,000	000	300
MW-8	05/25/05	<1.0	<1.0	<1.0	<3.0	<100	<70
W1 W -0	11/29/05	<1.0	<1.0	<1.0	<3.0	<100	<50
	12/11/07	<1.0	<1.0	<1.0	<3.0	<100	<50
	03/11/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	07/01/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	10/01/08	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA
MW-9	05/25/05	<1.0	<1.0	<1.0	<3.0	<100	<50
	11/28/05	<1.0	<1.0	<1.0	<3.0	<100	<50
	12/11/07	<1.0	<1.0	<1.0	<3.0	<100	<50
	03/11/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	07/02/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	10/02/08	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA
MW-10	05/25/05	45	<1.0	110	<2.0	1,000	1,200
	11/30/05	31	<1.0	110	<3.0	1,400	1,000 <sup>f</sup>
	12/11/07	9.0	3.0	65	<3.0	3,100	1,000 <sup>g</sup>
	03/11/08	16	2.0	40	<3.0	3,000	1,200 <sup>g</sup>
	07/03/08	18	2.0	53	41	2,500	1,100 <sup>g</sup>
	10/02/08	<1.0	<1.0	<1.0	<3.0	1,300	NA
	09/03/09	<1.0	<1.0	2.0	<3.0	200	NA
	12/15/09	3.0	<1.0	11	<3.0	310	NA
	03/18/10	<1.0	<1.0	<1.0	<3.0	<100	NA
	06/15/10	<1.0	<1.0	<1.0	<3.0	170	NA
	09/14/10	<1.0	<1.0	<1.0	<3.0	180	NA
MW-11	12/05/05	<1.0	<1.0	<1.0	<3.0	<100	< 50
	12/11/07	<1.0	<1.0	<1.0	<3.0	<100	< 50
	03/11/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	07/02/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	10/02/08	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA

Table 2
Groundwater Sample Analytical Results - Petroleum Hydrocarbons
Former Arco Service Station #0855
Longview, Washington

MTCA Method A Cleanup Let Shallow Monitoring Wells (con MW-12 12 07 10 10	nple Date vels <sup>d</sup> ntinued) 2/11/07 3/11/08 7/02/08 0/02/08 9/03/09	Benzene <sup>a</sup> (μg/L) 5 <1.0 <1.0 <1.0 <1.0	Toluene <sup>a</sup> (μg/L) 1,000  <1.0 <1.0	Ethylbenzene <sup>a</sup> (μg/L) 700 <1.0	Total Xylenes <sup>a</sup> (μg/L) 1,000	GRO <sup>b</sup> (μg/L) 800	DRO <sup>c</sup> (μg/L) 500
MTCA Method A Cleanup Let Shallow Monitoring Wells (con MW-12 12 07 10 10	vels <sup>d</sup> ntinued) 2/11/07 3/11/08 7/02/08 0/02/08	(μg/L) 5 <1.0 <1.0	(μg/L) 1,000 <1.0	(μg/L) 700	(μg/L)	(μg/L)	(μg/L)
MTCA Method A Cleanup Let Shallow Monitoring Wells (con MW-12 12 00 07 10	vels <sup>d</sup> ntinued) 2/11/07 3/11/08 7/02/08 0/02/08	<1.0 <1.0	<b>1,000</b> <1.0	700			
MW-12	ntinued) 2/11/07 3/11/08 7/02/08 0/02/08	<1.0 <1.0	<1.0				
MW-12 12 03 07 10 09 09 10 09 10 09 10 09 10 10 10 10 10 10 10 10 10 10 10 10 10	2/11/07 3/11/08 7/02/08 0/02/08	<1.0		<1.0			
03 07 10	3/11/08 7/02/08 0/02/08	<1.0		\1.U	<3.0	<100	<50
0° 10 09	7/02/08 0/02/08			<1.0	<3.0	<100	<50
09			<1.0	<1.0	<3.0	<100	< 50
II I	9/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
09	2/03/02	<1.0	<1.0	<1.0	<3.0	<100	NA
	9/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA
MW-13 12	2/11/07	<1.0	<1.0	<1.0	<3.0	<100	< 50
00	3/11/08	<1.0	<1.0	<1.0	<3.0	<100	< 50
0′	7/03/08	<1.0	<1.0	<1.0	<3.0	<100	<50
10	0/02/08	<1.0	<1.0	<1.0	<3.0	<100	NA
09	9/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
09	9/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA
MW-14 12	2/11/07	<1.0	<1.0	<1.0	<3.0	<100	< 50
03	3/11/08	<1.0	<1.0	<1.0	<3.0	<100	50
0′	7/02/08	<1.0	<1.0	<1.0	<3.0	<100	< 50
10	0/01/08	<1.0	<1.0	<1.0	<3.0	<100	NA
09	9/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
09	9/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA
Deep Monitoring Wells		no. Infolia valuations		e one attributed to half of the control of the standard of	a so andreas - NOT A broad stall	de J. Tudin i bilita at	25-2 ( 3 - 3+2 - <b>F</b> 3546
II 1 ·	2/07/05	4,000	160	1,100	4,090 <sup>e</sup>	22,000	2,900 <sup>f</sup>
08	8/17/06	4,100	<1.0	520	841 <sup>e</sup>	16,000	930 <sup>f</sup>
	- 10 - 10 - 1	(5.88 % 200 No. 180 N		Vell abandoned in			- 70
II I	2/07/05	11	<1.0	40	46 <sup>f</sup>	270	<50
	8/16/06	10	<1.0	5.6	<3.0	<100	<50
D) 61/2	2/07/05	-1.0		Vell abandoned in			-50
	2/07/05	<1.0	<1.0	<1.0	<3.0	<50 <100	<50 <50
II I	8/17/06	<1.0	<1.0 <1.0	<1.0 <1.0	<3.0 <3.0	<100	<50 <50
II I	2/11/07 3/11/08	<1.0	<1.0	<1.0	<3.0	<100	<50
II I	7/02/08	<1.0 <1.0	<1.0	<1.0	<3.0	<100	<50
II I	0/01/08	<1.0	<1.0	<1.0	<3.0	<100	NA
II I	9/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA NA
II I	9/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA NA
	2/05/05	56	<1.0	<1.0	<3.0	230	<50
II I	8/17/06	5.7	<1.0	<1.0	<3.0	210	<50
11	2/11/07	27	3.0	2.0	4.0	260	<50
	3/11/08	6.0	<1.0	<1.0	<3.0	230	68 <sup>g</sup>
	7/02/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	0/02/08	<1.0	<1.0	<1.0	<3.0	<100	NA
II I	9/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
11	9/03/09	<1.0	1.0	<1.0	3.3	<100	NA NA

Table 2
Groundwater Sample Analytical Results - Petroleum Hydrocarbons
Former Arco Service Station #0855
Longview, Washington

Well Number	Sample Date	Benzene <sup>a</sup> (μg/L)	Toluene <sup>a</sup> (μg/L)	Ethylbenzene <sup>a</sup> (µg/L)	Total Xylenes <sup>a</sup> (µg/L)	GRO <sup>b</sup> (μg/L)	DRO <sup>c</sup> (μg/L)
MTCA Method A Cleanu	p Levels <sup>d</sup>	5	1,000	700	1,000	800	500
Deep Monitoring Wells (c							
DMW-5	12/05/05	36	<1.0	<1.0	<3.0	130	< 50
	08/17/06	74	<1.0	<1.0	<3.0	170	< 50
	12/11/07	41	<1.0	<1.0	<3.0	100	< 50
	03/11/08	10	<1.0	<1.0	<3.0	<100	<50
	07/02/08	1.0	<1.0	<1.0	<3.0	<100	<50
	10/01/08	42	<1.0	<1.0	<3.0	110	NA
	09/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
	12/15/09	1.0	<1.0	<1.0	<3.0	<100	NA
	03/18/10	13	<1.0	<1.0	<3.0	<100	NA
	06/15/10	13	<1.0	<1.0	<3.0	<100	NA
	09/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA
	12/14/10	9.0	<1.0	<1.0	<3.0	<100	NA
DMW-6	08/16/06	<1.0	<1.0	<1.0	<3.0	<100	< 50
	12/11/07	<1.0	<1.0	<1.0	<3.0	<100	< 50
	03/11/08	<1.0	<1.0	<1.0	<3.0	<100	< 50
	07/02/08	<1.0	<1.0	<1.0	<3.0	<100	< 50
	10/02/08	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA
DMW-7	08/16/06	<1.0	<1.0	<1.0	<3.0	<100	<50
	12/11/07	<1.0	<1.0	<1.0	<3.0	<100	<50
	03/11/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	07/01/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	10/01/08	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
70 h 60 V V	09/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA
DMW-8	08/16/06	<1.0	<1.0	<1.0	<3.0	<100	<50
	12/11/07	<1.0	<1.0	<1.0	<3.0	<100	<50
	03/11/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	07/02/08	<1.0	<1.0	<1.0	<3.0	<100	<50
	10/02/08	<1.0	<1.0	<1.0	<3.0	<100	NA
	09/03/09	<1.0	<1.0	<1.0	<3.0	<100	NA
DMW 0	09/14/10	<1.0	<1.0	<1.0	<3.0	<100	NA
DMW-9	12/11/07	6,100	1,900	970	3,100	27,000	600 <sup>g</sup>
	03/11/08	3,000	150	380	880	13,000	450 <sup>g</sup>
	07/03/08	3,600	3.0	320	610	9,500	520 <sup>g</sup>
	10/02/08	3,300	4.0	140	270	8,600	NA
	09/03/09	2,800	4.0	320	1,100	14,000	NA NA
	12/15/09	980 100	2.0	<1.0	1,100	5,300	NA NA
	03/18/10	190 50	<1.0	10	200	1,600	NA NA
	06/15/10	50 210	<1.0	9.1	60	630	NA NA
	09/14/10 12/14/10	210	<1.0	5.2	120	1,000	NA NA
	12/14/10	3.3	<1.0	1.3	9.8	320	NA

# Table 2 Groundwater Sample Analytical Results - Petroleum Hydrocarbons Former Arco Service Station #0855 Longview, Washington

Well Number	Sample Date	Benzene <sup>a</sup>	Toluene <sup>a</sup> .	Ethylbenzene <sup>a</sup>	1 · 1	GRO <sup>b</sup>	DRO <sup>c</sup>
	<del>' ' '</del> ' ' '		(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)
MTCA Method A Cleani		5	1,000	700	1,000	800	500
Deep Monitoring Wells (	continued)						
DMW-10	12/11/07	60	4.0	88	130	750	53 <sup>g</sup>
	03/11/08	<b>75</b>	4.0	140	120	1,000	74 <sup>g</sup>
	07/02/08	89	6.0	160	130	1,100	68 <sup>g</sup>
	10/01/08	90	5.0	120	25	820	NA
	09/03/09	9.0	<1.0	2.0	<3.0	<100	NA
	12/15/09	20	<1.0	13	7.0	150	NA
	03/18/10	41	<1.0	21	13	310	NA
	06/15/10	34	2.3	14	12	340	NA
	09/14/10	12	<1.0	<1.0	<3.0	<100	NA
	12/14/10	32	1.7	7.1	11	120	NA

NOTES: Values in bold exceed the MTCA Method A cleanup levels.

All concentrations in micrograms per liter ( $\mu$ g/L).

ND = Not detected above the laboratory method reporting limit (MRL).

NA = Not analyzed.

<sup>&</sup>lt;sup>a</sup> Benzene, toluene, ethylbenzene, and total xylenes (BTEX) by EPA Method 8021B or EPA Method 8260B.

b Gasoline-range organics (GRO) by Ecology Method NWTPH-Gx.

<sup>&</sup>lt;sup>c</sup> Diesel-range organics (DRO) by Ecology Method NWTPH-Dx.

<sup>&</sup>lt;sup>d</sup> Chapter 173-340 WAC, Model Toxics Control Act (MTCA) Cleanup Regulation, Method A Cleanup Levels. Amended February 12, 2001.

Total xylenes calculated by using the formula: total xylenes concentration = (m, p-xylene concentration) + (o-xylene concentration).

The laboratory reported that the DRO concentration is due to overlap from the gasoline range.

The laboratory reported that the pattern of chromatogram peaks from the sample were not indicative of diesel.



Saved: Tuesday, July 20, 2010 3:58:43 PM by egoodwin Drawing path: R:\Figures\Bothel\001.0173.00001\7\07-01.dwg


22118 20th AVE SE BUILDING G, SUITE 202 BOTHELL, WA 98021


> T: 425-402-8800 F: 425-402-8488


DATE 01/10
DWN. BDT
APPR. REVIS.


PROJECT NO. 101.00173.00010 FIGURE 1 FORMER ARCO SERVICE STATION #0855 LONGVIEW, WASHINGTON

PROPERTY LOCATION MAP









DMW-7 DEEP GROUNDWATER MONITORING WELL LOCATION AND

RW-1 DEEP GROUNDWATER RECOVERY WELL LOCATION AND

DMW-1 @ ABANDONED DEEP GROUNDWATER MONITORING WELL


(3.37) DEEP GROUNDWATER ELEVATION (IN FEET)

32 B B = BENZENE CONCENTRATION IN GROUNDWATER SAMPLE (in  $\mu$ g/L) 120 G G = GRO CONCENTRATION IN GROUNDWATER SAMPLE (in  $\mu$ g/L)

VALUES IN BOLD EXCEED MTCA METHOD A CLEANUP LEVELS

NOTE:

THE DEPTHS TO GROUNDWATER WERE MEASURED AFTER THE DEEP GROUNDWATER RECOVERY/TREATMENT SYSTEM HAD BEEN DEACTIVATED FOR OVER 12 HOURS.





DATE DWN. BDT APPR. MIS REVIS. PROJECT NO. 101.00173.00010

FIGURE 3 FORMER ARCO SERVICE STATION #0855 LONGVIEW, WASHINGTON

DEEP GROUNDWATER SAMPLING RESULTS **DECEMBER 14, 2010** 

#### ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

December 20, 2010

Mike Staton, Project Manager SLR International Corp. 22118 20th Ave. SE., G-202 Bothell, WA 98021

Dear Mr. Staton:

Included are the results from the testing of material submitted on December 15, 2010 from the Longview 101-00173-00010, F&BI 012178 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Kurt Johnson Project Manager

Enclosures SLR1220R.DOC

## **ENVIRONMENTAL CHEMISTS**

# **CASE NARRATIVE**

This case narrative encompasses samples received on December 15, 2010 by Friedman & Bruya, Inc. from the SLR International Corp. Longview 101-00173-00010, F&BI 012178 project. Samples were logged in under the laboratory ID's listed below.

<u>Laboratory ID</u>	SLR International Corp.
012178-01	DMW9-121410
012178-02	DMW5-121410
012178-03	DMW10-121410

All quality control requirements were acceptable.

## **ENVIRONMENTAL CHEMISTS**

Date of Report: 12/20/10 Date Received: 12/15/10

Project: Longview 101-00173-00010, F&BI 012178

Date Extracted: 12/16/10 Date Analyzed: 12/17/10

# RESULTS FROM THE ANALYSIS OF WATER SAMPLES FOR BENZENE, TOLUENE, ETHYLBENZENE, XYLENES AND TPH AS GASOLINE USING EPA METHOD 8021B AND NWTPH-Gx

Results Reported as ug/L (ppb)

Sample ID Laboratory ID	<u>Benzene</u>	<u>Toluene</u>	Ethyl <u>Benzene</u>	Total <u>Xylenes</u>	Gasoline <u>Range</u>	Surrogate (% Recovery) (Limit 50-150)
DMW9-121410 012178-01	3.3	<1	1.3	9.8	320	106
DMW5-121410 012178-02	9.0	<1	<1	<3	<100	102
DMW10-121410 012178-03	32	1.7	7.1	11	120	103
Method Blank	<1	<1	<1	<3	<100	103

## ENVIRONMENTAL CHEMISTS

Date of Report: 12/20/10 Date Received: 12/15/10

Project: Longview 101-00173-00010, F&BI 012178

# QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR BENZENE, TOLUENE, ETHYLBENZENE, XYLENES, AND TPH AS GASOLINE USING EPA METHOD 8021B AND NWTPH-Gx

Laboratory Code: 012182-07 (Duplicate)

				Relative Percent
	Reporting	Sample	Duplicate	Difference
Analyte	Ûnits	Result	Result	(Limit 20)
Benzene	ug/L (ppb)	<1	<1	nm
Toluene	ug/L (ppb)	<1	<1	nm
Ethylbenzene	ug/L (ppb)	<1	<1	nm
Xylenes	ug/L (ppb)	<3	<3	nm
Gasoline	ug/L (ppb)	<100	<100	nm

Laboratory Code: Laboratory Control Sample

			Percent	
	Reporting	Spike	Recover	Acceptance
Analyte	Units	Level	y LCS	Criteria
Benzene	ug/L (ppb)	50	95	72-119
Toluene	ug/L (ppb)	50	89	71-113
Ethylbenzene	ug/L (ppb)	50	87	72-114
Xylenes	ug/L (ppb)	150	88	72-113
Gasoline	ug/L (ppb)	1,000	89	70-119

#### **ENVIRONMENTAL CHEMISTS**

## **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- $\operatorname{ca}$  The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ${
  m d}s$  The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- $\,$  nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- $\operatorname{pc}$  The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- $\operatorname{pr}$  The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

8	
27	HANGE THE PARTY OF
0	

SAMPLE CHAIN OF CUSTODY

ME 12-15-10

SAMPLERS (signature)

(01,00173,00010 PROJECT NAME/NO Congriew

Rush charges authorized by: X Standard (2 Weeks)

TURNAROUND TIM

# Od

SAMPLE DISPOSAL

Dispose after 30 days

Return samples

Will call with instructions

TOT BY NUTBY-GX

REMARKS

Mstaten @ Succorpicom

Company SLR - Mile staten

Send Report To

Phone # 425- 202-8800 Fax #

City, State, ZIP.

Address\_

	Notes			i					
			_						
LED								 _	
UES									
REQ.									
ANALYSES REQUESTED									
ALY	SAH SARA								1
A.	VOCs by 8270 SVOCs by 8270								
	BLEX by 8021B				,				
	TPH-Gasoline	$\langle \rangle$	$\langle \rangle$	$\langle \rangle$					
	TPH-Diesel	$\triangle$	$\Delta$			-	•		
	# of containers	8	-	<b>\rightarrow</b>					
	Sample Type	$\sim$	4	$\rightarrow$					
	Time Sampled	5/0/	1035	250/					
	Date Sampled	ozhifei	-	<b>&gt;</b>					
	Lab	J-410	02 A-C	03 R.C					
	Sample ID	DMW9-121410 014-41460 1015	DMINGS-121410 02H-4	Dmw10-121410					

Seattle, WA 98119-2029 Friedman & Bruya, Inc. 3012 16th Avenue West

Fax (206) 283-5044

Z Ş 12-10-01 Samples received at PRINT NAME SIGNATURE Relinquished by Relinquished by: Received by: Received by: FORMS\COC\COC.DOC Ph. (206) 285-8282

TIME

DATE

COMPANY