

LUST File Review  
February 8, 2002  
K. Rodriguez

Site Name: Benton County Road Department /Area 1 / Prosser  
Site ID: 3683  
Address: 9<sup>th</sup> Street & Sheridan Avenue, Prosser, WA  
County: Benton

References: UST Closure Report, White Shield Environmental, May 1999

Summary: In 1999, three USTs were removed from a single excavation at this site. No groundwater was encountered in the excavation. Approximately eight cubic yards of excavated soil was transported to the Lower Valley Remediation facility in Mabton, WA.

Soil samples were taken from the excavation and at the base of the fuel dispensers and analyzed for TPH-G, TPH-Dx (diesel and heavy oil), and BTEX, where appropriate. Discrete samples were taken beneath each tank and side samples were composited. Laboratory results indicate all samples were non-detect because they were below the Practical Quantitation Limits.

Action: I contacted Rick Funderburk at White Shield Environmental to clear up an error in the report. The chart in 15.0 Laboratory Results indicates that sample PPC-0391-211 was from under the gasoline UST and PPC-0391-212 was from under the diesel UST. The location/depth for these two samples needs to be reversed. Therefore, diesel was tested for beneath the diesel UST and gasoline beneath the gasoline UST.

Conclusion: The status for this site was previously Unknown however, there is no indication of contamination at this site. The status should be Reported Cleaned Up.