



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Ave SE • Bellevue, WA 98008-5452 • 425-649-7000
711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341

December 29, 2015

Mr. Chris Carter
SoundEarth Strategies, Inc.
2811 Fairview Avenue East, Suite 2000
Seattle, WA 98102

Re: Request for Information on Status of VCP Project for the Following Site:

- **Site Name:** Erickson Property (aka BP Station Brooklyn)
- **Site Address:** 4557 Brooklyn Avenue NE, Seattle, WA 98105
- **Facility/Site No.:** 4819383
- **Cleanup Site ID:** 7601
- **VCP Project No.:** NW2347

Dear Mr. Carter:

The Department of Ecology (Ecology) appreciates your decision to clean up the **Erickson Property** facility (Site) independently. However, our records indicate that you have not conducted any remedial actions during the past year at the Site. Ground water monitoring has been conducted quarterly for this project, with monitoring reports of the collected data provided to Ecology. It has been determined that residual petroleum contamination has remained on the Site, and impacts to groundwater beneath the Site continue to occur. This letter requests information on the status of your cleanup and your continued interest in the Voluntary Cleanup Program (VCP).

Request for Information

Please submit the following information to Ecology within 30 days of the date of this letter:

1. Cleanup status report.
2. Any reports documenting the cleanup.
3. Plan and schedule for completing the cleanup.

Next Steps

Based on your response, Ecology will decide whether to continue providing you services under the VCP. We will notify you of our decision in writing. Please note that we will terminate the Agreement governing this Project if you do not respond to this request. Also please note that



Mr. Chris Carter
December 29, 2015
Page 2

Ecology's position is that a VCP project which may be a year or more from completing final cleanup should have the Agreement governing the Project terminated, and re-enter the VCP once cleanup has been completed, or when the final four quarters of ground water monitoring confirming the adequacy of the final cleanup is being collected. A minimum of four consecutive quarters of groundwater monitoring data demonstrating Contaminant of Concern concentrations below MTCA Method A cleanup levels will be required to evaluate the effectiveness of the selected action.

Contact Information

We are committed to working with you to accomplish the prompt and effective cleanup of the Site. If you have any questions about this request, please contact me at (425) 649-4422 or by email at glynis.carrosino@ecy.wa.gov.

Sincerely,



Glynis A. Carrosino
VCP Project Manager
Toxics Cleanup Program

By Certified Mail [7012 3460 0000 2587 4801]

cc: Michael Miller, Cardno ERI
Louise Bardy, Ecology
Sonia Fernandez, Ecology