



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000

June 21, 2016

TO: TCP File (Southcenter Chevron Hoists)

FROM: Donna Musa
Ecology NWRO Initial Investigations Coordinator

SUBJECT: Initial Investigation: No Further Action (NFA) Determination
Southcenter Chevron Hoists
220 Strander Blvd
Tukwila, WA 98188
Parcel ID # 2623049104
Facility Site ID: 43787415
Cleanup Site ID: 13066

Ecology has determined that no further action is necessary (at the Initial Investigation stage) due to independent remediation.

Ecology reviewed the following document:

- Soil Remediation Report, 220 Strander Boulevard, Tukwila, Washington. ECI Environmental Services. June 8, 2015.

The above documentation provides sufficient evidence that this cleanup was conducted to MTCA Method A cleanup levels for unrestricted land use.

NOTE: This determination does not apply to the LUST/VCP site at the same address. These are separate releases.

Additional information about Ecology's review of this site cleanup may be accessed here:
<https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=13066>.

To view the documentation Ecology has available electronically, on the right-hand side of the page, click on [View Electronic Documents](#).