

INITIAL INVESTIGATION

SITE NAME: Rainier Beach Automotive
ADDRESS: 9479 Rainier Ave S, Seattle
INSP. DATE: 3/6/91
INSP. NAME: John Stormon

An initial investigation was conducted at Rainier Beach Automotive on 3/6/91 by John Stormon. I met with Jim Campbell, the owner who told me that the tanks were removed in October, 1990. Contaminated soil from the tank area was excavated and hauled off site. Contamination continues under the street and the station building. The excavation has been backfilled with clean material. A final cleanup report will be submitted to Ecology shortly.

STATUS: ~~Limited~~ Cleanup

ON-GOING

~~Soil~~

to Limited
Report Revd.
3/20/91 CN

RAINIER BEACH AUTOMOTIVE

DATE: 3-6-91

TIME: _____

TAKEN BY: STORMUN

WITNESS: _____

FILM: 6018

CAMERA: E 107787

DESCRIPTION:

BACKFILLED EXCAVATION

WHERE TANK

WAS REMOVED

COMMENTS:

PHOTO No. _____

DATE: _____

TIME: _____

TAKEN BY: _____

WITNESS: _____

FILM: _____

CAMERA: _____

DESCRIPTION:

COMMENTS:

