

ERTS # 619186

Initial Report

External Reference #

Caller Information

Where did it happen

First Name: JOHN
 Last Name: ERICKSON
 Business Name:
 Street Address:
 Other Address:
 City: State WA Zip:
 E-mail: Confidential_FL
 Phone: (206) 525-9075 Ext: Type: Mobile

Berth: Anchorage:
 Location Name:
 Street Address: 6548 43RD AVE NE
 Other Address:
 City/Place: SEATTLE State: WA Zip: 98115
 County - Region: KING NWRO FS ID:
 WIRA #:
 Waterway: Type:
 Latitude: Longitude:
 Topo Quad 1:24:00 SEATTLE

What happened

Spills Program Oil Spill? N

Direction/Landmark (mile post, cross roads, township/range):
 KING CO TAX PARCEL # 0435000015

Incident Date: 4/8/2010 Received Date: 4/12/2010 10:48

Medium: SOIL

Material: PETROLEUM - OIL OTHER
 Quantity: Unit:

Primary Potentially Responsible Party Information

First Name: JOHN B
 Last Name: ERICKSON

Business Name: ERICKSON PROPERTY

Street Address: 6548 43RD AVE NE

Other Address:

City: SEATTLE State: WA Zip: 98115

Phone: Ext: Type:

E-mail:

Source: UNDERGROUND STORAGE TANK

Cause: LEAKING UNDERGROUND STORAGE TANK

Activity: ROUTINE/NORMAL OPERATIONS

Impact: SOIL CONTAMINATION

Vessel Name:

Hull Number:

Additional Contact Information

Name: Phone: Ext: Type:

More Information

JOHN ERIKSON CONTACTED PEGGY (EMD) 800-258-5990 TO REPORT:
 AN UNDERGROUND STORAGE TANK HAD BEEN REMOVED FROM PRIVATE PROPERTY AND HAD BEEN LEAKING.
 UNKNOWN AMOUNT
 DISCOVERED ON 4/8/10.

Entry Person: Sacayanan, Tammy

Entry Date: 4/12/2010

ERTS # 619186

Referral

Referral Method		Person Referred to MUSA TCP, DONNA	Referral # 132288
<input type="radio"/> E-mail ERTS number		Phone (425) 649-7136 Fax (425) 649-7098	Primary <input type="checkbox"/>
<input checked="" type="radio"/> E-mail attachment		E-mail DMUS461@ECY.WA.GOV	
<input type="radio"/> Print		Program/Organization TOXICS CLEANUP	
<input type="radio"/> Telephone		Address 3190 160th AVE SE	
		City Bellevue WA 98008-5452	
		Region/Location NWRO	
		Referral Date 4/12/2010	

Department of Ecology - Environmental Report Tracking System

ERTS # 619186

Followup

Inspector Information

Referral # 132288
 Lead Inspector MUSA TCP, DONNA
 Program/Organization TOXICS CLEANUP
 * Region/Location NWRO
 # of Ecology Staff 1 Overtime

Where did it happen

Location Name Berth Anchorage
 Street Address 6548 43RD AVE NE
 Other Address
 City/Place SEATTLE State WA Zip 98115-
 County KING Region NWRO FS ID
 Waterway Type
 WRIA #

Followup #1

Action

	Start Date	End Date
TELEPHONE	5/11/2010	5/11/2010
REQUESTED INFORMATION	5/12/2010	5/12/2010
TCP - SIS	7/15/2010	7/15/2010

What happened

Incident Date 4/8/2010 Spills Program Oil Spill? N Latitude Longitude
 Topo Quad 1:24,000 SEATTLE
 Direction/Landmark (mile post, cross roads, township/range)
Medium
 SOIL
Material
 PETROLEUM - OIL OTHER
 Quantity Unit Est

Potentially Responsible Party Information

Check if the primary PRP provided notice to Ecology

Source Regulated?
 UNDERGROUND STORAGE TANK

Cause
 LEAKING UNDERGROUND STORAGE TANK

Activity
 ROUTINE/NORMAL OPERATIONS

Impact
 SOIL CONTAMINATION

Vessel

Narrative

Spoke to John Erickson. He had a tank removed in April that had been in place since 1994. This tank was not leaking. The tank it replaced in 1994 was the one that leaked. Budget Tank removed current tank and took soil samples, which came back at 19,000ppm. I explained to John that this is above Ecology's MTCA threshold of 2,000ppm and discussed options with him. I suggested he investigated Ecology's VCP information on the internet. I explained to him that if the site could not be cleaned up to the 2,000ppm level within 90 days, that it would be listed. I also told him how he can avoid that and get off the list at a later date. He will investigate further and consider his options and call me if/when he has further questions.

ENL mailed for Erickson HOT site on 11/3/14. New TCP file "Erickson HOT".

Vessel Emergency

Entry Person: MUSA TCP, DONNA

Entry Date 5/11/2010