

STATE OF WASHINGTON DEPARTMENT OF ECOLOGY

PO Box 47775 • Olympia, Washington 98504-7775 • (360) 407-6300

March 7, 2013

Weyerhaeuser Timber Co PO Box 9777 Auburn WA 98063-9777

Re: EARLY NOTICE LETTER

• Site Name: US West (Capital Peak Radio)

• Site Address: NE1/4 SE1/4 S11 T17N R4W, OLYMPIA, WA 98502

• Facility/Site No.: 53914154

LUST ID No.: 2764

Dear Weyerhaeuser Timber Co:

Under the Model Toxics Control Act (MTCA), Chapter 70.105D RCW, which governs the cleanup of hazardous waste sites in Washington State, the Department of Ecology (Ecology) maintains a list of sites where further testing and possible cleanup may be needed. We call this the Confirmed and Suspected Contaminated Sites List (List).

The US West (Capital Peak Radio) facility (Site) is part of a group of historical sites previously designated as "Reported Cleaned Up" (RCU). These are sites where cleanup reports and/or other documentation was submitted to Ecology by owners or consultants indicating to us they had "reportedly cleaned up the site" but did not enter Ecology's former Independent Remedial Action Program (IRAP) or current Voluntary Cleanup Program (VCP) to achieve closure. Ecology has recently reviewed the file for this Site. Our review confirms that soil and/or groundwater were contaminated due to a release from a leaking underground storage tank (LUST), and the documentation provided to Ecology thus far does not demonstrate MTCA cleanup standards were achieved. Specifically, our review noted the following:

• Soil and groundwater contaminated with diesel-range petroleum hydrocarbons were left in place above MTCA cleanup levels in the area of the newly installed UST. The results of groundwater monitoring indicates that TPH concentrations exceed the MTCA cleanup levels, including the presence of floating product. No final cleanup report or groundwater monitoring reports are known to have been submitted to Ecology. Also, no documentation demonstrating cleanup standards were achieved for soil and groundwater is known to have been provided.

Based on the available information in Ecology's files, this Site has been added to the List as a state cleanup site. Please note that inclusion on the List does not mean Ecology has determined

Weyerhaeuser Timber Co March 7, 2013 Page 2 of 2

you are a potentially liable person under MTCA. Further investigation or cleanup action will need to be done to comply with Washington State laws and regulations. Alternately, if historical documentation exists demonstrating MTCA cleanup standards were achieved that had not been provided to Ecology, please provide that documentation for review.

In the future, Ecology may conduct a more detailed inspection of this Site, including testing for possible contamination. This inspection is called a "Site Hazard Assessment." At that time, Ecology will establish a priority for the work.

Ecology has a strong commitment to working cooperatively with owners/operators to accomplish prompt and effective cleanups. Your cooperation in planning or conducting remedial action is not an admission of guilt or liability. Please be aware of state laws that must be adhered to if you decide to proceed with cleanup work on your own. The primary law is MTCA, Chapter 70.105D RCW, and the implementing regulation, the MTCA Cleanup Regulation, Chapter 173-340 WAC. These laws may be found at Ecology's Toxics Cleanup Program website: http://www.ecy.wa.gov/toxicscleanup/policy.

Ecology's VCP is designed to provide technical assistance, for a fee, to cleanup sites that qualify. If you would like additional information regarding this program, you can find information on our website at http://www.ecy.wa.gov/programs/tcp/vcp/vcpmain.htm.

Ecology's copies of documents on this Site are kept in the Records Center for the Southwest Regional Office (SWRO) of Ecology. These documents are available for public review by appointment only. Appointments can be made to review site files by calling the SWRO Records Center at (360) 407-6365.

Thank you for your work toward remediation of this Site. If you have any questions, please contact me by e-mail at scott.rose@ecy.wa.gov or by phone at (360) 407-6347.

Sincerely,


Scott Rose, L.G.

VCP/LUST Unit Supervisor Southwest Regional Office Toxics Cleanup Program

SR/ksc:SWRO ENL 03072013

By certified mail: (7012 1010 0003 0195 9685)

cc: Gerald Tousley, Thurston County Public Health & Social Services



SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
 Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. Article Addressed to: 	A. Signature X
Weyerhaeuser Timber Co PO Box 9777 Auburn WA 98063-9777	MAR 13 2013 WA State Department 3. Service Type Cology (SWHO) Certified Mail
2. Article Number 7012 1010 0003	0145 4685 11 11 11
PS Form 3811, February 2004 Domestic Return Receipt SUSIC Type 395-02-M-1540	