

Response to Comments

Draft Interim Action Work Plan – Alley Area of Block 38 West Site

Block 38 West Cleanup Site Seattle, WA

Facility Site ID: 62773 Cleanup Site ID: 15008

January 2021

Publication Information

This document is available on the Department of Ecology's website at: <u>https://apps.ecology.wa.gov/gsp/Sitepage.aspx?csid=15008</u>

Contact Information

Toxics Cleanup Program

Northwest Regional Office

Tena Seeds, PE Site Manager 425-649-7008, <u>Tena.Seeds@ecy.wa.gov</u>

Kelsey Ketcheson Public Involvement Coordinator 425-240-4353, <u>kelsey.ketcheson@ecy.wa.gov</u>

3190 160th Ave SE Bellevue, WA 98008 Phone: 425-649-7190 **Website¹:** <u>Washington State Department of Ecology</u>


ADA Accessibility

The Department of Ecology is committed to providing people with disabilities access to information and services by meeting or exceeding the requirements of the Americans with Disabilities Act (ADA), Section 504 and 508 of the Rehabilitation Act, and Washington State Policy #188.

To request an ADA accommodation, contact Ecology by phone at 360-407-6831 or email at <u>ecyadacoordinator@ecy.wa.gov</u>. For Washington Relay Service or TTY call 711 or 877-833-6341. Visit Ecology's website for more information.

¹ www.ecology.wa.gov/contact

Department of Ecology's Regional Offices



Map of Counties Served

Region	Counties served	Mailing Address	Phone
Southwest	Clallam, Clark, Cowlitz, Grays Harbor, Jefferson, Mason, Lewis, Pacific, Pierce, Skamania, Thurston, Wahkiakum		360-407-6300
Northwest	Island, King, Kitsap, San Juan, Skagit, Snohomish, Whatcom	3190 160th Ave SE Bellevue, WA 98008	425-649-7000
Central	Benton, Chelan, Douglas, Kittitas, Klickitat, Okanogan, Yakima	1250 W Alder St Union Gap, WA 98903	509-575-2490
Eastern	Adams, Asotin, Columbia, Ferry, Franklin, Garfield, Grant, Lincoln, Pend Oreille, Spokane, Stevens, Walla Walla, Whitman	4601 N Monroe Spokane, WA 99205	509-329-3400
Headquarters	Across Washington	PO Box 46700 Olympia, WA 98504	360-407-6000

Response to Comments

Draft Interim Action Work Plan – Alley Area of Block 38 West Site

Block 38 West Cleanup Site Seattle, WA

Toxics Cleanup Program Washington State Department of Ecology Northwest Regional Office

Bellevue, WA

January 2021



Table of Contents

List of Figures and Tables				
Figures				
Tables				
Public Outreach Summary	.6			
Comment Summary	.7			
Next Steps	.7			
Comments and Responses	.8			

List of Figures and Tables

Figures	
Figure 1:	Washington's formal cleanup process7
Tables	
Table 1:	List of Commenters

Public Outreach Summary

The Block 38 West cleanup site (Site), located in the South Lake Union neighborhood of Seattle, is beginning an Interim Action under Washington State's <u>formal cleanup process</u>² as directed under the Model Toxics Control Act (<u>MTCA</u>³). From December 21, 2020 to January 19, 2021, the Department of Ecology solicited public comments on an Interim Action Work Plan – Alley Area of Block 38 West Site.

The Department of Ecology's public involvement activities related to this Site's 30-day comment period included:

- Fact Sheet:
 - US mail distribution of a fact sheet providing information about the cleanup documents and the public comment period to approximately 8,000 people including neighboring businesses and other interested parties.
- Legal Notices:
 - Publication of one paid display ad in *The Seattle Times*, dated Friday, December 18, 2020.
- Site Register:
 - Publication of 3 notices in Ecology's Toxics Cleanup Site Register:
 - Comment Period Notice: December 17 and December 31, 2020 and January 14, 2021
 - Visit <u>Ecology's Site Register website</u>⁴ to download PDFs.
- Social Media:
 - Twitter: Ecology Northwest Region @ecyseattle posted a tweet on Friday, December, 17 2020⁵ connecting readers to the comment period including the cleanup site webpage, a virtual tour, and how to submit comments.
- Websites:
 - Announcement of the public comment period and posting of the fact sheet and associated documents for review on <u>Ecology's Block 38 West webpage</u>⁶ and Ecology's <u>Public Inputs & Events webpage</u>⁷.
- Document Repositories:
 - In consideration of public health and safety, Ecology made documents available online as well as by appointment at the Northwest Regional Office.

² https://ecology.wa.gov/Spills-Cleanup/Contamination-cleanup/Cleanup-process

³ https://ecology.wa.gov/Spills-Cleanup/Contamination-cleanup/Rules-directing-our-cleanup-work/Model-Toxics-Control-Act

⁴https://fortress.wa.gov/ecy/publications/UIPages/PublicationList.aspx?IndexTypeName=Program&NameValue=To xics+Cleanup&DocumentTypeName=Newsletter

⁵ <u>https://twitter.com/ecyseattle?lang=en</u>

⁶ https://apps.ecology.wa.gov/gsp/Sitepage.aspx?csid=15008

⁷ https://10ecology.wa.gov/Events/Search/Listing

Comment Summary

From December 21, 2020 to January 19, 2021 Ecology solicited public comments on a draft Interim Action Work Plan – Alley Area of Block 38 West Site for the Block 38 West cleanup site.

Ecology received 1 comment during the 30-day comment period.

Table 1: List of Commenters

	First Name	Last Name	Agency/Organization/Business	Submitted By
1	Lauren	Carroll		Individual

Next Steps

Ecology has reviewed and considered all public comments received on the Interim Action Work Plan – Alley Area of Block 38 West Site. Based on Ecology's evaluation of the comments, no changes were necessary in the document, and it is being finalized.

Work will begin on the Interim Action for the Alley Area of the Block 38 West Site. See graphic below and visit Ecology's <u>cleanup process webpage</u>⁸ to learn more about Washington's formal cleanup process.




Figure 1: Washington's formal cleanup process

⁸ https://ecology.wa.gov/Spills-Cleanup/Contamination-cleanup/Cleanup-process

Comments and Responses

The public comments are presented below, along with Ecology's responses.

Comment from: Lauren Carroll

Section 4.1.4 East Property - Lots 6 and 7. This section states that a heating oil release was confirmed on Lot 6 during removal in 1994, and references a report by GeoEngineers dated 1999. However, this information is not substantiated in this report, or in the Interim Action Work Plan (IAWP) for the Block 38 West property (Farallon November 8, 2019) (i.e., it is not included in Appendix E, as referenced in the document). The information in Farallon's report conflicts with a summary by CH2MHILL in the "Hazardous Materials Discipline Report" (CH2MHILL 2006), which indicates that all USTs and petroleum impacts were on Lots 1 through 5. If it exists, appropriate third-party documentation of the heating oil tank should be included in the report, or the report revised to omit it. It is requested that Ecology upload a complete copy of the 1999 GeoEngineers report onto its website. Thank you.

Response:

The 1999 GeoEngineers report (Phase I Environmental Site Assessment and Soil and Ground Water Sampling and Testing, UW-FAMS Rosen Property, 960-964 Republican, Seattle, Washington dated April 22, 1999) that is referenced in the work plan contains information confirming that a heating oil release occurred on Lot 6 of the East Property. This information is documented in Section 2.4.2 (pages 11-12) and Figure 3 of the 1999 GeoEngineers report, and is further supported by statements made in Section 4.2.1 (page 15) of the 1999 report.

Ecology's files do not appear to contain a complete copy of the 1999 GeoEngineers report; however, a partial hardcopy (i.e., text, tables, and figures) can be found in the Rosen Property file (Facility Site ID 2500) in Central Records of the Northwest Regional Office. An electronic copy has also been added to the online document repository for the Rosen Property, which can be accessed at

https://apps.ecology.wa.gov/gsp/CleanupSiteDocuments.aspx?csid=5123.

Ecology understands that the CH2MHILL 2006 Hazardous Materials Discipline Report was prepared to support work associated with the City of Seattle's Mercer Corridor Improvements Project. The information concerning the East Property that is contained in the CH2MHILL 2006 report appears to be primarily focused on the former USTs that were located on the northern portion of the property (Lots 1 through 5) where a gas station had historically operated and had released petroleum hydrocarbons.

Remedial actions were conducted on Lots 1 through 5 of the East Property in 1993 and 2008, which are documented in the Cleanup Action Report, Interurban Exchange 2, 535 Terry Avenue North, Seattle, Washington prepared by GeoEngineers, dated October 28, 2008. The information provided in Appendix E of Farallon's 2019 Interim Action Work Plan was from the GeoEngineers 2008 report to support their discussion of the remedial action work on Lots 1 through 5.