

Cleanup Site Details

Cleanup Site ID: 3704

Cleanup Site ID: 3704 Facility/Site ID: 75128579 UST ID: 1719 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Hardel Mutual Plywood [Glossary](#)

Alternate Names: Hardel Mutual Plywood, HARDEL MUTUAL PLYWOOD CORP, HARDEL MUTUAL PLYWOOD CORPORATION

LOCATION

Address: 1210 W BAY DR NW City: OLYMPIA Zip Code: 98502 County: Thurston
Latitude: 47.05800 Longitude: -122.91394 WRIA: 13 Legislative District: 22 Congressional District: 10 TRS: 18N 2W 59

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 5 - Lowest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Teel, Steve Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
HARDEL MUTUAL PLYWOOD CORPORATION	Upland	Cleanup Started	SW	Teel, Steve	Ecology-supervised or conducted
Hardel Mutual Plywood	Sediment	Awaiting Cleanup	SW	Teel, Steve	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C				
Benzene	C					
Dioxins/Furans				C		
Halogenated Solvents		C				
Metals - Other	C	C				
Other Non-Halogenated Organics	C					
Petroleum Products-Unspecified	C	C	RB			
Petroleum-Diesel	C	C				
Petroleum-Gasoline		C				
Polycyclic Aromatic Hydrocarbons	C	C	RB	C		

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 3704

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		10/12/2004
Early Notice Letter(s)	Completed		10/12/2004
Site Hazard Assessment/Federal Site Inspection	Completed	11/16/2004	1/19/2005
Hazardous Sites Listing/NPL	Completed		1/19/2005
Remedial Investigation and/or Feasibility Study	Completed	4/30/2007	4/30/2009
Order/Decree/Amendment	Completed	4/30/2007	8/22/2012
Interim Action	Completed	6/14/2010	8/22/2012
Interim Action - Construction	Completed	6/14/2010	12/15/2010
Site Status Changed to NFA	Completed		8/22/2012
Remove site from Hazardous Sites List	Completed		8/22/2012
Non-LUST Ind Report Received	Completed		7/28/2021
Non-LUST Ind Report Received	Completed		7/28/2021
Non-LUST Ind Report Received	Completed		7/28/2021
Non-LUST Ind Report Received	Completed		7/28/2021
Reopen Site	Completed		8/17/2021
Early Notice Letter(s)	Completed		8/19/2021
VCP Receipt of Plan or Report	Completed		8/31/2021
VCP Technical Assistance	Completed		9/22/2021
VCP Receipt of Plan or Report	Completed		9/23/2021
VCP Receipt of Plan or Report	Completed		9/29/2021
VCP Receipt of Plan or Report	Completed		3/11/2022
VCP Receipt of Plan or Report	Completed		3/31/2022
VCP Technical Assistance	Completed		6/17/2022
VCP Technical Assistance	Completed		9/13/2022
VCP Technical Assistance	Completed		9/13/2022
VCP Receipt of Plan or Report	Completed		10/25/2022
Order/Decree/Amendment	In Process	3/16/2023	
Remedial Investigation and/or Feasibility Study	Planned	6/3/2024	12/31/2024