

Cleanup Site Details

Cleanup Site ID: 3704

Cleanup Site ID: 3704 **Facility/Site ID:** 75128579 **UST ID:** 1719 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Hardel Mutual Plywood [Glossary](#)
Alternate Names: Hardel Mutual Plywood, HARDEL MUTUAL PLYWOOD CORP, HARDEL MUTUAL PLYWOOD CORPORATION

LOCATION

Address: 1210 W BAY DR NW **City:** OLYMPIA **Zip Code:** 98502 **County:** Thurston
Latitude: 47.05800 **Longitude:** -122.91394 **WRIA:** 13 **Legislative District:** 22 **Congressional District:** 10 **TRS:** 18N 2W 59

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 5 - Lowest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Teel, Steve **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
HARDEL MUTUAL PLYWOOD CORPORATION	Upland	Cleanup Started	SW	Teel, Steve	Ecology-supervised or conducted
Hardel Mutual Plywood	Sediment	Cleanup Started	SW	Teel, Steve	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C				
Benzene	C					
Dioxins/Furans				C		
Halogenated Solvents		C				
Metals - Other	C	C				
Other Non-Halogenated Organics	C					
Petroleum Products-Unspecified	C	C	RB			
Petroleum-Diesel	C	C				
Petroleum-Gasoline		C				
Polycyclic Aromatic Hydrocarbons	C	C	RB	C		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 3704

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		10/12/2004
Early Notice Letter(s)	Completed		10/12/2004
Site Hazard Assessment/Federal Site Inspection	Completed	11/16/2004	1/19/2005
Hazardous Sites Listing/NPL	Completed		1/19/2005
Remedial Investigation and/or Feasibility Study	Completed	4/30/2007	4/30/2009
Order/Decree/Amendment	Completed	4/30/2007	8/22/2012
Interim Action	Completed	6/14/2010	8/22/2012
Interim Action - Construction	Completed	6/14/2010	12/15/2010
Site Status Changed to NFA	Completed		8/22/2012
Remove site from Hazardous Sites List	Completed		8/22/2012
Non-LUST Ind Report Received	Completed		7/28/2021
Non-LUST Ind Report Received	Completed		7/28/2021
Non-LUST Ind Report Received	Completed		7/28/2021
Non-LUST Ind Report Received	Completed		7/28/2021
Reopen Site	Completed		8/17/2021
Early Notice Letter(s)	Completed		8/19/2021
VCP Receipt of Plan or Report	Completed		8/31/2021
VCP Technical Assistance	Completed		9/22/2021
VCP Receipt of Plan or Report	Completed		9/23/2021
VCP Receipt of Plan or Report	Completed		9/29/2021
VCP Receipt of Plan or Report	Completed		3/11/2022
VCP Receipt of Plan or Report	Completed		3/31/2022
VCP Technical Assistance	Completed		6/17/2022
VCP Technical Assistance	Completed		9/13/2022
VCP Technical Assistance	Completed		9/13/2022
VCP Receipt of Plan or Report	Completed		10/25/2022
Order/Decree/Amendment	In Process	3/16/2023	
Remedial Investigation and/or Feasibility Study	Planned	12/30/2024	12/31/2025