

Cleanup Site Details

Cleanup Site ID: 4533

Cleanup Site ID: 4533 Facility/Site ID: 2685 UST ID: 12024 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Custom Plywood Mill [Glossary](#)

Alternate Names: ANACORTES PLYWOOD, ANACORTES PLYWOOD INC, Anacortes Plywood Mill, CUSTOM PLYWOOD MILL

LOCATION

Address: 35TH & V ST City: ANACORTES Zip Code: 98221 County: Skagit
Latitude: 48.49390 Longitude: -122.60331 WRIA: 3 Legislative District: 40 Congressional District: 2 TRS: 35N 2E 30

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Morman, Josh Responsible Unit: Headquarters Active Institutional Control? No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-----------------------|-----------|-----------------|-----------|--------------|---------------------------------|
| ANACORTES PLYWOOD INC | Sediment | Cleanup Started | HQ | Morman, Josh | Ecology-supervised or conducted |
| ANACORTES PLYWOOD INC | Upland | Cleanup Started | HQ | Morman, Josh | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| Contaminant | MEDIA | | | | | |
|----------------------------------|-------|-------------|---------------|----------|-----|---------|
| | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Base/Neutral/Acid Organics | | R | S | | S | |
| Bioassay Benthic Failures | | | | C | | |
| Halogenated Organics | C | C | S | | S | |
| Metals Priority Pollutants | C | S | S | C | S | |
| Methyl tertiary-butyl ether | S | S | S | | S | |
| Non-Halogenated Solvents | C | S | S | | S | |
| Other Deleterious Substances | | | | C | | |
| Pesticides-Unspecified | S | S | S | | S | |
| Petroleum Products-Unspecified | C | S | R | C | S | |
| Phenolic Compounds | S | S | S | C | S | |
| Polychlorinated biPhenyls (PCB) | B | S | | S | S | |
| Polycyclic Aromatic Hydrocarbons | B | C | S | C | S | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 4533

| SITE ACTIVITIES | | | |
|---|---------------|-------------------|--------------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Order/Decree/Amendment | In Process | | |
| Site Discovery/Release Report Received | Completed | | 3/3/1993 |
| VCP Opinion on Remedial Investigation Work Plan | Completed | 6/3/1998 | |
| Site Hazard Assessment/Federal Site Inspection | Completed | 5/8/2001 | 8/24/2001 |
| Hazardous Sites Listing/NPL | Completed | | 8/28/2001 |
| VCP Opinion on Cleanup Action Plan | Canceled | 9/10/2004 | |
| VCP Status Request | Completed | 11/13/2006 | 4/10/2007 |
| Placement of Lien | Completed | 4/2/2012 | |