

1641D

Douglas Fir
Sitka Spruce
Western Hemlock
Western Red Cedar
Remanufacturing
Lumber Specialties



fred tebb and sons, inc.

February 14, 2006

Tacoma
P.O. Box 2235
Tacoma, WA 98401

Phone: 253-272-4107
Fax: 253-272-4292

Washington State Dept. of Ecology
P.O. Box 4796
Olympia, WA 98504-7696

Attn: Joyce M. Smith

Department of Ecology
Water Quality Program
FEB 16 2006

Level Two Response

Industrial Storm water Permit Manager:

In compliance with our industrial storm water permit, we are submitting a level two response, due to high zinc levels in the first and second quarter of 2005.

After conducting additional inspections, conferring with Paul Stach from the Dept. of Ecology and Linda Dawson (our storm water consultant), we have identified four possible sources of zinc.


1. Oil:
 - A. From Forklifts
 - B. From transport trucks
2. Galvanized blow pipe
3. Galvanized roofing
4. Tire Wear:
 - A. From forklifts
 - B. From transport trucks

Source control:

1. Forklifts:
 - A. Constant check for oil leaks
 - B. Change to zinc free hydraulic oil
2. Transport trucks:
 - A. Constant check for oil leaks in loading, unloading area
3. Galvanized blow pipe:
 - A. Paint pipe
4. Galvanized roofing:
 - A. Paint Roof
5. Tire wear:
 - A. Vacuum sweep monthly

Implementation:

1. Forklifts:
 - A. Change over to zinc free hydraulic oil before end of 2nd qtr. 2006
2. Paint galvanized blow pipe and roofing before end of 2nd qtr. 2006
3. Begin vacuum sweeping starting in Feb. 2006



Rick Tebb, Vice President
Fred Tebb & Sons Inc.
1906 Marc Street
Tacoma, WA 98421