

# Sumner National Auto Parts Cleanup Site

16008 60<sup>th</sup> Street East, Sumner

## Proposed removal from the Hazardous Sites List

Facility Site ID: 1304      Cleanup Site ID: 3653

### Comment accepted

**September 22—October 23,  
2022**

### Submit comments online

[http://tcp.ecology.commentinput.com  
/?id=bKdWS](http://tcp.ecology.commentinput.com/?id=bKdWS)

### Or by mail or email

**Tim Mullin, LHG, Site Manager**  
WA State Department of Ecology  
PO Box 47775  
Olympia, WA 98504-7775  
[tim.mullin@ecy.wa.gov](mailto:tim.mullin@ecy.wa.gov)

### Printed document review

#### Sumner Public Library

1116 Fryar Avenue  
Sumner, WA 98390

#### Ecology Lacey Office by appointment

300 Desmond Drive SE  
Lacey, WA 98503  
[PublicDisclosureSWRO@ecy.wa.gov](mailto:PublicDisclosureSWRO@ecy.wa.gov)  
or 360-407-6365

### Site webpage

[https://apps.ecology.wa.gov/cleanup  
search/site/3653](https://apps.ecology.wa.gov/cleanup/search/site/3653)

### Contaminants

Petroleum hydrocarbons.  
BTEX (benzene, toluene, ethylbenzene,  
and xylenes).  
PAHs (polycyclic aromatic  
hydrocarbons).  
Metals.  
Organic solvents.

### You are invited to comment

The Department of Ecology (Ecology) invites your comment about our proposal to remove the Sumner National Auto Parts cleanup site from the Hazardous Sites List.

The site was an auto supply store and an engine rebuild and metal machine shop. Leaks of hazardous chemicals into the soil likely caused contamination at the site.

Ecology ranked the site's relative risk to human health and the environment based on contamination and location of the site. The site is about a half mile from municipal water supply wells. When a cleanup site is ranked, we put the site on the state's Hazardous Sites List.

This site has been cleaned up and meets state cleanup standards. The cleanup is effective in protecting the health of people and the environment. Ecology determined no further cleanup action is required.

We want to hear from you about removal of the site from the Hazardous Sites List. You can submit comments online, by email, or by US Mail during the comment period.

The site webpage (see the blue box on the left) has electronic documents available about this site. We will consider the comments and post our response to comments on the webpage.

### Cleanup

**Soil:** About 513 tons of contaminated soil was excavated and removed from the site. After the contamination was removed, soil tests confirmed that contaminant concentrations were below state cleanup levels.

**Groundwater:** Monitoring wells were installed in and near areas where the contaminated soil was removed. Groundwater was tested periodically and results confirmed that for at least a year contaminants were either not present in groundwater or present at concentrations below state cleanup levels.



Toxics Cleanup Program  
 PO Box 47775  
 Olympia, WA 98504-7775

## Sumner National Auto Parts Site

16008 60<sup>th</sup> Street East, Sumner




Public comment period September 22 to October 23, 2022

**Why did I receive this mailing?** You live near the Sumner National Auto Parts Site or have expressed interest in the cleanup. This fact sheet informs you about the proposed removal of the site from the Hazardous Sites List and the opportunity for public comment.

**What can I do?** Please review the proposal to remove the Site from the Hazardous Sites List and submit your comment or question.

**¿Habla Español?** Unáse al diálogo sobre Sumner National Auto Parts Site. Cuando el período de comentarios termine, revisaremos los comentarios y haremos cambios antes de finalizar los documentos. Para más información en español llame al 360-489-4971 y solicite un intérprete.



**ADA accessibility.** To request an ADA accommodation, contact Ecology by phone at 360-489-4971 or email at [nancy.davis@ecy.wa.gov](mailto:nancy.davis@ecy.wa.gov), or visit [ecology.wa.gov/Accessibility](http://ecology.wa.gov/Accessibility). For Relay Service or TTY call 711 or 877-833-6341.