Bakkers Fine Dry Cleaning
Bakker's Co. Inc. Bellevue
FS 9264 5942

RECEIVED
SEP 03 2013
DEPT OF ECOLOGY
TCP - NWRO

Phase I Environmental Site Assessment
Volume I

Bakker Properties
Barrier Pre-Owned Sales and Parking Lot
(Former Dry Cleaner Plant and Office)
11855 NE Bellevue-Redmond Road
Bellevue, Washington

for
City of Bellevue c/o Parsons Brinckerhoff

April 27, 2012

GeoEngineers
8410 154th Avenue NE
Redmond, Washington 98052
425.861.6000

Phase I Environmental Site Assessment

Bakker Properties
Barrier Pre-Owned Sales and Parking Lot
(Former Dry Cleaner Plant and Office)
11855 NE Bellevue-Redmond Road
Bellevue, Washington

File No. 0526-170-01

April 27, 2012

Prepared for:

Parsons Brinckerhoff
999 Third Avenue Suite 3200
Seattle, Washington 98104

Attention: Ken Oswell

Prepared by:

GeoEngineers, Inc.
8410 154th Avenue NE
Redmond, Washington 98052
425.861.6000

DECLARATIONS

- "I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in Sec. 312.10 of 40 CFR Part 312."*
- "I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I performed and/or developed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312."*

*A person who does not qualify as an Environmental Professional may assist in the conduct of all appropriate inquiries in accordance with ASTM E 1527-05, if such person is under the supervision or responsible charge of a person meeting the definition of an environmental professional when conducting such activities.

Jessica A. Robertson, LG
Project Manager

Dana L. Carlisle, PE
Principal

JAR:DLC:lw:tt

Disclaimer: Any electronic form, facsimile or hard copy of the original document (email, text, table, and/or figure), if provided, and any attachments are only a copy of the original document. The original document is stored by GeoEngineers, Inc. and will serve as the official document of record

Copyright© 2013 by GeoEngineers, Inc. All rights reserved.

GeoEngineers

Table of Contents

ACRONYMS AND ABBREVIATIONS iii

EXECUTIVE SUMMARY ES-1

1.0 INTRODUCTION 1

1.1 Phase I Scope of Services 1
1.2 Special Considerations 3
1.3 Qualifications of Environmental Professional 3

2.0 PROPERTY DESCRIPTION 3

2.1 Involved Parties 3
2.2 Location, Legal Description and Setting 3
2.3 Site Reconnaissance 5
2.3.1 Summary of Observations 5
2.3.2 Findings 7
2.3.3 Data Gaps 7
2.4 Adjacent Property and Vicinity Observations 7
2.4.1 Summary of Observations 7
2.4.2 Findings 8
2.4.3 Data Gaps 9
2.5 Previous Reports 9
2.5.1 Summary of Previous Reports 9
2.5.2 Findings 15
2.5.3 Data Gaps 15

3.0 ENVIRONMENTAL RECORDS REVIEW 15

3.1 Database Search 15
3.2 Review of Regulatory Files 16
3.3 Review of Areawide Contamination Reports 16
3.4 Findings 17
3.5 Data Gaps 17

4.0 PROPERTY HISTORY 17

4.1 Historical Resources 17
4.2 Historical Property Ownership and Use Summary 19
4.2.1 Key Person Interviews 19
4.3 Adjacent Properties 20
4.4 Environmental Liens or Property Use Restrictions 20
4.5 Information Provided by User/User Obligations 20
4.6 Findings 21
4.7 Data Gaps 21

5.0 CONCLUSIONS AND RECOMMENDATIONS 21

6.0 LIMITATIONS 22

7.0 REFERENCES 22

LIST OF FIGURES

Figure 1. Vicinity Map
Figure 2. Site Plan
Figure 3. Site Photographs, January 2012

APPENDICES

Appendix A. Completed User Questionnaire
Appendix B. Environmental Data Resources (EDR) Report and Historical Research Documents
Appendix C. Key Maps from Prior Reports, Copies of Prior Environmental Reports
Appendix D. Environmental Professional Resumes
Appendix E. Report Limitations and Guidelines for Use

ACRONYMS AND ABBREVIATIONS

AAI – All Appropriate Inquiries

AST – aboveground storage tank

ASTM – ASTM International

BETX – benzene, ethylbenzene, toluene, xylenes

CERCLA – Comprehensive Environmental Response, Compensation and Liability Act

Ecology – Washington State Department of Ecology

EPA – U.S. Environmental Protection Agency

EDR – Environmental Data Resources, Inc.

ESA – Environmental Site Assessment

HREC – historical recognized environmental condition

LG – licensed geologist

MTCA – Model Toxics Control Act

NFA – No further Action

PCBs – polychlorinated biphenyls

PCE – perchloroethene

TCE – trichloroethene

PE – Professional Engineer

ppm – parts per million

REC – recognized environmental condition

USGS – United States Geological Survey

UST – underground storage tank

VCP – Voluntary Cleanup Program

VOCs – volatile organic compounds

EXECUTIVE SUMMARY

GeoEngineers has performed a Phase I ESA in general conformance with the scope and limitations of ASTM Practice E 1527-05 of the two parcels owned by Ernest Bakker located at 11855 NE Bellevue-Redmond Road in Bellevue, Washington. The City of Bellevue plans to purchase these two properties for the NE 8th to NE 12th segment of the 120th Avenue NE widening project. Any exceptions to, or deletions from, this practice are described in Section 1.2 of this report. This assessment has revealed no evidence of recognized environmental conditions (RECs) in connection with the subject properties with the exception of the following:

- Past use of the subject property as a dry cleaning plant is considered a REC for both properties. The rationale for this opinion includes: 1) prior environmental assessments of the Triangle Parking Lot property to the west identified concentrations of dry cleaning solvents perchloroethene (PCE), trichloroethene (TCE), and mineral spirits (Stoddard solvent) in soil and/or groundwater with the likely source being releases from the former dry cleaning plant; 2) potential for migration of dry cleaning solvents is high due to their volatile and mobile nature, long history of use (more than 40 years) and anecdotal information of poor housekeeping (spills) at the dry cleaning plant; 3) petroleum-related constituents were detected during underground storage tank (UST) removal activities in 1989, and available environmental reports (UST removals) for the property do not include a complete assessment or delineation of soil and groundwater conditions in our opinion. Releases of dry cleaning solvents also pose a vapor intrusion REC for indoor air or confined spaces on the subject properties based on the potential for residual volatile contaminants in soil, groundwater and/or soil vapor. We note that the recent "Reported Cleaned Up" designation by Ecology in October 2011 for the former Bakker's Fine Dry Cleaning Plant may meet the ASTM definition of "Historic REC" but because contaminants from the dry cleaner plant apparently migrated to the western adjacent properties and because of the potential for residual contaminants that could affect groundwater or indoor air, we have identified the former dry cleaner plant as a REC in this report.
- Past use of the west-adjacent property as a gas station and rental car facility is considered a REC for the subject property parking lot parcel based on the potential for releases of petroleum and related compounds to have impacted soil and/or groundwater. Releases of volatile petroleum-related constituents also may pose a vapor intrusion REC for indoor air or confined spaces on the subject properties.

A geophysics study and Phase II ESA to evaluate soil and groundwater conditions within the planned future right-of-way of 120th Avenue NE has been completed and will be reported separately.

This Executive Summary should be used only in the context of the full report for which it is intended.

1.0 INTRODUCTION

This report summarizes the results of our Phase I Environmental Site Assessment (ESA) of the Barrier Pre-Owned Sales and Parking Lot parcels owned by Ernest Bakker located at 11855 NE Bellevue-Redmond Road in Bellevue, Washington, as shown in Figures 1 and 2. The parcels are identified as King County parcel numbers 1099100419 (east parcel) and 1099100420 (west parcel) and are currently leased by Barrier Motors for Pre-Owned car sales. The east parcel is developed with a building that was previously the location of a dry cleaning plant ("Bakker Fine Dry Cleaning"). The west parcel, which previously was occupied by an office building, is currently a paved parking lot. The two parcels are collectively referred to in this report as "subject properties" or "subject property." The subject properties are shown relative to surrounding physical features on the Vicinity Map, Figure 1. The layout of the subject properties and surrounding properties is shown on the Site Plan, Figure 2.

We understand that City of Bellevue is planning to acquire the subject properties in connection with the widening and extension of 120th Avenue NE. Our study was completed at the request of Parsons Brinckerhoff on behalf of City of Bellevue. We further understand that the results of this Phase I ESA will be used by Parsons Brinckerhoff and City of Bellevue as part of their evaluation of potential environmental liabilities associated with ownership and redevelopment of the subject properties. This report has been prepared for the exclusive use of City of Bellevue, their agents and the project design team. Because this environmental report is not intended for use by others, no one else should rely on this report without first conferring with GeoEngineers.

1.1 Phase I Scope of Services

The purpose of this Phase I ESA is to identify recognized environmental conditions[1] (RECs) in connection with the subject property. Our scope of services is in general accordance with ASTM International (ASTM) Standard E 1527-05 for Phase I ESAs and the U.S. Environmental Protection Agency's (EPA's) Federal Standard 40 CFR Part 312 "Standards and Practices for All Appropriate Inquiries (AAI)," which are intended to permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner or bona fide prospective purchaser limitations on liability under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA). The standard outlines the practice that constitutes "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined by 42 U.S.C. §9601. Our services, described below, were completed in general accordance with Contract Amendment No. 2 to Agreement No. PW-R164. These services were completed by, or under the direction of, an environmental professional as described in 40 CFR Part 312.

---

[1] Recognized environmental conditions are defined in ASTM E 1527-05 as "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater or surface water of the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies."

Our specific scope of services for this Phase I ESA was as follows:

1. Review readily available geotechnical reports, environmental reports and/or other relevant documents pertaining to environmental conditions at or near the subject properties.
2. Review the results of a federal, state, local and tribal environmental database search provided by an outside environmental data service for listings of properties with known or suspected environmental concerns on or near the subject properties within the search distances specified by ASTM. Our database and file review search also included a review of Environmental Protection Agency (EPA) and Washington State Department of Ecology (Ecology) websites for readily available information (publications and reports) concerning areawide soil and groundwater contamination on or adjacent to the subject property. Evaluate the possibility for a vapor encroachment condition on the property generally as outlined in ASTM Standard E 2600-10 and state our opinion regarding possible vapor encroachment conditions where noted.
3. Review regulatory agency files regarding listed properties of potential environmental concern relative to the subject properties.
4. Identify a key site manager with specific knowledge of past and present property use and request that the key site manager meet a GeoEngineers' representative on site for an interview during the visual site reconnaissance and/or an interview by telephone if he or she is not available during the site reconnaissance. We also identified and interviewed others familiar with the use and history of the subject properties, as available and appropriate, including representatives of current occupants that likely use, store, treat, handle or dispose of hazardous substances now or in the past.
5. Interview current owners or occupants of neighboring properties as necessary to gather information or fill property use data gaps regarding the subject properties.
6. Interview past owners and occupants of the subject properties as necessary to gather information or fill property use data gaps regarding property use history.
7. Interview a representative of the local fire department, health department and/or Ecology as necessary to gather information or fill data gaps regarding the history of the subject properties and surrounding properties relative to the likely presence of hazardous substances.
8. Review historical aerial photographs, fire insurance maps, building department records, city directories, chain-of-title reports, and land use and tax assessor records, as available and appropriate, to identify past development history on and adjacent to the subject property relative to the possible use, generation, storage, release or disposal of hazardous substances. We attempted to identify uses of the subject property from the present back to the time that records show no apparent structures on the subject property, back to the time that the property was first used for residential, agricultural, commercial, industrial or governmental purposes, or back to 1940, whichever is earliest.
9. Review current United States Geological Survey (USGS) topographic maps to identify the physiographic setting of the subject property and provide a statement on the local geologic, soil and groundwater conditions based on our general experience and sources such as geologic maps and soil surveys.

10. Conduct a visual reconnaissance of the subject and adjacent properties to identify visible evidence of RECs.
11. Identify the source(s) of potable water for the subject properties and current heating and sewage disposal system(s) used at the subject property, if any, and their age if readily ascertainable.
12. Identify data gaps relative to the Phase I ESA study findings.
13. Provide a written summary of the Phase I ESA results and identified RECs along with our opinion and recommendations regarding the potential for contamination by hazardous substances at the subject properties and the significance of any data gaps identified.

1.2 Special Considerations

The Phase I ESA scope of services did not include an environmental compliance audit or an evaluation for the presence of lead-based paint, toxic mold, polychlorinated biphenyls (PCBs) in light ballasts, radon, lead in drinking water, asbestos-containing building materials, urea-formaldehyde insulation in on-site structures or debris or other potentially hazardous building materials. A hazardous building materials survey of the building will be conducted in the future. Our scope of services does not include an assessment of vapor intrusion into structures on the property per ASTM Standard E 2600-08.

A Phase II ESA including soil and groundwater sampling was performed in December 2011 and the results are provided in the Phase II ESA report under separate cover.

The content and format of this report meet the requirements of ASTM E 1527-05; however, for purposes of readability we use a table of contents for this report that is modified from the ASTM E 1527-05 Appendix X4 "Recommended Table of Contents."

1.3 Qualifications of Environmental Professional

Dana Carlisle is a registered Professional Engineer (PE) in Washington (#29634) and has at least 10 years of full-time experience doing Phase I ESAs. Dana is an Environmental Professional per 40 CFR Part 312. Jessica Robertson is a licensed geologist (LG) in Washington (#2570) and has at least 5 years of experience doing Phase I ESAs. Jessica is an Environmental Professional per 40 CFR Part 312. See Appendix D for resumes.

2.0 PROPERTY DESCRIPTION

2.1 Involved Parties

The subject properties are owned by Ernest Bakker. The parcels are leased by Barrier Certified Pre-Owned (CPO). We understand that City of Bellevue is planning to purchase the subject properties in connection with the expansion and rerouting of 120th Avenue NE.

2.2 Location, Legal Description and Setting

General information, property use(s) and environmental setting of the subject property area are summarized in Table I below. The location is shown relative to surrounding physical features in

Figure 1. The current layout of the subject properties and surrounding property uses are shown in Figure 2.

TABLE I. SUBJECT PROPERTY INFORMATION

Topographic Map	USGS, 7.5 minute Bellevue, Washington topographic quadrangle map dated 1983.
Quarter/Quarter, Section, Township and Range	SW quarter of SE quarter of Section 28, Township 25, Range 5, Willamette Meridian.
Address	The current address of the subject property is 11855 NE Bellevue-Redmond Road, Bellevue, King County, Washington. The former building on the west parcel was 11876 NE 8th Street. The former building on the east parcel was known as 12002 NE 8th Street.
General Location	Located at the southwest corner of the intersection of 120th Avenue NEt and NE Bellevue-Redmond Road.
Legal Description	Abbreviated legal description per King County iMAP: West parcel: BRIERWOOD PARK ADD POR OF 79 & E 8 FT OF 80 SLY OF BELLEVUE-REDMOND HWY & VAC RD & POR VAC RD ADJ LESS RD East parcel: BRIERWOOD PARK ADD W 72 FT OF POR SLY OF BELLEVUE REDMOND HSY INCL VAC RD LESS RD
Tax Parcel Number	West parcel: King County Parcel 1099100419 East parcel: King County Parcel 1099100420
Approximate Area	West parcel: 0.60 acres East parcel: 0.29 acres
Existing Use(s)	We parcel: Showroom for Barrier CPO car sales East parcel: Parking area for Barrier CPO car sales
Geologic Setting	Puget Lowland
Nearest Surface Water Bodies	Lake Bellevue (aka Lake Sturtevant) is located approximately 500 feet to the northwest.
Approximate Surface Elevation	Approximately 150 feet above mean sea level (msl; per King County iMAP).
Soil and Geologic Conditions	Based on results of recent soil borings at the subject properties, fill soil consisting of silt, sand and gravel is present to depths of between 4 and 13 feet bgs. Native soil encountered beneath the fill consists of stratified medium dense silty sand with occasional gravel typical of glacial outwash deposits. Occasional thin peat deposits are present in the upper portion of the native materials. Very dense glacial till generally underlies the outwash deposits to total depth explored.
Depth to Groundwater	Between approximately 5 and 16 feet bgs, as observed at the time of drilling during recent soil borings at the subject and nearby properties.
Inferred Direction of Shallow Groundwater Flow	Generally to the west or northwest, based on surface topography and previous reports for nearby property.

Our knowledge of the general physiographic setting, geology and groundwater occurrence in the vicinity of the subject property is based on our review of the maps listed above, previous reports for nearby property, and our general experience in the area.

2.3 Site Reconnaissance

2.3.1 Summary of Observations

A representative of GeoEngineers performed a visual reconnaissance of the subject property on December 15, 2011 and January 12, 2012. Property owner Ernest Bakker was interviewed by telephone in November 2011. Barrier CPO property managers Michael Mauk and Gregg Prokop, were identified as a "key site managers" with knowledge of the subject property and were interviewed via phone in December 2011. Interview responses from Mr. Mauk and Mr. Prokop are summarized in Section 4.0.

The west parcel is currently a paved parking lot used by the Barrier CPO (used car) sales facility. The east parcel is developed with one building used as a showroom and office for automobile sales. The Subject Properties are located in an area that is developed for commercial uses. Table II below summarizes conditions observed during our site reconnaissance. Section 2.3.2 contains additional details regarding conditions of potential environmental significance observed during our site reconnaissance and a summary list of potential RECs identified by this portion of our study. The approximate locations of the observed features discussed in this section are shown in Figure 2. Representative photographs of the subject property taken during our site reconnaissance are included in Figure 3.

TABLE II. SUMMARY OF SITE RECONNAISSANCE OBSERVATIONS

Features	Observed		Comment
	Yes	No	
Structures (existing)	X		The west parcel is currently undeveloped and entirely paved with asphalt. The east parcel is developed with one single-story concrete building used as a showroom and offices for used automobile sales.
Structures (evidence of former)	X		We observed a low concrete retaining wall along the west side of the west parcel which may have been an improvement associated with the former office building located on this parcel.
Heating/Cooling System	X		Showroom building is currently heated by natural gas and electric systems.
Floor Drains, Sumps or Drywells		X	The Barrier CPO showroom building is not used for vehicle service or repair.
Aboveground Storage Tanks (ASTs)		X	
Underground Storage Tanks (USTs) or Evidence of USTs		X	

Features	Observed		Comment
	Yes	No	
Drums or Other Containers	X		Three 55-gallon drums of soil cuttings from the recent Phase II ESA were temporarily stored along the east side of the building at the time of our site reconnaissance.
Chemicals or Hazardous Materials (other than *de minimis* quantities of cleaning products)		X	
Evidence of Leaks, Spills or Releases Surrounding ASTs, USTs and/or Chemical Storage Areas		X	
Stained or Corroded Floors, Walls or Drains (other than apparent water stains or minor oil stains on pavement from parked vehicles)		X	
Pipes of Unknown Origin or Use		X	
On-site Septic System		X	
Sewage Disposal System	X		The building is connected to the municipal sewer system.
Potable Water Supply	X		The building is connected to the municipal water supply.
Solid Waste Refuse Dumpsters		X	
Hydraulic Hoists		X	
Oil/Water Separators		X	Parking lot catch basins may contain oil/water separators; however, we did not observe any at the time of our site reconnaissance.
Discolored or Stained Soil or Vegetation Potentially from Hazardous Substances		X	
Hazardous Waste Disposal Areas		X	
Uncontained Debris, Refuse or Unidentified Waste Materials		X	
Standing Water or Other Liquids		X	
Catch Basins and Stormwater Drainage	X		Standard municipal catchbasins are located in asphalt parking areas of the Subject Properties. Catchbasins are reportedly connected to the municipal stormwater system which reportedly discharges to Lake Bellevue.
Pits/Ponds/Lagoons		X	
Waste or Wastewater Discharges		X	

Features	Observed		Comment
	Yes	No	
Unusual Odors		X	
Stressed Vegetation		X	
Fill Material	X		Fill is present on the property as described in more detail in the Phase II ESA report.
Water Wells (agricultural, domestic, monitoring)		X	
Pad-Mounted Transformers		X	Underground transformers may be located in adjacent sidewalks/right-of-way.
Pole-Mounted Transformers		X	
Other Conditions of Environmental Concern		X	

2.3.2 Findings

Potential RECs were not identified by this portion of the study.

2.3.3 Data Gaps

Data gaps were not identified by this portion of the study.

2.4 Adjacent Property and Vicinity Observations

2.4.1 Summary of Observations

We viewed properties located adjacent to and surrounding the subject property on December 15, 2011 and January 12, 2012 from accessible public rights-of-way and the Subject Properties. We did not enter adjacent properties or buildings except those evaluated for the City of Bellevue for the 120th Avenue widening project. The subject property generally is situated in an area that is developed with commercial uses. Section 2.4.2 contains additional details regarding conditions of potential environmental significance observed during our site reconnaissance and a list of potential RECs identified by this portion of our study. Table III below outlines adjacent land uses and pertinent observations with respect to conditions that could pose a REC on the subject property. Figure 2 shows adjacent property uses and locations in relation to the subject property.

TABLE III. ADJOINING STREETS AND ADJACENT PROPERTIES OBSERVATIONS

Direction	Adjoining Street	Position Relative to Subject Property[1]	Adjacent Property and Use	Comments
North	NE Bellevue Redmond Road	Down to Crossgradient	Barrier Mercedes west of 120th Avenue NE Barrier Porsche east of 120th Avenue NE	Both of these businesses have interior vehicle service and repair facilities. Barrier Porsche is not listed as a known or suspect contaminated site in regulatory agency databases. See Section 3.0 for more information regarding Barrier Mercedes.
West	None	Downgradient	Paved Parking lot also used by Barrier CPO	Former service station and car rental. One UST remains on this property. Three groundwater monitoring wells are located on this property related to prior assessment activities.
East	None	Upgradient	Office buildings	
South	NE 8th Street	Crossgradient	Shell gas station and retail strip mall (grocery and restaurants)	

Note:

[1] The inferred shallow groundwater flow direction in the vicinity of the subject property is toward the west or northwest, as described in Section 2.2.

2.4.2 Findings

One potential REC was identified by this portion of the study:

- The adjacent property to the west is former service station and car rental facility with one remaining UST (see Section 2.5 for more information). This property is also a listed contaminated site in Ecology databases. This property is considered a potential REC for the Bakker subject properties based on proximity and the potential for contaminant migration from past releases.

The northern adjacent Barrier Porsche is not considered a REC because it is not a listed contaminated site and based on information regarding the use of best management practices at this facility for use, storage and handling of waste oil and other hazardous substances related to automobile service and repair. See Section 2.5 for more information.

The other adjacent property uses to the north and south with auto service, repair and fueling are further discussed in Section 2.5 and based on the information provided in Section 2.5, there is a low potential for historic releases at these facilities to have migrated to the subject property in our opinion and therefore these businesses are not considered RECs for the subject properties.

2.4.3 Data Gaps

Data gaps were not identified by this portion of the study.

2.5 Previous Reports

2.5.1 Summary of Previous Reports

This section contains a summary of environmental conditions on the subject property and adjacent or nearby properties based on our review of previous environmental reports. The sources of information for this section include Ecology and City of Bellevue files for listings identified in Section 3.0, and the "Hazardous Materials Discipline Report" for the 120th Avenue NE Corridor Project (*"NE 4th Street/120th Avenue NE Corridor Project, Hazardous Materials Discipline Report"* prepared by Shannon & Wilson, Inc. for City of Bellevue dated July 29, 2011) and its appendices of prior reports.

Previous environmental reports for the subject property of this Phase I ESA are listed in Section 7.0.

The 2011 Discipline Report was prepared for the 120th Avenue NE corridor and presents the findings from a limited review of historical records, Ecology files, and a drive-by "Windshield Survey" for the sites along the corridor. Based on this information, the Discipline Report screened sites along the corridor for potential environmental effects to the 120th Avenue NE widening project and the screened sites were ranked for potential risk to the project. The Discipline Report identified the east subject property parcel, "Former Bakker's Fine Dry Cleaning Plant," as "High Risk" and the west subject property parcel, "Former Dry Cleaner Office Building," as "Moderate Risk."

2.5.1.1 EAST PARCEL SUBJECT PROPERTY: FORMER BAKKER'S FINE DRY CLEANING PLANT

The Former Bakker Fine Dry Cleaning Plant property is the east parcel of the Subject Property. This site was originally occupied by a dry cleaning facility from 1959 until the early 2000s. The site is now used as a showroom for Barrier Pre-Owned cars. Relevant information in the previous environmental reports and Ecology and City of Bellevue files are included in Appendix C and summarized as follows:

- Four USTs, presumably installed in the late 1950s or early 1960s, were removed from the site in 1989. The USTs were used to store Stoddard solvent (mineral spirits, 6,000-gallon), diesel fuel (2,000-gallon), distillation (presumed to be spent solvents, 400 or 500 gallons and shown as inactive as of 1989), and solvents (100 or 200 gallons and shown as in active as of 1989). The diesel UST was presumably used for heating oil and the building was converted to natural gas heat at the time. The remaining USTs were used in connection with dry cleaning activities. The four USTs were excavated from a location northeast of the existing building. The tanks were reported to be in good condition with no corrosion, holes or defects. Ten soil samples from the limits of the excavation were analyzed for petroleum by EPA Method 418.1 and one

soil sample was analyzed for chlorinated volatile organic compounds (VOCs) by EPA Method 8010. Analytes were either not detected or detected at concentrations less than applicable cleanup levels in place at the time the work was completed.

- A broken 4-inch tile drain line, which was connected to floor drains and the Stoddard tank room within the building, was observed to be discharging into the UST excavation. Anecdotal information indicated that "accidental" spills of Stoddard had occurred in the past at the floor drain location.
- Water seepage reported as "minor" was identified in the UST excavation at approximately 8 feet bgs and "discoloration or iridescent sheens" were reportedly observed on the water surface. The water and water-impacted backfill were reported removed during UST excavation activities and additional seepage was not observed. Groundwater samples were not obtained in connection with the 1989 UST removal and broken drain line cleanup activities.
- The 1989 UST removal report concluded that "soil and groundwater proximal to the UST installation were not significantly contaminated" and that "no further characterization...is required."
- One new 6,000-gallon Stoddard solvent (mineral spirits) UST was installed in 1989 in the same location as the four removed USTs; the tank was removed in 1999. Concentrations of petroleum- and solvent-related contaminants in soil samples from the limits of the 1999 UST excavation were reportedly less than the Model Toxics Control Act (MTCA) Method A cleanup level of 200 parts per million.
- The 1999 UST removal report concluded only that results of the soil samples collected from the excavation area contained concentrations below MTCA Method A cleanup guidelines and did not make any additional conclusions or recommendations regarding additional work at the property.
- Solvents spills associated with poor housekeeping practices were reported for the property. The Discipline Report concluded, "this site is considered high risk due to the relatively high expense of remediating solvent contamination and because the City would acquire the site."

Ecology's files for this property as of October 2011 did not contain additional environmental assessment or cleanup reports for the subject property beyond the report findings presented above; however, Ecology files for this property contain one significant change relative to the regulatory status for this property as of July 2011. In October 2011, Ecology designated the former Bakker's Fine Dry Cleaning site as "Reported Cleaned Up" (RCU). This designation was based on the prior cleanup action reports submitted to Ecology as part of the independent cleanup action on the property. Please see Ecology's recent email (Appendix C) regarding this designation. We understand Ecology will be issuing an administrative No Further Action letter for this property in the near future. The administrative No further Action (NFA) is different than an NFA Opinion Letter that Ecology issues for sites appropriately cleaned up and entered into Ecology's Voluntary Cleanup Program (VCP). It is our understanding that the prior UST removal and site assessment data were not formally reviewed or evaluated by Ecology and the updated designation as "Reported Cleaned Up" reflects only the conclusion in the reports submitted.

2.5.1.2 WEST PARCEL SUBJECT PROPERTY: FORMER DRY CLEANER OFFICE BUILDING, 11876 NE 8TH STREET

The Former Dry Cleaner Office Building property is the west parcel of the Subject Property (see Figure 2). This property was used as a bank in 1961 and later used as an office building related to the dry cleaning business whose operations were on the adjacent eastern parcel. No dry cleaning is known to have been conducted at the office building property; however, poor housekeeping practices on the adjacent Former Bakker's Dry Cleaning Plant property were documented and a drain pipe was identified in the past to have discharged solvent-contaminated waste onto the office building property during previous environmental work associated with another property (the west-adjacent former gas station site). The Discipline Report concluded that the dry cleaner office building property is a "moderate risk to the project because it was associated with a contamination source property, has known contamination exiting the western property boundary, and because the City would acquire the site."

2.5.1.3 ADJACENT AND NEARBY PROPERTIES

The Discipline Report for the 120th corridor also included information regarding several adjacent and nearby properties as outlined below. The Discipline Report includes a statement regarding the potential risk posed by each of these properties in relation to the 120th Avenue widening project. However, with respect to this Phase I ESA for the Bakker-owned subject properties, we have included our opinion in Section 2.5.2 as to whether any of these properties would pose a risk of contamination migration and therefore a REC for the Bakker-owned subject properties.

Former Service Station and Car Rental, 11866 NE 8th Street

The Former Gas/Service Station site is located immediately west of the Subject Property, approximately as shown in Figure 2. This property is the subject of a separate Phase I ESA Report for the City of Bellevue. Information regarding the Former Service Station and Car Rental site in the Discipline Report and Ecology files included the following:

- The site was occupied by a gasoline station from at least 1956 through at least 1975 (Gulf Oil, Fletcher Oil and Dubose, Inc.). The property was used by Avis Rent-A-Car as an automobile sales lot beginning in 1976 through approximately 1991. The site is identified on Ecology UST's, Leaking UST, and Independent Cleanup Report databases as the "Avis Rent-A-Car" site. Based on the UST database information, one UST was removed in 1996 and a second UST was "temporarily closed in place."
- The original service station USTs were located either north or west of the building and appeared to have been removed prior to 1976, based on test pit exploration and remedial excavation conducted in the early 1990s on behalf of Avis.
- Petroleum-contaminated soil and groundwater were identified in 1989 during the removal of one 5,000-gallon gasoline UST and one previously undocumented 500-gallon waste oil UST, both located south of the on-site building. Approximately 19 tons of contaminated soil were excavated and reportedly removed for off-site disposal. Petroleum- and benzene-contaminated soil was left in place beneath the building and beneath an underground utility corridor east of the building. A 1989 letter from Ecology recommends "removing the remaining contaminated soil at any time it becomes feasible."

- A new 5,000-gallon fiberglass UST was reportedly installed in 1989 in the same location as the removed gasoline UST.
- Six monitoring wells were installed on the parcel in 1991 and approximately eight test pits were completed west and north of the previous rental car building. The monitoring well and test pit locations are shown in the Key Maps from Prior Reports, presented at the beginning of Appendix C. The following information is based on the reports documenting the 1991 characterization activities:
    - No remnant USTs from the first generation service station on the property were encountered in the suspect UST areas north and west of the building. Pea gravel, indicative of excavation backfill, was encountered in test pits north and west of the building in the suspect UST locations.
    - Diesel-contaminated soil was identified north of the building. Approximately 130 cubic yards of the impacted soil was removed and transported to a landfill for disposal. Residual soil with diesel (63 milligrams per kilogram [mg/kg]) was left along the northern extent of the excavation(SS-3) at a depth of about 5.5 feet bgs.
    - An elevated concentration of mineral spirits (1,400 mg/kg) were detected in a soil sample (SS-8) obtained from the northeast corner of the Triangle Parking Lot parcel at a depth of 6 feet bgs.
    - Groundwater in the north portion of the site contained gasoline, mineral spirits (Stoddard solvent), and benzene at concentrations greater than applicable cleanup levels. The mineral spirits contamination was inferred to have migrated from the dry cleaning facility (Bakker Fine Dry Cleaning Plant) to the east.
    - Elevated concentrations of dry cleaning solvents PCE and TCE, greater than applicable cleanup levels, were detected in a water sample obtained from a drain pipe that was discovered in the excavation and discharged onto the northeast corner of the Triangle parking lot property. The pipe reportedly was connected to floor drains in the dry cleaning building to the east.
    - Concentrations of benzene, ethylbenzene, toluene, xylenes (BETX) greater than the MTCA groundwater cleanup levels in place in 1991 were detected in the 1991 groundwater samples from MW-1, MW-3 and MW-6.
    - Concentrations of PCE and TCE greater than the MTCA Method A cleanup levels were detected in one of the 1991 groundwater samples from a monitoring well (MW-1) on the Triangle parking lot. TCE and PCE were not detected in the MW-3 and MW-6 groundwater samples.
    - Two of the monitoring wells installed in 1991 (likely MW-1 and MW-5) are visible on the property currently. The four other previously installed monitoring wells were either paved over or decommissioned.
- The site building was demolished in 1999. The remaining 5,000-gallon UST on the property is listed as closed-in-place in Ecology's UST database.

The Discipline Report concluded that the gas station site was "considered a high risk to the project because: 1) known gasoline and diesel-range petroleum, benzene, mineral spirits, and chlorinated

solvent contamination is present and may be migrating off-site; 2) the former gasoline USTs may still be present on site; and 3) the City would acquire this property."

Barrier Porsche, 12000 NE Bellevue-Redmond Road

The Barrier Porsche site is located approximately 80 feet north (crossgradient) of the subject property across NE Bellevue Redmond Road. This property is the subject of a separate Phase I ESA Report for the City of Bellevue. Information regarding the Porsche Property in the Discipline Report included the following:

- The site building was constructed in 1969 and was occupied by a bakery until 1996 and remodeled as a car showroom in 2003.
- The Discipline Report concluded that the Porsche Property was "considered a moderate risk to the project because of historical and current use of petroleum products on the site, 10 to 15 feet of excavation is anticipated along the western boundary of this property for a cut wall, and the City anticipates acquiring the property."
- The Discipline Report identifies that the building was historically heated by oil; however, our research for the property as discussed in Section 4.0 did not confirm historic oil heat use at the site. Tax archive records for the property and key persons interviewed for this report indicate that the building originally used natural gas and electric heating systems.

Barrier Mercedes, 11950 NE Bellevue-Redmond Road

The Barrier Mercedes site is located approximately 100 feet northwest (downgradient) of the subject property across NE Bellevue Redmond Road and 120th Avenue NE, approximately as shown in Figure 2. The current use of the property includes an automotive service garage. The facility is listed on Ecology's Leaking UST, UST, and Independent Cleanup Report databases. A leaking UST was identified in 1994 and reportedly cleaned up in 1995. In 1996, two additional USTs were removed. Releases of waste oil from broken piping beneath the service garage floor were identified and partially cleaned up in 1994 including removal of approximately 650 gallons of free product (waste oil). Three monitoring wells were installed in 1995 in the service garage area several hundred feet northwest of the subject properties to evaluate the vertical extent of impacted soil and to evaluate whether groundwater was impacted from the waste oil release. The direction of shallow groundwater flow beneath the Barrier Mercedes property was to the northwest, based on data from the 1995 monitoring wells. Localized petroleum-related impacts to soil and groundwater were identified; however, the impacted locations are a several hundred feet downgradient of the subject properties. Based on the reported cleanup complete status of this facility, because the cleanup area is not directly within the road widening area, and because this property is downgradient of the subject property and the road corridor, the Discipline Report concluded that this facility was low risk.

Shell Service Station, 12001 NE 8th Street

The Shell Service Station site, situated approximately 100 feet south (crossgradient) of the subject property across NE 8th Street, has been an operating gas station since 1972. The site is listed on Confirmed and Suspected Contaminated Sites List (CSCSL), Leaking Underground Storage Tank

(LUST), UST, and VCP databases. Five fuel USTs were removed in this site in 1996 and three fuel USTs are currently in use at this site. Soil and groundwater contamination resulting from releases from the removed USTs were identified by the early 1990s. Petroleum-contaminated soil and groundwater may remain along the west boundary of this site. Based on this information and that approximately 3 feet of excavation along the west side of the site was proposed for the corridor, the Discipline Report concluded that this site was considered moderate risk.

Accutint, 12014 NE Bellevue-Redmond Road

The Accutint facility is located approximately 100 feet northeast (crossgradient) of the Porsche Property. The site has been occupied by at least three auto repair shops since 1969 and petroleum products were likely used and stored at the site. This facility is not listed on a database that would indicate presence of contamination and was considered low risk to the corridor.

Midas Auto Repair, 12020 NE Bellevue-Redmond Road

The Midas Auto Repair site is located approximately 120 feet northeast (crossgradient) of the Porsche Property. The site has been occupied by at least three auto repair shops since 1969 and petroleum products were likely used and stored at the site. The site is not listed on a database that would indicate presence of contamination and was considered low risk to the corridor.

Former VIP Cleaners, 12015 NE 8th Street

The former VIP Cleaners site is located approximately 100 feet south (crossgradient) of the Subject Property across NE 8th Street. The site was occupied by a dry cleaner for only a limited time (1985) and was reported to likely be a drop-off location only. The Discipline Report concluded it is therefore unlikely that widespread solvent contamination is associated with this site. The site is not listed on databases that would indicate presence of contamination and therefore this historical business was considered low risk to the corridor.

Former Priority Publishers, 12000 NE 8th Street

The former Priority Publishers site is located adjacent to the southeast (upgradient) of the Subject Property. The site was occupied by a printing company for only a limited time (1985). The Discipline Report concluded it is therefore unlikely that widespread solvents and metals contamination is associated with this site. The site is not listed on databases that would indicate presence of contamination and therefore this historical business was considered low risk to the corridor.

Office Building, 12011 NE Bellevue-Redmond Road

The Office site is located adjacent northeast (upgradient) of the Subject Property. The office building site was formerly occupied by a residence heated by oil. Based on distance to the corridor and site redevelopment, and because this site is not listed on databases that would indicate presence of contamination, the Discipline Report concluded that the site was considered low risk to the corridor.

2.5.2 Findings

The following potential RECs were identified by this portion of the study:

- Past use of the Subject Property (Former Bakker Fine Dry Cleaning) as a dry cleaning plant is considered a REC for both parcels.
- Past use of the west-adjacent site as a gas station and rental car facility and the presence of residual petroleum products in the soil is considered a REC for the subject property.

Except as noted above, the other adjacent and nearby sites of potential concern identified in the 2011 corridor study Discipline Report are not considered RECs to the Subject Properties based on one or more of the following: the distance between these properties and the subject property makes contaminant migration unlikely, the down- or crossgradient location in relation to the subject properties makes contaminant migration unlikely, documentation of prior cleanup actions performed at these sites indicates contaminant migration is unlikely, or because the sites are not listed as known or suspected contaminated sites.

2.5.3 Data Gaps

Data gaps were not identified by this portion of the study.

3.0 ENVIRONMENTAL RECORDS REVIEW

3.1 Database Search

GeoEngineers reviewed the results of a search of pertinent environmental regulatory lists and databases for current or previous facilities listed at addresses located within ASTM-specified distances from the subject property. The search was performed on January 11, 2012. The information reviewed was provided by a subcontracted regulatory list search service, Environmental Data Resources, Inc. (EDR). The EDR report is presented in Appendix B. The report includes details regarding the listed facilities identified and maps showing the approximate locations of the listed facilities relative to the subject properties.

GeoEngineers reviewed the search results for listings pertaining to the subject properties. GeoEngineers also reviewed EDR listing of database entries that could not be mapped by EDR because of insufficient addresses (orphans). Off-site facilities found within the specified distances from the subject property were evaluated for potential impact to the subject property.

The eastern parcel of the subject property was listed as "Bakker's/Coit on several Ecology databases. Table IV below summarizes the listed facilities that in our opinion could pose a REC to the subject property. Other listed facilities identified in Appendix B either are located a significant distance from the subject property or are located in an inferred down- or crossgradient position relative to the subject property and are unlikely to pose a potential environmental concern to the subject property, in our opinion.

TABLE IV. SUMMARY OF REGULATORY DATABASE SEARCH LISTINGS OF POTENTIAL ENVIRONMENTAL CONCERN

Location	Listed Business	Listed Address	Regulatory Database	Description
Subject Property	Bakkers/Coit Inc.	12002 NE 8th Street/11855 NE 8th Street	Inactive Dry Cleaners, UST, CSCSL No Further Action (CSCSL NFA)	See Section 2.5.
Adjacent West	Avis Car Rental aka Barrier Motors UST	11969 NE Bellevue-Redmond Road EDR also identifies this site as 11968 NE Bellevue-Redmond Road, which appears to be an error.	UST, Leaking UST (LUST), Independent Cleanup Report (ICR), Confirmed and Suspected Contaminated Sites List (CSCSL)	See Section 2.5.
Nearby approximately 100 feet northwest (downgradient) across NE Bellevue-Redmond Road	Barrier Motors Mercedes	11950 NE Bellevue-Redmond Road	UST, LUST, ICR, CSCSL	According to the EDR report, two USTs were removed from the site in 1996 and petroleum products related to release from the USTs was cleaned up in the mid-1990s. See Section 2.5.
Nearby approximately 80 feet south (crossgradient) across NE 8th Street	Texaco #0022 aka Shell Station 120546	12001 NE 8th	Spills, ICR, UST, LUST, VCP, CSCSL	According to the EDR report, five USTs were removed from the site in the mid-1990s and four USTs are currently operational at the site. Releases of petroleum and related compounds were identified in the early 1990s and cleanup and monitoring activities have been completed at the site since that time. See Section 2.5.

3.2 Review of Regulatory Files

We reviewed Ecology's files for the above-listed properties on November 10, 2011. Findings are incorporated into Section 2.5.

3.3 Review of Areawide Contamination Reports

We conducted a search of Ecology and EPA websites for readily available information (publications and reports) that may concern areawide soil and groundwater contamination on or adjacent to the

subject property. Areawide contamination reports pertaining to the subject property vicinity were not identified.

3.4 Findings

Additional RECs were not identified by this portion of the study. For clarification, it is important to note that despite Ecology's recent "Reported Cleaned Up" designation for the former Bakker's Fine Dry Cleaning site, it is our opinion that residual contaminants may remain on this property and that contaminants may historically have migrated off-site and impacted soil, groundwater and/or soil vapor conditions on the two parcels to the west as well as nearby rights-of-way (NE Bellevue Redmond Road). Therefore releases associated with the former dry cleaning site are considered a REC.

3.5 Data Gaps

Data gaps as defined by the AAI Rule and ASTM standard were not identified by this portion of the study. For clarification, we note that Phase I ESA data gaps are defined differently than the terminology "site characterization data gaps" used in Phase II ESA and Remedial Investigation (RI) reports. There are site characterization data gaps in connection with the subject properties in our opinion because the extent of contaminant migration from releases associated with the dry cleaner plant has not been fully evaluated.

4.0 PROPERTY HISTORY

4.1 Historical Resources

Our understanding of the history of the subject property is based on a review of the information from the historical resources listed in Table V and interviews with the individuals listed. Selected historical research documents are included in Appendix B.

TABLE V. HISTORICAL RESOURCES REVIEWED

Description	Provider or Interviewee	Dates of Coverage or Dates of Knowledge of the Property	Date Reviewed or Contacted	Comment (See Section 4.2 for findings)
Historical Aerial Photo-graphs[1]	Environmental Data Resources, Inc. (EDR)	1965, 1977, 1981, 1985, 1990, 2005, and 2006	01/12/2012	
Historical Aerial Photo-graphs[1]	King County iMAP	1936, 1998, 2000, 2002, 2005, and 2007	10/14/2011	
Historical Fire Insurance Maps	EDR	None	01/11/2012	Sanborn maps do not cover the subject property vicinity.

Description	Provider or Interviewee	Dates of Coverage or Dates of Knowledge of the Property	Date Reviewed or Contacted	Comment (See Section 4.2 for findings)
Historical Tax Assessors Records	Washington State Archives	1938 to 1973	10/14/2011	Archived King County assessor records for the subject property were obtained from Puget Sound Regional Archives.
Historical City Directories	EDR search at public libraries	1966, 1972, 1977, 1983, and 1996	01/12/2012	
Historical City Directories	GeoEngineers search at Puget Sound Regional Archives	1983 to 1984	11/10/2011	
Historical Topographic Maps	EDR search	1897, 1950, 1968, 1973, and 1983	01/11/2012	
Historical City Atlases	GeoEngineers search of Kroll Atlases	Circa 1940s, circa 1960, and circa late 1990s	11/10/2011	
Building Department Records	City of Bellevue Permit Lookup Online	Approximately 2000 to recent	01/11/2012	
Building and Fire Department Records	City of Bellevue, Kristina Thurstonson, City of Bellevue Public Disclosure Analyst	Recent	04/17/2012	Ms. Thurstonson checked Fire Department records pertaining to the subject property. According to Ms. Thurstonson, no records regarding USTs or conditions of environmental concerns are on file for the subject property.
Commitment for Title Insurance	First American Title	March 9, 2012	5/11/2012	
Interview	Gregg Prokop, Barrier Motors manager and 'key site manager'	Approximately 1980 to present	12/16/2011	
Interview	Michael Mauk, Barrier facilities manager and 'key site manager'	Approximately 1981 to present	12/14/2011 and 01/17/2012	

Description	Provider or Interviewee	Dates of Coverage or Dates of Knowledge of the Property	Date Reviewed or Contacted	Comment (See Section 4.2 for findings)
Interview	Ernest Bakker, Subject Property owner	Approximately 1981 to present	11/21/2011	
Interview	Seattle-King County Health Department	Recent	02/28/2012	SKCHD indicated they did not have files or records concerning the subject property.

Note:

[1] The scale of the photographs reviewed allowed for an interpretation of general property development/configuration, such as identifying most structures, roadways and clearings. However, the scale of the photographs did not allow for identification of specific property features, such as fuel pumps, wells or chemical storage areas on the subject property, if any.

4.2 Historical Property Ownership and Use Summary

The available historical sources indicate that Ernest Bakker purchased both subject property parcels from Simon Baker in 1981. Based on ownership information included on archived tax assessor documents, the property was owned by Bob Hagen between the 1950s and 1970s.

The subject property appears undeveloped and as a portion of a grassy field in a 1936 aerial photograph, with a driveway extending across the east parcel in generally a north-south orientation between 120th Avenue NE and NE Bellevue-Redmond Road. The first identified developed use of the subject property is the construction of the existing building on the east parcel in 1959. Archived tax assessor documents for the building indicate it was constructed as a dry cleaning plant, with building space for cleaning and finishing, washing and mechanical space, and a boiler room. The building was originally heated by an oil-burning system located in the northwest corner of the building. The building operated as a dry cleaner from the late 1950s into the 1990s. In the early 2000s, the building was extensively renovated for use as an auto showroom by Barrier Motors.

Tax archive records indicate a small wood-frame building was built on the west parcel in 1961 for use as a bank. The building was heated with electric baseboards. By the late 1980s, the building was used as an office for the east-adjacent dry cleaning plant. The building is visible in aerial photographs dated 1965 through 2000. The office building was demolished in approximately 2001 when the property use was established as a parking lot. A portion of the original building foundation remains visible in the 2002 aerial photograph but it is no longer visible and the property appears fully paved in subsequent aerial photographs.

Please refer to Section 2.5 for a discussion regarding USTs and subsurface conditions on the subject properties.

4.2.1 Key Person Interviews

We interviewed Gregg Prokop, Barrier Motors manager, and Michael Mauk, Barrier Motors facilities manager, regarding the subject property. Mr. Prokop and Mr. Mauk do not have any additional information regarding underground storage tanks at the subject property beyond that discussed in Section 2.5 and are not aware of any hazardous materials use, storage, spills, or disposal at the

subject property. According to Mr. Mauk, no auto repair or service activities are completed at the subject property and the property is used by Barrier Motors for used car sales only. They additionally are not aware of any information regarding past assessment information at the Subject Properties.

According to Mr. Bakker, property owner, previous cleanup (overexcavation) had been conducted at the subject property building in the vicinity of former USTs, but additional information beyond that presented in Section 2.5 was not available. He had no knowledge of existing contamination, USTs, or wells on the properties.

4.3 Adjacent Properties

Adjacent properties generally were developed for commercial purposes beginning in the 1940s and 1950s. Additional environmental information for several nearby and adjacent properties is included in Section 2.5 above.

North. The existing Barrier Mercedes sales and service facility to the north across NE Bellevue Redmond Road was built in sections between the 1970s and 1990s. The building has been used by Barrier Motors since at least 1985. The property appears undeveloped in 1936 and 1965 aerial photographs.

The existing Barrier Porsche facility to the north was built in 1969 and operated as a bakery until the 1990s. Barrier has operated a Porsche new car sales and service facility from the property beginning in the early 2000s.

East. Adjacent office buildings to the east were built in the 1980s. These buildings replaced small single-family homes built in the 1940s or 1950s.

West. The existing parking lot adjacent to the west formerly contained a small gas station in the 1950s and 1960s which was replaced by a car rental facility in the 1970s. The rental facility was demolished in the early 2000s. The property has been used by Barrier Motors for used car sales parking since approximately that time.

South. The existing Shell service station to the south across NE 8th Street was built in 1990 and replaced an older station that was built in the early 1970s. The property appears undeveloped in aerial photographs dated 1936 and 1965.

4.4 Environmental Liens or Property Use Restrictions

During the course of our research, we did not find that environmental liens had been filed against the subject property. Activity Use Restrictions, Restrictive Covenants or Environmental Covenants were not identified on the title report reviewed.

4.5 Information Provided by User/User Obligations

We did not receive any responses to a user questionnaire, a copy of which is provided in Appendix A. The questionnaire can be used to obtain user-provided information (for example, title records, environmental liens, specialized knowledge of the subject property, etc.) that may specify findings/

conditions that may pose potential environmental concerns or RECs relative to the subject property. The absence of this information represents a data gap.

4.6 Findings

Additional RECs beyond those previously noted in prior sections of this Phase I ESA were not identified by this portion of the study.

4.7 Data Gaps

One data gap was identified by this portion of the study:

- We did not receive a copy of the completed User Questionnaire for the Subject Property. This data gap is not considered significant for the purposes of this Phase I ESA.

5.0 CONCLUSIONS AND RECOMMENDATIONS

GeoEngineers has performed a Phase I ESA in general conformance with the scope and limitations of ASTM Practice E 1527-05 of the two parcels owned by Ernest Barrier located at 11855 NE Bellevue-Redmond Road in Bellevue, Washington and used by Barrier Pre-Owned Sales. The City of Bellevue plans to purchase these two properties for the NE 8th to NE 12th segment of the 120th Avenue NE widening project. Any exceptions to, or deletions from, this practice are described in Section 1.2 of this report. This assessment has revealed no evidence of RECs in connection with the subject property with the exception of the following:

- Past use of the subject property as a dry cleaning plant is considered a REC for both properties. The rationale for this opinion includes: 1) prior environmental assessments of the Triangle Parking Lot property to the west identified concentrations of dry cleaning solvents PCE, TCE, and mineral spirits (Stoddard solvent) in soil and/or groundwater with the likely source being releases from the former dry cleaning plant; 2) potential for migration of dry cleaning solvents is high due to their volatile and mobile nature, long history of use (more than 40 years) and anecdotal information of poor housekeeping (spills) at the dry cleaning plant; 3) petroleum-related constituents were detected during UST removal activities in 1989, and 4) available environmental reports (UST removals) for the property do not include a complete assessment or delineation of soil and groundwater conditions in our opinion. Releases of dry cleaning solvents also pose a vapor intrusion REC for indoor air or confined spaces on the subject properties based on the potential for residual volatile contaminants in soil, groundwater and/or soil vapor. We note that the recent "Reported Cleaned Up" designation by Ecology in October 2011 for the former Bakker's Fine Dry Cleaning Plant may meet the ASTM definition of "Historic REC" but because contaminants from the dry cleaner plant apparently migrated to the western adjacent properties and because of the potential for residual contaminants that could affect groundwater or indoor air, we have identified the former dry cleaner plant as a REC in this report.
- Past use of the west-adjacent property as a gas station and rental car facility is considered a REC for the subject property parking lot parcel based on the potential for releases of petroleum and related compounds to have impacted soil and/or groundwater. Releases of volatile

petroleum-related constituents also may pose a vapor intrusion REC for indoor air or confined spaces on the subject properties.

A geophysics study and Phase II ESA to evaluate soil and groundwater conditions within the planned future right of way of 120th Avenue Northeast has been completed and is reported separately.

6.0 LIMITATIONS

This Phase I ESA has been prepared for use by the City of Bellevue and PB. GeoEngineers has performed this Phase I ESA of two parcels owned by Ernest Barrier located at 11855 NE Bellevue-Redmond Road in Bellevue, Washington, in general accordance with the scope and limitations of Contract Amendment No. 2 to Agreement No. PW-R164 ASTM E 1527-05, Standard Practice for Phase I ESAs and EPA's Federal Standard 40 CFR Part 312 "Standards and Practices for All Appropriate Inquiries (AAI)."

Within the limitations of scope, schedule and budget, our services have been executed in accordance with the generally accepted environmental science practices for Phase I ESAs in this area at the time this report was prepared. No warranty or other conditions, express or implied, should be understood.

Please refer to Appendix E titled "Report Limitations and Guidelines for Use" for additional information pertaining to use of this report.

7.0 REFERENCES

ASTM International (ASTM) Standard E 1527-05 for Phase I ESAs.

Ecology Northwest Regional Office. LUST Leak, Bakker's Fine Dry Cleaning, 12002 NE 8th Street, Bellevue. Memo to Paul O'Brien from D.A. Davidson dated August 10, 1989.

Ecology Northwest Regional Office. Avis Rent-A-Car Underground Storage Tank. Letter to Perkins Coie from Joseph M. Hickey, UST Site Inspector dated July 20, 1989.

Environmental Data Resources, Inc. (EDR). 2012. EDR Radius Map report dated January 11, 2012 (comprehensive environmental database report, including Ecology and EPA databases).

Fuel Tank Installation Co., Inc. Underground Storage Tank Removal and Soil Sample Summary Report Re: Bakker's Fine Drycleaning, 12002 NE 8th Street, Bellevue, Washington. Dated October 18, 1999.

GeoTech Consultants. Closure Report, Multiple Underground Storage Tanks, 11855 Northeast 8th, Bellevue, Washington. Prepared for Bakker's Fine Dry Cleaning, dated August 17, 1989.

King County iMAP aerial photographs dated 1936, 1998, 2000, 2002, 2005, and 2007.

King County Tax Assessor records provided by Puget Sound Regional Archives dated 1930s-1970s.

Kroll City Atlases reviewed at Puget Sound Regional Archives, dated circa 1940s, circa 1960s, and circa late 1990s.

Landau Associates Inc. Final Report, Underground Storage Tanks Removal, Avis Rent a Car System Inc, 11969 Bellevue-Redmond Road, Bellevue, Washington. Prepared for Perkins Coie dated June 2, 1989.

Pacific Northern Environmental Corp dba Petroleum Services Unlimited Inc.. Limited Site Investigation Summary Letter, Avis Sales Lot, 11969 NE Bellevue Redmond Road, Bellevue, Washington. Prepared for Perkins Coie, dated July 18, 1991.

Pacific Northwest Environmental Corp dba Petroleum Services Unlimited.. Report on Groundwater Monitoring and Investigation and Cleanup of Petroleum Contaminated Soils at the Avis Rent-a-Car Sales Lot, 11969 NE Bellevue Redmond Road, Bellevue, Washington. Prepared for Perkins Coie, dated December 12, 1991.

Perkins Coie. Avis Rent-A-Car Underground Storage Tank. Letter to Joe Hickey, Ecology dated June 12, 1989.

Perkins Coie. Avis Rent-A-Car Property in Bellevue WA. Letter to Joe Hickey, Ecology dated December 17, 1991.

Polk City Directory listings provided by EDR, dated 1966, 1972, 1977, 1983, and 1996.

Shannon & Wilson, Inc. NE 4th Street/120th Avenue NE Corridor Project, Hazardous Materials Discipline Report. Prepared for City of Bellevue, dated July 29, 2011.

United States Geological Survey (USGS) topographic maps for Mercer and Bellevue, Washington quadrangles provided by EDR, dated 1936, 1998, 2000, 2002, 2005, and 2007.

USGS aerial photographs provided by EDR, dated 1965, 1977, 1981, 1985, 1990, 2005, and 2006.


U.S. Environmental Protection Agency (EPA) Federal Standard 40 CFR Part 312 "Standards and Practices for All Appropriate Inquiries (AAI).

Washington State Department of Natural Resources. 2002. Geologic Map of Washington—Northwest Quadrant.

DO NOT REMOVE

GeoEngineers


Image Provided by Environmental Data Resources, Inc.
Source: USGS Scale: 1" = 1,818'



GeoEngineers
Earth Science + Technology

Figure 1. Vicinity Map
Bakker Properties Phase I ESA
120th Avenue NE Widening Project
Bellevue, WA 98005

PREPARED FOR: City of Bellevue
PROJ. MGR: Jessica Robertson DATE: 01/18/2012
DRAWN BY: Jessica Robertson PROJ. #: 0526-170-01



LEGEND:

Subject Property Boundary

Existing UST

UST Underground Storage Tank

NOTES:

1. The locations of all features shown are approximate.
2. This drawing is only for information purposes. It is intended to assist in showing features discussed in an attached document. GeoEngineers, Inc. can not guarantee the accuracy and content of electronic files. The master file is stored by GeoEngineers, Inc. and will serve as the official record of this communication.

Reference: Parsons Brinckerhoff, 2011

80 0 80
Feet

Site Plan


Bakker Properties Phase I ESA
120th Avenue NE Widening Project
Bellevue, Washington

GeoEngineers

Figure 2



LOOKING SOUTHEAST ACROSS THE SUBJECT PROPERTY TOWARD EXISTING BUILDING




LOOKING NORTHWEST ACROSS WEST SUBJECT PROPERTY PARCEL

0526-170-01


GeoEngineers
Earth Science + Technology

SITE PHOTOGRAPHS – JANUARY 2012

FIGURE 3A



LOOKING NORTH ALONG EAST SUBJECT PROPERTY BOUNDARY



LOOKING NORTHEAST ALONG BELLEVUE-REDMOND ROAD
ADJACENT FORMER GAS STATION PROPERTY (TRIANGLE PARKING LOT)
IN RIGHT FOREGROUND

0526-170-01

GeoEngineers
Earth Science + Technology

SITE PHOTOGRAPHS – JANUARY 2012

FIGURE 3B

GeoEngineers



APPENDIX A
User Questionnaire

PHASE I ESA USER QUESTIONNAIRE
FORMER BAKKER'S DRY CLEANING PROPERTY (KING COUNTY TAX PARCEL 1099100419)
11855 NE BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON
GEI FILE NO: 0526-170-01

In order to qualify for one of the federal landowner liability protections, and to enable us to fully address the objectives of the Phase I ESA, please complete the questionnaire below and provide the additional information requested.

1. Are you aware of any environmental cleanup liens against the subject property that are filed or recorded under federal, tribal and state or local law?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

2. Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions or institutional controls, that are in place at the subject property and/or have been filed or recorded in a registry under federal, tribal, state or local law?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

3. As the user of this Phase I ESA, do you have any specialized knowledge or experience related to the subject property or nearby properties? For example are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

4. Does the purchase price being paid for the subject property reasonable reflect the fair market value of the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

a. If you conclude that there is a difference and you answered NO above, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

5. Are you aware of commonly known or reasonably ascertainable information about the subject property that would help us identify conditions indicative or releases or threatened releases? For example,

a. Do you know the past uses of the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

b. Do you know of specific chemicals that are present or once were present on the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

c. Do you know of spills or other chemical releases that have taken place at the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

d. Do you know of any environmental cleanups that have taken place at the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

6. Based on your knowledge and experience related to the subject property, are there any obvious indicators that point to the presence or likely presence of contamination at the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

User Questionnaire Completed By (Name and Organization): _____

_____

Date: _____

List of Requested Information, If Available

- Names and phone numbers of key individuals with knowledge of property use history.
- A map showing the boundaries of the subject property.
- Tax ID numbers for parcels included within the subject property.
- Copies of any past environmental site assessment and/or audit reports or risk assessment studies.
- Environmental permits.
- Registrations for underground and aboveground storage tanks (if any).
- Material data safety sheets for hazardous substances used or stored on-site (if any).
- Community right-to-know plans pertaining to the subject property.
- Safety plans pertaining to on-site facilities.
- Reports regarding geotechnical and/or hydrogeologic conditions at or near the subject property.
- Notices or other correspondence from any governmental agency relating to past or current violations of environmental laws with respect to the subject property or relating to environmental liens encumbering the property.
- Recorded Activity Use Limitations (AULs)

PHASE I ESA USER QUESTIONNAIRE
BAKKER FORMER OFFICE PROPERTY (KING COUNTY TAX PARCEL 1099100420)
11876 NE 8TH STREET
BELLEVUE, WASHINGTON
GEI FILE NO: 0526-170-01

In order to qualify for one of the federal landowner liability protections, and to enable us to fully address the objectives of the Phase I ESA, please complete the questionnaire below and provide the additional information requested.

7. Are you aware of any environmental cleanup liens against the subject property that are filed or recorded under federal, tribal and state or local law?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

8. Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions or institutional controls, that are in place at the subject property and/or have been filed or recorded in a registry under federal, tribal, state or local law?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

9. As the user of this Phase I ESA, do you have any specialized knowledge or experience related to the subject property or nearby properties? For example are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

10. Does the purchase price being paid for the subject property reasonable reflect the fair market value of the property?

    ☐ YES ☐ NO ☐ DON'T KNOW Explain:

a. If you conclude that there is a difference and you answered NO above, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

11. Are you aware of commonly known or reasonably ascertainable information about the subject property that would help us identify conditions indicative or releases or threatened releases? For example,

a. Do you know the past uses of the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

b. Do you know of specific chemicals that are present or once were present on the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

c. Do you know of spills or other chemical releases that have taken place at the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

d. Do you know of any environmental cleanups that have taken place at the property?

   ☐ YES ☐ NO ☐ DON'T KNOW Explain:

12. Based on your knowledge and experience related to the subject property, are there any obvious indicators that point to the presence or likely presence of contamination at the property?

    ☐ YES ☐ NO ☐ DON'T KNOW Explain:


User Questionnaire Completed By (Name and Organization): _____

_____

Date: _____

List of Requested Information, If Available

- Names and phone numbers of key individuals with knowledge of property use history.
- A map showing the boundaries of the subject property.
- Tax ID numbers for parcels included within the subject property.
- Copies of any past environmental site assessment and/or audit reports or risk assessment studies.
- Environmental permits.
- Registrations for underground and aboveground storage tanks (if any).
- Material data safety sheets for hazardous substances used or stored on-site (if any).
- Community right-to-know plans pertaining to the subject property.
- Safety plans pertaining to on-site facilities.
- Reports regarding geotechnical and/or hydrogeologic conditions at or near the subject property.
- Notices or other correspondence from any governmental agency relating to past or current violations of environmental laws with respect to the subject property or relating to environmental liens encumbering the property.
- Recorded Activity Use Limitations (AULs)



APPENDIX B
Environmental Data Resources (EDR) Report and Historical Records

120th and Bellevue-Redmond Road Properties
120th Avenue NE/NE Bellevue Redmond Road
Bellevue, WA 98005

Inquiry Number: 3237712.2s
January 11, 2012

The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	7
Orphan Summary	410
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-6
Physical Setting Source Map	A-12
Physical Setting Source Map Findings	A-14
Physical Setting Source Records Searched	A-43

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2012 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

120TH AVENUE NE/NE BELLEVUE REDMOND ROAD
BELLEVUE, WA 98005

COORDINATES

Latitude (North):	47.6183000 - 47° 37' 5.88''
Longitude (West):	122.1794000 - 122° 10' 45.84''
Universal Tranverse Mercator:	Zone 10
UTM X (Meters):	561665.0
UTM Y (Meters):	5273984.5
Elevation:	156 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	47122-E2 MERCER ISLAND, WA
Most Recent Revision:	1983
North Map:	47122-F2 KIRKLAND, WA
Most Recent Revision:	1982

AERIAL PHOTOGRAPHY IN THIS REPORT

Photo Year:	2009
Source:	USDA

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL---------- National Priority List

EXECUTIVE SUMMARY

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

CERCLIS ---------- Comprehensive Environmental Response, Compensation, and Liability Information System
FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal CERCLIS NFRAP site List

CERC-NFRAP ---------- CERCLIS No Further Remedial Action Planned

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal landfill and/or solid waste disposal site lists

SWF/LF ---------- Solid Waste Facility Database

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

AST ---------- Aboveground Storage Tank Locations
INDIAN UST ---------- Underground Storage Tanks on Indian Land
FEMA UST ---------- Underground Storage Tank Listing

State and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

BROWNFIELDS ---------- Brownfields Sites Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

EXECUTIVE SUMMARY

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9	Torres Martinez Reservation Illegal Dump Site Locations
ODI	Open Dump Inventory
SWTIRE	Solid Waste Tire Facilities
INDIAN ODI	Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL	Clandestine Drug Labs
CDL	Clandestine Drug Lab Contaminated Site List
HIST CDL	List of Sites Contaminated by Clandestine Drug Labs
US HIST CDL	National Clandestine Laboratory Register

Local Land Records

LIENS 2	CERCLA Lien Information
LUCIS	Land Use Control Information System

Records of Emergency Release Reports

HMIRS	Hazardous Materials Information Reporting System
SPILLS	Reported Spills

Other Ascertainable Records

DOT OPS	Incident and Accident Data
DOD	Department of Defense Sites
FUDS	Formerly Used Defense Sites
CONSENT	Superfund (CERCLA) Consent Decrees
ROD	Records Of Decision
UMTRA	Uranium Mill Tailings Sites
MINES	Mines Master Index File
TRIS	Toxic Chemical Release Inventory System
TSCA	Toxic Substances Control Act
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
SSTS	Section 7 Tracking Systems
ICIS	Integrated Compliance Information System
PADS	PCB Activity Database System
MLTS	Material Licensing Tracking System
RADINFO	Radiation Information Database
FINDS	Facility Index System/Facility Registry System
RAATS	RCRA Administrative Action Tracking System
UIC	Underground Injection Wells Listing
DRYCLEANERS	Drycleaner List
NPDES	Water Quality Permit System Data
AIRS	Washington Emissions Data System
INDIAN RESERV	Indian Reservations
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
FINANCIAL ASSURANCE	Financial Assurance Information Listing
COAL ASH	Coal Ash Disposal Site Listing
COAL ASH DOE	Sleam-Electric Plan Operation Data

EXECUTIVE SUMMARY

COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER..... PCB Transformer Registration Database

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants..... EDR Proprietary Manufactured Gas Plants
EDR Historical Auto Stations.. EDR Proprietary Historic Gas Stations
EDR Historical Cleaners..... EDR Proprietary Historic Dry Cleaners

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 06/15/2011 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BAKKERS COIT INC	***12002 NE 8TH***	***SW 0 - 1/8 (0.078 mi.)***	***10***	***21***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/15/2011 has revealed that there is 1 RCRA-SQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AURORA IMPROVEMENT COMPANY	12130 BEL RED RD	ENE 0 - 1/8 (0.047 mi.)	B5	13

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 06/15/2011 has revealed that there are 6 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BARRIER MOTORS INC MERCEDES	***11950 BELLEVUE REDMOND***	***W 0 - 1/8 (0.056 mi.)***	***C9***	***16***
ESCHEN AUTOMOTIVE INC NE 12TH	***12005 NE 12TH ST NO 14***	***N 1/8 - 1/4 (0.156 mi.)***	***F18***	***48***
MIDAS AUTO SERVICE EXPERTS BEL	***12005 NE 12TH ST***	***N 1/8 - 1/4 (0.156 mi.)***	***F19***	***50***
HI TECH CLEANERS BELLEVUE	***661 120TH AVE NE STE 15***	***SSW 1/8 - 1/4 (0.160 mi.)***	***G22***	***63***
ENVIRONMENTAL HEALTH SCIENCES	***9 LAKE BELLEVUE BLDG ST***	***NW 1/8 - 1/4 (0.193 mi.)***	***36***	***101***
OLYMPIC CLEANERS	***800 118TH AVE NE A***	***WSW 1/8 - 1/4 (0.196 mi.)***	***I38***	***105***

State- and tribal - equivalent NPL

HSL: The Hazardous Sites List is a subset of the CSCSL Report. It includes sites which have been assessed and ranked using the Washington Ranking Method (WARM).

A review of the HSL list, as provided by EDR, and dated 08/31/2011 has revealed that there is 1 HSL site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TIKI CAR WASH	***11909 NE 8TH ST***	***WSW 1/8 - 1/4 (0.164 mi.)***	***H31***	***92***
Facility Type: Hazardous Sites List				

State- and tribal - equivalent CERCLIS

CSCSL: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Ecology's Confirmed & Suspected Contaminated Sites List.

A review of the CSCSL list, as provided by EDR, and dated 10/25/2011 has revealed that there are 27 CSCSL sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OVERLAKE HOSPITAL MEDICAL CENT	***1035 116TH AVE NE***	***WNW 1/4 - 1/2 (0.336 mi.)***	***N56***	***190***
FIBRES INTERNATIONAL INC	***1533 120TH AVE NE***	***N 1/4 - 1/2 (0.424 mi.)***	***U81***	***271***
INTERNATIONAL PAPER BELLEVUE	***1899 120TH AVE NE***	***N 1/2 - 1 (0.581 mi.)***	***107***	***329***
KING CNTY DOT METRO TRANSIT EA	***1975 124TH AVENUE NORTH***	***NNE 1/2 - 1 (0.695 mi.)***	***109***	***341***

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CADMAN PREMIX CO INC	*1605 130TH AVE NE*	*NE 1/2 - 1 (0.728 mi.)*	*110*	*355*
WILSON TRANSMISSION INC	*1414 132ND AVE NE*	*ENE 1/2 - 1 (0.756 mi.)*	*111*	*356*
STAR RENTALS INC BELLEVUE	*12900 NORTHRUP WY*	*NE 1/2 - 1 (0.853 mi.)*	*Z113*	*367*
ARCO 6217	*12903 NE 20TH ST*	*NE 1/2 - 1 (0.854 mi.)*	*Z114*	*371*
FORMER THINKER TOYS	*10610 NE 8TH ST*	*W 1/2 - 1 (0.909 mi.)*	*115*	*380*
BELLEVUE CADILLAC	*1001 106TH AVE NE*	*W 1/2 - 1 (0.924 mi.)*	*116*	*385*
LOWES HIW 040	*11959 NORTHUP WAY*	*N 1/2 - 1 (0.934 mi.)*	*117*	*389*

Lower Elevation	Address	Direction / Distance	Map ID	Page
BARRIER MOTORS INC UST 6133	*11968 BEL RED RD*	*SW 0 - 1/8 (0.040 mi.)*	*A3*	*9*
BARRIER MOTORS INC MERCEDES	*11950 BELLEVUE REDMOND*	*W 0 - 1/8 (0.056 mi.)*	*C9*	*16*
SHELL STATION 120546	*12001 NORTHEAST 8TH STR*	*WSW 1/8 - 1/4 (0.136 mi.)*	*E15*	*34*
HI TECH CLEANERS BELLEVUE	*661 120TH AVE NE STE 15*	*SSW 1/8 - 1/4 (0.160 mi.)*	*G22*	*63*
EASTSIDE RENTAL EQUIPMENT	*11830 NE 8TH ST*	*WSW 1/8 - 1/4 (0.164 mi.)*	*H28*	*82*
TIKI CAR WASH	*11909 NE 8TH ST*	*WSW 1/8 - 1/4 (0.164 mi.)*	*H31*	*92*
MID LAKES PROPERTY	*11807 11811 11815 NE 8T*	*WSW 1/8 - 1/4 (0.194 mi.)*	*I37*	*104*
UNICRAFT PRINTING	*300 120TH AVE NE BLDG 6*	*S 1/4 - 1/2 (0.354 mi.)*	*O64*	*232*
BMC WEST BUILDING MATERIALS	*12600 BELLEVUE REDMOND*	*ENE 1/4 - 1/2 (0.393 mi.)*	*R75*	*254*
CHEVROLET OF BELLEVUE	*430 116TH AVE NE*	*SW 1/4 - 1/2 (0.449 mi.)*	*X92*	*279*
FOUR SEASONS CAR WASH	*12900 BEL RED RD*	*ENE 1/2 - 1 (0.558 mi.)*	*105*	*320*
TEXACO REFINING MARKETING IN 1	*615 112TH AVE NE*	*WSW 1/2 - 1 (0.568 mi.)*	*106*	*321*
BELLEVUE CITY HALL	*11511 MAIN ST*	*SSW 1/2 - 1 (0.671 mi.)*	*108*	*338*
MICHAELS TOYOTA	*306 116TH AVE SE*	*SSW 1/2 - 1 (0.798 mi.)*	*112*	*360*
BENENSON CAPITAL	*110 108TH AVENUE NORTHE*	*SW 1/2 - 1 (0.954 mi.)*	*AA118*	*402*
CHEVRON 92581	*10812 MAIN ST*	*SW 1/2 - 1 (0.955 mi.)*	*AA119*	*404*

State and tribal leaking storage tank lists

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Ecology's Leaking Underground Storage Tanks Site List.

A review of the LUST list, as provided by EDR, and dated 11/22/2011 has revealed that there are 14 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
APPLEGREEN CENTER	*1024 116TH AVE NE*	*WNW 1/4 - 1/2 (0.323 mi.)*	*N55*	*186*
OVERLAKE HOSPITAL MEDICAL CENT	*1035 116TH AVE NE*	*WNW 1/4 - 1/2 (0.336 mi.)*	*N57*	*205*
FIBRES INTERNATIONAL INC	*1533 120TH AVE NE*	*N 1/4 - 1/2 (0.424 mi.)*	*U79*	*268*

Lower Elevation	Address	Direction / Distance	Map ID	Page
BARRIER MOTORS INC UST 6133	*11968 BEL RED RD*	*SW 0 - 1/8 (0.040 mi.)*	*A3*	*9*
BARRIER MOTORS INC MERCEDES	*11950 BELLEVUE REDMOND*	*W 0 - 1/8 (0.056 mi.)*	*C9*	*16*
SHELL STATION 120546	*12001 NE 8TH ST*	*WSW 1/8 - 1/4 (0.136 mi.)*	*E14*	*29*
LARRYS MARKET	*655 120TH AVE NE*	*SSW 1/8 - 1/4 (0.164 mi.)*	*G26*	*79*
EASTSIDE RENTAL EQUIPMENT	*11830 NE 8TH ST*	*WSW 1/8 - 1/4 (0.164 mi.)*	*H29*	*85*
TIKI CAR WASH	*11909 NE 8TH ST*	*WSW 1/8 - 1/4 (0.164 mi.)*	*H30*	*90*
ARCO 0836	*11611 NE 8TH ST*	*WSW 1/4 - 1/2 (0.292 mi.)*	*L51*	*170*
K & L DISTRIBUTORS INC UST 622	*300 120 AVE NE*	*S 1/4 - 1/2 (0.354 mi.)*	*O62*	*229*
BMC WEST BUILDING MATERIALS	*12600 BELLEVUE REDMOND*	*ENE 1/4 - 1/2 (0.393 mi.)*	*R75*	*254*
CHEVROLET OF BELLEVUE	*430 116TH AVE NE*	*SW 1/4 - 1/2 (0.449 mi.)*	*X93*	*283*

Lower Elevation	Address	Direction / Distance	Map ID	Page
LINCOLN MERCURY OF BELLEVUE	*420 116TH AVE NE*	*SW 1/4 - 1/2 (0.454 mi.)*	*X99*	*301*

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Ecology's Statewide UST Site/Tank Report.

A review of the UST list, as provided by EDR, and dated 11/22/2011 has revealed that there are 11 UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BARRIER MOTORS INC UST 6133	*11968 BEL RED RD*	*SW 0 - 1/8 (0.040 mi.)*	*A3*	*9*
BARRIER MOTORS INC MERCEDES	*11950 BELLEVUE REDMOND*	*W 0 - 1/8 (0.056 mi.)*	*C9*	*16*
SHELL STATION 120546	*12001 NE 8TH ST*	*WSW 1/8 - 1/4 (0.136 mi.)*	*E14*	*29*
BELLEVUE CITY UST 11768	*657 120TH AVE NE*	*SSW 1/8 - 1/4 (0.162 mi.)*	*G24*	*74*
LARRYS MARKET	*655 120TH AVE NE*	*SSW 1/8 - 1/4 (0.164 mi.)*	*G26*	*79*
EASTSIDE RENTAL EQUIPMENT	*11830 NE 8TH ST*	*WSW 1/8 - 1/4 (0.164 mi.)*	*H29*	*85*
TIKI CAR WASH	*11909 NE 8TH ST*	*WSW 1/8 - 1/4 (0.164 mi.)*	*H30*	*90*
BAKKERS COIT INC BELLEVUE	*11855 NE 8TH ST*	*WSW 1/8 - 1/4 (0.180 mi.)*	*H34*	*96*
DOLLAR RENT A CAR SYSTEMS 223	*11839 NE 8TH*	*WSW 1/8 - 1/4 (0.185 mi.)*	*I35*	*98*
ACCUTRAN TRANSMISSIONS INC	*11811 NE 8TH*	*WSW 1/8 - 1/4 (0.196 mi.)*	*I39*	*109*
MUTUAL MATERIALS CO BELLEVUE	*605 119TH NE*	*SSW 1/8 - 1/4 (0.247 mi.)*	*41*	*112*

State and tribal institutional control / engineering control registries

INST CONTROL: Sites that have institutional controls.

A review of the INST CONTROL list, as provided by EDR, and dated 11/15/2011 has revealed that there is 1 INST CONTROL site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
EASTSIDE CHRYSLER JEEP	*400 116TH AVE NE*	*SW 1/4 - 1/2 (0.464 mi.)*	*X100*	*303*

State and tribal voluntary cleanup sites

VCP: Sites that have entered either the Voluntary Cleanup Program or its predecessor Independent Remedial Action Program.

A review of the VCP list, as provided by EDR, and dated 10/25/2011 has revealed that there are 14 VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WILBURTON HEIGHTS APARTMENTS	*12224 NE 8TH ST*	*SE 0 - 1/8 (0.110 mi.)*	*D12*	*25*
COCA COLA BOTTLING CO BELLEVUE	*1150 124TH AVE NE*	*NE 1/4 - 1/2 (0.261 mi.)*	*J44*	*116*
K & L DIST NORTH BELLEVUE FACI	*1445 120TH NE*	*N 1/4 - 1/2 (0.346 mi.)*	*59*	*224*
FIBRES INTERNATIONAL INC	*1533 120TH AVE NE*	*N 1/4 - 1/2 (0.424 mi.)*	*U81*	*271*

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAFEWAY WAREHOUSE INC DIST CEN	***1723 124TH AVE NE***	***NNE 1/4 - 1/2 (0.450 mi.)***	***V95***	***287***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SHELL STATION 120546	***12001 NORTHEAST 8TH STR***	***WSW 1/8 - 1/4 (0.136 mi.)***	***E15***	***34***
HI TECH CLEANERS BELLEVUE	***661 120TH AVE NE STE 15***	***SSW 1/8 - 1/4 (0.160 mi.)***	***G22***	***63***
BEST BUY SITE	***457 120TH AVE***	***S 1/4 - 1/2 (0.289 mi.)***	***47***	***147***
CHEVRON USA INC SS 97531	***11606 NORTHEAST 8TH STR***	***WSW 1/4 - 1/2 (0.290 mi.)***	***L48***	***148***
BELLEVUE PONTIAC GMC TRUCK	***620 116TH AVE NE***	***SW 1/4 - 1/2 (0.366 mi.)***	***Q71***	***249***
TRIVESTORS PARTNERSHIP PROPERT	***12700 NE BEL RED RD***	***ENE 1/4 - 1/2 (0.448 mi.)***	***W91***	***278***
CHEVROLET OF BELLEVUE	***430 116TH AVE NE***	***SW 1/4 - 1/2 (0.449 mi.)***	***X92***	***279***
FORD OF BELLEVUE	***411 116TH AVE NE***	***SW 1/4 - 1/2 (0.453 mi.)***	***Y97***	***289***
DODGE OF BELLEVUE	***316 116TH AVE NE***	***SW 1/4 - 1/2 (0.486 mi.)***	***104***	***315***

ICR: These are remedial action reports Ecology has received from either the owner or operator of the site. These actions have been conducted without department oversight or approval and are not under an order or decree.

A review of the ICR list, as provided by EDR, and dated 12/01/2002 has revealed that there are 24 ICR sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WILBERTON HEIGHTS (TWO REPORTS	12224 NE 8TH ST.	SE 0 - 1/8 (0.110 mi.)	D11	25
COCA COLA	1150 124TH AVE. NE	NE 1/4 - 1/2 (0.261 mi.)	J43	116
BELLEVUE SCHOOL TRANSPORTATION	12037 NE 5TH	S 1/4 - 1/2 (0.263 mi.)	K45	130
SAFEWAY WAREHOUSE INC DIST CEN	***1227 124TH AVENUE NORTH***	***NE 1/4 - 1/2 (0.297 mi.)***	***M53***	***182***
APPLE GREEN CENTER (POWELL DEV	1024 116TH AVE. NE	WNW 1/4 - 1/2 (0.323 mi.)	N54	185
K & L DIST NORTH BELLEVUE FACI	***1445 120TH NE***	***N 1/4 - 1/2 (0.346 mi.)***	***59***	***224***
FIBRES INTERNATIONAL, INC.	1533 120TH AVE. NE	N 1/4 - 1/2 (0.424 mi.)	U80	271

Lower Elevation	Address	Direction / Distance	Map ID	Page
AVIS CAR RENTALS/BELLEVUE	11968 BELLEVUE-REDMOND	SW 0 - 1/8 (0.040 mi.)	A2	8
BARRIER MOTORS	11950 BELLEVUE-REDMOND	W 0 - 1/8 (0.056 mi.)	C6	14
TEXACO #0022	***12001 NE 8TH***	***WSW 1/8 - 1/4 (0.136 mi.)***	***E13***	***26***
LARRY'S MARKET	655 120TH AVE. NE	SSW 1/8 - 1/4 (0.164 mi.)	G27	82
EASTSIDE RENTAL EQUIPMENT	***11830 NE 8TH ST***	***WSW 1/8 - 1/4 (0.164 mi.)***	***H28***	***82***
TIKI CAR WASH	***11909 NE 8TH***	***WSW 1/8 - 1/4 (0.164 mi.)***	***H32***	***94***
DOLLAR RENT A CAR SYSTEMS 223	***11839 NE 8TH***	***WSW 1/8 - 1/4 (0.185 mi.)***	***I35***	***98***
CHEVRON #9 7531	11606 NE 8TH	WSW 1/4 - 1/2 (0.290 mi.)	L49	164
ARCO #0836	11611 NE 8TH ST.	WSW 1/4 - 1/2 (0.292 mi.)	L50	166
K & L DISTRIBUTORS, INC.	300 120TH AVE. NE	S 1/4 - 1/2 (0.354 mi.)	O63	232
BELLEVUE BUICK GMC TRUCK (TWO	620 116TH AVE. NE	SW 1/4 - 1/2 (0.366 mi.)	Q70	249
BMC WEST	12600 BEL-RED ROAD	ENE 1/4 - 1/2 (0.393 mi.)	R74	253
TRIVESTOR'S PARTNERSHIP	12700 BEL-RED ROAD	ENE 1/4 - 1/2 (0.448 mi.)	W87	276
BROOKS MCKNIGHT CHEVROLET	430 116TH AVE. NE	SW 1/4 - 1/2 (0.449 mi.)	X94	286
FORD MOTOR COMPANY	411 116TH NE	SW 1/4 - 1/2 (0.453 mi.)	Y96	288
LINCOLN MERCURY OF BELLEVUE	***420 116TH AVE NE***	***SW 1/4 - 1/2 (0.454 mi.)***	***X98***	***297***
EASTSIDE JEEP EAGLE DEALERSHIP	400 116TH AVE. NE	SW 1/4 - 1/2 (0.468 mi.)	101	307

EXECUTIVE SUMMARY

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

ALLSITES: Information on facilities and sites of interest to the Department of Ecology.

A review of the ALLSITES list, as provided by EDR, and dated 11/08/2011 has revealed that there are 74 ALLSITES sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
AURORA IMPROVEMENT COMPANY	***12130 BEL RED RD***	***ENE 0 - 1/8 (0.047 mi.)***	***B4***	***12***
WILBURTON HEIGHTS APARTMENTS	***12224 NE 8TH ST***	***SE 0 - 1/8 (0.110 mi.)***	***D12***	***25***
SAFEWAY	***1124 124TH AVE NE***	***NE 1/8 - 1/4 (0.250 mi.)***	***J42***	***115***
COCA COLA BOTTLING CO BELLEVUE	***1150 124TH AVE NE***	***NE 1/4 - 1/2 (0.261 mi.)***	***J44***	***116***
BELLEVUE SCHOOL DIST 405	***12037 NE 5TH ST***	***S 1/4 - 1/2 (0.263 mi.)***	***K46***	***131***
BELLEVUE DISTRIBUTION CENTER	1227 124TH AVE NE	NE 1/4 - 1/2 (0.297 mi.)	M52	181
SAFEWAY WAREHOUSE INC DIST CEN	***1227 124TH AVENUE NORTH***	***NE 1/4 - 1/2 (0.297 mi.)***	***M53***	***182***
APPLEGREEN CENTER	***1024 116TH AVE NE***	***WNW 1/4 - 1/2 (0.323 mi.)***	***N55***	***186***
OVERLAKE HOSPITAL MEDICAL CENT	***1035 116TH AVE NE***	***WNW 1/4 - 1/2 (0.336 mi.)***	***N56***	***190***
K & L DIST NORTH BELLEVUE FACI	***1445 120TH NE***	***N 1/4 - 1/2 (0.346 mi.)***	***59***	***224***
DANA R MARTIN	***1100 116TH NE***	***WNW 1/4 - 1/2 (0.353 mi.)***	***P60***	***228***
OVERLAKE MEDICAL TOWER LLC	***1135 116TH AVE NE***	***NW 1/4 - 1/2 (0.365 mi.)***	***P69***	***248***
SAFEWAY INC MILK DEPT	***1469 124TH AVE NE***	***NNE 1/4 - 1/2 (0.420 mi.)***	***S77***	***261***
EASTSIDE MEDICAL LAB BELLEVUE	***1199 116TH AVE NE***	***NW 1/4 - 1/2 (0.424 mi.)***	***T78***	***266***
FIBRES INTERNATIONAL INC	***1533 120TH AVE NE***	***N 1/4 - 1/2 (0.424 mi.)***	***U81***	***271***
SAFEWAY INC BELLEVUE BEVERAGE	1500 124TH AVE NE	NNE 1/4 - 1/2 (0.426 mi.)	S82	273
LABCORP DYNACARE LABORATORIES	1200 116TH AVE NE STE G	NW 1/4 - 1/2 (0.431 mi.)	T83	274
OVERLAKE MOB	1232 116TH AVE NE	NW 1/4 - 1/2 (0.440 mi.)	84	274
PRINTEX PRESS	1600 124TH AVE NE STE E	NNE 1/4 - 1/2 (0.445 mi.)	V85	275
SAFEWAY WAREHOUSE INC DIST CEN	***1723 124TH AVE NE***	***NNE 1/4 - 1/2 (0.450 mi.)***	***V95***	***287***
EASTSIDE FERTILITY LABORATORY	1370 116TH AVE NE	NW 1/4 - 1/2 (0.483 mi.)	103	315

Lower Elevation	Address	Direction / Distance	Map ID	Page
AVIS RENT A CAR SYSTEMS INC	***11969 BELLEVUE REDMOND***	***SW 0 - 1/8 (0.032 mi.)***	***A1***	***7***
BARRIER MOTORS INC UST 6133	***11968 BEL RED RD***	***SW 0 - 1/8 (0.040 mi.)***	***A3***	***9***
BARRIER VOLVO SAAB	11850 BEL RED RD	W 0 - 1/8 (0.056 mi.)	C7	14
BARRIER MOTORS INC MERCEDES	***11950 BELLEVUE REDMOND***	***W 0 - 1/8 (0.056 mi.)***	***C9***	***16***
BAKKERS COIT INC	***12002 NE 8TH***	***SW 0 - 1/8 (0.078 mi.)***	***10***	***21***
SHELL STATION 120546	***12001 NORTHEAST 8TH STR***	***WSW 1/8 - 1/4 (0.136 mi.)***	***E15***	***34***
HC AUTO CARE INC BELLEVUE	***11807 & 11817 NE 8TH ST***	***SW 1/8 - 1/4 (0.152 mi.)***	***E16***	***45***
BELLEVUE AUTO TECH INC	***12005 NE 12TH STE 12***	***N 1/8 - 1/4 (0.156 mi.)***	***F17***	***47***
ESCHEN AUTOMOTIVE INC NE 12TH	***12005 NE 12TH ST NO 14***	***N 1/8 - 1/4 (0.156 mi.)***	***F18***	***48***
MIDAS AUTO SERVICE EXPERTS BEL	***12005 NE 12TH ST***	***N 1/8 - 1/4 (0.156 mi.)***	***F19***	***50***
ACCUTINT	12003 NE 12TH ST STE 74	N 1/8 - 1/4 (0.157 mi.)	F20	62
BEL RED TRANSMISSIONS INC	12003 NE 12TH ST	N 1/8 - 1/4 (0.157 mi.)	F21	62
HI TECH CLEANERS BELLEVUE	***661 120TH AVE NE STE 15***	***SSW 1/8 - 1/4 (0.160 mi.)***	***G22***	***63***
BELLEVUE ALFA ROMEO BELLEVUE	***11919 NE 8TH ST***	***WSW 1/8 - 1/4 (0.162 mi.)***	***H23***	***73***
BELLEVUE CITY UST 11768	***657 120TH AVE NE***	***SSW 1/8 - 1/4 (0.162 mi.)***	***G24***	***74***
LARRYS MARKET	***655 120TH AVE NE***	***SSW 1/8 - 1/4 (0.164 mi.)***	***G26***	***79***
EASTSIDE RENTAL EQUIPMENT	***11830 NE 8TH ST***	***WSW 1/8 - 1/4 (0.164 mi.)***	***H28***	***82***
TIKI CAR WASH	***11909 NE 8TH ST***	***WSW 1/8 - 1/4 (0.164 mi.)***	***H31***	***92***
BLUE OVAL PONY CARS LLC	11828 NE 8TH ST	WSW 1/8 - 1/4 (0.166 mi.)	H33	96
BAKKERS COIT INC BELLEVUE	***11855 NE 8TH ST***	***WSW 1/8 - 1/4 (0.180 mi.)***	***H34***	***96***
DOLLAR RENT A CAR SYSTEMS 223	***11839 NE 8TH***	***WSW 1/8 - 1/4 (0.185 mi.)***	***I35***	***98***
ENVIRONMENTAL HEALTH SCIENCES	***9 LAKE BELLEVUE BLDG ST***	***NW 1/8 - 1/4 (0.193 mi.)***	***36***	***101***

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
MID LAKES PROPERTY	***11807 11811 11815 NE 8T***	***WSW 1/8 - 1/4 (0.194 mi.)***	***I37***	***104***
OLYMPIC CLEANERS	***800 118TH AVE NE A***	***WSW 1/8 - 1/4 (0.196 mi.)***	***I38***	***105***
ACCUTRAN TRANSMISSIONS INC	***11811 NE 8TH***	***WSW 1/8 - 1/4 (0.196 mi.)***	***I39***	***109***
SWB CONSTRUCTION	***1307 120TH NE***	***N 1/8 - 1/4 (0.245 mi.)***	***40***	***110***
MUTUAL MATERIALS CO BELLEVUE	***605 119TH NE***	***SSW 1/8 - 1/4 (0.247 mi.)***	***41***	***112***
BEST BUY SITE	***457 120TH AVE***	***S 1/4 - 1/2 (0.289 mi.)***	***47***	***147***
CHEVRON USA INC SS 97531	***11606 NORTHEAST 8TH STR***	***WSW 1/4 - 1/2 (0.290 mi.)***	***L48***	***148***
ARCO 0836	***11611 NE 8TH ST***	***WSW 1/4 - 1/2 (0.292 mi.)***	***L51***	***170***
HOME DEPOT 4711	***325 120TH AVE NE***	***S 1/4 - 1/2 (0.344 mi.)***	***O58***	***209***
K & L DISTRIBUTORS INC UST 622	300 120TH AVE NE	S 1/4 - 1/2 (0.354 mi.)	O61	229
UNICRAFT PRINTING	***300 120TH AVE NE BLDG 6***	***S 1/4 - 1/2 (0.354 mi.)***	***O64***	***232***
HOME DEPOT	300 120TH AVE NE BLDG 5	S 1/4 - 1/2 (0.354 mi.)	O65	235
AGI TECHNOLOGIES 120TH AVE	300 120TH AVE NE BLDG 4	S 1/4 - 1/2 (0.354 mi.)	O66	236
EXOTIC MOTORS AUTO REBUILD INC	***638 116TH AVE NE E SIDE***	***SW 1/4 - 1/2 (0.360 mi.)***	***Q67***	***236***
DEALERS CHOICE AUTOMOTIVE INC	***638 B 116TH AVE NE***	***SW 1/4 - 1/2 (0.360 mi.)***	***Q68***	***246***
BELLEVUE PONTIAC GMC TRUCK	***620 116TH AVE NE***	***SW 1/4 - 1/2 (0.366 mi.)***	***Q71***	***249***
BELLEVUE ISUZU BELLEVUE	614 116TH AVE NE	SW 1/4 - 1/2 (0.369 mi.)	Q72	251
PUGET SOUND POWER & LIGHT CO C	***600 116TH AVE NE***	***SW 1/4 - 1/2 (0.374 mi.)***	***73***	***252***
BMC WEST BUILDING MATERIALS	***12600 BELLEVUE REDMOND***	***ENE 1/4 - 1/2 (0.393 mi.)***	***R75***	***254***
AGFA GEVAERT INC	***555 116TH AVE NE***	***SW 1/4 - 1/2 (0.394 mi.)***	***76***	***259***
EUROPA IMPORTED SERVICE LLC	12700 BEL RED RD	ENE 1/4 - 1/2 (0.448 mi.)	W86	275
MERCEDES CENTRUM INC	12700 BEL RED RD STE 8	ENE 1/4 - 1/2 (0.448 mi.)	W88	276
BALDWIN & SONS	12700 BEL RED RD	ENE 1/4 - 1/2 (0.448 mi.)	W89	277
BIGGS EASTSIDE AUTOMOTIVE	12700 BEL RED RD	ENE 1/4 - 1/2 (0.448 mi.)	W90	277
TRIVESTORS PARTNERSHIP PROPERT	***12700 NE BEL RED RD***	***ENE 1/4 - 1/2 (0.448 mi.)***	***W91***	***278***
CHEVROLET OF BELLEVUE	***430 116TH AVE NE***	***SW 1/4 - 1/2 (0.449 mi.)***	***X92***	***279***
FORD OF BELLEVUE	***411 116TH AVE NE***	***SW 1/4 - 1/2 (0.453 mi.)***	***Y97***	***289***
LINCOLN MERCURY OF BELLEVUE	***420 116TH AVE NE***	***SW 1/4 - 1/2 (0.454 mi.)***	***X99***	***301***
EASTSIDE CHRYSLER JEEP	***400 116TH AVE NE***	***SW 1/4 - 1/2 (0.464 mi.)***	***X100***	***303***
BEL KIRK MUSTANG	***12760 BEL RED RD***	***ENE 1/4 - 1/2 (0.481 mi.)***	***102***	***313***
DODGE OF BELLEVUE	***316 116TH AVE NE***	***SW 1/4 - 1/2 (0.486 mi.)***	***104***	***315***

CSCSL NFA: The data set contains information about sites previously on the Confirmed and Suspected Contaminated Sites list that have received a No Further Action (NFA) determination. Because it is necessary to maintain historical records of sites that have been investigated and cleaned up, sites are not deleted from the database when cleanup activities are completed. Instead a No Further Action code is entered based upon the type of NFA determination the site received.

A review of the CSCSL NFA list, as provided by EDR, and dated 10/25/2011 has revealed that there are 14 CSCSL NFA sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WILBURTON HEIGHTS APARTMENTS	***12224 NE 8TH ST***	***SE 0 - 1/8 (0.110 mi.)***	***D12***	***25***
COCA COLA BOTTLING CO BELLEVUE	***1150 124TH AVE NE***	***NE 1/4 - 1/2 (0.261 mi.)***	***J44***	***116***
BELLEVUE SCHOOL DIST 405	***12037 NE 5TH ST***	***S 1/4 - 1/2 (0.263 mi.)***	***K46***	***131***
K & L DIST NORTH BELLEVUE FACI	***1445 120TH NE***	***N 1/4 - 1/2 (0.346 mi.)***	***59***	***224***
SAFEWAY WAREHOUSE INC DIST CEN	***1723 124TH AVE NE***	***NNE 1/4 - 1/2 (0.450 mi.)***	***V95***	***287***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BAKKERS COIT INC BELLEVUE	***11855 NE 8TH ST***	***WSW 1/8 - 1/4 (0.180 mi.)***	***H34***	***96***
DOLLAR RENT A CAR SYSTEMS 223	***11839 NE 8TH***	***WSW 1/8 - 1/4 (0.185 mi.)***	***I35***	***98***
BEST BUY SITE	***457 120TH AVE***	***S 1/4 - 1/2 (0.289 mi.)***	***47***	***147***
CHEVRON USA INC SS 97531	***11606 NORTHEAST 8TH STR***	***WSW 1/4 - 1/2 (0.290 mi.)***	***L48***	***148***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BELLEVUE PONTIAC GMC TRUCK	*620 116TH AVE NE*	*SW 1/4 - 1/2 (0.366 mi.)*	*Q71*	*249*
TRIVESTORS PARTNERSHIP PROPERT	*12700 NE BEL RED RD*	*ENE 1/4 - 1/2 (0.448 mi.)*	*W91*	*278*
FORD OF BELLEVUE	*411 116TH AVE NE*	*SW 1/4 - 1/2 (0.453 mi.)*	*Y97*	*289*
EASTSIDE CHRYSLER JEEP	*400 116TH AVE NE*	*SW 1/4 - 1/2 (0.464 mi.)*	*X100*	*303*
DODGE OF BELLEVUE	*316 116TH AVE NE*	*SW 1/4 - 1/2 (0.486 mi.)*	*104*	*315*

Other Ascertainable Records

RCRA-NonGen: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA-NonGen list, as provided by EDR, and dated 06/15/2011 has revealed that there are 10 RCRA-NonGen sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
AVIS RENT A CAR SYSTEMS INC	*11969 BELLEVUE REDMOND*	*SW 0 - 1/8 (0.032 mi.)*	*A1*	*7*
BARRIER VOLVO	*11850 BEL-RED ROAD*	*W 0 - 1/8 (0.056 mi.)*	*C8*	*15*
SHELL STATION 120546	*12001 NORTHEAST 8TH STR*	*WSW 1/8 - 1/4 (0.136 mi.)*	*E15*	*34*
HC AUTO CARE INC BELLEVUE	*11807 & 11817 NE 8TH ST*	*SW 1/8 - 1/4 (0.152 mi.)*	*E16*	*45*
BELLEVUE AUTO TECH INC	*12005 NE 12TH STE 12*	*N 1/8 - 1/4 (0.156 mi.)*	*F17*	*47*
BELLEVUE ALFA ROMEO BELLEVUE	*11919 NE 8TH ST*	*WSW 1/8 - 1/4 (0.162 mi.)*	*H23*	*73*
LARRYS MARKET	*655 120TH AVE NE*	*SSW 1/8 - 1/4 (0.164 mi.)*	*G25*	*77*
EASTSIDE RENTAL EQUIPMENT	*11830 NE 8TH ST*	*WSW 1/8 - 1/4 (0.164 mi.)*	*H28*	*82*
SWB CONSTRUCTION	*1307 120TH NE*	*N 1/8 - 1/4 (0.245 mi.)*	*40*	*110*
MUTUAL MATERIALS CO BELLEVUE	*605 119TH NE*	*SSW 1/8 - 1/4 (0.247 mi.)*	*41*	*112*

MANIFEST: Hazardous waste manifest information.

A review of the MANIFEST list, as provided by EDR, and dated 12/31/2010 has revealed that there are 3 MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SHELL STATION 120546	*12001 NORTHEAST 8TH STR*	*WSW 1/8 - 1/4 (0.136 mi.)*	*E15*	*34*
MIDAS AUTO SERVICE EXPERTS BEL	*12005 NE 12TH ST*	*N 1/8 - 1/4 (0.156 mi.)*	*F19*	*50*
HI TECH CLEANERS BELLEVUE	*661 120TH AVE NE STE 15*	*SSW 1/8 - 1/4 (0.160 mi.)*	*G22*	*63*

Inactive Drycleaners: A listing of inactive drycleaner facility locations.

A review of the Inactive Drycleaners list, as provided by EDR, and dated 12/31/2010 has revealed that there are 3 Inactive Drycleaners sites within approximately 0.25 miles of the target property.


Lower Elevation	Address	Direction / Distance	Map ID	Page
BAKKERS COIT INC	*12002 NE 8TH*	*SW 0 - 1/8 (0.078 mi.)*	*10*	*21*
HI TECH CLEANERS BELLEVUE	*661 120TH AVE NE STE 15*	*SSW 1/8 - 1/4 (0.160 mi.)*	*G22*	*63*
OLYMPIC CLEANERS	*800 118TH AVE NE A*	*WSW 1/8 - 1/4 (0.196 mi.)*	*I38*	*105*

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 18 records.

Site Name	Database(s)
WA DOT NE 10TH BRIDGE CROSSING	ALLSITES
GROUP HEALTH COOP BELLEVUE MEDICAL	ALLSITES, MANIFEST
KELSEY CR STREAM CHANNEL MOD	ALLSITES, NPDES
BELLEVUE PARK II	CSCSL, ALLSITES, VCP
GREGS PLACE AUTO REBUILD	RCRA-NonGen, FINDS, ALLSITES
NE 8TH ST SIDEWALK IMPROVEMENT	ALLSITES
BARRIER MOTORS LLC	ALLSITES
MELODYS BELLEVUE NISSAN	RCRA-NonGen, CSCSL, ALLSITES, LUST, UST
NORTHUP WAY ROADWAY IMPROVEMENTS	ALLSITES
CITY OF BELLEVUE SUMMER COLLECTION	SWF/LF
CITY OF BELLEVUE FALL COLLECTION E	SWF/LF
WASTE MOBILE COLLECTIONS	SWF/LF
BELLEVUE PARK II	LUST, UST
GROUP HEALTH COOP BELLEVUE MEDICAL	RCRA-SQG
120TH BEL-RED RD. SAFEWAY DIST. PL	ERNS
CORNER OF 140TH AND KAMBER ROAD	ERNS
CITY OF BELLEVUE REHABILITATION PR	ICR
FORMER DRY CLEANERS-BELLEVUE VILLA	ICR

OVERVIEW MAP - 3237712.2s




This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	120th and Bellevue-Redmond Road Properties	CLIENT:	Geo Engineers, Inc.
ADDRESS:	120th Avenue NE/NE Bellevue Redmond Road Bellevue WA 98005	CONTACT:	Jessica Robertson
LAT/LONG:	47.6183 / 122.1794	INQUIRY #:	3237712.2s
		DATE:	January 11, 2012 12:47 pm

Copyright © 2012 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

DETAIL MAP - 3237712.2s



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Oil & Gas pipelines from USGS
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 120th and Bellevue-Redmond Road Properties	CLIENT: Geo Engineers, Inc.
ADDRESS: 120th Avenue NE/NE Bellevue Redmond Road Bellevue WA 98005	CONTACT: Jessica Robertson INQUIRY #: 3237712.2s
LAT/LONG: 47.6183 / 122.1794	DATE: January 11, 2012 12:48 pm

Copyright © 2012 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL		1.000	0	0	0	0	NR	0
Proposed NPL		1.000	0	0	0	0	NR	0
NPL LIENS		TP	NR	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL		1.000	0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS		0.500	0	0	0	NR	NR	0
FEDERAL FACILITY		1.000	0	0	0	0	NR	0
Federal CERCLIS NFRAP site List								
CERC-NFRAP		0.500	0	0	0	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS		1.000	0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF		0.500	0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG		0.250	1	0	NR	NR	NR	1
RCRA-SQG		0.250	1	0	NR	NR	NR	1
RCRA-CESQG		0.250	1	5	NR	NR	NR	6
Federal institutional controls / engineering controls registries								
US ENG CONTROLS		0.500	0	0	0	NR	NR	0
US INST CONTROL		0.500	0	0	0	NR	NR	0
Federal ERNS list								
ERNS		TP	NR	NR	NR	NR	NR	0
State- and tribal - equivalent NPL								
HSL		1.000	0	1	0	0	NR	1
State- and tribal - equivalent CERCLIS								
CSCSL		1.000	2	5	5	15	NR	27
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF		0.500	0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
LUST		0.500	2	4	8	NR	NR	14
INDIAN LUST		0.500	0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal registered storage tank lists								
UST		0.250	2	9	NR	NR	NR	11
AST		0.250	0	0	NR	NR	NR	0
INDIAN UST		0.250	0	0	NR	NR	NR	0
FEMA UST		0.250	0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
INST CONTROL		0.500	0	0	1	NR	NR	1
State and tribal voluntary cleanup sites								
INDIAN VCP		0.500	0	0	0	NR	NR	0
VCP		0.500	1	2	11	NR	NR	14
ICR		0.500	3	5	16	NR	NR	24
State and tribal Brownfields sites								
BROWNFIELDS		0.500	0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS		0.500	0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
DEBRIS REGION 9		0.500	0	0	0	NR	NR	0
ODI		0.500	0	0	0	NR	NR	0
SWTIRE		0.500	0	0	0	NR	NR	0
INDIAN ODI		0.500	0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL		TP	NR	NR	NR	NR	NR	0
ALLSITES		0.500	7	23	44	NR	NR	74
CSCSL NFA		0.500	1	2	11	NR	NR	14
CDL		TP	NR	NR	NR	NR	NR	0
HIST CDL		TP	NR	NR	NR	NR	NR	0
US HIST CDL		TP	NR	NR	NR	NR	NR	0
Local Land Records								
LIENS 2		TP	NR	NR	NR	NR	NR	0
LUCIS		0.500	0	0	0	NR	NR	0
Records of Emergency Release Reports								
HMIRS		TP	NR	NR	NR	NR	NR	0
SPILLS		TP	NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA-NonGen		0.250	2	8	NR	NR	NR	10

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
DOT OPS		TP	NR	NR	NR	NR	NR	0
DOD		1.000	0	0	0	0	NR	0
FUDS		1.000	0	0	0	0	NR	0
CONSENT		1.000	0	0	0	0	NR	0
ROD		1.000	0	0	0	0	NR	0
UMTRA		0.500	0	0	0	NR	NR	0
MINES		0.250	0	0	NR	NR	NR	0
TRIS		TP	NR	NR	NR	NR	NR	0
TSCA		TP	NR	NR	NR	NR	NR	0
FTTS		TP	NR	NR	NR	NR	NR	0
HIST FTTS		TP	NR	NR	NR	NR	NR	0
SSTS		TP	NR	NR	NR	NR	NR	0
ICIS		TP	NR	NR	NR	NR	NR	0
PADS		TP	NR	NR	NR	NR	NR	0
MLTS		TP	NR	NR	NR	NR	NR	0
RADINFO		TP	NR	NR	NR	NR	NR	0
FINDS		TP	NR	NR	NR	NR	NR	0
RAATS		TP	NR	NR	NR	NR	NR	0
UIC		TP	NR	NR	NR	NR	NR	0
MANIFEST		0.250	0	3	NR	NR	NR	3
DRYCLEANERS		0.250	0	0	NR	NR	NR	0
NPDES		TP	NR	NR	NR	NR	NR	0
AIRS		TP	NR	NR	NR	NR	NR	0
Inactive Drycleaners		0.250	1	2	NR	NR	NR	3
INDIAN RESERV		1.000	0	0	0	0	NR	0
SCRD DRYCLEANERS		0.500	0	0	0	NR	NR	0
FINANCIAL ASSURANCE		TP	NR	NR	NR	NR	NR	0
COAL ASH		0.500	0	0	0	NR	NR	0
COAL ASH DOE		TP	NR	NR	NR	NR	NR	0
COAL ASH EPA		0.500	0	0	0	NR	NR	0
PCB TRANSFORMER		TP	NR	NR	NR	NR	NR	0
EDR PROPRIETARY RECORDS								
EDR Proprietary Records								
Manufactured Gas Plants		1.000	0	0	0	0	NR	0
EDR Historical Auto Stations		0.250	0	0	NR	NR	NR	0
EDR Historical Cleaners		0.250	0	0	NR	NR	NR	0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **AVIS RENT A CAR SYSTEMS INC** **RCRA-NonGen** **1000375696**
SW **11969 BELLEVUE REDMOND RD** **FINDS** **WAD180184947**
< 1/8 **BELLEVUE, WA 98005** **ALLSITES**
0.032 mi.
169 ft. **Site 1 of 3 in cluster A**

Relative:
Lower

Actual:
150 ft.

RCRA-NonGen:

Date form received by agency:	12/31/1990
Facility name:	AVIS RENT A CAR SYSTEMS INC
Site name:	AVIS RENT A CAR SYSTEM INC
Facility address:	11969 BELLEVUE-REDMOND RD BELLEVUE, WA 98004
EPA ID:	WAD180184947
Mailing address:	900 OLD COUNTRY RD GARDEN CITY, NY 11530
Contact:	KARL WESTERMANN
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(516) 222-4735
Contact email:	Not reported
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	AVIS RENT A CAR SYSTEMS INC
Owner/operator address:	900 OLD COUNTRY RD GARDEN CITY, NY 11530
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/30/1989
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/30/1989
Facility name:	AVIS RENT A CAR SYSTEMS INC
Classification:	Not a generator, verified

AVIS RENT A CAR SYSTEMS INC (Continued) **1000375696**

Violation Status: No violations found

FINDS:

Registry ID: 110005333264

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:

Facility Id:	61285922
Latitude:	47.61835
Longitude:	-122.17915
Geographic location identifier (alias facid):	61285922
Facility Name:	Avis Rent A Car Systems Inc
Latitude Decimal Degrees:	47.61835
Longitude Decimal Degrees:	-122.17915000000001
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

A2 **AVIS CAR RENTALS/BELLEVUE** **ICR** **S104486052**
SW **11968 BELLEVUE-REDMOND ROAD** **N/A**
< 1/8 **BELLEVUE, WA 98005**
0.040 mi.
210 ft. **Site 2 of 3 in cluster A**

Relative:
Lower

Actual:
149 ft.

ICR:

Date Ecology Received Report:	12/19/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-14
County Code:	17
Contact:	Not reported
Report Title:	Not reported

A3 **BARRIER MOTORS INC UST 6133** **FINDS** **1007070075**
SW **11968 BEL RED RD** **CSCSL** **N/A**
< 1/8 **BELLEVUE, WA 98005** **ALLSITES**
0.040 mi. **LUST**
210 ft. **Site 3 of 3 in cluster A** **UST**

Relative: Lower

Actual: 149 ft.

FINDS:

Registry ID: 110015466814

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

CSCSL:

Facility ID:	47423378
Region:	Northwest
Lat/Long:	47.617611405083 / -122.1801378163
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	9364
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	C
Surface Water:	Not reported
Soil:	Not reported
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	47423378
Region:	Northwest
Lat/Long:	47.617611405083 / -122.1801378163
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	9364
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Metals - Other
Ground Water:	C
Surface Water:	Not reported
Soil:	Not reported
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	47423378
Region:	Northwest
Lat/Long:	47.617611405083 / -122.1801378163
Brownfield Status:	Not reported
Rank Status:	Not reported

BARRIER MOTORS INC UST 6133 (Continued) **1007070075**

Clean Up Siteid: 9364
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Other
Ground Water: C
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 47423378
Latitude: 47.6176114
Longitude: -122.18013
Geographic location identifier (alias facid): 47423378
Facility Name: BARRIER MOTORS INC UST 6133
Latitude Decimal Degrees: 47.618220999999998
Longitude Decimal Degrees: -122.180284
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 6
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

LUST:
FS ID: 47423378
Cleanup Site ID: 9364
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: RCU
Alternate Name: AVIS CAR RENTALS/BELLEVUE
Release Notification Date: Not reported
Release Status Date: 06/01/1995
Site Response Unit Code: Northwest
Lat/Long: 47.6176114 / -122.18013

FS ID: 47423378
Cleanup Site ID: 9364
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: AVIS CAR RENTALS/BELLEVUE
Release Notification Date: Not reported
Release Status Date: 07/01/2011
Site Response Unit Code: Northwest
Lat/Long: 47.6176114 / -122.18013

FS ID: 47423378
Cleanup Site ID: 9364
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: AVIS CAR RENTALS/BELLEVUE
Release Notification Date: Not reported

BARRIER MOTORS INC UST 6133 (Continued) **1007070075**

Release Status Date: 03/02/1989
Site Response Unit Code: Northwest
Lat/Long: 47.6176114 / -122.18013

UST:
Facility ID: 47423378
Site ID: 6133
Lat Deg: Not reported
Lat Min: Not reported
Lat Sec: Not reported
Long Deg: Not reported
Long Min: Not reported
Long Sec: Not reported
UBI: 6005676950010001
Phone Number: 4256433000

Tank ID: 43760
Tank Name: 2
Install Date: 3/10/1989
Capacity: 5,000 to 9,999 Gallons
Tank Upgrade Date: 2/23/1998
TankSystem Status: Temporarily Closed
TankSystem Status Change Date: 2/24/2003
Tank Status: Temporarily Closed
Tank Permit Expiration Date: 8/31/2012
Tank Closure Date: 1/1/0001
Tank Pumping System: Pressurized System
Tank Spill Prevention: Spill Bucket/Spill Box
Tank Overfill Prevention: Ball Float Valve (vent line)
Tank Material: Fiberglass Reinforced Plastic
Tank Construction: Double Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: Corrosion Resistant
Pipe Material: Fiberglass
Pipe Construction: Secondary Containment
Pipe Primary Release Detection: Interstitial Monitoring (sump sensor)
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Corrosion Resistant
Tank Primary Release Detection: Automatic Tank Gauging
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: A3760

Tank ID: 43814
Tank Name: 1
Install Date: 12/31/1964
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported

BARRIER MOTORS INC UST 6133 (Continued) **1007070075**

Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A3760

B4 **AURORA IMPROVEMENT COMPANY** **FINDS** **1011405695**
ENE **12130 BEL RED RD** **ALLSITES** **N/A**
< 1/8 **BELLEVUE, WA 98005**
0.047 mi.
250 ft. **Site 1 of 2 in cluster B**

Relative:
Higher

Actual:
171 ft.

FINDS:

Registry ID: 110035431725

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ALLSITES:

Facility Id:	3069649
Latitude:	47.6187910
Longitude:	-122.17859
Geographic location identifier (alias facid):	3069649
Facility Name:	Aurora Improvement Company
Latitude Decimal Degrees:	47.618791000000002
Longitude Decimal Degrees:	-122.17859900000001
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	8
Location Verified Code:	Not reported

B5 **AURORA IMPROVEMENT COMPANY** **RCRA-SQG** **1010788312**
ENE **12130 BEL RED RD** **WAH000031036**
< 1/8 **BELLEVUE, WA 98005**
0.047 mi.
250 ft. **Site 2 of 2 in cluster B**

Relative:
Higher

Actual:
171 ft.

RCRA-SQG:

Date form received by agency:	05/07/2008
Facility name:	AURORA IMPROVEMENT COMPANY
Facility address:	12130 BEL RED RD BELLEVUE, WA 98005
EPA ID:	WAH000031036
Mailing address:	PO BOX 99744 SEATTLE, WA 98199
Contact:	PAM BURNS
Contact address:	PO BOX 99744 SEATTLE, WA 98199
Contact country:	US
Contact telephone:	(206)284-3688
Contact email:	Not reported
EPA Region:	10
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	AURORA IMPROVEMENT COMPANY
Owner/operator address:	PO BOX 99744 SEATTLE, WA 98199
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	12/31/2007
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/31/2007

AURORA IMPROVEMENT COMPANY (Continued) **1010788312**

Facility name: AURORA IMPROVEMENT COMPANY
Classification: Small Quantity Generator

Violation Status: No violations found

C6 **BARRIER MOTORS** **ICR** **1000361778**
West **11950 BELLEVUE-REDMOND ROAD** **N/A**
< 1/8 **BELLEVUE, WA 98005**
0.056 mi.
296 ft. **Site 1 of 4 in cluster C**

Relative:
Lower

Actual:
147 ft.

ICR:

Date Ecology Received Report:	05/10/96
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-13
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	10/10/94
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	93-41
County Code:	17
Contact:	Not reported
Report Title:	Not reported

C7 **BARRIER VOLVO SAAB** **ALLSITES** **S109556151**
West **11850 BEL RED RD** **N/A**
< 1/8 **BELLEVUE, WA 98005**
0.056 mi.
296 ft. **Site 2 of 4 in cluster C**

Relative:
Lower

Actual:
147 ft.

ALLSITES:

Facility Id:	97549164	
Latitude:	47.6177599	
Longitude:	-122.18062	
Geographic location identifier (alias facid):		97549164
Facility Name:		Barrier Volvo Saab
Latitude Decimal Degrees:		47.617759999999997
Longitude Decimal Degrees:		-122.18062
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		99
Location Verified Code:		N

C8 **BARRIER VOLVO** **RCRA-NonGen** **1000474198**
West **11850 BEL-RED ROAD** **FINDS** **WAD988482972**
< 1/8 **BELLEVUE, WA 98005**
0.056 mi.
296 ft. **Site 3 of 4 in cluster C**

Relative:
Lower

Actual:
147 ft.

RCRA-NonGen:

Date form received by agency:	03/01/2004
Facility name:	BARRIER VOLVO SAAB
Facility address:	11850 BEL RED RD BELLEVUE, WA 98005
EPA ID:	WAD988482972
Contact:	MICHAEL B MAUK
Contact address:	11850 BEL RED RD BELLEVUE, WA 98005
Contact country:	US
Contact telephone:	(425)455-5522
Contact email:	Not reported
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	JASON VEVANG
Owner/operator address:	11850 BEL RED RD BELLEVUE, WA 98005
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/01/2003
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/31/2003
Facility name:	BARRIER VOLVO SAAB
Classification:	Not a generator, verified

Date form received by agency:	03/31/1994
Facility name:	BARRIER VOLVO SAAB
Site name:	BARRIER INFINITI

BARRIER VOLVO (Continued) **1000474198**

Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110001918300

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

C9 **BARRIER MOTORS INC MERCEDES** **RCRA-CESQG** **1004613830**
West **11950 BELLEVUE REDMOND RD** **FINDS** **WAD121149546**
< 1/8 **BELLEVUE, WA 98005** **CSCSL**
0.056 mi. **ALLSITES**
296 ft. **Site 4 of 4 in cluster C** **LUST**
UST

Relative:
Lower

Actual:
147 ft.

RCRA-CESQG:

Date form received by agency: 02/20/2004
Facility name: BARRIER MOTORS INC MERCEDES
Facility address: 11950 BELLEVUE REDMOND RD
BELLEVUE, WA 98005
EPA ID: WAD121149546
Mailing address: 11950 BEL RED RD
BELLEVUE, WA 98005-2407
Contact: BOB HUMPHRY
Contact address: 11950 BEL RED RD
BELLEVUE, WA 98005-2407
Contact country: US
Contact telephone: (425)455-8535
Contact email: Not reported
EPA Region: 10
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

BARRIER MOTORS INC MERCEDES (Continued) **1004613830**

hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: BARRIER MOTORS INC MERCEDES
Owner/operator address: 11950 BEL RED RD
BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 09/05/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2003
Facility name: BARRIER MOTORS INC MERCEDES
Classification: Not a generator, verified

Date form received by agency: 03/31/1994
Facility name: BARRIER MOTORS INC MERCEDES
Site name: BARRIER MOTORS, INC.
Classification: Large Quantity Generator

Date form received by agency: 09/01/1993
Facility name: BARRIER MOTORS INC MERCEDES
Site name: BARRIER MOTORS INC
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110005331122

Environmental Interest/Information System

BARRIER MOTORS INC MERCEDES (Continued) **1004613830**

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CSCSL:

Facility ID:	81269982
Region:	Northwest
Lat/Long:	47.618121000000 / -122.1807490000
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	10595
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	C
Surface Water:	Not reported
Soil:	Not reported
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	81269982
Region:	Northwest
Lat/Long:	47.618121000000 / -122.1807490000
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	10595
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Metals - Other
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	81269982
Region:	Northwest
Lat/Long:	47.618121000000 / -122.1807490000
Brownfield Status:	Not reported
Rank Status:	Not reported

BARRIER MOTORS INC MERCEDES (Continued) **1004613830**

Clean Up Siteid: 10595
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Other
Ground Water: Not reported
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 81269982
Latitude: 47.6181210
Longitude: -122.18074
Geographic location identifier (alias facid): 81269982
Facility Name: Barrier Motors Inc Mercedes
Latitude Decimal Degrees: 47.618121000000002
Longitude Decimal Degrees: -122.18074900000001
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 7
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

LUST:
FS ID: 81269982
Cleanup Site ID: 10595
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: RCU
Alternate Name: BARRIER MOTORS
Release Notification Date: Not reported
Release Status Date: 06/01/1995
Site Response Unit Code: Northwest
Lat/Long: 47.6181210 / -122.18074

FS ID: 81269982
Cleanup Site ID: 10595
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: BARRIER MOTORS
Release Notification Date: Not reported
Release Status Date: 09/23/1994
Site Response Unit Code: Northwest
Lat/Long: 47.6181210 / -122.18074

FS ID: 81269982
Cleanup Site ID: 10595
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: BARRIER MOTORS
Release Notification Date: Not reported

BARRIER MOTORS INC MERCEDES (Continued) **1004613830**

Release Status Date: 07/01/2011
Site Response Unit Code: Northwest
Lat/Long: 47.6181210 / -122.18074

UST:
Facility ID: 81269982
Site ID: 3871
Lat Deg: 47
Lat Min: 37
Lat Sec: 5.2356000000077074
Long Deg: -122
Long Min: 10
Long Sec: 50.696400000020958
UBI: Not reported
Phone Number: 2064558535

Tank ID: 3955
Tank Name: 2.
Install Date: 11/15/1984
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Not reported
Tank Construction: Not reported
Tank Tightness Test: Not reported
Tank Corrosion Protection: Not reported
Pipe Material: Not reported
Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

Tank ID: 786
Tank Name: 1.
Install Date: 11/15/1984
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported

BARRIER MOTORS INC MERCEDES (Continued) **1004613830**

Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

10
SW
< 1/8
0.078 mi.
412 ft.

BAKKERS COIT INC **RCRA-LQG 1004793838**
12002 NE 8TH **FINDS WAD982652562**
BELLEVUE, WA 98005 **ALLSITES**
Inactive Drycleaners

Relative:
Lower

Actual:
148 ft.

RCRA-LQG:

Date form received by agency:	03/10/2000
Facility name:	BAKKERS COIT INC
Facility address:	12002 NE 8TH BELLEVUE, WA 98005
EPA ID:	WAD982652562
Mailing address:	11630 98TH AVE NE KIRKLAND, WA 980344216
Contact:	MARK SCOTT
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(425) 820-4103
Contact email:	Not reported
EPA Region:	10
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

BAKKERS COIT INC (Continued) **1004793838**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/10/2000
Facility name: BAKKERS COIT INC
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110005345411

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:
Facility Id: 98946674
Latitude: 47.61739
Longitude: -122.17977
Geographic location identifier (alias facid): 98946674
Facility Name: Bakkers Coit Inc
Latitude Decimal Degrees: 47.61739
Longitude Decimal Degrees: -122.17977999999999
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

Inactive Drycleaners:
EPA I: WAD982652562
FS Id: 10975
Facility ID: WAD982652562
NAICS Code: Not reported
Fed Waste Code Desc: Not reported
State Waste Code Desc: Not reported
TAX REG NBR: 81232
BUSINESS TYPE: Not reported
MAIL NAME: Not reported
MAIL LINE1: Not reported

BAKKERS COIT INC (Continued) **1004793838**

MAIL LINE2:	Not reported
MAIL CITY:	Not reported
MAIL STATE:	Not reported
MAIL ZIP:	Not reported
MAIL COUNTRY:	Not reported
LEGAL ORG NAME:	Not reported
LEGAL PERSON FIRST NAME:	Not reported
LEGAL PERSON MIDDLE INIT:	Not reported
LEGAL PERSON LAST NAME:	Not reported
LEGAL LINE1:	Not reported
LEGAL LINE2:	Not reported
LEGAL CITY:	Not reported
LEGAL STATE:	Not reported
LEGAL ZIP:	Not reported
LEGAL COUNTRY:	Not reported
LEGAL PHONE NBR:	Not reported
LEGAL EFFECTIVE DATE:	Not reported
LEGAL ORGANIZATION TYPE:	Not reported
LAND ORG NAME:	Not reported
LAND PERSON FIRST NAME:	Not reported
LAND PERSON MIDDLE INIT:	Not reported
LAND PERSON LAST NAME:	Not reported
LAND LINE1:	Not reported
LAND LINE2:	Not reported
LAND CITY:	Not reported
LAND STATE:	Not reported
LAND ZIP:	Not reported
LAND COUNTRY:	Not reported
LAND PHONE NBR:	Not reported
LAND ORGANIZATION TYPE:	Not reported
OPERATOR ORG NAME:	Not reported
OPERATOR PERSON FIRST NAME:	Not reported
OPERATOR PERSON MIDDLE INIT:	Not reported
OPERATOR PERSON LAST NAME:	Not reported
OPERATOR LINE1:	Not reported
OPERATOR LINE2:	Not reported
OPERATOR CITY:	Not reported
OPERATOR STATE:	Not reported
OPERATOR ZIP:	Not reported
OPERATOR COUNTRY:	Not reported
OPERATOR PHONE NBR:	Not reported
OPERATOR EFFECTIVE DATE:	Not reported
OPERATOR ORGANIZATION TYPE:	Not reported
SITE CONTACT FIRST NAME:	Not reported
SITE CONTACT MIDDLE INIT:	Not reported
SITE CONTACT LAST NAME:	Not reported
SITE CONTACT LINE1:	Not reported
SITE CONTACT LINE2:	Not reported
SITE CONTACT CITY:	Not reported
SITE CONTACT STATE:	Not reported
SITE CONTACT ZIP:	Not reported
SITE CONTACT COUNTRY:	Not reported
SITE CONTACT PHONE NBR:	Not reported
SITE CONTACT EMAIL:	Not reported
FORM CONTACT FIRST NAME:	Not reported
FORM CONTACT MIDDLE INIT:	Not reported
FORM CONTACT LAST NAME:	Not reported

BAKKERS COIT INC (Continued) **1004793838**

FORM CONTACT LINE1:	Not reported
FORM CONTACT LINE2:	Not reported
FORM CONTACT CITY:	Not reported
FORM CONTACT STATE:	Not reported
FORM CONTACT ZIP:	Not reported
FORM CONTACT COUNTRY:	Not reported
FORM CONTACT PHONE NBR:	Not reported
FORM CONTACT EMAIL:	Not reported
GEN STATUS CD:	Not reported
MONTHLY GENERATION:	Not reported
BATCH GENERATION:	Not reported
ONE TIME GENERATION:	Not reported
TRANSPORTS OWN WASTE:	Not reported
TRANSPORTS OTHERS WASTE:	Not reported
RECYCLER ONSITE:	Not reported
TRANSFER FACILITY:	Not reported
PBR:	Not reported
TBG:	Not reported
MIXED RADIOACTIVE:	Not reported
IMPORTER:	Not reported
TSDR FACILITY:	Not reported
IMMEDIATE RECYCLER:	Not reported
GEN DANG FUEL:	Not reported
GEN MARKET TO BURNER:	Not reported
GEN OTHER MARKETERS:	Not reported
UTILITY BOILER BURNER:	Not reported
INDUSTRY BOILER BURNER:	Not reported
FURNACE BURNER:	Not reported
SMELTER DEFERRAL:	Not reported
SMALL QTY EXEMPTION:	Not reported
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	Not reported
UW THERMOSTATS GEN:	Not reported
UW MERCURY GEN:	Not reported
UW LAMPS GEN:	Not reported
UW BATTERY ACCUM:	Not reported
UW THERMOSTATS ACCUM:	Not reported
UW MERCURY ACCUM:	Not reported
UW LAMPS ACCUM:	Not reported
UW DESTINATION FACILITY:	Not reported
OFF SPEC UTILITY BOILER:	Not reported
OFF SPEC INDUSTRY BOILER:	Not reported
OFF SPEC FURNACE:	Not reported
USED OIL TRANSPORTER:	Not reported
USED OIL TRANSFER FACILITY:	Not reported
USED OIL PROCESSOR:	Not reported
USED OIL REREFINER:	Not reported
USED OIL FUEL MARKETER DIR SHIPMENTS:	Not reported
USED OIL FUEL MARKETER MEETS SPECS:	Not reported
Comments:	Not reported

D11 **WILBERTON HEIGHTS (TWO REPORTS)** **ICR** **S104485931**
SE **12224 NE 8TH ST.** **N/A**
< 1/8 **BELLEVUE, WA 98005**
0.110 mi.
581 ft. **Site 1 of 2 in cluster D**

Relative:
Higher

Actual:
214 ft.

ICR:

Date Ecology Received Report:	04/13/00
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Not reported
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-25
County Code:	17
Contact:	Not reported
Report Title:	Not reported

D12 **WILBURTON HEIGHTS APARTMENTS** **ALLSITES** **S104971833**
SE **12224 NE 8TH ST** **CSCSL NFA** **N/A**
< 1/8 **BELLEVUE, WA 98005** **VCP**
0.110 mi.
581 ft. **Site 2 of 2 in cluster D**

Relative:
Higher

Actual:
214 ft.

ALLSITES:

Facility Id:	75831138	
Latitude:	47.6175270	
Longitude:	-122.17708	
Geographic location identifier (alias facid):		75831138
Facility Name:		WILBURTON HEIGHTS APARTMENTS
Latitude Decimal Degrees:		47.617527000000003
Longitude Decimal Degrees:		-122.177082
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8
Location Verified Code:		N

CSCSL NFA:

Facility/Site Id:	75831138
CS Id:	1200
NFA Type:	NFA-VCP Review
NFA Date:	05/08/2000
Rank:	Not reported

VCP:

edr_fstat:	WA
edr_fzip:	98005
edr_fcnty:	KING COUNTY
edr_zip:	Not reported
Facility ID:	75831138
VCP Status:	Not reported
VCP:	Y
Ecology Status:	Not reported
NFA Type:	NFA-VCP Review
Date NFA:	05/08/2000
Rank:	Not reported

E13
WSW
1/8-1/4
0.136 mi.
718 ft.

TEXACO #0022
12001 NE 8TH
BELLEVUE, WA 98005

Site 1 of 4 in cluster E

SPILLS **S103503715**
ICR **N/A**
FINANCIAL ASSURANCE

Relative:
Lower

Actual:
142 ft.

SPILLS:

Facility ID:	530568
Medium:	Not reported
Material Desc:	PETROLEUM - GASOLINE
Material Qty:	Not reported
Material Units:	Not reported
Date Received:	12/4/2002
Contact Name:	Not reported

Facility ID:	428774
Medium:	Not reported
Material Desc:	PETROLEUM - GASOLINE
Material Qty:	10
Material Units:	GALLON
Date Received:	2/24/1998
Contact Name:	Not reported

ICR:

Date Ecology Received Report:	05/21/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-01
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	08/14/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-07
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	05/04/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-07
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	08/11/99
Contaminants Found at Site:	Petroleum products

TEXACO #0022 (Continued) **S103503715**

Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-17
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	11/17/99
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-21
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	06/19/00
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-26
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	05/18/90
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	90-03
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	05/23/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Not reported
Site Register Issue:	91-31
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	02/05/96
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater
Waste Management:	Tank

TEXACO #0022 (Continued) **S103503715**

Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-20
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 06/21/96
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-29
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 08/03/01
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-39
County Code: 17
Contact: Not reported
Report Title: Sampling - April 2001

Date Ecology Received Report: 01/16/00
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-32
County Code: 17
Contact: Not reported
Report Title: Monitoring - October 2000

Date Ecology Received Report: 03/11/02
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-46
County Code: 17
Contact: Not reported
Report Title: Monitoring - October 2001

WA FINANCIAL ASSURANCE:
edr_fstat: WA
edr_fzip: 98005
edr_fcnty: Not reported
edr_zip: Not reported
DOE Site ID: 4427

TEXACO #0022 (Continued) **S103503715**

Site Type: PLIA
Financial Resp Type: Great American (Top Tanx)
Inception Date: 11/09/2011
Expiration Date: 11/09/2012

E14 **SHELL STATION 120546** **LUST U003026967**
WSW **12001 NE 8TH ST** **UST N/A**
1/8-1/4 **BELLEVUE, WA 98005**
0.136 mi.
718 ft. **Site 2 of 4 in cluster E**

Relative:
Lower

Actual:
142 ft.

LUST:
FS ID: 83922248
Cleanup Site ID: 6740
Cleanup Unit Type: Upland
Process Type: Voluntary Cleanup Program
Facility Status: Cleanup Started
Alternate Name: TEXACO 63 232 0022
Release Notification Date: Not reported
Release Status Date: 04/10/1990
Site Response Unit Code: Northwest
Lat/Long: 47.6173700 / -122.1798

UST:
Facility ID: 83922248
Site ID: 4427
Lat Deg: 47
Lat Min: 37
Lat Sec: 2.5320000000039045
Long Deg: -122
Long Min: 10
Long Sec: 47.280000000000655
UBI: 6022264060010021
Phone Number: 2088846658

Tank ID: 4699
Tank Name: 8
Install Date: 1/1/1990
Capacity: 10,000 to 19,999 Gallons
Tank Upgrade Date: 2/9/1998
TankSystem Status: Operational
TankSystem Status Change Date: 8/26/1996
Tank Status: Operational
Tank Permit Expiration Date: 8/31/2012
Tank Closure Date: 1/1/0001
Tank Pumping System: Pressurized System
Tank Spill Prevention: Spill Bucket/Spill Box
Tank Overfill Prevention: Ball Float Valve (vent line)
Tank Material: Fiberglass Reinforced Plastic
Tank Construction: Double Wall Tank
Tank Tightness Test: Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection: Corrosion Resistant
Pipe Material: Fiberglass
Pipe Construction: Double Wall Pipe
Pipe Primary Release Detection: Automatic Line Leak Detection
Pipe Second Release Detection: Interstitial Monitoring (sump sensor)
Pipe Corrosion Protection: Corrosion Resistant

SHELL STATION 120546 (Continued) **U003026967**

Tank Primary Release Detection: Automatic Tank Gauging
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not Required
Tank Actual Status Date: 8/6/1996
Tag Number: A0440

Tank ID: 4708
Tank Name: 4
Install Date: 12/31/1964
Capacity: 111 TO 1,100 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Steel
Tank Construction: Not reported
Tank Tightness Test: Not reported
Tank Corrosion Protection: Impressed Current
Pipe Material: Steel
Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: A0440

Tank ID: 4746
Tank Name: 6
Install Date: 1/1/1990
Capacity: 5,000 to 9,999 Gallons
Tank Upgrade Date: 2/9/1998
TankSystem Status: Operational
TankSystem Status Change Date: 8/26/1996
Tank Status: Operational
Tank Permit Expiration Date: 8/31/2012
Tank Closure Date: 1/1/0001
Tank Pumping System: Pressurized System
Tank Spill Prevention: Spill Bucket/Spill Box
Tank Overfill Prevention: Ball Float Valve (vent line)
Tank Material: Fiberglass Reinforced Plastic
Tank Construction: Double Wall Tank
Tank Tightness Test: Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection: Corrosion Resistant
Pipe Material: Fiberglass
Pipe Construction: Double Wall Pipe
Pipe Primary Release Detection: Automatic Line Leak Detection
Pipe Second Release Detection: Interstitial Monitoring (sump sensor)

SHELL STATION 120546 (Continued) **U003026967**

Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not Required
Tank Actual Status Date:	8/6/1996
Tag Number:	A0440

Tank ID:	4751
Tank Name:	2
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Impressed Current
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0440

Tank ID:	4779
Tank Name:	5
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Impressed Current
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported

SHELL STATION 120546 (Continued) **U003026967**

Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: A0440

Tank ID: 4802
Tank Name: 9
Install Date: 1/1/1990
Capacity: 5,000 to 9,999 Gallons
Tank Upgrade Date: 2/9/1998
TankSystem Status: Operational
TankSystem Status Change Date: 8/26/1996
Tank Status: Operational
Tank Permit Expiration Date: 8/31/2012
Tank Closure Date: 1/1/0001
Tank Pumping System: Pressurized System
Tank Spill Prevention: Spill Bucket/Spill Box
Tank Overfill Prevention: Ball Float Valve (vent line)
Tank Material: Fiberglass Reinforced Plastic
Tank Construction: Double Wall Tank
Tank Tightness Test: Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection: Corrosion Resistant
Pipe Material: Fiberglass
Pipe Construction: Double Wall Pipe
Pipe Primary Release Detection: Automatic Line Leak Detection
Pipe Second Release Detection: Interstitial Monitoring (sump sensor)
Pipe Corrosion Protection: Corrosion Resistant
Tank Primary Release Detection: Automatic Tank Gauging
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not Required
Tank Actual Status Date: 8/6/1996
Tag Number: A0440

Tank ID: 4812
Tank Name: 1
Install Date: 12/31/1964
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Steel
Tank Construction: Not reported
Tank Tightness Test: Not reported
Tank Corrosion Protection: Impressed Current
Pipe Material: Steel
Pipe Construction: Not reported

SHELL STATION 120546 (Continued) **U003026967**

Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: A0440

Tank ID: 4819
Tank Name: 3
Install Date: 12/31/1964
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Steel
Tank Construction: Not reported
Tank Tightness Test: Not reported
Tank Corrosion Protection: Impressed Current
Pipe Material: Steel
Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: A0440

Tank ID: 4845
Tank Name: 7
Install Date: 1/1/1990
Capacity: 10,000 to 19,999 Gallons
Tank Upgrade Date: 2/9/1998
TankSystem Status: Operational
TankSystem Status Change Date: 8/26/1996
Tank Status: Operational
Tank Permit Expiration Date: 8/31/2012
Tank Closure Date: 1/1/0001
Tank Pumping System: Pressurized System
Tank Spill Prevention: Spill Bucket/Spill Box
Tank Overfill Prevention: Ball Float Valve (vent line)
Tank Material: Fiberglass Reinforced Plastic
Tank Construction: Double Wall Tank
Tank Tightness Test: Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection: Corrosion Resistant
Pipe Material: Fiberglass

SHELL STATION 120546 (Continued) **U003026967**

Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Interstitial Monitoring (sump sensor)
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not Required
Tank Actual Status Date:	8/6/1996
Tag Number:	A0440

E15 **SHELL STATION 120546** **RCRA-NonGen** **1000144968**
WSW **12001 NORTHEAST 8TH STREET** **FINDS** **WAD982652547**
1/8-1/4 **BELLEVUE, WA 98005** **CSCSL**
0.136 mi. **ALLSITES**
718 ft. **Site 3 of 4 in cluster E** **MANIFEST**
SPILLS
Relative: **VCP**
Lower

Actual: **142 ft.**

RCRA-NonGen:

Date form received by agency:	01/25/2010
Facility name:	SHELL STATION 120546
Facility address:	12001 NE 8TH ST BELLEVUE, WA 98005
EPA ID:	WAD982652547
Mailing address:	P O BOX 3127 RM 685 HOUSTON, TX 77253
Contact:	RAY E WALDING
Contact address:	P O BOX 3127 HOUSTON, TX 77253
Contact country:	US
Contact telephone:	(713) 241-7008
Contact email:	RAY.WALDING@SHELL.COM
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	EQUILON ENTERPRISES LLC
Owner/operator address:	P O BOX 3127 RM 685 HOUSTON, 77253
Owner/operator country:	US
Owner/operator telephone:	713-241-7008
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/01/1998
Owner/Op end date:	Not reported

Owner/operator name:	EQUILION ENTERPRISES LLC DBA SHELL OIL P
Owner/operator address:	P O BOX 3127 RM685 HOUSTON, 77253
Owner/operator country:	US
Owner/operator telephone:	713-241-7008
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	08/26/1996
Owner/Op end date:	Not reported

SHELL STATION 120546 (Continued) **1000144968**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/12/2008
Facility name: SHELL STATION 120546
Classification: Small Quantity Generator

Date form received by agency: 12/31/2007
Facility name: SHELL STATION 120546
Classification: Small Quantity Generator

Date form received by agency: 12/31/2005
Facility name: SHELL STATION 120546
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: SHELL STATION 120546
Classification: Not a generator, verified

Date form received by agency: 03/02/1998
Facility name: SHELL STATION 120546
Site name: TEXACO 63232 0022
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110000828891

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

SHELL STATION 120546 (Continued) **1000144968**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CSCSL:

Facility ID:	83922248
Region:	Northwest
Lat/Long:	47.617370000000 / -122.1798
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	6740
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	83922248
Region:	Northwest
Lat/Long:	47.617370000000 / -122.1798
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	6740
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Gasoline
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

ALLSITES:

Facility Id:	83922248
Latitude:	47.6173700
Longitude:	-122.1798
Geographic location identifier (alias facid):	83922248
Facility Name:	Shell Station 120546
Latitude Decimal Degrees:	47.617370000000001
Longitude Decimal Degrees:	-122.1798
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	8
Location Verified Code:	N

SHELL STATION 120546 (Continued) **1000144968**

WA MANIFEST:

Facility Site ID Number:	83922248
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2010
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD982652547
Facility Address 2:	Not reported
TAX REG NBR:	601238698
NAICS CD:	447110
BUSINESS TYPE:	GASOLINE SERVICE STATION
MAIL NAME:	Shell Oil Products US
MAIL ADDR LINE1:	P O Box 3127
MAIL ADDR LINE2:	rm 685
MAIL CITY,ST,ZIP:	HOUSTON, TX 77253
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Equilon Enterprises LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	P O Box 3127
LEGAL ADDR LINE2:	rm 685
LEGAL CITY,ST,ZIP:	HOUSTON, TX 77253
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	713-241-7008
LEGAL EFFECTIVE DATE:	8/1/1998
LAND ORG NAME:	Equilion Enterprises LLC dba Shell Oil P
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO Box 2099
LAND CITY,ST,ZIP:	HOUSTON, TX 77252-2099
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	713-241-7008
OPERATOR ORG NAME:	Equilion Enterprises LLC dba Shell Oil P

SHELL STATION 120546 (Continued) **1000144968**

OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	P O Box 3127
OPERATOR ADDR LINE2:	rm685
OPERATOR CITY,ST,ZIP:	HOUSTON, TX 77253
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	713-241-7008
OPERATOR EFFECTIVE DATE:	8/26/1996
SITE CONTACT NAME:	RAY E WALDING
SITE CONTACT ADDR LINE1:	P O BOX 3127
SITE CONTACT ZIP:	HOUSTON, TX 77253
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	713-241-7008
SITE CONTACT EMAIL:	RAY.WALDING@SHELL.COM
FORM CONTACT NAME:	Jeanne Traylor
FORM CONTACT ADDR LINE1:	P O Box 3127, Rm 669B
FORM CONTACT CITY,ST,ZIP:	HOUSTON, TX 77253
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	713-241-6992
FORM CONTACT EMAIL:	jeanne.traylor@shell.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	83922248
SWC Desc:	Not reported
FWC Desc:	D001 D018D001
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE

SHELL STATION 120546 (Continued) **1000144968**

Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD982652547
Facility Address 2:	Not reported
TAX REG NBR:	601238698
NAICS CD:	447110
BUSINESS TYPE:	GASOLINE SERVICE STATION
MAIL NAME:	Shell Oil Products US
MAIL ADDR LINE1:	12700 NORTHBOROUGH DR
MAIL ADDR LINE2:	NOB 300G04 - RACHEL HULL
MAIL CITY,ST,ZIP:	HOUSTON, TX 77067-2508
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Equilon Enterprises LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO BOX 2099
LEGAL ADDR LINE2:	NOB #300G04
LEGAL CITY,ST,ZIP:	HOUSTON, TX 77252-2099
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	281-874-2224
LEGAL EFFECTIVE DATE:	8/1/1998
LAND ORG NAME:	Equilion Enterprises LLC dba Shell Oil P
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO Box 2099
LAND ADDR LINE2:	NOB #300G04
LAND CITY,ST,ZIP:	HOUSTON, TX 77252-2099
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	281-874-2224
OPERATOR ORG NAME:	Equilion Enterprises LLC dba Shell Oil P
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	12700 NORTHBOROUGH DR
OPERATOR ADDR LINE2:	300F07
OPERATOR CITY,ST,ZIP:	HOUSTON, TX 77252-2099
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	281-874-2238
OPERATOR EFFECTIVE DATE:	8/26/1996
SITE CONTACT NAME:	DON F WISDOM
SITE CONTACT ADDR LINE1:	12700 NORTHBOROUGH DR
SITE CONTACT ADDR LINE2:	300F07
SITE CONTACT ZIP:	HOUSTON, TX 77252-2099
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	281-874-2238
SITE CONTACT EMAIL:	DON.F.WISDOM@SHELL.COM
FORM CONTACT NAME:	RACHEL HULL
FORM CONTACT ADDR LINE1:	12700 NORTHBOROUGH DR
FORM CONTACT ADDR LINE2:	NOB #300G04
FORM CONTACT CITY,ST,ZIP:	HOUSTON, TX 77067-2508
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(281) 874-2224
FORM CONTACT EMAIL:	RACHEL.HULL@SHELL.COM

SHELL STATION 120546 (Continued) **1000144968**

GEN STATUS CD:	SQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	FALSE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

Facility Site ID Number:	83922248
SWC Desc:	Not reported
FWC Desc:	D001 D018D001
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD982652547
Facility Address 2:	Not reported
TAX REG NBR:	601238698
NAICS CD:	447110
BUSINESS TYPE:	GASOLINE SERVICE STATION
MAIL NAME:	Shell Oil Products US
MAIL ADDR LINE1:	12700 NORTHBOROUGH DR
MAIL ADDR LINE2:	NOB 300G03 - RACHEL WILLIAMSON
MAIL CITY,ST,ZIP:	HOUSTON, TX 77067-2508
MAIL COUNTRY:	UNITED STATES

SHELL STATION 120546 (Continued) **1000144968**

LEGAL ORG NAME:	Equilon Enterprises LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO BOX 2099
LEGAL ADDR LINE2:	NOB #300G03
LEGAL CITY,ST,ZIP:	HOUSTON, TX 77252-2099
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	281-874-2224
LEGAL EFFECTIVE DATE:	8/1/1998
LAND ORG NAME:	Equilion Enterprises LLC dba Shell Oil P
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO Box 2099
LAND ADDR LINE2:	NOB #300G03
LAND CITY,ST,ZIP:	HOUSTON, TX 77252-2099
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	281-874-2224
OPERATOR ORG NAME:	Equilion Enterprises LLC dba Shell Oil P
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	12700 NORTHBOROUGH DR
OPERATOR ADDR LINE2:	300F07
OPERATOR CITY,ST,ZIP:	HOUSTON, TX 77252-2099
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	281-874-2238
OPERATOR EFFECTIVE DATE:	8/26/1996
SITE CONTACT NAME:	DON F WISDOM
SITE CONTACT ADDR LINE1:	12700 NORTHBOROUGH DR
SITE CONTACT ADDR LINE2:	300F07
SITE CONTACT ZIP:	HOUSTON, TX 77252-2099
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	281-874-2238
SITE CONTACT EMAIL:	DON.F.WISDOM@SHELL.COM
FORM CONTACT NAME:	RACHEL WILLIAMSON
FORM CONTACT ADDR LINE1:	12700 NORTHBOROUGH DR
FORM CONTACT ADDR LINE2:	NOB #300G03
FORM CONTACT CITY,ST,ZIP:	HOUSTON, TX 77067-2508
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(281) 874-2224
FORM CONTACT EMAIL:	RACHEL.WILLIAMSON@SHELL.COM
GEN STATUS CD:	SQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Facility Site ID Number:	83922248
SWC Desc:	Not reported

SHELL STATION 120546 (Continued) **1000144968**

FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2009
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD982652547
Facility Address 2:	Not reported
TAX REG NBR:	601238698
NAICS CD:	447110
BUSINESS TYPE:	GASOLINE SERVICE STATION
MAIL NAME:	Shell Oil Products US
MAIL ADDR LINE1:	P O Box 3127
MAIL ADDR LINE2:	rm 685
MAIL CITY,ST,ZIP:	HOUSTON, TX 77253
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Equilon Enterprises LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	P O Box 3127
LEGAL ADDR LINE2:	rm 685
LEGAL CITY,ST,ZIP:	HOUSTON, TX 77253
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	713-241-7008
LEGAL EFFECTIVE DATE:	8/1/1998
LAND ORG NAME:	Equilion Enterprises LLC dba Shell Oil P
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO Box 2099
LAND CITY,ST,ZIP:	HOUSTON, TX 77252-2099
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	713-241-7008
OPERATOR ORG NAME:	Equilion Enterprises LLC dba Shell Oil P
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	P O Box 3127
OPERATOR ADDR LINE2:	rm685

SHELL STATION 120546 (Continued) **1000144968**

OPERATOR CITY,ST,ZIP:	HOUSTON, TX 77253
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	713-241-7008
OPERATOR EFFECTIVE DATE:	8/26/1996
SITE CONTACT NAME:	RAY E WALDING
SITE CONTACT ADDR LINE1:	P O BOX 3127
SITE CONTACT ZIP:	HOUSTON, TX 77253
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	713-241-7008
SITE CONTACT EMAIL:	RAY.WALDING@SHELL.COM
FORM CONTACT NAME:	Jeanne Traylor
FORM CONTACT ADDR LINE1:	P O BOX 3127
FORM CONTACT ADDR LINE2:	RM 685
FORM CONTACT CITY,ST,ZIP:	HOUSTON, TX 77253
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	713-241-6992
FORM CONTACT EMAIL:	jeanne.traylor@shell.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	83922248
SWC Desc:	Not reported
FWC Desc:	D001, D018
Form Comm:	Not reported
Data Year:	2008
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False

SHELL STATION 120546 (Continued) **1000144968**

Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD982652547
Facility Address 2:	Not reported
TAX REG NBR:	601238698
NAICS CD:	447110
BUSINESS TYPE:	GASOLINE SERVICE STATION
MAIL NAME:	Shell Oil Products US
MAIL ADDR LINE1:	12700 NORTHBOROUGH DR
MAIL ADDR LINE2:	NOB 300G04 - RACHEL HULL
MAIL CITY,ST,ZIP:	HOUSTON, TX 77067-2508
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Equilon Enterprises LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO BOX 2099
LEGAL ADDR LINE2:	NOB #300G04
LEGAL CITY,ST,ZIP:	HOUSTON, TX 77252-2099
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	281-874-2224
LEGAL EFFECTIVE DATE:	8/1/1998
LAND ORG NAME:	Equilion Enterprises LLC dba Shell Oil P
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO Box 2099
LAND ADDR LINE2:	NOB #300G04
LAND CITY,ST,ZIP:	HOUSTON, TX 77252-2099
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	281-874-2224
OPERATOR ORG NAME:	Equilion Enterprises LLC dba Shell Oil P
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	12700 NORTHBOROUGH DR
OPERATOR ADDR LINE2:	300F08
OPERATOR CITY,ST,ZIP:	HOUSTON, TX 77252-2099
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	281-874-2247
OPERATOR EFFECTIVE DATE:	8/26/1996
SITE CONTACT NAME:	RAY E WALDING
SITE CONTACT ADDR LINE1:	12700 NORTHBOROUGH DR
SITE CONTACT ADDR LINE2:	300F08
SITE CONTACT ZIP:	HOUSTON, TX 77252-2099
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	281-874-2247
SITE CONTACT EMAIL:	RAY.WALDING@SHELL.COM
FORM CONTACT NAME:	Jeanne Traylor
FORM CONTACT ADDR LINE1:	12700 NORTHBOROUGH DR
FORM CONTACT ADDR LINE2:	NOB #300G04
FORM CONTACT CITY,ST,ZIP:	HOUSTON, TX 77067-2508
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(281) 874-2224
FORM CONTACT EMAIL:	jeanne.traylor@shell.com
GEN STATUS CD:	LQG
MONTHLY GENERATION:	False

SHELL STATION 120546 (Continued) **1000144968**

BATCH GENERATION: False
ONE TIME GENERATION: False
TRANSPORTS OWN WASTE: False
TRANSPORTS OTHRS WASTE: False
RECYCLER ONSITE: False
TRANSFER FACILITY: False
OTHER EXEMPTION: Not reported
UW BATTERY GEN: False
USED OIL TRANSPORTER: False
USED OIL TRANSFER FACLTY: False
USED OIL PROCESSOR: False
USED OIL REREFINER: False
USED OIL FUEL MRKTR DIRECTS SHPMNTS: False
USED OIL FUEL MRKTR MEETS SPECS: False

Click this hyperlink while viewing on your computer to access
1 additional WA MANIFEST: record(s) in the EDR Site Report.

SPILLS:
Facility ID: 541394
Medium: Not reported
Material Desc: PETROLEUM - GASOLINE
Material Qty: 1
Material Units: GALLON
Date Received: 6/11/2004
Contact Name: Haq

VCP:
edr_fstat: WA
edr_fzip: 98005-3110
edr_fcnty: KING COUNTY
edr_zip: Not reported
Facility ID: 83922248
VCP Status: VCP
VCP: Not reported
Ecology Status: Cleanup Started
NFA Type: Cleanup Started
Date NFA: Cleanup Started
Rank: Cleanup Started

E16 **HC AUTO CARE INC BELLEVUE** **RCRA-NonGen** **1000838393**
SW **11807 & 11817 NE 8TH ST** **FINDS** **WAD988511713**
1/8-1/4 **BELLEVUE, WA 98005** **ALLSITES**
0.152 mi.
805 ft. **Site 4 of 4 in cluster E**

Relative:
Lower

Actual:
142 ft.

RCRA-NonGen:
Date form received by agency: 12/02/1997
Facility name: HC AUTO CARE INC BELLEVUE
Facility address: 11807 & 11817 NE 8TH ST
BELLEVUE, WA 98004
EPA ID: WAD988511713
Mailing address: 11807 NE 8TH ST
BELLEVUE, WA 98004-0000
Contact: LON HAYS
Contact address: 11807 NE 8TH ST
BELLEVUE, WA 98004-0000

HC AUTO CARE INC BELLEVUE (Continued) **1000838393**

Contact country: US
Contact telephone: (425)637-1935
Contact email: Not reported
EPA Region: 10
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: HC AUTO CARE INC
Owner/operator address: 11807 NE 8TH ST
BELLEVUE, WA 98004
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/03/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110008225107

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:
Facility Id: 93425562
Latitude: 47.6174299
Longitude: -122.18454
Geographic location identifier (alias facid): 93425562
Facility Name: HC Auto Care Inc Bellevue

HC AUTO CARE INC BELLEVUE (Continued) **1000838393**

Latitude Decimal Degrees:	47.617429999999999
Longitude Decimal Degrees:	-122.18454
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

F17 **BELLEVUE AUTO TECH INC** **RCRA-NonGen** **1000659014**
North **12005 NE 12TH STE 12** **FINDS** **WAD988486767**
1/8-1/4 **BELLEVUE, WA 98005** **ALLSITES**
0.156 mi.
824 ft. **Site 1 of 5 in cluster F**

Relative:
Lower

Actual:
151 ft.

RCRA-NonGen:

Date form received by agency:	01/24/2001
Facility name:	BELLEVUE AUTO TECH INC
Facility address:	12005 NE 12TH STE 12 BELLEVUE, WA 98005
EPA ID:	WAD988486767
Mailing address:	25930 124TH AVE SE KENT, WA 98031-7808
Contact:	STEFAN PIECZATKOWSKI
Contact address:	25930 124TH AVE SE KENT, WA 98031-7808
Contact country:	US
Contact telephone:	(425)454-9779
Contact email:	Not reported
EPA Region:	10
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BELLEVUE AUTO TECH INC
Owner/operator address:	25930 124TH AVE SE KENT, WA 98031
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/02/1996
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

BELLEVUE AUTO TECH INC (Continued) **1000659014**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 12/17/1997
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/03/1997
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005361125

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:
Facility Id: 87439143
Latitude: 47.6206400
Longitude: -122.17827
Geographic location identifier (alias facid): 87439143
Facility Name: Bellevue Auto Tech Inc
Latitude Decimal Degrees: 47.620640000000002
Longitude Decimal Degrees: -122.17827
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

F18 **ESCHEN AUTOMOTIVE INC NE 12TH** **RCRA-CESQG** **1004794806**
North **12005 NE 12TH ST NO 14** **FINDS** **WAH000008136**
1/8-1/4 **BELLEVUE, WA 98005** **ALLSITES**
0.156 mi.
824 ft. **Site 2 of 5 in cluster F**

Relative:
Lower

Actual:
151 ft.

RCRA-CESQG:
Date form received by agency: 02/19/2004
Facility name: ESCHEN AUTOMOTIVE INC NE 12TH
Facility address: 12005 NE 12TH ST NO 14
BELLEVUE, WA 98005

ESCHEN AUTOMOTIVE INC NE 12TH (Continued) **1004794806**

EPA ID: WAH000008136
Mailing address: 12005 NE 12TH ST #14
BELLEVUE, WA 98005
Contact: GARY H ESCHEN
Contact address: 12005 NE 12TH ST #14
BELLEVUE, WA 98005
Contact country: US
Contact telephone: (425)456-0466
Contact email: Not reported
EPA Region: 10
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: ESCHEN AUTOMOTIVE INC NE 12TH
Owner/operator address: 12005 NE 12TH ST #14
BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 04/06/1999
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2003

ESCHEN AUTOMOTIVE INC NE 12TH (Continued) **1004794806**

Facility name: ESCHEN AUTOMOTIVE INC NE 12TH
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110005395045

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ALLSITES:

Facility Id:	59567759
Latitude:	47.6500410
Longitude:	-122.17734
Geographic location identifier (alias facid):	59567759
Facility Name:	Eschen Automotive Inc NE 12th
Latitude Decimal Degrees:	47.650041000000002
Longitude Decimal Degrees:	-122.17734400000001
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	8
Location Verified Code:	N

F19 **MIDAS AUTO SERVICE EXPERTS BELLEVUE** **RCRA-CESQG** **1004794200**
North **12005 NE 12TH ST** **PADS** **WAD988495958**
1/8-1/4 **BELLEVUE, WA 98005** **FINDS**
0.156 mi. **ALLSITES**
824 ft. **Site 3 of 5 in cluster F** **MANIFEST**

Relative:
Lower

Actual:
151 ft.

RCRA-CESQG:

Date form received by agency:	02/15/2010
Facility name:	MIDAS AUTO SERVICE EXPERTS BELLEVUE
Facility address:	12005 NE 12TH ST BELLEVUE, WA 98005
EPA ID:	WAD988495958
Mailing address:	17311 135TH AVE NE A450 WOODINVILLE, WA 98072
Contact:	KEVIN MCKENNEY
Contact address:	17311 135TH AVE NE A450 WOODINVILLE, WA 98072

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

Contact country: US
Contact telephone: (425) 424-0726
Contact email: KNMCKENNEY@COMCAST.NET
EPA Region: 10
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: SILENCE INC DBA MASE
Owner/operator address: 17311 135TH AVE NE A450
WOODINVILLE, 98072
Owner/operator country: US
Owner/operator telephone: (425)424-0726
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/01/1998
Owner/Op end date: Not reported

Owner/operator name: SILENCE INC
Owner/operator address: 17311 135TH AVE NE A450
WOODINVILLE, 98072
Owner/operator country: US
Owner/operator telephone: 425424-0726
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/22/1996
Owner/Op end date: Not reported

Owner/operator name: SILENCE INC
Owner/operator address: 17311 135TH AVE NE B-400
WOODINVILLE, WA 98072
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/22/1996
Owner/Op end date: Not reported

Owner/operator name: SILENCE INC DBA MASE
Owner/operator address: 17311 135TH AVE NE B400
WOODINVILLE, WA 98072
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

Owner/Operator Type: Owner
Owner/Op start date: 10/01/1998
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/08/2008
Facility name: MIDAS AUTO SERVICE EXPERTS BELLEVUE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/31/2007
Facility name: MIDAS AUTO SERVICE EXPERTS BELLEVUE
Classification: Not a generator, verified

Date form received by agency: 12/31/2005
Facility name: MIDAS AUTO SERVICE EXPERTS BELLEVUE
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: MIDAS AUTO SERVICE EXPERTS BELLEVUE
Classification: Not a generator, verified

Hazardous Waste Summary:
Waste code: WSQG
Waste name: A placeholder to allow BR submission to validate. In WA State, Conditionally Exempt Small Quantity Generators (Called SQG in WA) are not required to report waste streams, so no valid State or Fed codes are available for reporting to BR.

Violation Status: No violations found

PADS:
EPAID: WAD988495958
Facility name: MIDAS AUTO SERVICE EXPERTS BELLEVUE
Facility Address: 12005 NE 12TH ST
BELLEVUE, WA 98005
Facility country: US
Generator: No
Storer: Yes
Transporter: No

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

Disposer:	No
Research facility:	No
Smelter:	No
Facility owner name:	SILENCE INC
Contact title:	FIELD OPERATIONS MANAGER
Contact name:	ED WRIGHT
Contact tel:	206-388-9198
Contact extension:	Not reported
Mailing address:	17311 135TH AVE NE A450 WOODINVILLE, WA 98072
Mailing country:	US
Cert. title:	FIELD OPERATIONS MANAGER
Cert. name:	ED WRIGHT
Cert. date:	11/14/2008
Date received:	12/1/2008

FINDS:

Registry ID: 110009511910

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

ALLSITES:

Facility Id:	86543618
Latitude:	47.6206400

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

Longitude:	-122.17827
Geographic location identifier (alias facid):	86543618
Facility Name:	Midas Auto Service Experts Bellevue
Latitude Decimal Degrees:	47.620640000000002
Longitude Decimal Degrees:	-122.17827
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

WA MANIFEST:

Facility Site ID Number:	86543618
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2010
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD988495958
Facility Address 2:	Not reported
TAX REG NBR:	600179738
NAICS CD:	811112
BUSINESS TYPE:	Auto Repair
MAIL NAME:	Silence Inc dba MASE
MAIL ADDR LINE1:	17311 135th Ave NE A450
MAIL CITY,ST,ZIP:	WOODINVILLE, WA 98072
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Silence Inc dba MASE
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	17311 135th Ave NE A450
LEGAL CITY,ST,ZIP:	WOODINVILLE, WA 98072
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)424-0726

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

LEGAL EFFECTIVE DATE:	10/1/1998
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Hal Woosley
LAND ADDR LINE1:	PO Box 3325
LAND CITY,ST,ZIP:	BELLEVUE, WA 98009-3325
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-5730
OPERATOR ORG NAME:	Silence Inc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	17311 135TH AVE NE A450
OPERATOR CITY,ST,ZIP:	WOODINVILLE, WA 98072
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425424-0726
OPERATOR EFFECTIVE DATE:	8/22/1996
SITE CONTACT NAME:	Kevin Mckenney
SITE CONTACT ADDR LINE1:	17311 135TH AVE NE A450
SITE CONTACT ZIP:	WOODINVILLE, WA 98072
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425424-0726
SITE CONTACT EMAIL:	knmckenney@comcast.net
FORM CONTACT NAME:	Kevin Mckenney
FORM CONTACT ADDR LINE1:	17311 135TH AVE NE A450
FORM CONTACT CITY,ST,ZIP:	WOODINVILLE, WA 98072
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425424-0726
FORM CONTACT EMAIL:	knmckenney@mac.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	True
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	86543618
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD988495958
Facility Address 2:	Not reported
TAX REG NBR:	600179738
NAICS CD:	811112
BUSINESS TYPE:	Auto Repair
MAIL NAME:	Silence Inc dba MASE
MAIL ADDR LINE1:	17311 135th Ave NE B400
MAIL CITY,ST,ZIP:	WOODINVILLE, WA 98072
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Silence Inc dba MASE
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	17311 135th Ave NE B400
LEGAL CITY,ST,ZIP:	WOODINVILLE, WA 98072
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)424-0726
LEGAL EFFECTIVE DATE:	10/1/1998
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Hal Woosley
LAND ADDR LINE1:	PO Box 3325
LAND CITY,ST,ZIP:	BELLEVUE, WA 98009-3325
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-5730
OPERATOR ORG NAME:	Silence Inc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	17311 135TH AVE NE B-400
OPERATOR CITY,ST,ZIP:	WOODINVILLE, WA 98072
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425424-0726
OPERATOR EFFECTIVE DATE:	08/22/96
SITE CONTACT NAME:	Kevin Mckenney
SITE CONTACT ADDR LINE1:	17311 135TH AVE NE B-400
SITE CONTACT ZIP:	WOODINVILLE, WA 98072
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425424-0726
SITE CONTACT EMAIL:	knmckenney@comcast.net
FORM CONTACT NAME:	Kevin Mckenney
FORM CONTACT ADDR LINE1:	17311 135TH AVE NE B-400
FORM CONTACT CITY,ST,ZIP:	WOODINVILLE, WA 98072
FORM CONTACT COUNTRY:	UNITED STATES

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

FORM CONTACT PHONE NBR:	425424-0726
FORM CONTACT EMAIL:	knmckenney@mac.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	86543618
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD988495958
Facility Address 2:	Not reported
TAX REG NBR:	600179738
NAICS CD:	811112
BUSINESS TYPE:	Auto Repair
MAIL NAME:	Silence Inc dba MASE
MAIL ADDR LINE1:	17311 135th Ave NE B400
MAIL CITY,ST,ZIP:	WOODINVILLE, WA 98072

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Silence Inc dba MASE
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	17311 135th Ave NE B400
LEGAL CITY,ST,ZIP:	WOODINVILLE, WA 98072
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)424-0726
LEGAL EFFECTIVE DATE:	10/1/1998
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Hal Woosley
LAND ADDR LINE1:	PO Box 3325
LAND CITY,ST,ZIP:	BELLEVUE, WA 98009-3325
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-5730
OPERATOR ORG NAME:	Silence Inc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	17311 135TH AVE NE B-400
OPERATOR CITY,ST,ZIP:	WOODINVILLE, WA 98072
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425424-0726
OPERATOR EFFECTIVE DATE:	8/22/1996
SITE CONTACT NAME:	Kevin Mckenney
SITE CONTACT ADDR LINE1:	17311 135TH AVE NE B-400
SITE CONTACT ZIP:	WOODINVILLE, WA 98072
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425424-0726
SITE CONTACT EMAIL:	knmckenney@comcast.net
FORM CONTACT NAME:	Kevin Mckenney
FORM CONTACT ADDR LINE1:	17311 135TH AVE NE B-400
FORM CONTACT CITY,ST,ZIP:	WOODINVILLE, WA 98072
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425424-0726
FORM CONTACT EMAIL:	knmckenney@comcast.net
GEN STATUS CD:	SQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	FALSE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

Facility Site ID Number:	86543618
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2009
Permit by Rule:	False

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD988495958
Facility Address 2:	Not reported
TAX REG NBR:	600179738
NAICS CD:	811112
BUSINESS TYPE:	Auto Repair
MAIL NAME:	Silence Inc dba MASE
MAIL ADDR LINE1:	17311 135th Ave NE A450
MAIL CITY,ST,ZIP:	WOODINVILLE, WA 98072
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Silence Inc dba MASE
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	17311 135th Ave NE A450
LEGAL CITY,ST,ZIP:	WOODINVILLE, WA 98072
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)424-0726
LEGAL EFFECTIVE DATE:	10/1/1998
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Hal Woosley
LAND ADDR LINE1:	PO Box 3325
LAND CITY,ST,ZIP:	BELLEVUE, WA 98009-3325
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-5730
OPERATOR ORG NAME:	Silence Inc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	17311 135TH AVE NE A450
OPERATOR CITY,ST,ZIP:	WOODINVILLE, WA 98072
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425424-0726
OPERATOR EFFECTIVE DATE:	8/22/1996
SITE CONTACT NAME:	Kevin Mckenney
SITE CONTACT ADDR LINE1:	17311 135TH AVE NE A450
SITE CONTACT ZIP:	WOODINVILLE, WA 98072

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425424-0726
SITE CONTACT EMAIL:	knmckenney@comcast.net
FORM CONTACT NAME:	Kevin Mckenney
FORM CONTACT ADDR LINE1:	17311 135TH AVE NE A450
FORM CONTACT CITY,ST,ZIP:	WOODINVILLE, WA 98072
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425424-0726
FORM CONTACT EMAIL:	knmckenney@mac.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	True
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	86543618
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD988495958

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

Facility Address 2:	Not reported
TAX REG NBR:	600179738
NAICS CD:	811112
BUSINESS TYPE:	Auto Repair
MAIL NAME:	Silence Inc dba MASE
MAIL ADDR LINE1:	17311 135th Ave NE B400
MAIL CITY,ST,ZIP:	WOODINVILLE, WA 98072
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Silence Inc dba MASE
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	17311 135th Ave NE B400
LEGAL CITY,ST,ZIP:	WOODINVILLE, WA 98072
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)424-0726
LEGAL EFFECTIVE DATE:	10/1/1998
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Hal Woosley
LAND ADDR LINE1:	PO Box 3325
LAND CITY,ST,ZIP:	BELLEVUE, WA 98009-3325
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-5730
OPERATOR ORG NAME:	Silence Inc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	17311 135TH AVE NE B-400
OPERATOR CITY,ST,ZIP:	WOODINVILLE, WA 98072
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425424-0726
OPERATOR EFFECTIVE DATE:	8/22/1996
SITE CONTACT NAME:	Kevin Mckenney
SITE CONTACT ADDR LINE1:	17311 135TH AVE NE B-400
SITE CONTACT ZIP:	WOODINVILLE, WA 98072
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425424-0726
SITE CONTACT EMAIL:	knmckenney@comcast.net
FORM CONTACT NAME:	Kevin Mckenney
FORM CONTACT ADDR LINE1:	17311 135TH AVE NE B-400
FORM CONTACT CITY,ST,ZIP:	WOODINVILLE, WA 98072
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425424-0726
FORM CONTACT EMAIL:	knmckenney@comcast.net
GEN STATUS CD:	SQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

MIDAS AUTO SERVICE EXPERTS BELLEVUE (Continued) **1004794200**

Click this hyperlink while viewing on your computer to access
1 additional WA MANIFEST: record(s) in the EDR Site Report.

F20 **ACCUTINT** **ALLSITES** **S110123721**
North **12003 NE 12TH ST STE 74** **N/A**
1/8-1/4 **BELLEVUE, WA 98005**
0.157 mi.
827 ft. **Site 4 of 5 in cluster F**

Relative:
Lower

Actual:
151 ft.

ALLSITES:

Facility Id:	22086	
Latitude:	47.6205526	
Longitude:	-122.17957	
Geographic location identifier (alias facid):		22086
Facility Name:		Accutint
Latitude Decimal Degrees:		47.620552636900001
Longitude Decimal Degrees:		-122.179579831
Coordinate Point Areal Extent Code:		0
Horizontal Accuracy Code:		6
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported
Geographic Location Identifier (Alias Facid):		22086
Interaction (Aka Env Int) Type Code:		LSC
Interaction (Aka Env Int) Description:		Local Source Control
Interaction Status:		I
Federal Program Indentifier:		Not reported
Interaction Start Date:		05/14/2009
Interaction End Date:		04/29/2010
prgm_facil:		Accutint
cur_sys_pr:		HAZWASTE
cur_sys_nm:		LSC

F21 **BEL RED TRANSMISSIONS INC** **ALLSITES** **S109824188**
North **12003 NE 12TH ST** **N/A**
1/8-1/4 **BELLEVUE, WA 98005**
0.157 mi.
827 ft. **Site 5 of 5 in cluster F**

Relative:
Lower

Actual:
151 ft.

ALLSITES:

Facility Id:	11444	
Latitude:	47.6205580	
Longitude:	-122.17958	
Geographic location identifier (alias facid):		11444
Facility Name:		Bel Red Transmissions Inc
Latitude Decimal Degrees:		47.620558000000003
Longitude Decimal Degrees:		-122.17958
Coordinate Point Areal Extent Code:		0
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported
Geographic Location Identifier (Alias Facid):		11444
Interaction (Aka Env Int) Type Code:		LSC

BEL RED TRANSMISSIONS INC (Continued) **S109824188**

Interaction (Aka Env Int) Description:	Local Source Control
Interaction Status:	I
Federal Program Indentifier:	Not reported
Interaction Start Date:	06/05/2009
Interaction End Date:	04/29/2010
prgm_facil:	Bel-Red Transmissions Inc
cur_sys_pr:	HAZWASTE
cur_sys_nm:	LSC

G22 **HI TECH CLEANERS BELLEVUE** **RCRA-CESQG** **1001490631**
SSW **661 120TH AVE NE STE 15B** **FINDS** **WAD988481966**
1/8-1/4 **BELLEVUE, WA 98005** **CSCSL**
0.160 mi. **ALLSITES**
846 ft. **Site 1 of 5 in cluster G** **MANIFEST**
VCP
Relative: **Inactive Drycleaners**
Lower

Actual: **149 ft.**

RCRA-CESQG:

Date form received by agency:	03/16/2008
Facility name:	HI TECH CLEANERS BELLEVUE
Facility address:	661 120TH AVE NE STE 15B BELLEVUE, WA 98005
EPA ID:	WAD988481966
Contact:	YOUNG B KWON
Contact address:	661 120TH AVE NE STE 15B BELLEVUE, WA 98005-3047
Contact country:	US
Contact telephone:	(425)639-8963
Contact email:	Not reported
EPA Region:	10
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	YOUNG KWON
Owner/operator address:	661 120TH AVE NE STE 15B BELLEVUE, WA 98005
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/14/2002

HI TECH CLEANERS BELLEVUE (Continued) **1001490631**

Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2007
Facility name: HI TECH CLEANERS BELLEVUE
Classification: Not a generator, verified

Date form received by agency: 12/31/2005
Facility name: HI TECH CLEANERS BELLEVUE
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/12/2007
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005357728

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HI TECH CLEANERS BELLEVUE (Continued) **1001490631**

HAZARDOUS WASTE BIENNIAL REPORTER

CSCSL:

Facility ID:	68798133
Region:	Northwest
Lat/Long:	47.616280000000 / -122.17993
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	2959
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Halogenated Organics
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

ALLSITES:

Facility Id:	68798133
Latitude:	47.6162800
Longitude:	-122.17993
Geographic location identifier (alias facid):	68798133
Facility Name:	Hi Tech Cleaners Bellevue
Latitude Decimal Degrees:	47.616280000000003
Longitude Decimal Degrees:	-122.17993
Coordinate Point Areal Extent Code:	4
Horizontal Accuracy Code:	9
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

WA MANIFEST:

Facility Site ID Number:	68798133
SWC Desc:	F001
FWC Desc:	F002 D039F001
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No

HI TECH CLEANERS BELLEVUE (Continued) **1001490631**

Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD988481966
Facility Address 2:	Not reported
TAX REG NBR:	600600701
NAICS CD:	81232
BUSINESS TYPE:	Not reported
MAIL NAME:	Hi Tech Cleaners
MAIL ADDR LINE1:	661 120TH AVE NE STE 15B
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98005-3047
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Hi Tech Cleaners Bellevue
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	661 120TH AVE NE STE 15B
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98005-3047
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	425 639-8963
LEGAL EFFECTIVE DATE:	12/9/1996
LAND ORG NAME:	TRF Pacific Inc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	6410 ROOSEVELT WAY NE
LAND CITY,ST,ZIP:	SEATTLE, WA 98115
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	2069850100
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	661 120TH AVE NE STE 15B
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-3047
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425 639-8963
OPERATOR EFFECTIVE DATE:	10/14/2002
SITE CONTACT NAME:	Young B Kwon
SITE CONTACT ADDR LINE1:	661 120TH AVE NE STE 15B
SITE CONTACT ZIP:	BELLEVUE, WA 98005-3047
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425 639-8963
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Young B Kwon
FORM CONTACT ADDR LINE1:	661 120TH AVE NE STE 15B
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-3047
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425 639-8963
FORM CONTACT EMAIL:	kpak@key-enviro.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	Yes
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No

HI TECH CLEANERS BELLEVUE (Continued) **1001490631**

TRANSPORTS OTHRS WASTE: No
RECYCLER ONSITE: No
TRANSFER FACILITY: No
OTHER EXEMPTION: Not reported
UW BATTERY GEN: No
USED OIL TRANSPORTER: No
USED OIL TRANSFER FACLTY: No
USED OIL PROCESSOR: No
USED OIL REREFINER: No
USED OIL FUEL MRKTR DIRECTS SHPMNTS: No
USED OIL FUEL MRKTR MEETS SPECS: No

Facility Site ID Number: 68798133
SWC Desc: F001
FWC Desc: F002 D039F001
Form Comm: Not reported
Data Year: Not reported
Permit by Rule: False
Treatment by Generator: False
Mixed radioactive waste: False
Importer of hazardous waste: False
Immediate recycler: False
Treatment/Storage/Disposal/Recycling Facility: False
Generator of dangerous fuel waste: False
Generator marketing to burner: False
"Other marketers (i.e., blender, distributor, etc.)": False
Utility boiler burner: False
Industry boiler burner: False
Industrial Furnace: False
Smelter defferal: False
Universal waste - batteries - generate: False
Universal waste - thermostats - generate: False
Universal waste - mercury - generate: False
Universal waste - lamps - generate: False
Universal waste - batteries - accumulate: False
Universal waste - thermostats - accumulate: False
Universal waste - mercury - accumulate: False
Universal waste - lamps - accumulate: False
Destination Facility for Universal Waste: False
Off-specification used oil burner - utility boiler: False
Off-specification used oil burner - industrial boiler: False
Off-specification used oil burner - industrial furnace: False
EPA ID: WAD988481966
Facility Address 2: Not reported
TAX REG NBR: 600600701
NAICS CD: 812320
BUSINESS TYPE: Not reported
MAIL NAME: Hi Tech Cleaners
MAIL ADDR LINE1: 661 120TH AVE NE STE 15B
MAIL CITY,ST,ZIP: BELLEVUE, WA 98005-3047
MAIL COUNTRY: UNITED STATES
LEGAL ORG NAME: Hi Tech Cleaners Bellevue
LEGAL ORG TYPE: Private
LEGAL ADDR LINE1: 661 120TH AVE NE STE 15B
LEGAL CITY,ST,ZIP: BELLEVUE, WA 98005-3047
LEGAL COUNTRY: UNITED STATES
LEGAL PHONE NBR: 425 639-8963

HI TECH CLEANERS BELLEVUE (Continued) **1001490631**

LEGAL EFFECTIVE DATE:	12/9/1996
LAND ORG NAME:	TRF Pacific Inc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	6410 ROOSEVELT WAY NE
LAND CITY,ST,ZIP:	SEATTLE, WA 98115
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	2069850100
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	661 120TH AVE NE STE 15B
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-3047
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425 639-8963
OPERATOR EFFECTIVE DATE:	10/14/02
SITE CONTACT NAME:	Young B Kwon
SITE CONTACT ADDR LINE1:	661 120TH AVE NE STE 15B
SITE CONTACT ZIP:	BELLEVUE, WA 98005-3047
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425 639-8963
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Young B Kwon
FORM CONTACT ADDR LINE1:	661 120TH AVE NE STE 15B
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-3047
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425 639-8963
FORM CONTACT EMAIL:	kpak@key-enviro.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

VCP:

edr_fstat:	WA
edr_fzip:	98005
edr_fcnty:	KING COUNTY
edr_zip:	Not reported
Facility ID:	68798133
VCP Status:	VCP
VCP:	Not reported
Ecology Status:	Cleanup Started
NFA Type:	Cleanup Started
Date NFA:	Cleanup Started
Rank:	Cleanup Started

HI TECH CLEANERS BELLEVUE (Continued) **1001490631**

Inactive Drycleaners:

EPA I:	WAD988481966
FS Id:	68798133
Facility ID:	WAD988481966
NAICS Code:	600600701
Fed Waste Code Desc:	F001
State Waste Code Desc:	Not reported
TAX REG NBR:	81232
BUSINESS TYPE:	Not reported
MAIL NAME:	Hi Tech Cleaners
MAIL LINE1:	661 120TH AVE NE STE 15B
MAIL LINE2:	Not reported
MAIL CITY:	BELLEVUE
MAIL STATE:	WA
MAIL ZIP:	98005-3047
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Hi Tech Cleaners Bellevue
LEGAL PERSON FIRST NAME:	Young
LEGAL PERSON MIDDLE INIT:	B
LEGAL PERSON LAST NAME:	Kwon
LEGAL LINE1:	661 120TH AVE NE STE 15B
LEGAL LINE2:	Not reported
LEGAL CITY:	BELLEVUE
LEGAL STATE:	WA
LEGAL ZIP:	98005-3047
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	425 639-8963
LEGAL EFFECTIVE DATE:	12/9/1996
LEGAL ORGANIZATION TYPE:	Private
LAND ORG NAME:	TRF Pacific Inc
LAND PERSON FIRST NAME:	Not reported
LAND PERSON MIDDLE INIT:	Not reported
LAND PERSON LAST NAME:	Not reported
LAND LINE1:	6410 ROOSEVELT WAY NE
LAND LINE2:	Not reported
LAND CITY:	SEATTLE
LAND STATE:	WA
LAND ZIP:	98115
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	2069850100
LAND ORGANIZATION TYPE:	Private
OPERATOR ORG NAME:	Not reported
OPERATOR PERSON FIRST NAME:	Young
OPERATOR PERSON MIDDLE INIT:	B
OPERATOR PERSON LAST NAME:	Kwon
OPERATOR LINE1:	661 120TH AVE NE STE 15B
OPERATOR LINE2:	Not reported
OPERATOR CITY:	BELLEVUE
OPERATOR STATE:	WA
OPERATOR ZIP:	98005-3047
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425 639-8963
OPERATOR EFFECTIVE DATE:	10/14/2002
OPERATOR ORGANIZATION TYPE:	Private
SITE CONTACT FIRST NAME:	Young
SITE CONTACT MIDDLE INIT:	B
SITE CONTACT LAST NAME:	Kwon

HI TECH CLEANERS BELLEVUE (Continued) **1001490631**

SITE CONTACT LINE1:	661 120TH AVE NE STE 15B
SITE CONTACT LINE2:	Not reported
SITE CONTACT CITY:	BELLEVUE
SITE CONTACT STATE:	WA
SITE CONTACT ZIP:	98005-3047
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425 639-8963
SITE CONTACT EMAIL:	Not reported
FORM CONTACT FIRST NAME:	Young
FORM CONTACT MIDDLE INIT:	B
FORM CONTACT LAST NAME:	Kwon
FORM CONTACT LINE1:	661 120TH AVE NE STE 15B
FORM CONTACT LINE2:	Not reported
FORM CONTACT CITY:	BELLEVUE
FORM CONTACT STATE:	WA
FORM CONTACT ZIP:	98005-3047
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425 639-8963
FORM CONTACT EMAIL:	kpak@key-enviro.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	Yes
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHERS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
PBR:	No
TBG:	No
MIXED RADIOACTIVE:	No
IMPORTER:	No
TSDR FACILITY:	No
IMMEDIATE RECYCLER:	No
GEN DANG FUEL:	No
GEN MARKET TO BURNER:	No
GEN OTHER MARKETERS:	No
UTILITY BOILER BURNER:	No
INDUSTRY BOILER BURNER:	No
FURNACE BURNER:	No
SMELTER DEFERRAL:	No
SMALL QTY EXEMPTION:	Not reported
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
UW THERMOSTATS GEN:	No
UW MERCURY GEN:	No
UW LAMPS GEN:	No
UW BATTERY ACCUM:	No
UW THERMOSTATS ACCUM:	No
UW MERCURY ACCUM:	No
UW LAMPS ACCUM:	No
UW DESTINATION FACILITY:	No
OFF SPEC UTILITY BOILER:	No
OFF SPEC INDUSTRY BOILER:	No
OFF SPEC FURNACE:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACILITY:	Not reported
USED OIL PROCESSOR:	No

HI TECH CLEANERS BELLEVUE (Continued) **1001490631**

USED OIL REREFINER:	No
USED OIL FUEL MARKETER DIR SHIPMENTS:	No
USED OIL FUEL MARKETER MEETS SPECS:	No
Comments:	Not reported
EPA I:	WAD988481966
FS Id:	68798133
Facility ID:	WAD988481966
NAICS Code:	812320
Fed Waste Code Desc:	F001
State Waste Code Desc:	F001
TAX REG NBR:	600600701
BUSINESS TYPE:	Not reported
MAIL NAME:	Hi Tech Cleaners
MAIL LINE1:	661 120TH AVE NE STE 15B
MAIL LINE2:	Not reported
MAIL CITY:	BELLEVUE
MAIL STATE:	WA
MAIL ZIP:	98005-3047
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Hi Tech Cleaners Bellevue
LEGAL PERSON FIRST NAME:	Young
LEGAL PERSON MIDDLE INIT:	B
LEGAL PERSON LAST NAME:	Kwon
LEGAL LINE1:	661 120TH AVE NE STE 15B
LEGAL LINE2:	Not reported
LEGAL CITY:	BELLEVUE
LEGAL STATE:	WA
LEGAL ZIP:	98005-3047
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	425 639-8963
LEGAL EFFECTIVE DATE:	12/9/1996
LEGAL ORGANIZATION TYPE:	Private
LAND ORG NAME:	TRF Pacific Inc
LAND PERSON FIRST NAME:	Not reported
LAND PERSON MIDDLE INIT:	Not reported
LAND PERSON LAST NAME:	Not reported
LAND LINE1:	6410 ROOSEVELT WAY NE
LAND LINE2:	Not reported
LAND CITY:	SEATTLE
LAND STATE:	WA
LAND ZIP:	98115
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	2069850100
LAND ORGANIZATION TYPE:	Private
OPERATOR ORG NAME:	Not reported
OPERATOR PERSON FIRST NAME:	Young
OPERATOR PERSON MIDDLE INIT:	B
OPERATOR PERSON LAST NAME:	Kwon
OPERATOR LINE1:	661 120TH AVE NE STE 15B
OPERATOR LINE2:	Not reported
OPERATOR CITY:	BELLEVUE
OPERATOR STATE:	WA
OPERATOR ZIP:	98005-3047
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425 639-8963
OPERATOR EFFECTIVE DATE:	10/14/02
OPERATOR ORGANIZATION TYPE:	Private

HI TECH CLEANERS BELLEVUE (Continued) **1001490631**

SITE CONTACT FIRST NAME:	Young
SITE CONTACT MIDDLE INIT:	B
SITE CONTACT LAST NAME:	Kwon
SITE CONTACT LINE1:	661 120TH AVE NE STE 15B
SITE CONTACT LINE2:	Not reported
SITE CONTACT CITY:	BELLEVUE
SITE CONTACT STATE:	WA
SITE CONTACT ZIP:	98005-3047
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425 639-8963
SITE CONTACT EMAIL:	Not reported
FORM CONTACT FIRST NAME:	Young
FORM CONTACT MIDDLE INIT:	B
FORM CONTACT LAST NAME:	Kwon
FORM CONTACT LINE1:	661 120TH AVE NE STE 15B
FORM CONTACT LINE2:	Not reported
FORM CONTACT CITY:	BELLEVUE
FORM CONTACT STATE:	WA
FORM CONTACT ZIP:	98005-3047
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425 639-8963
FORM CONTACT EMAIL:	kpak@key-enviro.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	F
BATCH GENERATION:	T
ONE TIME GENERATION:	F
TRANSPORTS OWN WASTE:	F
TRANSPORTS OTHERS WASTE:	F
RECYCLER ONSITE:	F
TRANSFER FACILITY:	F
PBR:	F
TBG:	F
MIXED RADIOACTIVE:	F
IMPORTER:	F
TSDR FACILITY:	F
IMMEDIATE RECYCLER:	F
GEN DANG FUEL:	F
GEN MARKET TO BURNER:	F
GEN OTHER MARKETERS:	F
UTILITY BOILER BURNER:	F
INDUSTRY BOILER BURNER:	F
FURNACE BURNER:	F
SMELTER DEFERRAL:	F
SMALL QTY EXEMPTION:	F
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	F
UW THERMOSTATS GEN:	F
UW MERCURY GEN:	F
UW LAMPS GEN:	F
UW BATTERY ACCUM:	F
UW THERMOSTATS ACCUM:	F
UW MERCURY ACCUM:	F
UW LAMPS ACCUM:	F
UW DESTINATION FACILITY:	F
OFF SPEC UTILITY BOILER:	F
OFF SPEC INDUSTRY BOILER:	F
OFF SPEC FURNACE:	F

HI TECH CLEANERS BELLEVUE (Continued) **1001490631**

USED OIL TRANSPORTER: F
USED OIL TRANSFER FACILITY: F
USED OIL PROCESSOR: F
USED OIL REREFINER: F
USED OIL FUEL MARKETER DIR SHIPMENTS: F
USED OIL FUEL MARKETER MEETS SPECS: F
Comments: Not reported

H23 **BELLEVUE ALFA ROMEO BELLEVUE** **RCRA-NonGen** **1000838297**
WSW **11919 NE 8TH ST** **FINDS** **WAD988510640**
1/8-1/4 **BELLEVUE, WA 98005** **ALLSITES**
0.162 mi.
853 ft. **Site 1 of 8 in cluster H**

Relative:
Lower

Actual:
140 ft.

RCRA-NonGen:
Date form received by agency: 08/19/1992
Facility name: BELLEVUE ALFA ROMEO BELLEVUE
Facility address: 11919 NE 8TH ST
BELLEVUE, WA 98005
EPA ID: WAD988510640
Contact: TINO PERRINA
Contact address: 11919 NE 8TH ST
BELLEVUE, WA 98005-3023
Contact country: US
Contact telephone: (425)635-9331
Contact email: Not reported
EPA Region: 10
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: BELLEVUE ALFA ROMEO
Owner/operator address: 11919 NE 8TH ST
BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/19/1992
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

BELLEVUE ALFA ROMEO BELLEVUE (Continued) **1000838297**

Violation Status: No violations found

FINDS:

Registry ID: 110005378340

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:

Facility Id:	13521826
Latitude:	47.6173700
Longitude:	-122.18102
Geographic location identifier (alias facid):	13521826
Facility Name:	Bellevue Alfa Romeo Bellevue
Latitude Decimal Degrees:	47.617370000000001
Longitude Decimal Degrees:	-122.18102
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

G24 **BELLEVUE CITY UST 11768** **ALLSITES** **U001126940**
SSW **657 120TH AVE NE** **UST** **N/A**
1/8-1/4 **BELLEVUE, WA 98005**
0.162 mi.
858 ft. **Site 2 of 5 in cluster G**

Relative:
Lower

Actual:
149 ft.

ALLSITES:

Facility Id:	95537727
Latitude:	47.616031
Longitude:	-122.18114
Geographic location identifier (alias facid):	95537727
Facility Name:	BELLEVUE CITY UST 11768
Latitude Decimal Degrees:	47.616031
Longitude Decimal Degrees:	-122.181144
Coordinate Point Areal Extent Code:	4
Horizontal Accuracy Code:	6
Coordinate Point Geographic Position Code:	5
Location Verified Code:	N

UST:

Facility ID:	95537727
Site ID:	11768
Lat Deg:	47
Lat Min:	36
Lat Sec:	57.711599999998384
Long Deg:	-122
Long Min:	10

BELLEVUE CITY UST 11768 (Continued) **U001126940**

Long Sec:	52.118400000011889
UBI:	Not reported
Phone Number:	2064556862

Tank ID:	40424
Tank Name:	2
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	40446
Tank Name:	4
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported

BELLEVUE CITY UST 11768 (Continued) **U001126940**

Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	40507
Tank Name:	3
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	40546
Tank Name:	1
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported

BELLEVUE CITY UST 11768 (Continued) **U001126940**

Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

Tank ID: 40568
Tank Name: 5
Install Date: 12/31/1964
Capacity: 111 TO 1,100 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Steel
Tank Construction: Not reported
Tank Tightness Test: Not reported
Tank Corrosion Protection: Not reported
Pipe Material: Not reported
Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

G25 **LARRYS MARKET** **RCRA-NonGen** **1000282275**
SSW **655 120TH AVE NE** **FINDS** **WAD981765001**
1/8-1/4 **BELLEVUE, WA 98005**
0.164 mi.
864 ft. **Site 3 of 5 in cluster G**

Relative:
Lower

Actual:
149 ft.

RCRA-NonGen:
Date form received by agency: 01/29/1987
Facility name: LARRYS MARKET
Facility address: 655 120TH AVE NE
BELLEVUE, WA 98005
EPA ID: WAD981765001
Mailing address: PO BOX 90012
BELLEVUE, WA 98009-9012
Contact: PATRICK CONN
Contact address: PO BOX 90012
BELLEVUE, WA 98009-9012
Contact country: US
Contact telephone: (425)462-2736
Contact email: Not reported
EPA Region: 10
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

LARRYS MARKET (Continued) **1000282275**

Owner/Operator Summary:
Owner/operator name: BELLEVUE CITY
Owner/operator address: PO BOX 90012
BELLEVUE, WA 98009
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/29/1987
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110005341594

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

G26 **LARRYS MARKET** **ALLSITES** **U003795353**
SSW **655 120TH AVE NE** **LUST** **N/A**
1/8-1/4 **BELLEVUE, WA 98005** **UST**
0.164 mi.
864 ft. **Site 4 of 5 in cluster G**

Relative:
Lower

Actual:
149 ft.

ALLSITES:

Facility Id:	21839936	
Latitude:	47.6162399	
Longitude:	-122.17993	
Geographic location identifier (alias facid):		21839936
Facility Name:		LARRYS MARKET
Latitude Decimal Degrees:		47.616239999999998
Longitude Decimal Degrees:		-122.17993
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		99
Location Verified Code:		N

LUST:

FS ID:	21839936
Cleanup Site ID:	8295
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	RCU
Alternate Name:	LARRY'S MARKET
Release Notification Date:	Not reported
Release Status Date:	05/21/1995
Site Response Unit Code:	Northwest
Lat/Long:	47.6162399 / -122.17993

FS ID:	21839936
Cleanup Site ID:	8295
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	LARRY'S MARKET
Release Notification Date:	Not reported
Release Status Date:	07/28/1989
Site Response Unit Code:	Northwest
Lat/Long:	47.6162399 / -122.17993

UST:

Facility ID:	21839936
Site ID:	200704
Lat Deg:	47
Lat Min:	36
Lat Sec:	58.463999999991643
Long Deg:	-122
Long Min:	10
Long Sec:	47.747999999995727
UBI:	Not reported
Phone Number:	L00122

Tank ID:	576348
Tank Name:	1
Install Date:	1/1/1900

LARRYS MARKET (Continued) **U003795353**

Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/11/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/11/2001
Tag Number:	Not reported

Tank ID:	576353
Tank Name:	2
Install Date:	1/1/1900
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/11/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/11/2001
Tag Number:	Not reported

Tank ID:	576358
Tank Name:	3

LARRYS MARKET (Continued) **U003795353**

Install Date:	1/1/1900
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/11/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/11/2001
Tag Number:	Not reported

Tank ID:	576363
Tank Name:	4
Install Date:	1/1/1900
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/11/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/11/2001
Tag Number:	Not reported

G27
SSW
1/8-1/4
0.164 mi.
864 ft.

LARRY'S MARKET
655 120TH AVE. NE
BELLEVUE, WA 98005

Site 5 of 5 in cluster G

ICR **S104487012**
N/A

Relative:
Lower

Actual:
149 ft.

ICR:

Date Ecology Received Report:	12/05/90
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	91-19
County Code:	17
Contact:	Not reported
Report Title:	Not reported

H28
WSW
1/8-1/4
0.164 mi.
864 ft.

EASTSIDE RENTAL EQUIPMENT
11830 NE 8TH ST
BELLEVUE, WA 98005

Site 2 of 8 in cluster H

RCRA-NonGen **1000993037**
FINDS **WAR000000612**
CSCSL
ALLSITES
ICR

Relative:
Lower

Actual:
140 ft.

RCRA-NonGen:

Date form received by agency:	07/21/1997
Facility name:	EASTSIDE RENTAL EQUIPMENT
Facility address:	11830 NE 8TH ST BELLEVUE, WA 98005
EPA ID:	WAR000000612
Contact:	GREG ANDERSON
Contact address:	11830 NE 8TH ST BELLEVUE, WA 98005-3007
Contact country:	US
Contact telephone:	(425)454-4088
Contact email:	Not reported
EPA Region:	10
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ANDERSON COMMERCIAL PROPERTIES
Owner/operator address:	11830 NE 8TH ST BELLEVUE, WA 98005
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	07/20/1997
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

EASTSIDE RENTAL EQUIPMENT (Continued) **1000993037**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/03/1997
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005398621

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CSCSL:
Facility ID: 98375137
Region: Northwest
Lat/Long: 47.617400000000 / -122.18222
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 6980
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Other
Ground Water: C
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

EASTSIDE RENTAL EQUIPMENT (Continued) **1000993037**

ALLSITES:

Facility Id:	98375137	
Latitude:	47.6174000	
Longitude:	-122.18222	
Geographic location identifier (alias facid):		98375137
Facility Name:		Eastside Rental Equipment
Latitude Decimal Degrees:		47.617400000000004
Longitude Decimal Degrees:		-122.18222
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		99
Location Verified Code:		Y

ICR:

Date Ecology Received Report:	01/07/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	91-20
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	02/03/93
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-50
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	07/23/93
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	93-06
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	01/14/94
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	93-20
County Code:	17

EASTSIDE RENTAL EQUIPMENT (Continued) **1000993037**

Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	01/09/92
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-15
County Code:	17
Contact:	Not reported
Report Title:	Not reported

H29 **EASTSIDE RENTAL EQUIPMENT** **LUST 1001019664**
WSW **11830 NE 8TH ST** **UST N/A**
1/8-1/4 **BELLEVUE, WA 98005**
0.164 mi.
864 ft. **Site 3 of 8 in cluster H**

Relative:
Lower

Actual:
140 ft.

LUST:

FS ID:	98375137
Cleanup Site ID:	6980
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	EASTSIDE RENTAL
Release Notification Date:	Not reported
Release Status Date:	02/02/1993
Site Response Unit Code:	Northwest
Lat/Long:	47.6174000 / -122.18222

FS ID:	98375137
Cleanup Site ID:	6980
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Monitoring
Alternate Name:	EASTSIDE RENTAL
Release Notification Date:	Not reported
Release Status Date:	06/01/1995
Site Response Unit Code:	Northwest
Lat/Long:	47.6174000 / -122.18222

UST:

Facility ID:	98375137
Site ID:	100237
Lat Deg:	47
Lat Min:	37
Lat Sec:	2.6400000000126056
Long Deg:	-122
Long Min:	10
Long Sec:	55.992000000003372
UBI:	1790112710010001
Phone Number:	4254544088

Tank ID:	17575
Tank Name:	4

EASTSIDE RENTAL EQUIPMENT (Continued) **1001019664**

Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A3771

Tank ID:	17592
Tank Name:	8
Install Date:	3/15/1990
Capacity:	2,001 to 4,999 Gallons
Tank Upgrade Date:	2/23/1998
TankSystem Status:	Operational
TankSystem Status Change Date:	8/26/1996
Tank Status:	Operational
Tank Permit Expiration Date:	11/30/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Suction System Pump Check Valve
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Fiberglass
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Suction
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Interstitial Monitoring
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not Required
Tank Actual Status Date:	8/6/1996
Tag Number:	A3771

Tank ID:	17642

EASTSIDE RENTAL EQUIPMENT (Continued) **1001019664**

Tank Name:	2
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A3771

Tank ID:	17717
Tank Name:	6
Install Date:	4/15/1989
Capacity:	2,001 to 4,999 Gallons
Tank Upgrade Date:	2/23/1998
TankSystem Status:	Operational
TankSystem Status Change Date:	8/26/1996
Tank Status:	Operational
Tank Permit Expiration Date:	11/30/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Suction System Pump Check Valve
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Fiberglass
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Suction
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Interstitial Monitoring
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not Required
Tank Actual Status Date:	8/6/1996
Tag Number:	A3771

EASTSIDE RENTAL EQUIPMENT (Continued) **1001019664**

Tank ID:	17744
Tank Name:	1
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A3771

Tank ID:	17773
Tank Name:	5
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A3771

EASTSIDE RENTAL EQUIPMENT (Continued) **1001019664**

Tank ID:	17868
Tank Name:	7
Install Date:	3/15/1990
Capacity:	2,001 to 4,999 Gallons
Tank Upgrade Date:	2/23/1998
TankSystem Status:	Operational
TankSystem Status Change Date:	8/26/1996
Tank Status:	Operational
Tank Permit Expiration Date:	11/30/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Suction System Pump Check Valve
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Fiberglass
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Suction
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Interstitial Monitoring
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not Required
Tank Actual Status Date:	8/6/1996
Tag Number:	A3771

Tank ID:	17894
Tank Name:	3
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A3771

H30 **TIKI CAR WASH** **LUST** **U003353843**
WSW **11909 NE 8TH ST** **UST** **N/A**
1/8-1/4 **BELLEVUE, WA 98005**
0.164 mi.
868 ft. **Site 4 of 8 in cluster H**

Relative:
Lower

Actual:
140 ft.

LUST:

FS ID:	2352
Cleanup Site ID:	5096
Cleanup Unit Type:	Upland
Process Type:	Ecology-supervised or conducted
Facility Status:	Cleanup Started
Alternate Name:	TIKI CAR WASH
Release Notification Date:	Not reported
Release Status Date:	09/29/1995
Site Response Unit Code:	Northwest
Lat/Long:	47.6173100 / -122.18114

UST:

Facility ID:	2352
Site ID:	100678
Lat Deg:	47
Lat Min:	37
Lat Sec:	2.3160000000120817
Long Deg:	-122
Long Min:	10
Long Sec:	52.103999999997086
UBI:	6000377190010001
Phone Number:	4254554787
Tank ID:	740
Tank Name:	4
Install Date:	7/10/1978
Capacity:	10,000 to 19,999 Gallons
Tank Upgrade Date:	7/3/1998
TankSystem Status:	Operational
TankSystem Status Change Date:	8/26/1996
Tank Status:	Operational
Tank Permit Expiration Date:	9/30/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Ball Float Valve (vent line)
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Impressed Current and Interior Lining
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	7/10/1978
Tag Number:	A8051

TIKI CAR WASH (Continued) **U003353843**

Tank ID:	784
Tank Name:	2
Install Date:	7/18/1971
Capacity:	5,000 to 9,999 Gallons
Tank Upgrade Date:	7/3/1998
TankSystem Status:	Operational
TankSystem Status Change Date:	8/26/1996
Tank Status:	Operational
Tank Permit Expiration Date:	9/30/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Ball Float Valve (vent line)
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Impressed Current and Interior Lining
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	7/18/1971
Tag Number:	A8051

Tank ID:	824
Tank Name:	1
Install Date:	7/18/1971
Capacity:	10,000 to 19,999 Gallons
Tank Upgrade Date:	7/3/1998
TankSystem Status:	Operational
TankSystem Status Change Date:	8/26/1996
Tank Status:	Operational
Tank Permit Expiration Date:	9/30/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Ball Float Valve (vent line)
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Impressed Current and Interior Lining
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	7/18/1971
Tag Number:	A8051

TIKI CAR WASH (Continued) **U003353843**

Tank ID:	850
Tank Name:	3
Install Date:	7/18/1971
Capacity:	5,000 to 9,999 Gallons
Tank Upgrade Date:	7/3/1998
TankSystem Status:	Operational
TankSystem Status Change Date:	8/26/1996
Tank Status:	Operational
Tank Permit Expiration Date:	9/30/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Ball Float Valve (vent line)
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Impressed Current and Interior Lining
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	7/18/1971
Tag Number:	A8051

H31 **TIKI CAR WASH** **FINDS** **1007080521**
WSW **11909 NE 8TH ST** **CSCSL** **N/A**
1/8-1/4 **BELLEVUE, WA 98005** **HSL**
0.164 mi. **ALLSITES**
868 ft. **Site 5 of 8 in cluster H** **FINANCIAL ASSURANCE**

Relative: Lower

Actual: 140 ft.

FINDS:

Registry ID: 110015572414

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

CSCSL:

Facility ID:	2352
Region:	Northwest
Lat/Long:	47.617310000000 / -122.18114
Brownfield Status:	Not reported
Rank Status:	3
Clean Up Siteid:	5096
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Non-Halogenated Solvents

TIKI CAR WASH (Continued) **1007080521**

Ground Water: C
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 2352
Region: Northwest
Lat/Long: 47.617310000000 / -122.18114
Brownfield Status: Not reported
Rank Status: 3
Clean Up Siteid: 5096
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Gasoline
Ground Water: C
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

HSL:
edr_fstat: WA
edr_fzip: Not reported
edr_fcnty: KING
edr_zip: Not reported
Facility Type: Hazardous Sites List
Facility Status: Cleanup Started
FSID Number: 2352
Rank: 3
Region: NW

ALLSITES:
Facility Id: 2352
Latitude: 47.6173100
Longitude: -122.18114
Geographic location identifier (alias facid): 2352
Facility Name: TIKI CAR WASH
Latitude Decimal Degrees: 47.617310000000003
Longitude Decimal Degrees: -122.18114
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

Geographic Location Identifier (Alias Facid): 2352
Interaction (Aka Env Int) Type Code: UST
Interaction (Aka Env Int) Description: Underground Storage Tank
Interaction Status: A
Federal Program Indentifier: 100678
Interaction Start Date: 07/18/1971
Interaction End Date: Not reported

TIKI CAR WASH (Continued) **1007080521**

prgm_facil:	Not reported
cur_sys_pr:	TOXICS
cur_sys_nm:	ISIS
Geographic Location Identifier (Alias Facid):	2352
Interaction (Aka Env Int) Type Code:	LUST
Interaction (Aka Env Int) Description:	LUST Facility
Interaction Status:	A
Federal Program Indentifier:	100678
Interaction Start Date:	06/07/1990
Interaction End Date:	Not reported
prgm_facil:	Not reported
cur_sys_pr:	TOXICS
cur_sys_nm:	ISIS
Geographic Location Identifier (Alias Facid):	2352
Interaction (Aka Env Int) Type Code:	SCS
Interaction (Aka Env Int) Description:	State Cleanup Site
Interaction Status:	A
Federal Program Indentifier:	Not reported
Interaction Start Date:	01/01/1900
Interaction End Date:	Not reported
prgm_facil:	TIKI CAR WASH
cur_sys_pr:	TOXICS
cur_sys_nm:	ISIS

WA FINANCIAL ASSURANCE:

edr_fstat:	WA
edr_fzip:	98005
edr_fcnty:	Not reported
edr_zip:	Not reported
DOE Site ID:	100678
Site Type:	PLIA
Financial Resp Type:	Colony (GUS)
Inception Date:	07/17/2011
Expiration Date:	07/17/2012

H32 **TIKI CAR WASH** **SPILLS U003024911**
WSW **11909 NE 8TH** **ICR N/A**
1/8-1/4 **BELLEVUE, WA 98005**
0.164 mi.
868 ft. **Site 6 of 8 in cluster H**

Relative:
Lower

Actual:
140 ft.

SPILLS:

Facility ID:	604360
Medium:	Not reported
Material Desc:	PETROLEUM - GASOLINE
Material Qty:	Not reported
Material Units:	GALLON
Date Received:	3/14/2008 1:32:00 PM
Contact Name:	MATIC

ICR:

Date Ecology Received Report:	/ /
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater

TIKI CAR WASH (Continued) **U003024911**

Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-48
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 04/14/94
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-23
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 08/01/94
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-34
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 10/11/90
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 90-14
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 07/25/96
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-32
County Code: 17
Contact: Not reported
Report Title: Not reported

H33
WSW
1/8-1/4
0.166 mi.
877 ft.

BLUE OVAL PONY CARS LLC
11828 NE 8TH ST
BELLEVUE, WA 98005

Site 7 of 8 in cluster H

Relative:
Lower

Actual:
140 ft.

ALLSITES **S110039962**
N/A

ALLSITES:

Facility Id:	4495	
Latitude:	47.6175132	
Longitude:	-122.18194	
Geographic location identifier (alias facid):		4495
Facility Name:		Blue Oval Pony Cars LLC
Latitude Decimal Degrees:		47.617513269200003
Longitude Decimal Degrees:		-122.181947068
Coordinate Point Areal Extent Code:		0
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported
Geographic Location Identifier (Alias Facid):		4495
Interaction (Aka Env Int) Type Code:		LSC
Interaction (Aka Env Int) Description:		Local Source Control
Interaction Status:		I
Federal Program Indentifier:		Not reported
Interaction Start Date:		06/24/2009
Interaction End Date:		04/29/2010
prgm_facil:		Blue Oval Pony Cars LLC
cur_sys_pr:		HAZWASTE
cur_sys_nm:		LSC

H34
WSW
1/8-1/4
0.180 mi.
951 ft.

BAKKERS COIT INC BELLEVUE
11855 NE 8TH ST
BELLEVUE, WA 98005

Site 8 of 8 in cluster H

Relative:
Lower

Actual:
139 ft.

FINDS **1007062973**
ALLSITES **N/A**
CSCSL NFA
UST

FINDS:

Registry ID: 110015395179

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

ALLSITES:

Facility Id:	92645942	
Latitude:	47.6172010	
Longitude:	-122.18316	
Geographic location identifier (alias facid):		92645942
Facility Name:		BAKKERS COIT INC BELLEVUE
Latitude Decimal Degrees:		47.617201000000001
Longitude Decimal Degrees:		-122.183164
Coordinate Point Areal Extent Code:		4

BAKKERS COIT INC BELLEVUE (Continued) **1007062973**

Horizontal Accuracy Code: 6
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

CSCSL NFA:
Facility/Site Id: 92645942
CS Id: 11074
NFA Type: NFA-II
NFA Date: 10/03/2011
Rank: Not reported

UST:
Facility ID: 92645942
Site ID: 100125
Lat Deg: 47
Lat Min: 37
Lat Sec: 1.9236000000051945
Long Deg: -122
Long Min: 10
Long Sec: 59.390400000017962
UBI: 6004066520010001
Phone Number: 4259908295

Tank ID: 14346
Tank Name: 1
Install Date: 8/10/1989
Capacity: 5,000 to 9,999 Gallons
Tank Upgrade Date: 2/23/1998
TankSystem Status: Removed
TankSystem Status Change Date: 6/9/2008
Tank Status: Removed
Tank Permit Expiration Date: 7/31/2000
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Spill Bucket/Spill Box
Tank Overfill Prevention: Ball Float Valve (vent line)
Tank Material: Coated Steel
Tank Construction: Double Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: Sacrificial Anode
Pipe Material: Fiberglass
Pipe Construction: Single Wall Pipe
Pipe Primary Release Detection: Suction
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Corrosion Resistant
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

I35 **DOLLAR RENT A CAR SYSTEMS 223** **ALLSITES** **U000592134**
WSW **11839 NE 8TH** **CSCSL NFA** **N/A**
1/8-1/4 **BELLEVUE, WA 98005** **UST**
0.185 mi. **ICR**
976 ft. **Site 1 of 4 in cluster I**

Relative:
Lower

Actual:
139 ft.

ALLSITES:

Facility Id:	68711818	
Latitude:	47.6172010	
Longitude:	-122.18337	
Geographic location identifier (alias facid):		68711818
Facility Name:		DOLLAR RENT A CAR SYSTEMS 223
Latitude Decimal Degrees:		47.617201000000001
Longitude Decimal Degrees:		-122.183374
Coordinate Point Areal Extent Code:		4
Horizontal Accuracy Code:		6
Coordinate Point Geographic Position Code:		5
Location Verified Code:		N

CSCSL NFA:

Facility/Site Id:	68711818
CS Id:	10173
NFA Type:	NFA-II
NFA Date:	10/03/2011
Rank:	Not reported

UST:

Facility ID:	68711818
Site ID:	7678
Lat Deg:	47
Lat Min:	37
Lat Sec:	1.9236000000051945
Long Deg:	-122
Long Min:	11
Long Sec:	0.14640000000213149
UBI:	Not reported
Phone Number:	2064539770
Tank ID:	14963
Tank Name:	2
Install Date:	12/31/1964
Capacity:	10,000 to 19,999 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported

DOLLAR RENT A CAR SYSTEMS 223 (Continued) **U000592134**

Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

Tank ID: 15001
Tank Name: 4
Install Date: 12/31/1964
Capacity: 111 TO 1,100 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Exempt
TankSystem Status Change Date: 5/25/2000
Tank Status: Exempt
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Steel
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: Not reported
Pipe Material: Steel
Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

Tank ID: 15056
Tank Name: 3
Install Date: 12/31/1964
Capacity: 10,000 to 19,999 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Steel
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: Not reported
Pipe Material: Steel

DOLLAR RENT A CAR SYSTEMS 223 (Continued) **U000592134**

Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	15103
Tank Name:	1
Install Date:	12/31/1964
Capacity:	5,000 to 9,999 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	533680
Tank Name:	5
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	5/25/2000
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported

DOLLAR RENT A CAR SYSTEMS 223 (Continued) **U000592134**

Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	5/25/2000
Tag Number:	Not reported

ICR:

Date Ecology Received Report:	06/25/90
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-26
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	06/25/90
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	90-06
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	09/23/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-08
County Code:	17
Contact:	Not reported
Report Title:	Not reported

36
NW
1/8-1/4
0.193 mi.
1021 ft.

ENVIRONMENTAL HEALTH SCIENCES INC **RCRA-CESQG** **1001490466**
9 LAKE BELLEVUE BLDG STE 104 **PADS** **WAD982655011**
BELLEVUE, WA 98005 **FINDS**
ALLSITES

Relative:
Lower

Actual:
141 ft.

RCRA-CESQG:

Date form received by agency:	10/16/1995
Facility name:	ENVIRONMENTAL HEALTH SCIENCES INC
Facility address:	9 LAKE BELLEVUE BLDG STE 104 BELLEVUE, WA 98005
EPA ID:	WAD982655011

ENVIRONMENTAL HEALTH SCIENCES INC (Continued) **1001490466**

Mailing address: PO BOX 40673
BELLEVUE, WA 98015-4673
Contact: ROBERT GILMORE
Contact address: PO BOX 40673
BELLEVUE, WA 98015-4673
Contact country: US
Contact telephone: (425)455-2959
Contact email: Not reported
EPA Region: 10
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: ROBERT GILMORE
Owner/operator address: PO BOX 40673
BELLEVUE, WA 98015
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/16/1995
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

PADS:
EPAID: WAD982655011

ENVIRONMENTAL HEALTH SCIENCES INC (Continued) **1001490466**

Facility name:	ENVIRONMENTAL HEALTH SCIENCES
Facility Address:	9 LAKE BELLEVUE BLDG STE 104 BELLEVUE, WA 98005
Facility country:	US
Generator:	No
Storer:	No
Transporter:	Yes
Disposer:	No
Research facility:	No
Smelter:	No
Facility owner name:	ROBERT GILMORE
Contact title:	Not reported
Contact name:	GILMORE ROBERT D
Contact tel:	(206)455-2959
Contact extension:	Not reported
Mailing address:	9 LAKE BELLEVUE BLDG STE 104 BELLEVUE, WA 98005
Mailing country:	US
Cert. title:	Not reported
Cert. name:	Not reported
Cert. date:	4/4/1990
Date received:	5/17/1990

FINDS:

Registry ID: 110005346526

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit

ENVIRONMENTAL HEALTH SCIENCES INC (Continued) **1001490466**

Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

ALLSITES:

Facility Id:	97793475
Latitude:	47.61909
Longitude:	-122.1808
Geographic location identifier (alias facid):	97793475
Facility Name:	Environmental Health Sciences Inc
Latitude Decimal Degrees:	47.61909
Longitude Decimal Degrees:	-122.1808
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

I37 **MID LAKES PROPERTY** **CSCSL S107565975**
WSW **11807 11811 11815 NE 8TH ST** **ALLSITES N/A**
1/8-1/4 **BELLEVUE, WA 98005**
0.194 mi.
1025 ft. **Site 2 of 4 in cluster I**

Relative:
Lower

Actual:
139 ft.

CSCSL:

Facility ID:	4335752
Region:	Northwest
Lat/Long:	47.616517000000 / -122.182283
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	3367
Site Status:	Awaiting Cleanup
PSI?:	Not reported
Contaminant Name:	Non-Halogenated Solvents
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	4335752
Region:	Northwest
Lat/Long:	47.616517000000 / -122.182283
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	3367
Site Status:	Awaiting Cleanup
PSI?:	Not reported
Contaminant Name:	Petroleum Products - unspecified
Ground Water:	C
Surface Water:	Not reported
Soil:	C

MID LAKES PROPERTY (Continued) **S107565975**

Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest
Facility ID:	4335752
Region:	Northwest
Lat/Long:	47.616517000000 / -122.182283
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	3367
Site Status:	Awaiting Cleanup
PSI?:	Not reported
Contaminant Name:	Polychlorinated biPhenyls (PCB)
Ground Water:	C
Surface Water:	Not reported
Soil:	S
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

ALLSITES:

Facility Id:	4335752
Latitude:	47.6165170
Longitude:	-122.18228
Geographic location identifier (alias facid):	4335752
Facility Name:	Mid Lakes Property
Latitude Decimal Degrees:	47.616517000000002
Longitude Decimal Degrees:	-122.182283
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	5
Location Verified Code:	N

I38 **OLYMPIC CLEANERS** **RCRA-CESQG** **1000920534**
WSW **800 118TH AVE NE A** **FINDS** **WA0000379362**
1/8-1/4 **BELLEVUE, WA 98005** **ALLSITES**
0.196 mi. **Inactive Drycleaners**
1033 ft. **Site 3 of 4 in cluster I**

Relative:
Lower

Actual:
139 ft.

RCRA-CESQG:

Date form received by agency:	12/31/1993
Facility name:	OLYMPIC CLEANERS
Facility address:	800 118TH AVE NE A BELLEVUE, WA 98005
EPA ID:	WA0000379362
Mailing address:	800 118TH AVE NE BELLEVUE, WA 98005-2464
Contact:	JUN BAE KIM
Contact address:	800 118TH AVE NE BELLEVUE, WA 98005-2464
Contact country:	US
Contact telephone:	(425)462-6425
Contact email:	Not reported
EPA Region:	10

OLYMPIC CLEANERS (Continued) **1000920534**

Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: JUN BAE KIM
Owner/operator address: 800 118TH AVE NE
BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/31/1993
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110005305598

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

OLYMPIC CLEANERS (Continued) **1000920534**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:

Facility Id:	71539188	
Latitude:	47.6174499	
Longitude:	-122.18329	
Geographic location identifier (alias facid):		71539188
Facility Name:		Olympic Cleaners
Latitude Decimal Degrees:		47.617449999999998
Longitude Decimal Degrees:		-122.18329
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		99
Location Verified Code:		N

Inactive Drycleaners:

EPA I:	WA0000379362
FS Id:	14843
Facility ID:	WA0000379362
NAICS Code:	Not reported
Fed Waste Code Desc:	Not reported
State Waste Code Desc:	Not reported
TAX REG NBR:	81232
BUSINESS TYPE:	Not reported
MAIL NAME:	Not reported
MAIL LINE1:	Not reported
MAIL LINE2:	Not reported
MAIL CITY:	Not reported
MAIL STATE:	Not reported
MAIL ZIP:	Not reported
MAIL COUNTRY:	Not reported
LEGAL ORG NAME:	Not reported
LEGAL PERSON FIRST NAME:	Not reported
LEGAL PERSON MIDDLE INIT:	Not reported
LEGAL PERSON LAST NAME:	Not reported
LEGAL LINE1:	Not reported
LEGAL LINE2:	Not reported
LEGAL CITY:	Not reported
LEGAL STATE:	Not reported
LEGAL ZIP:	Not reported
LEGAL COUNTRY:	Not reported
LEGAL PHONE NBR:	Not reported
LEGAL EFFECTIVE DATE:	Not reported
LEGAL ORGANIZATION TYPE:	Not reported
LAND ORG NAME:	Not reported
LAND PERSON FIRST NAME:	Not reported
LAND PERSON MIDDLE INIT:	Not reported
LAND PERSON LAST NAME:	Not reported
LAND LINE1:	Not reported

OLYMPIC CLEANERS (Continued) **1000920534**

LAND LINE2:	Not reported
LAND CITY:	Not reported
LAND STATE:	Not reported
LAND ZIP:	Not reported
LAND COUNTRY:	Not reported
LAND PHONE NBR:	Not reported
LAND ORGANIZATION TYPE:	Not reported
OPERATOR ORG NAME:	Not reported
OPERATOR PERSON FIRST NAME:	Not reported
OPERATOR PERSON MIDDLE INIT:	Not reported
OPERATOR PERSON LAST NAME:	Not reported
OPERATOR LINE1:	Not reported
OPERATOR LINE2:	Not reported
OPERATOR CITY:	Not reported
OPERATOR STATE:	Not reported
OPERATOR ZIP:	Not reported
OPERATOR COUNTRY:	Not reported
OPERATOR PHONE NBR:	Not reported
OPERATOR EFFECTIVE DATE:	Not reported
OPERATOR ORGANIZATION TYPE:	Not reported
SITE CONTACT FIRST NAME:	Not reported
SITE CONTACT MIDDLE INIT:	Not reported
SITE CONTACT LAST NAME:	Not reported
SITE CONTACT LINE1:	Not reported
SITE CONTACT LINE2:	Not reported
SITE CONTACT CITY:	Not reported
SITE CONTACT STATE:	Not reported
SITE CONTACT ZIP:	Not reported
SITE CONTACT COUNTRY:	Not reported
SITE CONTACT PHONE NBR:	Not reported
SITE CONTACT EMAIL:	Not reported
FORM CONTACT FIRST NAME:	Not reported
FORM CONTACT MIDDLE INIT:	Not reported
FORM CONTACT LAST NAME:	Not reported
FORM CONTACT LINE1:	Not reported
FORM CONTACT LINE2:	Not reported
FORM CONTACT CITY:	Not reported
FORM CONTACT STATE:	Not reported
FORM CONTACT ZIP:	Not reported
FORM CONTACT COUNTRY:	Not reported
FORM CONTACT PHONE NBR:	Not reported
FORM CONTACT EMAIL:	Not reported
GEN STATUS CD:	Not reported
MONTHLY GENERATION:	Not reported
BATCH GENERATION:	Not reported
ONE TIME GENERATION:	Not reported
TRANSPORTS OWN WASTE:	Not reported
TRANSPORTS OTHERS WASTE:	Not reported
RECYCLER ONSITE:	Not reported
TRANSFER FACILITY:	Not reported
PBR:	Not reported
TBG:	Not reported
MIXED RADIOACTIVE:	Not reported
IMPORTER:	Not reported
TSDR FACILITY:	Not reported
IMMEDIATE RECYCLER:	Not reported
GEN DANG FUEL:	Not reported

OLYMPIC CLEANERS (Continued) **1000920534**

GEN MARKET TO BURNER:	Not reported
GEN OTHER MARKETERS:	Not reported
UTILITY BOILER BURNER:	Not reported
INDUSTRY BOILER BURNER:	Not reported
FURNACE BURNER:	Not reported
SMELTER DEFERRAL:	Not reported
SMALL QTY EXEMPTION:	Not reported
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	Not reported
UW THERMOSTATS GEN:	Not reported
UW MERCURY GEN:	Not reported
UW LAMPS GEN:	Not reported
UW BATTERY ACCUM:	Not reported
UW THERMOSTATS ACCUM:	Not reported
UW MERCURY ACCUM:	Not reported
UW LAMPS ACCUM:	Not reported
UW DESTINATION FACILITY:	Not reported
OFF SPEC UTILITY BOILER:	Not reported
OFF SPEC INDUSTRY BOILER:	Not reported
OFF SPEC FURNACE:	Not reported
USED OIL TRANSPORTER:	Not reported
USED OIL TRANSFER FACILITY:	Not reported
USED OIL PROCESSOR:	Not reported
USED OIL REREFINER:	Not reported
USED OIL FUEL MARKETER DIR SHIPMENTS:	Not reported
USED OIL FUEL MARKETER MEETS SPECS:	Not reported
Comments:	Not reported

I39 **ACCUTRAN TRANSMISSIONS INC** **ALLSITES U001123999**
WSW **11811 NE 8TH** **UST N/A**
1/8-1/4 **BELLEVUE, WA 98005**
0.196 mi.
1035 ft. **Site 4 of 4 in cluster I**

Relative:
Lower

Actual:
138 ft.

ALLSITES:

Facility Id:	65448253
Latitude:	47.6172109
Longitude:	-122.18373
Geographic location identifier (alias facid):	65448253
Facility Name:	ACCUTRAN TRANSMISSIONS INC
Latitude Decimal Degrees:	47.617210999999998
Longitude Decimal Degrees:	-122.183734
Coordinate Point Areal Extent Code:	4
Horizontal Accuracy Code:	6
Coordinate Point Geographic Position Code:	5
Location Verified Code:	N

UST:

Facility ID:	65448253
Site ID:	5356
Lat Deg:	47
Lat Min:	37
Lat Sec:	1.9595999999910418
Long Deg:	-122
Long Min:	11
Long Sec:	1.442400000004227
UBI:	1790204680010002

ACCUTRAN TRANSMISSIONS INC (Continued) **U001123999**

Phone Number:	2067280535
Tank ID:	43062
Tank Name:	1
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	4/9/1999
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

40
North
1/8-1/4
0.245 mi.
1296 ft.

SWB CONSTRUCTION **RCRA-NonGen** **1000108623**
1307 120TH NE **FINDS** **WAD131469512**
BELLEVUE, WA 98005 **ALLSITES**

Relative:
Lower

Actual:
149 ft.

RCRA-NonGen:

Date form received by agency:	11/15/1988
Facility name:	SWB CONSTRUCTION
Facility address:	1307 120TH NE BELLEVUE, WA 98005
EPA ID:	WAD131469512
Mailing address:	1347 120TH AVE NE BELLEVUE, WA 98005-2124
Contact:	CHUCK MATHENY
Contact address:	1347 120TH AVE NE BELLEVUE, WA 98005-2124
Contact country:	US
Contact telephone:	(425)451-9058
Contact email:	Not reported
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	SWB CONSTRUCTION
Owner/operator address:	1347 120TH AVE NE

SWB CONSTRUCTION (Continued) **1000108623**

BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 11/15/1988
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110005331514

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:
Facility Id: 85229975
Latitude: 47.62565
Longitude: -122.18067
Geographic location identifier (alias facid): 85229975
Facility Name: SWB Construction
Latitude Decimal Degrees: 47.62565
Longitude Decimal Degrees: -122.18067000000001
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

41 SSW 1/8-1/4 0.247 mi. 1303 ft.

MUTUAL MATERIALS CO BELLEVUE
605 119TH NE
BELLEVUE, WA 98005

RCRA-NonGen
FINDS
ALLSITES
UST

1000424010
WAD009244377

Relative: Lower

Actual: 140 ft.

RCRA-NonGen:

Date form received by agency:	07/25/1997
Facility name:	MUTUAL MATERIALS CO BELLEVUE
Facility address:	605 119TH NE BELLEVUE, WA 98005
EPA ID:	WAD009244377
Mailing address:	PO BOX 2009 BELLEVUE, WA 98009-2009
Contact:	BRAD CAHOON
Contact address:	PO BOX 2009 BELLEVUE, WA 98009-2009
Contact country:	US
Contact telephone:	(425)455-2869
Contact email:	Not reported
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	MUTUAL MATERIALS CO
Owner/operator address:	PO BOX 2009 BELLEVUE, WA 98009
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/02/1996
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/31/1990
Facility name:	MUTUAL MATERIALS CO BELLEVUE
Site name:	MUTUAL MATERIALS COMPANY
Classification:	Large Quantity Generator

MUTUAL MATERIALS CO BELLEVUE (Continued) **1000424010**

Violation Status: No violations found

FINDS:

Registry ID: 110005313142

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:

Facility Id:	3255715
Latitude:	47.6152000
Longitude:	-122.18112
Geographic location identifier (alias facid):	3255715
Facility Name:	Mutual Materials Co Bellevue
Latitude Decimal Degrees:	47.615200000000002
Longitude Decimal Degrees:	-122.18112000000001
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

UST:

Facility ID:	3255715
Site ID:	1872
Lat Deg:	47
Lat Min:	36
Lat Sec:	54.720000000005484
Long Deg:	-122
Long Min:	10
Long Sec:	52.032000000025391
UBI:	Not reported
Phone Number:	2064552869

Tank ID:	1629
Tank Name:	DIESEL #1
Install Date:	1/1/1977
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001

MUTUAL MATERIALS CO BELLEVUE (Continued) **1000424010**

Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	1807
Tank Name:	DIESEL #2
Install Date:	1/1/1977
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	35759
Tank Name:	GASS
Install Date:	6/1/1984
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed

MUTUAL MATERIALS CO BELLEVUE (Continued) **1000424010**

Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Suction System Tank Check Valve
Tank Spill Prevention:	None
Tank Overfill Prevention:	None
Tank Material:	Not reported
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	None
Pipe Material:	Not reported
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Manual Inventory Control (daily)
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Every 3 Years (suction tank check valve)
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

J42 **SAFEWAY** **ALLSITES** **S108894547**
NE **1124 124TH AVE NE** **SPILLS** **N/A**
1/8-1/4 **BELLEVUE, WA**
0.250 mi.
1320 ft. **Site 1 of 3 in cluster J**

Relative:
Higher

Actual:
185 ft.

ALLSITES:

Facility Id:	442286
Latitude:	47.6202699
Longitude:	-122.17503

Geographic location identifier (alias facid):	442286
Facility Name:	Safeway Inc 124th Ave
Latitude Decimal Degrees:	47.620269999999998
Longitude Decimal Degrees:	-122.175031
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	8
Location Verified Code:	N
Geographic Location Identifier (Alias Facid):	442286
Interaction (Aka Env Int) Type Code:	ENFORFNL
Interaction (Aka Env Int) Description:	Enforcement Final
Interaction Status:	A
Federal Program Indentifier:	Not reported
Interaction Start Date:	11/07/2007
Interaction End Date:	Not reported
prgm_facil:	Not reported
cur_sys_pr:	SPILLS
cur_sys_nm:	DMS

SPILLS:

Facility ID:	601647
Medium:	Not reported
Material Desc:	PETROLEUM - DIESEL FUEL
Material Qty:	Not reported
Material Units:	GALLON

SAFEWAY (Continued) **S108894547**

Date Received: 10/29/2007 5:10:00 PM
Contact Name: ERICSON

J43 **COCA COLA** **ICR** **S104485912**
NE **1150 124TH AVE. NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.261 mi.
1377 ft. **Site 2 of 3 in cluster J**

Relative:
Higher

Actual:
184 ft.

ICR:

Date Ecology Received Report:	03/16/00
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	98-24
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	04/23/93
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	93-04
County Code:	17
Contact:	Not reported
Report Title:	Not reported

J44 **COCA COLA BOTTLING CO BELLEVUE** **RCRA-CESQG** **1000251918**
NE **1150 124TH AVE NE** **ALLSITES** **WAD001328186**
1/4-1/2 **BELLEVUE, WA 98005** **CSCSL NFA**
0.261 mi. **UST**
1377 ft. **Site 3 of 3 in cluster J** **MANIFEST**
SPILLS
Relative: **VCP**
Higher **NPDES**

Actual:
184 ft.

RCRA-CESQG:

Date form received by agency:	06/07/2010
Facility name:	COCA COLA BOTTLING CO BELLEVUE
Facility address:	1150 124TH AVE NE BELLEVUE, WA 98005
EPA ID:	WAD001328186
Mailing address:	PO BOX 93346C BELLEVUE, WA 98009
Contact:	JED J RUSYNIAK
Contact address:	1150 124TH AVE NE BELLEVUE, WA 98005
Contact country:	US
Contact telephone:	(425) 453-1761
Contact email:	JRUSYNIAK@COKECCE.COM
EPA Region:	10

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: BCI COCA COLA BOTTLING CO OF WA
Owner/operator address: 1334 S CENTRAL AVE
LOS ANGELES, CA 90021
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/31/2002
Owner/Op end date: Not reported

Owner/operator name: BCI COCA COLA BOTTLING CO OF WA
Owner/operator address: 1334 S CENTRAL AVE
LOS ANGELES, 90021
Owner/operator country: US
Owner/operator telephone: (213)746-5555
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/31/2002
Owner/Op end date: Not reported

Owner/operator name: JED RUSYNIAK
Owner/operator address: 1150 124TH AVE NE
BELLEVUE, 98005
Owner/operator country: US
Owner/operator telephone: 425-453-1761
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/31/2003
Owner/Op end date: Not reported

Owner/operator name: MARGARET STEED
Owner/operator address: 1150 124TH AVE NE
BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/31/2003
Owner/Op end date: Not reported

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/29/2008
Facility name: COCA COLA BOTTLING CO BELLEVUE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/31/2007
Facility name: COCA COLA BOTTLING CO BELLEVUE
Classification: Not a generator, verified

Date form received by agency: 12/31/2005
Facility name: COCA COLA BOTTLING CO BELLEVUE
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: COCA COLA BOTTLING CO BELLEVUE
Classification: Not a generator, verified

Hazardous Waste Summary:
Waste code: WSQG
Waste name: A placeholder to allow BR submission to validate. In WA State, Conditionally Exempt Small Quantity Generators (Called SQG in WA) are not required to report waste streams, so no valid State or Fed codes are available for reporting to BR.

Waste code: WT02
Waste name: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 11/20/2006
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

Evaluation date: 08/01/1996
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

ALLSITES:
Facility Id: 93625221
Latitude: 47.6202109
Longitude: -122.17625
Geographic location identifier (alias facid): 93625221
Facility Name: COCA COLA BOTTLING CO BELLEVUE
Latitude Decimal Degrees: 47.620210999999998
Longitude Decimal Degrees: -122.176254
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 6
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

CSCSL NFA:
Facility/Site Id: 93625221
CS Id: 6893
NFA Type: NFA-VCP Review
NFA Date: 05/04/2000
Rank: Not reported

UST:
Facility ID: 93625221
Site ID: 5030
Lat Deg: 47
Lat Min: 37
Lat Sec: 12.759599999991451
Long Deg: -122
Long Min: 10
Long Sec: 34.514400000000478
UBI: Not reported
Phone Number: 2064552000

Tank ID: 10194
Tank Name: 2
Install Date: 7/1/1979
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Pressurized System
Tank Spill Prevention: None
Tank Overfill Prevention: None
Tank Material: Fiberglass Reinforced Plastic
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: Corrosion Resistant
Pipe Material: Not reported

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	10274
Tank Name:	4
Install Date:	7/1/1969
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	None
Tank Overfill Prevention:	None
Tank Material:	Not reported
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	None
Pipe Material:	Not reported
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	10311
Tank Name:	3
Install Date:	7/1/1969
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	None
Tank Overfill Prevention:	None
Tank Material:	Not reported
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	None

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

Pipe Material:	Not reported
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	10347
Tank Name:	1
Install Date:	7/1/1969
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Product Removed by Reclaimer
Tank Spill Prevention:	None
Tank Overfill Prevention:	None
Tank Material:	Not reported
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	None
Pipe Material:	Not reported
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

WA MANIFEST:

Facility Site ID Number:	93625221
SWC Desc:	WT02
FWC Desc:	D001, D002
Form Comm:	None
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	TRUE
Universal waste - lamps - generate:	TRUE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD001328186
Facility Address 2:	Not reported
TAX REG NBR:	601047843
NAICS CD:	312111
BUSINESS TYPE:	Food Manufacturing
MAIL NAME:	Coca Cola Bottling Co of Washington
MAIL ADDR LINE1:	PO Box 93346C
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98009-3346
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BCI Coca Cola Bottling Co of WA
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1334 S Central Ave
LEGAL CITY,ST,ZIP:	Los Angeles, CA 90021
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(213)746-5555
LEGAL EFFECTIVE DATE:	12/31/2002
LAND ORG NAME:	Coca Cola Bottling Co of Washington
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1150 124TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-2000
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1150 124TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-453-1761
OPERATOR EFFECTIVE DATE:	12/31/2003
SITE CONTACT NAME:	Jed J Rusyniak
SITE CONTACT ADDR LINE1:	1150 124TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98005-2102
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425-453-1761
SITE CONTACT EMAIL:	Jrusyniak@na.cokecce.com
FORM CONTACT NAME:	Jed J Rusyniak
FORM CONTACT ADDR LINE1:	1150 124TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425-453-1761
FORM CONTACT EMAIL:	Jrusyniak@na.cokecce.com
GEN STATUS CD:	SQG

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

MONTHLY GENERATION:	FALSE
BATCH GENERATION:	TRUE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	TRUE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

Facility Site ID Number:	93625221
SWC Desc:	Not reported
FWC Desc:	Waste Printing Ink, 3, UN1220, PG II (D001, D035, F003, F005) USDOT Label: Flammable Waste HPL
Form Comm:	Not reported
Data Year:	2010
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD001328186
Facility Address 2:	Not reported
TAX REG NBR:	601432144
NAICS CD:	312111
BUSINESS TYPE:	Food Manufacturing
MAIL NAME:	Coca Cola Bottling Co of Washington
MAIL ADDR LINE1:	PO Box 93346C
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98009-3346
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BCI Coca Cola Bottling Co of WA
LEGAL ORG TYPE:	Private

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

LEGAL ADDR LINE1:	1334 S Central Ave
LEGAL CITY,ST,ZIP:	Los Angeles, CA 90021
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(213)746-5555
LEGAL EFFECTIVE DATE:	12/31/2002
LAND ORG NAME:	Coca Cola Bottling Co of Washington
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1150 124TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-2000
OPERATOR ORG NAME:	Coca-Cola Bottling Company of Washington
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1150 124TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-453-1761
OPERATOR EFFECTIVE DATE:	12/31/2003
SITE CONTACT NAME:	Jed J Rusyniak
SITE CONTACT ADDR LINE1:	1150 124TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98005-2102
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425-453-1761
SITE CONTACT EMAIL:	Jrusyniak@cokecce.com
FORM CONTACT NAME:	Jed J Rusyniak
FORM CONTACT ADDR LINE1:	1150 124TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425-453-1761
FORM CONTACT EMAIL:	Jrusyniak@cokecce.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	93625221
SWC Desc:	WT02
FWC Desc:	D001, D002
Form Comm:	None
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD001328186
Facility Address 2:	Not reported
TAX REG NBR:	601047843
NAICS CD:	312111
BUSINESS TYPE:	Not reported
MAIL NAME:	Coca Cola Bottling Co of Washington
MAIL ADDR LINE1:	PO Box 93346C
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98009-3346
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BCI Coca Cola Bottling Co of WA
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1334 S Central Ave
LEGAL CITY,ST,ZIP:	Los Angeles, CA 90021
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(213)746-5555
LEGAL EFFECTIVE DATE:	12/31/2002
LAND ORG NAME:	Coca Cola Bottling Co of Washington
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1150 124TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-2000
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1150 124TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)463-2520
OPERATOR EFFECTIVE DATE:	12/31/2003
SITE CONTACT NAME:	Margaret Steed
SITE CONTACT ADDR LINE1:	1150 124TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98005-2102
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)463-2520
SITE CONTACT EMAIL:	msteed@na.cokecce.com

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

FORM CONTACT NAME:	Margaret Steed
FORM CONTACT ADDR LINE1:	1150 124TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)463-2520
FORM CONTACT EMAIL:	msteed@na.cokecce.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Facility Site ID Number:	93625221
SWC Desc:	WT02
FWC Desc:	D001, D002
Form Comm:	None
Data Year:	2008
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD001328186
Facility Address 2:	Not reported
TAX REG NBR:	601432144
NAICS CD:	312111

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

BUSINESS TYPE:	Food Manufacturing
MAIL NAME:	Coca Cola Bottling Co of Washington
MAIL ADDR LINE1:	PO Box 93346C
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98009-3346
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BCI Coca Cola Bottling Co of WA
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1334 S Central Ave
LEGAL CITY,ST,ZIP:	Los Angeles, CA 90021
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(213)746-5555
LEGAL EFFECTIVE DATE:	12/31/2002
LAND ORG NAME:	Coca Cola Bottling Co of Washington
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1150 124TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-2000
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1150 124TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-453-1761
OPERATOR EFFECTIVE DATE:	12/31/2003
SITE CONTACT NAME:	Jed J Rusyniak
SITE CONTACT ADDR LINE1:	1150 124TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98005-2102
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425-453-1761
SITE CONTACT EMAIL:	Jrusyniak@cokecce.com
FORM CONTACT NAME:	Jed J Rusyniak
FORM CONTACT ADDR LINE1:	1150 124TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425-453-1761
FORM CONTACT EMAIL:	Jrusyniak@cokecce.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	93625221
SWC Desc:	WT02

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

FWC Desc:	D001, D002
Form Comm:	None
Data Year:	Not reported
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD001328186
Facility Address 2:	Not reported
TAX REG NBR:	601432144
NAICS CD:	312111
BUSINESS TYPE:	Food Manufacturing
MAIL NAME:	Coca Cola Bottling Co of Washington
MAIL ADDR LINE1:	PO Box 93346C
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98009-3346
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BCI Coca Cola Bottling Co of WA
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1334 S Central Ave
LEGAL CITY,ST,ZIP:	Los Angeles, CA 90021
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(213)746-5555
LEGAL EFFECTIVE DATE:	12/31/2002
LAND ORG NAME:	Coca Cola Bottling Co of Washington
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1150 124TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-2000
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1150 124TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-453-1761

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

OPERATOR EFFECTIVE DATE:	12/31/03
SITE CONTACT NAME:	Jed J Rusyniak
SITE CONTACT ADDR LINE1:	1150 124TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98005-2102
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425-453-1761
SITE CONTACT EMAIL:	Jrusyniak@cokecce.com
FORM CONTACT NAME:	Jed J Rusyniak
FORM CONTACT ADDR LINE1:	1150 124TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-2102
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425-453-1761
FORM CONTACT EMAIL:	Jrusyniak@cokecce.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Click this hyperlink while viewing on your computer to access additional WA MANIFEST: detail in the EDR Site Report.

SPILLS:

Facility ID:	614580
Medium:	AIR
Material Desc:	OTHER HAZARDOUS
Material Qty:	Not reported
Material Units:	Not reported
Date Received:	8/7/2009 4:31:00 PM
Contact Name:	Not reported

Facility ID:	602761
Medium:	Not reported
Material Desc:	PETROLEUM - DIESEL FUEL
Material Qty:	5
Material Units:	GALLON
Date Received:	12/18/2007 12:53:00 PM
Contact Name:	UNKNOWN

Facility ID:	561509
Medium:	Not reported
Material Desc:	CHEMICAL
Material Qty:	Not reported
Material Units:	Not reported
Date Received:	3/28/2007
Contact Name:	Not reported

COCA COLA BOTTLING CO BELLEVUE (Continued) **1000251918**

VCP:
- edr_fstat: WA
- edr_fzip: 98005
- edr_fcnty: KING COUNTY
- edr_zip: Not reported
- Facility ID: 93625221
- VCP Status: Not reported
- VCP: Y
- Ecology Status: Not reported
- NFA Type: NFA-VCP Review
- Date NFA: 05/04/2000
- Rank: Not reported

NPDES:
- Facility Status: Active
- Facility Type: Industrial SW GP
- Admin Region: Headquarters
- Latitude: 47.620211
- Longitude: -122.176254
- Permit ID: WAR000872
- Permit Version: 5
- Permit Status: Active
- Permit SubStatus: Coverage Issued
- Ecology Contact: Greg Stegman
- WRIA: Cedar-Sammamish
- Permit Expiration Date: 01/01/2015
- Effective Date: 01/01/2010

K45 **BELLEVUE SCHOOL TRANSPORTATION** **ICR** **S103505539**
South **12037 NE 5TH** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.263 mi.
1388 ft. **Site 1 of 2 in cluster K**

Relative:
Higher

Actual:
164 ft.

ICR:
- Date Ecology Received Report: 05/19/93
- Contaminants Found at Site: Petroleum products
- Media Contaminated: Soil
- Waste Management: Tank
- Region: North Western
- Type of Report Ecology Received: Final cleanup report
- Site Register Issue: 93-06
- County Code: 17
- Contact: Not reported
- Report Title: Not reported

- Date Ecology Received Report: 07/01/93
- Contaminants Found at Site: Petroleum products
- Media Contaminated: Soil
- Waste Management: Tank
- Region: North Western
- Type of Report Ecology Received: Final cleanup report
- Site Register Issue: 93-21
- County Code: 17
- Contact: Not reported
- Report Title: Not reported

K46
South
1/4-1/2
0.263 mi.
1388 ft.

Relative:
Higher

Actual:
164 ft.

BELLEVUE SCHOOL DIST 405
12037 NE 5TH ST
BELLEVUE, WA 98005

Site 2 of 2 in cluster K

Database(s): RCRA-CESQG, PADS, FINDS, ALLSITES, CSCSL NFA, UST, MANIFEST

EDR ID Number: 1000282273
EPA ID Number: WAD980982276

RCRA-CESQG:

Date form received by agency:	02/16/2010
Facility name:	BELLEVUE SCHOOL DIST 405
Facility address:	12037 NE 5TH ST BELLEVUE, WA 98005
EPA ID:	WAD980982276
Contact:	WILLIAM SILVERMAN
Contact address:	12037 NE 5TH ST BELLEVUE, WA 98005
Contact country:	US
Contact telephone:	(425) 456-4567
Contact email:	SILVERMAJ@BSD405.ORG
EPA Region:	10
Land type:	District
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	BELLEVUE SCHOOL DIST
Owner/operator address:	12037 NE 5TH ST BELLEVUE, 98005
Owner/operator country:	US
Owner/operator telephone:	(425)455-6054
Legal status:	District
Owner/Operator Type:	Owner
Owner/Op start date:	05/02/1996
Owner/Op end date:	Not reported

Owner/operator name:	BELLEVUE SCHOOL DISTRICT
Owner/operator address:	12037 NE 5TH ST BELLEVUE, 98005
Owner/operator country:	US
Owner/operator telephone:	(425)456-4567
Legal status:	District
Owner/Operator Type:	Operator
Owner/Op start date:	08/12/1996
Owner/Op end date:	Not reported

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Yes
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: No

Waste type: Lamps
Accumulated waste on-site: Yes
Generated waste on-site: No

Historical Generators:
Date form received by agency: 02/25/2008
Facility name: BELLEVUE SCHOOL DIST 405
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/31/2007
Facility name: BELLEVUE SCHOOL DIST 405
Classification: Not a generator, verified

Date form received by agency: 12/31/2005
Facility name: BELLEVUE SCHOOL DIST 405
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: BELLEVUE SCHOOL DIST 405
Classification: Not a generator, verified

Date form received by agency: 03/01/1996
Facility name: BELLEVUE SCHOOL DIST 405
Site name: BELLEVUE SCHOOL DISTRICT #405
Classification: Large Quantity Generator

Date form received by agency: 12/31/1990
Facility name: BELLEVUE SCHOOL DIST 405
Site name: BELLEVUE SCHOOL DISTRICT
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: WSQG

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

Waste name: A placeholder to allow BR submission to validate. In WA State, Conditionally Exempt Small Quantity Generators (Called SQG in WA) are not required to report waste streams, so no valid State or Fed codes are available for reporting to BR.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 11/08/1990
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

PADS:
EPAID: WAD980982276
Facility name: Bellvue School District #405
Facility Address: 12037 NE 5th
Bellevue, WA 98005
Facility country: US
Generator: Yes
Storer: No
Transporter: No
Disposer: No
Research facility: No
Smelter: No
Facility owner name: Bellvue School District #405
Contact title: Not reported
Contact name: Colin MacRae
Contact tel: (425)455-4510
Contact extension: Not reported
Mailing address: 12037 NE 5th
Bellevue, WA 98005
Mailing country: US
Cert. title: Not reported
Cert. name: Not reported
Cert. date: 7/1/2003
Date received: 8/11/2003

FINDS:

Registry ID: 110000843393

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

HAZARDOUS WASTE BIENNIAL REPORTER

ALLSITES:

Facility Id:	11661625
Latitude:	47.61486
Longitude:	-122.17952
Geographic location identifier (alias facid):	11661625
Facility Name:	Bellevue School Dist 405
Latitude Decimal Degrees:	47.61486
Longitude Decimal Degrees:	-122.17952
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

CSCSL NFA:

Facility/Site Id:	11661625
CS Id:	7904
NFA Type:	NFA-II
NFA Date:	10/03/2011
Rank:	Not reported

UST:

Facility ID:	11661625
Site ID:	100367
Lat Deg:	47
Lat Min:	36
Lat Sec:	53.496000000000663
Long Deg:	-122
Long Min:	10
Long Sec:	46.271999999987656
UBI:	1790113630010004
Phone Number:	4254564595
Tank ID:	21064
Tank Name:	3
Install Date:	1/1/1971
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Automatic Line Leak Detection

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A3772

Tank ID:	21090
Tank Name:	7
Install Date:	5/13/1993
Capacity:	20,000 to 29,999 Gallons
Tank Upgrade Date:	5/13/1993
TankSystem Status:	Operational
TankSystem Status Change Date:	8/26/1996
Tank Status:	Operational
Tank Permit Expiration Date:	8/31/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Interstitial Monitoring (sump sensor)
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Interstitial Monitoring
Pipe Tightness Test:	No
Tank Actual Status Date:	8/6/1996
Tag Number:	A3772

Tank ID:	21128
Tank Name:	1
Install Date:	1/1/1971
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

Pipe Primary Release Detection: Automatic Line Leak Detection
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: None
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: A3772

Tank ID: 21167
Tank Name: 9
Install Date: 5/13/1993
Capacity: 20,000 to 29,999 Gallons
Tank Upgrade Date: 5/13/1993
TankSystem Status: Operational
TankSystem Status Change Date: 8/26/1996
Tank Status: Operational
Tank Permit Expiration Date: 8/31/2012
Tank Closure Date: 1/1/0001
Tank Pumping System: Pressurized System
Tank Spill Prevention: Spill Bucket/Spill Box
Tank Overfill Prevention: Automatic Shutoff (fill pipe)
Tank Material: Fiberglass Reinforced Plastic
Tank Construction: Double Wall Tank
Tank Tightness Test: Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection: Corrosion Resistant
Pipe Material: Fiberglass
Pipe Construction: Double Wall Pipe
Pipe Primary Release Detection: Automatic Line Leak Detection
Pipe Second Release Detection: Interstitial Monitoring (sump sensor)
Pipe Corrosion Protection: Corrosion Resistant
Tank Primary Release Detection: Automatic Tank Gauging
Tank Second Release Detection: Interstitial Monitoring
Pipe Tightness Test: No
Tank Actual Status Date: 8/6/1996
Tag Number: A3772

Tank ID: 21203
Tank Name: 5
Install Date: 12/31/1964
Capacity: 111 TO 1,100 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Exempt
TankSystem Status Change Date: 8/26/1996
Tank Status: Exempt
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Steel
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: Not reported
Pipe Material: Fiberglass

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A3772

Tank ID:	21228
Tank Name:	4
Install Date:	1/1/1971
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A3772

Tank ID:	21301
Tank Name:	8
Install Date:	5/13/1993
Capacity:	20,000 to 29,999 Gallons
Tank Upgrade Date:	5/13/1993
TankSystem Status:	Operational
TankSystem Status Change Date:	8/26/1996
Tank Status:	Operational
Tank Permit Expiration Date:	8/31/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection:	Corrosion Resistant

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Interstitial Monitoring (sump sensor)
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Interstitial Monitoring
Pipe Tightness Test:	No
Tank Actual Status Date:	8/6/1996
Tag Number:	A3772

Tank ID:	21329
Tank Name:	2
Install Date:	1/1/1971
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A3772

Tank ID:	21363
Tank Name:	6
Install Date:	10/1/1988
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Exempt
TankSystem Status Change Date:	8/26/1996
Tank Status:	Exempt
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Gravity Delivery System (No Pump)
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

Tank Corrosion Protection: Not reported
Pipe Material: Fiberglass
Pipe Construction: Double Wall Pipe
Pipe Primary Release Detection: Other
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Weekly Manual Gauging
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: A3772

WA MANIFEST:
Facility Site ID Number: 11661625
SWC Desc: Not reported
FWC Desc: Not reported
Form Comm: Not reported
Data Year: Not reported
Permit by Rule: FALSE
Treatment by Generator: FALSE
Mixed radioactive waste: FALSE
Importer of hazardous waste: FALSE
Immediate recycler: FALSE
Treatment/Storage/Disposal/Recycling Facility: FALSE
Generator of dangerous fuel waste: FALSE
Generator marketing to burner: FALSE
"Other marketers (i.e., blender, distributor, etc.)": FALSE
Utility boiler burner: FALSE
Industry boiler burner: FALSE
Industrial Furnace: FALSE
Smelter defferal: FALSE
Universal waste - batteries - generate: FALSE
Universal waste - thermostats - generate: FALSE
Universal waste - mercury - generate: FALSE
Universal waste - lamps - generate: TRUE
Universal waste - batteries - accumulate: FALSE
Universal waste - thermostats - accumulate: FALSE
Universal waste - mercury - accumulate: FALSE
Universal waste - lamps - accumulate: FALSE
Destination Facility for Universal Waste: FALSE
Off-specification used oil burner - utility boiler: FALSE
Off-specification used oil burner - industrial boiler: FALSE
Off-specification used oil burner - industrial furnace: FALSE
EPA ID: WAD980982276
Facility Address 2: Not reported
TAX REG NBR: 179011363
NAICS CD: 61111
BUSINESS TYPE: Not reported
MAIL NAME: Bellevue School Dist
MAIL ADDR LINE1: 12037 NE 5TH ST
MAIL CITY,ST,ZIP: BELLEVUE, WA 98005-3135
MAIL COUNTRY: UNITED STATES
LEGAL ORG NAME: Bellevue School Dist
LEGAL ORG TYPE: District
LEGAL ADDR LINE1: 12037 NE 5TH ST
LEGAL CITY,ST,ZIP: BELLEVUE, WA 98005-3135
LEGAL COUNTRY: UNITED STATES

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

LEGAL PHONE NBR:	(425)455-6054
LEGAL EFFECTIVE DATE:	5/2/1996
LAND ORG NAME:	Bellevue School Dist
LAND ORG TYPE:	District
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	P O Box 90010
LAND CITY,ST,ZIP:	BELLEVUE, WA 98009-9010
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)456-4068
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	District
OPERATOR ADDR LINE1:	12037 NE 5TH ST
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)456-4567
OPERATOR EFFECTIVE DATE:	8/12/1996
SITE CONTACT NAME:	William Silverman
SITE CONTACT ADDR LINE1:	12037 NE 5TH ST
SITE CONTACT ZIP:	BELLEVUE, WA 98005-3135
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)456-4567
SITE CONTACT EMAIL:	silvermaj@bsd405.org
FORM CONTACT NAME:	William Silverman
FORM CONTACT ADDR LINE1:	12037 NE 5TH ST
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)456-4567
FORM CONTACT EMAIL:	silvermaj@bsd405.org
GEN STATUS CD:	SQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	TRUE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	TRUE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	TRUE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

Facility Site ID Number:	11661625
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2010
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	True
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD980982276
Facility Address 2:	Not reported
TAX REG NBR:	179011363
NAICS CD:	611110
BUSINESS TYPE:	Not reported
MAIL NAME:	Bellevue School Dist
MAIL ADDR LINE1:	12037 NE 5TH ST
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Bellevue School Dist
LEGAL ORG TYPE:	District
LEGAL ADDR LINE1:	12037 NE 5TH ST
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)455-6054
LEGAL EFFECTIVE DATE:	5/2/1996
LAND ORG NAME:	Bellevue School Dist
LAND ORG TYPE:	District
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	P O Box 90010
LAND CITY,ST,ZIP:	BELLEVUE, WA 98009-9010
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)456-4068
OPERATOR ORG NAME:	Bellevue School District
OPERATOR ORG TYPE:	District
OPERATOR ADDR LINE1:	12037 NE 5TH ST
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)456-4567
OPERATOR EFFECTIVE DATE:	8/12/1996
SITE CONTACT NAME:	William Silverman
SITE CONTACT ADDR LINE1:	12037 NE 5TH ST
SITE CONTACT ZIP:	BELLEVUE, WA 98005-3135
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)456-4567
SITE CONTACT EMAIL:	silvermaj@bsd405.org
FORM CONTACT NAME:	William Silverman
FORM CONTACT ADDR LINE1:	12037 NE 5TH ST
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-3135

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

FORM CONTACT COUNTRY: UNITED STATES
FORM CONTACT PHONE NBR: (425)456-4567
FORM CONTACT EMAIL: silvermaj@bsd405.org
GEN STATUS CD: SQG
MONTHLY GENERATION: False
BATCH GENERATION: True
ONE TIME GENERATION: False
TRANSPORTS OWN WASTE: True
TRANSPORTS OTHRS WASTE: False
RECYCLER ONSITE: False
TRANSFER FACILITY: False
OTHER EXEMPTION: Not reported
UW BATTERY GEN: True
USED OIL TRANSPORTER: False
USED OIL TRANSFER FACLTY: False
USED OIL PROCESSOR: False
USED OIL REREFINER: False
USED OIL FUEL MRKTR DIRECTS SHPMNTS: False
USED OIL FUEL MRKTR MEETS SPECS: False

Facility Site ID Number: 11661625
SWC Desc: Not reported
FWC Desc: Not reported
Form Comm: Not reported
Data Year: 2009
Permit by Rule: False
Treatment by Generator: False
Mixed radioactive waste: False
Importer of hazardous waste: False
Immediate recycler: False
Treatment/Storage/Disposal/Recycling Facility: False
Generator of dangerous fuel waste: False
Generator marketing to burner: False
"Other marketers (i.e., blender, distributor, etc.)": False
Utility boiler burner: False
Industry boiler burner: False
Industrial Furnace: False
Smelter defferal: False
Universal waste - batteries - generate: False
Universal waste - thermostats - generate: False
Universal waste - mercury - generate: False
Universal waste - lamps - generate: False
Universal waste - batteries - accumulate: True
Universal waste - thermostats - accumulate: False
Universal waste - mercury - accumulate: False
Universal waste - lamps - accumulate: True
Destination Facility for Universal Waste: False
Off-specification used oil burner - utility boiler: False
Off-specification used oil burner - industrial boiler: False
Off-specification used oil burner - industrial furnace: False
EPA ID: WAD980982276
Facility Address 2: Not reported
TAX REG NBR: 179011363
NAICS CD: 611110
BUSINESS TYPE: Not reported
MAIL NAME: Bellevue School Dist
MAIL ADDR LINE1: 12037 NE 5TH ST

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

MAIL CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Bellevue School Dist
LEGAL ORG TYPE:	District
LEGAL ADDR LINE1:	12037 NE 5TH ST
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)455-6054
LEGAL EFFECTIVE DATE:	5/2/1996
LAND ORG NAME:	Bellevue School Dist
LAND ORG TYPE:	District
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	P O Box 90010
LAND CITY,ST,ZIP:	BELLEVUE, WA 98009-9010
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)456-4068
OPERATOR ORG NAME:	Bellevue School District
OPERATOR ORG TYPE:	District
OPERATOR ADDR LINE1:	12037 NE 5TH ST
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)456-4567
OPERATOR EFFECTIVE DATE:	8/12/1996
SITE CONTACT NAME:	William Silverman
SITE CONTACT ADDR LINE1:	12037 NE 5TH ST
SITE CONTACT ZIP:	BELLEVUE, WA 98005-3135
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)456-4567
SITE CONTACT EMAIL:	silvermaj@bsd405.org
FORM CONTACT NAME:	William Silverman
FORM CONTACT ADDR LINE1:	12037 NE 5TH ST
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)456-4567
FORM CONTACT EMAIL:	silvermaj@bsd405.org
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	True
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	11661625
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD980982276
Facility Address 2:	Not reported
TAX REG NBR:	179011363
NAICS CD:	61111
BUSINESS TYPE:	Not reported
MAIL NAME:	Bellevue School Dist
MAIL ADDR LINE1:	12037 NE 5TH ST
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Bellevue School Dist
LEGAL ORG TYPE:	District
LEGAL ADDR LINE1:	12037 NE 5TH ST
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)455-6054
LEGAL EFFECTIVE DATE:	5/2/1996
LAND ORG NAME:	Bellevue School Dist
LAND ORG TYPE:	District
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	P O Box 90010
LAND CITY,ST,ZIP:	BELLEVUE, WA 98009-9010
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)456-4068
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	District
OPERATOR ADDR LINE1:	12037 NE 5TH ST
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)455-6054
OPERATOR EFFECTIVE DATE:	8/12/1996
SITE CONTACT NAME:	Colin Macrae
SITE CONTACT ADDR LINE1:	12037 NE 5TH ST

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

SITE CONTACT ZIP:	BELLEVUE, WA 98005-3135
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)455-6054
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Colin Macrae
FORM CONTACT ADDR LINE1:	12037 NE 5TH ST
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)455-6054
FORM CONTACT EMAIL:	macraec@bsd405.org
GEN STATUS CD:	SQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Facility Site ID Number:	11661625
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2008
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	True
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	True
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

EPA ID:	WAD980982276
Facility Address 2:	Not reported
TAX REG NBR:	179011363
NAICS CD:	61111
BUSINESS TYPE:	Not reported
MAIL NAME:	Bellevue School Dist
MAIL ADDR LINE1:	12037 NE 5TH ST
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Bellevue School Dist
LEGAL ORG TYPE:	District
LEGAL ADDR LINE1:	12037 NE 5TH ST
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)455-6054
LEGAL EFFECTIVE DATE:	5/2/1996
LAND ORG NAME:	Bellevue School Dist
LAND ORG TYPE:	District
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	P O Box 90010
LAND CITY,ST,ZIP:	BELLEVUE, WA 98009-9010
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)456-4068
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	District
OPERATOR ADDR LINE1:	12037 NE 5TH ST
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)456-4567
OPERATOR EFFECTIVE DATE:	8/12/1996
SITE CONTACT NAME:	William Silverman
SITE CONTACT ADDR LINE1:	12037 NE 5TH ST
SITE CONTACT ZIP:	BELLEVUE, WA 98005-3135
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)456-4567
SITE CONTACT EMAIL:	silvermaj@bsd405.org
FORM CONTACT NAME:	William Silverman
FORM CONTACT ADDR LINE1:	12037 NE 5TH ST
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-3135
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)456-4567
FORM CONTACT EMAIL:	silvermaj@bsd405.org
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	True
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False

BELLEVUE SCHOOL DIST 405 (Continued) **1000282273**

USED OIL FUEL MRKTR MEETS SPECS: False

Click this hyperlink while viewing on your computer to access
1 additional WA MANIFEST: record(s) in the EDR Site Report.

47
South
1/4-1/2
0.289 mi.
1525 ft.

BEST BUY SITE
457 120TH AVE
BELLEVUE, WA 98005

ALLSITES
CSCSL NFA
VCP

S109824419
N/A

Relative:
Lower

Actual:
145 ft.

ALLSITES:

Facility Id:	21524
Latitude:	47.6138609
Longitude:	-122.18175
Geographic location identifier (alias facid):	21524
Facility Name:	Best Buy Site
Latitude Decimal Degrees:	47.613860934999998
Longitude Decimal Degrees:	-122.18175347099999
Coordinate Point Areal Extent Code:	0
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	8
Location Verified Code:	Not reported
Geographic Location Identifier (Alias Facid):	21524
Interaction (Aka Env Int) Type Code:	VOLCLNST
Interaction (Aka Env Int) Description:	Voluntary Cleanup Sites
Interaction Status:	I
Federal Program Indentifier:	nw2188
Interaction Start Date:	07/29/2009
Interaction End Date:	03/24/2010
prgm_facil:	Best Buy Site
cur_sys_pr:	TOXICS
cur_sys_nm:	ISIS

CSCSL NFA:

Facility/Site Id:	21524
CS Id:	2547
NFA Type:	NFA-SHA, IRAP, or VCP
NFA Date:	03/24/2010
Rank:	Not reported

VCP:

edr_fstat:	WA
edr_fzip:	98005
edr_fcnty:	KING COUNTY
edr_zip:	Not reported
Facility ID:	21524
VCP Status:	Not reported
VCP:	Y
Ecology Status:	Not reported
NFA Type:	NFA-SHA, IRAP, or VCP
Date NFA:	03/24/2010
Rank:	Not reported

L48
WSW
1/4-1/2
0.290 mi.
1530 ft.

Relative:
Lower

Actual:
130 ft.

CHEVRON USA INC SS 97531
11606 NORTHEAST 8TH STREET
BELLEVUE, WA 98005

Site 1 of 4 in cluster L

Database(s): RCRA-NonGen, FINDS, ALLSITES, CSCSL NFA, UST, MANIFEST, VCP

EDR ID Number: 1000659777
EPA ID Number: WAD988494530

RCRA-NonGen:

Date form received by agency:	02/11/2010
Facility name:	CHEVRON USA INC SS 97531
Facility address:	11608 NE 8TH ST BELLEVUE, WA 98005
EPA ID:	WAD988494530
Mailing address:	PO BOX 6004 SAN RAMON, CA 94583
Contact:	JOCKO RODRIGUEZ
Contact address:	PO BOX 6004 SAN RAMON, CA 94583
Contact country:	US
Contact telephone:	(925) 842-3733
Contact email:	NAWTDESK@CHEVRON.COM
EPA Region:	10
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CHEVRON PRODUCTS CO
Owner/operator address:	PO BOX 6004 SAN RAMON, 94583
Owner/operator country:	US
Owner/operator telephone:	(925)842-5931
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/14/1997
Owner/Op end date:	Not reported

Owner/operator name:	CHEVRON PRODUCTS CO
Owner/operator address:	11606 NE 8TH ST BELLEVUE, 98005
Owner/operator country:	US
Owner/operator telephone:	(425)454-9662
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	05/14/1997
Owner/Op end date:	Not reported

Owner/operator name:	CHEVRON PRODUCTS CO
Owner/operator address:	PO BOX 6004 SAN RAMON, CA 94583
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/14/1997
Owner/Op end date:	Not reported

Owner/operator name:	DAVID SWAP

CHEVRON USA INC SS 97531 (Continued) **1000659777**

Owner/operator address: 11606 NE 8TH ST
BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/14/1997
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/11/2008
Facility name: CHEVRON USA INC SS 97531
Classification: Not a generator, verified

Date form received by agency: 12/31/2007
Facility name: CHEVRON USA INC SS 97531
Classification: Not a generator, verified

Date form received by agency: 12/31/2005
Facility name: CHEVRON USA INC SS 97531
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: CHEVRON USA INC SS 97531
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 01/12/1993
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005367021

CHEVRON USA INC SS 97531 (Continued) **1000659777**

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ALLSITES:

Facility Id:	66175848
Latitude:	47.6172210
Longitude:	-122.18636
Geographic location identifier (alias facid):	66175848
Facility Name:	Chevron USA Inc SS 97531
Latitude Decimal Degrees:	47.617221000000001
Longitude Decimal Degrees:	-122.186364
Coordinate Point Areal Extent Code:	4
Horizontal Accuracy Code:	6
Coordinate Point Geographic Position Code:	5
Location Verified Code:	N

CSCSL NFA:

Facility/Site Id:	66175848
CS Id:	7110
NFA Type:	NFA-VCP Review
NFA Date:	12/19/2002
Rank:	Not reported

UST:

Facility ID:	66175848
Site ID:	5237
Lat Deg:	47
Lat Min:	37
Lat Sec:	1.9956000000024687
Long Deg:	-122
Long Min:	11
Long Sec:	10.910399999991114
UBI:	4090180690010067
Phone Number:	9258429002
Tank ID:	32721
Tank Name:	2
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001

CHEVRON USA INC SS 97531 (Continued) **1000659777**

TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0746

Tank ID:	32771
Tank Name:	6
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0746

Tank ID:	32827
Tank Name:	4
Install Date:	12/31/1964
Capacity:	Not reported

CHEVRON USA INC SS 97531 (Continued) **1000659777**

Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0746

Tank ID:	32885
Tank Name:	3
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0746

Tank ID:	32948
Tank Name:	5
Install Date:	12/31/1964

CHEVRON USA INC SS 97531 (Continued) **1000659777**

Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0746

Tank ID:	33007
Tank Name:	1
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0746

Tank ID:	35772
Tank Name:	4R

CHEVRON USA INC SS 97531 (Continued) **1000659777**

Install Date:	8/15/1991
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	8/15/1991
TankSystem Status:	Removed
TankSystem Status Change Date:	4/7/2004
Tank Status:	Removed
Tank Permit Expiration Date:	9/30/2000
Tank Closure Date:	11/26/2001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Ball Float Valve (vent line)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Interstitial Monitoring
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0746

Tank ID:	36967
Tank Name:	2R
Install Date:	8/15/1991
Capacity:	10,000 to 19,999 Gallons
Tank Upgrade Date:	8/15/1991
TankSystem Status:	Removed
TankSystem Status Change Date:	4/7/2004
Tank Status:	Removed
Tank Permit Expiration Date:	9/30/2000
Tank Closure Date:	11/26/2001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Ball Float Valve (vent line)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Interstitial Monitoring
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0746

Tank ID:	37991

CHEVRON USA INC SS 97531 (Continued) **1000659777**

Tank Name:	1R
Install Date:	8/15/1991
Capacity:	10,000 to 19,999 Gallons
Tank Upgrade Date:	8/15/1991
TankSystem Status:	Removed
TankSystem Status Change Date:	4/7/2004
Tank Status:	Removed
Tank Permit Expiration Date:	9/30/2000
Tank Closure Date:	11/26/2001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Ball Float Valve (vent line)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Interstitial Monitoring
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0746

Tank ID:	39106
Tank Name:	3R
Install Date:	8/15/1991
Capacity:	10,000 to 19,999 Gallons
Tank Upgrade Date:	8/15/1991
TankSystem Status:	Removed
TankSystem Status Change Date:	4/7/2004
Tank Status:	Removed
Tank Permit Expiration Date:	9/30/2000
Tank Closure Date:	11/26/2001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Ball Float Valve (vent line)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Interstitial Monitoring
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A0746

CHEVRON USA INC SS 97531 (Continued) **1000659777**

WA MANIFEST:

Facility Site ID Number:	66175848
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2010
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD988494530
Facility Address 2:	Not reported
TAX REG NBR:	409018069
NAICS CD:	562910
BUSINESS TYPE:	Remediation Site
MAIL NAME:	Chevron Products Co
MAIL ADDR LINE1:	PO Box 6004
MAIL CITY,ST,ZIP:	San Ramon, CA 94583-2324
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Chevron Products Co
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO Box 6004
LEGAL CITY,ST,ZIP:	San Ramon, CA 94583-2324
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(925)842-5931
LEGAL EFFECTIVE DATE:	5/14/1997
LAND ORG NAME:	Chevron Products Co
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO Box 6004
LAND CITY,ST,ZIP:	San Ramon, CA 94583-2324
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	877-386-6044
OPERATOR ORG NAME:	Chevron Products Co
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	11606 NE 8th St

CHEVRON USA INC SS 97531 (Continued) **1000659777**

OPERATOR CITY,ST,ZIP:	Bellevue, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)454-9662
OPERATOR EFFECTIVE DATE:	5/14/1997
SITE CONTACT NAME:	Jocko Rodriguez
SITE CONTACT ADDR LINE1:	PO Box 6004
SITE CONTACT ZIP:	San Ramon, CA 94583-2324
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	877-386-6044
SITE CONTACT EMAIL:	NAWTDesk@chevron.com
FORM CONTACT NAME:	Jocko Rodriguez
FORM CONTACT ADDR LINE1:	PO Box 6004
FORM CONTACT CITY,ST,ZIP:	San Ramon, CA 94583-2324
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	877-386-6044
FORM CONTACT EMAIL:	NAWTDesk@chevron.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	66175848
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2009
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False

CHEVRON USA INC SS 97531 (Continued) **1000659777**

Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD988494530
Facility Address 2:	Not reported
TAX REG NBR:	409018069
NAICS CD:	562910
BUSINESS TYPE:	Remediation Site
MAIL NAME:	Chevron Products Co
MAIL ADDR LINE1:	PO Box 6004
MAIL CITY,ST,ZIP:	San Ramon, CA 94583-2324
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Chevron Products Co
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO Box 6004
LEGAL CITY,ST,ZIP:	San Ramon, CA 94583-2324
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(925)842-5931
LEGAL EFFECTIVE DATE:	5/14/1997
LAND ORG NAME:	Chevron Products Co
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO Box 6004
LAND CITY,ST,ZIP:	San Ramon, CA 94583-2324
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(925)842-5931
OPERATOR ORG NAME:	Chevron Products Co
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	11606 NE 8th St
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)454-9662
OPERATOR EFFECTIVE DATE:	5/14/1997
SITE CONTACT NAME:	Jocko Rodriguez
SITE CONTACT ADDR LINE1:	PO Box 6004
SITE CONTACT ZIP:	San Ramon, CA 94583-2324
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	925-842-3733
SITE CONTACT EMAIL:	NAWTDesk@chevron.com
FORM CONTACT NAME:	Jocko Rodriguez
FORM CONTACT ADDR LINE1:	PO Box 6004
FORM CONTACT CITY,ST,ZIP:	San Ramon, CA 94583-2324
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	925-842-3733
FORM CONTACT EMAIL:	NAWTDesk@chevron.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported

CHEVRON USA INC SS 97531 (Continued) **1000659777**

UW BATTERY GEN:	False	
USED OIL TRANSPORTER:	False	
USED OIL TRANSFER FACLTY:	False	
USED OIL PROCESSOR:	False	
USED OIL REREFINER:	False	
USED OIL FUEL MRKTR DIRECTS SHPMNTS:		False
USED OIL FUEL MRKTR MEETS SPECS:		False
Facility Site ID Number:	66175848	
SWC Desc:	Not reported	
FWC Desc:	Not reported	
Form Comm:	Not reported	
Data Year:	Not reported	
Permit by Rule:	No	
Treatment by Generator:	No	
Mixed radioactive waste:	No	
Importer of hazardous waste:	No	
Immediate recycler:	No	
Treatment/Storage/Disposal/Recycling Facility:		No
Generator of dangerous fuel waste:		No
Generator marketing to burner:		No
"Other marketers (i.e., blender, distributor, etc.)":		No
Utility boiler burner:		No
Industry boiler burner:		No
Industrial Furnace:		No
Smelter defferal:		No
Universal waste - batteries - generate:		No
Universal waste - thermostats - generate:		No
Universal waste - mercury - generate:		No
Universal waste - lamps - generate:		No
Universal waste - batteries - accumulate:		No
Universal waste - thermostats - accumulate:		No
Universal waste - mercury - accumulate:		No
Universal waste - lamps - accumulate:		No
Destination Facility for Universal Waste:		No
Off-specification used oil burner - utility boiler:		No
Off-specification used oil burner - industrial boiler:		No
Off-specification used oil burner - industrial furnace:		No
EPA ID:	WAD988494530	
Facility Address 2:	Not reported	
TAX REG NBR:	601357682	
NAICS CD:	56291	
BUSINESS TYPE:	Remediation Site	
MAIL NAME:	Chevron Products Co	
MAIL ADDR LINE1:	PO Box 6004	
MAIL CITY,ST,ZIP:	San Ramon, CA 94583-2324	
MAIL COUNTRY:	UNITED STATES	
LEGAL ORG NAME:	Chevron Products Co	
LEGAL ORG TYPE:	Private	
LEGAL ADDR LINE1:	PO Box 6004	
LEGAL CITY,ST,ZIP:	San Ramon, CA 94583-2324	
LEGAL COUNTRY:	UNITED STATES	
LEGAL PHONE NBR:	(925)842-5931	
LEGAL EFFECTIVE DATE:	5/14/1997	
LAND ORG NAME:	Chevron Products Co	
LAND ORG TYPE:	Private	
LAND PERSON NAME:	Not reported	

CHEVRON USA INC SS 97531 (Continued) **1000659777**

LAND ADDR LINE1:	PO Box 6004
LAND CITY,ST,ZIP:	San Ramon, CA 94583-2324
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(925)842-5931
OPERATOR ORG NAME:	Chevron Products Co
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	11606 NE 8th St
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)454-9662
OPERATOR EFFECTIVE DATE:	5/14/1997
SITE CONTACT NAME:	Kathy L Norris
SITE CONTACT ADDR LINE1:	PO Box 6004
SITE CONTACT ZIP:	San Ramon, CA 94583-2324
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(925)842-5931
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Kathy L Norris
FORM CONTACT ADDR LINE1:	PO Box 6004
FORM CONTACT CITY,ST,ZIP:	SAN RAMON, CA 94583-2324
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(925)842-5931
FORM CONTACT EMAIL:	KNorris@ChevronTexaco.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Facility Site ID Number:	66175848
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2008
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False

CHEVRON USA INC SS 97531 (Continued) **1000659777**

Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD988494530
Facility Address 2:	Not reported
TAX REG NBR:	601357682
NAICS CD:	56291
BUSINESS TYPE:	Remediation Site
MAIL NAME:	Chevron Products Co
MAIL ADDR LINE1:	PO Box 6004
MAIL CITY,ST,ZIP:	San Ramon, CA 94583-2324
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Chevron Products Co
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO Box 6004
LEGAL CITY,ST,ZIP:	San Ramon, CA 94583-2324
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(925)842-5931
LEGAL EFFECTIVE DATE:	5/14/1997
LAND ORG NAME:	Chevron Products Co
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO Box 6004
LAND CITY,ST,ZIP:	San Ramon, CA 94583-2324
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(925)842-5931
OPERATOR ORG NAME:	Chevron Products Co
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	11606 NE 8th St
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)454-9662
OPERATOR EFFECTIVE DATE:	5/14/1997
SITE CONTACT NAME:	Kathy L Norris
SITE CONTACT ADDR LINE1:	PO Box 6004
SITE CONTACT ZIP:	San Ramon, CA 94583-2324
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(925)842-5931
SITE CONTACT EMAIL:	NAWTDesk@chevron.com
FORM CONTACT NAME:	Kathy L Norris
FORM CONTACT ADDR LINE1:	PO Box 6004
FORM CONTACT CITY,ST,ZIP:	SAN RAMON, CA 94583-2324
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(925)842-5931
FORM CONTACT EMAIL:	NAWTDesk@chevron.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	False

CHEVRON USA INC SS 97531 (Continued) **1000659777**

BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	66175848
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD988494530
Facility Address 2:	Not reported
TAX REG NBR:	601357682
NAICS CD:	56291
BUSINESS TYPE:	Remediation Site
MAIL NAME:	Chevron Products Co
MAIL ADDR LINE1:	PO Box 6004
MAIL CITY,ST,ZIP:	San Ramon, CA 94583-2324
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Chevron Products Co
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO Box 6004

CHEVRON USA INC SS 97531 (Continued) **1000659777**

LEGAL CITY,ST,ZIP:	San Ramon, CA 94583-2324
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(925)842-5931
LEGAL EFFECTIVE DATE:	5/14/1997
LAND ORG NAME:	Chevron Products Co
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO Box 6004
LAND CITY,ST,ZIP:	San Ramon, CA 94583-2324
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(925)842-5931
OPERATOR ORG NAME:	Chevron Products Co
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	11606 NE 8th St
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)454-9662
OPERATOR EFFECTIVE DATE:	5/14/1997
SITE CONTACT NAME:	Kathy L Norris
SITE CONTACT ADDR LINE1:	PO Box 6004
SITE CONTACT ZIP:	San Ramon, CA 94583-2324
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(925)842-5931
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Kathy L Norris
FORM CONTACT ADDR LINE1:	PO Box 6004
FORM CONTACT CITY,ST,ZIP:	SAN RAMON, CA 94583-2324
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(925)842-5931
FORM CONTACT EMAIL:	KNorris@Chevron.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	FALSE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

Click this hyperlink while viewing on your computer to access
1 additional WA MANIFEST: record(s) in the EDR Site Report.

VCP:

edr_fstat:	WA
edr_fzip:	98005
edr_fcnty:	KING COUNTY
edr_zip:	Not reported
Facility ID:	66175848
VCP Status:	Not reported

CHEVRON USA INC SS 97531 (Continued) **1000659777**

VCP: Y
Ecology Status: Not reported
NFA Type: NFA-VCP Review
Date NFA: 12/19/2002
Rank: Not reported

L49 **CHEVRON #9 7531** **ICR S103506337**
WSW **11606 NE 8TH** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.290 mi.
1533 ft. **Site 2 of 4 in cluster L**

Relative:
Lower

Actual:
130 ft.

ICR:

Date Ecology Received Report:	/ /
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	93-09
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	06/24/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-03
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	07/06/92
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-29
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	01/15/94
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	93-23
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	03/03/95

CHEVRON #9 7531 (Continued) **S103506337**

Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	94-03
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	08/09/95
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-13
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	04/12/01
Contaminants Found at Site:	Not reported
Media Contaminated:	Groundwater
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-42
County Code:	17
Contact:	Not reported
Report Title:	Well Abandonment - January 2001

Date Ecology Received Report:	05/08/02
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-48
County Code:	17
Contact:	Not reported
Report Title:	Environmental Investigation

Date Ecology Received Report:	09/19/96
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-41
County Code:	17
Contact:	Not reported
Report Title:	Not reported

L50 **ARCO #0836** **ICR** **S103503400**
WSW **11611 NE 8TH ST.** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.292 mi.
1541 ft. **Site 3 of 4 in cluster L**

Relative:
Lower

Actual:
129 ft.

ICR:

Date Ecology Received Report:	10/31/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	95-13
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	01/08/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	95-17
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	08/18/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-09
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	04/30/99
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-15
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	09/23/99
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-19
County Code:	17

ARCO #0836 (Continued) **S103503400**

Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	06/09/00
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-28
County Code:	17
Contact:	Not reported
Report Title:	First & Second Quarters Ground Water Monitoring 2000
Date Ecology Received Report:	03/03/00
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-27
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	07/30/92
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-30
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	04/26/93
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	93-02
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	05/25/93
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	93-01
County Code:	17
Contact:	Not reported
Report Title:	Not reported

ARCO #0836 (Continued) **S103503400**

Date Ecology Received Report: 08/03/93
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-09
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 01/10/94
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-17
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 02/10/94
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-29
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 06/15/94
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 93-34
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 08/25/94
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-03
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 09/23/94
Contaminants Found at Site: Petroleum products

ARCO #0836 (Continued) **S103503400**

Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-03
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 04/07/95
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-03
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 02/22/96
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-34
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 01/19/96
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 94-27
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 05/24/01
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-37
County Code: 17
Contact: Not reported
Report Title: First & Second Quarters 2001 Ground Water Monitoring

Date Ecology Received Report: 02/12/97
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank

ARCO #0836 (Continued) **S103503400**

Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-53
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	11/06/00
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-32
County Code:	17
Contact:	Not reported
Report Title:	Third & Fourth Quarters 2000 Ground Water Monitoring
Date Ecology Received Report:	12/13/02
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-55
County Code:	17
Contact:	Not reported
Report Title:	November 2002 Annual Report

L51 **ARCO 0836** **RCRA-NonGen** **1004794039**
WSW **11611 NE 8TH ST** **FINDS** **WAD988484887**
1/4-1/2 **BELLEVUE, WA 98005** **ALLSITES**
0.292 mi. **LUST**
1541 ft. **Site 4 of 4 in cluster L** **MANIFEST**
SPILLS

Relative:
Lower

Actual:
129 ft.

RCRA-NonGen:

Date form received by agency:	10/30/2009
Facility name:	ARCO 0836
Facility address:	11611 NE 8TH ST BELLEVUE, WA 98005
EPA ID:	WAD988484887
Mailing address:	PO BOX 6038 ARTESIA, CA 90702
Contact:	BRATZO BASAGOITIA
Contact address:	PO BOX 6038 ARTESIA, CA 90702
Contact country:	US
Contact telephone:	(714) 670-3958
Contact email:	BASABM@BP.COM
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	BP WEST COAST PRODUCTS LLC
Owner/operator address:	PO BOX 6038

ARCO 0836 (Continued) **1004794039**

ARTESIA, CA 90702
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/09/1996
Owner/Op end date: Not reported

Owner/operator name: BP WEST COAST PRODUCTS LLC
Owner/operator address: PO BOX 6038
ARTESIA, 90702
Owner/operator country: US
Owner/operator telephone: (714)670-3958
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/09/1996
Owner/Op end date: Not reported

Owner/operator name: MEK CORPORATION
Owner/operator address: 11611 NE 8TH STREET
BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/19/1991
Owner/Op end date: Not reported

Owner/operator name: MEK CORPORATION
Owner/operator address: 11611 NE 8TH STREET
BELLEVUE, 98005
Owner/operator country: US
Owner/operator telephone: 425-454-9685
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 07/19/1991
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:

ARCO 0836 (Continued) **1004794039**

Date form received by agency: 02/26/2008
Facility name: ARCO 0836
Classification: Not a generator, verified

Date form received by agency: 12/31/2007
Facility name: ARCO 0836
Classification: Not a generator, verified

Date form received by agency: 12/31/2005
Facility name: ARCO 0836
Classification: Small Quantity Generator

Date form received by agency: 12/31/2003
Facility name: ARCO 0836
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110005359815

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ALLSITES:

Facility Id: 63427923
Latitude: 47.6169999
Longitude: -122.18526
Geographic location identifier (alias facid): 63427923
Facility Name: Arco 0836
Latitude Decimal Degrees: 47.616999916499999
Longitude Decimal Degrees: -122.185265348
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 6
Coordinate Point Geographic Position Code: 8
Location Verified Code: Not reported

LUST:

FS ID: 63427923
Cleanup Site ID: 9966

ARCO 0836 (Continued) **1004794039**

Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: ARCO STATION # 0836
Release Notification Date: Not reported
Release Status Date: 08/24/1994
Site Response Unit Code: Northwest
Lat/Long: 47.6169999 / -122.18526

FS ID: 63427923
Cleanup Site ID: 9966
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Monitoring
Alternate Name: ARCO STATION # 0836
Release Notification Date: Not reported
Release Status Date: 08/28/1996
Site Response Unit Code: Northwest
Lat/Long: 47.6169999 / -122.18526

WA MANIFEST:
Facility Site ID Number: 63427923
SWC Desc: Not reported
FWC Desc: D001 D018
Form Comm: Not reported
Data Year: Not reported
Permit by Rule: False
Treatment by Generator: False
Mixed radioactive waste: False
Importer of hazardous waste: False
Immediate recycler: False
Treatment/Storage/Disposal/Recycling Facility: False
Generator of dangerous fuel waste: False
Generator marketing to burner: False
"Other marketers (i.e., blender, distributor, etc.)": False
Utility boiler burner: False
Industry boiler burner: False
Industrial Furnace: False
Smelter defferal: False
Universal waste - batteries - generate: False
Universal waste - thermostats - generate: False
Universal waste - mercury - generate: False
Universal waste - lamps - generate: False
Universal waste - batteries - accumulate: False
Universal waste - thermostats - accumulate: False
Universal waste - mercury - accumulate: False
Universal waste - lamps - accumulate: False
Destination Facility for Universal Waste: False
Off-specification used oil burner - utility boiler: False
Off-specification used oil burner - industrial boiler: False
Off-specification used oil burner - industrial furnace: False
EPA ID: WAD988484887
Facility Address 2: Not reported
TAX REG NBR: 409018414
NAICS CD: 44711
BUSINESS TYPE: Gas station with store
MAIL NAME: BP West Coast Products LLC

ARCO 0836 (Continued) **1004794039**

MAIL ADDR LINE1:	PO Box 6038
MAIL CITY,ST,ZIP:	ARTESIA, CA 90702-6038
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BP West Coast Products LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO Box 6038
LEGAL CITY,ST,ZIP:	ARTESIA, CA 90702-6038
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	530-524-5191
LEGAL EFFECTIVE DATE:	4/9/1996
LAND ORG NAME:	BP West Coast Products LLC
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO BOX 6038
LAND CITY,ST,ZIP:	ARTESIA, CA 90702-6038
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	530-524-6191
OPERATOR ORG NAME:	MEK Corporation
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	11611 NE 8th Street
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-454-9685
OPERATOR EFFECTIVE DATE:	07/19/91
SITE CONTACT NAME:	Ruth Ha
SITE CONTACT ADDR LINE1:	PO BOX 6038
SITE CONTACT ZIP:	ARTESIA, CA 90702
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	503-524-6191
SITE CONTACT EMAIL:	harx00@bp.com
FORM CONTACT NAME:	Ruth Ha
FORM CONTACT ADDR LINE1:	PO BOX 6038
FORM CONTACT CITY,ST,ZIP:	ARTESIA, CA 90702
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	503-524-6191
FORM CONTACT EMAIL:	harx00@bp.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	63427923
SWC Desc:	Not reported
FWC Desc:	D001 D018
Form Comm:	Not reported

ARCO 0836 (Continued) **1004794039**

Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD988484887
Facility Address 2:	Not reported
TAX REG NBR:	409018414
NAICS CD:	44711
BUSINESS TYPE:	Gas station with store
MAIL NAME:	BP West Coast Products LLC
MAIL ADDR LINE1:	PO Box 6038
MAIL CITY,ST,ZIP:	ARTESIA, CA 90702-6038
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BP West Coast Products LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO BOX 6038
LEGAL CITY,ST,ZIP:	ARTESIA, CA 90702-6038
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(714)670-3958
LEGAL EFFECTIVE DATE:	4/9/1996
LAND ORG NAME:	BP West Coast Products LLC
LAND ORG TYPE:	Private
LAND PERSON NAME:	Teresa Santana
LAND ADDR LINE1:	PO BOX 6038
LAND CITY,ST,ZIP:	ARTESIA, CA 90702-6038
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(714)670-3958
OPERATOR ORG NAME:	MEK Corporation
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	11611 NE 8th Street
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-454-9685
OPERATOR EFFECTIVE DATE:	7/19/1991
SITE CONTACT NAME:	Teresa Santana

ARCO 0836 (Continued) **1004794039**

SITE CONTACT ADDR LINE1:	PO BOX 6038
SITE CONTACT ZIP:	ARTESIA, CA 90702
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(714) 670-3958
SITE CONTACT EMAIL:	santanta@bp.com
FORM CONTACT NAME:	Teresa Santana
FORM CONTACT ADDR LINE1:	PO BOX 6038
FORM CONTACT CITY,ST,ZIP:	ARTESIA, CA 90702
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(714) 670-3958
FORM CONTACT EMAIL:	santanta@bp.com
GEN STATUS CD:	MQG
MONTHLY GENERATION:	No
BATCH GENERATION:	Yes
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Facility Site ID Number:	63427923
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2009
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False

ARCO 0836 (Continued) **1004794039**

Off-specification used oil burner - industrial furnace: False
EPA ID: WAD988484887
Facility Address 2: Not reported
TAX REG NBR: 409018414
NAICS CD: 44711
BUSINESS TYPE: Gas station with store
MAIL NAME: BP West Coast Products LLC
MAIL ADDR LINE1: PO Box 6038
MAIL CITY,ST,ZIP: ARTESIA, CA 90702-6038
MAIL COUNTRY: UNITED STATES
LEGAL ORG NAME: BP West Coast Products LLC
LEGAL ORG TYPE: Private
LEGAL ADDR LINE1: PO Box 6038
LEGAL CITY,ST,ZIP: ARTESIA, CA 90702-6038
LEGAL COUNTRY: UNITED STATES
LEGAL PHONE NBR: (714)670-3958
LEGAL EFFECTIVE DATE: 4/9/1996
LAND ORG NAME: BP West Coast Products LLC
LAND ORG TYPE: Private
LAND PERSON NAME: Not reported
LAND ADDR LINE1: PO BOX 6038
LAND CITY,ST,ZIP: ARTESIA, CA 90702-6038
LAND COUNTRY: UNITED STATES
LAND PHONE NBR: (714)670-3958
OPERATOR ORG NAME: MEK Corporation
OPERATOR ORG TYPE: Private
OPERATOR ADDR LINE1: 11611 NE 8th Street
OPERATOR CITY,ST,ZIP: Bellevue, WA 98005
OPERATOR COUNTRY: UNITED STATES
OPERATOR PHONE NBR: 425-454-9685
OPERATOR EFFECTIVE DATE: 7/19/1991
SITE CONTACT NAME: Bratzo Basagoitia
SITE CONTACT ADDR LINE1: PO BOX 6038
SITE CONTACT ZIP: ARTESIA, CA 90702
SITE CONTACT COUNTRY: UNITED STATES
SITE CONTACT PHONE NBR: (714)670-3958
SITE CONTACT EMAIL: basabm@bp.com
FORM CONTACT NAME: Bratzo Basagoitia
FORM CONTACT ADDR LINE1: PO BOX 6038
FORM CONTACT CITY,ST,ZIP: ARTESIA, CA 90702
FORM CONTACT COUNTRY: UNITED STATES
FORM CONTACT PHONE NBR: (714)670-3958
FORM CONTACT EMAIL: basabm@bp.com
GEN STATUS CD: XQG
MONTHLY GENERATION: False
BATCH GENERATION: False
ONE TIME GENERATION: False
TRANSPORTS OWN WASTE: False
TRANSPORTS OTHRS WASTE: False
RECYCLER ONSITE: False
TRANSFER FACILITY: False
OTHER EXEMPTION: Not reported
UW BATTERY GEN: False
USED OIL TRANSPORTER: False
USED OIL TRANSFER FACLTY: False
USED OIL PROCESSOR: False
USED OIL REREFINER: False

ARCO 0836 (Continued) **1004794039**

USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False
Facility Site ID Number:	63427923
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2008
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD988484887
Facility Address 2:	Not reported
TAX REG NBR:	409018414
NAICS CD:	44711
BUSINESS TYPE:	Gas station with store
MAIL NAME:	BP West Coast Products LLC
MAIL ADDR LINE1:	PO Box 6038
MAIL CITY,ST,ZIP:	ARTESIA, CA 90702-6038
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BP West Coast Products LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO Box 6038
LEGAL CITY,ST,ZIP:	ARTESIA, CA 90702-6038
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(714)670-3958
LEGAL EFFECTIVE DATE:	4/9/1996
LAND ORG NAME:	BP West Coast Products LLC
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO BOX 6038
LAND CITY,ST,ZIP:	ARTESIA, CA 90702-6038
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(714)670-3958
OPERATOR ORG NAME:	MEK Corporation

ARCO 0836 (Continued) **1004794039**

OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	11611 NE 8th Street
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-454-9685
OPERATOR EFFECTIVE DATE:	7/19/1991
SITE CONTACT NAME:	Bratzo Basagoitia
SITE CONTACT ADDR LINE1:	PO BOX 6038
SITE CONTACT ZIP:	ARTESIA, CA 90702
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(714)670-3958
SITE CONTACT EMAIL:	basabm@bp.com
FORM CONTACT NAME:	Bratzo Basagoitia
FORM CONTACT ADDR LINE1:	PO BOX 6038
FORM CONTACT CITY,ST,ZIP:	ARTESIA, CA 90702
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(714)670-3958
FORM CONTACT EMAIL:	basabm@bp.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	63427923
SWC Desc:	Not reported
FWC Desc:	D001 D018
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	TRUE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE

ARCO 0836 (Continued) **1004794039**

Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD988484887
Facility Address 2:	Not reported
TAX REG NBR:	409018414
NAICS CD:	44711
BUSINESS TYPE:	Gas station with store
MAIL NAME:	BP West Coast Products LLC
MAIL ADDR LINE1:	PO Box 6038
MAIL CITY,ST,ZIP:	ARTESIA, CA 90702-6038
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BP West Coast Products LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO BOX 6038
LEGAL CITY,ST,ZIP:	ARTESIA, CA 90702-6038
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(714)670-3958
LEGAL EFFECTIVE DATE:	4/9/1996
LAND ORG NAME:	BP West Coast Products LLC
LAND ORG TYPE:	Private
LAND PERSON NAME:	Teresa Santana
LAND ADDR LINE1:	PO BOX 6038
LAND CITY,ST,ZIP:	ARTESIA, CA 90702-6038
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(714)670-3958
OPERATOR ORG NAME:	MEK Corporation
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	11611 NE 8th Street
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-454-9685
OPERATOR EFFECTIVE DATE:	7/19/1991
SITE CONTACT NAME:	Teresa Santana
SITE CONTACT ADDR LINE1:	PO BOX 6038
SITE CONTACT ZIP:	ARTESIA, CA 90702
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(714) 670-3958
SITE CONTACT EMAIL:	santanta@bp.com
FORM CONTACT NAME:	Teresa Santana
FORM CONTACT ADDR LINE1:	PO BOX 6038
FORM CONTACT CITY,ST,ZIP:	ARTESIA, CA 90702
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(714) 670-3958
FORM CONTACT EMAIL:	santanta@bp.com
GEN STATUS CD:	MQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	TRUE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE

ARCO 0836 (Continued) **1004794039**

TRANSFER FACILITY: FALSE
OTHER EXEMPTION: Not reported
UW BATTERY GEN: FALSE
USED OIL TRANSPORTER: FALSE
USED OIL TRANSFER FACLTY: FALSE
USED OIL PROCESSOR: FALSE
USED OIL REREFINER: FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS: FALSE
USED OIL FUEL MRKTR MEETS SPECS: FALSE

Click this hyperlink while viewing on your computer to access additional WA MANIFEST: detail in the EDR Site Report.

SPILLS:
Facility ID: 522676
Medium: Not reported
Material Desc: PETROLEUM - OIL OTHER
Material Qty: 30
Material Units: GALLON
Date Received: 11/26/2001
Contact Name: ROPAS

M52 **BELLEVUE DISTRIBUTION CENTER** **ALLSITES** **S110039603**
NE **1227 124TH AVE NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.297 mi.
1570 ft. **Site 1 of 2 in cluster M**

Relative:
Higher

Actual:
184 ft.

ALLSITES:
Facility Id: 17040
Latitude: 47.6206000
Longitude: -122.175
Geographic location identifier (alias facid): 17040
Facility Name: BELLEVUE DISTRIBUTION CENTER
Latitude Decimal Degrees: 47.620600000000003
Longitude Decimal Degrees: -122.175
Coordinate Point Areal Extent Code: 0
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 0
Location Verified Code: Not reported

Geographic Location Identifier (Alias Facid): 17040
Interaction (Aka Env Int) Type Code: INDUSTGP
Interaction (Aka Env Int) Description: Industrial SW GP
Interaction Status: A
Federal Program Indentifier: WAR011626
Interaction Start Date: 06/01/2009
Interaction End Date: Not reported
prgm_facil: BELLEVUE DISTRIBUTION CENTER
cur_sys_pr: WATQUAL
cur_sys_nm: PARIS

M53
NE
1/4-1/2
0.297 mi.
1570 ft.

SAFEWAY WAREHOUSE INC DIST CENTER
1227 124TH AVENUE NORTH EAST
BELLEVUE, WA 98005

Site 2 of 2 in cluster M

RCRA-CESQG
ALLSITES
MANIFEST
ICR

1000225234
WAD117350264

Relative:
Higher

Actual:
184 ft.

RCRA-CESQG:

Date form received by agency:	02/14/2006
Facility name:	SAFEWAY INC DISTRIBUTION CTR TRUCK STOP
Facility address:	1227 124TH AVE NE TRUCK STOP BELLEVUE, WA 98005
EPA ID:	WAD117350264
Mailing address:	1227 124TH AVE NE BELLEVUE, WA 98005-2103
Contact:	BRIAN LANGLAIS
Contact address:	1227 124TH AVE NE BELLEVUE, WA 98005-2103
Contact country:	US
Contact telephone:	(253)299-5030
Contact email:	Not reported
EPA Region:	10
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SAFEWAY WAREHOUSE INC
Owner/operator address:	1227 124TH AVE NE BELLEVUE, WA 98005
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1997
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

SAFEWAY WAREHOUSE INC DIST CENTER (Continued) **1000225234**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2005
Facility name: SAFEWAY INC DISTRIBUTION CTR TRUCK STOP
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: SAFEWAY INC DISTRIBUTION CTR TRUCK STOP
Classification: Not a generator, verified

Date form received by agency: 03/31/1994
Facility name: SAFEWAY INC DISTRIBUTION CTR TRUCK STOP
Site name: SAFEWAY INC DISTRIBUTION CTR
Classification: Large Quantity Generator

Date form received by agency: 09/01/1993
Facility name: SAFEWAY INC DISTRIBUTION CTR TRUCK STOP
Site name: SAFEWAY INC
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/12/1997
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

ALLSITES:
Facility Id: 41344583
Latitude: 47.6208000
Longitude: -122.17504
Geographic location identifier (alias facid): 41344583
Facility Name: Safeway Inc Distribution Ctr Truck Stop
Latitude Decimal Degrees: 47.620800000000003
Longitude Decimal Degrees: -122.17504
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

WA MANIFEST:
Facility Site ID Number: 41344583
SWC Desc: Not reported
FWC Desc: Not reported
Form Comm: Not reported
Data Year: Not reported

SAFEWAY WAREHOUSE INC DIST CENTER (Continued) **1000225234**

Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD117350264
Facility Address 2:	Not reported
TAX REG NBR:	179013297
NAICS CD:	42441
BUSINESS TYPE:	Grocery Distribution Ctr
MAIL NAME:	Safeway Inc
MAIL ADDR LINE1:	1227 124TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98005-2103
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Safeway Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	5918 STONERIDGE MALL RD
LEGAL CITY,ST,ZIP:	PLEASANTON, CA 94588-3229
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(510)467-3000
LEGAL EFFECTIVE DATE:	8/30/1996
LAND ORG NAME:	Safeway Inc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	5918 STONERIDGE MALL RD
LAND CITY,ST,ZIP:	PLEASANTON, CA 94588-3229
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(510)467-3000
OPERATOR ORG NAME:	SAFEWAY WAREHOUSE INC
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1127 124TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-2101
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-455-6438
OPERATOR EFFECTIVE DATE:	1/1/1997
SITE CONTACT NAME:	Brian Langlais
SITE CONTACT ADDR LINE1:	3520 Pacific Ave S

SAFEWAY WAREHOUSE INC DIST CENTER (Continued) **1000225234**

SITE CONTACT ZIP:	Auburn, WA 98047
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	253-299-5030
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Brian Langlais
FORM CONTACT ADDR LINE1:	3520 Pacific Ave S
FORM CONTACT CITY,ST,ZIP:	Auburn, WA 98047
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	253-299-5030
FORM CONTACT EMAIL:	Not reported
GEN STATUS CD:	SQG
MONTHLY GENERATION:	No
BATCH GENERATION:	Yes
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

ICR:

Date Ecology Received Report:	10/27/93
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	93-15
County Code:	17
Contact:	Not reported
Report Title:	Not reported

N54 **APPLE GREEN CENTER (POWELL DEV. CO.)** **ICR** **S104484587**
WNW **1024 116TH AVE. NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98004**
0.323 mi.
1708 ft. **Site 1 of 4 in cluster N**

Relative:
Higher

Actual:
167 ft.

ICR:

Date Ecology Received Report:	08/15/90
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	90-09
County Code:	17
Contact:	Not reported
Report Title:	Not reported

N55 **APPLEGREEN CENTER** **ALLSITES** **U003795305**
WNW **1024 116TH AVE NE** **LUST** **N/A**
1/4-1/2 **BELLEVUE, WA 98004** **UST**
0.323 mi.
1708 ft. **Site 2 of 4 in cluster N**

Relative:
Higher

Actual:
167 ft.

ALLSITES:

Facility Id:	22465738	
Latitude:	47.6196594	
Longitude:	-122.18767	
Geographic location identifier (alias facid):		22465738
Facility Name:		APPLEGREEN CENTER
Latitude Decimal Degrees:		47.619659480899998
Longitude Decimal Degrees:		-122.18767620600001
Coordinate Point Areal Extent Code:		4
Horizontal Accuracy Code:		6
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported

LUST:

FS ID:	22465738
Cleanup Site ID:	8319
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	APPLEGREEN CENTER
Release Notification Date:	Not reported
Release Status Date:	05/21/1995
Site Response Unit Code:	Northwest
Lat/Long:	47.6196594 / -122.18767

UST:

Facility ID:	22465738
Site ID:	200535
Lat Deg:	Not reported
Lat Min:	Not reported
Lat Sec:	Not reported
Long Deg:	Not reported
Long Min:	Not reported
Long Sec:	Not reported
UBI:	Not reported
Phone Number:	Not reported
Tank ID:	575395
Tank Name:	1
Install Date:	1/1/1900
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/3/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported

APPLEGREEN CENTER (Continued) **U003795305**

Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/3/2001
Tag Number:	Not reported

Tank ID:	575400
Tank Name:	2
Install Date:	1/1/1900
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/3/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/3/2001
Tag Number:	Not reported

Tank ID:	575405
Tank Name:	3
Install Date:	1/1/1900
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/3/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported

APPLEGREEN CENTER (Continued) **U003795305**

Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/3/2001
Tag Number:	Not reported

Tank ID:	575410
Tank Name:	4
Install Date:	1/1/1900
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/3/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/3/2001
Tag Number:	Not reported

Tank ID:	575415
Tank Name:	5
Install Date:	1/1/1900
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/3/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported

APPLEGREEN CENTER (Continued) **U003795305**

Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/3/2001
Tag Number:	Not reported

Tank ID:	575420
Tank Name:	6
Install Date:	1/1/1900
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/3/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/3/2001
Tag Number:	Not reported

Tank ID:	575425
Tank Name:	7
Install Date:	1/1/1900
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/3/2001
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported

APPLEGREEN CENTER (Continued) **U003795305**

Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/3/2001
Tag Number:	Not reported

N56 **OVERLAKE HOSPITAL MEDICAL CENTER** **RCRA-LQG** **1000363873**
WNW **1035 116TH AVE NE** **FTTS** **WAD076631704**
1/4-1/2 **BELLEVUE, WA 98004** **HIST FTTS**
0.336 mi. **FINDS**
1775 ft. **Site 3 of 4 in cluster N** **CSCSL**
ALLSITES
Relative: **MANIFEST**
Higher

Actual: **170 ft.**

RCRA-LQG:

Date form received by agency:	02/25/2010
Facility name:	OVERLAKE HOSPITAL MEDICAL CENTER
Facility address:	1035 116TH AVE NE BELLEVUE, WA 98004
EPA ID:	WAD076631704
Contact:	LUIS M GONZALEZ
Contact address:	1035 116TH AVE NE BELLEVUE, WA 98004
Contact country:	US
Contact telephone:	(425) 688-5956
Contact email:	LUIS.GONZALEZ@OVERLAKEHOSPITAL.ORG
EPA Region:	10
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	OVERLAKE HEALTH CARE ASSOC
Owner/operator address:	1035 116TH AVE NE BELLEVUE, 98004

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

Owner/operator country: US
Owner/operator telephone: (425)688-5000
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/21/1996
Owner/Op end date: Not reported

Owner/operator name: OVERLAKE HEALTH CARE ASSOC
Owner/operator address: 1035 116TH AVE NE
BELLEVUE, 98004
Owner/operator country: US
Owner/operator telephone: (425)688-5000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/21/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/27/2008
Facility name: OVERLAKE HOSPITAL MEDICAL CENTER
Classification: Small Quantity Generator

Date form received by agency: 12/31/2007
Facility name: OVERLAKE HOSPITAL MEDICAL CENTER
Classification: Large Quantity Generator

Date form received by agency: 12/31/2005
Facility name: OVERLAKE HOSPITAL MEDICAL CENTER
Classification: Small Quantity Generator

Date form received by agency: 12/31/2003
Facility name: OVERLAKE HOSPITAL MEDICAL CENTER
Classification: Small Quantity Generator

Date form received by agency: 03/12/1998
Facility name: OVERLAKE HOSPITAL MEDICAL CENTER
Classification: Large Quantity Generator

Date form received by agency: 03/01/1996

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

Facility name: OVERLAKE HOSPITAL MEDICAL CENTER
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D008
Waste name: LEAD

Waste code: U010
Waste name: AZIRINO[2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA,8AALPHA,8BALPHA)]-

Waste code: WSC2
Waste name: Washington State solid or semisolid corrosive Dangerous Waste with a pH less than or equal to 2, or greater than or equal to 12.5, based upon a specific testing method.

Waste code: WT01
Waste name: Washington State Extremely Hazardous Toxic Waste with a toxic constituents concentration greater than or equal to 1.0%, determined by biological testing methods or a book designation procedure.

Waste code: WT02
Waste name: Washington State Dangerous Toxic Waste with a toxic constituents concentration greater than or equal to 0.001% and less than 1.0%, determined by biological testing methods or a book designation procedure.

Biennial Reports:

Last Biennial Reporting Year: 2011

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET,

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 2268

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
Amount (Lbs): 27

Waste code: D008
Waste name: LEAD
Amount (Lbs): 200

Waste code: U010
Waste name: AZIRINO[2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA,8AALPHA,8BALPHA)]-
Amount (Lbs): 2072

Facility Has Received Notices of Violations:
Regulation violated: SR - -200(1)(d)
Area of violation: Generators - General
Date violation determined: 07/22/2005
Date achieved compliance: 08/10/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/22/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -200(1)(c)
Area of violation: Generators - General
Date violation determined: 07/22/2005
Date achieved compliance: 08/10/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/22/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -630(7)

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

Area of violation: Generators - General
Date violation determined: 07/22/2005
Date achieved compliance: 08/10/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/22/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -340(1)
Area of violation: Generators - General
Date violation determined: 07/22/2005
Date achieved compliance: 08/10/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/22/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -573(10)(11)
Area of violation: Generators - General
Date violation determined: 07/22/2005
Date achieved compliance: 08/10/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/22/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -630(6)
Area of violation: Generators - General
Date violation determined: 07/22/2005
Date achieved compliance: 08/31/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/22/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Evaluation Action Summary:
Evaluation date: 07/22/2005

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/10/2005
Evaluation lead agency: State

Evaluation date: 07/22/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/31/2005
Evaluation lead agency: State

Evaluation date: 09/14/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FTTS INSP:
Inspection Number: 2002062516131 1
Region: 10
Inspection Date: 06/25/02
Inspector: HILEMAN
Violation occurred: No
Investigation Type: Section 6 PCB Federal Conducted
Investigation Reason: Neutral Scheme, Region
Legislation Code: TSCA
Facility Function: User

HIST FTTS INSP:
Inspection Number: 2002062516131 1
Region: 10
Inspection Date: Not reported
Inspector: HILEMAN
Violation occurred: No
Investigation Type: Section 6 PCB Federal Conducted
Investigation Reason: Neutral Scheme, Region
Legislation Code: TSCA
Facility Function: User

FINDS:

Registry ID: 110000897370

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

NCES (National Center for Education Statistics) is the primary federal entity for collecting and analyzing data related to education in the United States and other nations and the institute of education sciences.

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CSCSL:

Facility ID:	45225129
Region:	Northwest
Lat/Long:	47.620341000000 / -122.186694
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	9269
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Diesel
Ground Water:	S
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	45225129
Region:	Northwest
Lat/Long:	47.620341000000 / -122.186694
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	9269
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Other
Ground Water:	S
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

ALLSITES:

Facility Id:	45225129
Latitude:	47.6203410
Longitude:	-122.18669
Geographic location identifier (alias facid):	45225129
Facility Name:	Overlake Hospital Medical Center
Latitude Decimal Degrees:	47.620341000000003
Longitude Decimal Degrees:	-122.186694
Coordinate Point Areal Extent Code:	4
Horizontal Accuracy Code:	6
Coordinate Point Geographic Position Code:	5

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

Location Verified Code: N

WA MANIFEST:

Facility Site ID Number:	45225129
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2010
Permit by Rule:	False
Treatment by Generator:	True
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD076631704
Facility Address 2:	Not reported
TAX REG NBR:	179009836
NAICS CD:	622110
BUSINESS TYPE:	Medical/Surgical Hospital
MAIL NAME:	Overlake Hospital Medical Ctr
MAIL ADDR LINE1:	1035 116TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Overlake Health Care Assoc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1035 116TH AVE NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)688-5000
LEGAL EFFECTIVE DATE:	8/21/1996
LAND ORG NAME:	Overlake Health Care Assoc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1035 116TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)688-5000

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

OPERATOR ORG NAME:	Overlake Health Care Assoc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1035 116TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)688-5000
OPERATOR EFFECTIVE DATE:	8/21/1996
SITE CONTACT NAME:	Luis M Gonzalez
SITE CONTACT ADDR LINE1:	1035 116TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)688-5956
SITE CONTACT EMAIL:	luis.gonzalez@overlakehospital.org
FORM CONTACT NAME:	Luis M Gonzalez
FORM CONTACT ADDR LINE1:	1035 116TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)688-5956
FORM CONTACT EMAIL:	luis.gonzalez@overlakehospital.org
GEN STATUS CD:	MQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	45225129
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2009
Permit by Rule:	False
Treatment by Generator:	True
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD076631704
Facility Address 2:	Not reported
TAX REG NBR:	179009836
NAICS CD:	622110
BUSINESS TYPE:	Medical/Surgical Hospital
MAIL NAME:	Overlake Hospital Medical Ctr
MAIL ADDR LINE1:	1035 116TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Overlake Health Care Assoc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1035 116TH AVE NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)688-5000
LEGAL EFFECTIVE DATE:	8/21/1996
LAND ORG NAME:	Overlake Health Care Assoc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1035 116TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)688-5000
OPERATOR ORG NAME:	Overlake Health Care Assoc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1035 116TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)688-5000
OPERATOR EFFECTIVE DATE:	8/21/1996
SITE CONTACT NAME:	Luis M Gonzalez
SITE CONTACT ADDR LINE1:	1035 116TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)688-5956
SITE CONTACT EMAIL:	luis.gonzalez@overlakehospital.org
FORM CONTACT NAME:	Luis M Gonzalez
FORM CONTACT ADDR LINE1:	1035 116TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)688-5956
FORM CONTACT EMAIL:	luis.gonzalez@overlakehospital.org
GEN STATUS CD:	LQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

RECYCLER ONSITE: False
TRANSFER FACILITY: False
OTHER EXEMPTION: Not reported
UW BATTERY GEN: False
USED OIL TRANSPORTER: False
USED OIL TRANSFER FACLTY: False
USED OIL PROCESSOR: False
USED OIL REREFINER: False
USED OIL FUEL MRKTR DIRECTS SHPMNTS: False
USED OIL FUEL MRKTR MEETS SPECS: False

Facility Site ID Number: 45225129
SWC Desc: Not reported
FWC Desc: Not reported
Form Comm: Overlake Hospital had a single pickup of a bottle of extremely hazardous waste (P105, 10 lbs) in 2007 that caused it to designate as an LQG. The hospital was an MQG in 2006 and expects to designate as an MQG in 2008. Therefore, the hospital will operate and manage its dangerous waste as an MQG.
Data Year: Not reported
Permit by Rule: No
Treatment by Generator: Yes
Mixed radioactive waste: No
Importer of hazardous waste: No
Immediate recycler: No
Treatment/Storage/Disposal/Recycling Facility: No
Generator of dangerous fuel waste: No
Generator marketing to burner: No
"Other marketers (i.e., blender, distributor, etc.)": No
Utility boiler burner: No
Industry boiler burner: No
Industrial Furnace: No
Smelter defferal: No
Universal waste - batteries - generate: No
Universal waste - thermostats - generate: No
Universal waste - mercury - generate: No
Universal waste - lamps - generate: No
Universal waste - batteries - accumulate: No
Universal waste - thermostats - accumulate: No
Universal waste - mercury - accumulate: No
Universal waste - lamps - accumulate: No
Destination Facility for Universal Waste: No
Off-specification used oil burner - utility boiler: No
Off-specification used oil burner - industrial boiler: No
Off-specification used oil burner - industrial furnace: No
EPA ID: WAD076631704
Facility Address 2: Not reported
TAX REG NBR: 179009836
NAICS CD: 62211
BUSINESS TYPE: Medical/Surgical Hospital
MAIL NAME: Overlake Hospital Medical Ctr
MAIL ADDR LINE1: 1035 116TH AVE NE
MAIL CITY,ST,ZIP: BELLEVUE, WA 98004-4604
MAIL COUNTRY: UNITED STATES
LEGAL ORG NAME: Overlake Health Care Assoc
LEGAL ORG TYPE: Private
LEGAL ADDR LINE1: 1035 116TH AVE NE

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)688-5000
LEGAL EFFECTIVE DATE:	8/21/1996
LAND ORG NAME:	Overlake Health Care Assoc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1035 116TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)688-5000
OPERATOR ORG NAME:	Overlake Health Care Assoc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1035 116TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)688-5000
OPERATOR EFFECTIVE DATE:	8/21/1996
SITE CONTACT NAME:	Luis M Gonzalez
SITE CONTACT ADDR LINE1:	1035 116TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)688-5956
SITE CONTACT EMAIL:	luis.gonzalez@overlakehospital.org
FORM CONTACT NAME:	Luis M Gonzalez
FORM CONTACT ADDR LINE1:	1035 116TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)688-5956
FORM CONTACT EMAIL:	luis.gonzalez@overlakehospital.org
GEN STATUS CD:	MQG
MONTHLY GENERATION:	No
BATCH GENERATION:	Yes
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Facility Site ID Number:	45225129
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2008
Permit by Rule:	False
Treatment by Generator:	True
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD076631704
Facility Address 2:	Not reported
TAX REG NBR:	179009836
NAICS CD:	62211
BUSINESS TYPE:	Medical/Surgical Hospital
MAIL NAME:	Overlake Hospital Medical Ctr
MAIL ADDR LINE1:	1035 116TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Overlake Health Care Assoc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1035 116TH AVE NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)688-5000
LEGAL EFFECTIVE DATE:	8/21/1996
LAND ORG NAME:	Overlake Health Care Assoc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1035 116TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)688-5000
OPERATOR ORG NAME:	Overlake Health Care Assoc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1035 116TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)688-5000
OPERATOR EFFECTIVE DATE:	8/21/1996
SITE CONTACT NAME:	Luis M Gonzalez
SITE CONTACT ADDR LINE1:	1035 116TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)688-5956
SITE CONTACT EMAIL:	luis.gonzalez@overlakehospital.org
FORM CONTACT NAME:	Luis M Gonzalez

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

FORM CONTACT ADDR LINE1: 1035 116TH AVE NE
FORM CONTACT CITY,ST,ZIP: BELLEVUE, WA 98004
FORM CONTACT COUNTRY: UNITED STATES
FORM CONTACT PHONE NBR: (425)688-5956
FORM CONTACT EMAIL: luis.gonzalez@overlakehospital.org
GEN STATUS CD: MQG
MONTHLY GENERATION: False
BATCH GENERATION: True
ONE TIME GENERATION: False
TRANSPORTS OWN WASTE: False
TRANSPORTS OTHRS WASTE: False
RECYCLER ONSITE: False
TRANSFER FACILITY: False
OTHER EXEMPTION: Not reported
UW BATTERY GEN: False
USED OIL TRANSPORTER: False
USED OIL TRANSFER FACLTY: False
USED OIL PROCESSOR: False
USED OIL REREFINER: False
USED OIL FUEL MRKTR DIRECTS SHPMNTS: False
USED OIL FUEL MRKTR MEETS SPECS: False

Facility Site ID Number: 45225129
SWC Desc: Not reported
FWC Desc: Not reported
Form Comm: Overlake Hospital had a single pickup of a bottle of extremely hazardous waste (P105, 10 lbs) in 2007 that caused it to designate as an LQG. The hospital was an MQG in 2006 and expects to designate as an MQG in 2008. Therefore, the hospital will operate and manage its dangerous waste as an MQG.
Data Year: Not reported
Permit by Rule: FALSE
Treatment by Generator: TRUE
Mixed radioactive waste: FALSE
Importer of hazardous waste: FALSE
Immediate recycler: FALSE
Treatment/Storage/Disposal/Recycling Facility: FALSE
Generator of dangerous fuel waste: FALSE
Generator marketing to burner: FALSE
"Other marketers (i.e., blender, distributor, etc.)": FALSE
Utility boiler burner: FALSE
Industry boiler burner: FALSE
Industrial Furnace: FALSE
Smelter defferal: FALSE
Universal waste - batteries - generate: FALSE
Universal waste - thermostats - generate: FALSE
Universal waste - mercury - generate: FALSE
Universal waste - lamps - generate: FALSE
Universal waste - batteries - accumulate: FALSE
Universal waste - thermostats - accumulate: FALSE
Universal waste - mercury - accumulate: FALSE
Universal waste - lamps - accumulate: FALSE
Destination Facility for Universal Waste: FALSE
Off-specification used oil burner - utility boiler: FALSE
Off-specification used oil burner - industrial boiler: FALSE
Off-specification used oil burner - industrial furnace: FALSE
EPA ID: WAD076631704

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

Facility Address 2:	Not reported
TAX REG NBR:	179009836
NAICS CD:	62211
BUSINESS TYPE:	Medical/Surgical Hospital
MAIL NAME:	Overlake Hospital Medical Ctr
MAIL ADDR LINE1:	1035 116TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Overlake Health Care Assoc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1035 116TH AVE NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)688-5000
LEGAL EFFECTIVE DATE:	8/21/1996
LAND ORG NAME:	Overlake Health Care Assoc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1035 116TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)688-5000
OPERATOR ORG NAME:	Overlake Health Care Assoc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1035 116TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-4604
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)688-5000
OPERATOR EFFECTIVE DATE:	8/21/1996
SITE CONTACT NAME:	Luis M Gonzalez
SITE CONTACT ADDR LINE1:	1035 116TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)688-5956
SITE CONTACT EMAIL:	luis.gonzalez@overlakehospital.org
FORM CONTACT NAME:	Luis M Gonzalez
FORM CONTACT ADDR LINE1:	1035 116TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)688-5956
FORM CONTACT EMAIL:	luis.gonzalez@overlakehospital.org
GEN STATUS CD:	MQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	TRUE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **1000363873**

Click this hyperlink while viewing on your computer to access
1 additional WA MANIFEST: record(s) in the EDR Site Report.

N57 **OVERLAKE HOSPITAL MEDICAL CENTER** **LUST U003604579**
WNW **1035 116TH AVE NE** **UST N/A**
1/4-1/2 **BELLEVUE, WA 98004**
0.336 mi.
1775 ft. **Site 4 of 4 in cluster N**

Relative:
Higher

Actual:
170 ft.

LUST:

FS ID:	45225129
Cleanup Site ID:	9269
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	OVERLAKE HOSPITAL
Release Notification Date:	Not reported
Release Status Date:	04/06/1998
Site Response Unit Code:	Northwest
Lat/Long:	47.6203410 / -122.18669

FS ID:	45225129
Cleanup Site ID:	9269
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	OVERLAKE HOSPITAL
Release Notification Date:	Not reported
Release Status Date:	07/01/2011
Site Response Unit Code:	Northwest
Lat/Long:	47.6203410 / -122.18669

FS ID:	45225129
Cleanup Site ID:	9269
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	RCU
Alternate Name:	OVERLAKE HOSPITAL
Release Notification Date:	Not reported
Release Status Date:	09/18/2002
Site Response Unit Code:	Northwest
Lat/Long:	47.6203410 / -122.18669

UST:

Facility ID:	45225129
Site ID:	7316
Lat Deg:	47
Lat Min:	37
Lat Sec:	13.227600000012103
Long Deg:	-122
Long Min:	11
Long Sec:	12.098400000010088
UBI:	1790098360010001
Phone Number:	4256885240

Tank ID:	20153

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **U003604579**

Tank Name:	IV
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A5069

Tank ID:	20312
Tank Name:	II
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A5069

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **U003604579**

Tank ID:	34848
Tank Name:	III
Install Date:	1/1/1976
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	2/16/2000
Tank Status:	Removed
Tank Permit Expiration Date:	6/30/1999
Tank Closure Date:	1/1/0001
Tank Pumping System:	Suction System Tank Check Valve
Tank Spill Prevention:	None
Tank Overfill Prevention:	None
Tank Material:	Not reported
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	None
Pipe Material:	Not reported
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Suction
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Other
Tank Primary Release Detection:	Weekly Manual Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A5069

Tank ID:	37867
Tank Name:	V
Install Date:	1/1/1975
Capacity:	20,000 to 29,999 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Closed in Place
TankSystem Status Change Date:	1/20/2000
Tank Status:	Closed in Place
Tank Permit Expiration Date:	6/30/1999
Tank Closure Date:	1/1/0001
Tank Pumping System:	Gravity Delivery System (No Pump)
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Tank Material:	Not reported
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	None
Pipe Material:	Other
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Other
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Groundwater Monitoring
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A5069

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **U003604579**

Tank ID:	37967
Tank Name:	I
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A5069

Tank ID:	528675
Tank Name:	VI
Install Date:	12/1/1999
Capacity:	Not reported
Tank Upgrade Date:	12/1/1999
TankSystem Status:	Removed
TankSystem Status Change Date:	8/25/2006
Tank Status:	Removed
Tank Permit Expiration Date:	6/30/2007
Tank Closure Date:	1/1/0001
Tank Pumping System:	Suction System Tank Check Valve
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Tank Material:	Coated Steel
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Not Performed
Tank Corrosion Protection:	Sacrificial Anode
Pipe Material:	Flexible Piping
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Interstitial Monitoring (sump sensor)
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	No
Tank Actual Status Date:	3/23/2000
Tag Number:	A5069

OVERLAKE HOSPITAL MEDICAL CENTER (Continued) **U003604579**

Tank ID:	619166
Tank Name:	DIESEL
Install Date:	4/13/2006
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Operational
TankSystem Status Change Date:	1/1/0001
Tank Status:	Operational
Tank Permit Expiration Date:	2/29/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Pressurized System
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection:	None
Pipe Material:	Flexible Piping
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Automatic Line Leak Detection
Pipe Second Release Detection:	Interstitial Monitoring (sump sensor)
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Interstitial Monitoring
Pipe Tightness Test:	Electronic Automatic Leak Line Detector
Tank Actual Status Date:	1/1/0001
Tag Number:	A5069

O58 **HOME DEPOT 4711** **RCRA-SQG** **1005445022**
South **325 120TH AVE NE** **FINDS** **WAH000012666**
1/4-1/2 **BELLEVUE, WA 98005** **ALLSITES**
0.344 mi. **MANIFEST**
1817 ft. **Site 1 of 7 in cluster O**

Relative:
Lower

Actual:
135 ft.

RCRA-SQG:

Date form received by agency:	03/08/2010
Facility name:	HOME DEPOT 4711
Facility address:	325 120TH AVE NE BELLEVUE, WA 98005
EPA ID:	WAH000012666
Mailing address:	5151 SAN FELIPE ST, STE 1600 HOUSTON, TX 77056
Contact:	JORGE GOMEZ
Contact address:	5151 SAN FELIPE ST, STE 1600 HOUSTON, TX 77056
Contact country:	US
Contact telephone:	(713) 625-7015
Contact email:	JGOMEZ2@PSCNOW.COM
EPA Region:	10
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

HOME DEPOT 4711 (Continued) **1005445022**

Owner/Operator Summary:

Owner/operator name:	HOME DEPOT
Owner/operator address:	325 120TH AVE NE BELLEVUE, 98005
Owner/operator country:	US
Owner/operator telephone:	425-451-7351
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	08/23/2000
Owner/Op end date:	Not reported

Owner/operator name:	HOME DEPOT
Owner/operator address:	2455 PACES FERRY RD SE ATLANTA, 30339
Owner/operator country:	US
Owner/operator telephone:	(770)433-8211
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/23/2000
Owner/Op end date:	Not reported

Owner/operator name:	HOME DEPOT
Owner/operator address:	1905 ASTON AVE STE 100 CARLSBAD, CA 92008
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	08/23/2000
Owner/Op end date:	Not reported

Owner/operator name:	HOME DEPOT
Owner/operator address:	2455 PACES FERRY RD SE ATLANTA, GA 30339
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/23/2000
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No

HOME DEPOT 4711 (Continued) **1005445022**

Used oil transporter: No

Historical Generators:

Date form received by agency: 03/13/2008
Facility name: HOME DEPOT 4711
Classification: Small Quantity Generator

Date form received by agency: 12/31/2007
Facility name: HOME DEPOT 4711
Classification: Small Quantity Generator

Date form received by agency: 12/31/2005
Facility name: HOME DEPOT 4711
Classification: Small Quantity Generator

Date form received by agency: 12/31/2003
Facility name: HOME DEPOT 4711
Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D005
Waste name: BARIUM

Waste code: D006
Waste name: CADMIUM

Waste code: D007
Waste name: CHROMIUM

Waste code: D008
Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: D016
Waste name: 2,4-D

HOME DEPOT 4711 (Continued) **1005445022**

Waste code: D018
Waste name: BENZENE

Waste code: D035
Waste name: METHYL ETHYL KETONE

Waste code: U002
Waste name: ACETONE (I)

Waste code: U080
Waste name: METHANE, DICHLORO-

Waste code: U160
Waste name: 2-BUTANONE, PEROXIDE (R,T)

Facility Has Received Notices of Violations:
Regulation violated: SR - -573(11)
Area of violation: Generators - General
Date violation determined: 03/09/2005
Date achieved compliance: 03/09/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/12/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -201(2)(a)
Area of violation: Generators - General
Date violation determined: 03/09/2005
Date achieved compliance: 06/17/2005
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/12/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -070(1-5) / -170(1)
Area of violation: Generators - General
Date violation determined: 06/17/2004
Date achieved compliance: 12/13/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/30/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

HOME DEPOT 4711 (Continued) **1005445022**

Regulation violated: SR - -630(9) / -200(1)(b)
Area of violation: Generators - General
Date violation determined: 06/17/2004
Date achieved compliance: 08/11/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/30/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -573(11)
Area of violation: Generators - General
Date violation determined: 06/17/2004
Date achieved compliance: 08/05/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/30/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -573(9)
Area of violation: Generators - General
Date violation determined: 06/17/2004
Date achieved compliance: 09/01/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/30/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -200(1)(d) / -170(2)
Area of violation: Generators - General
Date violation determined: 06/17/2004
Date achieved compliance: 08/05/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/30/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -573(10)

HOME DEPOT 4711 (Continued) **1005445022**

Area of violation: Generators - General
Date violation determined: 06/17/2004
Date achieved compliance: 09/01/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/30/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -200(1)(c) / -170(2)
Area of violation: Generators - General
Date violation determined: 06/17/2004
Date achieved compliance: 08/05/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/30/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -630(5) / -200(1)(b)
Area of violation: Generators - General
Date violation determined: 06/17/2004
Date achieved compliance: 08/05/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/30/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - -630(6) / -200(1)(b)
Area of violation: Generators - General
Date violation determined: 06/17/2004
Date achieved compliance: 08/11/2004
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/30/2004
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Evaluation Action Summary:
Evaluation date: 03/09/2005

HOME DEPOT 4711 (Continued) **1005445022**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 06/17/2005
Evaluation lead agency: State

Evaluation date: 03/09/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/09/2005
Evaluation lead agency: State

Evaluation date: 06/17/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 12/13/2004
Evaluation lead agency: State

Evaluation date: 06/17/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/05/2004
Evaluation lead agency: State

Evaluation date: 06/17/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/01/2004
Evaluation lead agency: State

Evaluation date: 06/17/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/11/2004
Evaluation lead agency: State

FINDS:

Registry ID: 110012563092

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

HOME DEPOT 4711 (Continued) **1005445022**

ALLSITES:

Facility Id:	74661266
Latitude:	47.6150985
Longitude:	-122.18098
Geographic location identifier (alias facid):	74661266
Facility Name:	Home Depot 4711
Latitude Decimal Degrees:	47.615098524700002
Longitude Decimal Degrees:	-122.180983013
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	8
Location Verified Code:	N

WA MANIFEST:

Facility Site ID Number:	74661266
SWC Desc:	Not reported
FWC Desc:	D001 D002 D009 D016 D035D001, D002, D005, D006, D007, D008, D009, D011, D016, D018, D035
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAH000012666
Facility Address 2:	Not reported
TAX REG NBR:	581853319
NAICS CD:	44411
BUSINESS TYPE:	Not reported
MAIL NAME:	Home Depot
MAIL ADDR LINE1:	1905 Aston Ave
MAIL ADDR LINE2:	Ste 100
MAIL CITY,ST,ZIP:	CARLSBAD, CA 92008
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Home Depot

HOME DEPOT 4711 (Continued) **1005445022**

LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	2455 PACES FERRY RD SE
LEGAL CITY,ST,ZIP:	ATLANTA, GA 30339-4024
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(770)433-8211
LEGAL EFFECTIVE DATE:	8/23/2000
LAND ORG NAME:	Home Depot
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	2455 PACES FERRY RD SE
LAND CITY,ST,ZIP:	ATLANTA, GA 30339-4024
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(770)433-8211
OPERATOR ORG NAME:	Home Depot
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1905 Aston Ave
OPERATOR ADDR LINE2:	Ste 100
OPERATOR CITY,ST,ZIP:	CARLSBAD, CA 92008
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(760)602-8700
OPERATOR EFFECTIVE DATE:	8/23/2000
SITE CONTACT NAME:	Melanie Koske
SITE CONTACT ADDR LINE1:	1905 Aston Ave
SITE CONTACT ADDR LINE2:	Ste 100
SITE CONTACT ZIP:	CARLSBAD, CA 92008
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(760)602-8700,ext 7486
SITE CONTACT EMAIL:	mkoske@3ecompany.com
FORM CONTACT NAME:	Melanie Koske
FORM CONTACT ADDR LINE1:	1905 Aston Ave
FORM CONTACT ADDR LINE2:	Ste 100
FORM CONTACT CITY,ST,ZIP:	CARLSBAD, CA 92008
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(760)602-8700,ext 7486
FORM CONTACT EMAIL:	mkoske@3ecompany.com
GEN STATUS CD:	MQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	FALSE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

Facility Site ID Number:	74661266
SWC Desc:	Not reported
FWC Desc:	D001- Ignitable, D002- Corrosive, D005- Cadmium, D006-Barium, D007- Chromium, D008-Lead, D009-
Form Comm:	Not reported
Data Year:	2010

HOME DEPOT 4711 (Continued) **1005445022**

Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAH000012666
Facility Address 2:	Not reported
TAX REG NBR:	581853319
NAICS CD:	444110
BUSINESS TYPE:	Not reported
MAIL NAME:	Home Depot
MAIL ADDR LINE1:	5151 San Felipe St, Ste 1600
MAIL CITY,ST,ZIP:	Houston, TX 77056
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Home Depot
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	2455 PACES FERRY RD SE
LEGAL CITY,ST,ZIP:	ATLANTA, GA 30339-4024
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(770)433-8211
LEGAL EFFECTIVE DATE:	8/23/2000
LAND ORG NAME:	Home Depot
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	2455 PACES FERRY RD SE
LAND CITY,ST,ZIP:	ATLANTA, GA 30339-4024
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(770)433-8211
OPERATOR ORG NAME:	Home Depot
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	325 120TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-451-7351
OPERATOR EFFECTIVE DATE:	8/23/2000
SITE CONTACT NAME:	Jorge Gomez
SITE CONTACT ADDR LINE1:	5151 San Felipe St, Ste 1600

HOME DEPOT 4711 (Continued) **1005445022**

SITE CONTACT ZIP:	Houston, TX 77056
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	713-625-7015
SITE CONTACT EMAIL:	jgomez2@pscnow.com
FORM CONTACT NAME:	Jorge Gomez
FORM CONTACT ADDR LINE1:	5151 San Felipe St, Ste 1600
FORM CONTACT CITY,ST,ZIP:	Houston, TX 77056
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	713-625-7015
FORM CONTACT EMAIL:	jgomez2@pscnow.com
GEN STATUS CD:	MQG
MONTHLY GENERATION:	True
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	74661266
SWC Desc:	Not reported
FWC Desc:	D001- Ignitable, D002- Corrosive, D005- Cadmium, D006-Barium, D007- Chromium, D008-Lead, D009-
Form Comm:	Not reported
Data Year:	2009
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False

HOME DEPOT 4711 (Continued) **1005445022**

EPA ID:	WAH000012666
Facility Address 2:	Not reported
TAX REG NBR:	581853319
NAICS CD:	444110
BUSINESS TYPE:	Not reported
MAIL NAME:	Home Depot
MAIL ADDR LINE1:	5151 San Felipe St, Ste 1600
MAIL CITY,ST,ZIP:	Houston, TX 77056
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Home Depot
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	2455 PACES FERRY RD SE
LEGAL CITY,ST,ZIP:	ATLANTA, GA 30339-4024
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(770)433-8211
LEGAL EFFECTIVE DATE:	8/23/2000
LAND ORG NAME:	Home Depot
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	2455 PACES FERRY RD SE
LAND CITY,ST,ZIP:	ATLANTA, GA 30339-4024
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(770)433-8211
OPERATOR ORG NAME:	Home Depot
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	325 120TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-451-7351
OPERATOR EFFECTIVE DATE:	8/23/2000
SITE CONTACT NAME:	Jorge Gomez
SITE CONTACT ADDR LINE1:	5151 San Felipe St, Ste 1600
SITE CONTACT ZIP:	Houston, TX 77056
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	713-625-7015
SITE CONTACT EMAIL:	jgomez2@pscnow.com
FORM CONTACT NAME:	Jorge Gomez
FORM CONTACT ADDR LINE1:	5151 San Felipe St, Ste 1600
FORM CONTACT CITY,ST,ZIP:	Houston, TX 77056
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	713-625-7015
FORM CONTACT EMAIL:	jgomez2@pscnow.com
GEN STATUS CD:	MQG
MONTHLY GENERATION:	True
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False

HOME DEPOT 4711 (Continued) **1005445022**

USED OIL FUEL MRKTR MEETS SPECS: False

Facility Site ID Number: 74661266
SWC Desc: Not reported
FWC Desc: D001 D002 D009 D016 D035D001, D002, D005, D006, D007, D008, D009, D011, D016, D018, D035
Form Comm: Not reported
Data Year: Not reported
Permit by Rule: No
Treatment by Generator: No
Mixed radioactive waste: No
Importer of hazardous waste: No
Immediate recycler: No
Treatment/Storage/Disposal/Recycling Facility: No
Generator of dangerous fuel waste: No
Generator marketing to burner: No
"Other marketers (i.e., blender, distributor, etc.)": No
Utility boiler burner: No
Industry boiler burner: No
Industrial Furnace: No
Smelter defferal: No
Universal waste - batteries - generate: No
Universal waste - thermostats - generate: No
Universal waste - mercury - generate: No
Universal waste - lamps - generate: No
Universal waste - batteries - accumulate: No
Universal waste - thermostats - accumulate: No
Universal waste - mercury - accumulate: No
Universal waste - lamps - accumulate: No
Destination Facility for Universal Waste: No
Off-specification used oil burner - utility boiler: No
Off-specification used oil burner - industrial boiler: No
Off-specification used oil burner - industrial furnace: No
EPA ID: WAH000012666
Facility Address 2: Not reported
TAX REG NBR: 581853319
NAICS CD: 44411
BUSINESS TYPE: Not reported
MAIL NAME: Home Depot
MAIL ADDR LINE1: 1905 Aston Ave
MAIL ADDR LINE2: Ste 100
MAIL CITY,ST,ZIP: CARLSBAD, CA 92008
MAIL COUNTRY: UNITED STATES
LEGAL ORG NAME: Home Depot
LEGAL ORG TYPE: Private
LEGAL ADDR LINE1: 2455 PACES FERRY RD SE
LEGAL CITY,ST,ZIP: ATLANTA, GA 30339-4024
LEGAL COUNTRY: UNITED STATES
LEGAL PHONE NBR: (770)433-8211
LEGAL EFFECTIVE DATE: 8/23/2000
LAND ORG NAME: Home Depot
LAND ORG TYPE: Private
LAND PERSON NAME: Not reported
LAND ADDR LINE1: 2455 PACES FERRY RD SE
LAND CITY,ST,ZIP: ATLANTA, GA 30339-4024
LAND COUNTRY: UNITED STATES
LAND PHONE NBR: (770)433-8211
OPERATOR ORG NAME: Home Depot

HOME DEPOT 4711 (Continued) **1005445022**

OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1905 Aston Ave
OPERATOR ADDR LINE2:	Ste 100
OPERATOR CITY,ST,ZIP:	CARLSBAD, CA 92008
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(760)602-8700
OPERATOR EFFECTIVE DATE:	8/23/2000
SITE CONTACT NAME:	Robert Perkins
SITE CONTACT ADDR LINE1:	1905 Aston Ave
SITE CONTACT ADDR LINE2:	Ste 100
SITE CONTACT ZIP:	CARLSBAD, CA 92008
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(760)602-8839
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Robert Perkins
FORM CONTACT ADDR LINE1:	1905 Aston Ave
FORM CONTACT ADDR LINE2:	Ste 100
FORM CONTACT CITY,ST,ZIP:	CARLSBAD, CA 92008
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(760)602-8839
FORM CONTACT EMAIL:	rperkins@3ecompany.com
GEN STATUS CD:	MQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Facility Site ID Number:	74661266
SWC Desc:	Not reported
FWC Desc:	D001 D002 D009 D016 D035D001, D002, D005, D006, D007, D008, D009, D011, D016, D018, D035
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False

HOME DEPOT 4711 (Continued) **1005445022**

Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAH000012666
Facility Address 2:	Not reported
TAX REG NBR:	581853319
NAICS CD:	44411
BUSINESS TYPE:	Not reported
MAIL NAME:	Home Depot
MAIL ADDR LINE1:	1905 Aston Ave
MAIL ADDR LINE2:	Ste 100
MAIL CITY,ST,ZIP:	CARLSBAD, CA 92008
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Home Depot
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	2455 PACES FERRY RD SE
LEGAL CITY,ST,ZIP:	ATLANTA, GA 30339-4024
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(770)433-8211
LEGAL EFFECTIVE DATE:	8/23/2000
LAND ORG NAME:	Home Depot
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	2455 PACES FERRY RD SE
LAND CITY,ST,ZIP:	ATLANTA, GA 30339-4024
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(770)433-8211
OPERATOR ORG NAME:	Home Depot
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	325 120TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-451-7351
OPERATOR EFFECTIVE DATE:	08/23/00
SITE CONTACT NAME:	Melanie Koske
SITE CONTACT ADDR LINE1:	1905 Aston Ave
SITE CONTACT ADDR LINE2:	Ste 100
SITE CONTACT ZIP:	CARLSBAD, CA 92008
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(760)602-8700,ext 7486
SITE CONTACT EMAIL:	mkoske@3ecompany.com
FORM CONTACT NAME:	Melanie Koske
FORM CONTACT ADDR LINE1:	1905 Aston Ave
FORM CONTACT ADDR LINE2:	Ste 100
FORM CONTACT CITY,ST,ZIP:	CARLSBAD, CA 92008
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(760)602-8700,ext 7486
FORM CONTACT EMAIL:	mkoske@3ecompany.com
GEN STATUS CD:	MQG

HOME DEPOT 4711 (Continued) **1005445022**

MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Click this hyperlink while viewing on your computer to access additional WA MANIFEST: detail in the EDR Site Report.

59
North
1/4-1/2
0.346 mi.
1825 ft.

Relative:
Higher

Actual:
163 ft.

K & L DIST NORTH BELLEVUE FACILITY **RCRA-NonGen** **1000659553**
1445 120TH NE **FINDS** **WAD988492278**
BELLEVUE, WA 98005 **ALLSITES**
CSCSL NFA
UST
ICR
VCP

RCRA-NonGen:

Date form received by agency:	12/24/1997
Facility name:	K & L DIST NORTH BELLEVUE FACILITY
Facility address:	1445 120TH NE BELLEVUE, WA 980052127
EPA ID:	WAD988492278
Mailing address:	PO BOX 9300 RENTON, WA 98057-9300
Contact:	RICHARD MEDLANG
Contact address:	PO BOX 9300 RENTON, WA 98057-9300
Contact country:	US
Contact telephone:	(206)808-6000
Contact email:	Not reported
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	K & L DIST INC
Owner/operator address:	PO BOX 9300 RENTON, WA 98057
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/16/1996
Owner/Op end date:	Not reported

K & L DIST NORTH BELLEVUE FACILITY (Continued) **1000659553**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110005365149

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:
Facility Id: 21556254
Latitude: 47.6251299
Longitude: -122.17899
Geographic location identifier (alias facid): 21556254
Facility Name: K & L Dist North Bellevue Facility
Latitude Decimal Degrees: 47.625129999999999
Longitude Decimal Degrees: -122.17899
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

CSCSL NFA:
Facility/Site Id: 21556254
CS Id: 5688

K & L DIST NORTH BELLEVUE FACILITY (Continued) **1000659553**

NFA Type: NFA-VCP Review
NFA Date: 12/01/1998
Rank: Not reported

UST:
Facility ID: 21556254
Site ID: 6225
Lat Deg: 47
Lat Min: 37
Lat Sec: 30.467999999995072
Long Deg: -122
Long Min: 10
Long Sec: 44.36399999999594
UBI: Not reported
Phone Number: 2064533300

Tank ID: 32094
Tank Name: 2
Install Date: 5/1/1981
Capacity: 10,000 to 19,999 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 2/28/2008
Tank Status: Removed
Tank Permit Expiration Date: 12/31/1997
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Spill Bucket/Spill Box
Tank Overfill Prevention: Overfill Alarm
Tank Material: Not reported
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: None
Pipe Material: Not reported
Pipe Construction: Single Wall Pipe
Pipe Primary Release Detection: Suction
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: None
Tank Primary Release Detection: Automatic Tank Gauging
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 9/1/1998
Tag Number: Not reported

Tank ID: 32202
Tank Name: 1
Install Date: 5/1/1981
Capacity: 10,000 to 19,999 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 2/28/2008
Tank Status: Removed
Tank Permit Expiration Date: 12/31/1997
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Spill Bucket/Spill Box

K & L DIST NORTH BELLEVUE FACILITY (Continued) **1000659553**

Tank Overfill Prevention:	Overfill Alarm
Tank Material:	Not reported
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	None
Pipe Material:	Not reported
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Suction
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	9/1/1998
Tag Number:	Not reported

ICR:

Date Ecology Received Report:	10/23/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	98-09
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	10/20/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	98-11
County Code:	17
Contact:	Not reported
Report Title:	Not reported

VCP:

edr_fstat:	WA
edr_fzip:	98005
edr_fcnty:	KING COUNTY
edr_zip:	Not reported
Facility ID:	21556254
VCP Status:	Not reported
VCP:	Y
Ecology Status:	Not reported
NFA Type:	NFA-VCP Review
Date NFA:	12/01/1998
Rank:	Not reported

P60 **DANA R MARTIN** **RCRA-NonGen** **1000143144**
WNW **1100 116TH NE** **FINDS** **WAD982654568**
1/4-1/2 **BELLEVUE, WA 98005** **ALLSITES**
0.353 mi.
1862 ft. **Site 1 of 2 in cluster P**

Relative:
Higher

Actual:
176 ft.

RCRA-NonGen:

Date form received by agency:	03/15/1989
Facility name:	DANA R MARTIN
Facility address:	1100 116TH NE BELLEVUE, WA 98005
EPA ID:	WAD982654568
Mailing address:	12101 W OLYMPIC BLVD LOS ANGELES, CA 90064-1017
Contact:	DANA MARTIN
Contact address:	12101 W OLYMPIC BLVD LOS ANGELES, CA 90064-1017
Contact country:	US
Contact telephone:	(213)477-7069
Contact email:	Not reported
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110005346296

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:

Facility Id:	75232247
Latitude:	47.6211300

DANA R MARTIN (Continued) **1000143144**

Longitude:	-122.18692
Geographic location identifier (alias facid):	75232247
Facility Name:	Dana R Martin
Latitude Decimal Degrees:	47.621130000000001
Longitude Decimal Degrees:	-122.18692
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

O61 **K & L DISTRIBUTORS INC UST 6224** **ALLSITES** **S109824849**
South **300 120TH AVE NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98009**
0.354 mi.
1868 ft. **Site 2 of 7 in cluster O**

Relative:
Lower

Actual:
135 ft.

ALLSITES:

Facility Id:	31813216
Latitude:	47.6136314
Longitude:	-122.18039
Geographic location identifier (alias facid):	31813216
Facility Name:	K & L DISTRIBUTORS INC UST 6224
Latitude Decimal Degrees:	47.613631453499998
Longitude Decimal Degrees:	-122.18039067700001
Coordinate Point Areal Extent Code:	4
Horizontal Accuracy Code:	6
Coordinate Point Geographic Position Code:	8
Location Verified Code:	Not reported

O62 **K & L DISTRIBUTORS INC UST 6224** **FINDS** **1007072814**
South **300 120 AVE NE** **LUST** **N/A**
1/4-1/2 **BELLEVUE, WA 98005** **UST**
0.354 mi.
1868 ft. **Site 3 of 7 in cluster O**

Relative:
Lower

Actual:
135 ft.

FINDS:

Registry ID: 110015494428

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

LUST:

FS ID:	31813216
Cleanup Site ID:	8686
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Monitoring

K & L DISTRIBUTORS INC UST 6224 (Continued) **1007072814**

Alternate Name: K & L DISTRIBUTORS INC
Release Notification Date: Not reported
Release Status Date: 12/20/1994
Site Response Unit Code: Northwest
Lat/Long: 47.6136314 / -122.18039

FS ID: 31813216
Cleanup Site ID: 8686
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: K & L DISTRIBUTORS INC
Release Notification Date: Not reported
Release Status Date: 12/17/1991
Site Response Unit Code: Northwest
Lat/Long: 47.6136314 / -122.18039

UST:
Facility ID: 31813216
Site ID: 6224
Lat Deg: Not reported
Lat Min: Not reported
Lat Sec: Not reported
Long Deg: Not reported
Long Min: Not reported
Long Sec: Not reported
UBI: Not reported
Phone Number: 2064533300

Tank ID: 27478
Tank Name: 1 DRAIN OIL
Install Date: 12/31/1964
Capacity: 111 TO 1,100 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Steel
Tank Construction: Not reported
Tank Tightness Test: Not reported
Tank Corrosion Protection: Not reported
Pipe Material: Not reported
Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

K & L DISTRIBUTORS INC UST 6224 (Continued) **1007072814**

Tank ID:	31813
Tank Name:	3 GAS
Install Date:	12/31/1964
Capacity:	10,000 to 19,999 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	36849
Tank Name:	2 DIESEL
Install Date:	12/31/1964
Capacity:	2,001 to 4,999 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

O63 **K & L DISTRIBUTORS, INC.** **ICR** **S104484698**
South **300 120TH AVE. NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98009**
0.354 mi.
1868 ft. **Site 4 of 7 in cluster O**

Relative:
Lower

Actual:
135 ft.

ICR:

Date Ecology Received Report:	03/21/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	95-08
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	10/20/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	98-11
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	12/17/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	92-14
County Code:	17
Contact:	Not reported
Report Title:	Not reported

O64 **UNICRAFT PRINTING** **RCRA-CESQG** **1000474079**
South **300 120TH AVE NE BLDG 6 STE114** **FINDS** **WAD988481651**
1/4-1/2 **BELLEVUE, WA 98005** **CSCSL**
0.354 mi. **ALLSITES**
1868 ft. **Site 5 of 7 in cluster O**

Relative:
Lower

Actual:
135 ft.

RCRA-CESQG:

Date form received by agency:	01/15/1997
Facility name:	UNICRAFT PRINTING
Facility address:	300 120TH AVE NE BLDG 6 STE114 BELLEVUE, WA 98005
EPA ID:	WAD988481651
Mailing address:	300 120TH AVE NE BELLEVUE, WA 98005-3020
Contact:	MICHAEL BITTNER
Contact address:	300 120TH AVE NE BELLEVUE, WA 98005-3020
Contact country:	US
Contact telephone:	(425)453-0995
Contact email:	Not reported

UNICRAFT PRINTING (Continued) **1000474079**

EPA Region: 10
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: MICHAEL BITTNER
Owner/operator address: 300 120TH AVE NE
BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/15/1997
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/01/1996
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/12/1991

UNICRAFT PRINTING (Continued) **1000474079**

Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005357531

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CSCSL:

Facility ID: 16237766
Region: Northwest
Lat/Long: 47.613790000000 / -122.17977
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 3136
Site Status: Awaiting Cleanup
PSI?: Not reported
Contaminant Name: Halogenated Organics
Ground Water: C
Surface Water: Not reported
Soil: R
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 16237766
Region: Northwest
Lat/Long: 47.613790000000 / -122.17977
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 3136
Site Status: Awaiting Cleanup
PSI?: Not reported
Contaminant Name: Non-Halogenated Solvents
Ground Water: C
Surface Water: Not reported
Soil: R
Sediment: Not reported
Air: Not reported

UNICRAFT PRINTING (Continued) **1000474079**

Bedrock:	Not reported
Responsible Unit:	Northwest
Facility ID:	16237766
Region:	Northwest
Lat/Long:	47.613790000000 / -122.17977
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	3136
Site Status:	Awaiting Cleanup
PSI?:	Not reported
Contaminant Name:	Petroleum Products - unspecified
Ground Water:	C
Surface Water:	Not reported
Soil:	R
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

ALLSITES:

Facility Id:	16237766
Latitude:	47.6137900
Longitude:	-122.17977
Geographic location identifier (alias facid):	16237766
Facility Name:	Unicraft Printing
Latitude Decimal Degrees:	47.613790000000002
Longitude Decimal Degrees:	-122.17977
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

O65 **HOME DEPOT** **ALLSITES** **S109555616**
South **300 120TH AVE NE BLDG 5 S END TRUCK SHOP** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.354 mi.
1868 ft. **Site 6 of 7 in cluster O**

Relative:
Lower

Actual:
135 ft.

ALLSITES:

Facility Id:	73652312
Latitude:	47.6137900
Longitude:	-122.17977
Geographic location identifier (alias facid):	73652312
Facility Name:	Home Depot
Latitude Decimal Degrees:	47.613790000000002
Longitude Decimal Degrees:	-122.17977
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

O66 **AGI TECHNOLOGIES 120TH AVE** **ALLSITES** **S109555394**
South **300 120TH AVE NE BLDG 4 STE 215** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.354 mi.
1868 ft. **Site 7 of 7 in cluster O**

Relative:
Lower

Actual:
135 ft.

ALLSITES:

Facility Id:	61722956	
Latitude:	47.6137900	
Longitude:	-122.17977	
Geographic location identifier (alias facid):		61722956
Facility Name:		AGI Technologies 120th Ave
Latitude Decimal Degrees:		47.613790000000002
Longitude Decimal Degrees:		-122.17977
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		99
Location Verified Code:		N

Q67 **EXOTIC MOTORS AUTO REBUILD INC** **RCRA-NonGen** **1004793119**
SW **638 116TH AVE NE E SIDE OF BLD** **FINDS** **WA0000013508**
1/4-1/2 **BELLEVUE, WA 98004** **ALLSITES**
0.360 mi. **MANIFEST**
1898 ft. **Site 1 of 5 in cluster Q**

Relative:
Lower

Actual:
104 ft.

RCRA-NonGen:

Date form received by agency:	02/05/2010
Facility name:	EXOTIC MOTORS AUTO REBUILD INC
Facility address:	638 116TH AVE NE E SIDE OF BLD BELLEVUE, WA 98004
EPA ID:	WA0000013508
Mailing address:	638 116TH AVE NE BELLEVUE, WA 98004
Contact:	GEORGE BEJVL
Contact address:	638 116TH AVE NE BELLEVUE, WA 98004
Contact country:	US
Contact telephone:	(425) 451-0229
Contact email:	Not reported
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	EXOTIC MOTORS AUTO REBUILD INC
Owner/operator address:	638 116TH AVE NE BELLEVUE, 98004
Owner/operator country:	US
Owner/operator telephone:	(425)451-0229
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/16/2001
Owner/Op end date:	Not reported
Owner/operator name:	EXOTIC MOTORS AUTO REBUILD INC
Owner/operator address:	638 116TH AVE NE BELLEVUE, WA 98004
Owner/operator country:	US

EXOTIC MOTORS AUTO REBUILD INC (Continued) **1004793119**

Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 03/16/2001
Owner/Op end date: Not reported

Owner/operator name: JOHN KLEIN
Owner/operator address: 638 116TH AVE NE
BELLEVUE, 98004
Owner/operator country: US
Owner/operator telephone: (425)451-0229
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/12/1996
Owner/Op end date: Not reported

Owner/operator name: JIM KLEIN
Owner/operator address: 638 116TH AVE NE
BELLEVUE, WA 98004
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/12/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/08/2008
Facility name: EXOTIC MOTORS AUTO REBUILD INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/31/2007
Facility name: EXOTIC MOTORS AUTO REBUILD INC
Classification: Not a generator, verified

Date form received by agency: 12/31/2005
Facility name: EXOTIC MOTORS AUTO REBUILD INC
Classification: Not a generator, verified

EXOTIC MOTORS AUTO REBUILD INC (Continued) **1004793119**

Date form received by agency: 12/31/2003
Facility name: EXOTIC MOTORS AUTO REBUILD INC
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110008213744

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ALLSITES:

Facility Id:	94574951
Latitude:	47.6163499
Longitude:	-122.18635
Geographic location identifier (alias facid):	94574951
Facility Name:	Exotic Motors Auto Rebuild Inc
Latitude Decimal Degrees:	47.616349999999997
Longitude Decimal Degrees:	-122.18635999999999
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

WA MANIFEST:

Facility Site ID Number:	94574951
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False

EXOTIC MOTORS AUTO REBUILD INC (Continued) **1004793119**

Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WA0000013508
Facility Address 2:	Not reported
TAX REG NBR:	601578709
NAICS CD:	811121
BUSINESS TYPE:	Not reported
MAIL NAME:	Exotic Motors Auto Rebuild Inc
MAIL ADDR LINE1:	638 116th Ave NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Exotic Motors Auto Rebuild Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	638 116th Ave NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)451-0229
LEGAL EFFECTIVE DATE:	3/16/2001
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Lew Brunhavener
LAND ADDR LINE1:	201 116th Ave NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)454-2100
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	638 116th Ave NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)451-0229
OPERATOR EFFECTIVE DATE:	08/12/96
SITE CONTACT NAME:	George Bejvl
SITE CONTACT ADDR LINE1:	638 116th Ave NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)451-0229
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	George Bejvl
FORM CONTACT ADDR LINE1:	638 116th Ave NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)451-0229

EXOTIC MOTORS AUTO REBUILD INC (Continued) **1004793119**

FORM CONTACT EMAIL:	ken@exoticmotors.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	94574951
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2009
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WA0000013508
Facility Address 2:	Not reported
TAX REG NBR:	601578709
NAICS CD:	811121
BUSINESS TYPE:	Not reported
MAIL NAME:	Exotic Motors Auto Rebuild Inc
MAIL ADDR LINE1:	638 116th Ave NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
MAIL COUNTRY:	UNITED STATES

EXOTIC MOTORS AUTO REBUILD INC (Continued) **1004793119**

LEGAL ORG NAME:	Exotic Motors Auto Rebuild Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	638 116th Ave NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)451-0229
LEGAL EFFECTIVE DATE:	3/16/2001
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Lew Brunhavener
LAND ADDR LINE1:	201 116th Ave NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)454-2100
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	638 116th Ave NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)451-0229
OPERATOR EFFECTIVE DATE:	8/12/1996
SITE CONTACT NAME:	George Bejvl
SITE CONTACT ADDR LINE1:	638 116th Ave NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)451-0229
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	George Bejvl
FORM CONTACT ADDR LINE1:	638 116th Ave NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)451-0229
FORM CONTACT EMAIL:	ken@exoticmotors.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	94574951
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No

EXOTIC MOTORS AUTO REBUILD INC (Continued) **1004793119**

Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WA0000013508
Facility Address 2:	Not reported
TAX REG NBR:	601578709
NAICS CD:	811121
BUSINESS TYPE:	Not reported
MAIL NAME:	Exotic Motors Auto Rebuild Inc
MAIL ADDR LINE1:	638 116th Ave NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Exotic Motors Auto Rebuild Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	638 116th Ave NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)451-0229
LEGAL EFFECTIVE DATE:	3/16/2001
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Lew Brunhavener
LAND ADDR LINE1:	201 116th Ave NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)454-2100
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	638 116th Ave NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)451-0229
OPERATOR EFFECTIVE DATE:	8/12/1996
SITE CONTACT NAME:	George Bejvl
SITE CONTACT ADDR LINE1:	638 116th Ave NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES

EXOTIC MOTORS AUTO REBUILD INC (Continued) **1004793119**

SITE CONTACT PHONE NBR:	(425)451-0229
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	George Bejvl
FORM CONTACT ADDR LINE1:	638 116th Ave NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)451-0229
FORM CONTACT EMAIL:	Not reported
GEN STATUS CD:	SQG
MONTHLY GENERATION:	No
BATCH GENERATION:	Yes
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Facility Site ID Number:	94574951
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2008
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WA0000013508
Facility Address 2:	Not reported

EXOTIC MOTORS AUTO REBUILD INC (Continued) **1004793119**

TAX REG NBR:	601578709
NAICS CD:	811121
BUSINESS TYPE:	Not reported
MAIL NAME:	Exotic Motors Auto Rebuild Inc
MAIL ADDR LINE1:	638 116th Ave NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Exotic Motors Auto Rebuild Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	638 116th Ave NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)451-0229
LEGAL EFFECTIVE DATE:	3/16/2001
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Lew Brunhavener
LAND ADDR LINE1:	201 116th Ave NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)454-2100
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	638 116th Ave NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)451-0229
OPERATOR EFFECTIVE DATE:	8/12/1996
SITE CONTACT NAME:	George Bejvl
SITE CONTACT ADDR LINE1:	638 116th Ave NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)451-0229
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	George Bejvl
FORM CONTACT ADDR LINE1:	638 116th Ave NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)451-0229
FORM CONTACT EMAIL:	ken@exoticmotors.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	True
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

EXOTIC MOTORS AUTO REBUILD INC (Continued) **1004793119**

Facility Site ID Number:	94574951
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WA0000013508
Facility Address 2:	Not reported
TAX REG NBR:	601578709
NAICS CD:	811121
BUSINESS TYPE:	Not reported
MAIL NAME:	Exotic Motors Auto Rebuild Inc
MAIL ADDR LINE1:	638 116th Ave NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Exotic Motors Auto Rebuild Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	638 116th Ave NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-5206
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)451-0229
LEGAL EFFECTIVE DATE:	3/16/2001
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Lew Brunhavener
LAND ADDR LINE1:	201 116th Ave NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)454-2100
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	638 116th Ave NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-5206

EXOTIC MOTORS AUTO REBUILD INC (Continued) **1004793119**

OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)451-0229
OPERATOR EFFECTIVE DATE:	8/12/1996
SITE CONTACT NAME:	George Bejvl
SITE CONTACT ADDR LINE1:	638 116th Ave NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)451-0229
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	George Bejvl
FORM CONTACT ADDR LINE1:	638 116th Ave NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)451-0229
FORM CONTACT EMAIL:	ken@exoticmotors.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	TRUE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

Click this hyperlink while viewing on your computer to access
1 additional WA MANIFEST: record(s) in the EDR Site Report.

Q68 **DEALERS CHOICE AUTOMOTIVE INC** **RCRA-NonGen** **1000659325**
SW **638 B 116TH AVE NE** **FINDS** **WAD988489944**
1/4-1/2 **BELLEVUE, WA 98004** **ALLSITES**
0.360 mi.
1898 ft. **Site 2 of 5 in cluster Q**

Relative:
Lower

Actual:
104 ft.

RCRA-NonGen:

Date form received by agency:	07/16/1997
Facility name:	DEALERS CHOICE AUTOMOTIVE INC
Facility address:	638 B 116TH AVE NE BELLEVUE, WA 98004
EPA ID:	WAD988489944
Contact:	ERIC BOCKSBERGER
Contact address:	638 B 116TH AVE NE BELLEVUE, WA 98004-0000
Contact country:	US
Contact telephone:	(425)462-1323
Contact email:	Not reported
EPA Region:	10
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

DEALERS CHOICE AUTOMOTIVE INC (Continued) **1000659325**

Owner/Operator Summary:
Owner/operator name: DEALERS CHOICE AUTOMOTIVE INC
Owner/operator address: 638 B 116TH AVE NE
BELLEVUE, WA 98004
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/02/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/01/1993
Facility name: DEALERS CHOICE AUTOMOTIVE INC
Site name: H.C. AUTO CARE, INC.
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/06/1996
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005363542

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource

DEALERS CHOICE AUTOMOTIVE INC (Continued) **1000659325**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:

Facility Id:	51852149	
Latitude:	47.6165892	
Longitude:	-122.18641	
Geographic location identifier (alias facid):		51852149
Facility Name:		Dealers Choice Automotive Inc
Latitude Decimal Degrees:		47.616589273400002
Longitude Decimal Degrees:		-122.186419661
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		6
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported

P69 **OVERLAKE MEDICAL TOWER LLC** **ALLSITES** **U004040814**
NW **1135 116TH AVE NE** **UST** **N/A**
1/4-1/2 **BELLEVUE, WA 98004**
0.365 mi.
1927 ft. **Site 2 of 2 in cluster P**

Relative:
Higher

Actual:
181 ft.

ALLSITES:

Facility Id:	28517954	
Latitude:	47.621693	
Longitude:	-122.18563	
Geographic location identifier (alias facid):		28517954
Facility Name:		OVERLAKE MEDICAL TOWER LLC
Latitude Decimal Degrees:		47.621693
Longitude Decimal Degrees:		-122.185638
Coordinate Point Areal Extent Code:		4
Horizontal Accuracy Code:		8
Coordinate Point Geographic Position Code:		8
Location Verified Code:		N

UST:

Facility ID:	28517954
Site ID:	578959
Lat Deg:	47
Lat Min:	37
Lat Sec:	18.094800000001783
Long Deg:	-122
Long Min:	11
Long Sec:	8.2967999999902986
UBI:	6019332030010001
Phone Number:	4254622100
Tank ID:	580877
Tank Name:	1
Install Date:	1/1/2001
Capacity:	5,000 to 9,999 Gallons

OVERLAKE MEDICAL TOWER LLC (Continued) **U004040814**

Tank Upgrade Date:	1/1/2001
TankSystem Status:	Operational
TankSystem Status Change Date:	8/13/2001
Tank Status:	Operational
Tank Permit Expiration Date:	2/29/2012
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Double Wall Tank
Tank Tightness Test:	Part of Automatic Tank Gauging (ATG) System
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Flexible Piping
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Suction
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	8/13/2001
Tag Number:	A5144

Q70 **BELLEVUE BUICK GMC TRUCK (TWO REPORTS)** **ICR** **1001820632**
SW **620 116TH AVE. NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98004**
0.366 mi.
1935 ft. **Site 3 of 5 in cluster Q**

Relative:
Lower

Actual:
102 ft.

ICR:

Date Ecology Received Report:	04/06/95
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	94-09
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Q71 **BELLEVUE PONTIAC GMC TRUCK** **ALLSITES** **S104971566**
SW **620 116TH AVE NE** **CSCSL NFA** **N/A**
1/4-1/2 **BELLEVUE, WA 98004** **VCP**
0.366 mi.
1935 ft. **Site 4 of 5 in cluster Q**

Relative:
Lower

Actual:
102 ft.

ALLSITES:

Facility Id:	94227183	
Latitude:	47.6164399	
Longitude:	-122.1854	
Geographic location identifier (alias facid):		94227183
Facility Name:		Bellevue Pontiac GMC Truck
Latitude Decimal Degrees:		47.616439999999997
Longitude Decimal Degrees:		-122.1854

BELLEVUE PONTIAC GMC TRUCK (Continued) **S104971566**

Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 8
Location Verified Code: N

Facility Id: 2548
Latitude: 47.6161409
Longitude: -122.18667
Geographic location identifier (alias facid): 2548
Facility Name: BELLEVUE BUICK ISUZU
Latitude Decimal Degrees: 47.616140999999999
Longitude Decimal Degrees: -122.186674
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 6
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

Geographic Location Identifier (Alias Facid): 2548
Interaction (Aka Env Int) Type Code: LUST
Interaction (Aka Env Int) Description: LUST Facility
Interaction Status: I
Federal Program Indentifier: 10877
Interaction Start Date: 04/05/1995
Interaction End Date: 09/25/1995
prgm_facil: Not reported
cur_sys_pr: TOXICS
cur_sys_nm: ISIS

Geographic Location Identifier (Alias Facid): 2548
Interaction (Aka Env Int) Type Code: VOLCLNST
Interaction (Aka Env Int) Description: Voluntary Cleanup Sites
Interaction Status: I
Federal Program Indentifier: Not reported
Interaction Start Date: 09/25/1995
Interaction End Date: 09/26/1995
prgm_facil: BELLEVUE BUICK ISUZU
cur_sys_pr: TOXICS
cur_sys_nm: ISIS

Geographic Location Identifier (Alias Facid): 2548
Interaction (Aka Env Int) Type Code: UST
Interaction (Aka Env Int) Description: Underground Storage Tank
Interaction Status: I
Federal Program Indentifier: 10877
Interaction Start Date: 03/20/2000
Interaction End Date: 03/20/2000
prgm_facil: Not reported
cur_sys_pr: TOXICS
cur_sys_nm: ISIS

Geographic Location Identifier (Alias Facid): 2548
Interaction (Aka Env Int) Type Code: VOLCLNST
Interaction (Aka Env Int) Description: Voluntary Cleanup Sites
Interaction Status: I
Federal Program Indentifier: Not reported
Interaction Start Date: 05/21/2001

BELLEVUE PONTIAC GMC TRUCK (Continued) **S104971566**

Interaction End Date:	11/07/2001
prgm_facil:	BELLEVUE BUICK ISUZU
cur_sys_pr:	TOXICS
cur_sys_nm:	ISIS

CSCSL NFA:

Facility/Site Id:	2548
CS Id:	5144
NFA Type:	NFA-VCP Review
NFA Date:	09/28/2001
Rank:	Not reported

VCP:

edr_fstat:	WA
edr_fzip:	98004
edr_fcnty:	KING COUNTY
edr_zip:	Not reported
Facility ID:	2548
VCP Status:	Not reported
VCP:	Y
Ecology Status:	Not reported
NFA Type:	NFA-VCP Review
Date NFA:	09/28/2001
Rank:	Not reported

Q72 **BELLEVUE ISUZU BELLEVUE** **ALLSITES** **S109555375**
SW **614 116TH AVE NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98004**
0.369 mi.
1947 ft. **Site 5 of 5 in cluster Q**

Relative:
Lower

Actual:
101 ft.

ALLSITES:

Facility Id:	55232125	
Latitude:	47.6164199	
Longitude:	-122.1854	
Geographic location identifier (alias facid):		55232125
Facility Name:		Bellevue Isuzu Bellevue
Latitude Decimal Degrees:		47.616419999999998
Longitude Decimal Degrees:		-122.1854
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		99
Location Verified Code:		N

73
SW
1/4-1/2
0.374 mi.
1976 ft.

PUGET SOUND POWER & LIGHT CO CENTRAL
600 116TH AVE NE
BELLEVUE, WA 98004

RCRA-NonGen
FINDS
ALLSITES

1000878667
WA0000127472

Relative:
Lower

Actual:
101 ft.

RCRA-NonGen:

Date form received by agency:	05/14/1997
Facility name:	PUGET SOUND POWER & LIGHT CO CENTRAL
Facility address:	600 116TH AVE NE BELLEVUE, WA 98004
EPA ID:	WA0000127472
Mailing address:	PO BOX 97034 ENV-SVC BELLEVUE, WA 98009-9734
Contact:	LEA BOYLE
Contact address:	PO BOX 97034 ENV-SVC BELLEVUE, WA 98009-9734
Contact country:	US
Contact telephone:	(425)462-3224
Contact email:	Not reported
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	PUGET SOUND ENERGY
Owner/operator address:	PO BOX 97034 ENV-SVC BELLEVUE, WA 98009
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/03/1997
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110005303028

PUGET SOUND POWER & LIGHT CO CENTRAL (Continued) **1000878667**

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:

Facility Id:	44265987
Latitude:	47.6163499
Longitude:	-122.18541
Geographic location identifier (alias facid):	44265987
Facility Name:	Puget Sound Power & Light Co Central
Latitude Decimal Degrees:	47.616349999999997
Longitude Decimal Degrees:	-122.18541999999999
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

R74 **BMC WEST** **ICR S104486058**
ENE **12600 BEL-RED ROAD** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.393 mi.
2074 ft. **Site 1 of 2 in cluster R**

Relative: Lower

Actual: 148 ft.

ICR:

Date Ecology Received Report:	12/24/90
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	91-19
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	05/06/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Not reported
Site Register Issue:	91-29
County Code:	17
Contact:	Not reported

BMC WEST (Continued) **S104486058**

Report Title: Not reported

R75 **BMC WEST BUILDING MATERIALS** **RCRA-CESQG** **1001490781**
ENE **12600 BELLEVUE REDMOND RD** **FINDS** **WAD988501607**
1/4-1/2 **BELLEVUE, WA 98005** **CSCSL**
0.393 mi. **ALLSITES**
2074 ft. **Site 2 of 2 in cluster R** **LUST**
UST

Relative:
Lower

Actual:
148 ft.

RCRA-CESQG:

Date form received by agency:	10/15/1996
Facility name:	BMC WEST BUILDING MATERIALS
Facility address:	12600 BELLEVUE REDMOND RD BELLEVUE, WA 98005
EPA ID:	WAD988501607
Mailing address:	PO BOX 7015 ISSAQUAH, WA 98027-7015
Contact:	ROBERT EDGERS
Contact address:	PO BOX 7015 ISSAQUAH, WA 98027-7015
Contact country:	US
Contact telephone:	(425)454-3021
Contact email:	Not reported
EPA Region:	10
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	BMC WEST HOLDING CO INC
Owner/operator address:	PO BOX 7015 ISSAQUAH, WA 98027
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	10/15/1996
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

BMC WEST BUILDING MATERIALS (Continued) **1001490781**

Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110005372097

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CSCSL:

Facility ID:	27717562
Region:	Northwest
Lat/Long:	47.620649999999 / -122.1717
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	8556
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	B
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	27717562
Region:	Northwest
Lat/Long:	47.620649999999 / -122.1717
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	8556

BMC WEST BUILDING MATERIALS (Continued) **1001490781**

Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Diesel
Ground Water: B
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 27717562
Region: Northwest
Lat/Long: 47.620649999999 / -122.1717
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 8556
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Gasoline
Ground Water: B
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 27717562
Region: Northwest
Lat/Long: 47.620649999999 / -122.1717
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 8556
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Other
Ground Water: B
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 27717562
Latitude: 47.6206499
Longitude: -122.1717
Geographic location identifier (alias facid): 27717562
Facility Name: BMC West Building Materials
Latitude Decimal Degrees: 47.620649999999998
Longitude Decimal Degrees: -122.1717
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 4
Coordinate Point Geographic Position Code: 5
Location Verified Code: Y

BMC WEST BUILDING MATERIALS (Continued) **1001490781**

LUST:

FS ID:	27717562
Cleanup Site ID:	8556
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	RCU
Alternate Name:	BMC WEST
Release Notification Date:	Not reported
Release Status Date:	01/07/2004
Site Response Unit Code:	Northwest
Lat/Long:	47.6206499 / -122.1717

FS ID:	27717562
Cleanup Site ID:	8556
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	BMC WEST
Release Notification Date:	Not reported
Release Status Date:	12/20/1990
Site Response Unit Code:	Northwest
Lat/Long:	47.6206499 / -122.1717

FS ID:	27717562
Cleanup Site ID:	8556
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	BMC WEST
Release Notification Date:	Not reported
Release Status Date:	07/01/2011
Site Response Unit Code:	Northwest
Lat/Long:	47.6206499 / -122.1717

FS ID:	27717562
Cleanup Site ID:	8556
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Monitoring
Alternate Name:	BMC WEST
Release Notification Date:	Not reported
Release Status Date:	06/01/1995
Site Response Unit Code:	Northwest
Lat/Long:	47.6206499 / -122.1717

UST:

Facility ID:	27717562
Site ID:	7271
Lat Deg:	47
Lat Min:	37
Lat Sec:	14.339999999991733
Long Deg:	-122
Long Min:	10
Long Sec:	18.120000000004666
UBI:	Not reported
Phone Number:	2064543021

BMC WEST BUILDING MATERIALS (Continued) **1001490781**

Tank ID:	31090
Tank Name:	W-4
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	31102
Tank Name:	W-2
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

BMC WEST BUILDING MATERIALS (Continued) **1001490781**

Tank ID:	31316
Tank Name:	W-3
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

76
SW
1/4-1/2
0.394 mi.
2082 ft.

AGFA GEVAERT INC **RCRA-NonGen** **1000142598**
555 116TH AVE NE **FINDS** **WAD980983126**
BELLEVUE, WA 98004 **ALLSITES**

Relative:
Lower

Actual:
100 ft.

RCRA-NonGen:

Date form received by agency:	11/21/1997
Facility name:	AGFA GEVAERT INC
Facility address:	555 116TH AVE NE BELLEVUE, WA 98004
EPA ID:	WAD980983126
Contact:	KEN DOWD
Contact address:	555 116TH AVE NE BELLEVUE, WA 98004-5205
Contact country:	US
Contact telephone:	(425)454-1066
Contact email:	Not reported
EPA Region:	10
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	AGFA GEVAERT INC
Owner/operator address:	555 116TH AVE NE BELLEVUE, WA 98004
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private

AGFA GEVAERT INC (Continued) **1000142598**

Owner/Operator Type: Owner
Owner/Op start date: 05/02/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110005338036

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:
Facility Id: 18538463
Latitude: 47.6161499
Longitude: -122.1855
Geographic location identifier (alias facid): 18538463
Facility Name: Agfa Gevaert Inc
Latitude Decimal Degrees: 47.616149999999998
Longitude Decimal Degrees: -122.1855
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

S77 **SAFEWAY INC MILK DEPT** **RCRA-CESQG** **1004794644**
NNE **1469 124TH AVE NE** **FINDS** **WAH000000315**
1/4-1/2 **BELLEVUE, WA 98005** **ALLSITES**
0.420 mi. **MANIFEST**
2217 ft. **Site 1 of 2 in cluster S**

Relative:
Higher

Actual:
170 ft.

RCRA-CESQG:

Date form received by agency:	05/20/2008
Facility name:	SAFEWAY INC MILK DEPT
Facility address:	1469 124TH AVE NE BELLEVUE, WA 980052104
EPA ID:	WAH000000315
Contact:	GARY E GILL
Contact address:	1469 124TH AVE NE BELLEVUE, WA 98005-2104
Contact country:	US
Contact telephone:	(425)455-8734
Contact email:	Not reported
EPA Region:	10
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SAFEWAY INC
Owner/operator address:	1469 124TH AVE NE BELLEVUE, WA 98005
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/05/1997
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

SAFEWAY INC MILK DEPT (Continued) **1004794644**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2007
Facility name: SAFEWAY INC MILK DEPT
Classification: Not a generator, verified

Date form received by agency: 12/31/2005
Facility name: SAFEWAY INC MILK DEPT
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: SAFEWAY INC MILK DEPT
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110002347078

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also

SAFEWAY INC MILK DEPT (Continued) **1004794644**

has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

ALLSITES:

Facility Id:	28211346
Latitude:	47.6228899
Longitude:	-122.17507
Geographic location identifier (alias facid):	28211346
Facility Name:	Safeway Inc Milk Dept
Latitude Decimal Degrees:	47.622889999999998
Longitude Decimal Degrees:	-122.17507000000001
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

WA MANIFEST:

Facility Site ID Number:	28211346
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAH000000315
Facility Address 2:	Not reported
TAX REG NBR:	600643518
NAICS CD:	44511
BUSINESS TYPE:	Milk Processing
MAIL NAME:	Safeway Inc.

SAFEWAY INC MILK DEPT (Continued) **1004794644**

MAIL ADDR LINE1:	1469 124TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98005-2104
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Safeway Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1469 124TH AVE NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98005-2104
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	425-455-8734
LEGAL EFFECTIVE DATE:	1/21/1997
LAND ORG NAME:	Safeway Inc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1121 124TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98005-2101
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	425-455-8734
OPERATOR ORG NAME:	Safeway Inc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1121 124TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-2101
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-455-8734
OPERATOR EFFECTIVE DATE:	2/5/1997
SITE CONTACT NAME:	Gary E Gill
SITE CONTACT ADDR LINE1:	1469 124TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98005-2104
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)455-8734
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Gary E Gill
FORM CONTACT ADDR LINE1:	1469 124TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98005-2104
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425455-8734
FORM CONTACT EMAIL:	gary.gill@safeway.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	FALSE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

Facility Site ID Number:	28211346
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported

SAFEWAY INC MILK DEPT (Continued) **1004794644**

Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAH000000315
Facility Address 2:	Not reported
TAX REG NBR:	600643518
NAICS CD:	44511
BUSINESS TYPE:	Milk Processing
MAIL NAME:	Safeway Inc.
MAIL ADDR LINE1:	1469 124TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98005-2104
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Safeway Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1469 124TH AVE NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98005-2104
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	425-455-8734
LEGAL EFFECTIVE DATE:	1/21/1997
LAND ORG NAME:	Safeway Inc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1121 124TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98005-2101
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	425-455-8734
OPERATOR ORG NAME:	Safeway Inc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1121 124TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98005-2101
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-455-8734
OPERATOR EFFECTIVE DATE:	2/5/1997
SITE CONTACT NAME:	Gary E Gill

SAFEWAY INC MILK DEPT (Continued) **1004794644**

SITE CONTACT ADDR LINE1: 1469 124TH AVE NE
SITE CONTACT ZIP: BELLEVUE, WA 98005-2104
SITE CONTACT COUNTRY: UNITED STATES
SITE CONTACT PHONE NBR: (425)455-8734
SITE CONTACT EMAIL: Not reported
FORM CONTACT NAME: Gary E Gill
FORM CONTACT ADDR LINE1: 1469 124TH AVE NE
FORM CONTACT CITY,ST,ZIP: BELLEVUE, WA 98005-2104
FORM CONTACT COUNTRY: UNITED STATES
FORM CONTACT PHONE NBR: 425455-8734
FORM CONTACT EMAIL: gary.gill@safeway.com
GEN STATUS CD: SQG
MONTHLY GENERATION: No
BATCH GENERATION: No
ONE TIME GENERATION: No
TRANSPORTS OWN WASTE: No
TRANSPORTS OTHRS WASTE: No
RECYCLER ONSITE: No
TRANSFER FACILITY: No
OTHER EXEMPTION: Not reported
UW BATTERY GEN: No
USED OIL TRANSPORTER: No
USED OIL TRANSFER FACLTY: No
USED OIL PROCESSOR: No
USED OIL REREFINER: No
USED OIL FUEL MRKTR DIRECTS SHPMNTS: No
USED OIL FUEL MRKTR MEETS SPECS: No

T78 **EASTSIDE MEDICAL LAB BELLEVUE** **RCRA-NonGen** **1000421045**
NW **1199 116TH AVE NE** **FINDS** **WAD063345334**
1/4-1/2 **BELLEVUE, WA 98004** **ALLSITES**
0.424 mi.
2238 ft. **Site 1 of 2 in cluster T**

Relative:
Higher

Actual:
188 ft.

RCRA-NonGen:
Date form received by agency: 01/31/1989
Facility name: EASTSIDE MEDICAL LAB BELLEVUE
Facility address: 1199 116TH AVE NE
BELLEVUE, WA 98004
EPA ID: WAD063345334
Contact: AGGIE MAZA
Contact address: 1199 116TH AVE NE
BELLEVUE, WA 98004-4617
Contact country: US
Contact telephone: (425)454-3975
Contact email: Not reported
EPA Region: 10
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: EASTSIDE MEDICAL LAB
Owner/operator address: 1199 116TH AVE NE
BELLEVUE, WA 98004
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private

EASTSIDE MEDICAL LAB BELLEVUE (Continued) **1000421045**

Owner/Operator Type: Owner
Owner/Op start date: 01/31/1989
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110005324176

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:
Facility Id: 25171287
Latitude: 47.6223099
Longitude: -122.18562
Geographic location identifier (alias facid): 25171287
Facility Name: Eastside Medical Lab Bellevue
Latitude Decimal Degrees: 47.622309999999999
Longitude Decimal Degrees: -122.18562
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

U79 **FIBRES INTERNATIONAL INC** **LUST** **U003027335**
North **1533 120TH AVE NE** **UST** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.424 mi.
2241 ft. **Site 1 of 3 in cluster U**

Relative:
Higher

Actual:
177 ft.

LUST:

FS ID:	42828674
Cleanup Site ID:	6061
Cleanup Unit Type:	Upland
Process Type:	Voluntary Cleanup Program
Facility Status:	Cleanup Started
Alternate Name:	FIBRES INTERNATIONAL
Release Notification Date:	Not reported
Release Status Date:	02/05/1996
Site Response Unit Code:	Northwest
Lat/Long:	47.6254410 / -122.18060

FS ID:	42828674
Cleanup Site ID:	6061
Cleanup Unit Type:	Upland
Process Type:	Voluntary Cleanup Program
Facility Status:	RCU
Alternate Name:	FIBRES INTERNATIONAL
Release Notification Date:	Not reported
Release Status Date:	07/25/1996
Site Response Unit Code:	Northwest
Lat/Long:	47.6254410 / -122.18060

UST:

Facility ID:	42828674
Site ID:	5357
Lat Deg:	47
Lat Min:	37
Lat Sec:	31.587600000007683
Long Deg:	-122
Long Min:	10
Long Sec:	50.174400000008745
UBI:	6023911690010001
Phone Number:	4254558535

Tank ID:	142
Tank Name:	2-"UNLEADED"
Install Date:	1/15/1975
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported

FIBRES INTERNATIONAL INC (Continued) **U003027335**

Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: a8542

Tank ID: 27353
Tank Name: 1-"DIESEL"
Install Date: 6/1/1980
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Suction System Tank Check Valve
Tank Spill Prevention: None
Tank Overfill Prevention: None
Tank Material: Not reported
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: None
Pipe Material: Not reported
Pipe Construction: Single Wall Pipe
Pipe Primary Release Detection: Suction
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: None
Tank Primary Release Detection: Weekly Manual Gauging
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: a8542

Tank ID: 33878
Tank Name: 3-"LEADED"
Install Date: 1/15/1975
Capacity: 111 TO 1,100 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Suction System Tank Check Valve
Tank Spill Prevention: None
Tank Overfill Prevention: None
Tank Material: Not reported
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: None

FIBRES INTERNATIONAL INC (Continued) **U003027335**

Pipe Material: Not reported
Pipe Construction: Single Wall Pipe
Pipe Primary Release Detection: Suction
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: None
Tank Primary Release Detection: Weekly Manual Gauging
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: a8542

Tank ID: 354173
Tank Name: #1-DIESEL
Install Date: 1/12/1996
Capacity: 5,000 to 9,999 Gallons
Tank Upgrade Date: 1/12/1996
TankSystem Status: Operational
TankSystem Status Change Date: 8/26/1996
Tank Status: Operational
Tank Permit Expiration Date: 4/30/2012
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Spill Bucket/Spill Box
Tank Overfill Prevention: Overfill Alarm
Tank Material: Coated Steel
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: Sacrificial Anode
Pipe Material: Flexible Piping
Pipe Construction: Double Wall Pipe
Pipe Primary Release Detection: Suction
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Corrosion Resistant
Tank Primary Release Detection: Automatic Tank Gauging
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: a8542

Tank ID: 354174
Tank Name: #2-UNLEADED
Install Date: 1/12/1996
Capacity: Not reported
Tank Upgrade Date: 1/12/1996
TankSystem Status: Operational
TankSystem Status Change Date: 8/26/1996
Tank Status: Operational
Tank Permit Expiration Date: 4/30/2012
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Spill Bucket/Spill Box
Tank Overfill Prevention: Overfill Alarm
Tank Material: Coated Steel
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported

FIBRES INTERNATIONAL INC (Continued) **U003027335**

Tank Corrosion Protection:	Sacrificial Anode
Pipe Material:	Flexible Piping
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Suction
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Automatic Tank Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	a8542

U80 **FIBRES INTERNATIONAL, INC.** **ICR** **1001820133**
North **1533 120TH AVE. NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.424 mi.
2241 ft. **Site 2 of 3 in cluster U**

Relative:
Higher

Actual:
177 ft.

ICR:

Date Ecology Received Report:	07/25/96
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	94-32
County Code:	17
Contact:	Not reported
Report Title:	Not reported

U81 **FIBRES INTERNATIONAL INC** **CSCSL** **1000812899**
North **1533 120TH AVE NE** **ALLSITES** **N/A**
1/4-1/2 **BELLEVUE, WA 98005** **VCP**
0.424 mi. **FINANCIAL ASSURANCE**
2241 ft. **Site 3 of 3 in cluster U**

Relative:
Higher

Actual:
177 ft.

CSCSL:

Facility ID:	42828674
Region:	Northwest
Lat/Long:	47.625441000000 / -122.180604
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	6061
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	C
Surface Water:	Not reported
Soil:	Not reported
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	42828674
Region:	Northwest

FIBRES INTERNATIONAL INC (Continued) **1000812899**

Lat/Long: 47.625441000000 / -122.180604
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 6061
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Diesel
Ground Water: C
Surface Water: Not reported
Soil: Not reported
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 42828674
Region: Northwest
Lat/Long: 47.625441000000 / -122.180604
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 6061
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Gasoline
Ground Water: C
Surface Water: Not reported
Soil: Not reported
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 42828674
Region: Northwest
Lat/Long: 47.625441000000 / -122.180604
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 6061
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Other
Ground Water: Not reported
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 42828674
Latitude: 47.6254410
Longitude: -122.18060
Geographic location identifier (alias facid): 42828674
Facility Name: Fibres International Inc
Latitude Decimal Degrees: 47.625441000000002
Longitude Decimal Degrees: -122.180604

FIBRES INTERNATIONAL INC (Continued) **1000812899**

Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 6
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

VCP:
edr_fstat: WA
edr_fzip: 98005
edr_fcnty: KING COUNTY
edr_zip: Not reported
Facility ID: 42828674
VCP Status: VCP
VCP: Not reported
Ecology Status: Cleanup Started
NFA Type: Cleanup Started
Date NFA: Cleanup Started
Rank: Cleanup Started

WA FINANCIAL ASSURANCE:
edr_fstat: WA
edr_fzip: 98005
edr_fcnty: Not reported
edr_zip: Not reported
DOE Site ID: 5357
Site Type: Other Ins
Financial Resp Type: Zurich
Inception Date: 12/01/2010
Expiration Date: 12/01/2011

S82 **SAFEWAY INC BELLEVUE BEVERAGE** **ALLSITES** **S109556767**
NNE **1500 124TH AVE NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.426 mi.
2252 ft. **Site 2 of 2 in cluster S**

Relative:
Higher

Actual:
169 ft.

ALLSITES:
Facility Id: 78267881
Latitude: 47.6231300
Longitude: -122.17503
Geographic location identifier (alias facid): 78267881
Facility Name: Safeway Inc Bellevue Beverage
Latitude Decimal Degrees: 47.623130000000003
Longitude Decimal Degrees: -122.17503000000001
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

T83
NW
1/4-1/2
0.431 mi.
2275 ft.

LABCORP DYNACARE LABORATORIES
1200 116TH AVE NE STE G
YARROW POINT, WA 98004

Site 2 of 2 in cluster T

ALLSITES **S110124152**
N/A

Relative:
Higher

Actual:
187 ft.

ALLSITES:

Facility Id:	24472	
Latitude:	47.6212170	
Longitude:	-122.18502	
Geographic location identifier (alias facid):		24472
Facility Name:		LabCorp Dynacare Laboratories
Latitude Decimal Degrees:		47.621217000000001
Longitude Decimal Degrees:		-122.185028
Coordinate Point Areal Extent Code:		0
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported
Geographic Location Identifier (Alias Facid):		24472
Interaction (Aka Env Int) Type Code:		LSC
Interaction (Aka Env Int) Description:		Local Source Control
Interaction Status:		I
Federal Program Indentifier:		Not reported
Interaction Start Date:		11/17/2008
Interaction End Date:		04/29/2010
prgm_facil:		LabCorp Dynacare Laboratories
cur_sys_pr:		HAZWASTE
cur_sys_nm:		LSC

84
NW
1/4-1/2
0.440 mi.
2326 ft.

OVERLAKE MOB
1232 116TH AVE NE
BELLEVUE, WA 98004

ALLSITES **S110038603**
N/A

Relative:
Higher

Actual:
186 ft.

ALLSITES:

Facility Id:	21052	
Latitude:	47.6231000	
Longitude:	-122.185	
Geographic location identifier (alias facid):		21052
Facility Name:		OVERLAKE MOB
Latitude Decimal Degrees:		47.623100000000001
Longitude Decimal Degrees:		-122.185
Coordinate Point Areal Extent Code:		0
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		0
Location Verified Code:		Not reported
Geographic Location Identifier (Alias Facid):		21052
Interaction (Aka Env Int) Type Code:		CONSTGP
Interaction (Aka Env Int) Description:		Construction SW GP
Interaction Status:		A
Federal Program Indentifier:		WAR011637
Interaction Start Date:		07/01/2009
Interaction End Date:		Not reported
prgm_facil:		OVERLAKE MOB
cur_sys_pr:		WATQUAL
cur_sys_nm:		PARIS

V85 **PRINTEX PRESS** **ALLSITES** **S109555132**
NNE **1600 124TH AVE NE STE E** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.445 mi.
2352 ft. **Site 1 of 2 in cluster V**

Relative:
Higher

Actual:
165 ft.

ALLSITES:

Facility Id:	3691728	
Latitude:	47.6240219	
Longitude:	-122.17505	
Geographic location identifier (alias facid):		3691728
Facility Name:		Printex Press
Latitude Decimal Degrees:		47.624021999999997
Longitude Decimal Degrees:		-122.175056
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported

W86 **EUROPA IMPORTED SERVICE LLC** **ALLSITES** **S109824608**
ENE **12700 BEL RED RD** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.448 mi.
2365 ft. **Site 1 of 6 in cluster W**

Relative:
Lower

Actual:
133 ft.

ALLSITES:

Facility Id:	57134128	
Latitude:	47.6215520	
Longitude:	-122.17075	
Geographic location identifier (alias facid):		57134128
Facility Name:		Motorworks Ltd
Latitude Decimal Degrees:		47.621552000000001
Longitude Decimal Degrees:		-122.170753
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported

Facility Id:	1451	
Latitude:	47.6182073	
Longitude:	-122.17073	
Geographic location identifier (alias facid):		1451
Facility Name:		Europa Imported Service LLC
Latitude Decimal Degrees:		47.618207302800002
Longitude Decimal Degrees:		-122.17073936200001
Coordinate Point Areal Extent Code:		0
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported

Geographic Location Identifier (Alias Facid):	1451
Interaction (Aka Env Int) Type Code:	LSC
Interaction (Aka Env Int) Description:	Local Source Control
Interaction Status:	I
Federal Program Indentifier:	Not reported
Interaction Start Date:	06/19/2009
Interaction End Date:	04/29/2010
prgm_facil:	Europa Imported Service LLC

EUROPA IMPORTED SERVICE LLC (Continued) **S109824608**

cur_sys_pr: HAZWASTE
cur_sys_nm: LSC

W87 **TRIVESTOR'S PARTNERSHIP** **ICR** **S104485104**
ENE **12700 BEL-RED ROAD** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.448 mi.
2365 ft. **Site 2 of 6 in cluster W**

Relative:
Lower

Actual:
133 ft.

ICR:

Date Ecology Received Report:	08/03/98
Contaminants Found at Site:	Metals, Petroleum products
Media Contaminated:	Soil
Waste Management:	Not reported
Region:	North Western
Type of Report Ecology Received:	Not reported
Site Register Issue:	98-06
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	04/08/94
Contaminants Found at Site:	Metals, Petroleum products
Media Contaminated:	Soil, Sediment
Waste Management:	Spill, Handling practices
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	93-25
County Code:	17
Contact:	Not reported
Report Title:	Not reported

W88 **MERCEDES CENTRUM INC** **ALLSITES** **S109823971**
ENE **12700 BEL RED RD STE 8** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.448 mi.
2365 ft. **Site 3 of 6 in cluster W**

Relative:
Lower

Actual:
133 ft.

ALLSITES:

Facility Id:	19610	
Latitude:	47.6208038	
Longitude:	-122.17077	
Geographic location identifier (alias facid):		19610
Facility Name:		Mercedes Centrum Inc
Latitude Decimal Degrees:		47.620803856800002
Longitude Decimal Degrees:		-122.17077310400001
Coordinate Point Areal Extent Code:		0
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported

Geographic Location Identifier (Alias Facid):	19610
Interaction (Aka Env Int) Type Code:	LSC
Interaction (Aka Env Int) Description:	Local Source Control
Interaction Status:	I

MERCEDES CENTRUM INC (Continued) **S109823971**

Federal Program Indentifier:	Not reported
Interaction Start Date:	03/26/2009
Interaction End Date:	04/29/2010
prgm_facil:	Mercedes Centrum Inc
cur_sys_pr:	HAZWASTE
cur_sys_nm:	LSC

W89 **BALDWIN & SONS** **ALLSITES** **S109823972**
ENE **12700 BEL RED RD** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.448 mi.
2365 ft. **Site 4 of 6 in cluster W**

Relative:
Lower

Actual:
133 ft.

ALLSITES:

Facility Id:	14012	
Latitude:	47.6208038	
Longitude:	-122.17077	
Geographic location identifier (alias facid):		14012
Facility Name:		Baldwin & Sons
Latitude Decimal Degrees:		47.620803856800002
Longitude Decimal Degrees:		-122.17077310400001
Coordinate Point Areal Extent Code:		0
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported
Geographic Location Identifier (Alias Facid):		14012
Interaction (Aka Env Int) Type Code:		LSC
Interaction (Aka Env Int) Description:		Local Source Control
Interaction Status:		I
Federal Program Indentifier:		Not reported
Interaction Start Date:		03/26/2009
Interaction End Date:		04/29/2010
prgm_facil:		Baldwin & Sons
cur_sys_pr:		HAZWASTE
cur_sys_nm:		LSC

W90 **BIGGS EASTSIDE AUTOMOTIVE** **ALLSITES** **S109824031**
ENE **12700 BEL RED RD** **N/A**
1/4-1/2 **BELLEVUE, WA 98005**
0.448 mi.
2365 ft. **Site 5 of 6 in cluster W**

Relative:
Lower

Actual:
133 ft.

ALLSITES:

Facility Id:	23457	
Latitude:	47.6208038	
Longitude:	-122.17077	
Geographic location identifier (alias facid):		23457
Facility Name:		Biggs Eastside Automotive
Latitude Decimal Degrees:		47.620803856800002
Longitude Decimal Degrees:		-122.17077310400001
Coordinate Point Areal Extent Code:		0
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8

BIGGS EASTSIDE AUTOMOTIVE (Continued) **S109824031**

Location Verified Code:	Not reported
Geographic Location Identifier (Alias Facid):	23457
Interaction (Aka Env Int) Type Code:	LSC
Interaction (Aka Env Int) Description:	Local Source Control
Interaction Status:	I
Federal Program Indentifier:	Not reported
Interaction Start Date:	03/26/2009
Interaction End Date:	04/29/2010
prgm_facil:	Biggs Eastside Automotive
cur_sys_pr:	HAZWASTE
cur_sys_nm:	LSC

W91 **TRIVESTORS PARTNERSHIP PROPERTY** **ALLSITES** **S104971792**
ENE **12700 NE BEL RED RD** **CSCSL NFA** **N/A**
1/4-1/2 **BELLEVUE, WA 98005** **VCP**
0.448 mi.
2365 ft. **Site 6 of 6 in cluster W**

Relative:
Lower

Actual:
133 ft.

ALLSITES:

Facility Id:	2403
Latitude:	47.6209300
Longitude:	-122.17098
Geographic location identifier (alias facid):	2403
Facility Name:	TRIVESTORS PARTNERSHIP PROPERTY
Latitude Decimal Degrees:	47.620930000000001
Longitude Decimal Degrees:	-122.17098
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N
Geographic Location Identifier (Alias Facid):	2403
Interaction (Aka Env Int) Type Code:	VOLCLNST
Interaction (Aka Env Int) Description:	Voluntary Cleanup Sites
Interaction Status:	I
Federal Program Indentifier:	Not reported
Interaction Start Date:	01/01/1900
Interaction End Date:	09/14/1998
prgm_facil:	TRIVESTORS PARTNERSHIP PROPERTY
cur_sys_pr:	TOXICS
cur_sys_nm:	ISIS

CSCSL NFA:

Facility/Site Id:	2403
CS Id:	2932
NFA Type:	NFA-VCP Review
NFA Date:	08/18/1998
Rank:	Not reported

VCP:

edr_fstat:	WA
edr_fzip:	98005
edr_fcnty:	KING COUNTY
edr_zip:	Not reported

TRIVESTORS PARTNERSHIP PROPERTY (Continued) **S104971792**

Facility ID: 2403
VCP Status: Not reported
VCP: Y
Ecology Status: Not reported
NFA Type: NFA-VCP Review
Date NFA: 08/18/1998
Rank: Not reported

X92 **CHEVROLET OF BELLEVUE** **RCRA-CESQG** **1000333289**
SW **430 116TH AVE NE** **FINDS** **WAD027259225**
1/4-1/2 **BELLEVUE, WA 98004** **CSCSL**
0.449 mi. **ALLSITES**
2372 ft. **Site 1 of 6 in cluster X** **VCP**

Relative:
Lower

Actual:
86 ft.

RCRA-CESQG:
Date form received by agency: 02/19/2004
Facility name: CHEVROLET OF BELLEVUE
Facility address: 430 116TH AVE NE
BELLEVUE, WA 98004
EPA ID: WAD027259225
Contact: LONNIE ROBINETT
Contact address: 430 116TH AVE NE
BELLEVUE, WA 98004-5209
Contact country: US
Contact telephone: (425)454-8931
Contact email: Not reported
EPA Region: 10
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: BELLEVUE MOTORS INC
Owner/operator address: 430 116TH AVE NE
BELLEVUE, WA 98004
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 06/14/1999
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

CHEVROLET OF BELLEVUE (Continued) **1000333289**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 12/31/2003
Facility name: CHEVROLET OF BELLEVUE
Classification: Not a generator, verified

Date form received by agency: 03/31/1994
Facility name: CHEVROLET OF BELLEVUE
Site name: BROOKS MCKNIGHT CHEVROLET GEO
Classification: Large Quantity Generator

Date form received by agency: 09/01/1993
Facility name: CHEVROLET OF BELLEVUE
Site name: BROOKS MCKNIGHT CHEVROLET INC.
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110005316345

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CSCSL:

Facility ID: 33818696
Region: Northwest
Lat/Long: 47.61477 / -122.18552

CHEVROLET OF BELLEVUE (Continued) **1000333289**

Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	5893
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	33818696
Region:	Northwest
Lat/Long:	47.61477 / -122.18552
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	5893
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Methyl tertiary-butyl ether
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	33818696
Region:	Northwest
Lat/Long:	47.61477 / -122.18552
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	5893
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Non-Halogenated Solvents
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	33818696
Region:	Northwest
Lat/Long:	47.61477 / -122.18552
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	5893
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Diesel

CHEVROLET OF BELLEVUE (Continued) **1000333289**

Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest
Facility ID:	33818696
Region:	Northwest
Lat/Long:	47.61477 / -122.18552
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	5893
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Gasoline
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest
Facility ID:	33818696
Region:	Northwest
Lat/Long:	47.61477 / -122.18552
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	5893
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Other
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

ALLSITES:

Facility Id:	33818696
Latitude:	47.61477
Longitude:	-122.18552
Geographic location identifier (alias facid):	33818696
Facility Name:	Chevrolet of Bellevue
Latitude Decimal Degrees:	47.61477
Longitude Decimal Degrees:	-122.18552
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

CHEVROLET OF BELLEVUE (Continued) **1000333289**

VCP:
- edr_fstat: WA
- edr_fzip: 98004
- edr_fcnty: KING COUNTY
- edr_zip: Not reported
- Facility ID: 33818696
- VCP Status: VCP
- VCP: Not reported
- Ecology Status: Cleanup Started
- NFA Type: Cleanup Started
- Date NFA: Cleanup Started
- Rank: Cleanup Started

X93 **CHEVROLET OF BELLEVUE** **LUST U004020867**
SW **430 116TH AVE NE** **UST N/A**
1/4-1/2 **BELLEVUE, WA 98004**
0.449 mi.
2372 ft. **Site 2 of 6 in cluster X**

Relative:
Lower

Actual:
86 ft.

LUST:
- FS ID: 33818696
- Cleanup Site ID: 5893
- Cleanup Unit Type: Upland
- Process Type: Voluntary Cleanup Program
- Facility Status: Cleanup Started
- Alternate Name: BROOKS MCKNIGHT CHEVROLET
- Release Notification Date: Not reported
- Release Status Date: 11/16/1995
- Site Response Unit Code: Northwest
- Lat/Long: 47.61477 / -122.18552

UST:
- Facility ID: 33818696
- Site ID: 1308
- Lat Deg: 47
- Lat Min: 36
- Lat Sec: 53.172000000000139
- Long Deg: -122
- Long Min: 11
- Long Sec: 7.8719999999884749
- UBI: 6015475780010001
- Phone Number: 4254270101

- Tank ID: 318440
- Tank Name: 6
- Install Date: 8/23/1994
- Capacity: 111 TO 1,100 Gallons
- Tank Upgrade Date: 8/23/1994
- TankSystem Status: Removed
- TankSystem Status Change Date: 10/15/2007
- Tank Status: Removed
- Tank Permit Expiration Date: 2/29/2004
- Tank Closure Date: 10/5/2007
- Tank Pumping System: Suction System Pump Check Valve
- Tank Spill Prevention: Spill Bucket/Spill Box
- Tank Overfill Prevention: Automatic Shutoff (fill pipe)
- Tank Material: Fiberglass Reinforced Plastic

CHEVROLET OF BELLEVUE (Continued) **U004020867**

Tank Construction:	Double Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Suction
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Manual Inventory Control (daily)
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not Required
Tank Actual Status Date:	7/28/2007
Tag Number:	A8076

Tank ID:	38923
Tank Name:	3
Install Date:	1/1/1970
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/2000
TankSystem Status:	Closed in Place
TankSystem Status Change Date:	4/30/1999
Tank Status:	Closed in Place
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Gravity Delivery System (No Pump)
Tank Spill Prevention:	25 Gallons or Less
Tank Overfill Prevention:	25 Gallons or less
Tank Material:	Not reported
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not Performed
Tank Corrosion Protection:	None
Pipe Material:	No Piping Attached to Tank
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Groundwater Monitoring
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A8076

Tank ID:	38979
Tank Name:	1
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported

CHEVROLET OF BELLEVUE (Continued) **U004020867**

Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A8076

Tank ID:	39011
Tank Name:	4
Install Date:	8/21/1989
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Gravity Delivery System (No Pump)
Tank Spill Prevention:	None
Tank Overfill Prevention:	Automatic Shutoff (fill pipe)
Tank Material:	Fiberglass Reinforced Plastic
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Corrosion Resistant
Pipe Material:	Fiberglass
Pipe Construction:	Double Wall Pipe
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Corrosion Resistant
Tank Primary Release Detection:	Statistical Inventory Reconciliation
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	8/6/1996
Tag Number:	A8076

Tank ID:	39060
Tank Name:	2
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported

CHEVROLET OF BELLEVUE (Continued) **U004020867**

Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	A8076

X94 **BROOKS MCKNIGHT CHEVROLET** **ICR** **S104485199**
SW **430 116TH AVE. NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98004**
0.449 mi.
2372 ft. **Site 3 of 6 in cluster X**

Relative:
Lower

Actual:
86 ft.

ICR:

Date Ecology Received Report:	09/08/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-09
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	12/11/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-13
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	01/21/99
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater
Waste Management:	Not reported
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-12
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	06/19/95
Contaminants Found at Site:	Petroleum products

BROOKS MCKNIGHT CHEVROLET (Continued) **S104485199**

Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-13
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	12/12/00
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-33
County Code:	17
Contact:	Not reported
Report Title:	Results of Ground Water Monitoring - August & November 2000

Date Ecology Received Report:	06/15/00
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-28
County Code:	17
Contact:	Not reported
Report Title:	Results of Ground Water Monitoring - February & May 2000

V95 **SAFEWAY WAREHOUSE INC DIST CENTER** **ALLSITES** **S109554325**
NNE **1723 124TH AVE NE** **CSCSL NFA** **N/A**
1/4-1/2 **BELLEVUE, WA 98005** **VCP**
0.450 mi. **NPDES**
2379 ft. **Site 2 of 2 in cluster V**

Relative: Higher

Actual: 164 ft.

ALLSITES:

Facility Id:	35844253	
Latitude:	47.6239492	
Longitude:	-122.17677	
Geographic location identifier (alias facid):		35844253
Facility Name:		SAFEWAY WAREHOUSE INC DIST CENTER
Latitude Decimal Degrees:		47.624124000000002
Longitude Decimal Degrees:		-122.17506299999999
Coordinate Point Areal Extent Code:		0
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported

CSCSL NFA:

Facility/Site Id:	35844253
CS Id:	7078
NFA Type:	NFA-VCP Review
NFA Date:	04/20/2009
Rank:	Not reported

SAFEWAY WAREHOUSE INC DIST CENTER (Continued) **S109554325**

VCP:

edr_fstat:	WA
edr_fzip:	98005
edr_fcnty:	KING COUNTY
edr_zip:	Not reported
Facility ID:	35844253
VCP Status:	Not reported
VCP:	Y
Ecology Status:	Not reported
NFA Type:	NFA-VCP Review
Date NFA:	04/20/2009
Rank:	Not reported

NPDES:

Facility Status:	Active
Facility Type:	Industrial SW GP
Admin Region:	Headquarters
Latitude:	47.62394920
Longitude:	-122.176771
Permit ID:	WAR002354
Permit Version:	5
Permit Status:	Active
Permit SubStatus:	Coverage Issued
Ecology Contact:	Greg Stegman
WRIA:	Cedar-Sammamish
Permit Expiration Date:	01/01/2015
Effective Date:	01/01/2010

Y96 **FORD MOTOR COMPANY** **ICR** **S104782925**
SW **411 116TH NE** **N/A**
1/4-1/2 **BELLEVUE, WA 98004**
0.453 mi.
2390 ft. **Site 1 of 2 in cluster Y**

Relative:
Lower

Actual:
89 ft.

ICR:

Date Ecology Received Report:	09/06/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Final cleanup report
Site Register Issue:	92-08
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	04/19/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	91-27
County Code:	17
Contact:	Not reported
Report Title:	Not reported

FORD MOTOR COMPANY (Continued) **S104782925**

Date Ecology Received Report:	08/10/00
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-28
County Code:	17
Contact:	Not reported
Report Title:	Limited Phase II Subsurface Investigation

Y97 **FORD OF BELLEVUE** **RCRA-NonGen** **1000388933**
SW **411 116TH AVE NE** **FINDS** **WAD051239341**
1/4-1/2 **BELLEVUE, WA 98004** **ALLSITES**
0.453 mi. **CSCSL NFA**
2390 ft. **Site 2 of 2 in cluster Y** **UST**
MANIFEST
Relative: **VCP**
Lower **HAZNET**

Actual: **89 ft.**

RCRA-NonGen:

Date form received by agency:	04/17/2007
Facility name:	FORD OF BELLEVUE
Facility address:	411 116TH AVE NE BELLEVUE, WA 980045299
EPA ID:	WAD051239341
Contact:	TODD COFFER
Contact address:	411 116TH AVE NE BELLEVUE, WA 98004-5210
Contact country:	US
Contact telephone:	(425)454-2454
Contact email:	Not reported
EPA Region:	10
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	GARY DIXON
Owner/operator address:	411 116TH AVE NE BELLEVUE, WA 98004
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	08/20/1996
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

FORD OF BELLEVUE (Continued) **1000388933**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2005
Facility name: FORD OF BELLEVUE
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: FORD OF BELLEVUE
Classification: Not a generator, verified

Date form received by agency: 03/01/1996
Facility name: FORD OF BELLEVUE
Site name: PRESTIGE FORD
Classification: Large Quantity Generator

Date form received by agency: 03/31/1994
Facility name: FORD OF BELLEVUE
Site name: PRESTIGE FORD
Classification: Large Quantity Generator

Date form received by agency: 09/01/1993
Facility name: FORD OF BELLEVUE
Site name: PRESTIGE FORD
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: SR - 630(7)
Area of violation: Generators - General
Date violation determined: 11/05/1996
Date achieved compliance: 11/11/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/05/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - 200(1)(c)(d)
Area of violation: Generators - General
Date violation determined: 11/05/1996
Date achieved compliance: 11/13/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/05/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

FORD OF BELLEVUE (Continued) **1000388933**

Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - 200(1)(c)(d)
Area of violation: Generators - General
Date violation determined: 11/05/1996
Date achieved compliance: 11/15/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/05/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Regulation violated: SR - 200(1)(c)(d
Area of violation: Generators - General
Date violation determined: 11/05/1996
Date achieved compliance: 11/13/1996
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/05/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 0
Final penalty amount: 0
Paid penalty amount: 0

Evaluation Action Summary:
Evaluation date: 11/05/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/13/1996
Evaluation lead agency: State

Evaluation date: 11/05/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/15/1996
Evaluation lead agency: State

Evaluation date: 11/05/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/11/1996
Evaluation lead agency: State

FINDS:

Registry ID: 110000827963

Environmental Interest/Information System

FORD OF BELLEVUE (Continued) **1000388933**

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ALLSITES:

Facility Id:	93571261	
Latitude:	47.6144600	
Longitude:	-122.18676	
Geographic location identifier (alias facid):		93571261
Facility Name:		Ford Of Bellevue
Latitude Decimal Degrees:		47.614460000000001
Longitude Decimal Degrees:		-122.186761
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		6
Coordinate Point Geographic Position Code:		8
Location Verified Code:		N

CSCSL NFA:

Facility/Site Id:	93571261
CS Id:	6891
NFA Type:	NFA-VCP Review
NFA Date:	09/13/2007
Rank:	Not reported

UST:

Facility ID:	93571261
Site ID:	30
Lat Deg:	47
Lat Min:	36
Lat Sec:	52.056000000004019
Long Deg:	-122
Long Min:	11
Long Sec:	12.339600000015025
UBI:	Not reported
Phone Number:	2064542454
Tank ID:	30909
Tank Name:	1
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed

FORD OF BELLEVUE (Continued) **1000388933**

TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

WA MANIFEST:

Facility Site ID Number:	93571261
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD051239341
Facility Address 2:	Not reported
TAX REG NBR:	601968764
NAICS CD:	44111

FORD OF BELLEVUE (Continued) **1000388933**

BUSINESS TYPE:	Not reported
MAIL NAME:	Ford of Bellevue
MAIL ADDR LINE1:	411 116TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-5210
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Auto Nation
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	411 116th Ave NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-5210
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)454-2454
LEGAL EFFECTIVE DATE:	9/1/1999
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Gary Dixon
LAND ADDR LINE1:	411 116TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004-5210
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)454-2454
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	411 116TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-5210
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)454-2454
OPERATOR EFFECTIVE DATE:	8/20/1996
SITE CONTACT NAME:	Todd Coffer
SITE CONTACT ADDR LINE1:	411 116TH AVE NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004-5210
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	425454-2454 2240
SITE CONTACT EMAIL:	coffert@autonation.com
FORM CONTACT NAME:	Bill Balyeat
FORM CONTACT ADDR LINE1:	411 116TH AVE NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004-5210
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	425454-2454 2240
FORM CONTACT EMAIL:	balyeatw@autonation.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	FALSE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE
Facility Site ID Number:	93571261
SWC Desc:	Not reported

FORD OF BELLEVUE (Continued) **1000388933**

FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD051239341
Facility Address 2:	Not reported
TAX REG NBR:	601968764
NAICS CD:	44111
BUSINESS TYPE:	Not reported
MAIL NAME:	Ford of Bellevue
MAIL ADDR LINE1:	411 116TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-5210
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Auto Nation
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	411 116th Ave NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-5210
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)454-2454
LEGAL EFFECTIVE DATE:	9/1/1999
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Gary Dixon
LAND ADDR LINE1:	411 116TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004-5210
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)454-2454
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	411 116TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-5210
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)454-2454

FORD OF BELLEVUE (Continued) **1000388933**

OPERATOR EFFECTIVE DATE: 8/20/1996
SITE CONTACT NAME: David Werner
SITE CONTACT ADDR LINE1: 411 116TH AVE NE
SITE CONTACT ZIP: BELLEVUE, WA 98004-5210
SITE CONTACT COUNTRY: UNITED STATES
SITE CONTACT PHONE NBR: 425454-2454 2240
SITE CONTACT EMAIL: Not reported
FORM CONTACT NAME: Duane Delavallade
FORM CONTACT ADDR LINE1: 411 116TH AVE NE
FORM CONTACT CITY,ST,ZIP: BELLEVUE, WA 98004-5210
FORM CONTACT COUNTRY: UNITED STATES
FORM CONTACT PHONE NBR: 425454-2454 2240
FORM CONTACT EMAIL: marilyn@kpaonline.com
GEN STATUS CD: SQG
MONTHLY GENERATION: No
BATCH GENERATION: No
ONE TIME GENERATION: No
TRANSPORTS OWN WASTE: No
TRANSPORTS OTHRS WASTE: No
RECYCLER ONSITE: No
TRANSFER FACILITY: No
OTHER EXEMPTION: Not reported
UW BATTERY GEN: No
USED OIL TRANSPORTER: No
USED OIL TRANSFER FACLTY: No
USED OIL PROCESSOR: No
USED OIL REREFINER: No
USED OIL FUEL MRKTR DIRECTS SHPMNTS: No
USED OIL FUEL MRKTR MEETS SPECS: No

VCP:
edr_fstat: WA
edr_fzip: 98004
edr_fcnty: KING COUNTY
edr_zip: Not reported
Facility ID: 93571261
VCP Status: Not reported
VCP: Y
Ecology Status: Not reported
NFA Type: NFA-VCP Review
Date NFA: 09/13/2007
Rank: Not reported

HAZNET:
Year: 1995
Gepaid: WAD051239341
Contact: GARY DIXON
Telephone: 2064542454
Mailing Name: Not reported
Mailing Address: 411 116TH AVE NE
Mailing City,St,Zip: BELLEVUE, WA 980045210
Gen County: 99
TSD EPA ID: CAD009452657
TSD County: San Mateo
Waste Category: Unspecified organic liquid mixture
Disposal Method: R01

FORD OF BELLEVUE (Continued) **1000388933**

Tons: 5.7545
Facility County: 99

X98 **LINCOLN MERCURY OF BELLEVUE** **RCRA-NonGen** **1000282274**
SW **420 116TH AVE NE** **FINDS** **WAD981763576**
1/4-1/2 **BELLEVUE, WA 98004** **ICR**
0.454 mi.
2398 ft. **Site 4 of 6 in cluster X**

Relative:
Lower

Actual:
85 ft.

RCRA-NonGen:
Date form received by agency: 03/02/2005
Facility name: LINCOLN MERCURY OF BELLEVUE
Facility address: 420 116TH AVE NE
BELLEVUE, WA 98004
EPA ID: WAD981763576
Contact: FRANK BARTON
Contact address: 420 116TH AVE NE
BELLEVUE, WA 98004-5209
Contact country: US
Contact telephone: (425)454-9585
Contact email: Not reported
EPA Region: 10
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: FRANK BARTON
Owner/operator address: 420 116TH AVE NE
BELLEVUE, WA 98004
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1986
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2003
Facility name: LINCOLN MERCURY OF BELLEVUE

LINCOLN MERCURY OF BELLEVUE (Continued) **1000282274**

Classification: Not a generator, verified

Date form received by agency: 03/31/1994
Facility name: LINCOLN MERCURY OF BELLEVUE
Site name: BELLEVUE LINCOLN MERCURY INC.
Classification: Large Quantity Generator

Date form received by agency: 09/01/1993
Facility name: LINCOLN MERCURY OF BELLEVUE
Site name: BELLEVUE LINCOLN MERCURY
Classification: Large Quantity Generator

Date form received by agency: 12/31/1990
Facility name: LINCOLN MERCURY OF BELLEVUE
Site name: BELLEVUE LINCOLN MERCURY
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110005340871

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ICR:

Date Ecology Received Report: / /
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 95-12
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 05/22/98
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank

LINCOLN MERCURY OF BELLEVUE (Continued) **1000282274**

Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	02/10/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	11/26/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	08/06/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	05/07/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	02/07/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report

LINCOLN MERCURY OF BELLEVUE (Continued) **1000282274**

Site Register Issue: 98-05
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 01/30/97
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-05
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 05/12/95
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-05
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: / /
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-11
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 09/18/96
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-14
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 07/17/92
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-39
County Code: 17

LINCOLN MERCURY OF BELLEVUE (Continued) **1000282274**

Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	10/12/94
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	93-36
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	12/23/94
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	93-42
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	10/02/99
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-31
County Code:	17
Contact:	Not reported
Report Title:	Monitoring - September 1999

X99 **LINCOLN MERCURY OF BELLEVUE** **ALLSITES** **U004021011**
SW **420 116TH AVE NE** **LUST** **N/A**
1/4-1/2 **BELLEVUE, WA 98004** **UST**
0.454 mi.
2398 ft. **Site 5 of 6 in cluster X**

Relative:
Lower

Actual:
85 ft.

ALLSITES:

Facility Id:	52413526	
Latitude:	47.6145777	
Longitude:	-122.18516	
Geographic location identifier (alias facid):		52413526
Facility Name:		Lincoln Mercury of Bellevue
Latitude Decimal Degrees:		47.614577776200001
Longitude Decimal Degrees:		-122.185167607
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		6
Coordinate Point Geographic Position Code:		8
Location Verified Code:		Not reported

LUST:

LINCOLN MERCURY OF BELLEVUE (Continued) **U004021011**

FS ID:	52413526
Cleanup Site ID:	9539
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	BELLEVUE LINCOLN MERCURY
Release Notification Date:	Not reported
Release Status Date:	06/01/1995
Site Response Unit Code:	Northwest
Lat/Long:	47.6145777 / -122.18516

UST:

Facility ID:	52413526
Site ID:	257
Lat Deg:	Not reported
Lat Min:	Not reported
Lat Sec:	Not reported
Long Deg:	Not reported
Long Min:	Not reported
Long Sec:	Not reported
UBI:	1790104920010001
Phone Number:	2064549585

Tank ID:	43427
Tank Name:	2
Install Date:	9/1/1962
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	3/30/1996
Tank Status:	Removed
Tank Permit Expiration Date:	8/31/1996
Tank Closure Date:	1/1/0001
Tank Pumping System:	Product Removed by Reclaimer
Tank Spill Prevention:	25 Gallons or Less
Tank Overfill Prevention:	25 Gallons or less
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	None
Pipe Material:	Steel
Pipe Construction:	No Piping Attached to Tank
Pipe Primary Release Detection:	Suction
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Other
Tank Primary Release Detection:	Weekly Manual Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	43457
Tank Name:	1
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001

LINCOLN MERCURY OF BELLEVUE (Continued) **U004021011**

TankSystem Status:	Closed in Place
TankSystem Status Change Date:	8/26/1996
Tank Status:	Closed in Place
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

X100 **EASTSIDE CHRYSLER JEEP** **RCRA-CESQG** **1000697063**
SW **400 116TH AVE NE** **FINDS** **WAD988507414**
1/4-1/2 **BELLEVUE, WA 98004** **ALLSITES**
0.464 mi. **CSCSL NFA**
2450 ft. **Site 6 of 6 in cluster X** **INST CONTROL**

Relative:
Lower

Actual:
85 ft.

RCRA-CESQG:

Date form received by agency:	01/29/1997
Facility name:	EASTSIDE CHRYSLER JEEP
Facility address:	400 116TH AVE NE BELLEVUE, WA 98004
EPA ID:	WAD988507414
Mailing address:	9336 LOVEWELL CT ELK GROVE, CA 95758-4089
Contact:	ANDREW BUCCHIERE
Contact address:	9336 LOVEWELL CT ELK GROVE, CA 95758-4089
Contact country:	US
Contact telephone:	(916)684-0260
Contact email:	Not reported
EPA Region:	10
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

EASTSIDE CHRYSLER JEEP (Continued) **1000697063**

the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: CHRYSLER REALTY CORP NW
Owner/operator address: 9336 LOVEWELL CT
ELK GROVE, CA 95758
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/29/1997
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/01/1996
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005376208

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

EASTSIDE CHRYSLER JEEP (Continued) **1000697063**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ALLSITES:

Facility Id:	2497
Latitude:	47.6138509
Longitude:	-122.18676
Geographic location identifier (alias facid):	2497
Facility Name:	EASTSIDE CHRYSLER JEEP
Latitude Decimal Degrees:	47.613850999999997
Longitude Decimal Degrees:	-122.186764
Coordinate Point Areal Extent Code:	4
Horizontal Accuracy Code:	6
Coordinate Point Geographic Position Code:	5
Location Verified Code:	N

Geographic Location Identifier (Alias Facid):	2497
Interaction (Aka Env Int) Type Code:	HWG
Interaction (Aka Env Int) Description:	Hazardous Waste Generator
Interaction Status:	I
Federal Program Indentifier:	WAD988507414
Interaction Start Date:	06/10/1992
Interaction End Date:	12/31/1994
prgm_facil:	Not reported
cur_sys_pr:	HAZWASTE
cur_sys_nm:	TURBOWASTE

Geographic Location Identifier (Alias Facid):	2497
Interaction (Aka Env Int) Type Code:	LUST
Interaction (Aka Env Int) Description:	LUST Facility
Interaction Status:	I
Federal Program Indentifier:	456811
Interaction Start Date:	08/13/1993
Interaction End Date:	05/05/1999
prgm_facil:	Not reported
cur_sys_pr:	TOXICS
cur_sys_nm:	ISIS

Geographic Location Identifier (Alias Facid):	2497
Interaction (Aka Env Int) Type Code:	IRAP
Interaction (Aka Env Int) Description:	Independent Remedial Actn Prg
Interaction Status:	I
Federal Program Indentifier:	456811
Interaction Start Date:	12/27/1996
Interaction End Date:	05/05/1999
prgm_facil:	EASTSIDE CHRYSLER JEEP
cur_sys_pr:	TOXICS
cur_sys_nm:	ISIS

Geographic Location Identifier (Alias Facid):	2497
Interaction (Aka Env Int) Type Code:	UST
Interaction (Aka Env Int) Description:	Underground Storage Tank
Interaction Status:	A
Federal Program Indentifier:	456811
Interaction Start Date:	07/09/1998
Interaction End Date:	Not reported

EASTSIDE CHRYSLER JEEP (Continued) **1000697063**

prgm_facil: Not reported
cur_sys_pr: TOXICS
cur_sys_nm: ISIS

CSCSL NFA:
Facility/Site Id: 2497
CS Id: 5122
NFA Type: RC, IC
NFA Date: 05/05/1999
Rank: Not reported

INST CONTROL:
Facility Site ID: 2497
Document Type: Recording #: 9903121799, Date: Mar 12 1999 12:00AM
County Filing # For Individual IC Doc: 9903121799
Filing Date Of Individual IC Doc: 03/12/1999
Anchorage Restrictions: No
Drinking Water Restrictions: No
Education Programs: No
Financial Assurance: No
Finfish Harvesting Restrictions: No
Groundwater Restriction: No
Maintenance Requirements: Yes
No Dredge Zone: No
No Wake Zone: No
Property Use Restriction: No
Restrictive Signage: No
Shell Fish Harvesting Restrictions: No
Soil Restriction: No
Surface Water Restriction: No
Swimming Restriction: No
Vessel Draft Restriction: No
CS ID: 5122
Shoreline Stabilization Structure: N
Wave Attenuation Structure: N
Fencing or Other Permanent Access Barriers: N
Simple Soil CAP: N
Engineered CAP: N
Engineered Bottom Barriers: N
Immobilization by Stabilization, Solidification, or Encapsulation: N
Ground Water Extraction and Gradient Control: N
Vertical Ground Water Barrier: N
Impermeable Surface: N
Restrict Land Use: Y
Restrict All Ground Water Use: Y
Prohibit Domestic Ground Water Well Installation: N
Prohibit All Soil Disturbance: N
Access Barrier: N

101
SW
1/4-1/2
0.468 mi.
2470 ft.

EASTSIDE JEEP EAGLE DEALERSHIP
400 116TH AVE. NE
BELLEVUE, WA 98005

ICR **S104485039**
N/A

Relative:
Lower

Actual:
84 ft.

ICR:

Date Ecology Received Report:	11/26/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	09/11/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	08/13/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	05/16/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	05/12/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17

EASTSIDE JEEP EAGLE DEALERSHIP (Continued) **S104485039**

Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 03/03/97
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-05
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 12/23/96
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-05
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 05/13/96
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-05
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 01/29/96
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-05
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 10/27/95
Contaminants Found at Site: Petroleum products
Media Contaminated: Groundwater, Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Interim cleanup report
Site Register Issue: 98-05
County Code: 17
Contact: Not reported
Report Title: Not reported

EASTSIDE JEEP EAGLE DEALERSHIP (Continued) **S104485039**

Date Ecology Received Report:	10/12/95
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	07/03/95
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	05/12/95
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	09/20/94
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-05
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	10/01/98
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	01/31/98
Contaminants Found at Site:	Petroleum products

EASTSIDE JEEP EAGLE DEALERSHIP (Continued) **S104485039**

Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	10/31/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	07/31/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	04/30/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	02/26/97
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	10/31/96
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank

EASTSIDE JEEP EAGLE DEALERSHIP (Continued) **S104485039**

Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	06/15/95
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	10/31/94
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	10/10/94
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	05/31/94
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	06/16/92
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report

EASTSIDE JEEP EAGLE DEALERSHIP (Continued) **S104485039**

Site Register Issue:	98-16
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	09/20/94
Contaminants Found at Site:	Halogenated organic compounds, Petroleum products, Non-haologenated solvents
Media Contaminated:	Groundwater, Soil
Waste Management:	Not reported
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	93-36
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	10/12/95
Contaminants Found at Site:	Petroleum products, Non-haologenated solvents
Media Contaminated:	Groundwater, Soil
Waste Management:	Not reported
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-11
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	05/13/96
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Not reported
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-26
County Code:	17
Contact:	Not reported
Report Title:	Not reported
Date Ecology Received Report:	01/29/96
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Not reported
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-22
County Code:	17
Contact:	Not reported
Report Title:	Not reported

102 ENE 1/4-1/2 0.481 mi. 2538 ft.

BEL KIRK MUSTANG
12760 BEL RED RD
BELLEVUE, WA 98005

RCRA-CESQG FINDS ALLSITES

1004794415 WAD988513487

Relative: Lower

Actual: 123 ft.

RCRA-CESQG:

Date form received by agency:	03/04/2004
Facility name:	BEL KIRK MUSTANG
Facility address:	12760 BEL RED RD BELLEVUE, WA 98005
EPA ID:	WAD988513487
Contact:	RONALD M ALDRIDGE
Contact address:	12760 BEL RED RD BELLEVUE, WA 98005-2601
Contact country:	US
Contact telephone:	(425)455-1199
Contact email:	Not reported
EPA Region:	10
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	RONALD ALDRIDGE
Owner/operator address:	12760 BEL RED RD BELLEVUE, WA 98005
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	09/20/1996
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

BEL KIRK MUSTANG (Continued) **1004794415**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2003
Facility name: BEL KIRK MUSTANG
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110005380471

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ALLSITES:
Facility Id: 91877251
Latitude: 47.6210700
Longitude: -122.17032
Geographic location identifier (alias facid): 91877251
Facility Name: Bel Kirk Mustang
Latitude Decimal Degrees: 47.621070000000003
Longitude Decimal Degrees: -122.17032
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

103
NW
1/4-1/2
0.483 mi.
2551 ft.

EASTSIDE FERTILITY LABORATORY
1370 116TH AVE NE
BELLEVUE, WA 98004

ALLSITES **S109823943**
N/A

Relative:
Higher

Actual:
192 ft.

ALLSITES:

Facility Id:	4097
Latitude:	47.6239541
Longitude:	-122.18567
Geographic location identifier (alias facid):	4097
Facility Name:	Eastside Fertility Laboratory
Latitude Decimal Degrees:	47.623954153100001
Longitude Decimal Degrees:	-122.185671396
Coordinate Point Areal Extent Code:	0
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	8
Location Verified Code:	Not reported
Geographic Location Identifier (Alias Facid):	4097
Interaction (Aka Env Int) Type Code:	LSC
Interaction (Aka Env Int) Description:	Local Source Control
Interaction Status:	I
Federal Program Indentifier:	Not reported
Interaction Start Date:	12/05/2008
Interaction End Date:	04/29/2010
prgm_facil:	Eastside Fertility Laboratory
cur_sys_pr:	HAZWASTE
cur_sys_nm:	LSC

104
SW
1/4-1/2
0.486 mi.
2568 ft.

DODGE OF BELLEVUE
316 116TH AVE NE
BELLEVUE, WA 98004

RCRA-CESQG **1000230414**
FINDS **WAD053812061**
ALLSITES
CSCSL NFA
UST
MANIFEST
VCP

Relative:
Lower

Actual:
82 ft.

RCRA-CESQG:

Date form received by agency:	03/30/2007
Facility name:	DODGE OF BELLEVUE
Facility address:	316 116TH AVE NE BELLEVUE, WA 98004
EPA ID:	WAD053812061
Contact:	CAREN KASPERBAUER
Contact address:	316 116TH AVE NE BELLEVUE, WA 98004-5211
Contact country:	US
Contact telephone:	(425)454-8411
Contact email:	Not reported
EPA Region:	10
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less

DODGE OF BELLEVUE (Continued) **1000230414**

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: DODGE OF BELLEVUE
Owner/operator address: 316 116TH AVE NE
BELLEVUE, WA 98004
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/28/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2003
Facility name: DODGE OF BELLEVUE
Site name: PERFORMANCE DODGE
Classification: Not a generator, verified

Date form received by agency: 03/31/1994
Facility name: DODGE OF BELLEVUE
Classification: Large Quantity Generator

Date form received by agency: 09/01/1993
Facility name: DODGE OF BELLEVUE
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110005322203

DODGE OF BELLEVUE (Continued) **1000230414**

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ALLSITES:

Facility Id:	89172959
Latitude:	47.6131499
Longitude:	-122.18550
Geographic location identifier (alias facid):	89172959
Facility Name:	Dodge of Bellevue
Latitude Decimal Degrees:	47.613149999999997
Longitude Decimal Degrees:	-122.18550999999999
Coordinate Point Areal Extent Code:	99
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	99
Location Verified Code:	N

CSCSL NFA:

Facility/Site Id:	89172959
CS Id:	6822
NFA Type:	NFA-VCP Review
NFA Date:	11/15/2004
Rank:	Not reported

UST:

Facility ID:	89172959
Site ID:	97251
Lat Deg:	47
Lat Min:	36
Lat Sec:	47.33999999999071
Long Deg:	-122
Long Min:	11
Long Sec:	7.835999999977048
UBI:	Not reported
Phone Number:	2064548411
Tank ID:	17496
Tank Name:	#1
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001

DODGE OF BELLEVUE (Continued) **1000230414**

TankSystem Status:	Removed
TankSystem Status Change Date:	9/24/2004
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/11/1988
Tag Number:	Not reported

WA MANIFEST:

Facility Site ID Number:	89172959
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD053812061
Facility Address 2:	Not reported
TAX REG NBR:	601563571

DODGE OF BELLEVUE (Continued) **1000230414**

NAICS CD:	44111
BUSINESS TYPE:	automobile dealer
MAIL NAME:	Dodge of Bellevue
MAIL ADDR LINE1:	316 116TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-5211
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	AutoNation
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	316 116th Ave NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-5211
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)454-8411
LEGAL EFFECTIVE DATE:	7/1/1999
LAND ORG NAME:	Chrysler Realty Corp NW
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	PO Box 99081
LAND CITY,ST,ZIP:	CHICAGO, IL 60693-9081
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)454-8411
OPERATOR ORG NAME:	Dodge of Bellevue
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	316 116TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-5211
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)454-8411
OPERATOR EFFECTIVE DATE:	8/28/1996
SITE CONTACT NAME:	Caren Kasperbauer
SITE CONTACT ADDR LINE1:	316 116th Ave NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004-5211
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)454-8411
SITE CONTACT EMAIL:	kasperbauerc@autonation.com
FORM CONTACT NAME:	Caren Kasperbauer
FORM CONTACT ADDR LINE1:	316 116th Ave NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004-5211
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)454-8411
FORM CONTACT EMAIL:	kasperbauerc@autonation.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	TRUE
BATCH GENERATION:	FALSE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

DODGE OF BELLEVUE (Continued) **1000230414**

VCP:
edr_fstat: WA
edr_fzip: 98004
edr_fcnty: KING COUNTY
edr_zip: Not reported
Facility ID: 89172959
VCP Status: Not reported
VCP: Y
Ecology Status: Not reported
NFA Type: NFA-VCP Review
Date NFA: 11/15/2004
Rank: Not reported

---

105 **FOUR SEASONS CAR WASH** **CSCSL** **S105576114**
ENE **12900 BEL RED RD** **ALLSITES** **N/A**
1/2-1 **BELLEVUE, WA 98005**
0.558 mi.
2946 ft.

Relative:
Lower

Actual:
134 ft.

CSCSL:
Facility ID: 12627628
Region: Northwest
Lat/Long: 47.621260999999 / -122.169663
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 5542
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Benzene
Ground Water: C
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 12627628
Region: Northwest
Lat/Long: 47.621260999999 / -122.169663
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 5542
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Non-Halogenated Solvents
Ground Water: C
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 12627628
Region: Northwest
Lat/Long: 47.621260999999 / -122.169663

FOUR SEASONS CAR WASH (Continued) **S105576114**

Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	5542
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Diesel
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	12627628
Region:	Northwest
Lat/Long:	47.621260999999 / -122.169663
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	5542
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Gasoline
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

ALLSITES:

Facility Id:	12627628	
Latitude:	47.6212609	
Longitude:	-122.16966	
Geographic location identifier (alias facid):		12627628
Facility Name:		FOUR SEASONS CAR WASH
Latitude Decimal Degrees:		47.621260999999997
Longitude Decimal Degrees:		-122.169663
Coordinate Point Areal Extent Code:		4
Horizontal Accuracy Code:		6
Coordinate Point Geographic Position Code:		5
Location Verified Code:		N

106
WSW
1/2-1
0.568 mi.
3001 ft.

Relative:
Lower

Actual:
118 ft.

TEXACO REFINING MARKETING IN 12TH AVE **RCRA-NonGen** **1000144967**
615 112TH AVE NE **FINDS** **WAD982652539**
BELLEVUE, WA 98004 **CSCSL**
ALLSITES
LUST
UST
ICR

RCRA-NonGen:

Date form received by agency:	09/01/1993
Facility name:	TEXACO REFINING MARKETING IN 12TH AVE
Site name:	TEXACO REFINING & MARKETING IN

TEXACO REFINING MARKETING IN 12TH AVE (Continued) **1000144967**

Facility address: 615 112TH AVE NE
BELLEVUE, WA 98004
EPA ID: WAD982652539
Mailing address: PO BOX 2969
KIRKLAND, WA 980832969
Contact: ROBIN LANE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: (206) 827-0761
Contact email: Not reported
EPA Region: 10
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: EQUILION ENTERPRISES LLC DBA SHELL OIL P
Owner/operator address: PO BOX 4453 MFT226
HOUSTON, TX 77210
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/11/1988
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/11/1988
Facility name: TEXACO REFINING MARKETING IN 12TH AVE
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110005345395

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a

TEXACO REFINING MARKETING IN 12TH AVE (Continued) **1000144967**

means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CSCSL:

Facility ID:	6425419
Region:	Northwest
Lat/Long:	47.615640999999 / -122.192224
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7702
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	6425419
Region:	Northwest
Lat/Long:	47.615640999999 / -122.192224
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7702
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Diesel
Ground Water:	RB
Surface Water:	Not reported
Soil:	RB
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	6425419
Region:	Northwest
Lat/Long:	47.615640999999 / -122.192224
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7702
Site Status:	Cleanup Started
PSI?:	Not reported

TEXACO REFINING MARKETING IN 12TH AVE (Continued) **1000144967**

Contaminant Name: Petroleum-Gasoline
Ground Water: C
Surface Water: Not reported
Soil: RB
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 6425419
Region: Northwest
Lat/Long: 47.615640999999 / -122.192224
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 7702
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Other
Ground Water: C
Surface Water: Not reported
Soil: RB
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 6425419
Latitude: 47.6156409
Longitude: -122.19222
Geographic location identifier (alias facid): 6425419
Facility Name: Texaco Refining Marketing IN 12th Ave
Latitude Decimal Degrees: 47.615640999999997
Longitude Decimal Degrees: -122.192224
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 7
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

LUST:
FS ID: 6425419
Cleanup Site ID: 7702
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: TEXACO
Release Notification Date: Not reported
Release Status Date: 07/01/2011
Site Response Unit Code: Northwest
Lat/Long: 47.6156409 / -122.19222

FS ID: 6425419
Cleanup Site ID: 7702
Cleanup Unit Type: Upland
Process Type: Independent Action

TEXACO REFINING MARKETING IN 12TH AVE (Continued) **1000144967**

Facility Status: Cleanup Started
Alternate Name: TEXACO
Release Notification Date: Not reported
Release Status Date: 02/12/1991
Site Response Unit Code: Northwest
Lat/Long: 47.6156409 / -122.19222

FS ID: 6425419
Cleanup Site ID: 7702
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: RCU
Alternate Name: TEXACO
Release Notification Date: Not reported
Release Status Date: 06/01/1995
Site Response Unit Code: Northwest
Lat/Long: 47.6156409 / -122.19222

UST:
Facility ID: 6425419
Site ID: 4438
Lat Deg: 47
Lat Min: 36
Lat Sec: 56.307599999987588
Long Deg: -122
Long Min: 11
Long Sec: 32.006399999985433
UBI: Not reported
Phone Number: 2064545857

Tank ID: 2353
Tank Name: 2
Install Date: 12/31/1964
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Not reported
Tank Construction: Not reported
Tank Tightness Test: Not reported
Tank Corrosion Protection: Not reported
Pipe Material: Not reported
Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

TEXACO REFINING MARKETING IN 12TH AVE (Continued) **1000144967**

Tank ID:	2374
Tank Name:	6
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	2437
Tank Name:	4
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Fiberglass
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

TEXACO REFINING MARKETING IN 12TH AVE (Continued) **1000144967**

Tank ID:	2483
Tank Name:	3
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	2522
Tank Name:	5
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

TEXACO REFINING MARKETING IN 12TH AVE (Continued) **1000144967**

Tank ID:	2531
Tank Name:	1
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

ICR:

Date Ecology Received Report:	10/14/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-09
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	10/14/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-10
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	05/23/91
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Not reported

TEXACO REFINING MARKETING IN 12TH AVE (Continued) **1000144967**

Site Register Issue: 91-31
County Code: 17
Contact: Not reported
Report Title: Not reported

107
North
1/2-1
0.581 mi.
3067 ft.

Relative:
Higher

Actual:
158 ft.

INTERNATIONAL PAPER BELLEVUE **RCRA-CESQG** **1004793237**
1899 120TH AVE NE **FINDS** **WA0000275537**
BELLEVUE, WA 98005 **CSCSL**
ALLSITES
LUST
UST
MANIFEST

RCRA-CESQG:
Date form received by agency: 02/23/2010
Facility name: INTERNATIONAL PAPER BELLEVUE
Facility address: 1899 120TH AVE NE
BELLEVUE, WA 98005
EPA ID: WA0000275537
Contact: MARTIN TAYLOR
Contact address: 1899 120TH AVE NE
BELLEVUE, WA 98005
Contact country: US
Contact telephone: (425) 455-1111
Contact email: MARTIN.TAYLOR@WEYERHAEUSER.COM
EPA Region: 10
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: INTERNATIONAL PAPER
Owner/operator address: 6400 POPLAR AVE
MEMPHIS, 38197
Owner/operator country: US
Owner/operator telephone: (901)419-9000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/04/2008
Owner/Op end date: Not reported

Owner/operator name: INTERNATIONAL PAPER
Owner/operator address: 1899 120TH AVE NE
BELLEVUE, 98005
Owner/operator country: US

INTERNATIONAL PAPER BELLEVUE (Continued) **1004793237**

Owner/operator telephone: (425)455-1111
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/04/2008
Owner/Op end date: Not reported

Owner/operator name: WEYERHAEUSER COMPANY
Owner/operator address: 3366 WEYERHAEUSER WAY S
FEDERAL WAY, WA 98003
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/30/2002
Owner/Op end date: Not reported

Owner/operator name: WILLAMETTE INDUSTRIES
Owner/operator address: 1899 120TH AVE NE
BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1997
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/30/2008
Facility name: INTERNATIONAL PAPER BELLEVUE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/31/2003
Facility name: INTERNATIONAL PAPER BELLEVUE
Site name: WEYERHAEUSER COMPANY BELLEVUE
Classification: Not a generator, verified

Hazardous Waste Summary:
Waste code: WSQG
Waste name: A placeholder to allow BR submission to validate. In WA State,

INTERNATIONAL PAPER BELLEVUE (Continued) **1004793237**

Conditionally Exempt Small Quantity Generators (Called SQG in WA) are not required to report waste streams, so no valid State or Fed codes are available for reporting to BR.

Violation Status: No violations found

FINDS:

Registry ID: 110005304955

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

CSCSL:

Facility ID:	18313725
Region:	Northwest
Lat/Long:	47.627670999999 / -122.181354
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	8202
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	S
Surface Water:	Not reported

INTERNATIONAL PAPER BELLEVUE (Continued) **1004793237**

Soil:	RB
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest
Facility ID:	18313725
Region:	Northwest
Lat/Long:	47.627670999999 / -122.181354
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	8202
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Diesel
Ground Water:	C
Surface Water:	Not reported
Soil:	RB
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest
Facility ID:	18313725
Region:	Northwest
Lat/Long:	47.627670999999 / -122.181354
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	8202
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Gasoline
Ground Water:	S
Surface Water:	Not reported
Soil:	RB
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest
Facility ID:	18313725
Region:	Northwest
Lat/Long:	47.627670999999 / -122.181354
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	8202
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Other
Ground Water:	S
Surface Water:	Not reported
Soil:	RB
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

INTERNATIONAL PAPER BELLEVUE (Continued) **1004793237**

ALLSITES:

Facility Id:	18313725	
Latitude:	47.6276709	
Longitude:	-122.18135	
Geographic location identifier (alias facid):		18313725
Facility Name:		International Paper Bellevue
Latitude Decimal Degrees:		47.627670999999999
Longitude Decimal Degrees:		-122.181354
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		6
Coordinate Point Geographic Position Code:		5
Location Verified Code:		N

LUST:

FS ID:	18313725
Cleanup Site ID:	8202
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	WILLAMETTE INDUSTRIES
Release Notification Date:	Not reported
Release Status Date:	07/01/2011
Site Response Unit Code:	Northwest
Lat/Long:	47.6276709 / -122.18135

FS ID:	18313725
Cleanup Site ID:	8202
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	RCU
Alternate Name:	WILLAMETTE INDUSTRIES
Release Notification Date:	Not reported
Release Status Date:	03/21/2002
Site Response Unit Code:	Northwest
Lat/Long:	47.6276709 / -122.18135

FS ID:	18313725
Cleanup Site ID:	8202
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	WILLAMETTE INDUSTRIES
Release Notification Date:	Not reported
Release Status Date:	06/21/1995
Site Response Unit Code:	Northwest
Lat/Long:	47.6276709 / -122.18135

UST:

Facility ID:	18313725
Site ID:	6171
Lat Deg:	47
Lat Min:	37
Lat Sec:	39.615599999997926
Long Deg:	-122
Long Min:	10

INTERNATIONAL PAPER BELLEVUE (Continued) **1004793237**

Long Sec:	52.874399999996058
UBI:	6001230090010004
Phone Number:	2064551111

Tank ID:	22507
Tank Name:	3
Install Date:	6/1/1975
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Product Removed by Reclaimer
Tank Spill Prevention:	None
Tank Overfill Prevention:	None
Tank Material:	Not reported
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	None
Pipe Material:	Not reported
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	22541
Tank Name:	5
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported

INTERNATIONAL PAPER BELLEVUE (Continued) **1004793237**

Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	22602
Tank Name:	1
Install Date:	7/15/1980
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	None
Tank Overfill Prevention:	None
Tank Material:	Not reported
Tank Construction:	Secondary Containment
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	None
Pipe Material:	Not reported
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	None
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	22662
Tank Name:	4
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported

INTERNATIONAL PAPER BELLEVUE (Continued) **1004793237**

Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

Tank ID: 22756
Tank Name: 2
Install Date: 7/15/1980
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: None
Tank Overfill Prevention: None
Tank Material: Not reported
Tank Construction: Secondary Containment
Tank Tightness Test: Not reported
Tank Corrosion Protection: None
Pipe Material: Not reported
Pipe Construction: Single Wall Pipe
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: None
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Annual
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

WA MANIFEST:
Facility Site ID Number: 18313725
SWC Desc: Not reported
FWC Desc: Not reported
Form Comm: Not reported
Data Year: 2009
Permit by Rule: False
Treatment by Generator: False
Mixed radioactive waste: False
Importer of hazardous waste: False
Immediate recycler: False
Treatment/Storage/Disposal/Recycling Facility: False
Generator of dangerous fuel waste: False
Generator marketing to burner: False
"Other marketers (i.e., blender, distributor, etc.)": False
Utility boiler burner: False
Industry boiler burner: False
Industrial Furnace: False
Smelter defferal: False
Universal waste - batteries - generate: False
Universal waste - thermostats - generate: False
Universal waste - mercury - generate: False
Universal waste - lamps - generate: True

INTERNATIONAL PAPER BELLEVUE (Continued) **1004793237**

Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WA0000275537
Facility Address 2:	Not reported
TAX REG NBR:	600123009
NAICS CD:	322211
BUSINESS TYPE:	Corrugated Containers
MAIL NAME:	International Paper
MAIL ADDR LINE1:	1899 120th Ave NE
MAIL CITY,ST,ZIP:	Bellevue, WA 98005-2120
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	International Paper
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	6400 Poplar Ave
LEGAL CITY,ST,ZIP:	Memphis, TN 38197
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(901)419-9000
LEGAL EFFECTIVE DATE:	8/4/2008
LAND ORG NAME:	IP CBPR PROPERTIES 2 LLC
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	6400 Poplar Ave
LAND CITY,ST,ZIP:	Memphis, TN 38197
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(000)000-0000
OPERATOR ORG NAME:	International Paper
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1899 120th Ave NE
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98005-2120
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)455-1111
OPERATOR EFFECTIVE DATE:	8/4/2008
SITE CONTACT NAME:	Martin Taylor
SITE CONTACT ADDR LINE1:	1899 120th Ave NE
SITE CONTACT ZIP:	Bellevue, WA 98005
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)455-1111
SITE CONTACT EMAIL:	martin.taylor@weyerhaeuser.com
FORM CONTACT NAME:	Martin Taylor
FORM CONTACT ADDR LINE1:	1899 120th Ave NE
FORM CONTACT CITY,ST,ZIP:	Bellevue, WA 98005
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)455-1111
FORM CONTACT EMAIL:	martin.taylor@weyerhaeuser.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	True
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False

INTERNATIONAL PAPER BELLEVUE (Continued) **1004793237**

TRANSFER FACILITY: False
OTHER EXEMPTION: Not reported
UW BATTERY GEN: True
USED OIL TRANSPORTER: False
USED OIL TRANSFER FACLTY: False
USED OIL PROCESSOR: False
USED OIL REREFINER: False
USED OIL FUEL MRKTR DIRECTS SHPMNTS: False
USED OIL FUEL MRKTR MEETS SPECS: False

---

108 **BELLEVUE CITY HALL** **CSCSL** **U003024859**
SSW **11511 MAIN ST** **ALLSITES** **N/A**
1/2-1 **BELLEVUE, WA 98009** **LUST**
0.671 mi. **UST**
3541 ft. **NPDES**

Relative:
Lower

Actual:
61 ft.

CSCSL:
Facility ID: 45864671
Region: Northwest
Lat/Long: 47.609520000000 / -122.18579
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 9301
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Diesel
Ground Water: Not reported
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 45864671
Latitude: 47.6095200
Longitude: -122.18579
Geographic location identifier (alias facid): 45864671
Facility Name: BELLEVUE CITY HALL
Latitude Decimal Degrees: 47.609520000000003
Longitude Decimal Degrees: -122.18579
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 4
Coordinate Point Geographic Position Code: 5
Location Verified Code: Y

LUST:
FS ID: 45864671
Cleanup Site ID: 9301
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: RCU
Alternate Name: BELLEVUE CITY HALL
Release Notification Date: Not reported
Release Status Date: 02/27/2002

BELLEVUE CITY HALL (Continued) **U003024859**

Site Response Unit Code: Northwest
Lat/Long: 47.6095200 / -122.18579

FS ID: 45864671
Cleanup Site ID: 9301
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: BELLEVUE CITY HALL
Release Notification Date: Not reported
Release Status Date: 06/01/1995
Site Response Unit Code: Northwest
Lat/Long: 47.6095200 / -122.18579

FS ID: 45864671
Cleanup Site ID: 9301
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: BELLEVUE CITY HALL
Release Notification Date: Not reported
Release Status Date: 07/01/2011
Site Response Unit Code: Northwest
Lat/Long: 47.6095200 / -122.18579

UST:
Facility ID: 45864671
Site ID: 100562
Lat Deg: 47
Lat Min: 36
Lat Sec: 34.272000000012213
Long Deg: -122
Long Min: 11
Long Sec: 8.8439999999900465
UBI: 1790167460010018
Phone Number: 4254022040

Tank ID: 39769
Tank Name: 34
Install Date: 1/1/1983
Capacity: 111 TO 1,100 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 4/13/1999
Tank Status: Removed
Tank Permit Expiration Date: 6/30/1998
Tank Closure Date: 1/1/0001
Tank Pumping System: Suction System Tank Check Valve
Tank Spill Prevention: None
Tank Overfill Prevention: None
Tank Material: Not reported
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported
Tank Corrosion Protection: Other
Pipe Material: Not reported
Pipe Construction: Single Wall Pipe
Pipe Primary Release Detection: Not reported

BELLEVUE CITY HALL (Continued) **U003024859**

Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: None
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 2/2/1999
Tag Number: Not reported

Tank ID: 39879
Tank Name: 33
Install Date: 12/31/1964
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Not reported
Tank Construction: Not reported
Tank Tightness Test: Not reported
Tank Corrosion Protection: Not reported
Pipe Material: Not reported
Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

NPDES:
Facility Status: Active
Facility Type: Municipal SW Phase II Western WA GP
Admin Region: Headquarters
Latitude: 47.60952
Longitude: -122.18579
Permit ID: WAR045504
Permit Version: 1
Permit Status: Active
Permit SubStatus: Coverage Issued
Ecology Contact: Anne Dettelbach
WRIA: Cedar-Sammamish
Permit Expiration Date: 02/15/2012
Effective Date: 02/16/2007

109
NNE
1/2-1
0.695 mi.
3672 ft.

Relative:
Higher

Actual:
157 ft.

KING CNTY DOT METRO TRANSIT EAST BASE
1975 124TH AVENUE NORTHEAST
BELLEVUE, WA 98005

Database(s): RCRA-CESQG, FINDS, CSCSL, ALLSITES, LUST, MANIFEST, SPILLS, ICR, NPDES

EDR ID Number: 1000366462
EPA ID Number: WAD981762149

RCRA-CESQG:

Date form received by agency:	01/13/2010
Facility name:	KING CNTY DOT METRO TRANSIT EAST BASE
Facility address:	1975 124TH AVE NE BELLEVUE, WA 98005
EPA ID:	WAD981762149
Mailing address:	201 S JACKSON ST. MS SFM TR SEATTLE, WA 98104
Contact:	CATHY JOHNSON
Contact address:	201 S JACKSON ST MS SFM TR 01 SEATTLE, WA 98104
Contact country:	US
Contact telephone:	(206) 684-2266
Contact email:	CATHY.JOHNSON@KINGCOUNTY.GOV
EPA Region:	10
Land type:	County
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	KING CNTY DOT METRO TRANSIT
Owner/operator address:	201 S JACKSON ST MS SFM TR 0100 SEATTLE, 98104
Owner/operator country:	US
Owner/operator telephone:	(206)684-2266
Legal status:	County
Owner/Operator Type:	Operator
Owner/Op start date:	07/22/1996
Owner/Op end date:	Not reported

Owner/operator name:	METRO KING CNTY DOT
Owner/operator address:	201 S JACKSON ST MS SFM TR SEATTLE, 98104
Owner/operator country:	US
Owner/operator telephone:	(206)684-2266
Legal status:	County

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

Owner/Operator Type: Owner
Owner/Op start date: 07/22/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/20/2008
Facility name: KING CNTY DOT METRO TRANSIT EAST BASE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/31/2007
Facility name: KING CNTY DOT METRO TRANSIT EAST BASE
Classification: Not a generator, verified

Date form received by agency: 12/31/2005
Facility name: KING CNTY DOT METRO TRANSIT EAST BASE
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: KING CNTY DOT METRO TRANSIT EAST BASE
Site name: METRO KING CNTY DOT TRANSIT 124TH
Classification: Not a generator, verified

Date form received by agency: 02/07/2000
Facility name: KING CNTY DOT METRO TRANSIT EAST BASE
Site name: METRO KING CNTY DOT TRANSIT 124TH
Classification: Large Quantity Generator

Date form received by agency: 03/01/1996
Facility name: KING CNTY DOT METRO TRANSIT EAST BASE
Site name: METRO KING COUNTY-DEPT OF TRANS-TRANSIT
Classification: Large Quantity Generator

Date form received by agency: 03/31/1994
Facility name: KING CNTY DOT METRO TRANSIT EAST BASE
Site name: METRO KING CTY-DMS-TRANSIT-EAS
Classification: Large Quantity Generator

Date form received by agency: 09/01/1993
Facility name: KING CNTY DOT METRO TRANSIT EAST BASE

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

Site name: MUNIC METRO SEATTLE-EAST BASE
Classification: Large Quantity Generator

Date form received by agency: 12/31/1990
Facility name: KING CNTY DOT METRO TRANSIT EAST BASE
Site name: MUNICIPALITY OF METROPOLITAN S
Classification: Large Quantity Generator

Hazardous Waste Summary:
Waste code: WSQG
Waste name: A placeholder to allow BR submission to validate. In WA State, Conditionally Exempt Small Quantity Generators (Called SQG in WA) are not required to report waste streams, so no valid State or Fed codes are available for reporting to BR.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 11/20/2006
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/05/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110009511073

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

CSCSL:

Facility ID:	18962661
Region:	Northwest
Lat/Long:	47.626891000000 / -122.176354
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7067
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	18962661
Region:	Northwest
Lat/Long:	47.626891000000 / -122.176354
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7067
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Diesel
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	18962661
Region:	Northwest
Lat/Long:	47.626891000000 / -122.176354
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7067
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Gasoline
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	18962661
Region:	Northwest
Lat/Long:	47.626891000000 / -122.176354
Brownfield Status:	Not reported
Rank Status:	Not reported

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

Clean Up Siteid:	7067
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Other
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	18962661
Region:	Northwest
Lat/Long:	47.626891000000 / -122.176354
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7067
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Polynuclear Aromatic Hydrocarbons
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	18962661
Region:	Northwest
Lat/Long:	47.626891000000 / -122.176354
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7234
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	LUST - Other Hazardous Substance
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	18962661
Region:	Northwest
Lat/Long:	47.626891000000 / -122.176354
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7234
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Other
Ground Water:	C
Surface Water:	Not reported

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 18962661
Latitude: 47.6268910
Longitude: -122.17635
Geographic location identifier (alias facid): 18962661
Facility Name: King Cnty DOT Metro Transit East Base
Latitude Decimal Degrees: 47.626891000000001
Longitude Decimal Degrees: -122.176354
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 6
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

LUST:
FS ID: 18962661
Cleanup Site ID: 7234
Cleanup Unit Type: Upland
Process Type: No Process
Facility Status: Cleanup Started
Alternate Name: METRO EASTBASE MAINT BLDG Transmission Fluid
Release Notification Date: Not reported
Release Status Date: 06/01/1995
Site Response Unit Code: Northwest
Lat/Long: 47.6268910 / -122.17635

FS ID: 18962661
Cleanup Site ID: 7067
Cleanup Unit Type: Upland
Process Type: Ecology-supervised or conducted
Facility Status: Cleanup Started
Alternate Name: METRO EAST BASE - Diesel Tank
Release Notification Date: Not reported
Release Status Date: 06/01/1995
Site Response Unit Code: Northwest
Lat/Long: 47.6268910 / -122.17635

WA MANIFEST:
Facility Site ID Number: 18962661
SWC Desc: Not reported
FWC Desc: Not reported
Form Comm: Not reported
Data Year: Not reported
Permit by Rule: False
Treatment by Generator: False
Mixed radioactive waste: False
Importer of hazardous waste: False
Immediate recycler: False
Treatment/Storage/Disposal/Recycling Facility: False
Generator of dangerous fuel waste: False

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD981762149
Facility Address 2:	Not reported
TAX REG NBR:	578055920
NAICS CD:	48511
BUSINESS TYPE:	Not reported
MAIL NAME:	King Cnty DOT Metro Transit
MAIL ADDR LINE1:	201 S Jackson St. MS SFM TR 0100
MAIL CITY,ST,ZIP:	SEATTLE, WA 98104-1519
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Metro King Cnty DOT
LEGAL ORG TYPE:	County
LEGAL ADDR LINE1:	201 S Jackson St MS SFM TR 0100
LEGAL CITY,ST,ZIP:	SEATTLE, WA 98104-1519
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(206)684-2266
LEGAL EFFECTIVE DATE:	7/22/1996
LAND ORG NAME:	King Cnty DOT Metro Transit
LAND ORG TYPE:	County
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	201 S Jackson St MS SFM TR 0100
LAND CITY,ST,ZIP:	SEATTLE, WA 98104-1519
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(206)684-2266
OPERATOR ORG NAME:	King Cnty DOT Metro Transit
OPERATOR ORG TYPE:	County
OPERATOR ADDR LINE1:	201 S Jackson St
OPERATOR ADDR LINE2:	MS SFM TR 0100
OPERATOR CITY,ST,ZIP:	SEATTLE, WA 98104-1519
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(206)684-2266
OPERATOR EFFECTIVE DATE:	07/22/96
SITE CONTACT NAME:	Cathy Johnson
SITE CONTACT ADDR LINE1:	201 S Jackson St MS SFM TR 0100
SITE CONTACT ZIP:	SEATTLE, WA 98104-1519
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(206)684-2266
SITE CONTACT EMAIL:	cathy.johnson@kingcounty.gov
FORM CONTACT NAME:	Cathy Johnson
FORM CONTACT ADDR LINE1:	201 S Jackson St MS SFM TR 0100

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

FORM CONTACT CITY,ST,ZIP:	SEATTLE, WA 98104-1519
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(206)684-2266
FORM CONTACT EMAIL:	cathy.johnson@kingcounty.gov
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	18962661
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD981762149
Facility Address 2:	Not reported
TAX REG NBR:	578055920
NAICS CD:	48511
BUSINESS TYPE:	Not reported
MAIL NAME:	King Cnty DOT Metro Transit

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

MAIL ADDR LINE1:	201 S Jackson St. MS SFM TR 0100
MAIL CITY,ST,ZIP:	SEATTLE, WA 98104-1519
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Metro King Cnty DOT
LEGAL ORG TYPE:	County
LEGAL ADDR LINE1:	201 S Jackson St MS SFM TR 0100
LEGAL CITY,ST,ZIP:	SEATTLE, WA 98104-1519
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(206)684-2266
LEGAL EFFECTIVE DATE:	7/22/1996
LAND ORG NAME:	King Cnty DOT Metro Transit
LAND ORG TYPE:	County
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	201 S Jackson St MS SFM TR 0100
LAND CITY,ST,ZIP:	SEATTLE, WA 98104-1519
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(206)684-2266
OPERATOR ORG NAME:	King Cnty DOT Metro Transit
OPERATOR ORG TYPE:	County
OPERATOR ADDR LINE1:	201 S Jackson St
OPERATOR ADDR LINE2:	MS SFM TR 0100
OPERATOR CITY,ST,ZIP:	SEATTLE, WA 98104-1519
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(206)684-2266
OPERATOR EFFECTIVE DATE:	7/22/1996
SITE CONTACT NAME:	Cathy Johnson
SITE CONTACT ADDR LINE1:	201 S Jackson St MS SFM TR 0100
SITE CONTACT ZIP:	SEATTLE, WA 98104-1519
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(206)684-2266
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Cathy Johnson
FORM CONTACT ADDR LINE1:	201 S Jackson St MS SFM TR 0100
FORM CONTACT CITY,ST,ZIP:	SEATTLE, WA 98104-1519
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(206)684-2266
FORM CONTACT EMAIL:	cathy.johnson@metrokc.gov
GEN STATUS CD:	SQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Facility Site ID Number:	18962661
SWC Desc:	Not reported
FWC Desc:	Not reported

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

Form Comm:	Not reported
Data Year:	2009
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD981762149
Facility Address 2:	Not reported
TAX REG NBR:	578055920
NAICS CD:	485113
BUSINESS TYPE:	Not reported
MAIL NAME:	King Cnty DOT Metro Transit
MAIL ADDR LINE1:	201 S Jackson St. MS SFM TR 0100
MAIL CITY,ST,ZIP:	SEATTLE, WA 98104-1519
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Metro King Cnty DOT
LEGAL ORG TYPE:	County
LEGAL ADDR LINE1:	201 S Jackson St MS SFM TR 0100
LEGAL CITY,ST,ZIP:	SEATTLE, WA 98104-1519
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(206)684-2266
LEGAL EFFECTIVE DATE:	7/22/1996
LAND ORG NAME:	King Cnty DOT Metro Transit
LAND ORG TYPE:	County
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	201 S Jackson St MS SFM TR 0100
LAND CITY,ST,ZIP:	SEATTLE, WA 98104-1519
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(206)684-2266
OPERATOR ORG NAME:	King Cnty DOT Metro Transit
OPERATOR ORG TYPE:	County
OPERATOR ADDR LINE1:	201 S Jackson St
OPERATOR ADDR LINE2:	MS SFM TR 0100
OPERATOR CITY,ST,ZIP:	SEATTLE, WA 98104-1519
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(206)684-2266

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

OPERATOR EFFECTIVE DATE:	7/22/1996
SITE CONTACT NAME:	Cathy Johnson
SITE CONTACT ADDR LINE1:	201 S Jackson St MS SFM TR 0100
SITE CONTACT ZIP:	SEATTLE, WA 98104-1519
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(206)684-2266
SITE CONTACT EMAIL:	cathy.johnson@kingcounty.gov
FORM CONTACT NAME:	Cathy Johnson
FORM CONTACT ADDR LINE1:	201 S Jackson St MS SFM TR 0100
FORM CONTACT CITY,ST,ZIP:	SEATTLE, WA 98104-1519
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(206)684-2266
FORM CONTACT EMAIL:	cathy.johnson@kingcounty.gov
GEN STATUS CD:	SQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	18962661
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD981762149
Facility Address 2:	Not reported
TAX REG NBR:	578055920
NAICS CD:	48511
BUSINESS TYPE:	Not reported
MAIL NAME:	King Cnty DOT Metro Transit
MAIL ADDR LINE1:	201 S Jackson St. MS SFM TR 0100
MAIL CITY,ST,ZIP:	SEATTLE, WA 98104-1519
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Metro King Cnty DOT
LEGAL ORG TYPE:	County
LEGAL ADDR LINE1:	201 S Jackson St MS SFM TR 0100
LEGAL CITY,ST,ZIP:	SEATTLE, WA 98104-1519
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(206)684-2266
LEGAL EFFECTIVE DATE:	7/22/1996
LAND ORG NAME:	King Cnty DOT Metro Transit
LAND ORG TYPE:	County
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	201 S Jackson St MS SFM TR 0100
LAND CITY,ST,ZIP:	SEATTLE, WA 98104-1519
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(206)684-2266
OPERATOR ORG NAME:	King Cnty DOT Metro Transit
OPERATOR ORG TYPE:	County
OPERATOR ADDR LINE1:	201 S Jackson St
OPERATOR ADDR LINE2:	MS SFM TR 0100
OPERATOR CITY,ST,ZIP:	SEATTLE, WA 98104-1519
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(206)684-2266
OPERATOR EFFECTIVE DATE:	7/22/1996
SITE CONTACT NAME:	Cathy Johnson
SITE CONTACT ADDR LINE1:	201 S Jackson St MS SFM TR 0100
SITE CONTACT ZIP:	SEATTLE, WA 98104-1519
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(206)684-2266
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Cathy Johnson
FORM CONTACT ADDR LINE1:	201 S Jackson St MS SFM TR 0100
FORM CONTACT CITY,ST,ZIP:	SEATTLE, WA 98104-1519
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(206)684-2266
FORM CONTACT EMAIL:	cathy.johnson@metrokc.gov
GEN STATUS CD:	XQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	FALSE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

USED OIL TRANSFER FACLTY: FALSE
USED OIL PROCESSOR: FALSE
USED OIL REREFINER: FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS: FALSE
USED OIL FUEL MRKTR MEETS SPECS: FALSE

Facility Site ID Number: 18962661
SWC Desc: Not reported
FWC Desc: Not reported
Form Comm: In 2008 I shipped old paint products that were no longer usable. This was the only waste produced in 2008 at this site.
Data Year: 2008
Permit by Rule: False
Treatment by Generator: False
Mixed radioactive waste: False
Importer of hazardous waste: False
Immediate recycler: False
Treatment/Storage/Disposal/Recycling Facility: False
Generator of dangerous fuel waste: False
Generator marketing to burner: False
"Other marketers (i.e., blender, distributor, etc.)": False
Utility boiler burner: False
Industry boiler burner: False
Industrial Furnace: False
Smelter defferal: False
Universal waste - batteries - generate: False
Universal waste - thermostats - generate: False
Universal waste - mercury - generate: False
Universal waste - lamps - generate: False
Universal waste - batteries - accumulate: False
Universal waste - thermostats - accumulate: False
Universal waste - mercury - accumulate: False
Universal waste - lamps - accumulate: False
Destination Facility for Universal Waste: False
Off-specification used oil burner - utility boiler: False
Off-specification used oil burner - industrial boiler: False
Off-specification used oil burner - industrial furnace: False
EPA ID: WAD981762149
Facility Address 2: Not reported
TAX REG NBR: 578055920
NAICS CD: 48511
BUSINESS TYPE: Not reported
MAIL NAME: King Cnty DOT Metro Transit
MAIL ADDR LINE1: 201 S Jackson St. MS SFM TR 0100
MAIL CITY,ST,ZIP: SEATTLE, WA 98104-1519
MAIL COUNTRY: UNITED STATES
LEGAL ORG NAME: Metro King Cnty DOT
LEGAL ORG TYPE: County
LEGAL ADDR LINE1: 201 S Jackson St MS SFM TR 0100
LEGAL CITY,ST,ZIP: SEATTLE, WA 98104-1519
LEGAL COUNTRY: UNITED STATES
LEGAL PHONE NBR: (206)684-2266
LEGAL EFFECTIVE DATE: 7/22/1996
LAND ORG NAME: King Cnty DOT Metro Transit
LAND ORG TYPE: County
LAND PERSON NAME: Not reported
LAND ADDR LINE1: 201 S Jackson St MS SFM TR 0100

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

LAND CITY,ST,ZIP:	SEATTLE, WA 98104-1519
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(206)684-2266
OPERATOR ORG NAME:	King Cnty DOT Metro Transit
OPERATOR ORG TYPE:	County
OPERATOR ADDR LINE1:	201 S Jackson St
OPERATOR ADDR LINE2:	MS SFM TR 0100
OPERATOR CITY,ST,ZIP:	SEATTLE, WA 98104-1519
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(206)684-2266
OPERATOR EFFECTIVE DATE:	7/22/1996
SITE CONTACT NAME:	Cathy Johnson
SITE CONTACT ADDR LINE1:	201 S Jackson St MS SFM TR 0100
SITE CONTACT ZIP:	SEATTLE, WA 98104-1519
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(206)684-2266
SITE CONTACT EMAIL:	cathy.johnson@kingcounty.gov
FORM CONTACT NAME:	Cathy Johnson
FORM CONTACT ADDR LINE1:	201 S Jackson St MS SFM TR 0100
FORM CONTACT CITY,ST,ZIP:	SEATTLE, WA 98104-1519
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(206)684-2266
FORM CONTACT EMAIL:	cathy.johnson@kingcounty.gov
GEN STATUS CD:	MQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Click this hyperlink while viewing on your computer to access
1 additional WA MANIFEST: record(s) in the EDR Site Report.

SPILLS:

Facility ID:	541586
Medium:	Not reported
Material Desc:	PETROLEUM - DIESEL FUEL
Material Qty:	2400
Material Units:	GALLON
Date Received:	6/21/2004
Contact Name:	Not reported

ICR:

Date Ecology Received Report:	03/12/96
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Soil

KING CNTY DOT METRO TRANSIT EAST BASE (Continued) **1000366462**

Waste Management:	Spill
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-27
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	07/31/96
Contaminants Found at Site:	Total petroleum hydrocarbons
Media Contaminated:	Soil
Waste Management:	Unknown
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	94-35
County Code:	17
Contact:	Not reported
Report Title:	Not reported

Date Ecology Received Report:	12/23/92
Contaminants Found at Site:	Petroleum products
Media Contaminated:	Groundwater, Soil
Waste Management:	Tank
Region:	North Western
Type of Report Ecology Received:	Interim cleanup report
Site Register Issue:	92-47
County Code:	17
Contact:	Not reported
Report Title:	Not reported

NPDES:

Facility Status:	Active
Facility Type:	Industrial SW GP
Admin Region:	Headquarters
Latitude:	47.626891
Longitude:	-122.176354
Permit ID:	WAR000420
Permit Version:	5
Permit Status:	Active
Permit SubStatus:	Coverage Issued
Ecology Contact:	Greg Stegman
WRIA:	Cedar-Sammamish
Permit Expiration Date:	01/01/2015
Effective Date:	01/01/2010

110
NE
1/2-1
0.728 mi.
3841 ft.

CADMAN PREMIX CO INC **CSCSL S104971193**
1605 130TH AVE NE **ALLSITES N/A**
BELLEVUE, WA 98005

Relative:
Higher

Actual:
194 ft.

CSCSL:

Facility ID:	95738316
Region:	Northwest
Lat/Long:	47.624599000000 / -122.167129
Brownfield Status:	Not reported
Rank Status:	Not reported

CADMAN PREMIX CO INC (Continued) **S104971193**

Clean Up Siteid: 529
Site Status: Awaiting Cleanup
PSI?: Not reported
Contaminant Name: Petroleum Products - unspecified
Ground Water: C
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 95738316
Region: Northwest
Lat/Long: 47.624599000000 / -122.167129
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 529
Site Status: Awaiting Cleanup
PSI?: Not reported
Contaminant Name: Polynuclear Aromatic Hydrocarbons
Ground Water: S
Surface Water: Not reported
Soil: S
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 95738316
Latitude: 47.6245990
Longitude: -122.16712
Geographic location identifier (alias facid): 95738316
Facility Name: CADMAN PREMIX CO INC
Latitude Decimal Degrees: 47.624599000000003
Longitude Decimal Degrees: -122.167129
Coordinate Point Areal Extent Code: 2
Horizontal Accuracy Code: 7
Coordinate Point Geographic Position Code: 8
Location Verified Code: N

---

111 ENE 1/2-1 0.756 mi. 3993 ft.

Relative: Higher

Actual: 167 ft.

WILSON TRANSMISSION INC
1414 132ND AVE NE
BELLEVUE, WA 98005

RCRA-NonGen FINDS CSCSL ALLSITES LUST UST

1001806518
WAD982657793

RCRA-NonGen:
Date form received by agency: 06/24/2004
Facility name: WILSON TRANSMISSION INC
Facility address: 1414 132ND AVE NE
BELLEVUE, WA 98005
EPA ID: WAD982657793
Contact: MARK WAGNER

WILSON TRANSMISSION INC (Continued) **1001806518**

Contact address: 1414 132ND AVE NE
BELLEVUE, WA 98005-2223
Contact country: US
Contact telephone: (425)454-2822
Contact email: Not reported
EPA Region: 10
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: HIROSHI MYORUKU
Owner/operator address: 1414 132ND AVE NE
BELLEVUE, WA 98005
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/10/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2003
Facility name: WILSON TRANSMISSION INC
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110005347589

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

WILSON TRANSMISSION INC (Continued) **1001806518**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CSCSL:

Facility ID:	15492544
Region:	Northwest
Lat/Long:	47.622570000000 / -122.16432
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	8091
Site Status:	Awaiting Cleanup
PSI?:	Not reported
Contaminant Name:	Petroleum-Other
Ground Water:	Not reported
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

ALLSITES:

Facility Id:	15492544	
Latitude:	47.6225700	
Longitude:	-122.16432	
Geographic location identifier (alias facid):		15492544
Facility Name:		Wilson Transmission Inc
Latitude Decimal Degrees:		47.622570000000003
Longitude Decimal Degrees:		-122.16432
Coordinate Point Areal Extent Code:		99
Horizontal Accuracy Code:		99
Coordinate Point Geographic Position Code:		99
Location Verified Code:		N

LUST:

FS ID:	15492544
Cleanup Site ID:	8091
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	WILSON TRANSMISSION
Release Notification Date:	Not reported
Release Status Date:	12/11/1989
Site Response Unit Code:	Northwest
Lat/Long:	47.6225700 / -122.16432

FS ID:	15492544
Cleanup Site ID:	8091

WILSON TRANSMISSION INC (Continued) **1001806518**

Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Awaiting Cleanup
Alternate Name: WILSON TRANSMISSION
Release Notification Date: Not reported
Release Status Date: 07/01/2011
Site Response Unit Code: Northwest
Lat/Long: 47.6225700 / -122.16432

FS ID: 15492544
Cleanup Site ID: 8091
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: RCU
Alternate Name: WILSON TRANSMISSION
Release Notification Date: Not reported
Release Status Date: 08/01/2002
Site Response Unit Code: Northwest
Lat/Long: 47.6225700 / -122.16432

UST:
Facility ID: 15492544
Site ID: 2104
Lat Deg: 47
Lat Min: 37
Lat Sec: 21.252000000011435
Long Deg: -122
Long Min: 9
Long Sec: 51.552000000012868
UBI: Not reported
Phone Number: 2064542822

Tank ID: 43543
Tank Name: 1
Install Date: 12/31/1964
Capacity: 111 TO 1,100 Gallons
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Concrete
Tank Construction: Not reported
Tank Tightness Test: Not reported
Tank Corrosion Protection: Not reported
Pipe Material: Steel
Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported

WILSON TRANSMISSION INC (Continued) **1001806518**

Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

112
SSW
1/2-1
0.798 mi.
4212 ft.

Relative:
Lower

Actual:
94 ft.

MICHAELS TOYOTA
306 116TH AVE SE
BELLEVUE, WA 98004

RCRA-CESQG
FINDS
CSCSL
ALLSITES
LUST
UST
MANIFEST

1000282266
WAD048670848

RCRA-CESQG:
Date form received by agency: 02/26/2007
Facility name: MICHAELS TOYOTA
Facility address: 306 116TH AVE SE
BELLEVUE, WA 98004
EPA ID: WAD048670848
Mailing address: 120 116TH AVE NE
BELLEVUE, WA 98004-5215
Contact: RICK KUPFER
Contact address: 120 116TH AVE NE
BELLEVUE, WA 98004-5215
Contact country: US
Contact telephone: (425)455-9500
Contact email: Not reported
EPA Region: 10
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: RICK KUPFER
Owner/operator address: 120 116TH AVE NE
BELLEVUE, WA 98004
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2003
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

MICHAELS TOYOTA (Continued) **1000282266**

Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2005
Facility name: MICHAELS TOYOTA
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: MICHAELS TOYOTA
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/14/2008
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/08/2008
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/03/1997
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005321160

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource

MICHAELS TOYOTA (Continued) **1000282266**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CSCSL:

Facility ID:	41459519
Region:	Northwest
Lat/Long:	47.608950999999 / -122.186566
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	9048
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	Not reported
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	41459519
Region:	Northwest
Lat/Long:	47.608950999999 / -122.186566
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	9048
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Gasoline
Ground Water:	Not reported
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	41459519
Region:	Northwest
Lat/Long:	47.608950999999 / -122.186566
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	9048
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Other
Ground Water:	Not reported
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported

MICHAELS TOYOTA (Continued) **1000282266**

Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 41459519
Latitude: 47.6089509
Longitude: -122.18656
Geographic location identifier (alias facid): 41459519
Facility Name: Michaels Toyota
Latitude Decimal Degrees: 47.608950999999998
Longitude Decimal Degrees: -122.186566
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 13
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

LUST:
FS ID: 41459519
Cleanup Site ID: 9048
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: RCU
Alternate Name: IBSEN TOWING
Release Notification Date: Not reported
Release Status Date: 06/01/1995
Site Response Unit Code: Northwest
Lat/Long: 47.6089509 / -122.18656

FS ID: 41459519
Cleanup Site ID: 9048
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: IBSEN TOWING
Release Notification Date: Not reported
Release Status Date: 07/01/2011
Site Response Unit Code: Northwest
Lat/Long: 47.6089509 / -122.18656

FS ID: 41459519
Cleanup Site ID: 9048
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: IBSEN TOWING
Release Notification Date: Not reported
Release Status Date: 06/30/1989
Site Response Unit Code: Northwest
Lat/Long: 47.6089509 / -122.18656

UST:
Facility ID: 41459519
Site ID: 2219
Lat Deg: 47

MICHAELS TOYOTA (Continued) **1000282266**

Lat Min:	36
Lat Sec:	32.223599999991279
Long Deg:	-122
Long Min:	11
Long Sec:	11.637599999996837
UBI:	Not reported
Phone Number:	2064547201

Tank ID:	7593
Tank Name:	1
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

WA MANIFEST:

Facility Site ID Number:	41459519
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE

MICHAELS TOYOTA (Continued) **1000282266**

Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD048670848
Facility Address 2:	Not reported
TAX REG NBR:	600117397
NAICS CD:	44111
BUSINESS TYPE:	Not reported
MAIL NAME:	Michaels Toyota Inc
MAIL ADDR LINE1:	120 116TH AVE NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-5215
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Michaels Toyota
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	120 116TH AVE NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-5215
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)455-9500
LEGAL EFFECTIVE DATE:	8/4/1995
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Bruce Broadus
LAND ADDR LINE1:	120 116TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004-5215
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-9500
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	120 116TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-0000
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)455-9500
OPERATOR EFFECTIVE DATE:	1/1/2003
SITE CONTACT NAME:	Rick Kupfer
SITE CONTACT ADDR LINE1:	120 116th Ave NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)455-9500
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Rick Kupfer
FORM CONTACT ADDR LINE1:	120 116th Ave NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)455-9500
FORM CONTACT EMAIL:	rkupfer@michaelstoyota.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	FALSE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE

MICHAELS TOYOTA (Continued) **1000282266**

TRANSPORTS OTHRS WASTE: FALSE
RECYCLER ONSITE: FALSE
TRANSFER FACILITY: FALSE
OTHER EXEMPTION: Not reported
UW BATTERY GEN: FALSE
USED OIL TRANSPORTER: FALSE
USED OIL TRANSFER FACLTY: FALSE
USED OIL PROCESSOR: FALSE
USED OIL REREFINER: FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS: FALSE
USED OIL FUEL MRKTR MEETS SPECS: FALSE

Facility Site ID Number: 41459519
SWC Desc: Not reported
FWC Desc: Not reported
Form Comm: Not reported
Data Year: Not reported
Permit by Rule: No
Treatment by Generator: No
Mixed radioactive waste: No
Importer of hazardous waste: No
Immediate recycler: No
Treatment/Storage/Disposal/Recycling Facility: No
Generator of dangerous fuel waste: No
Generator marketing to burner: No
"Other marketers (i.e., blender, distributor, etc.)": No
Utility boiler burner: No
Industry boiler burner: No
Industrial Furnace: No
Smelter defferal: No
Universal waste - batteries - generate: No
Universal waste - thermostats - generate: No
Universal waste - mercury - generate: No
Universal waste - lamps - generate: No
Universal waste - batteries - accumulate: No
Universal waste - thermostats - accumulate: No
Universal waste - mercury - accumulate: No
Universal waste - lamps - accumulate: No
Destination Facility for Universal Waste: No
Off-specification used oil burner - utility boiler: No
Off-specification used oil burner - industrial boiler: No
Off-specification used oil burner - industrial furnace: No
EPA ID: WAD048670848
Facility Address 2: Not reported
TAX REG NBR: 600117397
NAICS CD: 44111
BUSINESS TYPE: Not reported
MAIL NAME: Michaels Toyota Inc
MAIL ADDR LINE1: 120 116TH AVE NE
MAIL CITY,ST,ZIP: BELLEVUE, WA 98004-5215
MAIL COUNTRY: UNITED STATES
LEGAL ORG NAME: Michaels Toyota
LEGAL ORG TYPE: Private
LEGAL ADDR LINE1: 120 116TH AVE NE
LEGAL CITY,ST,ZIP: BELLEVUE, WA 98004-5215
LEGAL COUNTRY: UNITED STATES
LEGAL PHONE NBR: (425)455-9500

MICHAELS TOYOTA (Continued) **1000282266**

LEGAL EFFECTIVE DATE:	8/4/1995
LAND ORG NAME:	Not reported
LAND ORG TYPE:	Private
LAND PERSON NAME:	Bruce Broadus
LAND ADDR LINE1:	120 116TH AVE NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004-5215
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)455-9500
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	120 116TH AVE NE
OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-0000
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)455-9500
OPERATOR EFFECTIVE DATE:	1/1/2003
SITE CONTACT NAME:	Rick Kupfer
SITE CONTACT ADDR LINE1:	120 116th Ave NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)455-9500
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Rick Kupfer
FORM CONTACT ADDR LINE1:	120 116th Ave NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)455-9500
FORM CONTACT EMAIL:	rkupfer@michaelstoyota.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Z113 **STAR RENTALS INC BELLEVUE** **CSCSL** **U001125857**
NE **12900 NORTHRUP WY** **ALLSITES** **N/A**
1/2-1 **BELLEVUE, WA 98005** **LUST**
0.853 mi. **UST**
4503 ft. **Site 1 of 2 in cluster Z**

Relative: Higher

Actual: 231 ft.

CSCSL:

Facility ID:	93312988
Region:	Northwest
Lat/Long:	47.628070999999 / -122.1694130000
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	11110
Site Status:	Cleanup Started

STAR RENTALS INC BELLEVUE (Continued) **U001125857**

PSI?: Not reported
Contaminant Name: Benzene
Ground Water: Not reported
Surface Water: Not reported
Soil: S
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 93312988
Region: Northwest
Lat/Long: 47.628070999999 / -122.1694130000
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 11110
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Diesel
Ground Water: Not reported
Surface Water: Not reported
Soil: RB
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 93312988
Region: Northwest
Lat/Long: 47.628070999999 / -122.1694130000
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 11110
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Gasoline
Ground Water: Not reported
Surface Water: Not reported
Soil: RB
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 93312988
Region: Northwest
Lat/Long: 47.628070999999 / -122.1694130000
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 11110
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Other
Ground Water: Not reported
Surface Water: Not reported
Soil: S
Sediment: Not reported

STAR RENTALS INC BELLEVUE (Continued) **U001125857**

Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 93312988
Latitude: 47.6280709
Longitude: -122.16941
Geographic location identifier (alias facid): 93312988
Facility Name: STAR RENTALS INC BELLEVUE
Latitude Decimal Degrees: 47.628070999999998
Longitude Decimal Degrees: -122.16941300000001
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 6
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

LUST:
FS ID: 93312988
Cleanup Site ID: 11110
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Awaiting Cleanup
Alternate Name: STAR RENTALS INC
Release Notification Date: Not reported
Release Status Date: 02/13/1997
Site Response Unit Code: Northwest
Lat/Long: 47.6280709 / -122.16941

FS ID: 93312988
Cleanup Site ID: 11110
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: RCU
Alternate Name: STAR RENTALS INC
Release Notification Date: Not reported
Release Status Date: 04/15/1997
Site Response Unit Code: Northwest
Lat/Long: 47.6280709 / -122.16941

FS ID: 93312988
Cleanup Site ID: 11110
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: STAR RENTALS INC
Release Notification Date: Not reported
Release Status Date: 07/01/2011
Site Response Unit Code: Northwest
Lat/Long: 47.6280709 / -122.16941

UST:
Facility ID: 93312988
Site ID: 9291
Lat Deg: 47

STAR RENTALS INC BELLEVUE (Continued) **U001125857**

Lat Min:	37
Lat Sec:	41.05559999999457
Long Deg:	-122
Long Min:	10
Long Sec:	9.8868000000209122
UBI:	6011112580010005
Phone Number:	2068855522

Tank ID:	419053
Tank Name:	3
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/3/1997
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Not reported
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	7/3/1997
Tag Number:	Not reported

Tank ID:	43600
Tank Name:	2
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/3/1997
Tank Status:	Removed
Tank Permit Expiration Date:	9/30/1997
Tank Closure Date:	1/1/0001
Tank Pumping System:	Other
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Other
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Other
Pipe Material:	Steel
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Not reported

STAR RENTALS INC BELLEVUE (Continued) **U001125857**

Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Other
Tank Primary Release Detection:	Weekly Manual Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	43627
Tank Name:	1
Install Date:	1/1/1975
Capacity:	1,101 to 2,000 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	7/3/1997
Tank Status:	Removed
Tank Permit Expiration Date:	9/30/1997
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Spill Bucket/Spill Box
Tank Overfill Prevention:	Other
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Other
Pipe Material:	Steel
Pipe Construction:	Single Wall Pipe
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Other
Tank Primary Release Detection:	Weekly Manual Gauging
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Annual
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Z114 **ARCO 6217** **RCRA-SQG** **1004794048**
NE **12903 NE 20TH ST** **FINDS** **WAD988484978**
1/2-1 **BELLEVUE, WA 98004** **CSCSL**
0.854 mi. **ALLSITES**
4510 ft. **Site 2 of 2 in cluster Z** **LUST**
MANIFEST
Relative: **VCP**
Higher **FINANCIAL ASSURANCE**

Actual: **231 ft.**

RCRA-SQG:

Date form received by agency:	02/26/2008
Facility name:	ARCO 6217
Facility address:	12903 NE 20TH ST BELLEVUE, WA 98004
EPA ID:	WAD988484978
Mailing address:	PO BOX 6038 ARTESIA, CA 90702
Contact:	RUTH HA
Contact address:	PO BOX 6038 ARTESIA, CA 90702
Contact country:	US

ARCO 6217 (Continued) **1004794048**

Contact telephone: (503)524-6191
Contact email: Not reported
EPA Region: 10
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: HANI INC
Owner/operator address: PO BOX 6038
ARTESIA, CA 90702
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 09/23/1998
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2007
Facility name: ARCO 6217
Classification: Small Quantity Generator

Date form received by agency: 12/31/2005
Facility name: ARCO 6217
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: ARCO 6217
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110005359904

ARCO 6217 (Continued) **1004794048**

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CSCSL:

Facility ID:	26773589
Region:	Northwest
Lat/Long:	47.627960000000 / -122.169431
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	4110
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Metals Priority Pollutants
Ground Water:	B
Surface Water:	Not reported
Soil:	B
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	26773589
Region:	Northwest
Lat/Long:	47.627960000000 / -122.169431
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	4110
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum Products - unspecified
Ground Water:	B
Surface Water:	Not reported
Soil:	B
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

ALLSITES:

Facility Id:	26773589
Latitude:	47.6279600

ARCO 6217 (Continued) **1004794048**

Longitude:	-122.16943
Geographic location identifier (alias facid):	26773589
Facility Name:	Arco 6217
Latitude Decimal Degrees:	47.627960000000002
Longitude Decimal Degrees:	-122.169431
Coordinate Point Areal Extent Code:	4
Horizontal Accuracy Code:	6
Coordinate Point Geographic Position Code:	5
Location Verified Code:	N

LUST:

FS ID:	26773589
Cleanup Site ID:	8525
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	RCU
Alternate Name:	ARCO STATION # 6217
Release Notification Date:	Not reported
Release Status Date:	09/28/2006
Site Response Unit Code:	Northwest
Lat/Long:	47.6279600 / -122.16943

FS ID:	26773589
Cleanup Site ID:	8525
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Monitoring
Alternate Name:	ARCO STATION # 6217
Release Notification Date:	Not reported
Release Status Date:	08/28/1996
Site Response Unit Code:	Northwest
Lat/Long:	47.6279600 / -122.16943

FS ID:	26773589
Cleanup Site ID:	8525
Cleanup Unit Type:	Upland
Process Type:	Independent Action
Facility Status:	Cleanup Started
Alternate Name:	ARCO STATION # 6217
Release Notification Date:	Not reported
Release Status Date:	11/05/1992
Site Response Unit Code:	Northwest
Lat/Long:	47.6279600 / -122.16943

WA MANIFEST:

Facility Site ID Number:	26773589
SWC Desc:	Not reported
FWC Desc:	D001 & D018
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE

ARCO 6217 (Continued) **1004794048**

Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE
Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD988484978
Facility Address 2:	Not reported
TAX REG NBR:	409018414
NAICS CD:	44711
BUSINESS TYPE:	Gas station with store
MAIL NAME:	BP West Coast Products
MAIL ADDR LINE1:	PO Box 6038
MAIL CITY,ST,ZIP:	ARTESIA, CA 90702
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BP West Coast Products LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO BOX 6038
LEGAL CITY,ST,ZIP:	ARTESIA, CA 90702
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(714)670-3958
LEGAL EFFECTIVE DATE:	9/2/1992
LAND ORG NAME:	BP West Coast Products LLC
LAND ORG TYPE:	Private
LAND PERSON NAME:	Teresa Santana
LAND ADDR LINE1:	PO BOX 6038
LAND CITY,ST,ZIP:	ARTESIA, CA 90702
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(714) 670-3958
OPERATOR ORG NAME:	Hani Inc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	12903 NE 20th St
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98004
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-885-9866
OPERATOR EFFECTIVE DATE:	9/23/1998
SITE CONTACT NAME:	Teresa Santana
SITE CONTACT ADDR LINE1:	PO BOX 6038
SITE CONTACT ZIP:	ARTESIA, CA 90702
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(714) 670-3958
SITE CONTACT EMAIL:	santanta@bp.com
FORM CONTACT NAME:	Teresa Santana

ARCO 6217 (Continued) **1004794048**

FORM CONTACT ADDR LINE1:	PO BOX 6038
FORM CONTACT CITY,ST,ZIP:	ARTESIA, CA 90702
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(714) 670-3958
FORM CONTACT EMAIL:	santanta@bp.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	TRUE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

Facility Site ID Number:	26773589
SWC Desc:	Not reported
FWC Desc:	D001 & D018
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD988484978
Facility Address 2:	Not reported
TAX REG NBR:	409018414
NAICS CD:	44711
BUSINESS TYPE:	Gas station with store

ARCO 6217 (Continued) **1004794048**

MAIL NAME:	BP West Coast Products
MAIL ADDR LINE1:	PO Box 6038
MAIL CITY,ST,ZIP:	ARTESIA, CA 90702
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BP West Coast Products LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO BOX 6038
LEGAL CITY,ST,ZIP:	ARTESIA, CA 90702
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(714)670-3958
LEGAL EFFECTIVE DATE:	9/2/1992
LAND ORG NAME:	BP West Coast Products LLC
LAND ORG TYPE:	Private
LAND PERSON NAME:	Teresa Santana
LAND ADDR LINE1:	PO BOX 6038
LAND CITY,ST,ZIP:	ARTESIA, CA 90702
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(714) 670-3958
OPERATOR ORG NAME:	Hani Inc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	12903 NE 20th St
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98004
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-885-9866
OPERATOR EFFECTIVE DATE:	9/23/1998
SITE CONTACT NAME:	Teresa Santana
SITE CONTACT ADDR LINE1:	PO BOX 6038
SITE CONTACT ZIP:	ARTESIA, CA 90702
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(714) 670-3958
SITE CONTACT EMAIL:	santanta@bp.com
FORM CONTACT NAME:	Teresa Santana
FORM CONTACT ADDR LINE1:	PO BOX 6038
FORM CONTACT CITY,ST,ZIP:	ARTESIA, CA 90702
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(714) 670-3958
FORM CONTACT EMAIL:	santanta@bp.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

Facility Site ID Number:	26773589
SWC Desc:	Not reported
FWC Desc:	D001 & D018

ARCO 6217 (Continued) **1004794048**

Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD988484978
Facility Address 2:	Not reported
TAX REG NBR:	409018414
NAICS CD:	44711
BUSINESS TYPE:	Gas station with store
MAIL NAME:	BP West Coast Products
MAIL ADDR LINE1:	PO Box 6038
MAIL CITY,ST,ZIP:	ARTESIA, CA 90702
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BP West Coast Products LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	PO BOX 6038
LEGAL CITY,ST,ZIP:	ARTESIA, CA 90702
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(714)670-3958
LEGAL EFFECTIVE DATE:	9/2/1992
LAND ORG NAME:	BP West Coast Products LLC
LAND ORG TYPE:	Private
LAND PERSON NAME:	Teresa Santana
LAND ADDR LINE1:	PO BOX 6038
LAND CITY,ST,ZIP:	ARTESIA, CA 90702
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	503-524-6191
OPERATOR ORG NAME:	Hani Inc
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	12903 NE 20th St
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98004
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	425-885-9866
OPERATOR EFFECTIVE DATE:	09/23/98

ARCO 6217 (Continued) **1004794048**

SITE CONTACT NAME:	Ruth Ha
SITE CONTACT ADDR LINE1:	PO BOX 6038
SITE CONTACT ZIP:	ARTESIA, CA 90702
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	503-524-6191
SITE CONTACT EMAIL:	harx00@bp.com
FORM CONTACT NAME:	Ruth Ha
FORM CONTACT ADDR LINE1:	PO BOX 6038
FORM CONTACT CITY,ST,ZIP:	ARTESIA, CA 90702
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	503-524-6191
FORM CONTACT EMAIL:	harx00@bp.com
GEN STATUS CD:	MQG
MONTHLY GENERATION:	False
BATCH GENERATION:	True
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

VCP:

edr_fstat:	WA
edr_fzip:	98004
edr_fcnty:	KING COUNTY
edr_zip:	Not reported
Facility ID:	26773589
VCP Status:	VCP
VCP:	Not reported
Ecology Status:	Cleanup Started
NFA Type:	Cleanup Started
Date NFA:	Cleanup Started
Rank:	Cleanup Started

WA FINANCIAL ASSURANCE:

edr_fstat:	WA
edr_fzip:	980051903
edr_fcnty:	Not reported
edr_zip:	Not reported
DOE Site ID:	8805
Site Type:	PLIA
Financial Resp Type:	Colony (GUS)
Inception Date:	08/10/2011
Expiration Date:	08/10/2012

115 West 1/2-1 0.909 mi. 4798 ft.

FORMER THINKER TOYS
10610 NE 8TH ST
BELLEVUE, WA 98004

FINDS CSCSL ALLSITES MANIFEST VCP

1008001498
N/A

Relative: Higher

Actual: 162 ft.

FINDS:

Registry ID: 110020768828

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

CSCSL:

Facility ID:	2462690
Region:	Northwest
Lat/Long:	47.617603000000 / -122.198733
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	2477
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Halogenated Organics
Ground Water:	C
Surface Water:	Not reported
Soil:	C
Sediment:	Not reported
Air:	C
Bedrock:	Not reported
Responsible Unit:	Northwest

ALLSITES:

Facility Id:	2462690
Latitude:	47.6176030
Longitude:	-122.19873
Geographic location identifier (alias facid):	2462690
Facility Name:	Thinker Toys Former
Latitude Decimal Degrees:	47.617603000000003
Longitude Decimal Degrees:	-122.198733
Coordinate Point Areal Extent Code:	4
Horizontal Accuracy Code:	99
Coordinate Point Geographic Position Code:	8
Location Verified Code:	Not reported
Geographic Location Identifier (Alias Facid):	2462690
Interaction (Aka Env Int) Type Code:	SCS
Interaction (Aka Env Int) Description:	State Cleanup Site
Interaction Status:	A
Federal Program Indentifier:	Not reported
Interaction Start Date:	02/07/2005
Interaction End Date:	Not reported
prgm_facil:	Thinker Toys Former

FORMER THINKER TOYS (Continued) **1008001498**

cur_sys_pr:	TOXICS
cur_sys_nm:	ISIS
Geographic Location Identifier (Alias Facid):	2462690
Interaction (Aka Env Int) Type Code:	HWG
Interaction (Aka Env Int) Description:	Hazardous Waste Generator
Interaction Status:	I
Federal Program Indentifier:	WAH000026182
Interaction Start Date:	05/31/2005
Interaction End Date:	12/31/2005
prgm_facil:	Not reported
cur_sys_pr:	HAZWASTE
cur_sys_nm:	TURBOWASTE
Geographic Location Identifier (Alias Facid):	2462690
Interaction (Aka Env Int) Type Code:	HWG
Interaction (Aka Env Int) Description:	Hazardous Waste Generator
Interaction Status:	A
Federal Program Indentifier:	WAH000026182
Interaction Start Date:	05/24/2010
Interaction End Date:	Not reported
prgm_facil:	THINKER TOYS FORMER
cur_sys_pr:	HAZWASTE
cur_sys_nm:	TURBOWASTE
Geographic Location Identifier (Alias Facid):	2462690
Interaction (Aka Env Int) Type Code:	VOLCLNST
Interaction (Aka Env Int) Description:	Voluntary Cleanup Sites
Interaction Status:	A
Federal Program Indentifier:	NW2338
Interaction Start Date:	09/24/2010
Interaction End Date:	Not reported
prgm_facil:	Thinker Toys Former
cur_sys_pr:	TOXICS
cur_sys_nm:	ISIS

WA MANIFEST:

Facility Site ID Number:	2462690
SWC Desc:	Not reported
FWC Desc:	F002 D039
Form Comm:	Additional remedial investigtion derived waste soil and groundwater with detections of PCE with TCF and DCF breakdown products/compounds. Waste generated from soil and groundwater testing, completed towards the end of 2010. Waste not shipped off site until February 2011 and pursuant to Department of Ecology's reporting manual, will be submitted with the company's 2011 annual report.
Data Year:	2010
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False

FORMER THINKER TOYS (Continued) **1008001498**

Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAH000026182
Facility Address 2:	Not reported
TAX REG NBR:	902302226
NAICS CD:	237210
BUSINESS TYPE:	Property Mgmt Real Estate
MAIL NAME:	BV Holdings LLC
MAIL ADDR LINE1:	833 108th Ave NE Ste 200
MAIL CITY,ST,ZIP:	Bellevue, WA 98004
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BV Holdings LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	833 108th Ave NE Ste 200
LEGAL CITY,ST,ZIP:	Bellevue, WA 98004
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(425)732-3675
LEGAL EFFECTIVE DATE:	9/25/2002
LAND ORG NAME:	BV Holdings LLC
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	833 108th Ave NE Ste 200
LAND CITY,ST,ZIP:	Bellevue, WA 98004
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(425)732-3675
OPERATOR ORG NAME:	BV Holdings LLC
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	833 108th Ave NE Ste 200
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98004
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)732-3672
OPERATOR EFFECTIVE DATE:	9/25/2002
SITE CONTACT NAME:	Mike Nielson
SITE CONTACT ADDR LINE1:	833 108th Ave NE Ste 200
SITE CONTACT ZIP:	Bellevue, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)974-7078
SITE CONTACT EMAIL:	michaeln@netwasatch.com
FORM CONTACT NAME:	Mike Nielson
FORM CONTACT ADDR LINE1:	833 108th Ave NE Ste 200
FORM CONTACT CITY,ST,ZIP:	Bellevue, WA 98004
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)974-7078

FORMER THINKER TOYS (Continued) **1008001498**

FORM CONTACT EMAIL:	michaeln@netwasatch.com
GEN STATUS CD:	MQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	True
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	2462690
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAH000026182
Facility Address 2:	Not reported
TAX REG NBR:	902302226
NAICS CD:	237210
BUSINESS TYPE:	Property Mgmt Real Estate
MAIL NAME:	BV Holdings LLC
MAIL ADDR LINE1:	399 N Main
MAIL ADDR LINE2:	Ste 200
MAIL CITY,ST,ZIP:	Logan, UT 84321

FORMER THINKER TOYS (Continued) **1008001498**

MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	BV Holdings LLC
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	399 N Main
LEGAL ADDR LINE2:	Ste 200
LEGAL CITY,ST,ZIP:	Logan, UT 84321
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(435)755-2032
LEGAL EFFECTIVE DATE:	9/25/2002
LAND ORG NAME:	BV Holdings LLC
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	399 N Main
LAND ADDR LINE2:	Ste 200
LAND CITY,ST,ZIP:	Logan, UT 84321
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(435)755-2032
OPERATOR ORG NAME:	BV Holdings LLC
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	10620 NE 8th
OPERATOR ADDR LINE2:	Ste 201
OPERATOR CITY,ST,ZIP:	Bellevue, WA 98004
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)467-8451
OPERATOR EFFECTIVE DATE:	9/25/2002
SITE CONTACT NAME:	Lee Stubbe
SITE CONTACT ADDR LINE1:	10620 NE 8th
SITE CONTACT ADDR LINE2:	Ste 201
SITE CONTACT ZIP:	Bellevue, WA 98004
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)467-8451
SITE CONTACT EMAIL:	lstubbe@netwasatch.com
FORM CONTACT NAME:	Bret Rigby
FORM CONTACT ADDR LINE1:	399 N Main
FORM CONTACT ADDR LINE2:	Ste 200
FORM CONTACT CITY,ST,ZIP:	Logan, UT 84321
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(435)755-2032
FORM CONTACT EMAIL:	brigby@netwasatch.com
GEN STATUS CD:	LQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	Yes
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

FORMER THINKER TOYS (Continued) **1008001498**

VCP:
edr_fstat: WA
edr_fzip: 98004
edr_fcnty: KING COUNTY
edr_zip: Not reported
Facility ID: 2462690
VCP Status: VCP
VCP: Not reported
Ecology Status: Cleanup Started
NFA Type: Cleanup Started
Date NFA: Cleanup Started
Rank: Cleanup Started

---

116 West 1/2-1 0.924 mi. 4880 ft.

Relative: Higher

Actual: 166 ft.

BELLEVUE CADILLAC
1001 106TH AVE NE
BELLEVUE, WA 98004

RCRA-NonGen FINDS CSCSL ALLSITES MANIFEST VCP

1001806147
WAD061680096

RCRA-NonGen:
Date form received by agency: 02/08/2006
Facility name: BELLEVUE CADILLAC
Facility address: 1001 106TH AVE NE
BELLEVUE, WA 98004
EPA ID: WAD061680096
Contact: JERRY ANDRIST
Contact address: 1001 106TH AVE NE
BELLEVUE, WA 98004-4317
Contact country: US
Contact telephone: (425)450-1717
Contact email: Not reported
EPA Region: 10
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: JERRY ANDRIST
Owner/operator address: 1001 106TH AVE NE
BELLEVUE, WA 98004
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/12/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No

BELLEVUE CADILLAC (Continued) **1001806147**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2005
Facility name: BELLEVUE CADILLAC
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: BELLEVUE CADILLAC
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 03/15/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005323925

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CSCSL:
Facility ID: 84476447
Region: Northwest
Lat/Long: 47.619370000000 / -122.1989899999
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 6755

BELLEVUE CADILLAC (Continued) **1001806147**

Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Metals Priority Pollutants
Ground Water: B
Surface Water: Not reported
Soil: B
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 84476447
Region: Northwest
Lat/Long: 47.619370000000 / -122.1989899999
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 6755
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum Products - unspecified
Ground Water: B
Surface Water: Not reported
Soil: Not reported
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 84476447
Region: Northwest
Lat/Long: 47.619370000000 / -122.1989899999
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 6755
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Other
Ground Water: Not reported
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 84476447
Latitude: 47.6193700
Longitude: -122.19898
Geographic location identifier (alias facid): 84476447
Facility Name: Bellevue Cadillac
Latitude Decimal Degrees: 47.619370000000004
Longitude Decimal Degrees: -122.19898999999999
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 99
Location Verified Code: N

BELLEVUE CADILLAC (Continued) **1001806147**

WA MANIFEST:

Facility Site ID Number:	84476447
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No
Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD061680096
Facility Address 2:	Not reported
TAX REG NBR:	601099774
NAICS CD:	44111
BUSINESS TYPE:	New Car Dealer
MAIL NAME:	Bellevue Cadillac
MAIL ADDR LINE1:	1001 106th Ave NE
MAIL CITY,ST,ZIP:	BELLEVUE, WA 98004-4317
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Ragnar Pettersson Ron Rennebohn
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1001 106th Ave NE
LEGAL CITY,ST,ZIP:	BELLEVUE, WA 98004-4317
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(206)450-1717
LEGAL EFFECTIVE DATE:	12/1/1997
LAND ORG NAME:	Ragnar Pettersson Ron Rennebohn
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1001 106th Ave NE
LAND CITY,ST,ZIP:	BELLEVUE, WA 98004-4317
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(206)450-1717
OPERATOR ORG NAME:	Not reported
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1001 106TH AVE NE

BELLEVUE CADILLAC (Continued) **1001806147**

OPERATOR CITY,ST,ZIP:	BELLEVUE, WA 98004-4317
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(206)447-1717
OPERATOR EFFECTIVE DATE:	8/12/1996
SITE CONTACT NAME:	Jerry Andrist
SITE CONTACT ADDR LINE1:	1001 106th Ave NE
SITE CONTACT ZIP:	BELLEVUE, WA 98004-4317
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)450-1717
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Jerry Andrist
FORM CONTACT ADDR LINE1:	1001 106th Ave NE
FORM CONTACT CITY,ST,ZIP:	BELLEVUE, WA 98004-4317
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(425)450-1717
FORM CONTACT EMAIL:	jerrya@gmcarsnw.com
GEN STATUS CD:	XQG
MONTHLY GENERATION:	No
BATCH GENERATION:	No
ONE TIME GENERATION:	No
TRANSPORTS OWN WASTE:	No
TRANSPORTS OTHRS WASTE:	No
RECYCLER ONSITE:	No
TRANSFER FACILITY:	No
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	No
USED OIL TRANSPORTER:	No
USED OIL TRANSFER FACLTY:	No
USED OIL PROCESSOR:	No
USED OIL REREFINER:	No
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	No
USED OIL FUEL MRKTR MEETS SPECS:	No

VCP:

edr_fstat:	WA
edr_fzip:	98004
edr_fcnty:	KING COUNTY
edr_zip:	Not reported
Facility ID:	84476447
VCP Status:	VCP
VCP:	Not reported
Ecology Status:	Cleanup Started
NFA Type:	Cleanup Started
Date NFA:	Cleanup Started
Rank:	Cleanup Started

---

117 **LOWES HIW 040** **RCRA-NonGen** **1000312762**
North **11959 NORTHUP WAY** **FINDS** **WAD173823568**
1/2-1 **BELLEVUE, WA 98005** **CSCSL**
0.934 mi. **ALLSITES**
4933 ft. **LUST**
UST
Relative: **MANIFEST**
Higher **ICR**

Actual: RCRA-NonGen:
178 ft. Date form received by agency: 03/29/2010

LOWES HIW 040 (Continued) **1000312762**

Facility name:	LOWES HIW 040
Facility address:	11959 NORTHUP WAY BELLEVUE, WA 98005
EPA ID:	WAD173823568
Mailing address:	P.O. BOX 1000 MAILCODE A2ELP MOORESVILLE, WA 28117
Contact:	MANAGER ON DUTY
Contact address:	11959 NORTHRUP WAY BELLEVUE, WA 98005
Contact country:	US
Contact telephone:	(425) 646-9031
Contact email:	Not reported
EPA Region:	10
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	LOWES HIW INC
Owner/operator address:	101 ANDOVER PARK E. SUITE 200 TUKWILA, 98188
Owner/operator country:	US
Owner/operator telephone:	(206)242-8570
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1900
Owner/Op end date:	Not reported

Owner/operator name:	LOWE'S HIW, INC.
Owner/operator address:	101 ANDOVER PARK E. SUITE 200 TUKWILA, 98188
Owner/operator country:	US
Owner/operator telephone:	(206)242-8570
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1900
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

LOWES HIW 040 (Continued) **1000312762**

Historical Generators:
Date form received by agency: 04/24/2008
Facility name: LOWES HIW 040
Classification: Not a generator, verified

Date form received by agency: 12/31/2007
Facility name: LOWES HIW 040
Classification: Not a generator, verified

Date form received by agency: 12/31/2005
Facility name: LOWES HIW 040
Classification: Not a generator, verified

Date form received by agency: 12/31/2003
Facility name: LOWES HIW 040
Classification: Not a generator, verified

Date form received by agency: 03/01/2000
Facility name: LOWES HIW 040
Classification: Large Quantity Generator

Date form received by agency: 09/01/1993
Facility name: LOWES HIW 040
Site name: VERNELS FINE CANDIES INC
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 11/08/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110005333139

Environmental Interest/Information System

Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

LOWES HIW 040 (Continued) **1000312762**

CSCSL:
Facility ID: 36286977
Region: Northwest
Lat/Long: 47.631580999999 / -122.1821439999
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 8878
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Diesel
Ground Water: C
Surface Water: Not reported
Soil: RB
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 36286977
Latitude: 47.6315809
Longitude: -122.18214
Geographic location identifier (alias facid): 36286977
Facility Name: Lowes HIW 040
Latitude Decimal Degrees: 47.631580999999997
Longitude Decimal Degrees: -122.18214399999999
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 6
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

LUST:
FS ID: 36286977
Cleanup Site ID: 8878
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: VERNELLS CANDY
Release Notification Date: Not reported
Release Status Date: 07/01/2011
Site Response Unit Code: Northwest
Lat/Long: 47.6315809 / -122.18214

FS ID: 36286977
Cleanup Site ID: 8878
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: VERNELLS CANDY
Release Notification Date: Not reported
Release Status Date: 06/04/1992
Site Response Unit Code: Northwest
Lat/Long: 47.6315809 / -122.18214

FS ID: 36286977

LOWES HIW 040 (Continued) **1000312762**

Cleanup Site ID: 8878
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: RCU
Alternate Name: VERNELLS CANDY
Release Notification Date: Not reported
Release Status Date: 06/01/1995
Site Response Unit Code: Northwest
Lat/Long: 47.6315809 / -122.18214

UST:
Facility ID: 36286977
Site ID: 9131
Lat Deg: 47
Lat Min: 37
Lat Sec: 53.691599999989421
Long Deg: -122
Long Min: 10
Long Sec: 55.718399999977919
UBI: Not reported
Phone Number: 2064558400

Tank ID: 5070
Tank Name: 2
Install Date: 12/31/1964
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Steel
Tank Construction: Not reported
Tank Tightness Test: Not reported
Tank Corrosion Protection: Sacrificial Anode
Pipe Material: Not reported
Pipe Construction: Not reported
Pipe Primary Release Detection: Not reported
Pipe Second Release Detection: Not reported
Pipe Corrosion Protection: Not reported
Tank Primary Release Detection: Not reported
Tank Second Release Detection: Not reported
Pipe Tightness Test: Not reported
Tank Actual Status Date: 8/6/1996
Tag Number: Not reported

Tank ID: 5133
Tank Name: 1
Install Date: 12/31/1964
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed

LOWES HIW 040 (Continued) **1000312762**

TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Sacrificial Anode
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	5203
Tank Name:	3
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Closed in Place
TankSystem Status Change Date:	8/26/1996
Tank Status:	Closed in Place
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Not reported
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

WA MANIFEST:

Facility Site ID Number:	36286977
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2010

LOWES HIW 040 (Continued) **1000312762**

Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD173823568
Facility Address 2:	Not reported
TAX REG NBR:	601213703
NAICS CD:	444110
BUSINESS TYPE:	Not reported
MAIL NAME:	LOWE'S HIW, INC.
MAIL ADDR LINE1:	P.O. BOX 1000
MAIL ADDR LINE2:	MAILCODE A2ELP
MAIL CITY,ST,ZIP:	MOORESVILLE, NC 28117
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Lowes HIW Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	101 ANDOVER PARK E.
LEGAL ADDR LINE2:	SUITE 200
LEGAL CITY,ST,ZIP:	TUKWILA, WA 98188
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(206)242-8570
LEGAL EFFECTIVE DATE:	Not reported
LAND ORG NAME:	Lowes HIW Inc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	101 ANDOVER PARK E.
LAND ADDR LINE2:	SUITE 200
LAND CITY,ST,ZIP:	TUKWILA, WA 98188
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(206)242-8570
OPERATOR ORG NAME:	LOWE'S HIW, INC.
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	101 ANDOVER PARK E.
OPERATOR ADDR LINE2:	SUITE 200
OPERATOR CITY,ST,ZIP:	TUKWILA, WA 98188
OPERATOR COUNTRY:	UNITED STATES

LOWES HIW 040 (Continued) **1000312762**

OPERATOR PHONE NBR:	(206)242-8570
OPERATOR EFFECTIVE DATE:	Not reported
SITE CONTACT NAME:	MANAGER ON DUTY
SITE CONTACT ADDR LINE1:	11959 NORTHRUP WAY
SITE CONTACT ZIP:	BELLEVUE, WA 98005-1919
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)646-9031
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	ROB GASS
FORM CONTACT ADDR LINE1:	P.O. BOX 1000
FORM CONTACT ADDR LINE2:	MAILCODE A2ELP
FORM CONTACT CITY,ST,ZIP:	MOORESVILLE, NC 28117
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(704)758-6033
FORM CONTACT EMAIL:	ROBERT.A.GASS@LOWES.COM
GEN STATUS CD:	XQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	36286977
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	FALSE
Treatment by Generator:	FALSE
Mixed radioactive waste:	FALSE
Importer of hazardous waste:	FALSE
Immediate recycler:	FALSE
Treatment/Storage/Disposal/Recycling Facility:	FALSE
Generator of dangerous fuel waste:	FALSE
Generator marketing to burner:	FALSE
"Other marketers (i.e., blender, distributor, etc.)":	FALSE
Utility boiler burner:	FALSE
Industry boiler burner:	FALSE
Industrial Furnace:	FALSE
Smelter defferal:	FALSE
Universal waste - batteries - generate:	FALSE
Universal waste - thermostats - generate:	FALSE
Universal waste - mercury - generate:	FALSE
Universal waste - lamps - generate:	FALSE
Universal waste - batteries - accumulate:	FALSE
Universal waste - thermostats - accumulate:	FALSE
Universal waste - mercury - accumulate:	FALSE

LOWES HIW 040 (Continued) **1000312762**

Universal waste - lamps - accumulate:	FALSE
Destination Facility for Universal Waste:	FALSE
Off-specification used oil burner - utility boiler:	FALSE
Off-specification used oil burner - industrial boiler:	FALSE
Off-specification used oil burner - industrial furnace:	FALSE
EPA ID:	WAD173823568
Facility Address 2:	Not reported
TAX REG NBR:	601213703
NAICS CD:	44413
BUSINESS TYPE:	Not reported
MAIL NAME:	Not reported
MAIL ADDR LINE1:	8015 W KENTON CIRCLE STE 130
MAIL CITY,ST,ZIP:	HUNTSVILLE, NC 28078
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Lowes HIW Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1605 Curtis Bridge Road
LEGAL CITY,ST,ZIP:	WILKESBORO, NC 28697
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(336)658-4095
LEGAL EFFECTIVE DATE:	7/29/2000
LAND ORG NAME:	Lowes HIW Inc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1605 Curtis Bridge Road
LAND CITY,ST,ZIP:	WILKESBORO, NC 28697
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(336)658-4095
OPERATOR ORG NAME:	LOWES HIW
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1605 Curtis Bridge Road
OPERATOR CITY,ST,ZIP:	WILKESBORO, NC 28697
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)227-5740
OPERATOR EFFECTIVE DATE:	9/26/1996
SITE CONTACT NAME:	Scott Biesecker
SITE CONTACT ADDR LINE1:	11919 Northup Way
SITE CONTACT ZIP:	BELLEVUE, WA 98005
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)646-9031
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Damon Chappell
FORM CONTACT ADDR LINE1:	8015 W KENTON CIRCLE
FORM CONTACT ADDR LINE2:	STE 130
FORM CONTACT CITY,ST,ZIP:	HUNTSVILLE, NC 28078
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	704-655-6024
FORM CONTACT EMAIL:	damon.m.chappell@lowes.com
GEN STATUS CD:	SQG
MONTHLY GENERATION:	FALSE
BATCH GENERATION:	TRUE
ONE TIME GENERATION:	FALSE
TRANSPORTS OWN WASTE:	FALSE
TRANSPORTS OTHRS WASTE:	FALSE
RECYCLER ONSITE:	FALSE
TRANSFER FACILITY:	FALSE
OTHER EXEMPTION:	Not reported

LOWES HIW 040 (Continued) **1000312762**

UW BATTERY GEN:	FALSE
USED OIL TRANSPORTER:	FALSE
USED OIL TRANSFER FACLTY:	FALSE
USED OIL PROCESSOR:	FALSE
USED OIL REREFINER:	FALSE
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	FALSE
USED OIL FUEL MRKTR MEETS SPECS:	FALSE

Facility Site ID Number:	36286977
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	2009
Permit by Rule:	False
Treatment by Generator:	False
Mixed radioactive waste:	False
Importer of hazardous waste:	False
Immediate recycler:	False
Treatment/Storage/Disposal/Recycling Facility:	False
Generator of dangerous fuel waste:	False
Generator marketing to burner:	False
"Other marketers (i.e., blender, distributor, etc.)":	False
Utility boiler burner:	False
Industry boiler burner:	False
Industrial Furnace:	False
Smelter defferal:	False
Universal waste - batteries - generate:	False
Universal waste - thermostats - generate:	False
Universal waste - mercury - generate:	False
Universal waste - lamps - generate:	False
Universal waste - batteries - accumulate:	False
Universal waste - thermostats - accumulate:	False
Universal waste - mercury - accumulate:	False
Universal waste - lamps - accumulate:	False
Destination Facility for Universal Waste:	False
Off-specification used oil burner - utility boiler:	False
Off-specification used oil burner - industrial boiler:	False
Off-specification used oil burner - industrial furnace:	False
EPA ID:	WAD173823568
Facility Address 2:	Not reported
TAX REG NBR:	601213703
NAICS CD:	444110
BUSINESS TYPE:	Not reported
MAIL NAME:	LOWE'S HIW, INC.
MAIL ADDR LINE1:	P.O. BOX 1000
MAIL ADDR LINE2:	MAILCODE A2ELP
MAIL CITY,ST,ZIP:	MOORESVILLE, NC 28117
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Lowes HIW Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	101 ANDOVER PARK E.
LEGAL ADDR LINE2:	SUITE 200
LEGAL CITY,ST,ZIP:	TUKWILA, WA 98188
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(206)242-8570
LEGAL EFFECTIVE DATE:	Not reported
LAND ORG NAME:	Lowes HIW Inc

LOWES HIW 040 (Continued) **1000312762**

LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	101 ANDOVER PARK E.
LAND ADDR LINE2:	SUITE 200
LAND CITY,ST,ZIP:	TUKWILA, WA 98188
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(206)242-8570
OPERATOR ORG NAME:	LOWE'S HIW, INC.
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	101 ANDOVER PARK E.
OPERATOR ADDR LINE2:	SUITE 200
OPERATOR CITY,ST,ZIP:	TUKWILA, WA 98188
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(206)242-8570
OPERATOR EFFECTIVE DATE:	Not reported
SITE CONTACT NAME:	MANAGER ON DUTY
SITE CONTACT ADDR LINE1:	11959 NORTHRUP WAY
SITE CONTACT ZIP:	BELLEVUE, WA 98005-1919
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)646-9031
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	ROB GASS
FORM CONTACT ADDR LINE1:	P.O. BOX 1000
FORM CONTACT ADDR LINE2:	MAILCODE A2ELP
FORM CONTACT CITY,ST,ZIP:	MOORESVILLE, NC 28117
FORM CONTACT COUNTRY:	UNITED STATES
FORM CONTACT PHONE NBR:	(704)758-6033
FORM CONTACT EMAIL:	ROBERT.A.GASS@LOWES.COM
GEN STATUS CD:	XQG
MONTHLY GENERATION:	False
BATCH GENERATION:	False
ONE TIME GENERATION:	False
TRANSPORTS OWN WASTE:	False
TRANSPORTS OTHRS WASTE:	False
RECYCLER ONSITE:	False
TRANSFER FACILITY:	False
OTHER EXEMPTION:	Not reported
UW BATTERY GEN:	False
USED OIL TRANSPORTER:	False
USED OIL TRANSFER FACLTY:	False
USED OIL PROCESSOR:	False
USED OIL REREFINER:	False
USED OIL FUEL MRKTR DIRECTS SHPMNTS:	False
USED OIL FUEL MRKTR MEETS SPECS:	False

Facility Site ID Number:	36286977
SWC Desc:	Not reported
FWC Desc:	Not reported
Form Comm:	Not reported
Data Year:	Not reported
Permit by Rule:	No
Treatment by Generator:	No
Mixed radioactive waste:	No
Importer of hazardous waste:	No
Immediate recycler:	No
Treatment/Storage/Disposal/Recycling Facility:	No
Generator of dangerous fuel waste:	No

LOWES HIW 040 (Continued) **1000312762**

Generator marketing to burner:	No
"Other marketers (i.e., blender, distributor, etc.)":	No
Utility boiler burner:	No
Industry boiler burner:	No
Industrial Furnace:	No
Smelter defferal:	No
Universal waste - batteries - generate:	No
Universal waste - thermostats - generate:	No
Universal waste - mercury - generate:	No
Universal waste - lamps - generate:	No
Universal waste - batteries - accumulate:	No
Universal waste - thermostats - accumulate:	No
Universal waste - mercury - accumulate:	No
Universal waste - lamps - accumulate:	No
Destination Facility for Universal Waste:	No
Off-specification used oil burner - utility boiler:	No
Off-specification used oil burner - industrial boiler:	No
Off-specification used oil burner - industrial furnace:	No
EPA ID:	WAD173823568
Facility Address 2:	Not reported
TAX REG NBR:	601213703
NAICS CD:	44413
BUSINESS TYPE:	Not reported
MAIL NAME:	Not reported
MAIL ADDR LINE1:	8015 W KENTON CIRCLE STE 130
MAIL CITY,ST,ZIP:	HUNTSVILLE, NC 28078
MAIL COUNTRY:	UNITED STATES
LEGAL ORG NAME:	Lowes HIW Inc
LEGAL ORG TYPE:	Private
LEGAL ADDR LINE1:	1605 Curtis Bridge Road
LEGAL CITY,ST,ZIP:	WILKESBORO, NC 28697
LEGAL COUNTRY:	UNITED STATES
LEGAL PHONE NBR:	(336)658-4095
LEGAL EFFECTIVE DATE:	7/29/2000
LAND ORG NAME:	Lowes HIW Inc
LAND ORG TYPE:	Private
LAND PERSON NAME:	Not reported
LAND ADDR LINE1:	1605 Curtis Bridge Road
LAND CITY,ST,ZIP:	WILKESBORO, NC 28697
LAND COUNTRY:	UNITED STATES
LAND PHONE NBR:	(336)658-4095
OPERATOR ORG NAME:	LOWES HIW
OPERATOR ORG TYPE:	Private
OPERATOR ADDR LINE1:	1605 Curtis Bridge Road
OPERATOR CITY,ST,ZIP:	WILKESBORO, NC 28697
OPERATOR COUNTRY:	UNITED STATES
OPERATOR PHONE NBR:	(425)227-5740
OPERATOR EFFECTIVE DATE:	9/26/1996
SITE CONTACT NAME:	Scott Biesecker
SITE CONTACT ADDR LINE1:	11919 Northup Way
SITE CONTACT ZIP:	BELLEVUE, WA 98005
SITE CONTACT COUNTRY:	UNITED STATES
SITE CONTACT PHONE NBR:	(425)646-9031
SITE CONTACT EMAIL:	Not reported
FORM CONTACT NAME:	Damon Chappell
FORM CONTACT ADDR LINE1:	8015 W KENTON CIRCLE
FORM CONTACT ADDR LINE2:	STE 130

LOWES HIW 040 (Continued) **1000312762**

FORM CONTACT CITY,ST,ZIP: HUNTSVILLE, NC 28078
FORM CONTACT COUNTRY: UNITED STATES
FORM CONTACT PHONE NBR: 704-655-6024
FORM CONTACT EMAIL: damon.m.chappell@lowes.com
GEN STATUS CD: SQG
MONTHLY GENERATION: No
BATCH GENERATION: Yes
ONE TIME GENERATION: No
TRANSPORTS OWN WASTE: No
TRANSPORTS OTHRS WASTE: No
RECYCLER ONSITE: No
TRANSFER FACILITY: No
OTHER EXEMPTION: Not reported
UW BATTERY GEN: No
USED OIL TRANSPORTER: No
USED OIL TRANSFER FACLTY: No
USED OIL PROCESSOR: No
USED OIL REREFINER: No
USED OIL FUEL MRKTR DIRECTS SHPMNTS: No
USED OIL FUEL MRKTR MEETS SPECS: No

ICR:
Date Ecology Received Report: 07/13/92
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-28
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 09/09/92
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-33
County Code: 17
Contact: Not reported
Report Title: Not reported

Date Ecology Received Report: 10/01/92
Contaminants Found at Site: Petroleum products
Media Contaminated: Soil
Waste Management: Tank
Region: North Western
Type of Report Ecology Received: Final cleanup report
Site Register Issue: 92-34
County Code: 17
Contact: Not reported
Report Title: Not reported

AA118 **BENENSON CAPITAL** **RCRA-NonGen** **1004614246**
SW **110 108TH AVENUE NORTHEAST** **FINDS** **WAD988475992**
1/2-1 **BELLEVUE, WA 98004** **CSCSL**
0.954 mi. **ALLSITES**
5035 ft. **Site 1 of 2 in cluster AA**

Relative:
Lower

Actual:
137 ft.

RCRA-NonGen:
Date form received by agency: 01/10/2005
Facility name: BENENSON CAPITAL
Facility address: 110 108TH AVE NE
BELLEVUE, WA 98004
EPA ID: WAD988475992
Mailing address: 708 3RD AVE
NEW YORK, NY 10017-4201
Contact: TOM COLLIGAN
Contact address: 708 3RD AVE
NEW YORK, NY 10017-4201
Contact country: US
Contact telephone: (206)292-2078
Contact email: Not reported
EPA Region: 10
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: BENENSON BELLEVUE ASSOCIATES II
Owner/operator address: 708 3RD AVE
NEW YORK, NY 10017
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/17/1996
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/31/2003
Facility name: BENENSON CAPITAL
Classification: Large Quantity Generator

Date form received by agency: 04/03/1998

BENENSON CAPITAL (Continued) **1004614246**

Facility name: BENENSON CAPITAL
Site name: SHOPS AT FIRST ST
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110000829177

Environmental Interest/Information System
Washington Facility / Site Identification System (WA-FSIS) provides a means to query and display data maintained by the Washington Department of Ecology. This system contains key information for each facility/site that is currently, or has been, of interest to the Air Quality, Dam Safety, Hazardous Waste, Toxics Cleanup, and Water Quality Programs.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

CSCSL:
Facility ID: 50534232
Region: Northwest
Lat/Long: 47.611109999999 / -122.1962099999
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 4179
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Halogenated Organics
Ground Water: S
Surface Water: Not reported
Soil: C
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 50534232
Latitude: 47.6111099
Longitude: -122.19620
Geographic location identifier (alias facid): 50534232
Facility Name: Benenson Capital
Latitude Decimal Degrees: 47.611109999999996
Longitude Decimal Degrees: -122.19620999999999
Coordinate Point Areal Extent Code: 99
Horizontal Accuracy Code: 99
Coordinate Point Geographic Position Code: 8

BENENSON CAPITAL (Continued) **1004614246**

Location Verified Code: N

AA119 **CHEVRON 92581** **CSCSL** **U000711819**
SW **10812 MAIN ST** **ALLSITES** **N/A**
1/2-1 **BELLEVUE, WA 98004** **LUST**
0.955 mi. **UST**
5043 ft. **Site 2 of 2 in cluster AA**

Relative:
Lower

Actual:
137 ft.

CSCSL:

Facility ID:	6565892
Region:	Northwest
Lat/Long:	47.609971000000 / -122.197084
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7709
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Benzene
Ground Water:	S
Surface Water:	Not reported
Soil:	RB
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	6565892
Region:	Northwest
Lat/Long:	47.609971000000 / -122.197084
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7709
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Non-Halogenated Solvents
Ground Water:	C
Surface Water:	Not reported
Soil:	Not reported
Sediment:	Not reported
Air:	Not reported
Bedrock:	Not reported
Responsible Unit:	Northwest

Facility ID:	6565892
Region:	Northwest
Lat/Long:	47.609971000000 / -122.197084
Brownfield Status:	Not reported
Rank Status:	Not reported
Clean Up Siteid:	7709
Site Status:	Cleanup Started
PSI?:	Not reported
Contaminant Name:	Petroleum-Diesel
Ground Water:	S
Surface Water:	Not reported
Soil:	RB
Sediment:	Not reported
Air:	Not reported

CHEVRON 92581 (Continued) **U000711819**

Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 6565892
Region: Northwest
Lat/Long: 47.609971000000 / -122.197084
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 7709
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Gasoline
Ground Water: S
Surface Water: Not reported
Soil: RB
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

Facility ID: 6565892
Region: Northwest
Lat/Long: 47.609971000000 / -122.197084
Brownfield Status: Not reported
Rank Status: Not reported
Clean Up Siteid: 7709
Site Status: Cleanup Started
PSI?: Not reported
Contaminant Name: Petroleum-Other
Ground Water: S
Surface Water: Not reported
Soil: RB
Sediment: Not reported
Air: Not reported
Bedrock: Not reported
Responsible Unit: Northwest

ALLSITES:
Facility Id: 6565892
Latitude: 47.6099710
Longitude: -122.19708
Geographic location identifier (alias facid): 6565892
Facility Name: CHEVRON 92581
Latitude Decimal Degrees: 47.609971000000002
Longitude Decimal Degrees: -122.197084
Coordinate Point Areal Extent Code: 4
Horizontal Accuracy Code: 6
Coordinate Point Geographic Position Code: 5
Location Verified Code: N

LUST:
FS ID: 6565892
Cleanup Site ID: 7709
Cleanup Unit Type: Upland
Process Type: Independent Action

CHEVRON 92581 (Continued) **U000711819**

Facility Status: Cleanup Started
Alternate Name: CHEVRON STATION # 9-2581
Release Notification Date: Not reported
Release Status Date: 07/25/1990
Site Response Unit Code: Northwest
Lat/Long: 47.6099710 / -122.19708

FS ID: 6565892
Cleanup Site ID: 7709
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: RCU
Alternate Name: CHEVRON STATION # 9-2581
Release Notification Date: Not reported
Release Status Date: 06/01/1995
Site Response Unit Code: Northwest
Lat/Long: 47.6099710 / -122.19708

FS ID: 6565892
Cleanup Site ID: 7709
Cleanup Unit Type: Upland
Process Type: Independent Action
Facility Status: Cleanup Started
Alternate Name: CHEVRON STATION # 9-2581
Release Notification Date: Not reported
Release Status Date: 07/01/2011
Site Response Unit Code: Northwest
Lat/Long: 47.6099710 / -122.19708

UST:
Facility ID: 6565892
Site ID: 5120
Lat Deg: 47
Lat Min: 36
Lat Sec: 35.895600000005743
Long Deg: -122
Long Min: 11
Long Sec: 49.502400000013722
UBI: Not reported
Phone Number: 2064547468

Tank ID: 23506
Tank Name: 2
Install Date: 12/31/1964
Capacity: Not reported
Tank Upgrade Date: 1/1/0001
TankSystem Status: Removed
TankSystem Status Change Date: 8/26/1996
Tank Status: Removed
Tank Permit Expiration Date: 1/1/0001
Tank Closure Date: 1/1/0001
Tank Pumping System: Not reported
Tank Spill Prevention: Not reported
Tank Overfill Prevention: Not reported
Tank Material: Steel
Tank Construction: Single Wall Tank
Tank Tightness Test: Not reported

CHEVRON 92581 (Continued) **U000711819**

Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	23549
Tank Name:	4
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	23635
Tank Name:	3
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank

CHEVRON 92581 (Continued) **U000711819**

Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	23696
Tank Name:	1
Install Date:	12/31/1964
Capacity:	Not reported
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel
Tank Construction:	Single Wall Tank
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Tank ID:	23735
Tank Name:	5
Install Date:	12/31/1964
Capacity:	111 TO 1,100 Gallons
Tank Upgrade Date:	1/1/0001
TankSystem Status:	Removed
TankSystem Status Change Date:	8/26/1996
Tank Status:	Removed
Tank Permit Expiration Date:	1/1/0001
Tank Closure Date:	1/1/0001
Tank Pumping System:	Not reported
Tank Spill Prevention:	Not reported
Tank Overfill Prevention:	Not reported
Tank Material:	Steel

CHEVRON 92581 (Continued) **U000711819**

Tank Construction:	Not reported
Tank Tightness Test:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Material:	Steel
Pipe Construction:	Not reported
Pipe Primary Release Detection:	Not reported
Pipe Second Release Detection:	Not reported
Pipe Corrosion Protection:	Not reported
Tank Primary Release Detection:	Not reported
Tank Second Release Detection:	Not reported
Pipe Tightness Test:	Not reported
Tank Actual Status Date:	8/6/1996
Tag Number:	Not reported

Count: 18 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BELLEVUE	1014402297	GROUP HEALTH COOP BELLEVUE MEDICAL	11511 NE 10TH ST	98004	RCRA-SQG
BELLEVUE	S110037312	WA DOT NE 10TH BRIDGE CROSSING	NE 10TH BETWEEN 112TH NE	98004	ALLSITES
BELLEVUE	S110040172	GROUP HEALTH COOP BELLEVUE MEDICAL	11511 NE 10TH ST	98004	ALLSITES, MANIFEST
BELLEVUE	90191637	120TH BEL-RED RD. SAFEWAY DIST. PL	120TH BEL-RED RD. SAFEWAY DIST		ERNS
BELLEVUE	S111101747	KELSEY CR STREAM CHANNEL MOD	121ST SE UPSTREAM TO 8TH ST NE	98005	ALLSITES, NPDES
BELLEVUE	S111151742	BELLEVUE PARK II	NE 1ST ST & 102ND AVE SEC NE	98004	CSCSL, ALLSITES, VCP
BELLEVUE	U004183606	BELLEVUE PARK II	NE 1ST ST & 102ND AVE SEC NE	98004	LUST, UST
BELLEVUE	1004793850	GREGS PLACE AUTO REBUILD	1042 NE 8TH	98004	RCRA-NonGen, FINDS, ALLSITES
BELLEVUE	S110040674	NE 8TH ST SIDEWALK IMPROVEMENT	NE 8TH ST LK WASHINGTON BLVD &	98005	ALLSITES
BELLEVUE	S110123608	BARRIER MOTORS LLC	1200 BEL RED RD	98005	ALLSITES
BELLEVUE	S104485900	CITY OF BELLEVUE REHABILITATION PR	11200 BLOCK OF SE 8TH ST	98004	ICR
BELLEVUE	99636311	CORNER OF 140TH AND KAMBER ROAD	CORNER OF 140TH AND KAMBER ROA		ERNS
BELLEVUE	S108107941	CITY OF BELLEVUE SUMMER COLLECTION	LOWER EASTGATE PARK		SWF/LF
BELLEVUE	S108107966	CITY OF BELLEVUE FALL COLLECTION E	LOWER EAST GATE PARK N		SWF/LF
BELLEVUE	1004793589	MELODYS BELLEVUE NISSAN	13817 NORTHRUP WAY	98005	RCRA-NonGen, CSCSL, ALLSITES, LUST, UST
BELLEVUE	S110040268	NORTHUP WAY ROADWAY IMPROVEMENTS	NORTHUP WAY 120TH AVE NE	98005	ALLSITES
BELLEVUE	S105454343	FORMER DRY CLEANERS-BELLEVUE VILLA	NW OF NE 8TH ST & 102ND AVE N	98004	ICR
KING COUNTY	S108107942	WASTE MOBILE COLLECTIONS	MOVES LOCATIONS (SEE COMMENT F		SWF/LF

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 06/30/2011
Date Data Arrived at EDR: 07/12/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 79

Source: EPA
Telephone: N/A
Last EDR Contact: 01/11/2012
Next Scheduled EDR Contact: 04/23/2012
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 06/30/2011
Date Data Arrived at EDR: 07/12/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 79

Source: EPA
Telephone: N/A
Last EDR Contact: 01/11/2012
Next Scheduled EDR Contact: 04/23/2012
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 06/30/2011
Date Data Arrived at EDR: 07/12/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 79

Source: EPA
Telephone: N/A
Last EDR Contact: 01/10/2012
Next Scheduled EDR Contact: 04/23/2012
Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/25/2011
Date Data Arrived at EDR: 03/01/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 62

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 11/29/2011
Next Scheduled EDR Contact: 03/12/2012
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 12/10/2010
Date Data Arrived at EDR: 01/11/2011
Date Made Active in Reports: 02/16/2011
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 10/14/2011
Next Scheduled EDR Contact: 01/23/2012
Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 02/25/2011
Date Data Arrived at EDR: 03/01/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 62

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 11/29/2011
Next Scheduled EDR Contact: 03/12/2012
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 08/19/2011
Date Data Arrived at EDR: 08/31/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 132

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 11/14/2011
Next Scheduled EDR Contact: 02/27/2012
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (206) 553-1200
Last EDR Contact: 01/05/2012
Next Scheduled EDR Contact: 04/16/2012
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (206) 553-1200
Last EDR Contact: 01/05/2012
Next Scheduled EDR Contact: 04/16/2012
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (206) 553-1200
Last EDR Contact: 01/05/2012
Next Scheduled EDR Contact: 04/16/2012
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (206) 553-1200
Last EDR Contact: 01/05/2012
Next Scheduled EDR Contact: 04/16/2012
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 12/30/2011
Date Data Arrived at EDR: 12/30/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 12/09/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 12/30/2011
Date Data Arrived at EDR: 12/30/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 12/09/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 10/03/2011
Date Data Arrived at EDR: 10/04/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 38

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 01/06/2012
Next Scheduled EDR Contact: 04/16/2012
Data Release Frequency: Annually

State- and tribal - equivalent NPL

HSL: Hazardous Sites List

The Hazardous Sites List is a subset of the CSCSL Report. It includes sites which have been assessed and ranked using the Washington Ranking Method (WARM).

Date of Government Version: 08/31/2011
Date Data Arrived at EDR: 09/22/2011
Date Made Active in Reports: 11/10/2011
Number of Days to Update: 49

Source: Department of Ecology
Telephone: 360-407-7200
Last EDR Contact: 12/12/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Semi-Annually

State- and tribal - equivalent CERCLIS

CSCSL: Confirmed and Suspected Contaminated Sites List

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 10/25/2011
Date Data Arrived at EDR: 10/27/2011
Date Made Active in Reports: 12/06/2011
Number of Days to Update: 40

Source: Department of Ecology
Telephone: 360-407-7200
Last EDR Contact: 10/27/2011
Next Scheduled EDR Contact: 02/06/2012
Data Release Frequency: Semi-Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Solid Waste Facility Database

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 10/11/2011
Date Data Arrived at EDR: 10/11/2011
Date Made Active in Reports: 11/10/2011
Number of Days to Update: 30

Source: Department of Ecology
Telephone: 360-407-6132
Last EDR Contact: 12/12/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Annually

State and tribal leaking storage tank lists

LUST: Leaking Underground Storage Tanks Site List

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 11/22/2011
Date Data Arrived at EDR: 11/23/2011
Date Made Active in Reports: 12/08/2011
Number of Days to Update: 15

Source: Department of Ecology
Telephone: 360-407-7183
Last EDR Contact: 11/23/2011
Next Scheduled EDR Contact: 03/05/2012
Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 12/05/2011
Date Data Arrived at EDR: 12/07/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Quarterly

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 12/14/2011
Date Data Arrived at EDR: 12/15/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 26

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Semi-Annually

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 11/02/2011
Date Data Arrived at EDR: 11/04/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 7

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/01/2011
Date Data Arrived at EDR: 11/01/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 10

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 11/01/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 09/12/2011
Date Data Arrived at EDR: 09/13/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 59

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 11/01/2011
Date Data Arrived at EDR: 11/21/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 50

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/18/2011
Date Data Arrived at EDR: 08/19/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 25

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Quarterly

State and tribal registered storage tank lists

UST: Underground Storage Tank Database
Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 11/22/2011
Date Data Arrived at EDR: 11/23/2011
Date Made Active in Reports: 12/08/2011
Number of Days to Update: 15

Source: Department of Ecology
Telephone: 360-407-7183
Last EDR Contact: 12/09/2011
Next Scheduled EDR Contact: 03/05/2012
Data Release Frequency: Quarterly

AST: Aboveground Storage Tank Locations
A listing of aboveground storage tank locations regulated by the Department of Ecology's Spill Prevention, Preparedness and Response Program.

Date of Government Version: 05/27/2009
Date Data Arrived at EDR: 05/28/2009
Date Made Active in Reports: 06/19/2009
Number of Days to Update: 22

Source: Department of Ecology
Telephone: 360-407-7562
Last EDR Contact: 11/07/2011
Next Scheduled EDR Contact: 02/20/2012
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 12/14/2011
Date Data Arrived at EDR: 12/15/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 26

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Semi-Annually

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 11/28/2011
Date Data Arrived at EDR: 11/29/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 42

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 08/18/2011
Date Data Arrived at EDR: 08/19/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 25

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 11/02/2011
Date Data Arrived at EDR: 11/04/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 7

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Quarterly

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/01/2011
Date Data Arrived at EDR: 11/01/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 10

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 07/01/2011
Date Data Arrived at EDR: 08/26/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 18

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/10/2011
Date Data Arrived at EDR: 05/11/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 34

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Semi-Annually

INDIAN UST R7: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 11/01/2011
Date Data Arrived at EDR: 11/21/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 50
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Varies

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55
Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 10/17/2011
Next Scheduled EDR Contact: 01/30/2012
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

INST CONTROL: Institutional Control Site List
Sites that have institutional controls.

Date of Government Version: 11/15/2011
Date Data Arrived at EDR: 11/17/2011
Date Made Active in Reports: 12/08/2011
Number of Days to Update: 21
Source: Department of Ecology
Telephone: 360-407-7170
Last EDR Contact: 11/17/2011
Next Scheduled EDR Contact: 02/27/2012
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 08/04/2011
Date Data Arrived at EDR: 10/04/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 38
Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 01/06/2012
Next Scheduled EDR Contact: 04/16/2012
Data Release Frequency: Varies

VCP: Voluntary Cleanup Program Sites
Sites that have entered either the Voluntary Cleanup Program or its predecessor Independent Remedial Action Program.

Date of Government Version: 10/25/2011
Date Data Arrived at EDR: 11/04/2011
Date Made Active in Reports: 12/06/2011
Number of Days to Update: 32
Source: Department of Ecology
Telephone: 360-407-7200
Last EDR Contact: 10/25/2011
Next Scheduled EDR Contact: 02/06/2012
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27
Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

ICR: Independent Cleanup Reports
These are remedial action reports Ecology has received from either the owner or operator of the sites. These actions have been conducted without department oversight or approval and are not under an order or decree. This database is no longer updated by the Department of Ecology.

Date of Government Version: 12/01/2002
Date Data Arrived at EDR: 01/03/2003
Date Made Active in Reports: 01/22/2003
Number of Days to Update: 19
Source: Department of Ecology
Telephone: 360-407-7200
Last EDR Contact: 08/10/2009
Next Scheduled EDR Contact: 11/09/2009
Data Release Frequency: No Update Planned

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Sites Listing
A listing of brownfields sites included in the Confirmed & Suspected Sites Listing. Brownfields are abandoned, idle or underused commercial or industrial properties, where the expansion or redevelopment is hindered by real or perceived contamination. Brownfields vary in size, location, age, and past use -- they can be anything from a five-hundred acre automobile assembly plant to a small, abandoned corner gas station.

Date of Government Version: 10/25/2011
Date Data Arrived at EDR: 10/27/2011
Date Made Active in Reports: 12/06/2011
Number of Days to Update: 40
Source: Department of Ecology
Telephone: 360-725-4030
Last EDR Contact: 10/27/2011
Next Scheduled EDR Contact: 02/06/2012
Data Release Frequency: Varies

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 06/27/2011
Date Data Arrived at EDR: 06/27/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 78
Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 12/27/2011
Next Scheduled EDR Contact: 04/09/2012
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137
Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 12/21/2011
Next Scheduled EDR Contact: 04/09/2012
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39
Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SWTIRE: Solid Waste Tire Facilities
This study identified sites statewide with unauthorized accumulations of scrap tires.

Date of Government Version: 11/01/2005
Date Data Arrived at EDR: 03/16/2006
Date Made Active in Reports: 04/13/2006
Number of Days to Update: 28
Source: Department of Ecology
Telephone: N/A
Last EDR Contact: 12/14/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 11/07/2011
Next Scheduled EDR Contact: 02/20/2012
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs
A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 10/07/2011
Date Data Arrived at EDR: 12/09/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 32
Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 12/05/2011
Next Scheduled EDR Contact: 03/19/2012
Data Release Frequency: Quarterly

ALLSITES: Facility/Site Identification System Listing
Information on facilities and sites of interest to the Department of Ecology.

Date of Government Version: 11/08/2011
Date Data Arrived at EDR: 11/08/2011
Date Made Active in Reports: 12/06/2011
Number of Days to Update: 28
Source: Department of Ecology
Telephone: 360-407-6423
Last EDR Contact: 11/08/2011
Next Scheduled EDR Contact: 02/20/2012
Data Release Frequency: Quarterly

CSCSL NFA: Confirmed and Contaminated Sites - No Further Action
The data set contains information about sites previously on the Confirmed and Suspected Contaminated Sites list that have received a No Further Action (NFA) determination. Because it is necessary to maintain historical records of sites that have been investigated and cleaned up, sites are not deleted from the database when cleanup activities are completed. Instead, a No Further Action code is entered based upon the type of NFA determination the site received.

Date of Government Version: 10/25/2011
Date Data Arrived at EDR: 10/27/2011
Date Made Active in Reports: 12/06/2011
Number of Days to Update: 40

Source: Department of Ecology
Telephone: 360-407-7170
Last EDR Contact: 10/27/2011
Next Scheduled EDR Contact: 02/06/2012
Data Release Frequency: Semi-Annually

CDL: Clandestine Drug Lab Contaminated Site List

Illegal methamphetamine labs use hazardous chemicals that create public health hazards. Chemicals and residues can cause burns, respiratory and neurological damage, and death. Biological hazards associated with intravenous needles, feces, and blood also pose health risks.

Date of Government Version: 02/09/2009
Date Data Arrived at EDR: 03/18/2009
Date Made Active in Reports: 03/24/2009
Number of Days to Update: 6

Source: Department of Health
Telephone: 360-236-3380
Last EDR Contact: 11/15/2011
Next Scheduled EDR Contact: 02/27/2012
Data Release Frequency: Varies

HIST CDL: List of Sites Contaminated by Clandestine Drug Labs

This listing of contaminated sites by Clandestine Drug Labs includes non-remediated properties. The current CDL listing does not. This listing is no longer updated by the state agency.

Date of Government Version: 02/08/2007
Date Data Arrived at EDR: 06/26/2007
Date Made Active in Reports: 07/19/2007
Number of Days to Update: 23

Source: Department of Health
Telephone: 360-236-3381
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 11/19/2008
Date Made Active in Reports: 03/30/2009
Number of Days to Update: 131

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 09/09/2011
Date Data Arrived at EDR: 09/16/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005
Date Data Arrived at EDR: 12/11/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 31

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 11/22/2011
Next Scheduled EDR Contact: 03/05/2012
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 10/04/2011
Date Data Arrived at EDR: 10/04/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 38

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 01/03/2012
Next Scheduled EDR Contact: 04/16/2012
Data Release Frequency: Annually

SPILLS: Reported Spills

Spills reported to the Spill Prevention, Preparedness and Response Division.

Date of Government Version: 09/23/2011
Date Data Arrived at EDR: 09/27/2011
Date Made Active in Reports: 11/10/2011
Number of Days to Update: 44

Source: Department of Ecology
Telephone: 360-407-6950
Last EDR Contact: 01/03/2012
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Semi-Annually

Other Ascertainable Records

RCRA-NonGen: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/15/2011
Date Data Arrived at EDR: 07/07/2011
Date Made Active in Reports: 08/08/2011
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: (206) 553-1200
Last EDR Contact: 01/05/2012
Next Scheduled EDR Contact: 04/16/2012
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/29/2011
Date Data Arrived at EDR: 08/09/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 94

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 11/08/2011
Next Scheduled EDR Contact: 02/20/2012
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 10/20/2011
Next Scheduled EDR Contact: 01/30/2012
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 08/12/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 112

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 12/09/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/01/2011
Date Data Arrived at EDR: 11/18/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 53

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 12/27/2011
Next Scheduled EDR Contact: 04/16/2012
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 09/28/2011
Date Data Arrived at EDR: 12/14/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 27

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 12/14/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/21/2010
Date Made Active in Reports: 01/28/2011
Number of Days to Update: 99

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 11/29/2011
Next Scheduled EDR Contact: 03/12/2012
Data Release Frequency: Varies

MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/18/2011
Date Data Arrived at EDR: 09/08/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 21

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 12/07/2011
Next Scheduled EDR Contact: 03/19/2012
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 09/01/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 131

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 12/02/2011
Next Scheduled EDR Contact: 03/12/2012
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 09/29/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 64

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 12/27/2011
Next Scheduled EDR Contact: 04/09/2012
Data Release Frequency: Every 4 Years

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 11/28/2011
Next Scheduled EDR Contact: 03/12/2012
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 11/28/2011
Next Scheduled EDR Contact: 03/12/2012
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems
Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77
Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 10/31/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 07/20/2011
Date Data Arrived at EDR: 11/10/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 61

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 12/21/2011
Next Scheduled EDR Contact: 04/09/2012
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 11/01/2010
Date Data Arrived at EDR: 11/10/2010
Date Made Active in Reports: 02/16/2011
Number of Days to Update: 98

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 10/19/2011
Next Scheduled EDR Contact: 01/30/2012
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 06/21/2011
Date Data Arrived at EDR: 07/15/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 60

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 12/12/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/11/2011
Date Data Arrived at EDR: 01/13/2011
Date Made Active in Reports: 02/16/2011
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 10/13/2011
Next Scheduled EDR Contact: 01/23/2012
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 08/02/2011
Date Data Arrived at EDR: 09/13/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 119

Source: EPA
Telephone: (206) 553-1200
Last EDR Contact: 12/13/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 03/01/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 62

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 11/30/2011
Next Scheduled EDR Contact: 03/12/2012
Data Release Frequency: Biennially

UIC: Underground Injection Wells Listing

A listing of underground injection wells.

Date of Government Version: 11/22/2011
Date Data Arrived at EDR: 11/23/2011
Date Made Active in Reports: 01/04/2012
Number of Days to Update: 42

Source: Department of Ecology
Telephone: 360-407-6143
Last EDR Contact: 11/23/2011
Next Scheduled EDR Contact: 03/05/2012
Data Release Frequency: Varies

WA MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 06/30/2011
Date Made Active in Reports: 07/27/2011
Number of Days to Update: 27

Source: Department of Ecology
Telephone: N/A
Last EDR Contact: 10/24/2011
Next Scheduled EDR Contact: 02/06/2012
Data Release Frequency: Annually

DRYCLEANERS: Drycleaner List

A listing of registered drycleaners who registered with the Department of Ecology (using the SIC code of 7215 and 7216) as hazardous waste generators.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 06/30/2011
Date Made Active in Reports: 07/27/2011
Number of Days to Update: 27

Source: Department of Ecology
Telephone: 360-407-6732
Last EDR Contact: 10/24/2011
Next Scheduled EDR Contact: 02/06/2012
Data Release Frequency: Varies

NPDES: Water Quality Permit System Data

A listing of permitted wastewater facilities.

Date of Government Version: 11/15/2011
Date Data Arrived at EDR: 11/17/2011
Date Made Active in Reports: 01/04/2012
Number of Days to Update: 48

Source: Department of Ecology
Telephone: 360-407-6073
Last EDR Contact: 11/07/2011
Next Scheduled EDR Contact: 02/06/2012
Data Release Frequency: Quarterly

AIRS (EMI): Washington Emissions Data System

Emissions inventory data.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 01/11/2011
Date Made Active in Reports: 02/23/2011
Number of Days to Update: 43

Source: Department of Ecology
Telephone: 360-407-6040
Last EDR Contact: 12/23/2011
Next Scheduled EDR Contact: 04/09/2012
Data Release Frequency: Annually

INACTIVE DRYCLEANERS: Inactive Drycleaners
A listing of inactive drycleaner facility locations.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 06/30/2011
Date Made Active in Reports: 07/27/2011
Number of Days to Update: 27
Source: Department of Ecology
Telephone: 360-407-6732
Last EDR Contact: 10/24/2011
Next Scheduled EDR Contact: 02/06/2012
Data Release Frequency: Annually

INDIAN RESERV: Indian Reservations
This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34
Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 10/20/2011
Next Scheduled EDR Contact: 01/30/2012
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing
The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54
Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 10/24/2011
Next Scheduled EDR Contact: 02/06/2012
Data Release Frequency: Varies

FINANCIAL ASSURANCE 3: Financial Assurance Information Listing
A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 03/06/2007
Date Made Active in Reports: 04/19/2007
Number of Days to Update: 44
Source: Department of Ecology
Telephone: 360-407-6136
Last EDR Contact: 11/22/2011
Next Scheduled EDR Contact: 03/05/2012
Data Release Frequency: Varies

FINANCIAL ASSURANCE 1: Financial Assurance Information Listing
A listing of financial assurance information for underground storage tank facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 11/21/2011
Date Data Arrived at EDR: 11/30/2011
Date Made Active in Reports: 12/08/2011
Number of Days to Update: 8
Source: Department of Ecology
Telephone: 360-586-1060
Last EDR Contact: 11/21/2011
Next Scheduled EDR Contact: 03/05/2012
Data Release Frequency: Varies

FINANCIAL ASSURANCE 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 05/23/2011
Date Data Arrived at EDR: 05/26/2011
Date Made Active in Reports: 06/27/2011
Number of Days to Update: 32
Source: Department of Ecology
Telephone: 360-407-6754
Last EDR Contact: 11/21/2011
Next Scheduled EDR Contact: 03/05/2012
Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 06/29/2009
Date Data Arrived at EDR: 07/02/2009
Date Made Active in Reports: 07/08/2009
Number of Days to Update: 6
Source: Department of Ecology
Telephone: 360-407-6933
Last EDR Contact: 12/12/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 12/08/2011
Next Scheduled EDR Contact: 01/30/2012
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 08/17/2010
Date Data Arrived at EDR: 01/03/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 77
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 12/08/2011
Next Scheduled EDR Contact: 03/26/2012
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 11/04/2011
Next Scheduled EDR Contact: 02/13/2012
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands
Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339
Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/20/2011
Next Scheduled EDR Contact: 01/30/2012
Data Release Frequency: N/A

EDR PROPRIETARY RECORDS

EDR Proprietary Records

Manufactured Gas Plants: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Historical Auto Stations: EDR Proprietary Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Historical Cleaners: EDR Proprietary Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

KING COUNTY:

Abandoned Landfill Study in King County

The King County Abandoned Landfill Survey was conducted from October through December 1984 by the Health Department's Environmental Health Division at the request of the King County Council. The primary objective of the survey was to determine if any public health problems existed at the predetermined 24 sites.

Date of Government Version: 04/30/1985
Date Data Arrived at EDR: 11/07/1994
Date Made Active in Reports: N/A
Number of Days to Update: 0

Source: Seattle-King County Department of Public Health
Telephone: 206-296-4785
Last EDR Contact: 10/21/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SEATTLE COUNTY:

Abandoned Landfill Study in the City of Seattle

The Seattle Abandoned Landfill Survey was conducted in June and July of 1984 by the Health Department's Environmental Health Division at the request of the Mayor's Office. The primary objective of the survey was to determine if any public health problems existed at the predetermined 12 sites.

Date of Government Version: 07/30/1984
Date Data Arrived at EDR: 11/07/1994
Date Made Active in Reports: N/A
Number of Days to Update: 0

Source: Seattle - King County Department of Public Health
Telephone: 206-296-4785
Last EDR Contact: 10/21/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SEATTLE/KING COUNTY:

Seattle - King County Abandoned Landfill Toxicity / Hazard Assessment Project

This report presents the Seattle-King County Health Department's follow-up investigation of two city owned and four county owned abandoned landfills which was conducted from February to December 1986.

Date of Government Version: 12/31/1986
Date Data Arrived at EDR: 08/18/1995
Date Made Active in Reports: 09/20/1995
Number of Days to Update: 33

Source: Department of Public Health
Telephone: 206-296-4785
Last EDR Contact: 08/14/1995
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SNOHOMISH COUNTY:

Solid Waste Sites of Record at Snohomish Health District

Solid waste disposal and/or utilization sites in Snohomish County.

Date of Government Version: 03/08/2011
Date Data Arrived at EDR: 03/31/2011
Date Made Active in Reports: 05/06/2011
Number of Days to Update: 36

Source: Snohomish Health District
Telephone: 206-339-5250
Last EDR Contact: 12/30/2011
Next Scheduled EDR Contact: 04/09/2012
Data Release Frequency: Semi-Annually

TACOMA/PIERCE COUNTY:

Closed Landfill Survey

Following numerous requests for information about closed dumpsites and landfills in Pierce County, the Tacoma-Pierce County Health Department decided to conduct a study on the matter. The aim of the study was to evaluate public health risks associated with the closed dumpsites and landfills, and to determine the need, if any, for further investigations of a more detailed nature. The sites represent all of the known dumpsites and landfills closed after 1950.

Date of Government Version: 09/01/2002
Date Data Arrived at EDR: 03/24/2003
Date Made Active in Reports: 05/14/2003
Number of Days to Update: 51

Source: Tacoma-Pierce County Health Department
Telephone: 206-591-6500
Last EDR Contact: 03/19/2003
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/21/2011
Date Data Arrived at EDR: 11/22/2011
Date Made Active in Reports: 12/22/2011
Number of Days to Update: 30

Source: Department of Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 11/22/2011
Next Scheduled EDR Contact: 03/05/2012
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 11/01/2011
Date Data Arrived at EDR: 11/08/2011
Date Made Active in Reports: 12/22/2011
Number of Days to Update: 44

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 11/08/2011
Next Scheduled EDR Contact: 02/20/2012
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2008
Date Data Arrived at EDR: 12/01/2009
Date Made Active in Reports: 12/14/2009
Number of Days to Update: 13

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 09/26/2011
Next Scheduled EDR Contact: 01/09/2012
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 08/19/2011
Date Made Active in Reports: 09/15/2011
Number of Days to Update: 27

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 12/19/2011
Next Scheduled EDR Contact: 04/02/2012
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data
Source: Rextag Strategies Corp.
Telephone: (281) 769-2247
U.S. Electric Transmission and Power Plants Systems Digital GIS Data

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Daycare Center Listing
Source: Department of Social & Health Services
Telephone: 253-383-1735

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

120TH AND BELLEVUE-REDMOND ROAD PROPERTIES
120TH AVENUE NE/NE BELLEVUE REDMOND ROAD
BELLEVUE, WA 98005

TARGET PROPERTY COORDINATES

Latitude (North):	47.6183 - 47° 37' 5.89''
Longitude (West):	122.1794 - 122° 10' 45.83''
Universal Tranverse Mercator:	Zone 10
UTM X (Meters):	561665.0
UTM Y (Meters):	5273984.5
Elevation:	156 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	47122-E2 MERCER ISLAND, WA
Most Recent Revision:	1983
North Map:	47122-F2 KIRKLAND, WA
Most Recent Revision:	1982

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION


Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General WNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES





Target Property Elevation: 156 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
KING, WA	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property:	53033C0656F - FEMA Q3 Flood data
Additional Panels in search area:	53033C0368F - FEMA Q3 Flood data 53033C0365F - FEMA Q3 Flood data 53033C0652F - FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
MERCER ISLAND	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1/2 - 1 Mile NE
Site Name:	BELLEVUE PLATING CO INC
Site EPA ID Number:	WAD078194107
Groundwater Flow Direction:	NOT AVAILABLE
Inferred Depth to Water:	15 feet to 25 feet
Hydraulic Connection:	The uppermost water-bearing strata is a glacial drift composed of sands, gravel, and clay with lenses of consolidated till.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information is inferred in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
3	1/8 - 1/4 Mile NE	E
9	1/4 - 1/2 Mile South	NW
D11	1/4 - 1/2 Mile SW	Varies
D13	1/4 - 1/2 Mile SW	Not Reported
I36	1/2 - 1 Mile West	SE

For additional site information, refer to Physical Setting Source Map Findings.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Cenozoic
System:	Quaternary
Series:	Quaternary
Code:	Q *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 3237712.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	120th and Bellevue-Redmond Road Properties	CLIENT:	Geo Engineers, Inc.
ADDRESS:	120th Avenue NE/NE Bellevue Redmond Road Bellevue WA 98005	CONTACT:	Jessica Robertson
LAT/LONG:	47.6183 / 122.1794	INQUIRY #:	3237712.2s
		DATE:	January 11, 2012 12:48 pm

Copyright © 2012 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class:
Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 2

Soil Component Name: Tukwila

Soil Surface Texture: muck

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Very poorly drained

Hydric Status: All hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	18 inches	muck	A-8	Highly organic soils, Peat.	Max: 14 Min: 4	Max: Min:
2	18 inches	59 inches	stratified diatomaceous earth to muck	A-8	Highly organic soils, Peat.	Max: 14 Min: 4	Max: Min:

Soil Map ID: 3

Soil Component Name: Alderwood

Soil Surface Texture: gravelly sandy loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Moderately well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 84 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	11 inches	gravelly sandy loam	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 0.42 Min: 0.01	Max: 6 Min: 5.1
2	11 inches	26 inches	very gravelly sandy loam	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 0.42 Min: 0.01	Max: 6 Min: 5.1

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
3	26 inches	59 inches	very gravelly sandy loam	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 0.42 Min: 0.01	Max: 6 Min: 5.1

Soil Map ID: 4

Soil Component Name: Bellingham

Soil Surface Texture: silt loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Poorly drained

Hydric Status: All hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 15 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	11 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 1.4 Min: 0.42	Max: 7.3 Min: 5.6
2	11 inches	59 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 1.4 Min: 0.42	Max: 7.3 Min: 5.6

Soil Map ID: 5

Soil Component Name: Water

Soil Surface Texture: silt loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class:
Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 6

Soil Component Name: Arents

Soil Surface Texture: gravelly sandy loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Moderately well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 84 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	25 inches	gravelly sandy loam	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 0.42 Min: 0.01	Max: 6 Min: 5.1

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
2	25 inches	59 inches	very gravelly sandy loam	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Gravels, Gravels with fines, Silty Gravel	Max: 0.42 Min: 0.01	Max: 6 Min: 5.1

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	USGS3277863	1/8 - 1/4 Mile SSW
A2	USGS3277858	1/8 - 1/4 Mile SSW
B4	USGS3277925	1/4 - 1/2 Mile ENE
B5	USGS3277919	1/4 - 1/2 Mile ENE
6	USGS3277960	1/4 - 1/2 Mile NW
7	USGS3277929	1/4 - 1/2 Mile ENE
8	USGS3277963	1/4 - 1/2 Mile NE
C10	USGS3277892	1/4 - 1/2 Mile ESE
C12	USGS3277899	1/4 - 1/2 Mile ESE
14	USGS3277903	1/4 - 1/2 Mile East
15	USGS3277922	1/4 - 1/2 Mile West
E16	USGS3277818	1/2 - 1 Mile SSE
17	USGS3277812	1/2 - 1 Mile SSW
E18	USGS3277811	1/2 - 1 Mile SSE
E19	USGS3277803	1/2 - 1 Mile SSE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
20	USGS3277797	1/2 - 1 Mile SSE
21	USGS3277813	1/2 - 1 Mile SSW
F22	USGS3277934	1/2 - 1 Mile ENE
23	USGS3277810	1/2 - 1 Mile SE
F24	USGS3277931	1/2 - 1 Mile ENE
F25	USGS3277932	1/2 - 1 Mile ENE
26	USGS3277988	1/2 - 1 Mile NW
G27	USGS3277780	1/2 - 1 Mile South
G28	USGS3277776	1/2 - 1 Mile South
G29	USGS3277772	1/2 - 1 Mile South
G30	USGS3277770	1/2 - 1 Mile South
H31	USGS3277751	1/2 - 1 Mile South
H32	USGS3277743	1/2 - 1 Mile South
33	USGS3278070	1/2 - 1 Mile North
34	USGS3278051	1/2 - 1 Mile NNW
35	USGS3278078	1/2 - 1 Mile NNW
37	USGS3278077	1/2 - 1 Mile NNE
38	USGS3277737	1/2 - 1 Mile SSE
I39	USGS3277907	1/2 - 1 Mile West
40	USGS3277910	1/2 - 1 Mile West

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

PHYSICAL SETTING SOURCE MAP - 3237712.2s



0 1/4 1/2 1 Miles

- County Boundary
- Major Roads
- Contour Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data

SITE NAME:	120th and Bellevue-Redmond Road Properties	CLIENT:	Geo Engineers, Inc.
ADDRESS:	120th Avenue NE/NE Bellevue Redmond Road Bellevue WA 98005	CONTACT:	Jessica Robertson
LAT/LONG:	47.6183 / 122.1794	INQUIRY #:	3237712.2s
		DATE:	January 11, 2012 12:48 pm

Copyright © 2012 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
SSW
1/8 - 1/4 Mile
Lower

FED USGS **USGS3277863**

Agency cd:	USGS	Site no:	473655122104701
Site name:	25N/05E-33D01		
Latitude:	473655	EDR Site id:	USGS3277863
Longitude:	1221047	Dec lat:	47.6150993
Dec lon:	-122.18095623	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NW NW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	125		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19580513
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	62	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1958-05-13	Ground water data end date:	1958-05-13
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1958-05-13	7	

A2
SSW
1/8 - 1/4 Mile
Lower

FED USGS **USGS3277858**

Agency cd:	USGS	Site no:	473654122104601
Site name:	25N/05E-33D02		
Latitude:	473654	EDR Site id:	USGS3277858
Longitude:	1221046	Dec lat:	47.61482153
Dec lon:	-122.18067845	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NW NW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	80	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

3
NE
1/8 - 1/4 Mile
Higher

AQUIFLOW **61245**

Site ID:	4085
Groundwater Flow:	E
Shallowest Water Table Depth:	6
Deepest Water Table Depth:	10
Average Water Table Depth:	Not Reported
Date:	01/1993

B4
ENE
1/4 - 1/2 Mile
Higher

FED USGS **USGS3277925**

Agency cd:	USGS	Site no:	473711122102101
Site name:	25N/05E-28P01		
Latitude:	473711	EDR Site id:	USGS3277925
Longitude:	1221021	Dec lat:	47.61954377
Dec lon:	-122.17373398	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE SW S28 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000

Altitude:	205		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	115	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-19	Ground water data end date:	1951-03-19
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-19	70	

B5
ENE
1/4 - 1/2 Mile
Higher

FED USGS USGS3277919

Agency cd:	USGS	Site no:	473710122102001
Site name:	25N/05E-28P02		
Latitude:	473710	EDR Site id:	USGS3277919
Longitude:	1221020	Dec lat:	47.61926599
Dec lon:	-122.17345619	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE SW S28 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	139		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	52	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-19	Ground water data end date:	1951-03-19
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-19	23	

6
NW
1/4 - 1/2 Mile
Higher

FED USGS **USGS3277960**

Agency cd:	USGS	Site no:	473721122105701
Site name:	25N/05E-28M01		
Latitude:	473721	EDR Site id:	USGS3277960
Longitude:	1221057	Dec lat:	47.62232146
Dec lon:	-122.18373416	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NW SW S28 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	180		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19490901
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	69	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

7
ENE
1/4 - 1/2 Mile
Higher

FED USGS **USGS3277929**

Agency cd:	USGS	Site no:	473712122101401
Site name:	25N/05E-28Q01		
Latitude:	473712	EDR Site id:	USGS3277929
Longitude:	1221014	Dec lat:	47.61982156
Dec lon:	-122.17178951	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SW SE S28 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	180		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	117	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-21	Ground water data end date:	1951-03-21
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-21	40	

8
NE
1/4 - 1/2 Mile
Higher

FED USGS USGS3277963

Agency cd:	USGS	Site no:	473722122102301
Site name:	25N/05E-28L01		
Latitude:	473722	EDR Site id:	USGS3277963
Longitude:	1221023	Dec lat:	47.6225993
Dec lon:	-122.17428958	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NE SW S28 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	180		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST

Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	11	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-06-11	Ground water data end date:	1951-06-11
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-06-11	6	

9
South
1/4 - 1/2 Mile
Lower

AQUIFLOW **61079**

Site ID:	2782
Groundwater Flow:	NW
Shallowest Water Table Depth:	2.27
Deepest Water Table Depth:	7.12
Average Water Table Depth:	Not Reported
Date:	03/20/1997

C10
ESE
1/4 - 1/2 Mile
Lower

FED USGS **USGS3277892**

Agency cd:	USGS	Site no:	473701122101201
Site name:	25N/05E-33B01		
Latitude:	473701	EDR Site id:	USGS3277892
Longitude:	1221012	Dec lat:	47.61676603
Dec lon:	-122.1712339	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NW NE S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	175		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	37.7	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00

Peak flow data count: 0
Water quality data begin date: 0000-00-00
Water quality data end date: 0000-00-00
Water quality data count: 0
Ground water data begin date: 1951-03-20
Ground water data end date: 1951-03-20
Ground water data count: 1

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-20	30	

D11
SW
1/4 - 1/2 Mile
Lower

AQUIFLOW **61181**

Site ID: 2530
Groundwater Flow: Varies
Shallowest Water Table Depth: 11.77
Deepest Water Table Depth: 17.50
Average Water Table Depth: Not Reported
Date: 11/1998

C12
ESE
1/4 - 1/2 Mile
Lower

FED USGS **USGS3277899**

Agency cd: USGS
Site no: 473702122101101
Site name: 25N/05E-33B02
Latitude: 473702
EDR Site id: USGS3277899
Longitude: 1221011
Dec lat: 47.61704381
Dec lon: -122.17095612
Coor meth: M
Coor accr: S
Latlong datum: NAD27
Dec latlong datum: NAD83
District: 53
State: 53
County: 033
Country: US
Land net: NW NE S33 T25N R05E W
Location map: MERCER ISLAND
Map scale: 24000
Altitude: 200
Altitude method: Interpolated from topographic map
Altitude accuracy: 2
Altitude datum: National Geodetic Vertical Datum of 1929
Hydrologic: Lake Washington. Washington. Area = 619 sq.mi.
Topographic: Not Reported
Site type: Ground-water other than Spring
Date construction: 19010101
Date inventoried: Not Reported
Mean greenwich time offset: PST
Local standard time flag: Y
Type of ground water site: Single well, other than collector or Ranney type
Aquifer Type: Not Reported
Aquifer: Not Reported
Well depth: 32
Hole depth: Not Reported
Source of depth data: driller
Project number: Not Reported
Real time data flag: 0
Daily flow data begin date: 0000-00-00
Daily flow data end date: 0000-00-00
Daily flow data count: 0
Peak flow data begin date: 0000-00-00
Peak flow data end date: 0000-00-00
Peak flow data count: 0
Water quality data begin date: 0000-00-00
Water quality data end date: 0000-00-00
Water quality data count: 0
Ground water data begin date: 1901-01-01
Ground water data end date: 1901-01-01
Ground water data count: 1

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1901-01-01	17	

D13
SW
1/4 - 1/2 Mile
Lower

AQUIFLOW **61054**

Site ID:	1901
Groundwater Flow:	Not Reported
Shallowest Water Table Depth:	Not Reported
Deepest Water Table Depth:	Not Reported
Average Water Table Depth:	47
Date:	09/05/1991

14
East
1/4 - 1/2 Mile
Lower

FED USGS **USGS3277903**

Agency cd:	USGS	Site no:	473704122100901
Site name:	25N/05E-33B04		
Latitude:	473704	EDR Site id:	USGS3277903
Longitude:	1221009	Dec lat:	47.61759936
Dec lon:	-122.17040057	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NW NE S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19400101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	19	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-21	Ground water data end date:	1951-03-21
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-21	9	

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

15
West
1/4 - 1/2 Mile
Lower | **FED USGS** | **USGS3277922**

Agency cd:	USGS	Site no:	473710122361501
Site name:	25N/05E-29R01		
Latitude:	473710	EDR Site id:	USGS3277922
Longitude:	1221115	Dec lat:	47.61926589
Dec lon:	-122.18873418	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE SE S29 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19510417
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	28	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-04-17	Ground water data end date:	1951-04-17
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-04-17	16	

E16
SSE
1/2 - 1 Mile
Higher | **FED USGS** | **USGS3277818**

Agency cd:	USGS	Site no:	473642122102701
Site name:	25N/05E-33F01		
Latitude:	473642	EDR Site id:	USGS3277818
Longitude:	1221027	Dec lat:	47.61148825
Dec lon:	-122.17540055	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE NW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19510320
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	104	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-20	Ground water data end date:	1951-03-20
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-20	84	

17
SSW
1/2 - 1 Mile
Higher

FED USGS USGS3277812

Agency cd:	USGS	Site no:	473641122105201
Site name:	25N/05E-33E01		
Latitude:	473641	EDR Site id:	USGS3277812
Longitude:	1221052	Dec lat:	47.61121043
Dec lon:	-122.18234509	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SW NW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	175		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST

Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	75	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-21	Ground water data end date:	1951-03-21
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-21	72	

E18
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS3277811**

Agency cd:	USGS	Site no:	473641122102601
Site name:	25N/05E-33F02		
Latitude:	473641	EDR Site id:	USGS3277811
Longitude:	1221026	Dec lat:	47.61121048
Dec lon:	-122.17512276	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE NW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	210		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19390901
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	115	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E19
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS3277803**

Agency cd:	USGS	Site no:	473640122102501
Site name:	25N/05E-33F03		
Latitude:	473640	EDR Site id:	USGS3277803
Longitude:	1221025	Dec lat:	47.61093271
Dec lon:	-122.17484497	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE NW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	220		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	85	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-21	Ground water data end date:	1951-03-21
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-21	79	

20
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS3277797**

Agency cd:	USGS	Site no:	473639122102401
Site name:	25N/05E-33F04		
Latitude:	473639	EDR Site id:	USGS3277797
Longitude:	1221024	Dec lat:	47.61065493
Dec lon:	-122.17456719	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE NW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	Not Reported	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

21
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS3277813**

Agency cd:	USGS	Site no:	473641122110501
Site name:	25N/05E-29J01		
Latitude:	473641	EDR Site id:	USGS3277813
Longitude:	1221105	Dec lat:	47.6112104
Dec lon:	-122.18595625	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NE SE S29 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	190		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19510417
Date inventoried:	Not Reported	Mean greenwich time offset:	PST

Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	43	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-04-17	Ground water data end date:	1951-04-17
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-04-17	40	

F22
ENE
1/2 - 1 Mile
Lower

FED USGS USGS3277934

Agency cd:	USGS	Site no:	473714122095701
Site name:	25N/05E-28R01		
Latitude:	473714	EDR Site id:	USGS3277934
Longitude:	1220957	Dec lat:	47.62037714
Dec lon:	-122.16706723	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE SE S28 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	130		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	11	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-22	Ground water data end date:	1951-03-22
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-22	3	

23
SE
1/2 - 1 Mile
Higher

FED USGS **USGS3277810**

Agency cd:	USGS	Site no:	473641122101501
Site name:	25N/05E-33G01		
Latitude:	473641	EDR Site id:	USGS3277810
Longitude:	1221015	Dec lat:	47.6112105
Dec lon:	-122.17206716	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SW NE S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	230		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19510301
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	110	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-01	Ground water data end date:	1951-03-01
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-01	100	

F24
ENE
1/2 - 1 Mile
Lower

FED USGS **USGS3277931**

Agency cd:	USGS	Site no:	473713122095601
Site name:	25N/05E-28R02		
Latitude:	473713	EDR Site id:	USGS3277931
Longitude:	1220956	Dec lat:	47.62009937
Dec lon:	-122.16678944	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE SE S28 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	130		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	35	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-22	Ground water data end date:	1951-03-22
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-22	17	

F25
ENE
1/2 - 1 Mile
Lower

FED USGS USGS3277932

Agency cd:	USGS	Site no:	473713122095602
Site name:	25N/05E-28R03		
Latitude:	473713	EDR Site id:	USGS3277932
Longitude:	1220956	Dec lat:	47.62009937
Dec lon:	-122.16678944	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE SE S28 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	125		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST

Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	12	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-22	Ground water data end date:	1951-03-22
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-22	4	

26
NW
1/2 - 1 Mile
Higher

FED USGS **USGS3277988**

Agency cd:	USGS	Site no:	473732122111001
Site name:	25N/05E-29H01		
Latitude:	473732	EDR Site id:	USGS3277988
Longitude:	1221110	Dec lat:	47.62537697
Dec lon:	-122.18734536	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE NE S29 T25N R05E W
Location map:	KIRKLAND	Map scale:	24000
Altitude:	225		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	35	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-04-17	Ground water data end date:	1951-04-17
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-04-17	23	

G27
South
1/2 - 1 Mile
Higher

FED USGS **USGS3277780**

Agency cd:	USGS	Site no:	473634122103701
Site name:	25N/05E-33L01		
Latitude:	473634	EDR Site id:	USGS3277780
Longitude:	1221037	Dec lat:	47.60926603
Dec lon:	-122.17817833	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NE SW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	18.9	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-20	Ground water data end date:	1951-03-20
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-20	2	

G28
South
1/2 - 1 Mile
Higher

FED USGS **USGS3277776**

Agency cd:	USGS	Site no:	473633122103601
Site name:	25N/05E-33L02		
Latitude:	473633	EDR Site id:	USGS3277776
Longitude:	1221036	Dec lat:	47.60898825
Dec lon:	-122.17790054	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NE SW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	190		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	38.8	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1901-01-01	Ground water data end date:	1901-01-01
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1901-01-01		

Note: The site was dry (no water level recorded).

G29
South
1/2 - 1 Mile
Higher

FED USGS **USGS3277772**

Agency cd:	USGS	Site no:	473632122103401
Site name:	25N/05E-33L03		
Latitude:	473632	EDR Site id:	USGS3277772
Longitude:	1221034	Dec lat:	47.60871048
Dec lon:	-122.17734498	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NE SW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000

Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	Not Reported	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

G30
South
1/2 - 1 Mile
Higher

FED USGS **USGS3277770**

Agency cd:	USGS	Site no:	473631122103501
Site name:	25N/05E-33L04		
Latitude:	473631	EDR Site id:	USGS3277770
Longitude:	1221035	Dec lat:	47.6084327
Dec lon:	-122.17762275	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NE SW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	60	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported

Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

H31
South
1/2 - 1 Mile
Higher

FED USGS **USGS3277751**

Agency cd:	USGS	Site no:	473625122105001
Site name:	25N/05E-33M01		
Latitude:	473625	EDR Site id:	USGS3277751
Longitude:	1221050	Dec lat:	47.60676602
Dec lon:	-122.18178946	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NW SW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	71	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-21	Ground water data end date:	1951-03-21
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-21	64	

H32
South
1/2 - 1 Mile
Higher

FED USGS **USGS3277743**

Agency cd:	USGS	Site no:	473624122104901
Site name:	25N/05E-33M02		
Latitude:	473624	EDR Site id:	USGS3277743
Longitude:	1221049	Dec lat:	47.60648824
Dec lon:	-122.18151167	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NW SW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	175		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	76	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-03-22	Ground water data end date:	1951-03-22
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-03-22	68	

33
North
1/2 - 1 Mile
Higher

FED USGS USGS3278070

Agency cd:	USGS	Site no:	473750122104101
Site name:	25N/05E-28C01		
Latitude:	473750	EDR Site id:	USGS3278070
Longitude:	1221041	Dec lat:	47.63037699
Dec lon:	-122.17928977	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NE NW S28 T25N R05E W
Location map:	KIRKLAND	Map scale:	24000
Altitude:	195		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19460101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST

Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	213	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1946-01-01	Ground water data end date:	1946-01-01
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1946-01-01	152	

34
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS3278051**

Agency cd:	USGS	Site no:	473747122110801
Site name:	25N/05E-29A01		
Latitude:	473747	EDR Site id:	USGS3278051
Longitude:	1221108	Dec lat:	47.62954361
Dec lon:	-122.18678986	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NE NE S29 T25N R05E W
Location map:	KIRKLAND	Map scale:	24000
Altitude:	230		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	18	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1951-04-17	Ground water data end date:	1951-04-17
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-04-17	5	

35
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS3278078**

Agency cd:	USGS	Site no:	473751122110101
Site name:	25N/05E-28D01		
Latitude:	473751	EDR Site id:	USGS3278078
Longitude:	1221101	Dec lat:	47.63065473
Dec lon:	-122.18484541	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NW NW S28 T25N R05E W
Location map:	KIRKLAND	Map scale:	24000
Altitude:	160		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	36	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1901-01-01	Ground water data end date:	1901-01-01
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1901-01-01	26	

I36
West
1/2 - 1 Mile
Higher

AQUIFLOW **41924**

Site ID:	1919
Groundwater Flow:	SE
Shallowest Water Table Depth:	21.30
Deepest Water Table Depth:	31.35
Average Water Table Depth:	Not Reported
Date:	09/05/1990

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

37
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS3278077**

Agency cd:	USGS	Site no:	473751122101401
Site name:	25N/05E-28B01		
Latitude:	473751	EDR Site id:	USGS3278077
Longitude:	1221014	Dec lat:	47.63065482
Dec lon:	-122.17178967	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NW NE S28 T25N R05E W
Location map:	KIRKLAND	Map scale:	24000
Altitude:	330		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	90	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1952-01-29	Ground water data end date:	1952-01-29
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1952-01-29	72	

38
SSE
1/2 - 1 Mile
Lower

FED USGS **USGS3277737**

Agency cd:	USGS	Site no:	473623122100801
Site name:	25N/05E-33M03		
Latitude:	473623	EDR Site id:	USGS3277737
Longitude:	1221008	Dec lat:	47.60621055
Dec lon:	-122.17012261	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	NW SW S33 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19010101
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	32	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1901-01-01	Ground water data end date:	1901-01-01
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1901-01-01	26	

I39
West
1/2 - 1 Mile
Higher

FED USGS USGS3277907

Agency cd:	USGS	Site no:	473706122365401
Site name:	25N/05E-29P02		
Latitude:	473706	EDR Site id:	USGS3277907
Longitude:	1221154	Dec lat:	47.61815471
Dec lon:	-122.19956766	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE SW S29 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	PST

Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	Not Reported	Hole depth:	Not Reported
Source of depth data:	Not Reported		
Project number:	Not Reported		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date:	Not Reported	Water quality data count:	Not Reported
Ground water data begin date:	Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

40
West
1/2 - 1 Mile
Higher

FED USGS **USGS3277910**

Agency cd:	USGS	Site no:	473707122365501
Site name:	25N/05E-29P01		
Latitude:	473707	EDR Site id:	USGS3277910
Longitude:	1221155	Dec lat:	47.61843248
Dec lon:	-122.19984544	Coor meth:	M
Coor accr:	S	Latlong datum:	NAD27
Dec latlong datum:	NAD83	District:	53
State:	53	County:	033
Country:	US	Land net:	SE SW S29 T25N R05E W
Location map:	MERCER ISLAND	Map scale:	24000
Altitude:	200		
Altitude method:	Interpolated from topographic map		
Altitude accuracy:	2		
Altitude datum:	National Geodetic Vertical Datum of 1929		
Hydrologic:	Lake Washington. Washington. Area = 619 sq.mi.		
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	19460701
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector or Ranney type		
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	1120	Hole depth:	Not Reported
Source of depth data:	driller		
Project number:	Not Reported		
Real time data flag:	0	Daily flow data begin date:	0000-00-00
Daily flow data end date:	0000-00-00	Daily flow data count:	0
Peak flow data begin date:	0000-00-00	Peak flow data end date:	0000-00-00
Peak flow data count:	0	Water quality data begin date:	0000-00-00
Water quality data end date:	0000-00-00	Water quality data count:	0
Ground water data begin date:	1958-05-15	Ground water data end date:	1958-05-15
Ground water data count:	1		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1958-05-15	115	

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KING County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 98005

Number of sites tested: 3

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.733 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	0.350 pCi/L	100%	0%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Water Wells
Source: Department of Health
Telephone: 360-236-3148
Group A and B well locations.

Water Well Listing
Source: Public Utility District
Telephone: 206-779-7656
A listing of water well locations in Kitsap County.

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Listing
Source: Department of Natural Resources
Telephone: 360-902-1445
Locations that represent oil and gas test well sites in Washington State from 1890 to present.

RADON

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER


Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration


PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION


© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.



APPENDIX C
Key Maps from Prior Reports, Copies of Prior Environmental Reports




Vicinity Map
NO SCALE



Site Plan
NOT TO SCALE

LANDAU ASSOCIATES, INC.	Site Plan




AVIS CAR SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON

Figure 1

Site Location

PETROLEUM SERVICES UNLIMITED, INC.




AVIS SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 2

SITE FACILITY MAP

PETROLEUM SERVICES UNLIMITED




AVIS SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 3

UTILITIES MAP

PETROLEUM SERVICES UNLIMITED




AVIS SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 4

EXCAVATION AND SOIL SAMPLE LOCATIONS

PETROLEUM SERVICES UNLIMITED




AVIS SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 5

EXCAVATION AND SOIL SAMPLE LOCATIONS

PETROLEUM SERVICES UNLIMITED



AVIS SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 6

GROUNDWATER WELL LOCATIONS

PETROLEUM SERVICES UNLIMITED

RECEIVED
JUN 14 1989
DEPARTMENT OF ECOLOGY
NORTHWEST REGION

Final Report

UNDERGROUND STORAGE TANKS REMOVAL AVIS RENT A CAR SYSTEM, INC. 11969 BELLEVUE-REDMOND ROAD BELLEVUE, WASHINGTON

Prepared for

Perkins Coie
Seattle, Washington

Prepared by

Landau Associates, Inc.
P.O. Box 1029
Edmonds, WA 98020-1029

June 2, 1989

LANDAU ASSOCIATES, INC.
GEOTECHNICAL ENGINEERING AND HYDROLOGY
P.O. BOX 1029
EDMONDS, WASHINGTON 98020-1029

(206) 778-0907

June 2, 1989

Perkins Coie
1201 Third Avenue, 40th Floor
Seattle, WA 98101-3099

Attention: Mr. Douglas S. Little

REPORT
UNDERGROUND STORAGE TANKS REMOVAL
AVIS RENT A CAR SYSTEM, INC.
11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON

INTRODUCTION

This report documents the removal of two underground storage tanks (USTs) at the Bellevue Avis site located at 11969 Bellevue-Redmond Road in Bellevue, Washington, as shown on the Site Plan, Figure 1. The approximate former locations of the two tanks relative to other features that currently exist on the site are shown on Figure 1.

Landau Associates, Inc. was contacted by Perkins Coie on March 2, 1989, to represent Avis Rent A Car System, Inc. (Avis) during the removal of petroleum-contaminated soil that was discovered by Petroleum Equipment Maintenance Company (PEMCO) of Portland, Oregon, during removal of one 5,000-gallon UST at the Bellevue site. PEMCO was contracted by Avis to remove the 5,000-gallon steel gasoline tank and replace it with a new fiberglass tank of comparable size.

BACKGROUND

We understand that the site has been owned and operated by Avis since the mid-1970s. According to existing information, the 5,000-gallon gasoline tank was installed by Avis; prior to purchase by Avis, it is reported that the site was operated as a commercial gas station.

DISCUSSION OF UST CLOSURE ACTIVITIES

- March 1, 1989. During removal of the 5,000-gallon steel gasoline tank by PEMCO, some petroleum product was observed floating on the ground water surface and coating soil below product lines at the east end of the tank excavation. According to PEMCO, the tank appeared to be in good condition following removal with no apparent leaks. Two soil samples and one ground water sample were collected by PEMCO following the tank removal to determine site conditions and disposal procedures for soil and water to be removed from the excavation limits. The water sample was analyzed to evaluate the appropriate disposal of dewatering water.
- March 2, 1989. First site visit by Landau Associates, Inc. to evaluate extent of contamination. About one-third of the ground water surface in the excavation had a floating product film. A slightly oily sheen was observed emanating from soil on the west end and a mild odor of fuel was detected at the east and west ends of the excavation. Soil conditions at the site consist of 2- to 3-inches of asphalt overlying approximately 6 inches of brown silty, sandy, crushed rock, which in turn overlies glacial till fill. The Washington State Depart-

ment of Ecology (Ecology) Spill Response Team was notified and informed of existing site conditions.

- March 3, 1989. Verbal results from Sound Analytical Services, Inc. indicate that levels of contamination (see Table 1) are below Ecology's cleanup level guidelines. The Ecology guidelines are presented in Table 2.
- March 6, 1989. The City of Bellevue authorizes disposal of excavated soil to Coal Creek Landfill and ground water to METRO providing adequate sediment control measures are implemented. Northwest Enviroservice removes 600 gallons of oil/water from the surface of the ground water for treatment. PEMCO constructs a sediment catch basin to control turbidity of dewatering water.
- March 7, 1989. Stockpiled soil removed from site and hauled to Coal Creek Landfill for disposal. Dewatering activities at the site were shut down by the City of Bellevue because of excessive sediment being discharged to METRO. Measurements by Landau Associates, Inc. with a Photovac TIP photoionization meter indicate an increase above background of 1.6 units near the exposed product pipes on the east end of the excavation. Other measurements in the excavated area showed no significant increase above background levels.
- March 8, 1989. Excavation dewatered by Allied Environmental Services, Inc. with vacuum trucks. Water was disposed of in a settling basin facility operated by the City of Bellevue for sediment removal prior to discharge to METRO. Soil excavation continued for the new tank installation until sidewall

sloughing threatened the Avis building and nearby sidewalk. Work was shut down until shoring could be installed.

- March 9, 1989. PEMCO set shoring in the excavation to prevent sidewall sloughing.
- March 10, 1989. PEMCO completed excavating for the replacement tank. Soil samples were collected on the east and west ends of the excavation 7 feet below ground surface. Landau Associates determined that no additional sample collection would be necessary for closure of the 5,000-gallon gasoline tank. Laboratory test results, presented in Table 1, from two soil and one water sample collected on March 1 and two soil samples collected on March 10, indicate that all levels of contamination are below Ecology's soil and water cleanup level guidelines. The Ecology guidelines are presented in Table 2.
- March 16, 1989. A second 500-gallon waste oil UST was discovered by PEMCO at the east end of the tank excavation when excavation sidewall sloughing exposed a damaged tank below the previously identified product lines. This 500-gallon tank was not installed or used by Avis; thus, it is probable that the tank was associated with the former gasoline station. The tank contained approximately 250 gallons of oily sludge (on the bottom of the tank) and approximately 250 gallons of water. Samples of the sludge and water from inside the waste oil tank were collected by Northwest Enviroservice for laboratory analysis.
- March 24, 1989. Landau Associates contacted by PEMCO and informed of 500-gallon waste oil tank. The waste oily sludge

was classified by Northwest Enviroservice as hazardous waste based on chromium levels in exceedence of U.S. Environmental Protection Agency (EPA) standards established for used oil. Laboratory results for the waste oily sludge and the EPA waste oil criteria are presented in Table 3. Based on verbal results from PEMCO, the water in the tank did not exceed Ecology's guidelines as presented in Table 2. Laboratory results for the water sample are not included in this report, but are available from PEMCO or Northwest Enviroservice.

- March 28, 1989. Ground water was pumped from the waste oil tank by Northwest Enviroservice for disposal. The tank was purged with dry ice in preparation for excavation and removal. The 500-gallon steel tank was removed and inspected. In addition to a large hole about 6 inches wide by 8 inches long (physical damage prior to discovery by PEMCO) on the top of the tank, three holes approximately 1/8-inch diameter were discovered on the south end, and one hole approximately 5/8-inch diameter was discovered on the east side of the tank. A small amount of water and waste oil sludge leaked from these holes as the tank was being removed from the excavation. The holes were temporarily plugged by PEMCO using clay.

The tank with its contents of oily sludge was removed from the site by and Northwest Enviroservice for processing and proper disposal. Soil around the tank was excavated to remove as much contamination as possible without undermining the building or damaging underground utilities in the area.

It was determined by site inspection that the Avis building is supported by auger cast piles.

During soil excavation, some petroleum product was released from the oily soil onto the ground water in the excavation forming a floating product film. When the maximum practical excavation limits were reached, soil samples were collected from soil at the bottom of the tank excavation, the north sidewall, the east sidewall, and the excavated tank backfill material. Northwest Enviroservice returned and skimmed the floating product film from the ground water surface for processing and disposal. PEMCO planned to skim any additional floating product from the ground water surface prior to backfilling the excavation with pea gravel.

- March 31, 1989. Laboratory test results indicate that some contamination associated with the 500-gallon waste oil tank exists in the soil under the Avis building and the underground utilities at the east limits of the excavation (see Table 4).
- April 4, 1989. Approximately 19 tons of contaminated soil shipped to Cedar Hills Landfill for disposal.

CONCLUSIONS AND RECOMMENDATIONS

Satisfactory removal of two USTs at the Avis Rent A Car facility has been accomplished to the extent that soil removal is feasible. Based on a comparison of the test results in Table 4 and the soil cleanup guidelines in Table 2, a relatively minor exceedence of benzene and total petroleum hydrocarbons exists under the Avis Rent A Car building, and a minor exceedence of total petroleum hydrocarbons exists under the utilities located to the

east of the former waste oil tank. Due to the low levels of contamination remaining, the low permeability characteristics of glacial till fill, presence of the existing building and underground utilities, and the lack of downgradient receptors, we do not believe any additional remedial action is feasible or warranted or that long-term monitoring is necessary. A photographic record of site conditions, as well as all field memorandum documenting UST removal activities, will be maintained in our files to support this conclusion.

We trust that this report meets your current needs. Please contact us if you have any questions.

Respectfully submitted,

LANDAU ASSOCIATES, INC.


By:

William D. Evans, CPG
Project Manager

and


Kenneth G. Chaput
Assistant Project Manager

WDE/KGC:sg
No. 66-05
2 copies submitted



Vicinity Map

NO SCALE



Site Plan

NOT TO SCALE

LANDAU ASSOCIATES, INC.	Site Plan

TABLE 1

Chemical Test Results for 5,000-gallon
Gasoline Tank Soil and Water Samples

	Sample Description				
	Following Steel Tank Removal			Prior to Fiberglass Tank Installation	
Sample Type	Soil	Soil	Water	Soil	Soil
Sample I.D.	1	2	3	1	2
Date Sampled	1 Mar 89	1 Mar 89	1 Mar 89	10 Mar 89	10 Mar 89
Description	West wall of excavation, 5 ft. depth	Center of excavation bottom, 8 ft. depth	Center of excavation bottom, 7 ft. depth	Tank excavation East wall, 7 ft. depth	Tank excavation West wall, 7 ft. depth
Constituents (ppm)	Analysis Results				
Benzene	0.11	0.18	0.033	<0.1	<0.1
Toluene	0.35	2.24	0.038	<0.1	2
Ethylbenzene	<0.05	0.29	0.021	<0.1	<0.1
Total Xylene	1.00	1.90	0.126	<0.1	<0.1
Total Petroleum Hydrocarbons	78	149	<5	50	51
Volatile Petroleum Hydrocarbons	*	*	*	<1	<1

---

* = Not tested.
< = Less than.
ppm = Parts per million.

TABLE 2

Ecology Soil and Water
Cleanup Guidance Levels

Contaminant	Parameter	Soil Cleanup Levels	Water Cleanup Levels
Gasoline	Benzene	660 ppb	66 ppb
	Toluene	143 ppm	14.3 ppm
	Ethylbenzene	14 ppm	1.4 ppm
Diesel, #2 Fuel Oil	Total Petroleum Hydrocarbons (TPH)	200 ppm	15 ppm

---

ppb = Parts per billion.
ppm = Parts per million.

TABLE 3

Chemical Test Results for Oily Sludge
From 500-Gallon Waste Oil Tank

Parameter	Analysis Results	Waste Oil Criteria(a)
Metals (ppm)		
Arsenic	NT	5 ppm max.
Barium	NT	--
Cadmium	<1	2 ppm max.
Chromium	14	10 ppm max.
Copper	13	--
Lead	13	100 ppm max.
Mercury	NT	
Nickel	22	
Selenium	NT	
Silver	NT	
Zinc	80	
PCBs (ppm)	<1	
HOCs (ppm)	<200	1,000 ppm(b)
Flash Point	NT	100 Deg.F. min.

NT = Not tested.
< = Less than.
ppm = Parts per million.

(a) 40 CFR Parts 260, 261, 264, 265, 266, 270, 271 and 302; Regulations Regarding Used Oil.
(b) 4,000 ppm maximum if burned for energy recovery.

TABLE 4

Chemical Test Results for 500-Gallon Waste Oil Tank Soil Samples

	Sample Description			
	Following Waste Oil Tank Removal			
Sample Type	Soil	Soil	Soil	Soil
Sample I.D.	1	2	3	4
Date Sampled	28 Mar 89	28 Mar 89	28 Mar 89	28 Mar 89
Description	Center of Tank, bottom of excavation 8 ft. depth	Composite of excavated Tank backfill for disposal	East wall of excavation, 6.5 ft. depth	North wall of excavation, 6 ft depth
Constituents (ppm)	Analysis Results			
Metals (ppm)				
Cadmium	<0.01	<0.01	<0.01	<0.01
Chromium	<0.05	<0.05	<0.05	<0.05
Copper	<0.03	<0.03	<0.03	<0.03
Lead	<0.10	<0.10	<0.10	<0.10
Nickel	<0.07	<0.07	<0.07	<0.07
Zinc	0.03	0.17	0.04	0.21
Arsenic	<0.03	<0.03	<0.03	<0.03
Purgeable Aromatic Compounds (ppb)				
Benzene	*	55 (a)	*	1,300 (c)
Toluene	*	ND (a)	*	980 (c)
Chlorobenzene	*	ND (a)	*	ND (c)
Ethylbenzene	*	125 (a)	*	3,200 (c)
M+P=Xylene	*	730 (b)	*	15,000 (d)
O-Xylene	*	95 (a)	*	2,800 (c)
1,3-Dichlorobenzen	*	ND (a)	*	ND (c)
1,4-Dichlorobenzen	*	ND (a)	*	ND (c)
1,2-Dichlorobenzen	*	ND (a)	*	ND (c)
Total Petroleum Hydrocarbons (ppm)				
TPH	<5.0	396	626	3,310

(a) Detection Limit = 15 ppb.
(b) Detection Limit = 30 ppb.
(c) Detection Limit = 200 ppb.
(d) Detection Limit = 400 ppb.

* = Not tested.
< = Less than.
ppm = Parts per million.
ppb = Parts per billion.
ND = Not detected.

Ecology Northwest Regional Office

August 10, 1989

TO: Paul O'Brien

FROM: D.A. Davidson

SUBJECT: LUST Leak, Bakker's Fine Dry Cleaning, Bellevue

Case #:	N0094
Date/Time:	8/8/89 - 1350
Substance:	Stoddard's Solvent
Amount:	Unknown
Amount Removed:	Unknown
Reporting Party:	Dave Renstrom City of Bellevue Phone: 455-7818
Responsible Party:	Bakker's Fine Dry Cleaning 12002 NE 8th Street Bellevue, Washington Phone: 454-3003
Environmental Damage:	None Apparent
Media Interest:	None

At 1350, August 8, 1989, I received a call from the City of Bellevue that a LUST was being removed from behind Bakker's Fine Dry Cleaning. During the removal, the tank had apparently leaked an undetermined amount of Stoddard's Solvent (Class 2 Flammability).

Upon arriving on scene I met with Bill Doyle, Bakker's Facilities Manager and John Curnow, a consultant with Geotech. They stated that the tank did not have a leak. Instead they had found that a facility drain line had a crack in it and had been leaking the solvent for an undetermined period of time. The product was fully contained within the evacuation.* Because of the soil makeup, it did not appear that any of the solvent leached into groundwater. John Curnow was taking soil samples. The contaminated soil was being transported to the Fife Sand and Gravel Company to be properly treated/disposed of.

Conclusions/Recommendations

Recommend any followup be carried out by the LUST program.

DAD:kr

cc: Jon Neel
Lee Dorigan

*The soil surrounding the tanks is hard packed glacial till. The tanks themselves were buried in packing sand which appeared to have soaked up most of the product.

PERKINS COIE

A LAW PARTNERSHIP INCLUDING PROFESSIONAL CORPORATIONS
1201 THIRD AVENUE, 40TH FLOOR • SEATTLE, WASHINGTON 98101-3099 • (206) 583-8888

RECEIVED
JUN 14 1989
DEPARTMENT OF ECOLOGY
NORTHWEST REGION

June 12, 1989

Joe Hickey
Northwest Regional Office
Washington State Department
of Ecology
4350 150th Avenue N.E.
Redmond, WA 98052

Re: Avis Rent A Car Underground Storage Tanks

Dear Mr. Hickey:

Enclosed for your information on behalf of our client Avis Rent A Car System, Inc. is a report prepared by Landau Associates, Inc. on the removal of one 5,000 gallon and one 500 gallon underground storage tank from the Avis facility at 11969 Bellevue-Redmond Road, Bellevue, Washington.

The report confirms that both the 5,000 gallon tank and the 500 gallon tank have been removed. Residual soil contamination associated with the 5,000 gallon tank is below Department of Ecology guidelines for gasoline constituents and total petroleum hydrocarbons.

The report indicates that soil around the 500 gallon tank was excavated as completely as possible, but that excavation could not continue without undermining the Avis building or damaging underground utilities. As a result, according to the report, a relatively minor exceedence of Ecology guidelines for benzene and total petroleum hydrocarbons remains under the Avis building and a minor exceedence of total petroleum hydrocarbons remains under the utilities located to the east of the 500 gallon tank site.

Landau Associates believes that due to the low levels of contamination remaining, the low permeability characteristics of the glacial till fill, the presence of the existing buildings and underground utilities, and the lack of downgradient receptors, additional remedial action is not feasible or warranted and long-term monitoring is not

necessary. Accordingly, Avis does not intend to undertake further remedial action or institute long-term monitoring.

If the Department of Ecology has any comments on this matter, we would appreciate your advising us.

Very truly yours,

Douglas S. Little

DSL:FAM:jd
Enclosure

cc: Jerry Pessah
Bill Evans

9553o

CHRISTINE O. GREGOIRE
Director

STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY
4350-150th Ave. N.E. • Redmond, Washington 98052-5301 • (206) 867-7000

July 20, 1989

Douglas S. Little
Perkins Core
1201 Third Avenue, 40th Floor
Seattle, Washington 98101-3099

Re: Avis Rent-A-Car Underground Storage Tank

Dear Mr. Little:

Thank you for the final report from Landau Associates on the underground tank removal and subsequent site remediation at 11969 Bellevue-Redmond Road, Bellevue, WA. I will place the report in our files.

You've indicated in your letter and in a telephone conversation that a small amount of petroleum contaminated soil still remains in excess of Department of Ecology recommended clean-up levels. It's my understanding that this soil could not be removed because further excavation would undermine the existing structure on the property. I will note this fact in the file, and I would recommend removing the remaining contaminated soil at any time it became feasible. I might also suggest as a precaution against future liabilities to monitor the situation with a monitoring well(s).

Sincerely,

Joseph M. Hickey
UST Site Inspector

JH:cw

GEOTECH CONSULTANTS

13256 N.E. 20th St. (Northup Way), Suite 16
Bellevue, WA 98005
(206) 747-5618
(206) 343-7959

ATTACHMENT #2

August 17, 1989

JN 9033

Bakkers Fine Dry Cleaning
11855 Northeast 8th
Bellevue, Washington 98005

Attention: William Doyle, Facilities Manager

Subject: Closure Report
Multiple Underground Storage Tanks
11855 Northeast 8th
Bellevue, Washington

Gentlemen:

In accordance with the terms of our proposal of June 28, 1989, the Environmental Services Division of Geotech Consultants, Inc. has completed field observation, documentation, and laboratory analysis associated with formal "closure" of multiple underground storage tanks (UST's) at the subject site. This activity was initiated to satisfy regulatory requirements imposed under 40 CFR, part 280.72, pertaining to site assessments at time of closure. This report provides a summary of our field and laboratory methods along with results and conclusions.

METHODOLOGY/SCOPE OF WORK

Agency Notification

In compliance with 40 CFR, part 280.71, a letter of notification to the implementing agency (Washington Department of Ecology - WDOE) was sent on June 23, 1989 by Mr. William Doyle of Bakker's Cleaners. A copy of this letter is on file in our office. In addition, in compliance with the request of the Northwest Regional WDOE office, a telephone call was made to the agency at the time of tank removal. Finally, environmental staff of Geotech Consultants, Inc. consulted with Mr. Joe Hickey, UST coordinator for the WDOE Northwest Regional Office regarding details of laboratory testing of soils.

Tank Excavation/Soil and Groundwater Sampling

From August 8 through August 10, 1989 an environmental engineer from Geotech Consultants, Inc. was present during the removal of multiple UST's at the subject site. Tank removal was performed using a track-mounted backhoe operated by Joe Hall Construction of Fife, Washington. Prior to removal, the tank was "conditioned" in a manner consistent with guidelines offered for such work in API Recommended Practice 1604 (Removal and Disposal of Underground Petroleum Storage Tanks), and API Publication 2015. The removal was witnessed by Richard Henderson, Fire Marshall for the City of Bellevue.

Objectives for our participation in the project included:

(1) Photo-documentation of the condition of the UST's along with soil and groundwater appearance in the tank excavation.

(2) Sampling of soil and groundwater for subsequent laboratory analysis.

(3) Generation of a coherent report documenting the activity and findings.

Soil Sampling

With respect to details of soil sampling, following current WDOE guidelines, we obtained a soil sample from each of the four sides of each excavation, and from the bottom of each excavation. Samples were placed in sterilized glass jars with teflon lids furnished by the project laboratory. Samples were stored in an iced chest at the site and taken to the lab in this condition to preserve sample integrity by minimizing excessive dissipation of volatile fraction hydrocarbons. Each jar was clearly labeled as to sampling location, time of sampling, sampling person, project number, etc. EPA recommended protocol for sample management, including maintenance of chain-of-custody documentation, was observed during the course of the project.

Laboratory Analysis

As the UST's at this site reportedly had contained solvents, diesel and distillates during their operating life, EPA Method 418.1 and EPA Method 8010 were used to analyze soil samples. These methods provide a basis for comparison of site conditions at UST sites published in current WDOE guidelines. The detection sensitivity for Method 418.1 is approximately 1 part per million (ppm) for petroleum in water and 5 ppm for petroleum in soils. In addition to EPA Method 418.1, Geotech Consultants, Inc. included one soil sample using EPA Method 8010 for analysis underneath the tank area. This analysis was performed in an effort to assess the potential for the presence of halogenated volatile organic compounds. Included in this family of compounds are many common dry cleaning solvents such as carbon tetrachloride and trichloroethylene.

The test methodology was by Gas Chromatography (GC) accompanied by a Hall-type detector in accordance with EPA Method 8010. Detection limits using this methodology are on the order of 1 part per billion (ppb).

RESULTS OF CLOSURE INVESTIGATION

General Discussion

The subject site is situated on the north side of Northeast 8th Street in Bellevue, Washington, approximately one mile east from the "core" high-rise area. Two buildings on the property are used as dry cleaning facilities. One building is located on the east side of the property and is used for dry cleaning operations. The second building is located directly west and is used for office space and storage.

This site is located in an area underlain by glacially-consolidated materials. Soil materials in this locality are typically characterized by glacial till, clayey silt and gravelly sands. Glacial till is a mixture of compact silt, clay, gravel and sand.

Some minor groundwater seepage was noted during the tank excavation at a depth of approximately eight feet below the ground surface.

Observations During Tank Removal

The multiple tanks removed on August 8 through August 10 included: one 6,000-gallon-capacity UST used for stoddard solvent, one 2,000-gallon-capacity diesel tank, one 2,000-gallon tank formerly used to store distillates (previously thought to be a 400 to 500-gallon tank), and one 200-gallon tank formerly used to store solvents.

Tanks on the property were separated into two adjoining excavations. Excavation No. 1 contained the 200-gallon solvent tank, the 2,000-gallon distillate tank, and the 2,000-gallon diesel tank. This excavation measured approximately 21 feet in width by 28 feet in length, and was 13 feet deep at a location immediately northeast of the existing dry cleaning building. Excavation No. 2 contained the 6,000-gallon stoddard tank and measured approximately 15 feet in width, 34 feet in length, and 11 feet in depth.

All tanks visually appeared to be in very good condition. A review of all tank distribution lines showed no corrosion, holes or defects. All of the tanks had been originally installed in an inert brown sand backfill material.

A characterization of a typical profile of materials/native soil conditions adjacent to the tank excavation (excluding the tank backfill) is as follows:

Depth Range	Soil/Material Description
0 - 3 inches	Asphalt surface pavement
4 - 6 inches	Crushed rock pavement subgrade
6 - 18 inches	Gravelly sand sub-base
1.5 - 5 feet	Light brown silty clay with mottled grey lenses. Firm to stiff, moist.
5.0 - 13 feet	Grey silty clay with occasional sand lenses. Hard, very moist.

During the excavation, discoloration or iridescent "sheens" were noticed in some soil and groundwater near the 2,000-gallon distillate and 200-gallon solvent tanks. In addition, a hydrocarbon odor was detected within the same area. Upon further investigation during the excavation and

tank removal process, it was established that a crushed 4-inch tile drain line was leaking into the subsurface soil within the area of the distillate and solvent tanks, discharging water from a 2-inch floor drain connected to the 4-inch tile line beneath the dry cleaning building. The 2-inch floor drain is connected directly to the stoddard tank room inside the building by two floor drains. According to the operator, this area has been the location of occasional "accidental" spills discharging stoddard fluid directly into the drains during cleanup.

As the excavation process continued, the contaminated water appeared to be confined within the backfill bedding material of the 2,000-gallon distillate tank and the 200-gallon solvent tank. Following the removal of these two tanks, the remaining sand bedding and accumulated water was overexcavated and removed from the site. No further hydrocarbon odor or iridescent "sheens" were noted in the soil or groundwater after this removal. Photographs were made of the excavation to document this observation.

The broken 4-inch tile drain leading from the building has been replaced with a 4-inch PVC drain line and the 2-inch floor drain has been reconnected to the PVC drain line. Based on these repairs, no further seepage of contaminants below the surface is anticipated at this time. Photographs were also made of this repair procedure.

Hydrocarbon Analysis of Soil and Groundwater

As mentioned earlier, a total of five soil samples were obtained from each excavation for laboratory analysis for total petroleum hydrocarbons using EPA Method 418.1 (infrared spectro-photometry). In addition, a single sample from the floor of excavation Number one was analyzed in accordance with EPA Method 8010 for halogenated volatile organic compounds. The following table provides as summary of the results of the laboratory analysis.

As subsurface water encountered during this investigation was attributed solely to seepage from the broken 4-inch tile and connecting 2-inch floor drain, no water samples were analyzed for this site. The removal of contaminated bedding sand and subsequent water contained in the sand left the site devoid of water at the excavation floor.

RESULTS OF ANALYSIS OF SOIL SAMPLES FOR TOTAL PETROLEUM HYDROCARBONS BY IR (EPA METHOD 418.1)

Sample #	Location	Depth (ft.)	Total Petroleum Hydrocarbons (ppm)
3A soil	West Wall	5.5 - 6.0	229.0
4A soil	North Wall	7.5 - 8.0	58.6
5A soil	South Wall	8.5 - 9.0	18.1
6A soil	Floor	12.5 - 13.0	58.1
7A soil	East Wall	7.5 - 8.0	22.3
1B soil	East Wall	6.5 - 7.0	58.4
2B soil	North Wall, ctr.	8.5 - 9.0	27.8
3B soil	West Wall	6.5 - 7.0	14.3
4B soil	Floor	10.5 - 11.0	21.0
5B soil	North Wall, W.sec.	4.5 - 5.0	< 5.0
Quality Assurance			
Method Blank			< 5.0

RESULTS OF ANALYSIS OF SOIL SAMPLE FOR CHLORINATED ORGANIC COMPOUNDS BY EPA METHOD 601/8010

Results Reported as ng/g (ppb)

Sample #	Location	Depth
6A soil	Floor	13.0'

Sample #:	6A
Matrix	soil
Dilution Factor	1:1

Analyte:	
1,1-Dichloroethylene	<1
Methylene Chloride	<1
t-Dichloroethylene	<1
1,1-Dichloroethane	<1
Chloroform	<1
1,1,1-Trichloroethane	<1
Carbon Tetrachloride	<1
1,2-Dichloroethane	<1
Trichloroethylene	<1
Tetrachloroethylene	<1
Tetrachloroethane	<1

CONCLUSIONS/RECOMMENDATIONS

Based on the information developed as a result of this closure investigation, it appears that the soil and groundwater proximal to the former UST installation were not significantly contaminated as as result of the installation's presence or operation. Having satisfied the site assessment requirements of 40 CFR, parts 280.71 and 280.72 in a manner consistent with the guidelines for such actions provided by the Washington State Department of Ecology, and having found no residual hydrocarbon contamination exceeding limits prescribed under prevailing regulatory guidelines of this state, we conclude that no further characterization of this tank installation is required and that it has been properly closed in conformance with the intent and purpose of the aforesaid federal and state regulations-guidelines.

LIMITATIONS

This report has been prepared for specific application to this project in a manner consistent with that level of care and skill normally exercised by members of the environmental science profession currently practicing under similar conditions in the area, and in accordance with the terms and conditions set forth in our proposal dated June 28, 1989. This report is for the exclusive use of Bakkers Fine Dry Cleaning and their representatives. No other warranty, expressed or implied, is made. If new information is developed in future site work which may include excavations, borings, studies, etc., Geotech Consultants, Inc., should be allowed to reevaluate the conclusions of this report and to provide amendments as required.

We appreciate the opportunity to serve you on this interesting project and we trust that the information provided here will be of value in your planning efforts. If you have any questions, or if we can be of further service, please do not hesitate to contact us.

Respectfully submitted,

GEOTECH CONSULTANTS, INC.

John A. Curnow by DWS
Environmental Engineer

Don W. Spencer, M.Sc.
Vice President
Director-Environmental Services

REGISTERED ENVIRONMENTAL ASSESSOR
DON W. SPENCER
No. 876
Expires: _____
STATE OF CALIFORNIA

JAC/DWS:cvb

Petroleum Services Unlimited, Inc.

P S U I

July 18, 1991

Douglas Little
Perkins Coie
1201 Third Avenue, 40th Floor
Seattle, Washington 98101-3099

RECEIVED
SEP 6 1991
STORM & SURFACE WATER UTILITY

Via Facsimile

Re: Avis Sales Lot located at 11969 Bel-Red Road
in Bellevue, Washington

Dear Mr. Little:

Petroleum Services Unlimited, Inc. (PSUI) is pleased to present this summary of the limited site investigation conducted at the above referenced site. As part of the original scope of work, PSUI was to excavate test pits along the north side of the building located at the site in an attempt to locate an underground storage tank (UST) that was suspected to exist. This suspicion was based on a magnetometer survey conducted by Geotech Consultants in the area to the north of the building. The magnetometer survey had identified sub-surface anomalies that could not be positively identified as being an UST, but were of such nature that additional subsurface investigation was warranted.

In addition, PSUI, under Geotech Consultants' direction, conducted additional test pits in an area of the site not previously investigated. The test pit locations were based on historical photos of the site that showed former petroleum handling equipment at the site as well as other sub-surface anomalies.

1081 Columbia Boulevard • Longview, Washington 98632
(206) 423-2245 FAX (206) 423-2272


Summary Activities

Based on previous subsurface investigations (Landau and Assoc. 1989; Geotech Consultants 1991), petroleum contamination is known to exist at the Avis Car Sales Lot from previous petroleum handling equipment operated at the site. Therefore, in coordinating site activities to minimize disruption of current site uses, a permit for disposal of contaminated soils was applied for and granted by the King County Department of Public Health, Waste Screening Program. The reason for immediate disposal was to remove contaminated soils from the site and avoid stockpiling where space for such activities is limited.

PSUI mobilized and coordinated the test pit activities on July 16 and 17, 1991 under the general direction of Geotech Consultants. Utilities markouts were arranged to aid in determining safe test pit locations. The following observations and activities were conducted:

o Eight test pits at the Avis Car Sales Lot site were excavated, logged and sampled in accordance with generally accepted scientific procedures;

o Four of the test pits were located adjacent to the north wall of the building located at the site (refer Figure 1);



AVIS CAR SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON

Figure 1

Site Location

PETROLEUM SERVICES UNLIMITED, INC.

o All four of the test pits encountered pea gravel of varying thickness. The first test pit 1, TP1, encountered pea gravel approximately 2 feet thick adjacent to the building overlying a remnant asphalt pavement layer. Soils encountered below this layer were a grey gravelly sand with an odor of petroleum and photo-ionization detector (PID) measurements of 21.5 parts per million (ppm). Two soils samples were collected at the south end of the excavation. One sample, TP1-1, was collected using the backhoe bucket to bring soils to the surface where they were transferred with a decontaminated stainless steel trowel into a laboratory prepared sample container. The other sample, TP1-2, was collected from undisturbed soils approximately 3 feet from the north wall of the building using a decontaminated stainless steel hand auger that was used to auger into the side wall of TP1. The auger was then brought to the surface where the soils were transferred by a stainless steel spoon into a laboratory prepared sample container;

o A decision was made in the field to expanded TP1 by trenching out perpendicular to the building to determine if the extent of field detectable contaminated soils could be identified. The pea gravel back fill created excavation difficulties due to sloughing of the side walls. TP1 was expanded to approximately 20 feet out from the building. Pea gravel was estimated to extended 6 feet below pavement grade at this location. A soil sample (TP1-3) was collected from soils brought up from below the pea gravel at the 6

to 7 foot depth in gravelly sands with PID measurements of 23 ppm. TP1 was then abandoned and back filled with material brought from off site;

o A decision was made in the field to have sample TP1-2 analyzed to identify the type of contaminant (if any) in the soils at this location. The sample was hand delivered to ASI Laboratories in Bothell, Washington for total petroleum hydrocarbons analysis by EPA Method 8015 Modified;

o TP2 was excavated out from the northwest corner of the building (refer figure 1) in an area identified as having a magnetic anomaly. TP2 is characterized as back fill material with a .5 foot layer of pea gravel at the 1.5 to 2 foot depth below pavement grade. None of the back fill material exhibited any PID measurements. A brown silt loam with roots throughout was encountered at the 5 foot depth. A soil sample (TP2-4) was collected at the fill material/loam interface;

o TP3 was excavated out from the natural gas utility meter (refer figure 1). Pea gravel was encountered from below pavement grade to approximately the 4 to 5 foot depth. Due to sloughing of the pea gravel, the bottom of the excavation was not observed. Soils brought to the surface in the backhoe bucket were characterized as a grey/blue gravelly sand-sandy gravel fill material with PID measurements of 72 ppm. A soil sample was collected from these

soils (TP3-5);

o TP4 was excavated out from the northeast corner of the building (refer figure 1) adjacent to a 2.5 foot high retaining wall bordering the neighbors' property to the east. Pea gravel was encountered from below pavement grade to approximately the 4 to 4.5 foot depth. Due to sloughing of the pea gravel, the bottom of the excavation was not observed. The retaining wall was exposed as a result of the sloughing and is estimated to extend 3 feet below pavement grade. Soils brought to the surface in the backhoe bucket were characterized as a gravelly sand with some clay lenses with PID measurements of 74 ppm. A soil sample was collected (TP4-6);

o TP5 was excavated out from the building (refer figure 1) in an attempt to determine if field detectable contaminated soils extended to the north at the site. Upon excavating TP5, a vertical cut in the subsurface soils was observed. To the south toward the building was pea gravel to an unknown depth. To the north, TP5 is characterized as a crushed rock back fill below pavement grade to the 1 foot depth that is in contact with a 4 inch layer of remnant asphalt pavement. Below this asphalt layer is a brown gravelly sand to the 2 foot depth and below this is a blue/green sand with occasional gravels with PID measurements of 32 ppm. At the 6 foot depth these sands become wet to the 7 foot depth where they are in sharp contact with a peat loam. The sands at the 5 foot depth have PID measurements of 64 ppm. A soil sample (TP5-7) was collected

from the sands at the 6 to 7 foot depth;

Based on the above observations, it can be summarized that a shallow depression or excavation in the area to the north of the existing building has been back filled with pea gravel and brought to the current grade at the site.

o TP6 was excavated to the west of the building (refer figure 1) at the center of the parking area. This area is a low spot at the site and historical photos show that a pump island had been located in the general vicinity. Soils in TP6 are characterized as blue/green gravelly sand to the 1 foot depth, brown sands to the 2 foot depth in contact with a blue/green coarse sand with gravels with an odor of petroleum to the 3 foot depth. These sands are in sharp contact with a dark brown silt loam with wood chips and roots throughout. A soil sample (TP6-8) was collected at the 3 foot depth at the sand/loam interface;

o TP7 was excavated approximately 22 feet south of TP6 (refer figure 1). Pea gravel was encountered at the 2 foot depth below a sandy gravel fill material. Due to sloughing of the pea gravel, TP7 was abandoned for structural reasons to avoid creating a depression after back fill and compaction. It is estimated that the backhoe bucket penetrated to 5 feet below pavement grade without encountering any soils. No sample was collected;

o TP8 was placed and excavated approximately 16 feet south of TP7

toward NE 8th Street. Soils in TP8 are characterized as a brown sandy gravel fill material to the 1.75 foot depth below pavement grade. At 1.75 feet is a blue/green gravelly sand with an odor of petroleum to the 3 foot depth, a brown silt loam with roots throughout to the 3.5 foot depth, a light green, fine to medium sand with silt with and odor of petroleum to the total depth of the test pit at the 6 foot depth. A groundwater seep was noted at the 5 to 5.5 foot depth in TP8. This groundwater entered the test pit and ponded in the bottom. A noticeable sheen was observed floating on the surface of the water in TP8. Soil samples were collected from two different depths in the test pit. Sample TP8-9 was collected at the 5 foot depth in sandy soils with PID measurements of 7.2 ppm. Sample TP8-10 was collected at the 3 foot depth above the silt/loam layer of soil in gravelly sand with an odor of petroleum and PID measurements of 418 ppm. The PID measurements on samples TP8-9 and TP8-10 were made in the headspace of the sample jars on July 18, 1991.

Based on the above observations, it can be summarized that a second depression or excavation was identified to the west of the building at the Avis Car Sales Lot in an area that had been identified as having petroleum dispensing equipment operated on or near.

Sample TP1-2 analytical results indicated diesel contamination at 2200 ppm in the soils adjacent to the north wall of the building at the site. This level of contamination did not affect the

disposition or disposal of the soils excavated during test pit explorations.

In an interview with Gary Smith, the current Avis site manager, he indicated that the prior Avis site manager was aware of UST removal in the general area of TP7. This is information that can only be verified by Avis and is incorporated into this report as information that should be substantiated or investigated at greater depth as field detectable petroleum contamination has been identified in this general area.

In a matter of expediency, this letter has been prepared to summarize the extent of field activities conducted by Petroleum Services Unlimited, Inc. We are now in possession of nine soil samples collected during the exploratory test pit activities. The holding times of samples of this type are 14 days for petroleum hydrocarbons analysis. We would be happy to have selected samples analyzed at the request of Perkins Coie.

Reporting requirements for this project were not specified in the scope of work, therefore, this correspondence, without further scope of work modification, will be considered the extent of reporting.

Petroleum Services would be happy to consult and propose additional work at the site that appears to be necessitated based on the field and analytical data collected to date.

Please feel free to call me or John Polk if you have any questions or need additional information regarding the project.

Sincerely:
Petroleum Services Unlimited, Inc.

Charles R. Grant
Washington Department of Ecology UST Section Registered Site Assessor

xc: Mark Holcomb, Avis Rent A Car Systems, Inc
Don Spencer, Geotech Consultants

BORING 3

Moisture Content(%)	Sample	Blows per Foot	USCS	Description	Elevation	Dep
				Asphaltic concrete, pea gravel		
		4.67' ▼	SM	Gray, silty SAND with some gravel, wet, loose.		
5	1	10		Hydrocarbon odors noted in soil and groundwater		
			ML	Gray, sandy, coarse, non-plastic SILT, moist, wet, very loose.		
10	2	50/3"				
			SM	Gray, coarse SAND with gravel and silt, wet.		
16	3	50/6"				

Test boring terminated at 16.5 feet on 5/1/91.

GEOTECH
CONSULTANTS, INC.

TEST BORING LOG

11969 BELLEVUE - REDMOND ROAD
BELLEVUE, WASHINGTON

Job No:	Date:	Logged by:	Plate:
1107	MAY 1991	SPO	6

SR
12-23-91
BDF

Soil, Gw
Interim

#1215

DEC 19 1991
DEPT. OF ECOLOGY

12-12-91

Report on

Groundwater Monitoring and Investigation and Cleanup

of

Petroleum Contaminated Soils

at the

Avis Rent-A-Car Sales Lot
11969 Bellevue-Redmond Road
Bellevue, Washington 98005

Prepared for

Perkins Coie
1201 Third Avenue
Seattle, Washington 98101-3099

Prepared by

Pacific Northern Environmental Corp.
dba Petroleum Services Unlimited
1081 Columbia Blvd.
Longview, Washington 98632

12.12.91

Introduction

Petroleum Services Unlimited was contracted through counsel for Avis Rent-A-Car Systems to conduct an investigation and clean-up of Avis' property at 11969 Bellevue-Redmond Road in Bellevue, Washington. Please see figure 1 for site location. The scope of work consisted of the following:


- Excavation and removal of petroleum impacted soils and disposal at an approved facility;
- Confirmation sampling;
- Installation of one groundwater monitoring well and development and sampling of the well;
- Sampling of existing groundwater monitoring wells in the clean-up area at the site;
- Restoration of the impacted area and previous subsurface investigation areas;
- Oversite, documentation and reporting of activities.

Prior to initiating the work, the following City of Bellevue permits were required:

- Storm and Surface Water Utility Engineering Division: Clearing, Grading Excavation or Fill Permit;
- Department of Public Works and Utilities: Side Sewer Permit;
- Department of Public works and Utilities: Right of Way Use Permit.

During the clean-up action, the following unforeseen circumstances were encountered:

- Discovery of an abandoned and truncated City of Bellevue 16 inch concrete storm or sanitary sewer pipe that was discharging water into the subsurface at the site;
- Discovery of a 4 inch concrete pipe that was connected to and was discharging water into the abandoned sewer pipe;
- Mineral spirits contaminated soils identified beneath the abandoned sewer pipe in a corner of the property that had not been previously investigated.



AVIS CAR SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON

Figure 1
Site Location

PETROLEUM SERVICES UNLIMITED, INC.

Upon discovery of the abandoned sewer pipe and running water, the City of Bellevue was notified. Subsequent actions regarding the sewer pipe and soils are discussed later in this report.

The field activities were conducted during the week of 23 September, 1991. Photographs were taken during the course of the field activities and are attached. This report discusses the environmental oversite and construction activities undertaken to remove diesel and mineral spirits impacted soils, and characterization and monitoring of groundwater at the site during this clean-up.

Background

The Avis Sales Lot property has been owned and operated by Avis Rent-A-Car Systems as an automobile sales lot since approximately 1976. Prior to Avis, the lot was owned by Dubose, Inc. for approximately three years (1973-1976). Prior to then, the lot was owned by Gulf Oil and prior to Gulf by Fletcher Oil. Historical records indicate that Gulf and Fletcher operated the site as a commercial gas station and automobile service station. The commercial gasoline station was built in 1956. A records search to determine when the petroleum handling/dispensing equipment operated by Gulf and Fletcher was removed from the site has not been conducted.

In 1991, Avis initiated a property transaction for the Avis Sales Lot. As part of the transaction, a Phase II property investigation was conducted for the potential buyer by Geotech Consultants of Bellevue, Washington. Exploratory soil borings with monitoring well installations were conducted. Geotech identified diesel contaminated soils and gasoline contaminated groundwater and recommended additional investigation to determine the source for the contamination that it found.

In July of 1991, Petroleum Services Unlimited was contracted to investigate the extent of diesel contaminated soils at the site. During this investigation, these soils were approximately delineated in the area to the north of the building at the site. Also during the investigation, soils containing low levels of mineral spirits were identified in the south west portion of the site adjacent to NE 8th Street in an exploratory test pit. This mineral spirits contamination was determined to be below Ecology cleanup guidelines and no further action was taken regarding these soils.

Site Description

The Avis Sales Lot is located on a pie shaped lot on the corner of Bellevue-Redmond Road and NE 8th Street in Bellevue, Washington (refer figure 2). There is one building at the site. Part of the building is used for offices. A drive through garage bay is used as a hand car wash. Another room, now used for storage, is a former service bay with a hydraulic hoist in the floor. There is one 6000 gallon double wall fiberglass underground storage tank (UST) located in the south east corner of the lot that is used to store unleaded gasoline for refueling Avis' rental fleet. The remainder of the lot is a paved parking/storage area used for sale of automobiles.

The site is located at the basal part of a small hill and is generally flat with a slight grade toward the west for drainage of the pavement. Soils at the site are described as follows:

o The top 1 to 2 feet are a crushed rock, gravel and sand back fill material;


o From approximately the 2 to 4.5-7 foot depth, there is an unconsolidated layer described as a brown, sometimes grey to grey blue clay, very compact, dry to moist, clay with silty clay and sandy clay lenses with occasional angular gravels throughout. This material varies in thickness from 3 to 5 feet thick at the site;

o This material is in direct contact with a dark brown, wet, organic rich peat loam with abundant roots throughout. This peat layer was penetrated and is between 1 and 2 feet thick in the area investigated;

o The peat layer overlies a light grey, saturated, poorly graded fine sand to a depth of at least 16 feet, the total depth of the exploratory borings drilled at the site.

Utilities and Permits

In planning the clean-up, certain utilities were known to cross the area north of the Avis building where most of the work was to be conducted. In addition, the City of Bellevue has construction regulations that require work plan review and approval prior to issuance of permits to conduct construction activities. The permits were applied for and granted. The permitting process added about a month to the schedule for the work.



AVIS SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 2

SITE FACILITY MAP

PETROLEUM SERVICES UNLIMITED

Prior to initiating the field work, these subsurface utilities had to be addressed:

- Washington Natural Gas service hookup to Avis building;
- Side Sewer to City of Bellevue Sanitary Sewer;
- Puget Power electric cables.

The following is a brief discussion of the actions taken with the known utilities during the field activities at the site:


Washington Natural Gas Washington Natural Gas service to the Avis building from the north east corner of the lot was to be exposed in the area to be excavated. The location of the gas line is shown on figure 3. On 23 September, 1991 this line was capped and cut and the service to the Avis building disconnected by Washington Natural Gas.

The natural gas was reconnected on 26 September, 1991 by Washington Natural Gas. The hook up was completed with plastic pipe. Service to the building was restored on 30 September, 1991 after completion of subsurface activities at the site.

The natural gas line that was removed was of a coated steel construction. For age dating purposes, it is likely that the gas utility was installed prior to 1971. After 1971, plastic pipe was used for gas service hookups to residential and commercial buildings from the main lines. The steel line has had some repairs conducted on it in the past as indicated by sealant tape on different sections of the line.

Puget Sound Power and Light Company A Puget Power Utility vault is located in the north east corner of the property as shown on figure 3. The cover to the vault was not marked. During surface asphalt excavation, the vault cover was knocked loose. Some damage to the electric cables occurred. Puget Power was notified of the mishap. A representative of Puget Power visited the site and assessed that the coating on two of the three electric cables had been scraped.

Puget Power indicated to Petroleum Services that the cables could be fixed in the vault using a heat shrink wrap patch over the scraped portions of the cable. The damage did not appear extensive and Puget Power replaced the vault cover and left the site. At the time of this report, Petroleum Services has not been notified that the repairs have been made.



AVIS SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 3

UTILITIES MAP

PETROLEUM SERVICES UNLIMITED

City of Bellevue: Side Sewer Permit #9138 It had been anticipated that, during the soils removal to the north of the office building and car wash, a portion of the side sewer to the building would be removed and replaced. Therefore, a side sewer permit from the City of Bellevue (COB) Department of Public Works and Utilities was obtained to work on the side sewer, which is shown on figure 3.

During excavation, the 6 inch side sewer pipe was located and exposed. It was discovered that the pipe could be excavated around and left intact. The soils around the sewer pipe were removed for the entire length it crossed the excavation.

On 24 September, 1991 prior to backfilling, the sewer pipe was inspected by the City of Bellevue. During the inspection, the city observed that the 6 inch sewer pipe was not in compliance with current City Codes. The current codes require the following:

- Clean out traps within 2 feet of exterior walls of building;
- Rubber connections between pipe sections.

Based on Petroleum Services not impacting or disturbing the sewer pipe, the City Inspector indicated that current codes did not have to be met. Special instructions were given regarding back filling the sewer pipe with pea gravel. These instructions were carried out and the sewer pipe was back filled on 24 September, 1991. A copy of the completed and signed side sewer pipe permit is attached to this report.

City of Bellevue Storm and Surface Water Utility: Clearing, Grading, Excavating or Fill Permit #CGLF-91-7706 Before initiating subsurface work, a clearing, grading, excavating or fill permit from the City of Bellevue Engineering Section was obtained. Due to the limited area being impacted, the City did not impose some of the typical requirements (Geotechnical Report, Engineer's stamp, Architect's stamp).

The excavation was backfilled and compacted on 1 foot lifts from the total depth of the excavation (depths varied from 4.5 to 7 feet) with a 1500 pound, walk behind "whacker". The impacted area was regraded and re-paved during the week of 14 October, 1991 by Emerald Paving of Kent, Washington.

City of Bellevue Right of Way Use Permit #2411 In order to use public right of ways for heavy equipment and transportation trucks, a use permit was obtained. Two licensed traffic control flaggers and proper traffic control signage were utilized throughout the onsite activities.

Soils Removal

Soil removal activities were conducted on 23 and 24 September, 1991 under the supervision of a Washington Department of Ecology (Ecology) Underground Storage Tank Program Registered Site Assessor from Petroleum Services. Based on previous investigations (Geotech, May, 1991; Petroleum Services, July, 1991) conducted at the site, diesel concentrations above the Model Toxics Control Act Cleanup Regulations (MTCA from WAC 173-340) Method A Cleanup Levels were known to exist in the soil to the north of the Avis building. Shallow groundwater is found at between 5 and 6 feet below grade surface at the site. Therefore, the soils cleanup consisted of excavating field detectable contaminated soils down to groundwater.

During excavation activities, the following observations and actions were made:

o A field notebook was maintained during all field activities;

o A Photovac Microtip photo-ionization detector (serial #NA900031) was calibrated in accordance with manufacturer's specifications at the beginning of each work day;

o The surface asphalt layer to the north of the Avis building was broken up, excavated and removed from the site. The asphalt was disposed of at Cadman Gravel Company in Redmond, Washington;

o It had been anticipated that pea gravel would be encountered in the area to the north of the Avis building. The surface layer of crushed rock and gravels was excavated down to the pea gravel fill and was stockpiled in the western portion of the parking area. At the end of the stockpiling activities, a sample (PCA-EX1) was collected from the stockpile for characterization to determine if the approximately 30 yards of stockpiled material could be used as backfill material. The sample was analyzed by Ecology Method WTPH-HCID. Analytical results of the sample identified oil contamination and a subsequent analysis for total petroleum hydrocarbons by EPA Method 418.1 indicated petroleum hydrocarbons at 280 parts per million (ppm). Table 1 presents the results of the analyses. These materials were subsequently removed and transported to Hillsboro Landfill in Oregon for disposal;

o Pea gravel at the site was stockpiled separately from the crushed rock and gravel fill material Petroleum Service's interpretation is that the pea gravel was back fill in a former UST excavation. Thereafter, the pea gravel was used as back fill in the excavation after field detectable soils had been removed. A sample of the pea gravel (PCA-EX2-PEA) was collected and analyzed by EPA Method 8015. The results did not indicate the presence of

petroleum hydrocarbons. The analytical results are presented in Table 1.

Table 1

Excavated Surface Fill and Pea Gravel Analytical Results by Method WTPH-HCID, EPA Method 418.1, and EPA Method 8015 in parts per million (ppm)

Sample Number	Location	WTPH-HCID	418.1	8015
PCA-EX1	One location in excavated soils stockpile	*D	280	
PCA-EX2-PEA	One location in pea gravel back fill			ND


*D = analytical method detected oil contamination
ND = none detected at or above the method reporting limit
A blank means no analysis was made

A copy of the analytical results with QA/QC data and chain of custody records is attached to this report;

o During excavation of the pea gravel, some large blocks of concrete and a floor hoist were encountered. The concrete was removed and disposed of at Cadman Gravel in Redmond, Washington. The floor hoist was removed and disposed of as scrap metal;

o Field screening methods (odor, color, photo-ionization detector measurements) were used to identify contaminated soils at the site. Field detectable contaminated soils were encountered adjacent to the pea gravel in the excavation. A verticle cut in the native soils was in contact with the pea gravel. This verticle cut was followed in a northerly and westerly direction at the site (see figure 4 for excavation boundaries). The majority of field detectable contaminated soils appeared to extend laterally approximately 2 to 3 feet into the native soils in the verticle cut;

o Soils were excavated to below the groundwater table on both the east and west sides of the side sewer that is located in the



AVIS SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 4

EXCAVATION AND SOIL SAMPLE LOCATIONS

PETROLEUM SERVICES UNLIMITED

contaminated soils excavation area (refer figure 3). Groundwater that ponded in the excavation had a sheen;

o The native clayey material and peat soils that exhibited field detectable contamination in the side walls were excavated and loaded into dump trucks for transport to and disposal at Hillsboro Landfill in Hillsboro, Oregon. The soils were disposed of under Hillsboro Landfill special waste permit #611. A copy of the permit is attached to this report;

o The dump trucks were operated by Cornerstone Construction of Tacoma, Washington (ICC Permit #MC-225354). Five dump trucks totaling approximately 130 cubic yards of diesel contaminated soils were removed from the site. One dump truck load of the stockpiled oil contaminated soils was also removed from the site. All soils were transported to and disposed of at Hillsboro Landfill;

o During excavation on 23 September, 1991 a 16 inch outside diameter concrete sewer pipe was uncovered. The sewer pipe had not been identified during utilities locating at the site (locate #91383960). As shown on figure 5, the pipe runs along the east property boundary adjacent to a concrete retaining wall that separates the Avis Sales Lot and the neighbor to the east, Bakker's Fine Dry Cleaning. Upon discovering the sewer pipe, Petroleum Services notified the City of Bellevue Storm and Surface Water Utility (SSWU);

o A soil sample (PCA-SS1-6.5') was collected from beneath the 16" concrete pipe, because at the time of discovery of the pipe, it was not anticipated that the pipe would be removed. The soils from beneath the 16" pipe exhibited odors of petroleum and photo-ionization detector measurements of 90 ppm. See table 2 for analytical results;

o Confirmation soil samples were collected from the cleanup excavation side walls after field detectable contaminated soils had been removed (refer figure 4 for soil sample locations). A discussion of soil sampling methods is attached to this report. Initially, the confirmation samples were analyzed for WTPH-HCID. This sampling protocol was modified to EPA Method 8015 for Diesel #2 because the initial WTPH-HCID samples and previous investigations indicated the presence of diesel in the soils. Table 2 presents the sample identification numbers, location, and the analytical results of the confirmation samples;

Table 2

Excavation Confirmation Samples Analytical Results by WTPH-HCID and for Diesel #2 by Modified EPA Method 8015
In parts per million (ppm)

Sample Number	Location	WTPH-HCID	8015
PCA-SS1-6.5'	East side wall of excavation beneath 16" concrete pipe at 6.5 foot depth	*D	2,100
PCA-SS2-5.5'	NE side wall of excavation at 5.5 foot depth	ND	
PCA-SS3-5.5'	North side wall of excavation at 5.5 foot depth		63
PCA-SS4-5.5'	West side wall of excavation at 5.5 foot depth		ND

*D = analytical method detected diesel contamination
ND = none detected at or above the method reporting limit
A blank indicates no analysis was made.

Copies of the analytical results with QA/QC data and chain of custody records is attached to this report.

o During excavation activities, the 16 inch sewer pipe had been knocked loose at a bell joint in the pipe. Water was leaking from this joint and a temporary patch of clay from the site was used to stop the flow of water until the pipe could be inspected. On 24 September, 1991 during an attempt to patch another leak at another bell joint in the 16 inch sewer pipe, the pipe was observed to terminate without any capping in the excavation created during contaminated soils removal. The end of the pipe was approximately 15 feet north of the Avis Building. The pipe at this time was discharging a steady stream of water into the excavation. A sample (PCA-Sewer) of the water being discharged was collected for chemical analyses. Results of the analyses are discussed below. Further attempts to cap the sewer pipe were unsuccessful due to the volume of water that was running through the pipe. An estimate as to the volume of water that had discharged into the excavation on 24 September, 1991 was put at greater than 200 gallons but less than 500 gallons;

o The water sample collected from the 16" concrete pipe was analyzed for benzene, toluene, ethyl-benzene and xylenes by EPA

Method 8020 (BTEX) and for total petroleum hydrocarbons by EPA Method 8015 (TPH). Results of the BTEX analysis identified only meta- and para-xylene at 3 parts per billion (ppb). Results of the TPH analysis indicated the presence of gasoline and oil. Further discussion of the water being discharged is presented below;

o On 24 September, 1991 a City of Bellevue SSWU Inspector visited the site to observe the 16 inch sewer pipe. Upon the inspection, it was determined that the sewer is an abandoned line and is not shown on any current Bellevue sewer maps. The timing of the abandonment of the pipe as not been determined.

o Further investigation with the City of Bellevue Inspector revealed the following: There is a surface water catch basin located in the north east corner of the property. This catch basin acts as a storm water drain for the Bakker's Fine Dry Cleaning property located to the east of the Avis property (refer figure 2). A test to see if the 16 inch sewer pipe was connected to the catch basin was conducted by banging the 16" pipe in the excavation and listening for the repercussion at the catch basin. This test indicated that the catch basin and 16" sewer pipe were connected. To verify the connection, a dye test was conducted by dumping approximately 40 gallons of green dyed water into the catch basin and awaiting the discharge from the 16" pipe. This test proved conclusively that the catch basin and 16" pipe were connected. It was also noted that the 16" pipe was plumbed to drain to the south toward NE 8th Street, i.e. away from the catch basin and onto the Avis property;

o The water discharging from the 16" pipe was coming from an unknown source. This observation was evidenced by the fact that the surface water catch basin in the northeast corner of the lot was dry, but water was discharging from the pipe. Therefore, a decision was made to excavate and remove the 16" concrete pipe in an attempt to identify the source of the water;

o On 25 September, 1991 the 16" concrete pipe was excavated in a northerly direction. Soils identified as having diesel concentrations at 2,100 ppm (PCA-SS1-6.5') below the pipe were excavated in an easterly direction to the concrete retaining wall on the property boundary between the Avis Sales Lot and Bakker's Fine Dry Cleaners;

o Upon further excavation of the 16" concrete pipe in a northerly direction, field detectable contaminated soils ended and only the 16" pipe was excavated and removed;

o After excavation in this area, confirmation samples were collected from the clays in the east side wall and from the floor of the excavation in native peat soils. The sample locations are shown on figure 4. The samples were analyzed for diesel #2 by Modified EPA Method 8015. Table 3 presents the sample identification numbers, location, and the analytical results. Analytical results of the samples indicate that the contamination identified in PCA-SSI-6.5' was removed by this subsequent excavation.

Table 3

Excavation Confirmation Samples Analytical Results for
Diesel #2 by Modified EPA Method 8015
In parts per million (ppm)

Sample Number	Location	8015
PCA-SS5-5.5'	East floor of excavation at 5.5 foot depth in peat soils	ND
PCA-SS6-5'	East side wall of excavation at 5' depth below former 16" concrete pipe location	ND

ND = none detected at or above the method reporting limit


Copies of the analytical results with QA/QC data and chain of custody records is attached to this report;

Based on the information presented above, diesel contaminated soils to the north of the Avis building have been removed with the exception of the north side wall (sample PCA-SS3-5.5') of the cleanup excavation. Diesel contaminated soils remaining in the north side wall are below MTCA Method A cleanup levels.

4" Concrete Pipe and Mineral Spirits Contaminated Soils

Upon completion of the soils removal from below the 16" concrete pipe, excavation of the 16" concrete pipe continued. The following observations and actions were made on 25, 26 and 27 September, 1991:

o As shown on figure 5, approximately 40 feet north from the Avis building, a 4" concrete pipe was connected to and discharging a steady stream of water into the 16" concrete pipe.



AVIS SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 5

EXCAVATION AND SOIL SAMPLE LOCATIONS

PETROLEUM SERVICES UNLIMITED

The 4" pipe trends directly east and exits from the Bakker's Fine Dry Cleaners' property. The water was coming from an as yet unidentified source and was notably warm and clear. A sample of the water discharging from the 4" pipe was collected for chemical analyses. Results of the analyses conducted are discussed below;

o Upon collection of the water sample, a test plug was inserted into the 4" pipe to seal it from discharging water. This plug proved to be unsuccessful as the soils around the 4" pipe became saturated with water and started seeping into the 16" concrete pipe excavation, indicating the 4" pipe had some cracks or leaks upstream from its outlet;

o A City of Bellevue SSWU Inspector observed the water discharging from the 4" pipe. At this time, the inspector indicated that a plug could be placed into the 16" pipe at the catch basin at the northeast corner of the lot. He was satisfied that the source of the water discharging from the 16" pipe had been found;

o Bakker's Fine Dry Cleaners had become an active observer of the site activities after discovery of the 4" concrete pipe. In communications on 25 September, 1991 with Ernie Bakker of Bakker's Fine Dry Cleaning, it was learned that the 4" pipe was connected to floor drains in the laundry processing rooms and steam boiler room in the Bakker's dry cleaning facility;

o On 26 September, 1991 at the request of Mr. Bakker, Petroleum Services assisted with the collection of a second sample of the water discharging from the 4" pipe. This sample was taken by a representative of Bakker's. Bakker subsequently provided the test results, which are reproduced in Table 4 (see #1 Bakker Dr). Bakker is responsible for the chain of custody and results on this sample. The Bakker sample and the earlier sample (PCA-4" H20), were collected about 23 hours apart;

o Water sample PCA-4" H20, collected from the 4" concrete pipe, was analyzed for BTEX by EPA Method 8020, for TPH by EPA Method 8015, and for chlorinated solvents by EPA Method 8010. Results of the BTEX analysis did not identify any of the BTEX group of compounds. Results of the TPH analysis did not detect any petroleum hydrocarbons. Results of the chlorinated solvents analysis indicated the presence of trichloroethylene at 11 ppb and tetrachloroethylene at 1,600 ppb. Table 4 presents these results;

o The Bakker water sample (#1 Bakker Dr), from the 4" pipe was analyzed for BTEX by EPA Method 8020 and TPH by EPA Method 8015 by AmTest Laboratory in Redmond, Washington. Results of the TPH analysis did not detect any petroleum hydrocarbons. The BTEX volatiles analysis results on the water sample indicated that

assorted halogenated compounds were detected. They included isomers of di, tri, and tetrachloroethane. No quantitation for the halogenated compounds were performed, but the levels were noted by the lab to be significant. Results of the analyses are presented in table 4.

Table 4

16" Sewer Pipe and Bakker's 4" Pipe: Water Analytical Results for BTEX by EPA Method 8020, TPH by EPA Method 8015, and Chlorinated Solvents by EPA Method 8010 in parts per billion

Sample Name	Location	8020	8015	8010
PCA-Sewer	16" abandoned concrete sewer pipe	3*	ND	
PCA-4"H20	4" concrete pipe from Bakker's property	ND	ND	11** 1,600***
#1BakkerDr	4" concrete pipe from Bakker's property	ND****	ND	

ND = none detected at or above the method reporting limit
A blank indicates no analysis was made
* = analytical method identified meta- and para-xylene
** = analytical method identified trichloroethylene
*** = analytical method identified tetrachloroethylene
**** = AmTest Laboratory analytical results (done for Bakker's) note assorted halogenated compounds were detected in the samples. They included isomers of di, tri, and tetrachloroethane. The lab performed no quantitation, but noted that levels are significant.

Copies of the analytical results for each sample with QA/QC data and chain of custody records is attached to this report.

o Native soils from beneath the 16" pipe in the vicinity of where the 4" pipe was connected had a petroleum odor with photo-ionization detector measurements of 92 ppm. The odor was dissimilar to the diesel odors emanating from the previously excavated soils. A sample (PCA-SS7-4') of the soils was collected for chemical analysis by WTPH-HCID from the location shown in Figure 5. Table 5 presents the sample number, location and analytical results of the sample collected;

o Results of the WTPH-HCID analysis identified the presence of mineral spirits. Although there was no apparent source on the Avis property for this contamination, a decision was made to excavate the mineral spirits contaminated soils as close to the property line as possible;

o In addition, a representative for Bakker's collected a soil sample (#4 Avis Soil) from the soils beneath and to the north of where the 4" pipe exits the Bakker property and submitted it for chemical analyses at AmTest laboratory in Redmond (refer figure 5). This sample was taken approximately 12 feet from where sample PCA-SS8-6' was collected. Results of the analysis are presented in table 5;

o On 26 September, 1991 mineral spirits contaminated soils were excavated in a northerly direction along the property boundary between the Avis Sales Lot and Bakker's Fine Dry Cleaning. Grey green discolored soils (with photo-ionization detector measurements of 12 to 316 ppm) were noted to slope down in the subsurface from the concrete retaining wall on the property boundary and bisect the 16" concrete pipe. The discolored soils then continued in a nearly verticle contact with non-discolored soils to the 7 foot depth. These field observations indicate that the mineral spirits contamination spread to the Avis property from the Bakker property;

o The 16" pipe and field detectable contaminated soils were excavated in a northerly direction until the Washington Natural Gas line was encountered. No further excavation was done in this direction due to the gas line and the underground electrical utility (refer to figure 5). Approximately 20 yards of the mineral spirits contaminated soils were removed and subsequently disposed of at Hillsboro Landfill in Oregon. The disposal was delayed for several days until this unexpected contamination could be adequately characterized and assesses by the disposal facility;

o Upon completion of this excavation, confirmation samples were collected from the east (PCA-SS8-6') and west (PCA-SS10-4.5) side walls. The sample locations are shown on figure 5. The samples were analyzed for TPH as mineral spirits by Modified EPA Method 8015. Table 5 presents the sample identification numbers, location, and the analytical results;

Table 5

Mineral Spirits Excavation Soil Sample Analytical Results by WTPH-HCID and TPH as Mineral Spirits by Modified EPA Method 8015
In parts per million (ppm)

Sample Number	Location	WTPH-HCID	8015
PCA-SS7-4'	Beneath 4" pipe at 4 foot depth	*D	
PCA-SS8-6'	West side wall of excavation at 6 foot depth in clayey soils		1,400
PCA-SS10-4.5'	East side wall of excavation at 4.5' depth in clayey soils		ND
#4AvisSoil	East side wall of excavation at approximately 4 foot depth		*87

*D = analytical method detected mineral spirits contamination
ND = none detected at or above the method reporting limit
A blank indicates no analysis was made.


Copies of the analytical results with QA/QC data and chain of custody records is attached to this report;

o Subsequent actions were taken by Bakker's Fine Dry Cleaners to re-route the water being discharged into the floor drains in the Bakker's cleaning processing and steam boiler facility. On 9 October, 1991 Petroleum Services was notified by Bakker's that the floor drains had been permanently plugged;

o On 14 October, 1991 the 4" pipe exposed on the Avis Sales Lot was plugged with concrete by Petroleum Services.

Groundwater Characterization

In addition to the soils removal, one groundwater monitoring well (MW6) was installed on September 25, 1991 in an inferred down gradient direction from the other monitoring wells existing at the property. The inferred down gradient direction was based on Geotech Consultant's groundwater investigation and subsequent survey and water level measurements study. The approximate locations of the monitoring wells installed by Geotech Consultants and MW6 are presented in figure 6. The monitoring



AVIS SALES LOT

11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 6

GROUNDWATER WELL LOCATIONS

PETROLEUM SERVICES UNLIMITED

well was installed to further characterize and assess the extent of petroleum contaminated groundwater known to exist at the site.

Mc-Garrett Drilling of Seattle, Washington was subcontracted to perform the monitoring well installation. Drilling was conducted using a BRATT 22R Mobile Drill Rig utilizing 6 inch diameter hollow stem augers. All down hole drilling equipment and monitoring well construction materials were steam-cleaned prior to drilling, sampling and installation.

A field notebook was maintained for the drilling, sampling and monitoring well construction activities. The monitoring well installation diagram with soil descriptions has been reproduced and is attached to this letter report. Drill cuttings were placed directly into the existing soils stockpile on the site and later disposed of at the Hillsboro Landfill.

Sampling Methods Soil Samples were collected from the monitoring well boring using a standard 18" long x 2" diameter stainless steel split spoon advanced using standard penetration test procedures in accordance with ASTM Method 1586. The sample was split with a clean, decontaminated, stainless steel knife. A portion of the sample was then placed into a laboratory cleaned, 8-ounce glass jar with a Teflon-lined cap. Field screening techniques were used to screen the soils for the potential presence of petroleum in the soil samples. The photo-ionization detector did not indicate the presence of volatile organic compounds in any of the samples collected. A description of the soil sample in accordance with ASTM D2487-85 was entered into the field notebook. The soil descriptions and sample collection depths are provided on the monitoring well installation log that is attached to this report.

The samples were hand delivered to Analytical Services, Inc. in Redmond, Washington under chain-of-custody procedures. Based on field screening techniques and depth to groundwater, only one sample (PCA-MW-3-3.5') was analyzed.

The sample was analyzed for diesel #2 by Modified EPA Method 8015. The remaining two soil samples were archived in the event the analytical results identified concentrations above MTCA Method A clean-up levels. However, the analytical results showed no detection.

Soil Sample Analytical Results Table 6 presents the sample identification number, location, and the analytical results.

Table 6

Monitoring Well Soil Sample Analytical Results for
Diesel #2 by Modified EPA Method 8015
In parts per million (ppm)

Sample Number	Location	8015
PCA-MW-3.5-5'	Collected at 3.5 to 5 foot depth in boring MW6	ND


ND = none detected at or above the method reporting limit

A copy of the analytical results with QA/QC data and chain of custody records is attached to this report.

Monitoring Well Installation The monitoring well was installed in accordance with WAC 173-360. During drilling of the monitoring well boring, moist soils were encountered at the 5 foot depth and saturated soils were encountered at the 8.5 foot depth. Groundwater elevation at the site is between 5 and 6 feet below grade level as was indicated in the existing monitoring wells. Therefore, the monitoring well was drilled to 15 feet to allow for adequate coverage of the saturated zone.

The monitoring well was constructed as follows:

Four feet of blank two-inch diameter, Schedule 40, threaded polyvinyl chloride (PVC) casing was used. Ten feet of two-inch, Schedule 40, threaded PVC pipe with 0.020-inch slots was used as screen to straddle the groundwater table. The screen extended from four feet to fourteen feet. A six inch bottom sump of two-inch, Schedule 40, threaded PVC was used. Three each 100-pound bags of Colorado silica sand were used as sand pack around the screen. The sand pack extended from the bottom of the monitoring well installation boring to three feet from the surface. A seal was placed over the sand pack with 2.5 each 50 pound bags of Wyo-Ben EnviroPlug bentonite chips. The seal extended from three feet to 16 inches below grade. A concrete seal was then used to the surface. A flush monument cover was used to secure the well. Refer to figure 7 for the groundwater monitoring well installation diagram.



AVIS SALES LOT
11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON 98004

FIGURE 7
TYPICAL MONITORING WELL

PETROLEUM SERVICES UNLIMITED

Well Development The monitoring well was developed on 14 October, 1991. The delay between monitoring well installation and well development was to ensure proper setting of the seals and materials used to construct the well.

The well was developed by purging three casing volumes of water using a decontaminated, stainless steel bailer. After each purge, field parameters (pH, conductivity and temperature) were measured. The development process was completed after three casing volumes had been purged and the field parameters measurements were within ten percent of the previous casing volume's measurements. It should be noted that MW6 was slow to recharge after each casing volume purge. Table 7 presents the field parameters measurements for MW6.

Table 7

MW6 Monitoring Well Field Parameters Measurements

Time	Gallons Purged	Temperature	pH	Specific Conductivity
1810	2	66.2	8.41	1.02 x 1
1818	5	65.6	7.95	1.02 x 1
1848	7	61.8	8.02	1.03 x 1

In addition to developing and sampling MW6, two monitoring wells installed by Geotech Consultants (MW1 and MW3) in the area to the north of the Avis building were purged and sampled (refer figure 6). The stainless steel bailer was decontaminated between each well.

It should be noted that MW3 was slow to recharge and was purged to dryness after one casing volume of water was extracted. MW3 was then sampled after sufficient water had recharged the monitoring well. Table 8 presents the field parameters measurements for monitoring well MW1 and MW3.

Table 8

MW1 and MW3 Monitoring Well Field Parameters Measurements

MW	Time	Gallons Purged	Temperature	pH	Specific Conductivity
MW1	1537	2.5	88	8.06	0.98 x 1
	1614	5.0	86.4	8.40	1.00 x 1
	1627	7.5	82.6	8.47	1.00 x 1
MW3	1720	1	71.2	8.82	1.02 x 1

Sampling After each well had recovered from the final purge, the groundwater was sampled. The groundwater samples were collected with the decontaminated stainless steel bailer used to purge each monitoring well. Groundwater was transferred from the bailer into four 40-ml VOA vials and into a 1-Liter amber glass sample container. The VOA vials were collected for BTEX analysis by EPA Method 8020 and for chlorinated solvents by EPA Method 8010. The amber glass jar was collected for total petroleum hydrocarbons (TPH) analysis by EPA Method 8015.

Analytical Results The water samples were hand delivered under chain-of-custody procedures at the end of the sampling event to Analytical Services, Inc. in Redmond, Washington for chemical analyses. Table 9 presents the results of the BTEX and TPH scan. The results of the chlorinated solvents analyses are presented in table 10 in the Summary and Recommendations section of this report. In addition, table 9 presents the analytical results of the May, 1991 water sampling event conducted by Geotech Consultants for monitoring wells MW1 and MW3, and shows the MTCA Method A Cleanup Levels.

Groundwater from MW1 exhibited higher temperatures than groundwater from MW3 and MW6. Reasons for the higher temperature are unknown. Explanations for the a anomaly can possibly be attributed to the proximity of MW1 to the 4" and 16" concrete pipe discharge locations. The water that discharged from the 4" pipe from Bakker's dry cleaning processing room and steam boiler room was noted as being warm when handled. This factor, and MW1's proximity to the 16" concrete pipe my have resulted in increased groundwater temperatures in this area of the site.

Table 9

MW1, MW3, and MW6 Groundwater Monitoring Well Analytical Results for BTEX and TPH as Gas By EPA Method 8020 and TPH by EPA Method 8015 In parts per billion (ppb)

	MW1		MW3		MW6	MTCA Method A
Analyte	5-91	10-91	5-91	10-91	10-91	Cleanup Levels
Benzene	4	<1	36	<1	22	5
Toluene	147	5	85	1	<1	40
Ethylbenzene	19	5	140	<1	<1	20
Xylene: m+p	247	8	360	1	<1	20
ortho-		7		<1	<1	
TPH-Gas*	3	<1	27	3	<1	1
HCID*		ND		5**	ND	1

* = in parts per million
ND = none detected at or above the method reporting limit
A blank indicates no analysis was made.
** = analytical method identified Mineral Spirits

Copies of the analytical results with QA/QC data and chain of custody records is attached to this report.

Summary and Recommendations

Based on the information and data presented herein, Petroleum Services summarizes the following regarding the area to the north of the Avis building at the Avis Sales Lot located at 11969 Bellevue-Redmond Road in Bellevue, Washington:

Based on previous subsurface investigations at the Avis Sales Lot, diesel contamination has been identified in site soils to the north of the existing building. The source of the contamination is at present unknown, but based on the observed subsurface conditions, an area of pea gravel fill bounded by a verticle cut in the native soils appears to be a former UST excavation. As indicated by field observation and confirmation sampling, the extent of diesel contamination above the groundwater table was isolated to within a few feet of the native soils in the verticle cut.

The extent of the diesel contamination has been removed with the exception of a pocket of soils at the northern portion of the cleanup action excavation. This pocket is below MTCA Method A Cleanup Levels (WAC 173-340-740). Further sampling was conducted approximately 6 feet north of this area during drilling and monitoring well MW6 installation. A soil sample collected from the 3.5 to 5 foot depth in the boring did not detect petroleum hydrocarbons. This would indicate that diesel contaminated soils do not penetrate into native soils beyond the perimeter of the cleanup action excavation.

Diesel contaminated soils adjacent to the north wall of the Avis building remain at the site. This contamination was identified during Petroleum Services extent of contamination investigation in July 1991. During this exploratory work, a sample (PCA-TP1-2) was collected using a decontaminated stainless steel hand auger in the side wall of a test pit at the 4 foot depth. Analytical results for the sample by EPA Method 8015 indicated diesel contamination at 2200 parts per million. This area of contamination was not excavated because of the potential for structural damage to the Avis building. Due to the observed low permeability characteristics of the clayey native material in the subsurface at the site, the extent of this diesel contamination is not anticipated to extend a great distance beneath the building.

Groundwater on the north portion of the Avis Sales Lot has been confirmed to contain gasoline and the BTEX group of compounds. This was confirmed by chemical analyses during Geotech Consultant's May, 1991 site investigation. Based on analytical results of groundwater samples collected during this work, contaminant levels in groundwater from monitoring wells MW1 and MW3 have decreased in the 5 months since the May, 1991 sampling event. The decreases indicated are to below MTCA cleanup levels for all constituents except gasoline in MW3 at 3 ppm. This concentration has decreased by about an order of magnitude since the May, 1991 results.

An analysis for TPH by Modified EPA Method 8015, indicated mineral spirits contamination at 5 ppm in MW3. Mineral spirits contamination was not identified in MW1 or MW6.

Groundwater flow and gradient were not part of the scope of work for this project. Monitoring well MW6 was placed in an inferred down gradient direction based on Geotech Consultant's previous study of the Avis Sales Lot. MW6 was constructed in accordance with WAC 173-360, and developed and sampled in accordance with generally accepted professional practices. Analytical results from the BTEX and TPH analyses conducted on the groundwater sample from MW6 identified only benzene at 22 ppb. This is above MTCA cleanup levels.

The discharge of water from the 16" abandoned sewer pipe through the 4" concrete pipe from Bakker's property may have contributed to an artificially high groundwater gradient in the area to the north of the Avis building at the site. Water was observed to discharge at a rate of greater than 200 gallons on 24 September, 1991 into the excavation. The source areas for this discharge (floor drains in Bakker's laundry processing rooms and steam boiler room) have subsequently been plugged. Continued groundwater level monitoring would be necessary to support this theory.

Based on this information, Petroleum Services recommends that further groundwater gradient study be conducted to determine groundwater flow direction at the site. Petroleum Services further recommends that a program of continued monitoring of groundwater at the site be conducted to track the effect of soils removal on groundwater contamination.

A City of Bellevue 16" diameter abandoned concrete sewer pipe was discovered during the Cleanup Action. A steady flow of water was discharging from the pipe and subsequent actions to excavate and identify the source of the water were conducted. The City of Bellevue was notified and became involved with decisions made regarding the abandoned pipe. The pipe was not on any researched sewer maps and the timing of its abandonment has not been determined.

Excavation of the 16" concrete pipe led to the discovery of a 4" concrete pipe that was plumbed into the 16" pipe and responsible for discharging water onto the Avis Sales Lot. The 4" pipe was observed to exit Bakker's Fine Dry Cleaning property located to the east of the Avis Sales Lot. Upon discovery of the 4" pipe and water discharge, samples of the water were collected by Petroleum Services and a representative for Bakker's. Analytical results of the water samples indicated the presence of chlorinated organic compounds, specifically, trichloroethylene at 11 ppb and tetrachloroethylene at 1600 ppb. The source of water was determined to be laundry processing rooms and a steam boiler room at the Bakker's facility. The duration of discharge of chlorinated organic compounds from Bakker's Fine Dry Cleaning facility is unknown. Also unknown is whether other constituents may have been discharged at prior times.

Based on this development during the work, groundwater from the monitoring wells to the north of the Avis building were also sampled for chlorinated organic compounds by EPA Method 601/8010. Table 10 presents the results of the groundwater analysis.

Table 10

Groundwater Sample Analytical Results
by EPA Method 601/8010
in parts per billion (ppb)

Analyte*	MW1	MW3	MW6	MTCA Method A Clean Up Levels for Groundwater
1,1-Dichloroethane	34	ND	3	
Trichloroethylene	9	ND	ND	5
Tetrachloroethylene	7	ND	ND	5

* = chlorinated organic compounds identified in analysis
ND = none detected at or above the method reporting limit

A copy of the laboratory analytical results with chain of custody records is attached to this report.

MW1 is located in close proximity to the area where the 4" pipe was discharging water. MW1 is located in close proximity to where the 16" concrete pipe that was fed by the 4" pipe was discharging into the Avis property from Bakker's Find Dry Cleaning's laundry processing room and steam boiler room. Water from this source has been confirmed by chemical analyses from two independent laboratories to contain detectable levels of chlorinated organic compounds. This information supports a conclusion that Bakker's Fine Dry Cleaning is responsible for chlorinated organic compounds contamination in groundwater at the Avis Sales Lot.

Mineral spirits contaminated soils were identified in the north east corner of the site adjacent to the Bakker's Fine Dry Cleaners' property. The Avis property does not appear to be a source for this contamination. Field observations indicate that it spread onto the Avis site from the Bakker's property.

The full extent of the mineral spirits contaminated soils in the north east corner of the Avis site was not removed for these reasons:

o further excavation in a northerly direction was unsafe because the contamination extended beneath the Washington Natural Gas pipeline and the Puget Sound Power and Light Company underground electric cables in the north east corner of the lot and;

o the contamination appeared to cross Bakker's Fine Dry Cleaning property boundary to the east.

Closing Statement

This work was performed, and this report prepared, in accordance with generally accepted professional practices for the nature and conditions of the work performed. It is intended for the use of Avis Rent-A-Car for specific application to the Avis Sales Lot in Bellevue, Washington. No other warranty, express or implied, should be understood.

The observations, interpretations, and recommendations presented in this report are based on the data obtained from the samples, and other data contained herein and on the assumption that subsurface conditions do not vary from those found during the course of the investigation and cleanup work. If any variations for this project are encountered during any further investigation or excavations for this project, Petroleum Services should be notified so that supplemental interpretations can be made. The observations and interpretations of this report are intended only for the area investigated and are inferred to adjacent areas.

This report prepared by:

Charles R. Grant
Washington Department of Ecology Underground Storage Tank Program
Registered Site Assessor
Pacific Northern Environmental dba Petroleum Services Unlimited, Inc.

Attachments

crg/

A:\pcarpt3.wp

October 3, 1991

Pacific Northern Environmental
1081 Columbia
Longview, WA 98632

Dear Chas:

Enclosed are the results of the analyses of samples submitted on September 27, 1991 from Project PC\Avis.

We appreciate this opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to call me.

Sincerely,

Stephen J.
Senior Che

SJL:tmh

Enclosures

Post-it™ brand fax transmittal memo 7671 | # of pages ▸ 2

To Chas Grant	From S. I.
Co. Pacific Northern Env.	Co. Spokane
Dept.	Phone # 820-4551
Fax # 423-2272	Fax # 820-6337

Date of Report: October 3, 1991
Samples Submitted: September 27, 1991
Lab Traveler: 09-084
Project: PC\Avis

RESULTS OF ANALYSES OF SAMPLES FOR TPH AS MINERAL SPIRITS BY MODIFIED EPA METHOD 8015

Sample #	Matrix	Dilution Factor	Mineral Spirits (ppm)	Surrogate Recovery (%)
PCA-SS8-6'	soil	2	1400	112%
PCA-SS10-4.5'	soil	2	<20	108%
Quality Assurance				
Method Blank		2	<20	114%

Date of Report: October 3, 1991
Samples Submitted: September 27, 1991
Lab Traveler: 09-084
Project: PC\Avis

ANALYSIS OF ENVIRONMENTAL SAMPLES
FOR CHLORINATED ORGANIC COMPOUNDS
BY EPA METHOD 601/8010
Results Reported as ng/g (ppb)

Sample #:	PCA-SS-6'	MW1	MW3 - MW6	
Matrix	soil			
Dilution Factor	50			
Analyte:				
1,1-Dichloroethylene	<50	<1	ND ↓	ND ↓
Methylene Chloride	<50	<1		
t-Dichloroethylene	<50	<1		
1,1-Dichloroethane	<50	34 ppb		3 ppb
Chloroform	<50	<1		ND ↓
1,1,1-Trichloroethane	<50	<1		
Carbon Tetrachloride	<50	<1		
1,2-Dichloroethane	<50	<1		
Trichloroethylene	<50	9		
Tetrachloroethylene	<50	7		
Tetrachloroethane	<50	<1		

PRELIMINARY DATA

Date of Report: October 3, 1991
Samples Submitted: September 27, 1991
Lab Traveler: 09-084
Project: PC\Avis

RESULTS OF ANALYSES OF ENVIRONMENTAL SAMPLES FOR FLASH POINT

Sample #	Matrix	Flash Degrees C
PCA-SS8-6'	soil	>200

Columbia Analytical Services, Inc.
1317 South 13th Ave. • Kelso, WA 98626 • (206) 577-7222, FAX (206) 636-1068

9-084

CHAIN OF CUSTODY/LABORATORY ANALYSIS REQUEST FORM

DATE 9.26.91 PAGE 1 OF 1

PROJECT NAME PC/AVIS #
PROJECT MNGR CHAS. GRANT
COMPANY/ADDRESS PACIFIC NORTHERN ENVIRONMENTAL
1081 COLUMBIA BLVD
LONGVIEW, WA 98632 PHONE 4232245
SAMPLERS SIGNATURE Charles R. Grant

SAMPLE I.D.	1991 DATE	TIME	LAB I.D.	SAMPLE MATRIX	NUMBER OF CONTAINERS	Base/Neu/Acid Organics GC/MS 625/8270	Volatile Organics GC/MS 624/8240	Halogenated or Aromatic Volatiles 601/8010 ☐	Pesticides/PCBs 608/8080 ☐	Total Petroleum Hydrocarbons EPA 418.1 ☐	TPH/Gas/BTEX Oregon 418.1 ☐ Gas ☐ BTEX ☐	TPH/8015 Modified 5030/8015/8020 Diesel ☐	TPH - HCID Hydrocarbon Scan ☒	TCLP Metals ☐	Semi Pest/ VOA ☐ VOA ☐ Herb ☐ Metals (total or dissolved) List Below	Cyanide	pH, Cond, Cl, SO_4, PO_4, F, Br NO_2 NO_3 (circle)	NH_3-N, COD, Total-P, TKN, TOC (circle)	Total Organic Halides (TOX) 9020	ARCHIVE		REMARKS
PCA-SS8-6'	9.26	1730		SOIL								X										8oz GLASS
PCA-SS9-7'	9.26	1732		↓																X		↓
PCA-SS10-4,5	9.27	0900		↓								X										

RELINQUISHED BY:	RECEIVED BY:
Signature: Charles R. Grant	Signature: Rick Brown
Printed Name: PNE	Printed Name: ASI
Firm: 1000 - 9.27.91	Firm: 9/27/91 10:00
Date/Time	Date/Time
RELINQUISHED BY:	RECEIVED BY:
Signature	Signature
Printed Name	Printed Name
Firm	Firm
Date/Time	Date/Time

TURNAROUND REQUIREMENTS:
___ 24 hr X 48 hr ___ 5 day
___ Standard (~ 10-15 working days)
___ Provide Verbal Preliminary Results
___ Provide FAX Preliminary Results
Requested Report Date ___

REPORT REQUIREMENTS
___ I. Routine Report
___ II. Report (includes DUP, MS, MSD, as required, may be charged as samples)
___ III. Data Validation Report (includes All Raw Data)
___ IV. CLP Deliverable Report

INVOICE INFORMATION:
P.O. # ___
Bill to: ___

SAMPLE RECEIPT:
Shipping VIA: ___
Shipping #: ___
Condition: ___
Lab No.: ___

SPECIAL INSTRUCTIONS/COMMENTS:
NEED ANALYSES BY MONDAY MORNING RUSH
AMMONIA BOD FOR SAMPLE SS8-6 ON 10.2.91 - ALONG W/ FLASH POINT

October 2, 1991

Chas Grant, Project Manager
Pacific Northern Environmental
1081 Columbia Blvd.
Longview, WA 98632

Dear Chas:

Enclosed are the results of the analyses of samples submitted on September 26, 1991 from Project PC/402S.

We appreciate this opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to call me.

Sincerely,

Stephen J. Loague
Senior Chemist

SJL:tmh

Enclosures

Post-it™ brand fax transmittal memo 7671 | # of pages ▸ 6

To: Chas Grant	From: A.S.I.
Co.: Pacific Northern Env.	Co.: Steve Loague
Dept.:	Phone #: 820-4551
Fax #: 1-423-2272	Fax #: 820-6337

Date of Report: October 2, 1991
Samples Submitted: September 26, 1991
Lab Traveler: 09-081
Project: PC/402S

RESULTS OF ANALYSES OF SAMPLES FOR DIESEL #2 BY MODIFIED EPA METHOD 8015

Sample #	Matrix	Dilution Factor	Diesel #2 (ppm)	Surrogate Recovery (%)
PCA-MW-3.5.5'	soil	2	<40	105%
SS5-5.5'	soil	2	<40	87%
SS6-5'	soil	2	<40	105%
PCA 4" H_2O	water	0.04	<0.8	
Quality Assurance				
Method Blank	soil		<40	107%
09-075-10	soil	2	<40	115%
09-075-10 (Duplicate)	soil	2	<40	117%
(Matrix Spike) Spiked @ 200 ppm Recovery			71%	109%
(M.S. Duplicate) Spiked @ 200 ppm Recovery			79%	116%
Method Blank	water	0.4	<0.8	
PCA-4"H_2O	water	0.4	<0.8	

Date of Report: October 2, 1991
Samples Submitted: September 26, 1991
Lab Traveler: 09-081
Project: PC/402S

HYDROCARBON INDENTIFICATION BY METHOD WTPH-HCID

Sample #	GC Characterization	Surr. Recovery
PCA-SS7-4'[A]	Soil	
	The chromatogram indicates the presence of hydrocarbons in the Gasoline range (C6-C11).	110%
	The chromatogram indicates the presence of hydrocarbons in the Gasoline range (C6-C11).	
Method Blank	<20 ppm Gasoline <40 ppm Diesel Fuel	110%

A-Chromatogram indicates the presence of Mineral Spirits in the sample

Date of Report: October 2, 1991
Samples Submitted: September 26, 1991
Lab Traveler: 09-081
Project: PC/402S

ANALYSIS FOR BTEX AND TPH-GAS
EPA MOD. 8015 (PURGE & TRAP)

Sample #:	PCA-4" H_2O
Matrix	water
Dilution Factor	1
Units	ppb
Analyte:	
Benzene	<1
Toluene	<1
Ethylbenzene	<1
m- & p-Xylene	<1
o-Xylene	<1
Units	ppm
TPH/Gas	<1
Surr. Recovery	96%

Date of Report: October 2, 1991
Samples Submitted: September 26, 1991
Lab Traveler: 09-081
Project: PC/402S

ANALYSIS FOR BTEX AND TPH-GAS
EPA MOD. 8015 (PURGE & TRAP)

QUALITY CONTROL

Sample #:	Method Blank	09-087-7 Original	09-087-7 Duplicate	09-087-7 Matrix Spike @ 20 ppb	09-087-7 M Spike Duplicat
Matrix		water	water	water	water
Dil.Fact.	1	1	1		
Units	ppb	ppb	ppb	%Rec.	%Rec.
Analyte:					
Benzene	<1	<1	<1	93%	96%
Toluene	<1	<1	<1	90%	94%
Ethylbenzene	<1	<1	<1	91%	98%
m- & p-Xylene	<1	<1	<1	91%	99%
o-Xylene	<1	<1	<1	91%	96%
Units	ppm	ppm	ppm	%Rec.	%Rec.
TPH/Gas	<1	<1	<1	NA	NA
Surr. Recovery	99%	96%	90%	99%	94%

NA-Not Analyzed.

ANALYSIS OF ENVIRONMENTAL SAMPLES
FOR CHLORINATED ORGANIC COMPOUNDS
BY EPA METHOD 601/8010
Results Reported as ng/g (ppb)

PRELIMINARY DATA

Sample #:	PCA 4" H2O
Matrix	water
Dilution Factor	10
Analyte:	
1,1-Dichloroethylene	<10
Methylene Chloride	<10
t-Dichloroethylene	<10
1,1-Dichloroethane	<10
Chloroform	<10
1,1,1-Trichloroethane	<10
Carbon Tetrachloride	<10
1,2-Dichloroethane	<10
Trichloroethylene	11
Tetrachloroethylene	1600
Tetrachloroethane	<10

PRELIMINARY DATA

PRELIMINARY DATA

Final 08.4.21

PRELIMINARY DATA

PRELIMINARY DATA

Columbia Analytical Services, Inc.
1317 South 13th Ave. • Kelso, WA 98626 • (206) 577-7222, FAX (206) 636-1068

CHAIN OF CUSTODY/LABORATORY ANALYSIS REQUEST FORM

DATE 9.25-91 PAGE 1 OF 1

PROJECT NAME PC/AGLS #
PROJECT MNGR CHAS. GRANT
COMPANY/ADDRESS PACIFIC NORTHWEST ENVIRONMENTAL
1681 COLUMBIA BLVD
LONGVIEW, WA 98632 PHONE 423 2245
SAMPLERS SIGNATURE

SAMPLE I.D.	1991 DATE	TIME	LAB I.D.	SAMPLE MATRIX	NUMBER OF CONTAINERS	Base/Neu/Acid Organics GC/MS 625/8270	Volatile Organics GC/MS 624/8240	Halogenated or Aromatic Volatiles 601/8010 ☐	Pesticides/PCBs 608/8080	Total Petroleum Hydrocarbons EPA 418.1 ☐	Oregon 418.1 ☐	TPH/Gas/BTEX 5030/8015/8020 Gas ☐ BTEX ☐	TPH/8015 Modified Diesel ☐	Hydrocarbon Scan ☐	TPH - HCID	TCLP Metals ☐	Semi Pest/ VOA ☐ VOA ☐ Herb ☐ Metals (total or dissolved) List Below	Cyanide	pH, Cond, Cl, SO_4, PO_4, F, Br NO_2, NO_3 (circle)	NH_3-N, COD, Total-P, TKN, TOC (circle)	Total Organic Halides (TOX) 8020	Archive	REMARKS
PCA-MW-3.5-5'	9.25	0820		SOIL	1							X											8 oz GLASS
PCA-MW-8.5-10	|	0835		|	1															X		
PCA-MW-13.5-15	|	0845		|	1															X		
PCA-SS5-5.5'	|	1430		|	1							X											
PCA-SS6-5'	|	1435		|	1							X											
PCA-SS7-4'	|	1745		↓	1									X									↓
PCA-4" H20	↓	1705		WATER	3						X	X											2 x 1 (oml VOA HCl to Amber

RELINQUISHED BY:	RECEIVED BY:
Signature PNE	Signature STEPHEN LOAGLE
Printed Name CHARLES R. GRANT	Printed Name AST
Firm 9/26/91 1230	Firm 9-26-91 1245
Date/Time	Date/Time

RELINQUISHED BY:	RECEIVED BY:
Signature	Signature
Printed Name	Printed Name
Firm	Firm
Date/Time	Date/Time

TURNAROUND REQUIREMENTS:
X 24 hr ___ 48 hr ___ 5 day
___ Standard (~ 10-15 working days)
___ Provide Verbal Preliminary Results
___ Provide FAX Preliminary Results
Requested Report Date

REPORT REQUIREMENTS
___ I. Routine Report
___ II. Report (includes DUP,MS, MSD, as required, may be charged as samples)
___ III. Data Validation Report (includes All Raw Data)
___ IV. CLP Deliverable Report

INVOICE INFORMATION:
P.O. #
Bill to:

SAMPLE RECEIPT:
Shipping VIA:
Shipping #:
Condition:
Lab No.:

SPECIAL INSTRUCTIONS/COMMENTS:
NEED SAMPLE SS7 ASAP - IF DETECTION - WHAT LEVELS?
AUTHORIZED AS 8010 ON SAMPLE PCA-4"H20 ON 10.2.91

Analytical Services, Inc.
12277 134th Court NE Redmond, Washington 98052
(206) 820-4551 (fax) 820-6337

October 1, 1991

Chas Grant, Project Manager
Pacific Northern Environmental
1081 Columbia Blvd.
Longview, WA 98632

Dear Chas:

Enclosed are the results of the analyses of samples submitted on September 24, 1991 from Project PC/Avis.

We appreciate this opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to call me.

Sincerely,

Stephen J. Loague
Senior Chemist

SJL:tmh

Enclosures

Date of Report: October 1, 1991
Samples Submitted: September 24, 1991
Lab Traveler: 09-073
Project: PC/Avis

RESULTS OF ANALYSES OF SAMPLES FOR DIESEL #2 BY MODIFIED EPA METHOD 8015

Sample #	Matrix	Dilution Factor	Diesel #2 (ppm)	Surrogate Recovery (%)
PCA-553-5.5	soil	2	63	120%
PCA-554-5.5	soil	2	<40	100%
PCA-EXZ-PEA	soil	2	<40	100%
PCA-SEWER[A]	water	0.04	<0.8	---
Quality Assurance				
Method Blank	soil	2	<40	99%
PCA-553-5.5 (Duplicate)	soil	2	87	100%
Method Blank	water	0.04	<0.8	---
PCA-SEWER[A] (Duplicate)	water	0.04	<0.8	---

A-Chromatogram indicates the presence of Gasoline and Oil.

Matrix Spikes not determined due to matrix effects.

Date of Report: October 1, 1991
Samples Submitted: September 24, 1991
Lab Traveler: 09-073
Project: PC/Avis

ANALYSIS FOR BTEX AND TPH-GAS
EPA MOD. 8015 (PURGE & TRAP)

Sample #:	PCA-SEWER
Matrix	water
Dilution Factor	1
Units	ppb
Analyte:	
Benzene	<1
Toluene	<1
Ethylbenzene	<1
m- & p-Xylene	3
o-Xylene	<1
Units	ppm
TPH/Gas	<1
Surr. Recovery	124%

Date of Report: October 1, 1991
Samples Submitted: September 24, 1991
Lab Traveler: 09-073
Project: PC/Avis

ANALYSIS FOR BTEX AND TPH-GAS
EPA MOD. 8015 (PURGE & TRAP)

QUALITY CONTROL

Batch Sample #:	Method Blank	09-069-8 Original	09-069-8 Duplicate	09-069-8 Matrix Spike @ 20 ppb	09-069- M Spik Duplica
Matrix		water	water	water	water
Dil.Fact.	1	1	1		
Units	ppb	ppb	ppb	%Rec.	%Rec.
Analyte:					
Benzene	<1	<1	<1	100%	97%
Toluene	<1	<1	<1	98%	94%
Ethylbenzene	<1	<1	<1	100%	96%
m- & p-Xylene	<1	<1	<1	98%	95%
o-Xylene	<1	<1	<1	100%	96%
Units	ppm	ppm	ppm	%Rec.	%Rec.
TPH/Gas	<1	<1	<1	NA	NA
Surr. Recovery	100%	96%	98%	99%	99%

NA-Not Analyzed.

Date of Report: October 1, 1991
Samples Submitted: September 24, 1991
Lab Traveler: 09-073
Project: PC/Avis

RESULTS OF DRY WEIGHT

Sample #	Matrix	Moisture
PCA-553-5.5	soil	23%
PCA-554-5.5	soil	15%
PCA-EXZ-PEA	soil	2%

Columbia Analytical Services, Inc.
1317 South 13th Ave. • Kelso, WA 98626 • (206) 577-7222, FAX (206) 636-1068

CHAIN OF CUSTODY/LABORATORY ANALYSIS REQUEST FORM

DATE 9.24.91 PAGE 1 OF 1

PROJECT NAME PCI AUS # _____
PROJECT MNGR CHAS. GRANT
COMPANY/ADDRESS PACIFIC NORTHWEST ENVIRONMENTAL
1081 COLUMBIA BLVD
LONGVIEW, WA 98632 PHONE 423 2245
SAMPLERS SIGNATURE [signature]

SAMPLE I.D.	1991 DATE	TIME	LAB I.D.	SAMPLE MATRIX	NUMBER OF CONTAINERS	Base/Neu/Acid Organics GC/MS 625/8270	Volatile Organics GC/MS 624/8240	Halogenated or Aromatic Volatiles 601/8010 ☐ 602/8020 ☐	Pesticides/PCBs 608/8080	Total Petroleum Hydrocarbons EPA 418.1 ☐ Oregon 418.1 ☐	TPH/Gas/BTEX 5030/8015/8020 Gas ☐ BTEX ☐	TPH/8015 Modified Diesel ☐ Hydrocarbon Scan ☐	TPH - HCID	TCLP Metals ☐	Semi PesU VOA ☐ VOA ☐ Herb ☐ Metals (total or dissolved) List Below	Cyanide	pH, Cond, Cl, SO4, PO4, F, Br NO2, NO3 (circle)	NH3-N, COD, Total-P, TKN, TOC	Total Organic Halides (TOX) 9020	PCB TPH HCID	REMARKS
PCA-SS3-5.5'	9.24	1620		SOIL	1							X								X PCB	8076 GASS
PCA-SS4-5.5		1625		↓	1							X								X PCB	↓
PCA-EX2-P&A		1650		↓	1							X								X PCB	↓
PCA-SEWER		1100		WATER	3						X	X									2x40ml VOA + 1x1LAMBER

RELINQUISHED BY:
Signature [signature]
Printed Name CHARLES R. GRANT
Firm PAC. NW. ENVIRO
Date/Time 9.24.91 1745

RECEIVED BY:
Signature JIM HALLORAN
Printed Name AST
Firm 9/24/91 1752
Date/Time

RELINQUISHED BY:
Signature
Printed Name
Firm
Date/Time

RECEIVED BY:
Signature
Printed Name
Firm
Date/Time

TURNAROUND REQUIREMENTS:
X 24 hr ___ 48 hr ___ 5 day
___ Standard (~ 10-15 working days)
___ Provide Verbal Preliminary Results
___ Provide FAX Preliminary Results
Requested Report Date _____

REPORT REQUIREMENTS
___ I. Routine Report
___ II. Report (includes DUP, MS, MSD, as required, may be charged as samples)
___ III. Data Validation Report (includes All Raw Data)
___ IV. CLP Deliverable Report

INVOICE INFORMATION:
P.O. # _____
Bill to: _____

SAMPLE RECEIPT:
Shipping VIA: _____
Shipping #: _____
Condition: _____
Lab No.: _____

SPECIAL INSTRUCTIONS/COMMENTS:

Analytical Services, Inc.
12277 134th Court NE Redmond, Washington 98052
(206) 820-4551 (fax) 820-6337

October 1, 1991

Chas Grant, Project Manager
Pacific Northern Environmental
1081 Columbia Blvd.
Longview, WA 98632

Dear Chas:

Enclosed are the results of the analyses of samples submitted on September 23, 1991 from Project PC-Avis.

We appreciate this opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to call me.

Sincerely,

Stephen J. Loague
Senior Chemist

SJL:tmh

Enclosures

Date of Report: October 1, 1991
Samples Submitted: September 23, 1991
Lab Traveler: 09-070
Project: PC-Avis

HYDROCARBON INDENTIFICATION BY METHOD WTPH-HCID

Sample #	GC Characterization	Surr. Recovery
PCA-SS1-6.5	Soil	
	The chromatogram indicates the presence of hydrocarbons in the Diesel Fuel range (C11-C24)	A
PCA-SS2-5.5	Soil	
	<20 ppm Gasoline <40 ppm Diesel Fuel	95%
PCA-EX1	Soil	
	The chromatogram indicates the presence of hydrocarbons in the Lubricant range (>C24).	100%

Quality Assurance

Method Blank	<20 ppm Gasoline <40 ppm Diesel Fuel	95%

A-Surrogate Recovery data not available due to the high concentration in the sample.

Date of Report: October 1, 1991
Samples Submitted: September 23, 1991
Lab Traveler: 09-070
Project: PC-Avis

RESULTS OF ANALYSES OF SAMPLES FOR DIESEL #2 BY MODIFIED EPA METHOD 8015

Sample #	Matrix	Dilution Factor	Diesel #2 (ppm)	Surrogate Recovery (%)
PCA-EX1	soil	20	2,100	A
Quality Assurance				
Method Blank		2	<20	99%
09-073-1	soil	2	58	100%
09-073-1 (Duplicate)	soil	2	80	100%

A-Surrogate recovery data not available due to the necessary dilu c of the sample.

Matrix Spikes not available due to matrix effects.

Date of Report: October 1, 1991
Samples Submitted: September 23, 1991
Lab Traveler: 09-070
Project: PC-Avis

RESULTS OF ANALYSES OF ENVIRONMENTAL SAMPLES FOR TOTAL PETROLEUM HYDROCARBONS BY IR (EPA METHOD 418.1) (Extracted using EPA Method 3550)

Sample #	Matrix	Dilution Factor	Total Petroleum Hydrocarbons (ppm)
PCA-EX1	soil	5	280
Quality Assurance			
Method Blank			<25
09-074-1	soil	5	<25
09-074-1 (Duplicate)	soil	5	<25

Date of Report: October 1, 1991
Samples Submitted: September 23, 1991
Lab Traveler: 09-070
Project: PC-Avis

RESULTS OF DRY WEIGHT

Sample #	Matrix	Moisture
PCA-SS1-6.5	soil	15%
PCA-EX1	soil	7%

Columbia Analytical Services, Inc.
1317 South 13th Ave. • Kelso, WA 98626 • (206) 577-7222, FAX (206) 636-1068

CHAIN OF CUSTODY/LABORATORY ANALYSIS REQUEST FORM

DATE 9.23.91 PAGE 1 OF 1

PROJECT NAME PC/AVIS # _____
PROJECT MNGR CHAS. GRANT
COMPANY/ADDRESS PACIFIC NORTHERN ENGRG
1081 COLUMBIA BLVD
LONGVIEW, WA 98632 PHONE 423 2245
SAMPLERS SIGNATURE Charles R. Grant

SAMPLE I.D.	LAB I.D.	DATE	TIME	SAMPLE MATRIX	NUMBER OF CONTAINERS	ANALYSIS REQUESTED: Base/Neu/Acid Organics GC/MS 625/8270	Volatile Organics GC/MS 624/8240	Halogenated or Aromatic Volatiles 601/8010 ☐ 602/8020 ☐	Pesticides/PCBs 608/8080	Total Petroleum Hydrocarbons EPA 418.1 ☐ Oregon 418.1 ☐	TPH/Gas/BTEX 5030/8015/8020 Gas ☐ BTEX ☐	TPH/8015 Modified Diesel ☐ Hydrocarbon Scan ☐	TPH - HCID	TCLP Metals ☐ VOA ☐ Semi ☐ VOA ☐ Pest/Herb ☐ Metals (total or dissolved) List Below	Cyanide	pH, Cond, Cl, SO_4, PO_4, F, Br NO_2, NO_3 (circle)	NH_3-N, COD, Total-P, TKN, TOC (circle)	Total Organic Halides (TOX) 9020	BOE TPH HCID	REMARKS
PCA-SS1-6.5'		9.23	1625	SOIL	1														X	8026 GLASS
PCA-SS2-5.5'		1	1630	1	1														X	
PCA-SX1		↓	1720	↓	1														X	

RELINQUISHED BY:
Signature: Charles R. Grant
Printed Name: CHARLES R. GRANT
Firm: PNE
Date/Time: 9.23.91 1805

RECEIVED BY:
Signature: Cynthia L Rocenic
Printed Name: ITSI
Firm: 9/23/91 1705
Date/Time

RELINQUISHED BY:
Signature
Printed Name
Firm
Date/Time

RECEIVED BY:
Signature
Printed Name
Firm
Date/Time

TURNAROUND REQUIREMENTS:
X 24 hr ___ 48 hr ___ 5 day
___ Standard (~ 10-15 working days)
___ Provide Verbal Preliminary Results
___ Provide FAX Preliminary Results
Requested Report Date _____

REPORT REQUIREMENTS
___ I. Routine Report
___ II. Report (includes DUP,MS, MSD, as required, may be charged as samples)
___ III. Data Validation Report (includes All Raw Data)
___ IV.CLP Deliverable Report

INVOICE INFORMATION:
P.O. # _____
Bill to: _____

SAMPLE RECEIPT:
Shipping VIA: _____
Shipping #: _____
Condition: _____
Lab No.: _____

SPECIAL INSTRUCTIONS/COMMENTS:
RUSH - ASAP - CALL 206 4307827 IF A PROBLEM

Analytical Services Inc.
INVOICE #9110-059

Bill To: Pacific Northern Envnmntl.
1081 Columbia Blvd.
Longview, WA 98632

Payment Terms: Net 30

Invoice Date: 10/23/91

Chas Grant, Project Manager

Attn: ACCOUNTS PAYABLE

Date of Report: October 23, 1991
Samples Submitted: October 15, 1991
Project: PC-Avis

3 samples analyzed for Diesel #2 by modified EPA Method 8015 @ $100 per sample	$300.00
3 water samples analyzed for Volatile Organic Compounds by EPA Method 601 @ $125 per sample	$300.00
3 samples analyzed for BTEX and TPH/Gas Mod.EPA 8015 @ $125 per sample	$375.00
4 samples for waste disposal @ $5.00 per sample	$20.00
Amount Due	$995.00

Analytical Services, Inc. (206) 820-4551 (fax) 820-6337
12277 134th Court NE Redmond, Washington 98052

TO SCHEDULE INSPECTION
CALL 455-6977
24 HOURS IN ADVANCE

City of Bellevue
Department of Public Works & ~~Utilities~~

SS No. 9128

PAD No. SSSF-91-7305

Side Sewer Permit

Date 8/23/91 C.O.B. ☐

Owner's Name AVIS RENTaA-CAR SYSTEMS B.S.D. XXXX

Owner's Mailing Address 18811 - 16th Avenue South Seattle, WA 98199 L.H.S. ☐

Property Address 11866 NE 8th St U./L.I.D. ☒7

Property Legal Description lots 81, 82, 83 Brierwood Park

Grid as Built Number G-9 Easement Number NA

Right of Way Permit Number NA

Permit Type: SF ☐ Comm XXXX MF ☐ Revision XXX repair only

DE ☐ Conn XXX R or W ☐ MU ☐ Fee $165.00

Connection Charge in Lieu of Assessment NA

Issued By: Carol Cap Amount Collected $165.00

Contractor Petroleum Services (ok by Carol) for reconnection of existing pipe with adapters

Inspection Comments

Work Inspected and Approved By Rick Reber

Partial _____ Date _____ Final ✓ Date 9/24/91

This permit expires one (1) year from date of issue.

Form No. 0241 Routing: WHITE-Office, YELLOW-Contractor, PINK-PITS, GOLDENROD-file

REMARKS:

RECEIPT NUMBER AMOUNT

RECEIPT NUMBER AMOUNT

CITY OF BELLEVUE WASHINGTON

STORM & SURFACE WATER UTILITY
ENGINEERING DIVISION

CCLF-91-7706
PERMIT NUMBER

$800.00
PERMIT FEE

CLEARING, GRADING, EXCAVATION OR FILL PERMIT

AT 11866 NE 8th St (~~11969 Bellevue Redmond Road~~) ON LOT 81-82-83 BLOCK POR. LY. S. OF BEL-RED Rd
Number Street

OF BRIERWOOD PARK ADDITION. LOT IS _____ X _____ ALLEY _____

LIFE OF PERMIT	PLANS FILED	YES / NO	SEPA CHECKLIST REQUIRED: DNS DS EXEMPT	VALIDATION
1 yr		NO		

Permission is hereby given to do the following described work, according to the conditions hereon and according to the approved plans and specifications pertaining thereto, subject to compliance with Ordinance 2799, Chapter 23.76 of the Bellevue City Code.

This permit pertains only to the above-cited provisions of the Bellevue City Code pertaining to clearing, grading, fill or excavations. Additional authorization from other public agencies may be necessary for work to be accomplished under this permit.

The Permit Authority reserves the right to make additional restrictions for conditions or revoke this permit if deemed necessary by the Permit Authority to correct and/or eliminate hazardous conditions or bring conditions into compliance with this Code.

The City of Bellevue will not be held liable for any property damage which might occur as a result of work to be accomplished under this permit.

DESCRIPTION OF WORK TO BE PERFORMED IS AS FOLLOWS: ASPHALT IN AREA TO BE EXCAVATED WILL BE REMOVED AND DISPOSED; PETROLEUM CONTAMINATED SOILS WILL BE EXCAVATED AND REMOVED; INERT BACKFILL WILL BE PUT INTO EXCAVATION; BACKFILL MATERIAL WILL BE COMPACTED 95% (PROCTOR TEST) ON 1' LIFTS STARTING @ 4' BELOW SURFACE GRADE; BACKFILLED EXCAVATION WILL BE COVERED W/ 3" ASPHALT CAP AND SEALED TO EXISTING ASPHALT; UTILITIES TO BUILDING (GAS, SANITARY SEWER) WILL BE RE-INSTALLED AND INSPECTED PRIOR TO RE-SURFACING

I certify that I am a currently registered contractor, doing business under the name of PETROLEUM SERVICES UNLTD., INC. and my Contractor Reg. No. is PETROSU110CA

Signed John Poe

I certify that I am exempt from the requirements of the Contractor Registration Law under Sec. 3 Chap. 126, Laws of 1987.

Signed _____

CERTIFICATE OF USE & OCCUPANCY MUST BE ISSUED PER SEC. 306 BEFORE PREMISES ARE OCCUPIED OR USED

OWNER AVIS RENT-A-CAR SYSTEMS ADDRESS 1884-16TH AVE. SO. / SEATTLE 98188 PHONE 433 5860

CONTRACTOR PETROLEUM SERVICES UNLIMITED, INC PHONE 423 2245

ENGINEER N/A PHONE _____

ARCHITECT N/A PHONE _____

ADDRESS _____

I have read the conditions of this permit and I agree that I will do the work described above in conformance with the Bellevue City Code and approved plans.

SIGNED John Poe (OWNER) _____

APPLICATION MADE _____ 19 ____ BY _____

PERMIT ISSUED 9/20/91 STORM & SURFACE WATER UTILITY By Lisa Harris 9/19/91

Authorized Agent

STARTING CONSTRUCTION WITHOUT A BUILDING OR CLEARING & GRADING PERMIT IS PUNISHABLE BY FINE AND IMPRISONMENT

CALL 451-4476 HOURS PRIOR TO START OF WORK FOR REQUIRED PRE-CONSTRUCTION CONFERENCE

Form No 0054P

ROUTING: WHITE - Applicant, CANARY - Drainage Utility, PINK - Drainage Utility, GOLDENROD - Permit Coordination, GREEN - Inspection

RECEIVED
AUG 30 1991
PERMIT PROCESSING

Clearing and Grading Permit Long Form

C. Plans and Drawings


1. Survey: See figure 1. Property lines are generally defined by side walk edges to the north and south on N.E. 8th Street and Bellevue Redmond Road and by a concrete retaining wall to the east that separates the property from the neighbors property. The site is essentially flat with a slight grade sloping from east to west. There is a depression in the north west portion of the site for surface drainage.

2. Site Plan: See figure 1. The western portion of the site is not shown in figure 1 as this area of the site will not be impacted by the work to be performed. There is one building at the site that is used for offices and a car wash. The remainder of the property is used as a car lot for auto sales. There is one known underground storage tank at the site that is used to store gasoline for auto fueling.

3. Grading Plan: See figure 1. The site is essentially flat with a slight grade sloping from east to west. The excavating will temporarily impact the surface grade at the site, but upon completion of backfilling and resurfacing, the grade will be restored.

6. Temporary Erosion and Sedimentation Control Plan: See figure 1. During excavation, a limited soils stockpile will be generated. The stockpile will consist of pea gravel currently located in the area to be excavated. The stockpile will be lined with 6 mill plastic and covered with 6 mil plastic at the end of each work day. The stockpile will be bermed with hay bales on the down gradient side toward the north west.

RECEIVED
SEP 6 1991
SURFACE WATER



AVIS CAR SALES LOT
11969 BELLEVUE-REDMOND ROAD
BELLEVUE, WASHINGTON

Figure 1
Site Location

PETROLEUM SERVICES UNLIMITED, INC.

Protection shall be provided for all catch basins which may impacted.

CITY OF BELLEVUE
Department of Public Works & Utilities

Entered By

RIGHT OF WAY USE PERMIT

PART A

Permit Yr. 91 Type D No. 2411 Charles Grant Date

Applicant Name PETROLEUM SERVICES UNLIMITED, INC. C. GRANT Home Phone 206.578.1251
Co./Org. AUTO RENT-A-CAN SYSTEMS W.O. No. Bus. Phone 206.423.224
Address 11969 BELLEVUE REDMOND Rd City BELLEVUE State WA Zip 98004
Location SEND PERMIT TO PETROLEUM SERVICES / 1081 COLUMBIA BLVD. / LONGVIEW, WA 98632

Cut/Length Ft. Sq. Ft.
Describe Use EXCAVATING AND HAULING PETROLEUM CONTAMINATED SOILS FROM SITE. BRINGING IN BACK FILL MATERIAL AND GRADING, ASPHALT PATCH

Dates of use From Date 9-16-91 To Date 10-4-91
Hours of use From Time ~~0800~~ 9AM To Time ~~1500~~ 3PM

Received By DIRK Mitchell Date Received 8/21/91

PART B

Site Inspection Please contact Dennis Powers at 462-2913 48 hours p[rior] to start of work.
Need Conference
Requirement List Must maintain two-way traffic at all times. Proper signing and flagging shall be per MUTCD & City standards.
Other Permits
Attachments
Other Haul route shall be as described in attached plan. Truck traffic allowed only from 9AM to 3PM

Fees 35.00 200.00 Total 235.00
Paid Billed Date Paid

Part C

	DES & DEV	PLANNING	POLICE	CITY ATT	STORM & SURF
DATE RECEIVED					
REVIEWED BY (INITIAL)					
DATE APPROVED					
DATE DENIED					

	TRANS	MAINT & OP	FIRE	R of W	PARKS & REC
DATE RECEIVED	8/21/91				
REVIEWED BY (INITIAL)	MRB				
DATE APPROVED	9/5/91				
DATE DENIED					

Date Issued 9/5/91 Signed Michael R. Bonn
Notify Dennis Powers at 462-2913 48 HRS.
before beginning event or work or permit is invalid.

Form No.0005

Routing: White-Applicant, Canary-Public Works Traffic, Pink-Inspector, Goldenrod-DDD

Soil Sample Collection Methods

Soil samples were collected by two different methods during confirmation sampling of the excavation. All confirmation samples were collected by the Ecology registered site assessor. The two methods were as follows:

o One method used to collect samples was by entering the excavation. This procedure was used when entering the excavation was determined to be safe with the side walls sloped to prevent cave ins. The sampling location was based on areas where field detectable contamination had been removed. A decontaminated, stainless steel hand trowel was then used to scrape the side wall of surface material. The freshly exposed soils were then placed into laboratory prepared, 8 ounce sample containers with Teflon lined lids;

o The other method used involved using the backhoe bucket. The sampling location was based on areas where field detectable contamination had been removed. The backhoe bucket was used collect soils from the desired location and these soils were then brought to the surface. The surface soils in the bucket were then quickly scraped away using a decontaminated, stainless steel trowel. The freshly exposed soils were then placed into laboratory prepared, 8 ounce sample containers with Teflon lined lids.

All of the samples were collected while using clean vinyl gloves that were disposed of after sample collection.

After sample collection, the sample containers were placed into an iced cooler under chain-of-custody procedures for transport to the laboratory.

The decontamination procedures for the sampling equipment (trowels) were conducted using the following procedures:

o TSP, Joy detergent and tap water wash;
o Tap water rinse;
o distilled water rinse.

ILLSBORO LANDFILL, INC.
05 S.F. Minter Bridge Road
...sboro, OR 97123
hone: 503-640-9427 FAX: 648-2400

Application to Dispose of Special Wastes

STRUCTIONS: Please read important sheet attached. Type, or print heavily in ink. The person responsible for accuracy of information must sign., Return copy of completed application and any supporting information to Hillsboro Landfill, Inc. along with check for the $25 application fee.

Office use only
Permit no. 611
Expires 11/12/91

received
8/12/91 Billed

pplicant's Name Petroleum Services Unlimited, Inc.

ddress 1081 Columbia Blvd City Longview WA Zip Code 98632

ontact Person Charles R Grant Phone (206) 423-2245

ob Site Address 11969 Bellevue-Redmond Bellevue, WA City
(if different than applicant's)

cription of Special Waste (waste composition and physical, chemical, manufacturing process from which waste originated)

Diesel contaminated soil → 2200 ppm

time disposal? X yes no Deposal frequency (if more than one time)

antity; (gallons, drums, lbs., cubic yards) 300 yds Quantity per year

ardous. yes X no How did you determine whether hazardous or not? Material Safety Data Sheet,

test results X other (enclose documents)

dling and spill clean up directions Shovel and/or front loader

nsporter Cornerstone Construction, Inc.

vious permit for this waste, if any, Number

EMPTY CONTAINERS WILL BE ACCEPTED. If empty containers only describe material originally in container and whether the been rinsed.

ification of Accuracy of Description: This is to certify that the above described materials are properly classified, identified, packaged, ed, labeled, cleansed, rinsed and prepared as indicated above.

Signature Rochelle A Shaw Date 8/12/91

HILLSBORO LANDFILL ACTION: Disposal of the above described Special Waste is

Approved ✓ Disapproved for disposal at the Hillsboro Landfill

at the disposal rate of $ 18.25 ~~per ton~~ cubic yd per trip minimum charge.

Signature Charles R. Grant Date 8-12-91

GENERAL INSTRUCTIONS: Appointment may be required 24 HOURS prior to each disposal. Cash on disposal, business check or have prior account established. To establish an account or to call for an appointment, Telephone 640-9427.

SPECIAL INSTRUCTIONS: Out of state waste

Petroleum Services Unlimited, Inc.
1081 Columbia Blvd.
Longview, WA 98632

PROJECT NUMBER	WELL NUMBER MW6	SHEET 1 OF 1

MONITORING WELL DRILLING & CONSTRUCTION LOG


PROJECT PC/AVIS Avis Sales Lot LOCATION 11969 Bel-Red Rd., Bellevue, WA


ELEVATION _____ DRILLING CONTRACTOR McGarret Drilling


DRILLING METHOD AND EQUIPMENT BRATT-22R Mobile Hollow Stem Auger Drill Rig


START DATE 9-25-91 FINISH DATE 9-25-91 WATER LEVEL _____ LOGGER C. Grant

DEPTH BELOW SURFACE	SAMPLE INTERVAL	SAMPLE TYPE AND NUMBER	SAMPLE RECOVERY	STANDARD PENETRATION TEST RESULTS 6"-6"-6" (N)	SOIL DESCRIPTION: NAME, GRADATION OR PLASTICITY, PARTICLE SIZE DISTRIBUTION, COLOR, MOISTURE CONTENT, RELATIVE DENSITY OR CONSISTENCY, SOIL STRUCTURE, MINERALOGY, USCS GROUP SYMBOL	WELL CONSTRUCTION: CASING TYPE, DIAMETER, SCREEN INTERVAL, SLOT SIZE, GRAVEL PACK GRADATION & INTERVAL, GROUT INTERVAL, ETC.
						Flush mount monument cover
2.5'						4.25' of 2" DIA Schedule 40 PVC blank casing used
						2 ea.50# bags Bariod hole plug bentonite seal to 3' depth
	3.5				Top 2.5" is Gravelly sand w/ silt, brown moist, loose, sand w/ gravel to 1.25"(SP), next 3" is a clay w/ silt, grey green, moist, mottled, clay w/ some roots (SC), bottom 9" is a poorly graded fine sand w/ silt, brown grey, moist, loose, sand w/ occasional gravel (SP) PID=2.1ppm	
			15"	2-1-4		10' of 2" DIA schedule 40 20 slot PVC Screen used
5.0'	5.0			(5)		
						3 ea. 100# Bags 8-12 CSSI-Silica sand used as sand pack
						Estimate groundwater at 5.75' sand pack from 3' to TD boring
7.5'						Screened section from 4.25 to 14.25'
	8.5				Top 3" is a peat, dark brown, loam w/ roots (PT), bottom 14" is a poorly graded fine sand, grey white, wet, medium dense, sand w/ occasional gravel (SP)	
			17"	3-5-12		
10'	10.0			(17)		
12.5'						
	13.5				Sand, grey, wet, sand (SP) rock was lodged in sampler	
			2"	10-19-22		.5' bottom sump used from 14.25' to 14.75'
15.0'	15.0			(41)		Total depth boring 15'



Discovery of 16" abandoned concrete pipe
91 9 23


Attempted plug of 16" sewer pipe failed
91 9 24



91 9 25


4" pipe connection into 16" pipe
91 9 25


Excavation of mineral spirits contaminated soils




Mineral spirits contaminated soils stock-piles



Stop excavation because of subsurface utilities in NE corner




Running water from 4" concrete pipe from dry cleaner's property



Puget Power Utility Vault


6" Dia. side sewer - back filling w/ available pea gravel




Surface excavation activities



Excavation to below ground water table



Excavtion activities in NW corner - Note Remnant Asphalt Layer



Excavation in SE corner

PERKINS COIE

A LAW PARTNERSHIP INCLUDING PROFESSIONAL CORPORATIONS
1201 THIRD AVENUE, 40TH FLOOR • SEATTLE, WASHINGTON 98101-3099 • (206) 583-8888

DEC 19
DEPT. OF ECOLOGY

December 17, 1991

Joseph M. Hickey
Northwest Regional Office
Washington State Department of Ecology
4350 - 150th Avenue, N. E.
Redmond, WA 98052

Re: Avis Rent-A-Car Property in Bellevue, WA

Dear Mr. Hickey:

On behalf of our client, Avis Rent-A-Car Systems, Inc., I am enclosing a report prepared by Pacific Northern Environmental Corp. (PNE) concerning the investigation and cleanup of Avis's property at 11969 Bellevue-Redmond Road in Bellevue, Washington.

Your records should indicate that on June 12, 1989 we filed a report prepared by Landau & Associates, Inc. concerning the removal of two underground storage tanks at this site. That tank removal and related site remediation occurred on the south side of the existing building on the site. The remediation work covered by the PNE report occurred on the north side of the building and does not appear to have any relation to the previous removal work.

The investigations and cleanup described in the PNE report were instigated by a contemplated sale of the property. That sale is still pending. The potential purchaser has been provided with a copy of the enclosed report.

As indicated in the PNE report, three contamination problems were encountered and dealt with during the course of PNE's work. None of these had any relation to Avis's current or past operations at the site. All three problems appear to be related to either prior gas station operations at the site or contamination emanating from off-property sources. The three matters are: (1) diesel contaminated soils north of the building, most likely associated with a previously removed underground storage tank; (2) a truncated and uncapped abandoned 16" sewer pipe, into which was plumbed a 4" pipe from the floor drain of the neighboring drycleaning facility

[06266-0003/SL913510.038]

to the east; and (3) mineral spirits contaminated soil in the far northeast tip of the property, which appears to have originated from the drycleaning facility property. The investigation and remediation of each of these matters is fully discussed in the PNE report.

PNE recommends that an additional study be conducted to define more accurately the groundwater flow direction at the site and to monitor the effect of the soils removal on the groundwater contamination that was detected.

Avis is reviewing PNE's recommendations and expects to be discussing them with the potential purchaser of the property. Avis will report to the Department of Ecology on decisions reached regarding further actions at the site. In the interim, should you have any questions regarding the site or the PNE report, please give me a call.

Sincerely yours,

Douglas S. Little

DSL:sab

cc: Karl Westermann
Charles Grant

FTI

FUEL TANK INSTALLATION CO., INC.

UNDERGROUND STORAGE TANK REMOVAL AND SOIL SAMPLE SUMMARY REPORT

October 18, 1999

Re: Bakker's Fine Drycleaning, 12002 NE 8th Street, Bellevue, WA

This report presents the site assessment services performed by myself, Thomas H. Anderson, relating to the 6000 gallon steel double wall underground storage tank removal, soil samples and laboratory report at the above referenced property.

PURPOSE

The purpose of this work was to assess the conditions of the adjacent soils following the removal of the 6000 gallon underground storage tank (UST). This work was accomplished by Fuel Tank Installation Company, Inc. (FTICI). This work included removal of the UST and collection of soil samples from the area of the excavation to be delivered to a laboratory for analysis. This report is prepared to present the events as they occurred and to help illustrate the conditions present at the site.

SCOPE OF INSPECTION

The scope of services included: removal and disposal of the 6000 gallon UST, visual and olfactory inspection of the soil in the vicinity of the excavation, collection of soil samples for analysis of Total Petroleum Hydrocarbons (TPH) by an approved laboratory using methods NWTPH-Dx; and preparation of this written report.

SITE DESCRIPTION

The subject site is located at 12002 NE 8th Street, Bellevue, WA., see F-4 on Vicinity Map (attachment #1). The property is used as a drycleaning business. The UST was located on the north side of the building (attachment #2). The UST was used to store stoddard solvent.

PROJECT DESCRIPTION AND SITE OBSERVATIONS

On October 11, 1999 the UST was inerted by Marine Chemist, Certificate #43992 (attachment #3). The UST was then excavated and removed. The UST was disposed of

in the city of Seattle in a legal manner. Three grab soil samples were collected in prepared four ounce sampling jars by FTICI personnel at the South-1, West-2 and East-3 areas of the excavation site just above the water line (see attachment #2). A chain of custody was completed at the time of transport (attachment #4). Visual and olfactory observations by FTICI personnel noted that no obvious signs of petroleum contaminated soil exsisted. The soil samples were taken to Friedman & Bruya, Inc. for analysis (attachment #5 A&B). Laboratory test results of the soil samples collected from the excavation area confirmed that the soils tested were well below the Model Toxics Control Act (MTCA) Method A* clean up guidelines of 200 parts per million (ppm). The UST site was backfilled with clean fill material and compacted.

LIMITATIONS

This report has been prepared using generally accepted professional practices, related to the nature of the work accomplished, in the same or similar localities, at the time the services were performed. This report was prepared for the use of Bakker's Fine Drycleaning, 12002 NE 8th Street, Bellevue, WA. This report should not be construed to represent a legal opinion. No other conditions, expressed or implied, should be understood.

If there are any questions concerning this information please call me at 206-244-8020.
Thank you for this opportunity to do business with you!

Sincerely,

Thomas H. Anderson
IFCI # 1059581-26 ASI# 32002112
CONTRACTOR'S LICENSE #FUELTIC080B8

*Model Toxics Control Act (MTCA) is Washington's hazardous waste cleanup law, Chapter 70.105D RCW.

10/15/99

FRIEDMAN & BRUYA, INC.
3012 16th Avenue West
Seattle, WA 98119-2029
(206) 285-8282

910070

SAMPLE CHAIN OF CUSTODY

Send Report To: Fuel TANK INSTALLATION Contact: TOM
Company:
Address:
City, State, Zip:
Phone # 206-244-8020 FAX # 901-9147 Date: 10/12/99

SITE NO.	PROJECT NAME	PURCHASE ORDER #
	BAKER'S	

SAMPLERS (signature): [signature] PROJECT LOCATION: 12002 N.E. 8TH Bellu

REMARKS:

SAMPLE DISPOSAL INFORMATION
- [x] Dispose after 30 days
- [ ] Return Samples
- [ ] Call for Instructions

Sample #	Date/Time Sampled	Type of Sample	# of Jars	Lab Sample #	Analyses Requested
SOUTH	10/11/99	SOIL		01	STODDARD SOLVENT
WEST				02	
EAST				03	

SIGNATURE	PRINT NAME	COMPANY	Date	Time
Relinquished by: [signature]	THOMAS H. ANDERSON	F.T.I. Co.	10/12/99	9:37
Received by: Dianne C. Hurt	DIANNE C. HURT	F&B, Inc.	10/13/99	9:50 AM
Relinquished by:				
Received by:				

ENVIRONMENTAL CHEMISTS

Date of Report: 10/21/99
Date Received: 10/13/99
Project: Bakker's

QUALITY ASSURANCE RESULTS FROM THE ANALYSIS OF SOIL SAMPLES FOR TOTAL PETROLEUM HYDROCARBONS AS STODDARD SOLVENT USING METHOD NWTPH-Dx

Laboratory Code: 910070-01 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria
Stoddard Solvent	µg/g (ppm)	26	16	48 a	0-20

Laboratory Code: 910070-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	% Recovery MS	% Recovery MSD	Acceptance Criteria	Relative Percent Difference
Stoddard Solvent	µg/g (ppm)	500	26	112	112	41-170	0

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	% Recovery LCS	% Recovery LCSD	Acceptance Criteria	Relative Percent Difference
Stoddard Solvent	µg/g (ppm)	500	94	98	59-138	4

a - The analyte was detected at a level less than five times the detection limit. The RPD results may not provide reliable information on the variability of the analysis.

5-B

FRIEDMAN & BRUYA, INC.

ENVIRONMENTAL CHEMISTS


Date of Report: 10/21/99
Date Received: 10/13/99
Project: Bakker's
Date Extracted: 10/15/99
Date Analyzed: 10/16/99


RESULTS FROM THE ANALYSIS OF THE SOIL SAMPLES FOR TOTAL PETROLEUM HYDROCARBONS AS STODDARD SOLVENT USING METHOD NWTPH-Dx

Results Reported on a Dry Weight Basis
Results Reported as µg/g (ppm)

Sample ID Laboratory ID	Stoddard Solvent	Surrogate (% Recovery)
SOUTH 910070-01	26	101
WEST 910070-02	<10	100
EAST 910070-03	<10	102
Method Blank	<10	116

5-A


"STODDARD SOLVENT", 6,000 GAL
○ SOIL SAMPLES
EXIST. APPR.
BEL-RED ROAD
EXISTING SIDEWALK
EXISTING PLANTER
P.L. 230'±
N
②
③
①
EXISTING SIGN
EXISTING BASEMENT BOILER ROOM
EXISTING ASPHALT PAVING
EXISTING BAKKER'S DRYCLEANING SHOP
P.L. 243'±


BELLEVUE
MEDINA
CLYDE HILL
HUNTS POINT
YARROW POINT
KIRKLAND
WILBURTON
LAKE WASHINGTON
FAIRWEATHER BAY
OVERLAKE GOLF & COUNTRY CLUB
HIDDEN VALLEY SPORTS PARK
MEYDENBAUER BEACH PARK
CHISM BEACH PARK
WILBURTON HILL PARK
BOTANICAL GARDENS
NE 24TH ST
NE 20TH ST
NE 12TH ST
NE 8TH ST
NE 6TH ST
MAIN ST
BELLEVUE WAY NE
BELLEVUE WAY SE
NE BELLEVUE
124TH AVE NE
108TH AVE NE
100TH AVE NE
98TH AVE NE
92ND AVE NE
84TH AVE NE
80TH AVE NE
SE 8TH ST
SE 6TH ST
SE 5TH ST
SE 4TH PL
SE 3RD ST
SE 2ND ST
SE 1ST ST
SE 1ST PL
SE 24TH ST
SE 16TH ST
SE 12TH ST
SE 10TH ST
SE 8TH ST
108TH AVE SE
112TH AVE SE
116TH AVE SE
118TH AVE SE
120TH AVE SE
124TH AVE SE
128TH AVE SE
132ND AVE SE
136TH PL SE
140TH AVE SE
144TH AVE SE
148TH AVE SE
150TH AVE SE
156TH AVE SE
164TH AVE SE
168TH AVE SE
172ND AVE SE
SHOREHAM DR
SHOREHAM PL
SHOREHAM CT
SHOREHAM WAY
SHOREHAM LN
SHOREHAM CIR
SHOREHAM PARK
SHOREHAM BEACH
SHOREHAM PARK
SHOREHAM BEACH
SHOREHAM PARK
SHOREHAM BEACH

P.O. BOX 16204 SEATTLE, WA 98116
(206) 932-0206.

MARINE CHEMIST CERTIFICATE

SERIAL No. 43992

FUEL TANK INS.	BARKER'S - 12002 NE 8th BELLEVUE	10/11/99
Survey Requested by	Vessel Owner or Agent	Date
PLEASE SEE BELOW	STEEL CYLINDRICAL UNDERGROUND	
Vessel	Type of Vessel	Specific Location of Vessel
STODDARD SOLVENT	O_2 LEL	9:00AM
Last Three (3) Cargoes	Test Method	Time Survey Completed

5-6000 GAL UST — INERTED WITH CO_2

— MAY BE SAFELY EXCAVATED

— PLEASE TAKE CARE TO SEAL TANK OPENINGS BEFORE TRANSPORTATION

READINGS: INITIAL LEL - 18
O_2 - 5-8%

In the event of any physical or atmospheric changes adversely affecting the gas-free condition of the above spaces, or if in any doubt, immediately stop all work and contact the undersigned Marine Chemist.

QUALIFICATIONS: Transfer of ballast or manipulation of valves or closure equipment tending to alter conditions in pipe lines, tanks or compartments subject to gas accumulation, unless specifically approved in this Certificate, requires inspection and endorsement or reissue of Certificate for the spaces so affected. All lines, vents, heating coils, valves, and similarly enclosed appurtenances shall be considered "not safe" unless otherwise specifically designated.

STANDARD SAFETY DESIGNATIONS

SAFE FOR WORKERS: Means that in the compartment or space so designated, (a) the oxygen content of the atmosphere is at least 19.5 percent by volume; and that, (b) toxic materials in the atmosphere are within permissible concentrations; and that, (c) the residues are not capable of producing toxic materials under existing atmospheric conditions while maintained as directed on the Marine Chemist's Certificate.

NOT SAFE FOR WORKERS. Means that in the compartment or space so designated, the requirements of Safe for Workers has not been met.

SAFE FOR HOT WORK: Means that in the compartment so designated; (a) oxygen content of the atmosphere is at least 19.5 percent by volume, with the exception of inerted spaces or where external hot work is to be performed; and that, (b) the concentration of flammable materials in the atmosphere is below 10 percent of the lower flammable limit; and that, (c) the residues are not capable of producing a higher concentration than permitted by (b) above under existing atmospheric conditions in the presence of fire; and while maintained as directed on the Marine Chemist's Certificate; and further, that, (d) all adjacent spaces have been cleaned sufficiently to prevent the spread of fire, or are satisfactorily inerted, or, in the case of fuel tanks, or lube oil tanks, or engine room or fire room bilges, have been treated in accordance with the Marine Chemist's requirements.

NOT SAFE FOR HOT WORK. Means that in the compartment so designated, the requirements of Safe for Hot Work have not been met.

SAFE FOR REPAIR YARD ENTRY Means that the compartments and spaces of the flammable cryogenic liquid carrier so designated: (a) have been tested by sampling at remote sampling stations, and results indicate the atmosphere tested to be above 19.5 percent oxygen, and less than 10 percent of the lower flammable limit, or (b) are inerted.

CHEMIST'S ENDORSEMENT: This is to certify that I have personally determined that all spaces in the foregoing list are in accordance with NFPA 306-1980 Control of Gas Hazards on Vessels and have found the condition of each to be in accordance with its assigned designation.


"The undersigned acknowledges receipt of this Certificate under Section 2-3 of NFPA 306-1980 and understands conditions and limitations under which it was issued."

This Certificate is based on conditions existing at the time the inspection herein set forth was completed and is issued subject to compliance with all qualifications and instructions.

Signed		10/11/99	Signed	Don Sly	MC-598
Name	Company	Date	Marine Chemist		Certificate No.

VESSEL POSTING

3



APPENDIX D
Environmental Professional Resumes

DANA CARLISLE, ENVIRONMENTAL MANAGER/PRINCIPAL

Education
B.A., University of Pennsylvania

M.S.E, University of Washington

Commercial Real Estate Certificate, University of Washington

Registrations
Washington: Professional Engineer

Environmental Professional (EP) for Phase I ESAs

Dana is an Engineer, an experienced Project Manager and licensed Professional Engineer. In addition to these qualifications, Dana also holds a Certificate in Commercial Real Estate from the UW. Dana has 20 years of environmental engineering consulting experience specializing in environmental due diligence (EDD), site characterization, cleanup action planning, cost estimating, remedial action engineering design, and mitigation. She has worked through the MTCA process achieving dozens of site closure/No Further Action decisions through Ecology's Voluntary Cleanup Program.

Dana's 20 years of experience in Puget Sound provides the foundation by which she understands the issues. Her experience spans the acquisition of an individual parcel, acquisitions of multiple contiguous parcels or multiple non-contiguous parcels. She frequently acts as liaison between facility owners and regulatory agencies while flawlessly managing project budget, schedule and scope; permit application and coordination; project quality; and overall consultant team management. Representative project experience includes:

- City of Bellevue, N.E. 8th Street Widening, Phase I ESA and Linear Corridor ESA
- City of Everett, Phase I ESA, Preferred UW North Site, City of Everett Public Works Cedar Street Complex
- City of Kenmore, Phase I and Phase II ESA, Cleanup Action Plan and No Further Action, Kenmore New City Hall, Former Northshore Utility District Maintenance Headquarters
- City of Redmond, Environmental Cleanup, Leary Way Shops
- City of Redmond, Phase II ESA and Haz-Mat Soil Handling Specifications, Leary Way Water Quality Facility
- City of Redmond, Wellhead Protection Program Monitoring/Groundwater Monitoring Network Enhancement
- City of Redmond, Fire Station 17, Phase I ESA
- King County Housing Authority, Phase I and Phase II ESAs for Hope VI Redevelopment Projects at Park Lake Homes Site II, Seattle
- Seattle Housing Authority, Phase I and Phase II ESAs for Acquisition Property at High Point Redevelopment, Seattle
- Seattle Housing Authority, Phase I and Phase II ESA and Cleanup Action Plan, EPA Brownfields Site Former Dry Cleaner, Property Acquisition at Yesler Terrace, Seattle
- On-call Contract Due Diligence work includes Seattle Housing Authority, City of Redmond, City of Everett, City of Kenmore, Pierce County and Snohomish County
- Pierce County Surface Water Management, Training Course on Conducting Phase I ESAs and Transaction Screens

Community Involvement Outreach

- Peace Corps Volunteer, Botswana
- Commercial Real Estate Women, Seattle and Sound


JESSICA ROBERTSON, LG, ENVIRONMENTAL GEOLOGIST

Education
M.S., Geology, Central Washington University

B.A., Chemistry-Geology, Whitman College

Registrations
Washington: Licensed Geologist

Jessica has been an environmental geologist in Washington State since 2002 and has specialized in completion of Phase I ESAs since 2003, completing over 100 Phase I ESA reports since that time. She is well versed in the requirements of American Society for Testing and Materials (ASTM) Standard E 1527-05 for Phase I ESAs and the U.S. Environmental Protection Agency's (EPAs) Federal Standard 40 CFR Part 312 "Standards and Practices for All Appropriate Inquiries (AAI)." Jessica is an historical research specialist who can efficiently acquire historical information from the many different resources needed to compile a proper Phase I ESA. She is also familiar in MTCA Method A and B cleanup level methodology and UST site inspections. Jessica has performed Phase II ESAs, groundwater and soil sampling, remedial excavations and drilling explorations. Many of her projects are in the development and transportation markets, and she has completed Phase I ESAs and related tasks for a wide range of projects, including 1,000-acre undeveloped forest land parcels as well as large urban city blocks with over 100 years of industrial and commercial development history.



APPENDIX E
Report Limitations and Guidelines for Use

APPENDIX E
REPORT LIMITATIONS AND GUIDELINES FOR USE

This appendix provides information to help you manage your risks with respect to the use of this report.

Read These Provisions Closely

Some clients, design professionals and contractors may not recognize that the geoscience practices (geotechnical engineering, geology and environmental science) are far less exact than other engineering and natural science disciplines. This lack of understanding can create unrealistic expectations that could lead to disappointments, claims and disputes. GeoEngineers includes these explanatory "limitations" provisions in our reports to help reduce such risks. Please confer with GeoEngineers if you are unclear how these "Report Limitations and Guidelines for Use" apply to your project or site.

Environmental Services Are Performed for Specific Purposes, Persons and Projects

GeoEngineers has performed this ESA of the of two parcels owned by Ernest Bakker located at 11855 NE Bellevue-Redmond Road in Bellevue, Washington in general accordance with the scope and limitations of Contract Amendment No. 2 to Agreement No. PW-R164, ASTM E 1527-05, Standard Practice for Phase I ESAs, and EPA's Federal Standard 40 CFR Part 312 "Standards and Practices for All Appropriate Inquiries (AAI)." This report has been prepared for the exclusive use of the City of Bellevue and PB, their agents and project design team. This report is not intended for use by others, and the information contained herein is not applicable to other properties.

GeoEngineers structures our services to meet the specific needs of our clients. For example, an environmental site assessment study conducted for a property owner may not fulfill the needs of a prospective purchaser of the same property. Because each environmental study is unique, each environmental report is unique, prepared solely for the specific client and project property. This report should not be applied for any purpose or project except the one originally contemplated.

This Environmental Report Is Based on a Unique Set of Project-Specific Factors

This report has been prepared for the two parcels owned by Ernest Bakker located at 11855 NE Bellevue-Redmond Road in Bellevue, Washington. GeoEngineers considered a number of unique, project-specific factors when establishing the scope of services for this project and report. Unless GeoEngineers specifically indicates otherwise, do not rely on this report if it was:

- not prepared for you,
- not prepared for your project,
- not prepared for the specific property explored, or
- completed before important project changes were made.

If important changes are made to the project or subject property after the date of this report, GeoEngineers should be retained to review our interpretations and recommendations and to provide written modifications or confirmation, as appropriate.

Reliance Conditions for Third Parties

Our report was prepared for the exclusive use of City of Bellevue and PB. No other party may rely on the product of our services unless we agree in advance to such reliance in writing. This is to provide our firm with reasonable protection against open-ended liability claims by third parties with whom there would otherwise be no contractual limits to their actions. Within the limitations of scope, schedule and budget, our services have been executed in accordance with our Agreement with the Client and generally accepted environmental practices in this area at the time this report was prepared.

Historical Information Provided by Others

GeoEngineers makes no warranties or guarantees regarding the accuracy or completeness of information provided or compiled by others. The information presented in this report is based on the above-described research and a single recent site visit. GeoEngineers has relied upon information provided by others in our description of historical conditions and in our review of regulatory databases and files. The available data do not provide definitive information with regard to all past uses, operations or incidents at the subject property or adjacent properties.

Uncertainty Remains Even After This ESA Study Is Completed

No ESA can wholly eliminate uncertainty regarding the potential for recognized environmental conditions (RECs) in connection with a property. Performance of an ESA study is intended to reduce, but not eliminate, uncertainty regarding the potential for RECs in connection with a property. There is always a potential that areas with contamination that were not identified during this Phase I ESA exist at the subject property or in the study area. Further evaluation of such potential would require additional research, subsurface exploration, sampling and/or testing.

Environmental Regulations Are Always Evolving

Some substances may be present in the vicinity of the subject property in quantities or under conditions that may have led, or may lead, to contamination of the subject property, but are not included in current local, state or federal regulatory definitions of hazardous substances or do not otherwise present current potential liability. GeoEngineers cannot be responsible if the standards for appropriate inquiry, or regulatory definitions of hazardous substance, change or if more stringent environmental standards are developed in the future.

Property Conditions Can Change

This environmental report is based on conditions that existed at the time the study was performed. The findings and conclusions of this report may be affected by the passage of time (for example, a Phase I ESA report is typically applicable for 180 days), by events such as a change in property use or occupancy, or by natural events, such as floods, earthquakes, slope instability or groundwater fluctuations. If more than six months have passed since issuance of our report or work product, or if any of the described events may have occurred, please contact GeoEngineers before applying

this report so that we may evaluate whether changed conditions affect the continued reliability or applicability of our conclusions and recommendations.

Geotechnical, Geologic and Environmental Reports Should Not Be Interchanged

The equipment, techniques and personnel used to perform an environmental study differ significantly from those used to perform a geotechnical or geologic study and vice versa. For that reason, a geotechnical engineering or geologic report does not usually relate any environmental findings, conclusions or recommendations; e.g., about the likelihood of encountering underground storage tanks or regulated contaminants. Similarly, environmental reports are not used to address geotechnical or geologic concerns regarding a specific project.

Biological Pollutants

GeoEngineers' Scope of Work specifically excludes the investigation, detection, prevention or assessment of the presence of Biological Pollutants. Accordingly, this report does not include any interpretations, recommendations, findings, or conclusions regarding the detecting, assessing, preventing or abating of Biological Pollutants and no conclusions or inferences should be drawn regarding Biological Pollutants, as they may relate to this project. The term "Biological Pollutants" includes, but is not limited to, molds, fungi, spores, bacteria, and viruses, and/or any of their byproducts.

If Client desires these specialized services, they should be obtained from a consultant who offers services in this specialized field.