SNOHOMISH HEALTH DISTR
3020 Rucker, Suite 104
Everett, WA 98201
425.339.5250

FIELD INVESTIGATION REPORT

RECEIVED
DEC 12 2007
DEPT. OF ECOLOGY
TCP-NWRO

Date Rec'd	10/4/2007	CB1	11-13
Rec'd By	DOE/sei	CB2	11-27
Complaint #	070988	CB3	12-4
Area	GWC		

5-day check [ ]

Address_of_Complaint: 18306 Hwy 99

City of Complaint: Lynnwood

ZIP:

Person_Causing_Complaint: @ Pull-A-Part Wrecking Yard

Cause_Phone: 425-778-3147

Nature_of_Complaint

Solid_Waste [ ] ChemPhys_Haz [1] Prom_Dump [ ] PD/TypWst [ ]

Vector [ ] HHW [ ] IIs [1] SQG [ ] Drug Lab [ ] PD/Qty [ ]

Misc [ ]

G T [ ] BG TW [ ] DD R [ ] E-W LC [ ] IW YW [ ]

Cleaned up by: Dumper [ ] Owner [ ] Agency [ ]

ERTS # 600700 See attached re Self-Service auto wrecking yard. Stream runs thru the yard in a pipe. They are not draining the fluids adequately & the site is heavily contaminated. All the pollutants drain into Scriber Creek.

N 47° 49' 58.4" ✓
W 122° 18' 20.6" ✓

Complainant: Tracie Walters for Jared Bond

Complainant_Phone: / 425-670-6637

Refer to #:

Complainant_Address: DOE / City of Lynnwood Public Works, PO Box 5008, Lynnwood 98046-5008

Property Owner ~~not on Assessor's web~~ Ferrells Auto Parts Inc ✓ Phone

Mailing Address Same Tax Acct. # 003743 003 00400 ✓

City, State Zip

Retained [ ] ✓

Thomas Guide [ ] Latitude Longitude

Sign-off Retained Location: Chem-phys.

Status

10/15/07. S.E visit noted a site with a paved lot on the Eastern most 50 feet section of property. North the remainder of the prop beyond the pad to the west appeared to be un-paved and covered in cars + auto parts. Noted what appeared to be Stream running from the position of the NE corner of the shop. Noted debris and evident in the soil noted site appears to slope from the shop down to the west. about 1/2 Thy the pad to the west the grade increases to form a slight belly Thy to the

12/11/07 Cy of file & DOE. sei

Abated/Completed Name Date 12/10/07

Recomend listing on CSCS Due to confirmed Exceedances of MTCA Method A standards

12-5-07

SNOHOMISH HEALTH DISTR
3020 Rucker, Suite 104
Everett, WA 98201
425.339.5250
FIELD INVESTIGATION REPORT

Date Rec'd	12/5/2007	CB1	
Rec'd By	DOE/ek	CB2	
Complaint #	071147	CB3	
Area	GWC		

5-day check: yes

Address_of_Complaint	City of Complaint	ZIP
18306 Hwy 99	Lynnwood	98037

Person_Causing_Complaint	Cause_Phone
Pull-A-Part	425-778-3147

Nature_of_Complaint

Solid_Waste ☐ | ChemPhys_Haz 1 | Prom_Dump ☐ | PD/TypWst ☐ | Cleaned up by: Dumper ☐ Owner ☐ Agency ☐

Vector ☐ | HHW ☐ IIs ☐ SQG ☐ | Drug Lab ☐ | PD/Qty ☐ | G T ☐ BG TW ☐ DD R ☐ E-W LC ☐ IW YW ☐

Misc ☐

ERTS # 602375 See attached re vehicle fluids on ground; stream nearby.

070988

Complainant	Complainant_Phone	Refer to #
Tamara Sacayanan (DOE) for / Scotty Emerle	425-649-7229 / 206-696-1029	070988

Complainant_Address: DOE

Property Owner: Ferrills Auto Parks Inc Phone:

Mailing Address: same Tax Acct. #: 003743 003 00400

City, State Zip:

Retained: Y

Thomas Guide ☐ Latitude X: Longitude Y: Sign-off Retained Location: Chem-Phys

Status

12/5/07 See complaint # SW 070988 - ERTS # 600700

Abated/Completed 12/5/2007

Name Date

12/11/07 Cy of file mailed to Donna Musa, DOE, per GWC. ser

SERVICE RECORD

SNOHOMISH HEALTH DISTRICT
ENVIRONMENTAL HEALTH

SITE ADDRESS

COMPLAINT NO. PTA NO.

Date	Notes	Recorded by	Title
	middle of the site.		
	→ observed a shop person washing down the paved area @ the shop toward the west to the unpaved area.		
	→ Did not locate surface water at this time. There appears to be a ditch on the S. side of the site which may be the stream.		
	→ Further investigation is required w/ possible sampling due to the observed conditions @ the site on unpaved areas.		

Ferrill's Auto Parts, Inc.

Bruce Thomson

PULL A PART

360.403.9606 x 112
ferrills@comcast.net
425.388.5866 cell
pullapartwa.com

Professional Crushing

SERVICE RECORD

SNOHOMISH HEALTH DISTRICT
ENVIRONMENTAL HEALTH

SITE ADDRESS

COMPLAINT NO. PTA NO.

Date	Notes	Recorded by	Title
11/5/07	Site visit to "pull a part" yard in lynnwood @ 18306 Hy 99.		
	Spoke w/ Mike Bollerslev / Manager @ TR site. Walked TR site + noted several areas of obvious soil staining w/ TPH or automotive related liquids / Gels or oils. Noted metal in soil w/out content - noted obvious contamination of surface soils. Several phots taken documenting TR visit are attached.		
	phone for Mike Bollerslev 425-778-3147 241		
	Contact ext → 112 → 113		
	~~OWNERS~~ — Bruce + Mindy		
	(2 @ Fact 1) 360-403-9606		
	~~Ted~~ pull apart brand.		

PULL A PART

Mike Bollerslev
Lynnwood Store Manager
18306 Hwy 99
Lynnwood, WA 98037

425-778-3147 ext. 241
Cell: 425-418-6706 Fax: 425-771-3147
Email: PAPWAMIKE@comcast.net
Website: www.PullAPartWA.com

Rev081403AE:jsf

SERVICE RECORD

SNOHOMISH HEALTH DISTRICT
ENVIRONMENTAL HEALTH

SITE ADDRESS

COMPLAINT NO. PTA NO.

Date	Notes	Recorded by	Title
1/5/07 Contd	→ TC to Brian w/ Pull-a-Part Scheduled a site visit for 11/13/07 @ 10:am to conduct some soil sampling @ the site. CLOSED.		
11/13/07	Site visit to pull apart auto on the Date noted. For the purpose of collecting soil samples from the yard. Noted area on the yard was wet from a heavy rain the day prior (11/12/07). Noted significant puddling around prop. Most such water had some sort of sheen. Noted the oil/H2O separator @ the S. side of the yard. Inspected the oil/H2O separator + the engineered discharge unit. Noted that to the W. of the discharge unit a spill was allowed direct discharge from the site to the ditch line to the south and eventually Seabrook Creek. Noted some sheen @ the ditchline to the South. → Continued on next SR		

Ferrill's Auto Parts, Inc.

Bruce Thomson

PULL A PART

360.403.9606 x 112
ferrills@comcast.net
425.388.5866 cell
pullapartwa.com

Professional Crushing

Rev081403AE:jsl

SERVICE RECORD

SNOHOMISH HEALTH DISTRICT
ENVIRONMENTAL HEALTH

SITE ADDRESS

COMPLAINT NO. PTA NO.

Date	Notes	Recorded by	Title
11/13/07.	-collected 3 samples.		

1) Fan area just N. of oil/H_2O sep.
2) NTA of oil/H_2O sep by 30 feet.
2) a same location as #2, 2a sampled for VOC. gas/BTEX

	TPHdx	Pb	Cd	Cr	Hg	As	VOC BTEX
1	X	X	X	X	X	X	
2	X	X	X	X	X	X	
2a							X



- Observed standing H_2O in TA area & TA oil H_2O/seeping sheen.
- Spoke w/ Brad Thompson who

Rev081403AE:jsf

SERVICE RECORD

SNOHOMISH HEALTH DISTRICT
ENVIRONMENTAL HEALTH

SITE ADDRESS

COMPLAINT NO. PTA NO.

Date	Notes	Recorded by	Title
11/13/07	Witnessed TC sample event.		
	-Explained TC IF process.		
	-Explained TC SHA/Ranking process.		
	Bruce Noted That TC owners were committed to operating a 'clean' operation and would be interested in making changes.		
	- While @ TC site TC spill was to TC stream - off-site was blocked with a silt fence + straw bales to prevent standing H_2O from moving off site w/out first going Thru TC oil/H_2O sep. CB/4. (C EHS.		
11/13/07	TC to Steve Batch @ SW. Co shirt Hat Refused to WDOE - Megan Wisdom - also noted That TC site is in Lynnwood.		
11/13/07.	TC to Megan Wisdom. (C EHS		

Rev081403AE:jsf

SERVICE RECORD

SNOHOMISH HEALTH DISTRICT
ENVIRONMENTAL HEALTH

SITE ADDRESS 18306 Hwy 99 Lynnwood

COMPLAINT NO. 070988 PTA NO. 00374300300400

Date	Notes	Recorded by	Title
11/27/07.	CCS 7 due to no ~~test~~ results on This Date. CCEHS.		
12/3/07.	Test Results indicate ↑ levels of Cd + ↑ levels of TPH heavy oil. See results. Recommend listing on CSCS for MTCA Exceedance of Cd + TPH Heavy Oil. CCEHS		
12/14/07	TC to Bruce Thompson @ Pull apart. Informed Bruce of my plans to Recommend The Site to be listed on The CSCS Bruce plans for The contact w/ WDOE Site mgr. advised also to contact The VCP. Sent VCP Contact via Email. Also sent Public Request for info Form via Email. CCEHS.	12/18/07	

Rev/081403AE:jsf

18306 · Hy 99

Rollaway
11/5/07



11/5/07

11/5/07





PHOTO NO.	1
DATE	11/13/2007
TIME	
COMPL. NO.	600700
ADDRESS	18306 Hwy 99
	Lynnwood wa
	98037
CAMERA	Cannon s300
TAKEN BY	GWC
WITNESS	Pete Jorgenson

DESCRIPTION /COMMENTS:
Depicts the oil water separator, sampling location of #1 sample. Also depicts the spill way to the west of the oil water separator. Note the standing water at the left hand side of the photo.



PHOTO NO.	2
DATE	11/13/2007
TIME	
COMPL. NO.	600700
ADDRESS	18306 Hwy 99
	Lynnwood wa
	98037
CAMERA	Cannon s300
TAKEN BY	GWC
WITNESS	Pete Jorgenson

DESCRIPTION /COMMENTS:
Depicts the location sample 2 and 2a. This area is similar to other areas on the site in that it is unprotected with a pad and contained various chemical contaminants as well as various part from cars.

PHOTO NO.	3
DATE	11/13/2007
TIME	
COMPL. NO.	600700
ADDRESS	18306 Hwy 99
	Lynnwood wa
	98037
CAMERA	Cannon s300
TAKEN BY	GWC
WITNESS	Pete Jorgenson

DESCRIPTION /COMMENTS:
Photo depicts the southerly view of the oil water separator. Note the arrows show general flow of surface water.

PHOTO NO.	
DATE	
TIME	
COMPL. NO.	
ADDRESS	
CAMERA	
TAKEN BY	
WITNESS	

DESCRIPTION /COMMENTS:
(Start typing here)