



Practical Environmental Compliance Solutions

Offices In: Anchorage | Tacoma | Portland

July 10, 2020

Muscatel Midway Properties, LLC
Attn: Laurie Goldman
P.O. Box 826
Mercer Island, Washington 98040

Re: Correction to the Cleanup Action Report
23418 Pacific Highway South
Kent, Washington 98032

Dear Ms. Goldman:

ECI Environmental Service, Inc. (ECI) issued a Cleanup Action Report (CAR) for the property located at 23418 Pacific Highway South in Kent, Washington on December 31, 2019. Subsequent review of the CAR revealed that an inadvertent mistake was made on Figures 4 and 5 of the CAR, which are attached to the CAR under Appendix A.

Upon review of Figures 4 and 5 of the CAR, it was realized that sample locations B1-B-10', B1-ESW-5', and B1-ESW-10' were incorrectly identified on the figures. ECI reviewed the field notes recorded by ECI field technician, Brad Reilly, and spoke with Mr. Reilly concerning the sample locations. Mr. Reilly confirmed that the sample locations were in fact inadvertently placed on Figures 4 and 5, and that the locations identified in his field notes are accurate. A copy of Mr. Reilly's field notes is attached to this letter as Attachment 1.

Figures 4 and 5 to the CAR have been revised to reflect the correct sample locations, which are attached to this Correction Letter as Attachment 2, and identified as "CORRECTED Figure 4" and "CORRECTED Figure 5", and dated July 10, 2020.

Please append this Correction Letter to the CAR.

Sincerely,

A handwritten signature in blue ink that reads 'Kaden Reed'.

Kaden Reed
Sr. Environmental Professional
Direct: (253) 561-3298

ECI | Environmental Services

Office: (253) 238-9270 | Fax: (253) 369-6228 | email: info@ecocononline.com

File: Corrections to the CAR-07102020

List of Attachments

Attachment 1: Field Notes

Attachment 2: Corrected Figures

List of Attachments

KENT MUSCATTEL

B1-B-10	9:45
B1-SSW-5	9:48
B1-SSW-10	9:50
B1-NSW-10	9:55
B1-NSW-5	10:02
B1-ESW-5	10:10
B1-ESW-10	10:15





