

Nelson Consulting Engineering PS
19221 58th Ave NE
Kenmore, Washington 98028-3118

(425) 483 9126
Fax: (425) 485 1136

January 18th, 2007

Farallon Consulting
Attn: Ms. Carla Brock, Geologist
975 5th Ave NW, Issaquah, 98027
Fax: 425 295 0850

Mr. Gary Flowers
Gary Flowers PLLC
19532 12th Ave NE
Shoreline, WA 98155-1106

Subject: Evergreen Fuel retaining wall earth anchor repair
661 East Pine Street
Shelton, WA

Ms. Brock and Mr. Flowers:

I have reviewed the photographs provided by the contractor on the installation of the Grid B concrete earth anchors. They show the construction of earth anchors considerably larger than suggested by this office. Their installation is sufficient to allow the abandonment of the Grid C earth anchors with no reduction in the original capacity of the grid A tie back retaining wall.

As noted in my previous letter, a comprehensive inspection of this wall system is not within this engineer's Scope of Work, and was not performed. Refer to this letter for recommendations concerning the long term performance of this wall.

This report respectfully presented, without prejudice, by:

Jeffrey A Nelson PE SE
Principal
Nelson Consulting Engineering PS

