

UPDATE




Boeing Everett Former South Fire Pit Cleanup

At Boeing's request, Ecology granted an extension to the required schedule to investigate and clean up the Former South Fire Pit at the Everett facility. The extension was granted because of the potential presence of PFAS (per- and polyfluoroalkyl substances) in the pit.

Ecology granted a 1-year extension to allow for the development of cleanup levels for PFAS, which Ecology anticipates will be final at the end of 2022. This extension applies only to the Former South Fire Pit (SWMU/AOC No. 068) and doesn't increase risk to human health or the environment.

For more information about PFAS, please visit ecology.wa.gov/PFAS.

To learn more about the cleanup, please visit ecology.wa.gov/BoeingEverett.



Google Map of Boeing Everett's location.



DEPARTMENT OF
ECOLOGY
State of Washington

Department of Ecology
Northwest Office
15700 Dayton Ave. N.
Shoreline, WA 98133

ADA Accessibility

To request an ADA accommodation, contact Ecology by phone at 360-407-6700 or email at hwtrpubs@ecy.wa.gov, or visit ecology.wa.gov/accessibility. For Relay Service or TTY call 711 or 877-833-6341.

May 2022 | Publication 22-04-026