



Sumner National Auto Parts Site Responsiveness Summary—No Comments

Today's Date: October 25, 2022

Cleanup Site ID: 3653
Facility ID: 1304
VCP ID: SW1729
Address: 16008 60th Street East, Sumner
County: Pierce County

Ecology held a comment period from September 22 to October 23, 2022, giving the public an opportunity to comment on Ecology's proposal to remove the Site from the Hazardous Sites List.

Ecology received no public comments during the comment period. We will remove the Site from the Hazardous Sites List.

Relevant Model Toxics Control Act Cleanup Regulation: WAC 173-340-330(10)

Document providing background information during the comment period

Sumner National Auto Parts – VCP SW1729 – Site No Further Action Letter dated February 8, 2022

Site background

The site was an auto supply store and an engine rebuild and metal machine shop. Contamination at the site was likely caused by leaks of hazardous chemicals into the soil.

We ranked the site's relative risk to human health and the environment based on contamination and the location of the site. When a cleanup site is ranked, we put the site on the state's Hazardous Sites List.

About 513 tons of contaminated soil was excavated and removed from the site. After the contaminated soil was removed, tests confirmed that contaminant concentrations were below state cleanup levels.

Groundwater monitoring showed that contaminants were not present in groundwater, or present at low concentrations that are below state cleanup levels.

The cleanup is effective in protecting the health of people and the environment. We determined no further cleanup action is required.

A comment period is required before we can consider removing the site from the Hazardous Sites List.

This report prepared by

Tim Mullin, LHG
Cleanup Project Manager

Nancy Davis
Public Involvement Coordinator