

**LOWER YARD INTERIM ACTION
AS-BUILT REPORT
UNOCAL EDMONDS TERMINAL**

EDMONDS, WA

VOLUME III- APENDICES E THROUGH H

Prepared for

Unocal Corporation

November 30, 2002

Prepared by

Maul Foster & Alongi, Inc.
17171 Bothell Way N.E. #264
Seattle, Washington 98155

APPENDIX E
SOIL AND ASPHALT SHIPMENTS DOCUMENTATION



UNOCAL
#50263 / Edmonds Terminal
Export Summary

RECEIVED
JAN - 4 2002
BY: _____

	<u>Date</u>	<u>Product</u>	<u>Site</u>	<u>Hauler</u>	<u>Truck#</u>	<u>Scale/BOL Ticket #</u>	<u>Amount</u>	<u>Measure</u>
aug	8/29/01	PCS - CON	LaFarge			141306	28.35	tons
aug	8/29/01	PCS - CON	LaFarge			141307	28.25	tons
aug	8/29/01	PCS - CON	LaFarge			141320	29.98	tons
aug	8/29/01	PCS - CON	LaFarge			141321	28.31	tons
aug	8/29/01	PCS - CON	LaFarge			141330	33.30	tons
aug	8/29/01	PCS - CON	LaFarge			141332	29.99	tons
aug	8/30/01	PCS - CON	LaFarge			141371	26.14	tons
aug	8/30/01	PCS - CON	LaFarge			141376	23.11	tons
aug	8/30/01	PCS - CON	LaFarge			141385	25.98	tons
aug	8/30/01	PCS - CON	LaFarge			141389	28.48	tons
aug	8/30/01	PCS - CON	LaFarge			141390	24.60	tons
aug	8/30/01	PCS - CON	LaFarge			141395	32.08	tons
aug	8/30/01	PCS - CON	LaFarge			141401	27.37	tons
aug	8/30/01	PCS - CON	LaFarge			141402	26.55	tons
aug	8/30/01	PCS - CON	LaFarge			141416	29.94	tons
aug	8/30/01	PCS - CON	LaFarge			141421	27.68	tons
aug	8/30/01	PCS - CON	LaFarge			141422	23.77	tons
aug Total							473.88	
sept	9/5/01	PCS - CON	LaFarge			141642	25.58	tons
sept	9/5/01	PCS - CON	LaFarge			141649	27.86	tons
sept	9/5/01	PCS - CON	LaFarge			141651	26.25	tons
sept	9/5/01	PCS - CON	LaFarge			141662	25.60	tons
sept	9/5/01	PCS - CON	LaFarge			141666	26.55	tons
sept	9/5/01	PCS - CON	LaFarge			141671	25.62	tons
sept	9/5/01	PCS - CON	LaFarge			141680	24.33	tons
sept	9/5/01	PCS - CON	LaFarge			141682	25.54	tons
sept	9/5/01	PCS - CON	LaFarge			141686	25.31	tons
sept	9/6/01	PCS - CON	LaFarge	Steve Forler	33/33A	141733	31.87	tons
sept	9/6/01	PCS - CON	LaFarge	Steve Forler	S608	141743	27.96	tons
sept	9/6/01	PCS - CON	LaFarge	Steve Forler	A103	141744	34.70	tons
sept	9/6/01	PCS - CON	LaFarge	Steve Forler	33/33A	141755	36.59	tons
sept	9/6/01	PCS - CON	LaFarge	Steve Forler	S608	141762	31.99	tons
sept	9/6/01	PCS - CON	LaFarge	Steve Forler	A103	141765	34.02	tons
sept	9/6/01	PCS - CON	LaFarge	Steve Forler	33/33A	141773	36.87	tons
sept	9/6/01	PCS - CON	LaFarge			141780	31.98	tons
sept	9/6/01	PCS - CON	LaFarge	Steve Forler	A103	141781	35.12	tons
sept	9/7/01	PCS - CON	LaFarge	Steve Forler	Trucking	141828	36.97	tons
sept	9/7/01	PCS - CON	LaFarge	Steve Forler	A103	141829	35.28	tons
sept	9/7/01	PCS - CON	LaFarge	Steve Forler	Trucking	141840	32.54	tons
sept	9/7/01	PCS - CON	LaFarge	Steve Forler	A103	141844	35.23	tons
sept	9/7/01	PCS - CON	LaFarge	Steve Forler	Trucking	141856	34.88	tons
sept	9/7/01	PCS - CON	LaFarge	Steve Forler	A103	141861	34.91	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler	Trucking	141949	36.00	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler	6	141952	38.76	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler	Trucking	141954	40.70	tons

UNOCAL
#50263 / Edmonds Terminal
Export Summary

	<u>Date</u>	<u>Product</u>	<u>Site</u>	<u>Hauler</u>	<u>Truck#</u>	<u>Scale/BOL</u> <u>Ticket #</u>	<u>Amount</u>	<u>Measure</u>
sept	9/10/01	PCS - CON	LaFarge	Steve Forler Trucking		141957	32.88	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler Trucking		141971	37.77	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler 6		141979	36.60	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler Trucking		141982	36.36	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler Trucking		141983	34.07	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler Trucking		141993	38.25	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler 6		141997	35.15	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler Trucking		141998	33.27	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler Trucking		142000	36.30	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler Trucking		142006	37.03	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler Trucking		142008	34.95	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler 6		142010	36.09	tons
sept	9/10/01	PCS - CON	LaFarge	Steve Forler Trucking		142011	33.65	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142053	38.12	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142060	33.54	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142061	34.02	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142063	29.88	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142066	38.45	tons
sept	9/11/01	PCS - CON	LaFarge			142071	26.33	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142076	28.84	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142077	31.35	tons
sept	9/11/01	PCS - CON	LaFarge			142078	34.04	tons
sept	9/11/01	PCS - CON	LaFarge			142081	27.44	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142082	34.15	tons
sept	9/11/01	PCS - CON	LaFarge			142084	35.89	tons
sept	9/11/01	PCS - CON	LaFarge			142087	31.12	tons
sept	9/11/01	PCS - CON	LaFarge			142089	31.35	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142093	34.66	tons
sept	9/11/01	PCS - CON	LaFarge			142094	30.49	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142097	33.64	tons
sept	9/11/01	PCS - CON	LaFarge			142098	30.32	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142099	35.78	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142104	38.45	tons
sept	9/11/01	PCS - CON	LaFarge			142105	30.29	tons
sept	9/11/01	PCS - CON	LaFarge			142106	29.37	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142108	34.02	tons
sept	9/11/01	PCS - CON	LaFarge			142111	28.73	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142112	32.61	tons
sept	9/11/01	PCS - CON	LaFarge			142113	29.43	tons
sept	9/11/01	PCS - CON	LaFarge	Steve Forler Trucking		142119	34.05	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142155	36.26	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142158	38.02	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142160	34.56	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142164	36.12	tons
sept	9/12/01	PCS - CON	LaFarge			142169	35.58	tons
sept	9/12/01	PCS - CON	LaFarge			142176	35.34	tons

UNOCAL
#50263 / Edmonds Terminal
Export Summary

	<u>Date</u>	<u>Product</u>	<u>Site</u>	<u>Hauler</u>	<u>Truck#</u>	<u>Scale/BOL</u>	<u>Amount</u>	<u>Measure</u>
						<u>Ticket #</u>		
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142178	37.06	tons
sept	9/12/01	PCS - CON	LaFarge			142182	32.78	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142183	31.55	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142184	33.09	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142190	35.16	tons
sept	9/12/01	PCS - CON	LaFarge			142191	32.94	tons
sept	9/12/01	PCS - CON	LaFarge			142192	29.80	tons
sept	9/12/01	PCS - CON	LaFarge			142193	32.34	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142201	37.55	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142202	37.80	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142206	33.99	tons
sept	9/12/01	PCS - CON	LaFarge			142208	34.76	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142209	35.65	tons
sept	9/12/01	PCS - CON	LaFarge			142213	35.83	tons
sept	9/12/01	PCS - CON	LaFarge			142214	37.90	tons
sept	9/12/01	PCS - CON	LaFarge			142215	31.52	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142221	37.40	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142222	39.88	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142224	34.64	tons
sept	9/12/01	PCS - CON	LaFarge			142226	32.58	tons
sept	9/12/01	PCS - CON	LaFarge	Steve Forler Trucking		142227	36.34	tons
sept	9/12/01	PCS - CON	LaFarge			142229	40.35	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142270	33.89	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142274	33.29	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142277	38.65	tons
sept	9/13/01	PCS - CON	LaFarge			142281	25.39	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142284	37.90	tons
sept	9/13/01	PCS - CON	LaFarge			142287	37.87	tons
sept	9/13/01	PCS - CON	LaFarge			142292	30.66	tons
sept	9/13/01	PCS - CON	LaFarge			142293	32.58	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142294	36.04	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142296	34.54	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142301	38.37	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142304	38.90	tons
sept	9/13/01	PCS - CON	LaFarge			142307	29.59	tons
sept	9/13/01	PCS - CON	LaFarge			142309	33.22	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142310	34.42	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142313	34.60	tons
sept	9/13/01	PCS - CON	LaFarge			142314	34.53	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142323	36.76	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142324	36.57	tons
sept	9/13/01	PCS - CON	LaFarge			142326	28.64	tons
sept	9/13/01	PCS - CON	LaFarge			142327	25.06	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142328	37.16	tons
sept	9/13/01	PCS - CON	LaFarge			142332	29.73	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142334	35.70	tons

UNOCAL
#50263 / Edmonds Terminal
Export Summary

	<u>Date</u>	<u>Product</u>	<u>Site</u>	<u>Hauler</u>	<u>Truck#</u>	<u>Scale/BOL</u> <u>Ticket #</u>	<u>Amount</u>	<u>Measure</u>
sept	9/13/01	PCS - CON	LaFarge			142336	31.89	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142339	35.26	tons
sept	9/13/01	PCS - CON	LaFarge	Steve Forler Trucking		142341	36.35	tons
sept	9/13/01	PCS - CON	LaFarge			142343	28.17	tons
sept	9/13/01	PCS - CON	LaFarge			142345	33.00	tons
sept	9/13/01	PCS - CON	LaFarge			142346	29.08	tons
sept	9/13/01	PCS - CON	LaFarge			142347	25.21	tons
sept	9/14/01	PCS - CON	LaFarge			142422	35.75	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142376	37.21	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142380	34.04	tons
sept	9/14/01	PCS - CON	LaFarge			142381	30.10	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142382	35.16	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142383	38.50	tons
sept	9/14/01	PCS - CON	LaFarge			142385	26.54	tons
sept	9/14/01	PCS - CON	LaFarge			142395	32.12	tons
sept	9/14/01	PCS - CON	LaFarge			142396	33.17	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142398	37.74	tons
sept	9/14/01	PCS - CON	LaFarge			142400	33.38	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142403	32.61	tons
sept	9/14/01	PCS - CON	LaFarge			142404	34.95	tons
sept	9/14/01	PCS - CON	LaFarge			142406	26.44	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142408	37.53	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142411	37.32	tons
sept	9/14/01	PCS - CON	LaFarge			142413	34.59	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142418	37.28	tons
sept	9/14/01	PCS - CON	LaFarge			142419	36.34	tons
sept	9/14/01	PCS - CON	LaFarge			142420	32.15	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142424	33.12	tons
sept	9/14/01	PCS - CON	LaFarge			142430	38.68	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142432	37.84	tons
sept	9/14/01	PCS - CON	LaFarge			142436	30.63	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142439	36.50	tons
sept	9/14/01	PCS - CON	LaFarge			142440	28.11	tons
sept	9/14/01	PCS - CON	LaFarge	Steve Forler Trucking		142444	37.30	tons
sept	9/14/01	PCS - CON	LaFarge			142447	31.29	tons
sept	9/14/01	PCS - CON	LaFarge			142449	33.25	tons
sept	9/14/01	PCS - CON	LaFarge			142451	29.30	tons
sept	9/14/01	PCS - CON	LaFarge			142452	31.83	tons
sept	9/14/01	PCS - CON	LaFarge			142454	33.61	tons
sept	9/14/01	PCS - CON	LaFarge			142455	25.21	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142496	38.71	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142498	32.65	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142500	36.99	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142504	37.53	tons
sept	9/17/01	PCS - CON	LaFarge			142509	31.37	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142517	36.98	tons

UNOCAL
#50263 / Edmonds Terminal
Export Summary

	<u>Date</u>	<u>Product</u>	<u>Site</u>	<u>Hauler</u>	<u>Truck#</u>	<u>Scale/BOL Ticket #</u>	<u>Amount</u>	<u>Measure</u>
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142521	35.46	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142523	31.23	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142525	36.61	tons
sept	9/17/01	PCS - CON	LaFarge			142530	34.26	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142540	38.55	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142542	33.94	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142545	31.41	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142548	36.28	tons
sept	9/17/01	PCS - CON	LaFarge			142551	34.36	tons
sept	9/17/01	PCS - CON	LaFarge			142553	28.75	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142558	39.41	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142562	30.57	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142565	34.19	tons
sept	9/17/01	PCS - CON	LaFarge	Steve Forler Trucking		142566	34.32	tons
sept	9/17/01	PCS - CON	LaFarge			142569	29.78	tons
sept	9/17/01	PCS - CON	LaFarge			142570	25.74	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142618	31.48	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142620	38.18	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142638	33.84	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142641	37.58	tons
sept	9/18/01	PCS - CON	LaFarge			142643	39.40	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142653	37.39	tons
sept	9/18/01	PCS - CON	LaFarge			142656	37.62	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142658	39.45	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142659	34.27	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142660	36.63	tons
sept	9/18/01	PCS - CON	LaFarge			142663	35.35	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142665	40.62	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142671	39.46	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142673	34.30	tons
sept	9/18/01	PCS - CON	LaFarge	Steve Forler Trucking		142674	38.36	tons
sept	9/18/01	PCS - CON	LaFarge			142677	34.92	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142715	33.87	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142718	37.43	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142720	29.25	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler 301		142724	28.73	tons
sept	9/19/01	PCS - CON	LaFarge			142727	32.80	tons
sept	9/19/01	PCS - CON	LaFarge			142728	29.82	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142737	33.30	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142740	38.88	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142744	29.19	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler 301		142748	30.52	tons
sept	9/19/01	PCS - CON	LaFarge			142752	32.52	tons
sept	9/19/01	PCS - CON	LaFarge			142754	32.27	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142759	32.47	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142761	36.46	tons

UNOCAL
 #50263 / Edmonds Terminal
 Export Summary

Date	Product	Site	Hauler	Truck#	Scale/BOL	Amount	Measure	
					Ticket #			
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142764	25.71	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler 301		142769	31.04	tons
sept	9/19/01	PCS - CON	LaFarge			142771	33.69	tons
sept	9/19/01	PCS - CON	LaFarge	258		142773	31.03	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142777	32.34	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142779	36.06	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler Trucking		142782	29.88	tons
sept	9/19/01	PCS - CON	LaFarge	Steve Forler 301		142783	31.26	tons
sept	9/20/01	PCS - CON	LaFarge			142834	31.71	tons
sept	9/20/01	PCS - CON	LaFarge			142837	30.54	tons
sept	9/20/01	PCS - CON	LaFarge			142851	30.39	tons
sept	9/20/01	PCS - CON	LaFarge			142852	33.96	tons
sept	9/20/01	PCS - CON	LaFarge			142862	32.03	tons
sept	9/20/01	PCS - CON	LaFarge			142863	29.66	tons
sept	9/21/01	PCS - CON	LaFarge			142888	32.44	tons
sept	9/21/01	PCS - CON	LaFarge			142890	38.55	tons
sept	9/21/01	PCS - CON	LaFarge	Steve Forler Trucking		142894	32.36	tons
sept	9/21/01	PCS - CON	LaFarge			142895	30.33	tons
sept	9/21/01	PCS - CON	LaFarge			142896	32.96	tons
sept	9/21/01	PCS - CON	LaFarge			142899	31.89	tons
sept	9/21/01	PCS - CON	LaFarge			142911	28.04	tons
sept	9/21/01	PCS - CON	LaFarge			142917	33.61	tons
sept	9/21/01	PCS - CON	LaFarge			142919	30.66	tons
sept	9/21/01	PCS - CON	LaFarge			142921	28.43	tons
sept	9/21/01	PCS - CON	LaFarge			142925	28.52	tons
sept	9/21/01	PCS - CON	LaFarge			142934	24.85	tons
sept	9/21/01	PCS - CON	LaFarge			142936	32.31	tons
sept	9/21/01	PCS - CON	LaFarge			142938	30.95	tons
sept	9/21/01	PCS - CON	LaFarge			142940	36.45	tons
sept	9/21/01	PCS - CON	LaFarge			142943	29.17	tons
sept	9/21/01	PCS - CON	LaFarge	Steve Forler Trucking		142949	30.34	tons
sept	9/21/01	PCS - CON	LaFarge			142953	27.12	tons
sept	9/21/01	PCS - CON	LaFarge			142954	30.87	tons
sept	9/21/01	PCS - CON	LaFarge			142955	30.16	tons
sept	9/24/01	PCS - CON	LaFarge			143014	30.03	tons
sept	9/24/01	PCS - CON	LaFarge			143016	33.43	tons
sept	9/24/01	PCS - CON	LaFarge			143042	33.12	tons
sept	9/24/01	PCS - CON	LaFarge			143046	33.42	tons
sept	9/24/01	PCS - CON	LaFarge			143063	33.73	tons
sept	9/24/01	PCS - CON	LaFarge			143071	28.57	tons
sept	9/24/01	PCS - CON	LaFarge			143075	30.87	tons
sept	9/25/01	PCS - CON	LaFarge			143097	29.34	tons
sept	9/25/01	PCS - CON	LaFarge			143099	28.83	tons
sept	9/25/01	PCS - CON	LaFarge			143107	32.77	tons
sept	9/25/01	PCS - CON	LaFarge			143117	26.36	tons
sept	9/25/01	PCS - CON	LaFarge			143119	21.89	tons

UNOCAL
 #50263 / Edmonds Terminal
 Export Summary

	Date	Product	Site	Hauler	Truck#	Scale/BOL	Amount	Measure
						Ticket #		
sept	9/25/01	PCS - CON	LaFarge			143127	27.61	tons
sept	9/25/01	PCS - CON	LaFarge			143136	27.50	tons
sept	9/25/01	PCS - CON	LaFarge			143138	27.44	tons
sept	9/25/01	PCS - CON	LaFarge			143144	31.61	tons
sept	9/25/01	PCS - CON	LaFarge			143152	29.71	tons
sept	9/25/01	PCS - CON	LaFarge			143153	27.11	tons
sept	9/26/01	PCS - CON	LaFarge			143188	24.83	tons
sept	9/26/01	PCS - CON	LaFarge			143195	25.94	tons
sept	9/26/01	PCS - CON	LaFarge			143196	15.66	tons
sept	9/26/01	PCS - CON	LaFarge			143215	30.51	tons
sept	9/26/01	PCS - CON	LaFarge			143227	29.13	tons
sept	9/27/01	PCS - CON	LaFarge			143291	29.37	tons
sept	9/27/01	PCS - CON	LaFarge			143314	28.46	tons
sept	9/28/01	PCS - CON	LaFarge			143388	17.20	tons
sept Total							8916.34	
oct	10/9/01	PCS - CON	LaFarge			143919	30.36	tons
oct	10/9/01	PCS - CON	LaFarge			143921	26.36	tons
oct	10/9/01	PCS - CON	LaFarge			143924	30.16	tons
oct	10/9/01	PCS - CON	LaFarge			143939	38.03	tons
oct	10/9/01	PCS - CON	LaFarge			143941	30.34	tons
oct	10/9/01	PCS - CON	LaFarge			143943	31.34	tons
oct	10/9/01	PCS - CON	LaFarge			143949	34.39	tons
oct	10/9/01	PCS - CON	LaFarge			143952	31.77	tons
oct	10/9/01	PCS - CON	LaFarge			143958	36.67	tons
oct	10/9/01	PCS - CON	LaFarge			143965	37.30	tons
oct	10/10/01	PCS - CON	LaFarge			144024	38.80	tons
oct	10/10/01	PCS - CON	LaFarge			144025	34.77	tons
oct	10/10/01	PCS - CON	LaFarge			144028	31.36	tons
oct	10/10/01	PCS - CON	LaFarge			144030	29.17	tons
oct	10/11/01	PCS - CON	LaFarge			144058	31.55	tons
oct	10/11/01	PCS - CON	LaFarge			144063	27.86	tons
oct	10/11/01	PCS - CON	LaFarge			144071	28.99	tons
oct	10/11/01	PCS - CON	LaFarge			144078	27.88	tons
oct	10/11/01	PCS - CON	LaFarge			144086	31.24	tons
oct	10/11/01	PCS - CON	LaFarge			144096	29.40	tons
oct	10/11/01	PCS - CON	LaFarge			144196	30.11	tons
oct	10/16/01	PCS - CON	LaFarge			144249	27.50	tons
oct	10/16/01	PCS - CON	LaFarge			144252	23.46	tons
oct	10/16/01	PCS - CON	LaFarge			144253	25.11	tons
oct	10/16/01	PCS - CON	LaFarge			144274	30.51	tons
oct	10/16/01	PCS - CON	LaFarge			144276	23.20	tons
oct	10/16/01	PCS - CON	LaFarge			144278	29.54	tons
oct	10/16/01	PCS - CON	LaFarge			144285	36.28	tons
oct	10/16/01	PCS - CON	LaFarge			144286	26.49	tons
oct	10/16/01	PCS - CON	LaFarge			144287	31.15	tons
oct	10/19/01	PCS - CON	LaFarge			144464	28.37	tons

UNOCAL
#50263 / Edmonds Terminal
Export Summary

	<u>Date</u>	<u>Product</u>	<u>Site</u>	<u>Hauler</u>	<u>Truck#</u>	<u>Scale/BOL</u> <u>Ticket #</u>	<u>Amount</u>	<u>Measure</u>
oct	10/19/01	PCS - CON	LaFarge			144465	31.46	tons
oct	10/19/01	PCS - CON	LaFarge			144468	32.23	tons
oct	10/19/01	PCS - CON	LaFarge			144479	34.39	tons
oct	10/19/01	PCS - CON	LaFarge			144480	29.80	tons
oct	10/19/01	PCS - CON	LaFarge			144481	32.68	tons
oct	10/23/01	PCS - CON	LaFarge			144584	35.43	tons
oct	10/23/01	PCS - CON	LaFarge			144613	29.75	tons
oct	10/23/01	PCS - CON	LaFarge			144636	34.57	tons
oct	10/24/01	PCS - CON	LaFarge			144705	26.61	tons
oct	10/24/01	PCS - CON	LaFarge			144706	27.22	tons
oct	10/24/01	PCS - CON	LaFarge			144727	30.95	tons
oct	10/24/01	PCS - CON	LaFarge			144731	28.99	tons
oct	10/25/01	PCS - CON	LaFarge			144793	31.69	tons
oct	10/25/01	PCS - CON	LaFarge			144795	17.99	tons
oct Total							1373.22	
Grand Total							10763.44	

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



8/30/01
SM
ahy

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD SERVICES <i>Construction</i>		EMERALD SERVICES INC		SLI	141306
SEATTLE WA		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
600099-		0600099 002	32-50263		08/29/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011	01	TRAILER GROSS	95,300	
			TARE	38,600	
			*NET	56,700	10:11 AUG-29
			TOTAL	28.35ST	10:12 AUG-29

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	252		100	000352-186	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: Wade Spear
DRIVER: Michael S. [Signature]
CUSTOMER: [Signature]

FORM #
49764

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charge...

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



8/30/01
sm
dy

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD SERVICES <i>Construction</i>		EMERALD SERVICES INC		SLI	141307
CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE		
SEATTLE WA <i>600099 001</i>	0520056 <i>32-50263</i>		08/29/2001		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	91,460	
			TARE	34,960	10:16 AUG-29
			*NET	56,500	
			TOTAL	28.25ST	10:17 AUG-29

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	258		100	000352-187	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Wade Stearns*
DRIVER: *D. H. ...*
CUSTOMER:

FORM #
49765

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



8/30/01
SM
dry

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO) EMERALD SERVICES <i>Construction</i>		SOLD TO EMERALD SERVICES, INC		SHIPPED FROM SLI	BILL OF LADING NO. 141320
SEATTLE WA	CUSTOMER NO. <i>600099001</i>	CUSTOMER PURCHASE ORDER NO. <i>32-50263</i>	SEE B/L NO.	SHIP DATE 08/29/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 98,560 TARE 38,600 *NET 59,960	12:27 AUG-29
			TOTAL 29.98ST	12:30 AUG-29

CARRIER PICKUP	CARRIER CODE	TRUCK <input checked="" type="checkbox"/>	TRAILER 252	PUP	TRANS CODE 100	ORDER NO. <i>514</i> 000262-188	CUSTOMER REQUIRED DELIVERY
-------------------	--------------	--	----------------	-----	-------------------	--	----------------------------

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:
------------------------	-----------------	------------------	--------------	---

SHIPPER: *Sett Ward*

DRIVER: *Mike*

CUSTOMER:

FORM #
49776

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.

LAFARGE
CORPORATION
DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

8/30/01
SM
dyg

FROM

P.O. #
32-50263

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD SERVICES <i>Construction</i>		EMERALD SERVICES INC		SLL	141321
SEATTLE WA		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		002	600099 001		08/29/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	91,580	12:46 AUG-29
			TARE	34,960	
			*NET	56,620	
			TOTAL	28.318T	12:47 AUG-29

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	258		100	000362-189	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Scott Ward*

DRIVER: *S. K. O.*

CUSTOMER:

FORM #
49778

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141330
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060095		32-50263			08/29/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 105,200 TARE 38,600 *NET 66,600	14:39 AUG-29
			TOTAL 33,30ST	14:49 AUG-29

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		252	252		100	000516-001	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
49785

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141332
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			08/29/11
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	94,940	
			TARE	34,960	15:12 AUG-29
			*NET	59,980	
			TOTAL	29.995T	15:13 AUG-29

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		258	258		100	000516-008	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
49786

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50463

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141371
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		08/30/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTMNATED SOIL	AM-0011		TRAILER GROSS	87,300	08:28 AUG-30 08:28 AUG-30
			TARE	35,020	
			*NET	52,280	
			TOTAL	26.14ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	KP1		100	000516-003	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
[Signature]
DRIVER:
[Signature]
CUSTOMER:

FORM #
49825

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

CUSTOMER

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-5026

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141376
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		001 32-50263			08/30

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	82,700	
			TARE	36,480	09:13 AUG-3
			*NET	46,220	
			TOTAL	23.11ST	09:14 AUG-3

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	04		100	000516-004	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
49828

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

CUSTOMER

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue. Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned, destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141385
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			08/30/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	93,300	10:14 AUG-30 10:14 AUG-30
			TARE	41,340	
			*NET	51,960	
			TOTAL	25.98ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	15		100	000516-005	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
49836

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

CUSTOMER

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION		SLL	141389
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600095 001		32-50263			08/30/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	95,560	
			TARE	38,600	
			*NET	56,960	10:33 AUG-30
			TOTAL	28.48ST	10:34 AUG-30

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	252		100	000516-006	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED.		

Job # 32-50263

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
49841

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141390
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		08/30/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	84,160	
			TARE	34,960	10:37 AUG-30
			*NET	49,200	
			TOTAL	24.60ST	10:38 AUG-30

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	258		100	000516-007	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

REW

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
49842

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

CUSTOMER

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141395
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		08/30/11	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,180	11:22 AUG-30 11:22 AUG-30
			TARE	35,020	
			*NET	64,160	
			TOTAL	32,085T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	KP1		100	000516-008	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
49848

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

CUSTOMER

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-5046

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are property described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141401
CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE		
0600095 001	32-50263		08/30/2001		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	91,440	12:23 AUG-30 12:23 AUG-30
			TARE	36,700	
			*NET	54,740	
			TOTAL	27,375	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	JRF 4		100	000516-009	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
49853

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

CUSTOMER

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	141402
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		08/30/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	94,480	12:28 AUG-30 12:28 AUG-30
			TARE	41,380	
			*NET	53,100	
			TOTAL	26,55ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	15		100	000516-010	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Scott W. ...*

DRIVER: *Dung*

CUSTOMER: _____

FORM #
49854

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

CUSTOMER

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141416
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			08/30/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTMNATED SOIL	AM-0011		TRAILER GROSS	94,900	14:17 AUG-30
			TARE	35,020	
			*NET	59,880	
			TOTAL	29.945T	14:18 AUG-30

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	KP1		100	000516-011	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
49866

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

CUSTOMER

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

30-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	141421
CUSTOMER NO. 0600095 001		CUSTOMER PURCHASE ORDER NO. 32-50263		SEE B/L NO.	SHIP DATE 08/30 01

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	91,840	
			TARE	36,480	15:14 AUG-3
			*NET	55,360	
			TOTAL	27.68ST	15:15 AUG-3

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		04	04		100	002516-012	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
49869

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

CUSTOMER

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141422
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			08/30/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	88,920	
			TARE	41,380	
			*NET	47,540	15:41 AUG-30
			TOTAL	23.775T	15:41 AUG-30

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		15	15		100	000516-013	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
49870

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

CUSTOMER

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

39-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	141642
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/05/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	92,540	
			TARE	41,380	
			*NET	51,160	08:48 SEP-05
			TOTAL	25.58ST	08:50 SEP-05

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
DICKUP			15		100	002516-014	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
50070

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received, subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosive, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 1343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141649
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600095 001	32-50263		09/05/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO				LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		LBS			09:43 SEP-05
			TRAILER GROSS	92,520		
			TARE	36,800		
			*NET	55,720		
			TOTAL	27,865T	09:43 SEP-05	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		9	9		100	000516-015	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____

DRIVER: *Joe Comstock*

CUSTOMER: *Joe Comstock*

FORM #
50076

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
SHIPPED TO (CONSIGNEE TO)		EMERALD CONSTRUCTION		SLI	141651
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/05/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	87,850	
			TARE	35,360	09:55 SEP-05
			*NET	52,500	09:55 SEP-05
			TOTAL	26.255T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
						100 000516-016	

PICKUP RAIL ROUTE DESCRIPTION 1 RAIL ROUTE CODE 01 TRAILER SEAL NO. PUP SEAL NO. RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *D. Ryker*

DRIVER: *W. [Signature]*

CUSTOMER:

FORM #
50078

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

I shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	141662
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/05/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	92,580	
			TARE	41,380	11:10 SEP-05
			*NET	51,200	
			TOTAL	25.60ST	11:10 SEP-05

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	15			100 000516-017	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]
DRIVER:
[Signature]
CUSTOMER:
[Signature]

FORM #
50086

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

30-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	141666
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		001	32-50263	09/05/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	89,900	
			TARE	36,800	
			*NET	53,100	12:02 SEP-05
			TOTAL	26,55ST	12:03 SEP-05

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		009	009		100	000516-018	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

141 666

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50089

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper: _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING

SHIPPED TO (CONSIGNEE TO)	SOLD TO	SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108	EMERALD CONSTRUCTION	SLI	141671
	CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.
	0600099	001	32-50263
			SHIP DATE
			09/05/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		
		TRAILER GROSS	12:23 SEP-05
		TARE	12:23 SEP-05
		*NET	
		TOTAL	
		LBS	
		86,600	
		35,360	
		51,240	
		25,62ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		01	01			100 000516-019	
RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:			

SHIPPER: Wade Shearn
DRIVER: Warner
CUSTOMER:

FORM # 50094

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE OF

SEATTLE (SHIPPER'S ADDRESS)		SOLD TO		SHIPPED FROM	BILL OF LADING NO. 1
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE		EMERALD CONSTRUCTION CUSTOMER NO. 0600099		SL	141680
PRODUCT DESCRIPTION		PRODUCT CODE	SILO	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.
CONTAMINATED SOIL		AM-0011	001	32-50263	
				LBS	LOAD TIME DATED
				TRAILER GROSS 90,040	13:39 SEP-05
				TARE 41,380	
				*NET 48,660	13:40 SEP-05
				TOTAL 24.335T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		
P1		17	15				

SHIPPER: Wade Shearn
DRIVER: [Signature]
CUSTOMER: [Signature]

FORM # 50102

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32 50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE OF

SEATTLE WA PROCESSING	SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE	EMERALD CONSTRUCTION CUSTOMER NO.	SL	141682	
	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
	0600099			

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	001	32-50263	LOADING DATE
CONTAMINATED SOIL	AM-0011			LBS	
			TRAILER GROSS	87,880	
			TARE	36,800	
			*NET	51,080	14:07 SEP-05
			TOTAL	25.54ST	14:07 SEP-05

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICHAIR							
RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN ACCORDANCE WITH ORDER EXCEPT AS NOTED: 14:07 SEP-05			

SHIPPER: *Wadey Shoen*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50104

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32 50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE OF

SEATTLE SHIPPER (CONSIGNEE)			SOLD TO			SHIPPED FROM	BILL OF LADING NO. 1	
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE			EMERALD CONSTRUCTION			SLL	141686	
CUSTOMER NO. 0600099			CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE		
PRODUCT DESCRIPTION	PRODUCT CODE	SILO	001 32-50263				LOAD TIME/DATE	
CONTAMINATED SOIL	AM-0011		LBS					
			TRAILER GROSS	85,980				
			TARE	35,360				
			*NET	50,620	14:31 SEP-05			
			TOTAL	25.31ST	14:32 SEP-05			
CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN FULL BY REFERENCE AS NOTED:			
					SHIPPER: <i>Wade Spears</i> DRIVER: <i>Warrin</i> CUSTOMER:			

FORM #
50107

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

I shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

	BILL OF LADING NUMBER
--	-----------------------

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	141733
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/06/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	101,640	09:13 SEP-06 09:14 SEP-06
			TARE	37,900	
			*NET	63,740	
			TOTAL	31.875T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		33	33		100	000516-023	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Mark S, SF#33

DRIVER:
[Signature]

CUSTOMER:

FORM #
50151

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141743
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/06/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	90,460	
			TARE	34,540	10:12 SEP-06
			*NET	55,920	
			TOTAL	27.96ST	10:12 SEP-06

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	608		100	000516-024	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

141743

SHIPPER: *[Signature]*
DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
50161

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE OF

SEATTLE SHIPPED TO (CONSIGNEE)			SOLD TO			SHIPPED FROM	BILL OF LADING NO. 1
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE			CONSTRUCTION			SL	141744
CUSTOMER PURCHASE ORDER NO. 0600099			SEE B/L NO.			SHIP DATE	
PRODUCT DESCRIPTION	PRODUCT CODE	SILG	001 32-50263			LOAD TIME/DATE	
CONTAMINATED SOIL	AM-0011		LBS				
			TRAILER GROSS	106,000			
			TARE	36,600			
			*NET	69,400	10:17 SEP-06		
			TOTAL	34,70ST	10:17 SEP-06		
CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP							
RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED: 000516-125			
	103	103					

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
50162

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	141755
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/06/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTMATED SOIL	AM-0011		TRAILER GROSS	111,000	
			TARE	37,900	11:30 SEP-06
			*NET	73,100	
			TOTAL	36.59ST	11:31 SEP-06

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		33	33		100	000516-026	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
50172

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT, OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32 50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon; in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141762
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/06/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,520	12:43 SEP-06 12:43 SEP-06
			TARE	34,540	
			*NET	63,980	
			TOTAL	31.995T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	608		100	000516-027	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Wade Stearns*
DRIVER: *Jay D. Conroy # 608*
CUSTOMER:

FORM #
50177

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141765
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600039 001	32-50263		09/06/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	104,640	
			TARE	36,600	13:00 SEP-06
			*NET	68,040	
			TOTAL	34,025T	13:01 SEP-06

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	103		100	000516-028	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50179

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING			SOLD TO			SHIPPED FROM	BILL OF LADING NO.
SHIPPED TO (CONSIGNEE TO)			EMERALD CONSTRUCTION			SLI	141773
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)			CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
			0600039 001	32-50263		09/08/2001	
PRODUCT DESCRIPTION			PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL			AM-0011		TRAILER GROSS 111,640 TARE 37,900 *NET 73,740 TOTAL 36.875T		13:56 SEP-06 13:57 SEP-06
CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-029	
RAIL ROUTE DESCRIPTION			RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:	
						SHIPPER: <i>[Signature]</i> DRIVER: <i>[Signature]</i> CUSTOMER:	

FORM #
50185

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION CUSTOMER NO. 0600095 001		SLI	141780
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		32-50263		09/06/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,500	
			TARE	34,540	
			*NET	63,960	15:33 SEP-06
			TOTAL	31.98ST	15:34 SEP-06

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-030	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature] # 608

CUSTOMER:

FORM #
50190

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING			SOLD TO			SHIPPED FROM	BILL OF LADING NO.	
SHIPPED TO (CONSIGNEE TO)			EMERALD CONSTRUCTION			SLI	141781	
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -			CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE		
			0600099 001	32-50263		09/06/2001		
PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS				LOAD TIME/DATE	
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	106,840			15:38 SEP-06	
			TARE	36,600				
			*NET	70,240			15:39 SEP-06	
			TOTAL	35.12ST				
CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY	
PICKUP		103	A-103		100	000516-031		
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:			

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
70191

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141828
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/07/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,840	09:04 SEP-07 09:04 SEP-07
			TARE	37,900	
			*NET	73,940	
			TOTAL	36.97ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-032	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50239

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141829
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/07/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	107,160	09:11 SEP-07 09:12 SEP-07
			TARE	36,600	
			*NET	70,560	
			TOTAL	35.28ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	103		100	000516-033	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
Wade Mean
DRIVER:

CUSTOMER:
[Signature]

FORM #
50240

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-08263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	141840
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/07/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	102,980	11:03 SEP-07
			TARE	37,900	
			*NET	65,080	
			TOTAL	32.54ST	11:03 SEP-07

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-034	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50252

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

CARRIER LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

I shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141844
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/07/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	107,060	
			TARE	36,600	11:25 SEP-07
			*NET	70,460	
			TOTAL	35.235T	11:26 SEP-07

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	103		100	000516-035	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
K. Woodbury

DRIVER:
[Signature]

CUSTOMER:
[Signature]

FORM #
50256

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

52-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	141856
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		001	32-50263	09/07/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	107,660	
			TARE	37,900	13:18 SEP-07
			*NET	69,760	
			TOTAL	34.88ST	13:19 SEP-07

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-036	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Wade Allen
DRIVER:
CUSTOMER:

FORM #
50266

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

32-50263

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141861
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099 001		32-50263			09/07/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	106,420	
			TARE	36,600	
			*NET	69,820	13:35 SEP-07
			TOTAL	34,918T	13:36 SEP-07

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	103		100	000516-037	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
Wade Shearer
DRIVER:
[Signature]
CUSTOMER:

FORM #
50271

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141949
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/10/71

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTMNATED SOIL	AM-0011		TRAILER GROSS	109,900	08:21 SEP-10 08:22 SEP-10
			TARE	37,300	
			*NET	72,000	
			TOTAL	35,00ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-038	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]
DRIVER:
[Signature]
CUSTOMER:

FORM #
50361

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142078
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	102,720	11:23 SEP-11
			TARE	34,640	
			*NET	68,080	
			TOTAL	34,045T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	608		100	000516-062	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
D. Ryker

DRIVER:
Jay Wong

CUSTOMER:

FORM #
50481

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	142077
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099 001		32-50263		09/11/11	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	101,400	11:11 SEP-11 11:11 SEP-11
			TARE	38,700	
			*NET	62,700	
			TOTAL	31.35ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	17		100	000516-061	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50480

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN:

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s), transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142076
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/11/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,400	10:54 SEP-11
			TARE	39,720	
			*NET	57,680	
			TOTAL	28.84ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	I-4		100	000516-060	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Wade Stearn
DRIVER:
Ray S. Taylor
CUSTOMER:

FORM #
50479

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142071
CUSTOMER NO. 0600099 001		CUSTOMER PURCHASE ORDER NO. 32-50263		SEE B/L NO.	SHIP DATE 09/11/78

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	88,480	10:07 SEP-11 10:07 SEP-11
			TARE	35,820	
			*NET	52,660	
			TOTAL	26.33ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	A1		100	000516-059	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50475

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142066
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	114,800	09:38 SEP-11 09:38 SEP-11
			TARE	37,900	
			*NET	76,900	
			TOTAL	38.45ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		33	33		100	000516-059	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50470

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142063
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/11/8	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 98,460 TARE 38,700 *NET 59,760	09:05 SEP-11
			TOTAL 29.88ST	09:06 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	17		100	000516-057	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
Wade Mean
DRIVER:
[Signature]
CUSTOMER:

FORM #
50467

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142061
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600095		32-50263		09/11/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	107,440	08:46 SEP-11
			TARE	39,400	
			*NET	68,040	
			TOTAL	34,025T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	B1		100	000516-056	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50465

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142060
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099 001		32-50263		09/11/11	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	101,720	08:41 SEP-11
			TARE	34,640	
			*NET	67,080	
			TOTAL	33,545T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	608		100	000516-055	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *Wade Munn*
DRIVER: *Gregory D. Curran*
CUSTOMER: _____

FORM #
50464

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142053
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		060099 001	32-50263		09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	114,140	
			TARE	37,900	
			*NET	76,240	07:33 SEP-11
			TOTAL	38.12ST	07:33 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	33		100	000516-054	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *D. Ryker*

DRIVER: *Mark S. SFT*

CUSTOMER:

FORM #
50458

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142011
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/10/21	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	101,840	16:16 SEP-10 16:17 SEP-10
			TARE	34,540	
			*NET	67,300	
			TOTAL	33.65ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-053	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
50417

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142010
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
050095 001		32-50263		09/10/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	110,180	15:59 SEP-10 15:59 SEP-10
			TARE	38,000	
			*NET	72,180	
			TOTAL	36.09ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		E	E		100	000516-052	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
50416

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		BL	142008
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/10/11	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	108,600	15:51 SEP-10
			TARE	38,700	
			*NET	69,900	
			TOTAL	34,955T	15:51 SEP-10

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		17	SF17		100	000516-051	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
50414

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142006
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/10/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 111,960 TARE 37,900 *NET 74,060 TOTAL 37.03ST	15:13 SEP-10 15:13 SEP-10

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		33	33		100	000516-050	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
50412

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading. The property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SL	142000
CUSTOMER NO. 0600099 001		CUSTOMER PURCHASE ORDER NO. 32-50263	SEE B/L NO.	SHIP DATE 09/10/71	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,300	13:55 SEP-10 13:57 SEP-10
			TARE	38,700	
			*NET	72,600	
			TOTAL	36.30ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		17	17		100	000516-049	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50407

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141998
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		060099 001	32-50263		09/10/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	101,000	13:46 SEP-10 13:46 SEP-10
			TARE	34,540	
			*NET	66,540	
			TOTAL	33,275T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-048	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
50405

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141997
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/10/2	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	108,300	13:39 SEP-10
			TARE	38,000	
			*NET	70,300	
			TOTAL	35.15ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		6	6		100	000516-047	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *K. McElroy*
DRIVER: *M. McElroy*
CUSTOMER:

FORM #
50404

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	141993
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/10/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	114,400	13:11 SEP-10
			TARE	37,900	
			*NET	76,500	
			TOTAL	38,255T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		33	33		100	000516-048	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
E0401

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141983
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/10/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	102,680	
			TARE	34,540	
			*NET	68,140	11:49 SEP-10
			TOTAL	34.07ST	11:49 SEP-10

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	608		100	000516-045	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Dryden*

DRIVER: *Jay J. Corry*

CUSTOMER: _____

FORM #
50391

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	141982
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600095 001	32-50263		09/10/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,420	11:42 SEP-10
			TARE	38,700	
			*NET	72,720	
			TOTAL	36.365T	11:43 SEP-10

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	17		100	000516-044	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50390

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	141979
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/10/00
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 111,200 TARE 38,000 *NET 73,200	11:38 SEP-10
			TOTAL 36.60ST	11:39 SEP-10

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	6		100	000516-043	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *D. Ryker*

DRIVER: *M. [Signature]*

CUSTOMER:

FORM #
50388

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	141971
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/10/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	113,440	11:11 SEP-10 11:12 SEP-10
			TARE	37,900	
			*NET	75,540	
			TOTAL	37.77ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-042	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
30381

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE. USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 () -		EMERALD CONSTRUCTION		SLL	141957
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/10/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,300	09:18 SEP-10 09:19 SEP-10
			TARE	34,540	
			*NET	65,760	
			TOTAL	32.88ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	608		100	000516-041	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Jay D Corry
DRIVER:
D. Ryker
CUSTOMER:

FORM #
50368

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

SEATTLE CD-PROCESSING

BILL OF LADING NUMBER

1 OF 1
PAGE OF

SHIPPED TO (CONSIGNEE TO) EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		SOLD TO EMERALD CONSTRUCTION		SHIPPED FROM	BILL OF LADING NO. 141954
CUSTOMER NO. 001	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE 03/10/2001		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	120,100	08:59 SEP-10 09:01 SEP-10
			TARE	38,700	
			*NET	81,400	
			TOTAL	40,705T	

CARRIER PICKUP	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
			17			0402	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50366

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	141952
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600095 001	32-50263		09/10/8

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	115,520	
			TARE	38,000	08:40 SEP-10
			*NET	77,520	
			TOTAL	38.76ST	08:41 SEP-10

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		E	E		100	000516-039	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
50364

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

LOADING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



Received 9/21
Plung 1234

FROM

_____ []
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 () -		EMERALD CONSTRUCTION		SLI	142081
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0500099 001		32-50263			09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	92,200	11:32 SEP-11 11:33 SEP-11
			TARE	37,320	
			*NET	54,880	
			TOTAL	27,445T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	309		100	000516-063	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: *John S. Gray*
CUSTOMER: _____

FORM #
50484

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

	<div style="border: 1px solid black; width: 100px; height: 30px; margin: 0 auto;"></div> <p align="center">BILL OF LADING NUMBER</p>
SEATTLE CO-PROCESSING	PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)	SOLD TO	SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)	EMERALD CONSTRUCTION	SLL	142082
	CUSTOMER NO. 0600099 001	CUSTOMER PURCHASE ORDER NO. 32-50263	SEE B/L NO. SHIP DATE 09/11/11

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 107,700 TARE 39,400 *NET 68,300 TOTAL 34.15ST	11:36 SEP-11 11:36 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	B1		100	000516-064	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *Wade Shear*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
50485

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142084
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		060099 001	32-50263		09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	109,680	11:44 SEP-11 11:45 SEP-11
			TARE	37,900	
			*NET	71,780	
			TOTAL	35.89ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-065	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]* #33
CUSTOMER:

FORM #
50487

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading. The property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142087
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099001		32-50263			09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,140	
			TARE	37,900	
			*NET	62,240	12:04 SEP-11
			TOTAL	31.125T	12:04 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	CM4		100	000516-066	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
50489

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142089
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600093		32-50263		09/11/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,520	
			TARE	35,820	
			*NET	62,700	12:10 SEP-11
			TOTAL	31.35ST	12:10 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	A1		100	000516-067	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50490

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



17

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SILL	142093
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/11/11

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	108,020	12:56 SEP-11 12:57 SEP-11
			TARE	38,700	
			*NET	69,320	
			TOTAL	34.66ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	17		100	000516-068	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
50492

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142094
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,700	
			TARE	39,720	13:09 SEP-11
			*NET	60,980	
			TOTAL	30.49ST	13:10 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	I-4		100	000516-069	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50493

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading. The property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142097
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	101,920	
			TARE	34,640	13:23 SEP-11
			*NET	67,280	
			TOTAL	33.648T	13:24 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	608		100	000516-070	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
50495

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received, subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

I shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142098
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/11/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,960	13:30 SEP-11 13:30 SEP-11
			TARE	37,320	
			*NET	60,640	
			TOTAL	30,32ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	309		100	000516-071	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *Wade Shearn*
DRIVER: *John F. King*
CUSTOMER:

FORM #
50496

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142099
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		060099 001	32-50263		09/11/2011

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	109,460	13:45 SEP-11 13:45 SEP-11
			TARE	37,900	
			*NET	71,560	
			TOTAL	35.78ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-072	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: *[Signature]* #33
CUSTOMER: _____

FORM #
50497

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142104
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/11/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	113,120	
			TARE	36,220	14:18 SEP-11
			*NET	76,900	
			TOTAL	38.45ST	14:18 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	1		100	000516-073	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Dryden*

DRIVER: *Wyle*

CUSTOMER:

FORM #
50501

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142105
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/11/11

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,480	14:19 SEP-11
			TARE	37,900	
			*NET	60,580	
			TOTAL	30.29ST	14:20 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		i	CM4		100	000516-074	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER:

FORM #
50502

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading. The property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JDE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142106
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	94,560	
			TARE	35,820	14:24 SEP-11
			*NET	58,740	
			TOTAL	29.37ST	14:25 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	A1		100	002516-075	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Dryden*

DRIVER: *R.W.M.*

CUSTOMER:

FORM #
50503

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading. The property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142108
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099 001		32-50263		09/11/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	105,840	
			TARE	37,800	
			*NET	68,040	14:50 SEP-11
			TOTAL	34.02ST	14:51 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		17	17		100	000516-076	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
50505

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading. The property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142111
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,180	15:22 SEP-11 15:23 SEP-11
			TARE	39,720	
			*NET	57,460	
			TOTAL	28.73ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-077	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
50508

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading. The property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper: _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142112
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/11/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,840	15:32 SEP-11
			TARE	34,620	
			*NET	65,220	
			TOTAL	32.61ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-078	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
50509

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading. The property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142113
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/11/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	96,480	15:42 SEP-11
			TARE	37,620	
			*NET	58,860	
			TOTAL	29,435T	15:42 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		3009	309		100	000516-079	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50510

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading for the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142119
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	107,500	16:24 SEP-11 16:24 SEP-11
			TARE	39,400	
			*NET	68,100	
			TOTAL	34.05ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		B1	B1		100	000516-080	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50516

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
 BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142155
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/12/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	110,420	07:20 SEP-12 07:20 SEP-12
			TARE	37,900	
			#NET	72,520	
			TOTAL	36.265T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		33	33		100	000516-081	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *K. McE...*
 DRIVER: *Mark S. SA #3*
 CUSTOMER:

FORM #
50554

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142158
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/12/2011

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	113,840	07:40 SEP-12 07:40 SEP-12
			TARE	37,800	
			*NET	76,040	
			TOTAL	38.02ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		17	17		100	000516-082	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
00557

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.

9/12/01



Shipper

FROM

142160

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

69720 PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142160
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0500095 001		32-50263		09/12/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,740	
			TARE	34,620	
			*NET	69,120	07:56 SEP-12
			TOTAL	34.56ST	07:57 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	608		100	000516-083	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *D. Ryber*

DRIVER: *J. Casey*

CUSTOMER: _____

FORM #
50559

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142164
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099		32-50263		09/12/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTMNATED SOIL	AM-0011		TRAILER GROSS	111,640	
			TARE	39,400	
			*NET	72,240	08:33 SEP-12
			TOTAL	36.12ST	08:34 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	B1		100	000516-084	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Dryden

DRIVER:
Wife

CUSTOMER:

FORM #
50562

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.

LAFARGE
CORPORATION
DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142169
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099		32-50253			09/12/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	106,980	
			TARE	35,820	08:58 SEP-11
			*NET	71,160	08:59 SEP-11
			TOTAL	35.58ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	A1		100	000516-085	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50566

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142176
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600095		32-50263		09/12/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	107,280	09:35 SEP-12 09:35 SEP-12
			TARE	36,600	
			*NET	70,680	
			TOTAL	35.34ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		103	103		100	000516-088	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
 DRIVER: *Mark Pal*
 CUSTOMER: _____

FORM #
00571

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142178
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/12/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,020	09:41 SEP-12 09:42 SEP-12
			TARE	37,900	
			*NET	74,120	
			TOTAL	37.06ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		336	33		100	000516-087	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: *Matthew SF#377*
CUSTOMER: _____

FORM #
50573

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142182
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600095		32-50263		09/12/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,760	10:04 SEP-12
			TARE	34,200	
			*NET	65,560	
			TOTAL	32.78ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		301	301		100	000516-088	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *K. Mc*
DRIVER: *John F. Gering*
CUSTOMER:

FORM #
50577

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE. USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142183
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099001		32-50263		09/12/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,900	
			TARE	37,800	10:08 SEP-12
			*NET	63,100	
			TOTAL	31.55ST	10:09 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		17	17		100	000516-089	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
50578

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142184
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/12/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,800	
			TARE	34,620	10:10 SEP-12
			*NET	66,180	
			TOTAL	33.09ST	10:11 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-090	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
50579

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142190
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/12/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	109,720	10:49 SEP-12
			TARE	39,400	
			*NET	70,320	
			TOTAL	35.16ST	10:49 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	B1		100	000516-091	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
50584

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined, as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142191
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0500099 001		32-50263		09/12/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTMNATED SOIL	AM-0011		TRAILER GROSS	100,800	
			TARE	34,920	
			*NET	65,880	10:51 SEP-12
			TOTAL	32.94ST	10:52 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		258	258		100	000516-092	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
50585

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

SEATTLE CO-PROCESSING

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142192
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/12/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,200	10:54 SEP-12 10:55 SEP-12
			TARE	38,600	
			*NET	59,600	
			TOTAL	29.80ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		252	252		100	000516-093	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
K. E. Oberer

DRIVER:
Brian K. Young

CUSTOMER:
LETR GROVE 252/252

FORM #
50586

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142193
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		001	32-50263	09/12/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LB5	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 100,500 TARE 35,820 *NET 64,680	11:03 SEP-12
			TOTAL 32,345T	11:03 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		A1	A1		100	000516-094	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50587

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142201
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099001		32-50263			09/12/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS.		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	113,000	
			TARE	37,900	11:41 SEP-12
			*NET	75,100	
			TOTAL	37.55ST	11:42 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		33	33		100	000516-095	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: *[Signature]* SF#33
CUSTOMER: _____

FORM #
50593

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142202
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/12/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	113,400	
			TARE	37,800	11:55 SEP-12
			*NET	75,600	
			TOTAL	37.80ST	11:56 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		17	17		100	000516-096	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
50594

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142206
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/12/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	102,600	12:23 SEP-12
			TARE	34,620	
			*NET	67,980	12:24 SEP-12
			TOTAL	33.99ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-097	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50598

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SL	142208
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/12/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,720	
			TARE	34,200	12:45 SEP-12
			*NET	69,520	
			TOTAL	34,765T	12:46 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		301	301		100	000516-098	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: BT
CUSTOMER: _____

FORM #
50600

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142209
PRODUCT NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099		32-50263			09/12/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	110,700	
			TARE	39,400	12:58 SEP-12
			*NET	71,300	
			TOTAL	35.655T	12:58 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		B1	B1		100	000516-099	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
50601

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7342 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142213
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/12/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 106,580 TARE 34,920 *NET 71,660	13:20 SEP-12
			TOTAL 35.83ST	13:20 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		25	258		100	000516-100	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
50604

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SLIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142214
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099		32-50263			09/12/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	114,400	13:24 SEP-12
			TARE	38,600	
			*NET	75,800	
			TOTAL	37.90ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		252	252		100	000516-101	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:
[Signature]

FORM #
50605

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142215
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/12/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	98,860	13:27 SEP-12 13:27 SEP-12
			TARE	35,820	
			*NET	63,040	
			TOTAL	31.52ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		A1	A1		100	000516-102	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50606

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142221
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/12/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,700	14:02 SEP-12
			TARE	37,900	
			*NET	74,800	
			TOTAL	37,40ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		33	33		100	002516-103	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____ 37,800
 DRIVER: *[Signature]*
 CUSTOMER: _____ #3

FORM #
50611

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98148 (0)		EMERALD CONSTRUCTION		SLL	142222
CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE		
0600099 001	32-50263		09/12/2001		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	117,560	
			TARE	37,800	14:08 SEP-12
			*NET	79,760	14:08 SEP-12
			TOTAL	39.885T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		17	17		100	000516-104	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER: _____

CUSTOMER: _____

FORM #
50612

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

Shipper shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142224
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/12/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	103,900	14:19 SEP-12 14:19 SEP-12
			TARE	34,620	
			*NET	69,280	
			TOTAL	34.645T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-105	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50614

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142226
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/12/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	99,360	14:53 SEP-12 14:54 SEP-12
			TARE	34,200	
			*NET	65,160	
			TOTAL	32.58ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		301	301		100	000516-106	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: *John F. Gray*
CUSTOMER: _____

FORM #
50616

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 of 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142227
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/12/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,080	
			TARE	39,400	15:04 SEP-12
			*NET	72,680	
			TOTAL	36.345T	15:05 SEP-12

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	B1		100	000516-107	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
50617

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charge

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142223
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/12/ 11
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTMNATED SOIL	AM-0011		TRAILER GROSS	115,620	15:16 SEP-12
			TARE	34,920	
			*NET	80,700	15:16 SEP-12
			TOTAL	40.35ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		258	258		100	000516-100	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50618

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	142270
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	105,680	
			TARE	37,900	07:16 SEP-13
			*NET	67,780	
			TOTAL	33.89ST	07:17 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-109	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
 DRIVER: *[Signature]* GF #33
 CUSTOMER:

FORM #
30659

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE OF

SEATTLE CO. PROCESSING SHIPPED TO (CONSIGNEE TO)	SOLD TO	SHIPPED FROM	BILL OF LADING NO. 1
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE	EMERALD CONSTRUCTION CUSTOMER NO. 0600099	SLI	142274
	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	001	32-50263	LOAD TIME/DATE
CONTAMINATED SOIL	AM-001				07:40 SEP-13
				LBS	07:40 SEP-13
				TRAILER GROSS 101,200	
				TARE 34,620	
				*NET 66,580	
				TOTAL 33.29ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP			5/18				
RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN ORDER EXCEPT AS NOTED:			

SHIPPER: *Had M*

DRIVER: *J. G. Cory*

CUSTOMER: _____

FORM #
50662

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE OF

SEATTLE (SHIPPED TO) (CONSIGNEE)	SOLD TO	SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE	EMERALD CONSTRUCTION CUSTOMER NO. 0600099	SL	142277
	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	WEIGHT	LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		LBS	
			TRAILER GROSS 115,100	
			TARE 37,800	
			*NET 77,300	08:00 SEP-13
			TOTAL 38.65ST	08:00 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN ORDER EXCEPT AS NOTED:
		17		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
50664

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

I shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

		BILL OF LADING NUMBER	
			PAGE OF

SHIPPED TO (CONIGNED TO) SEATTLE CO PROCESSING	SOLD TO	SHIPPED FROM	BILL OF LADING NO. 1
---	---------	--------------	-------------------------

EMERALD CONSTRUCTION
JOE COMSTOCK
7343 EAST MARGINAL WAY
SEATTLE
WA 98108

CUSTOMER NO. EMERALD	CONSTRUCTION	SEE B/L NO.	BILL OF LADING NO. 142284
CUSTOMER PURCHASE ORDER NO.		SHIP DATE	

PRODUCT DESCRIPTION CONTAMINATED SOIL	PRODUCT CODE AM-0011	SILO	001	32-50263	LBS	TRAILER GROSS 90,500	TARE 39,720	*NET 50,780	TOTAL 25.39ST	LOAD TIME/DATE 08:12 SEP-13 08:13 SEP-13
--	-------------------------	------	-----	----------	-----	-------------------------	----------------	----------------	------------------	--

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO. 100 002515-112	CUSTOMER REQUIRED DELIVERY
PICKUP		RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:	

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50667

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



LAFARGE CORPORATION
DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

PAGE OF

~~SEATTLE CO-PROCESSING~~ SHIPPED TO (CONSIGNEE TO) SOLD TO SHIPPED FROM BILL OF LADING NO. 1

EMERALD CONSTRUCTION
JOE COMSTOCK
7343 EAST MARGINAL WAY
SEATTLE

EMERALD CONSTRUCTION
CUSTOMER NO.

SLL 142284

CUSTOMER PURCHASE ORDER NO. SEE B/L NO. SHIP DATE

0600099

32-50263

09/13/2001
LOAD TIME/DATE

PRODUCT DESCRIPTION	PRODUCT CODE	SILO			LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	115,200	08:23 SEP-13 06:23 SEP-13
			TARE	39,400	
			*NET	75,800	
			TOTAL	37.90ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP			E1			1201 020516-118	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50669

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING SHIPPED TO (CONSIGNEE TO)			SOLD TO			SHIPPED FROM	BILL OF LADING NO.	
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108			EMERALD CONSTRUCTION CUSTOMER NO. 0600099			SL	142287	
			CUSTOMER PURCHASE ORDER NO. 32 50253		SEE B/L NO.	SHIP DATE 09/13/2001		
PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS				LOAD TIME/DATE	
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,560				
			TARE	35,820				
			*NET	75,740		09:04 SEP-13		
			TOTAL	37.87ST		09:05 SEP-13		
CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY	
PICKUP		1	A1					
RAIL ROUTE DESCRIPTION			RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN ORDER EXCEPT AS NOTED:		

SHIPPER: *D. Ryher*

DRIVER: *PICK ALLYCA*

CUSTOMER:

FORM #
50672

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO PROCESSING SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION CUSTOMER NO. 0600099		SLI	142292
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		001	32-50253	09/13/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO				LOAD TIME/DATE										
CONTAMINATED SOIL	AM-0011		<table border="0"> <tr><td colspan="2">LBS</td></tr> <tr><td>TRAILER GROSS</td><td>95,520</td></tr> <tr><td>TARE</td><td>34,200</td></tr> <tr><td>*NET</td><td>61,320</td></tr> <tr><td>TOTAL</td><td>30.665T</td></tr> </table>			LBS		TRAILER GROSS	95,520	TARE	34,200	*NET	61,320	TOTAL	30.665T	09:41 SEP-13
LBS																
TRAILER GROSS	95,520															
TARE	34,200															
*NET	61,320															
TOTAL	30.665T															
						09:42 SEP-13										

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
RAIL ROUTE DESCRIPTION		301	RAIL ROUTE CODE	301	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED INTO ORDER EXCEPT AS NOTED: 000318-115

SHIPPER: *[Signature]*
 DRIVER: *[Signature]*
 CUSTOMER: _____

FORM #
50976

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

QUIDDING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

		BILL OF LADING NUMBER
--	--	-----------------------

SEATTLE CO PROCESSING SHIPPED TO (CONSIGNEE TO)	SOLD TO	SHIPPED FROM	PAGE OF	BILL OF LADING NO.
---	---------	--------------	---------	--------------------

EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE	EMERALD CONSTRUCTION CUSTOMER NO. 0600099	SLI	142293	SHIP DATE: 09/13/2001
	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	TRAILER GROSS	TARE	*NET	TOTAL	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011			100,080	34,920	65,160	32.585T	09:45 SEP-13 09:46 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED
PICKUP	256	256		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
50677

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received, subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosive, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION CUSTOMER NO. 0600099		SLC	142294
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		001	32-50263	09/13/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	109,980	09:49 SEP-12 09:49 SEP-13
			TARE	37,900	
			*NET	72,080	
			TOTAL	36.04ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP			33			127-000516-117	
RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:			

SHIPPER:
Wade Shear

DRIVER:
Max Goo SF#3

CUSTOMER:

FORM #
50678

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142296
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,700	
			TARE	34,620	
			*NET	69,080	09:59 SEP-13
			TOTAL	34,545T	10:00 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		03	60A		100	000516-11A	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Brad Sh

DRIVER:
Ly Com

CUSTOMER:

FORM #
50680

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
SHIPPED TO (CONSIGNEE TO)		EMERALD CONSTRUCTION		SLL	142301
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	114,540	10:25 SEP-13 10:25 SEP-13
			TARE	37,800	
			*NET	76,740	
			TOTAL	38,378T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	17		100	000516-119	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Brad Shean

DRIVER:
[Signature]

CUSTOMER:

FORM #
50683

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
SHIPPED TO (CONSIGNEE TO)		EMERALD CONSTRUCTION		SL	142304
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
WA 98108		0600059	32 50263		09/13/2001
PRODUCT DESCRIPTION	PRODUCT CODE	SILO			LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		LBS		
			TRAILER GROSS	117,200	
			TARE	39,400	
			*NET	77,800	10:41 SEP-13
			TOTAL	38.90ST	10:42 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP							
RAIL ROUTE DESCRIPTION	1	RAIL ROUTE CODE	B1 TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
50686

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 1343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142307
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/13/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	97,780	
			TARE	38,600	10:48 SEP-13
			*NET	59,180	
			TOTAL	29.59ST	10:49 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	4		100	000516-121	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Brad Shew

DRIVER:

CUSTOMER:
James Taylor

FORM #
50689

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142309
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTINATED SOIL	AM-0011		TRAILER GROSS	102,260	
			TARE	35,820	
			*NET	66,440	11:14 SEP-13
			TOTAL	33.22ST	11:14 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	A1		100	000516-122	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Wade Shean*
DRIVER: *Wade Alyca*
CUSTOMER:

FORM #
50691

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION CUSTOMER NO. 0600099 001		SL	142310
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		32-50263		09/13/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	106,740	
			TARE	37,900	11:36 SEP-13
			*NET	68,840	
			TOTAL	34,428	11:36 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-123	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Brad Shea

DRIVER:
Ma SF II 33

CUSTOMER:

FORM #
50692

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142313
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099		32-50263		09/13/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,820	
			TARE	34,620	12:01 SEP-13
			*NET	69,200	
			TOTAL	34,608	12:02 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	608			100 002516-124	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Wade Stearn*
DRIVER: *Jay Corey*
CUSTOMER: _____

FORM #
50695

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142314
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		001 32-50263		09/13/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,960	12:15 SEP-13
			TARE	34,920	
			*NET	69,060	
			TOTAL	34.53ST	12:16 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP			258			100-002516-125	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
50696

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charge

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142323
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,320	
			TARE	37,800	12:55 SEP-11
			*NET	73,520	
			TOTAL	36.76ST	12:55 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	17			100 000516-126	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50702

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

**STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE**

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING SHIPPED TO (CONSIGNEE TO)			SOLD TO			SHIPPED FROM	BILL OF LADING NO.	
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (01)			EMERALD CONSTRUCTION CUSTOMER NO. 0500099 001			SLL 142324		
			CUSTOMER PURCHASE ORDER NO. 32-50263		SEE B/L NO.	SHIP DATE 09/13/2001		
PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS				LOAD TIME/DATE	
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,540			12:58 SEP-13	
			TARE	39,400				
			*NET	73,140			12:58 SEP-13	
			TOTAL	36.575T				
CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY	
PICKUP		0	B1			100 000516-127		
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:			

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50703

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

		BILL OF LADING NUMBER
--	--	-----------------------

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142326
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	93,100	
			TARE	35,820	13:18 SEP-13
			*NET	57,280	
			TOTAL	28.64ST	13:19 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	A1			100 000516-120	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50705

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLIL	142327
PRODUCT DESCRIPTION		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	88,720	
			TARE	38,600	13:23 SEP-13
			*NET	50,120	
			TOTAL	25.06ST	13:24 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	4			100 000516-129	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Brad

DRIVER:

CUSTOMER:
George S. Taylor

FORM #
50706

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
SHIPPED TO (CONSIGNED TO)		EMERALD CONSTRUCTION		SLL	142328
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) --		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,220	
			TARE	37,900	13:26 SEP-13
			*NET	74,320	
			TOTAL	37.16ST	13:27 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-130	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Blade Mean*
DRIVER: *Mont SF #30*
CUSTOMER:

FORM #
50707

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment, without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE OF

SEATTLE SHIPPED TO (CONSIGNEE)	SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE	EMERALD CONSTRUCTION CUSTOMER NO. 0600099	CONSTRUCTION	SLL	142332
	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	WEIGHT	LOAD TIME	DATE
CONTAMINATED SOIL	AM-001		LBS	13:43	SEP-13
			TRAILER GROSS 93,660		
			TARE 34,200		
			*NET 59,460		
			TOTAL 29.73ST	13:44	SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP	RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER:

FORM #
50711

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE OF

SEATTLE WA PROCESSING SHIPPED TO (CONSIGNEE) SOLD TO SHIPPED FROM BILL OF LADING NO. 1

EMERALD CONSTRUCTION
JOE COMSTOCK
7343 EAST MARGINAL WAY
SEATTLE

EMERALD CONSTRUCTION
CUSTOMER NO. 0600099
CUSTOMER PURCHASE ORDER NO. 32-50253
SEE B/L NO.
SHIP DATE 09/13/2021

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	WEIGHT	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		LBS	
			TRAILER GROSS 106,020	
			TARE 34,620	
			*NET 71,400	14:05 SEP-13
			TOTAL 35.706T	14:05 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

PICKUP RAIL ROUTE DESCRIPTION RAIL ROUTE CODE TRAILER SEAL NO. PUP SEAL NO. RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
50713

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE OF

SEATTLE TO PROCESSING SHIPPED TO (CONSIGNEE TO)	SOLD TO	SHIPPED FROM	BILL OF LADING NO.
---	---------	--------------	--------------------

EMERALD CONSTRUCTION
JOE COMSTOCK
7343 EAST MARGINAL WAY
SEATTLE

EMERALD CONSTRUCTION
CUSTOMER NO.

SLI 142336

CUSTOMER PURCHASE ORDER NO.

SEE B/L NO.

SHIP DATE

0600099

32-50263

09/17/2001
LOAD TIME/DATE

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	WEIGHT	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,700	14:16 SEP-13 14:17 SEP-13
			TARE	34,920	
			*NET	63,780	
			TOTAL	31.89ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN ORDER EXCEPT AS NOTED:
PICKUP	1	250		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER:

FORM #
50715

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE OF

SEATTLE CO. PROCESSING SHIPPED TO (CONSIGNEE TO)			SOLD TO			SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE			EMERALD CONSTRUCTION CUSTOMER NO. 0600099			SLL	142339
WA 28105			CUSTOMER PURCHASE ORDER NO. 32-50263			SEE B/L NO.	SHIP DAT
PRODUCT DESCRIPTION			PRODUCT CODE	SILO	LOAD TIME/DATE		
CONTAMINATED SOIL AM-0011					LBS		
			TRAILER GROSS		108,320		
			TARE		37,800		
			*NET		70,520		15:07 SEP-1
			TOTAL		35.26ST		15:08 SEP-1
CARRIER	CARRIER CODE	17 TRUCK	17 TRAILER	PUP	TRANS CODE	ORDER NO-134	CUSTOMER REQUIRED DELIVERY
RAIL ROUTE DESCRIPTION			RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:	
						SHIPPER:	
						DRIVER:	
						CUSTOMER:	

FORM #
50717

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDRE

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING			EMERALD CONSTRUCTION				SL	142341
SHIPPED TO (CONSIGNEE TO)			SOLD TO				SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98188 (0)			EMERALD CONSTRUCTION CUSTOMER NO. 0600099 001				CUSTOMER PURCHASE ORDER NO. 32-50263	SEE B/L NO.
PRODUCT DESCRIPTION			PRODUCT CODE	SILO	LBS		SHIP DATE	
CONTAMINATED SOIL			AM-0011		TRAILER GROSS 112,100 TARE 39,400 *NET 72,700 TOTAL 36.355T		09/13/2001 15:36 SEP-13 15:36 SEP-13	
CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY	
PICKUP		1	B1		100	000516-135		
RAIL ROUTE DESCRIPTION			RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		
						SHIPPER: _____ DRIVER: _____ CUSTOMER: _____		

FORM #
50719

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
SHIPPED TO (CONSIGNEE TO)		EMERALD CONSTRUCTION		SLI	142343
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	87,620	15:45 SEP-13
			TARE	31,280	
			*NET	56,340	15:45 SEP-13
			TOTAL	28.17ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	1		100	002516-136	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
 DRIVER: *Rich Alley*
 CUSTOMER: _____

FORM #
50721

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT, OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142345
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,920	
			TARE	34,920	16:58 SEP-13
			*NET	66,000	
			TOTAL	33.00ST	16:59 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		258	258		100	000516-137	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
 DRIVER: _____
 CUSTOMER: _____

FORM #
50725

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142346 REPRINTED
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/13/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 92,580 TARE 34,420 *NET 58,160	17:01 SEP-11
			TOTAL 29.08ST	17:01 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		301	301		100	000516-138	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50723

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL, NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SL	142347
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/13/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	89,020	
			TARE	38,600	17:04 SEP-13
			*NET	50,420	
			TOTAL	25.21ST	17:05 SEP-13

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-139	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
DRIVER:
CUSTOMER:
[Signature]

FORM #
50724

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of Issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charge

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM



BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142375
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/14/ 1

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,320	07:15 SEP-14 07:15 SEP-14
			TARE	37,900	
			*NET	74,420	
			TOTAL	37.21ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		33	33		100	000516-140	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
 DRIVER: *Mark #33*
 CUSTOMER: _____

FORM #
50755

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142380
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/14/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	102,700	07:50 SEP-14 07:51 SEP-14
			TARE	34,620	
			*NET	68,080	
			TOTAL	34,048T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-142	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *K. McAdams*

DRIVER: *D. J. [Signature]*

CUSTOMER: _____

FORM #
50759

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142381
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0500099 001	32-50263		09/14/14

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,800	07:52 SEP-14 07:52 SEP-14
			TARE	38,600	
			*NET	60,200	
			TOTAL	30.10ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-143	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
 DRIVER: _____
 CUSTOMER: _____

FORM #
50760

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142382
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/14/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	106,920	
			TARE	36,600	
			*NET	70,320	07:59 SEP-14
			TOTAL	35.16ST	07:59 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		103	A103		100	000516-144	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50761

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be the Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	142383
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		001	32-50263	09/14/2011	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,900	08:05 SEP-14 08:06 SEP-14
			TARE	34,900	
			*NET	77,000	
			TOTAL	38.50ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		B1	B1		100	000516-145	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
50762

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	142385
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/14/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	88,900	08:24 SEP-14 08:25 SEP-14
			TARE	35,820	
			*NET	53,080	
			TOTAL	26.54ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	A1		100	000516-146	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature] *Allycat*

CUSTOMER:

FORM #
50764

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charge

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION CUSTOMER NO. 0600099		SLI	142395
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		001	32-50263	09/14/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS.		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	105,420	09:26 SEP-1 09:27 SEP-1
			TARE	41,180	
			*NET	64,240	
			TOTAL	32,125T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

PICKUP RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50774

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

9:33 AM

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142396
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/14/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	100,760	09:30 SEP-14 09:31 SEP-14
			TARE	34,420	
			*NET	66,340	
			TOTAL	33.17ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	301		100	000516-140	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
00775

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142398
CUSTOMER NO. 0600099 001		CUSTOMER PURCHASE ORDER NO. 32-50263		SEE B/L NO.	SHIP DATE 09/14/77

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	113,380	09:34 SEP-14 09:34 SEP-14
			TARE	37,900	
			*NET	75,480	
			TOTAL	37.745T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-149	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
[Signature]
DRIVER:
[Signature] 58733
CUSTOMER:

FORM #
50777

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

**STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE**

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	142400
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/14/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	108,220	
			TARE	41,460	
			*NET	66,760	09:35 SEP-14
			TOTAL	33.38ST	09:36 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		102	102		100	000516-150	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Ken*

DRIVER: *(Signature) B102*

CUSTOMER:

FORM #
50778

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142403
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/14/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,840	10:15 SEP-14 10:16 SEP-14
			TARE	34,620	
			*NET	65,220	
			TOTAL	32.61ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-151	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:
[Signature]

FORM #
50781

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading; the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives; hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM



BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142404
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/14/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	104,820	
			TARE	34,920	10:20 SEP-14
			*NET	69,900	
			TOTAL	34,955T	10:21 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		258	258		100	000516-152	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
50782

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142406
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/14/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	91,480	
			TARE	38,600	10:32 SEP-14
			*NET	52,880	
			TOTAL	26.44ST	10:32 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-153	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50784

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142408
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/14/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,660	
			TARE	36,600	10:35 SEP-14
			*NET	75,060	
			TOTAL	37.53ST	10:35 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	103		100	000516-154	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50786

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION		SLL	142411
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		001 32-50263		09/14/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	109,540	
			TARE	34,900	
			*NET	74,640	10:49 SEP-14
			TOTAL	37.32ST	10:49 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		B1	B1			1001 000516-155	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50788

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING			EMERALD CONSTRUCTION			SHIPPED FROM	BILL OF LADING NO.	
SHIPPED TO (CONSIGNEE TO)			SOLD TO			SL	142413	
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -			EMERALD CONSTRUCTION					
			CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE		
			0600099	32-50263		09/14/2001		
			001					
PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS				LOAD TIME/DATE	
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	105,000				
			TARE	35,820				
			*NET	69,180	10:55 SEP-14			
			TOTAL	34.59ST	10:56 SEP-14			
CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY	
PICKUP		A1	A1			100 000516-156		
RAIL ROUTE DESCRIPTION			RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		
SHIPPER:						KN		
DRIVER:						Rock Alleye		
CUSTOMER:								

FORM #
50790

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE OF

SEATTLE, WASHINGTON SHIPPED TO (CONSIGNEE TO)	SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE	EMERALD CONSTRUCTION CUSTOMER NO.		SLL	142418
	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
	0600099			

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	WEIGHT	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		LBS	
			TRAILER GROSS 112,460	
			TARE 37,900	
			*NET 74,560	11:31 SEP-14
			TOTAL 37.28ST	11:32 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
[Signature]

DRIVER:
[Signature] SF #22

CUSTOMER:

FORM #
50794

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE OF

SEATTLE WA 98124-1935	SOLD TO	SHIPPED FROM	BILL OF LADING NO. 1
-----------------------	---------	--------------	----------------------

EMERALD CONSTRUCTION
JOE COMSTOCK
7343 EAST MARGINAL WAY
SEATTLE

CUSTOMER NO.	CONSTRUCTION	SLI	142419
CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099			

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	001	32-50263	LOAD TIME/DATE
CONTAMINATED SOIL	AM-001				
				LBS	
			TRAILER GROSS	113,860	
			TARE	41,180	
			*NET	72,680	11:52 SEP-14
			TOTAL	36.34ST	11:52 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED
		22		11:52 SEP-14

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
30795

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE OF

SEATTLE CO. (CONSIGNEE) SHIPPED TO (CONSIGNEE) SOLD TO SHIPPED FROM BILL OF LADING NO. 1

EMERALD CONSTRUCTION
JDE COMSTOCK
7343 EAST MARGINAL WAY
SEATTLE

EMERALD CONSTRUCTION
CUSTOMER NO. 0600039
CUSTOMER PURCHASE ORDER NO. SEE B/L NO. SHIP DATE

SLL 142420

PRODUCT DESCRIPTION PRODUCT CODE SILO 001 32-50263 LOAD TIME/DATE 11:59 SEP-14

CONTAMINATED SOIL AM-0011 TRAILER GROSS 105,500 LBS
TARE 41,200
*NET 64,300
TOTAL 32.15ST

11:59 SEP-14
12:00 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN FULL ORDER EXCEPT AS NOTED

SHIPPER: *[Signature]*
DRIVER:
CUSTOMER: *[Signature]* B102

FORM #
50796

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
SHIPPED TO (CONSIGNEE TO)		EMERALD CONSTRUCTION		SLL	142422
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
()		0600099 001	32-50263		09/14/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	106,400	12:06 SEP-14 12:06 SEP-14
			TARE	34,900	
			*NET	71,500	
			TOTAL	35.75ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
			301			1001 002516-160	
PICKUP							
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50798

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142424
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		001 32-50263		09/14/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,860	12:14 SEP-14 12:14 SEP-14
			TARE	34,620	
			*NET	66,240	
			TOTAL	33.12ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	ERA			100 000516-161	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
50800

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

SEATTLE CO-PROCESSING

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142430
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/14/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,280	12:48 SEP-14 12:48 SEP-14
			TARE	34,920	
			*NET	77,360	
			TOTAL	38,685T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	258		100	000516-162	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
 DRIVER: *[Signature]*
 CUSTOMER: _____

FORM #
50805

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE OF

SEATTLE CO PROCESSING SHIPPED TO (CONSIGNEE TO) SOLD TO SHIPPED FROM BILL OF LADING NO.

EMERALD CONSTRUCTION
JOE COMSTOCK
7343 EAST MARGINAL WAY
SEATTLE
WA 98105

EMERALD CONSTRUCTION
CUSTOMER NO.

SLI 142432

CUSTOMER PURCHASE ORDER NO. SEE B/L NO. SHIP DATE

0600099

001 32-50263

09/14/2001
LOAD TIME/DATE

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	112,280	12:50 SEP-14
			TARE	36,600	
			*NET	75,680	
			TOTAL	37,845T	12:51 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP			103			1007 7027516-1E3	
RAIL ROUTE DESCRIPTION					RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.

SHIPPED:

DRIVER:

CUSTOMER:

FORM #
50806

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO REPROCESSING SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE		EMERALD CONSTRUCTION CUSTOMER NO. 0600099		SLL	142436
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	001	32-50263	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011				09/14/2001
			LBS		
			TRAILER GROSS	99,860	
			TARE	38,600	13:16 SEP-14
			*NET	61,260	
			TOTAL	30.63ST	13:17 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP	RAIL ROUTE DESCRIPTION	1	RAIL ROUTE CODE	4	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED.

SHIPPER: *D. Ryben*
DRIVER: *George H. Taylor*
CUSTOMER:

FORM #
50810

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION CUSTOMER NO. 0500099		SLL	142439
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		001	32-50263	09/14/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,400	13:19 SEP-14
			TARE	39,400	
			*NET	73,000	
			TOTAL	36.50ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	01			100 020516-165	
RAIL ROUTE DESCRIPTION					RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
50812

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

PAGE OF

SEATTLE CO PROCESSING SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION CUSTOMER NO. 0600099		SLL	142440
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		001	32-50263	09/14/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	92,040	
			TARE	35,820	13:20 SEP-14
			*NET	56,220	
			TOTAL	28.11ST	13:22 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP			A1			100-702516-156	
RAIL ROUTE DESCRIPTION					RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.

RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*

DRIVER: *Rock ALLYcat*

CUSTOMER: _____

FORM #
50813

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be the Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142444
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099 001		32-50263			09/14/200

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,500	14:15 SEP-1 14:15 SEP-1
			TARE	37,900	
			*NET	74,600	
			TOTAL	37.30ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-167	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]* 65#33
CUSTOMER:

FORM #
50816

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142447
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/14/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,760	
			TARE	41,180	14:37 SEP-14
			*NET	62,580	
			TOTAL	31.295T	14:38 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	22		100	000516-168	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *Sam Shires*

DRIVER:

CUSTOMER: *Paul*

FORM #
50819

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE OF

SEATTLE SHIPPED TO CONSIGNEE	SOLD TO		SHIPPED FROM	BILL OF LADING NO. 1
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE	CUSTOMER NO. 0600099	CONSTRUCTION	SLL 142449	
	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	

PRODUCT DESCRIPTION	PRODUCT CODE	SILG	001	32-50263	LOAD TIME DATE
CONTAMINATED SOIL	AM-0011				
				LBS	
			TRAILER GROSS	107,700	
			TARE	41,200	
			*NET	66,500	14:44 SEP-14
			TOTAL	33.25ST	14:45 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED: 10/23/14			

SHIPPER: *Tom Spier*
DRIVER: *[Signature]* B02
CUSTOMER:

FORM #
50821

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION CUSTOMER NO. 0600099 001		SL	142451
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		32-50263		09/14/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	93,020	15:05 SEP-14 15:06 SEP-14
			TARE	34,420	
			*NET	58,600	
			TOTAL	29.30ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		301	301			100 000516-170	
RAIL ROUTE DESCRIPTION					RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.

SHIPPER: _____
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50823

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper: _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING			SHIPPED TO (CONSIGNEE TO)			SOLD TO			SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)			EMERALD CONSTRUCTION CUSTOMER NO. 0600099 001			CUSTOMER PURCHASE ORDER NO. 32-50263		SEE B/L NO.	SL	142452
PRODUCT DESCRIPTION			PRODUCT CODE	SILO	LBS				LOAD TIME/DATE	
CONTAMINATED SOIL			AM-001		TRAILER GROSS	98,580				15:34 SEP-14
					TARE	34,920				
					*NET	63,660				
					TOTAL	31.835T				15:34 SEP-14
CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY			
PICKUP		0	25A		100	000516-171				
RAIL ROUTE DESCRIPTION			RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:				

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50824

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
SHIPPED TO (CONSIGNEE TO)		EMERALD CONSTRUCTION		SLL	142454
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/14/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,820	
			TARE	36,600	
			*NET	67,220	15:45 SEP-1
			TOTAL	33.61ST	15:46 SEP-1

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP			103		100	000516-172	
RAIL ROUTE DESCRIPTION					RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.

SHIPPER: *Tom Shires*
 DRIVER: *[Signature]*
 CUSTOMER:

FORM #
50826

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILD

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT-NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING SHIPPED TO (CONIGNED TO) PAGE 1 OF 1
SOLD TO BILL OF LADING NO.

EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)	EMERALD CONSTRUCTION CUSTOMER NO. 0600099 001	CUSTOMER PURCHASE ORDER NO. 32-50263	SEE B/L NO.	SLL 142455 SHIP DATE 09/14/2001
---	--	---	-------------	---------------------------------------

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTINATED SOIL	AM-0011		TRAILER GROSS 86,220 TARE 35,800 *NET 50,420 TOTAL 25.21ST	15:57 SEP-14 15:57 SEP-14

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	A1		100	000516-173	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Tom Shires*
DRIVER: *Rick Alley*
CUSTOMER:

FORM #
50827

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper: _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142496
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/17/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	115,320	
			TARE	37,900	07:24 SEP-17
			*NET	77,420	
			TOTAL	38,718T	07:25 SEP-17

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-174	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Brad*

DRIVER: *Man SF#39*

CUSTOMER:

FORM #
50873

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	142498
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099		32-50263			09/17/11
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,920	
			TARE	34,620	
			*NET	65,300	07:52 SEP-17
			TOTAL	32.65ST	07:52 SEP-17

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	ECS		100	000516-175	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
50874

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER



SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO) EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		SOLD TO EMERALD CONSTRUCTION		SHIPPED FROM SLI	BILL OF LADING NO. 142500
CUSTOMER NO. 0500099		CUSTOMER PURCHASE ORDER NO. 32-50263		SEE B/L NO.	SHIP DATE 09/17/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	113,380	07:58 SEP-17 07:58 SEP-17
			TARE	39,400	
			*NET	73,980	
			TOTAL	36.99ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	01		100	000516-176	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: 
DRIVER: 
CUSTOMER:

FORM #
50876

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142504
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/17/01

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	109,660	08:35 SEP-17 08:35 SEP-17
			TARE	34,600	
			*NET	75,060	
			TOTAL	37.53ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	17		100	000516-177	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
50880

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

I shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER



SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	142509
CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE		
0600099 001	32-50263		09/17/2001		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,940	09:08 SEP-17 09:08 SEP-17
			TARE	41,200	
			*NET	62,740	
			TOTAL	31.375T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	102		100	000516-178	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: 
CUSTOMER:  3102

FORM #
50884

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

SEATTLE CO-PROCESSING

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142517
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060059		32-50263			09/17/11
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,860	
			TARE	37,900	
			*NET	73,960	10:14 SEP-11
			TOTAL	36.98ST	10:14 SEP-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	33		100	000516-179	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]* LF # 33

CUSTOMER:

FORM #
0891

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142521
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600095 001		32-50263		09/17/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	110,320	
			TARE	39,400	10:44 SEP-17
			*NET	70,920	
			TOTAL	35.46ST	10:45 SEP-17

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	B1		100	000516-180	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
50895

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142523
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/17/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,060	
			TARE	34,600	10:46 SEP-17
			*NET	62,460	
			TOTAL	31.235T	10:47 SEP-17

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	608		100	000516-181	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Wade Stearns
DRIVER:
Jim Co...
CUSTOMER:
[Signature]

FORM #
50897

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142525
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/17/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,020	
			TARE	37,800	10:48 SEP-17
			*NET	73,220	
			TOTAL	36.61ST	10:49 SEP-17

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	17		100	000516-182	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
50898

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charge

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142530
CUSTOMER NO. 0600095 001		CUSTOMER PURCHASE ORDER NO. 32-50263	SEE B/L NO.	SHIP DATE 09/17 0	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	109,720	11:16 SEP-1 11:16 SEP-1
			TARE	41,200	
			*NET	68,520	
			TOTAL	34.26ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	102		100	000516-183	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Wade M*
DRIVER: *(Signature) 13102*
CUSTOMER:

FORM #
50903

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Required subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

I shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION		SLL	142540
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/17/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	115,000	12:16 SEP-17 12:17 SEP-17
			TARE	37,900	
			*NET	77,100	
			TOTAL	38.55ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-184	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
Wade Moore
DRIVER:
Mark G. Fitz
CUSTOMER:

FORM #
50911

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SL	142542
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		060099 001	32-50263		09/17/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	105,600	
			TARE	37,800	12:43 SEP-17
			*NET	67,800	
			TOTAL	33.94ST	12:43 SEP-17

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	17		100	000516-185	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50913

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper: _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142545
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/17/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,420	
			TARE	34,600	12:51 SEP-17
			*NET	62,820	
			TOTAL	31.41ST	12:51 SEP-17

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		01	608		100	000516-186	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Wade Mea*
DRIVER: *Jay Cruz*
CUSTOMER: _____

FORM #
50915

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charge...

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142548
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/17/...	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,960	13:07 SEP-17
			TARE	39,400	
			*NET	72,560	
			TOTAL	36,285T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	B1		100	000516-187	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
50918

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER


SEATTLE CO-PROCESSING

PAGE 1 OF 1


SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142551
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/17/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMNATED SOIL	AM-0011		TRAILER GROSS	109,900	13:35 SEP-17
			TARE	41,180	
			*NET	68,720	
			TOTAL	34,365T	13:36 SEP-17

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	32		100	000516-188	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: 

DRIVER: _____

CUSTOMER: 

FORM #
50921

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142553
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099 001		32-50263			09/17/cw1

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,700	
			TARE	41,200	
			*NET	57,500	13:38 SEP-17
			TOTAL	28.75ST	13:38 SEP-17

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	102		100	000516-189	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *Wade Shea*
DRIVER: *B102*
CUSTOMER:

FORM #
50923

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142558
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099		32-50263		09/17/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	116,720	
			TARE	37,900	14:02 SEP-17
			*NET	78,820	14:02 SEP-17
			TOTAL	<u>39,41ST</u>	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-190	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
Wade Sheeran

DRIVER:
Mark Go SF #32

CUSTOMER:

FORM #
50927

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charge

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142562
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099		32-50263		09/17/	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,940	14:35 SEP-17 14:35 SEP-17
			TARE	37,800	
			*NET	61,140	
			TOTAL	30.575T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		17	17		100	000516-191	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50930

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142565
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/17/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	102,980	14:58 SEP-1 14:59 SEP-1
			TARE	34,600	
			*NET	68,380	
			TOTAL	34.19ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-192	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
50933

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charge...

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	142566
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		060099 001	32-50263		09/17/1

PRODUCT DESCRIPTION	PRODUCT CODE	SIL	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 108,040 TARE 39,400 *NET 68,640 TOTAL 34.32ST	15:01 SEP-17 15:01 SEP-17

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	B1		100	000516-193	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50934

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

I shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142569
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/17/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,760	15:54 SEP-17 15:54 SEP-17
			TARE	41,200	
			*NET	59,560	
			TOTAL	29,785T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		102	102		100	000516-194	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
TT

DRIVER:
(Signature) B102

CUSTOMER:

FORM #
50936

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 ()		EMERALD CONSTRUCTION		SLU	142570
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099		32-50263			09/17/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	92,660	15:56 SEP-17
			TARE	41,180	
			*NET	51,480	
			TOTAL	25.74ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		22	22		100	000516-195	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
50937

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING		SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		EMERALD CONSTRUCTION		SLL	142618
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE	
		0600099 001	32-50263			09/18/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,560	
			TARE	34,600	07:57 SEP-18
			*NET	62,960	
			TOTAL	31.48ST	07:58 SEP-18

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	60B		100	000516-196	
RAIL ROUTE DESCRIPTION					RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.

SHIPPER:

DRIVER:

Joe Comstock

CUSTOMER:

FORM #
50983

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

		BILL OF LADING NUMBER


SEATTLE CO-PROCESSING


PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142620
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/18/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,260	08:10 SEP-18 08:11 SEP-18
			TARE	34,900	
			*NET	76,360	
			TOTAL	38.18ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	B1		100	000516-197	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: 

DRIVER: 

CUSTOMER: _____

FORM #
50985

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

all be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION THE COMSTOCK 343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION CUSTOMER NO. 0600099 001		SLI	142638
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		32-50263		09/18/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	102,280	
			TARE	34,600	10:17 SEP-18
			*NET	67,680	
			TOTAL	33,845T	10:18 SEP-18

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	608		100	000516-198	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
51001

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, all fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	142641
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D
		0600099 001	32-50263		09/18/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	110,060	
			TARE	34,900	10:32 SEP-10
			*NET	75,160	
			TOTAL	37.58ST	10:33 SEP-10

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	B1		100	000516-199	
RAIL ROUTE DESCRIPTION					RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.

SHIPPER:
Wade Shear

DRIVER:
[Signature]

CUSTOMER:

FORM #
51004

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 43 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION CUSTOMER NO. 0600039 001		SLI	142643
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		32-50263		09/18/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO				LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		<p align="center">LBS</p> <p>TRAILER GROSS 117,480</p> <p>TARE 38,680</p> <p>*NET 78,800</p> <p>TOTAL 39.40ST</p>			<p>10:39 SEP-18</p> <p>10:39 SEP-18</p>

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP			253			1001 002515-2001	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *D. Ryker*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
51006

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING SHIPPED TO (CONSIGNEE TO)		EMERALD CONSTRUCTION SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION CUSTOMER NO. 0600099001		SLI	142653
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D.	
		32-50263		09/18/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,680	
			TARE	37,900	11:43 SEP-18
			*NET	74,780	
			TOTAL	37,396T	11:44 SEP-18

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	33		100	000516-201	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *Wade Stearns*
 DRIVER: *Mark SF #33*
 CUSTOMER:

FORM #
51015

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING SHIPPED TO (CONIGNED TO) SOLD TO EMERALD CONSTRUCTION SHIPPED FROM SLL BILL OF LADING NO. 142656 PAGE 1 OF 1

EMERALD CONSTRUCTION JOE COMSTOCK 43 EAST MARGINAL WAY SEATTLE WA 98108	EMERALD CONSTRUCTION CUSTOMER NO. 0600099 001	CUSTOMER PURCHASE ORDER NO. 32-50263	SEE B/L NO.	SHIP DATE 09/18/2001
---	--	---	-------------	-------------------------

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 113,840 TARE 38,600 *NET 75,240	12:06 SEP-18
			TOTAL 37.62ST	12:07 SEP-18

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	252		100	000516-203	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Brad Shear*
DRIVER: *James R. M.*
CUSTOMER:

FORM #
51017

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, at fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION		SLI	142658
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099	32-50263		09/18/2001
		001			

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	113,760	
			TARE	34,860	12:27 SEP-16
			*NET	78,900	
			TOTAL	39.455T	12:28 SEP-16

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	17		100	000516-203	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51018

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION THE COMSTOCK 143 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION CUSTOMER NO. 0600099 001		SL	142659
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		32-50263		09/18/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,140	
			TARE	34,600	12:40 SEP-18
			*NET	68,540	
			TOTAL	34,279T	12:41 SEP-18

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	608		100	000516-204	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Wade Mean*
DRIVER: *Dan Cross*
CUSTOMER: _____

FORM #
51020

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att. fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142660
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D.
		0600099 001	32-50263		09/18/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	108,160	12:45 SEP-18 12:45 SEP-18
			TARE	34,900	
			*NET	73,260	
			TOTAL	36.63ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	B1		100	000516-205	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
 DRIVER: *[Signature]*
 CUSTOMER: _____

FORM #
51021

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7743 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142663
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/18/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	109,380	13:02 SEP-18 13:03 SEP-18
			TARE	38,680	
			*NET	70,700	
			TOTAL	35,358T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	253		100	000516-206	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
51024

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142665
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D.	
060099		32-50263		09/10/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	119,140	13:36 SEP-18 13:36 SEP-18
			TARE	37,900	
			*NET	81,240	
			TOTAL	40,625T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	33		100	000516-207	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *Mark S SF #3*

CUSTOMER:

FORM #
51026

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 143 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142571
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/18/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	116,720	
			TARE	37,800	14:33 SEP-18
			*NET	78,920	
			TOTAL	39,465T	14:33 SEP-18

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		17	17		100	000516-208	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
TT

DRIVER:
[Signature]

CUSTOMER:

FORM #
51029

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att. fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142673
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D.	
0600099		32-50263		09/10/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,200	14:52 SEP-18
			TARE	34,600	
			*NET	68,600	
			TOTAL	34,30ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		608	608		100	000516-209	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
 DRIVER: _____
 CUSTOMER: _____

FORM #
51030

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NO-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142674
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/18/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,620	
			TARE	34,900	15:02 SEP-18
			*NET	76,720	
			TOTAL	38.365T	15:02 SEP-18

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	E1		100	000516-210	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51031

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, air fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142677
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D/	
0600099		32-50263		09/16/01	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	108,520	
			TARE	38,680	15:32 SEP-18
			*NET	69,840	
			TOTAL	34,925T	15:33 SEP-18

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		516	253		100	000516-211	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51033

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

all be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142715
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	102,340	07:45 SEP-15 07:46 SEP-15
			TARE	34,600	
			*NET	67,740	
			TOTAL	33.87ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	608		100	000516-212	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *D. Ryker*

DRIVER: *Jay Coney*

CUSTOMER: _____

FORM #
51074

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 () -		EMERALD CONSTRUCTION		SL	142718
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D
		060099 001	32-50263		09/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	109,760	08:07 SEP-19 08:08 SEP-19
			TARE	34,900	
			*NET	74,860	
			TOTAL	37.43ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	B1		100	000516-213	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
51077

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 43 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142720
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50253		09/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	96,940	08:17 SEP-19 08:17 SEP-19
			TARE	38,440	
			*NET	58,500	
			TOTAL	29.25ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	4		100	000516-214	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *D. Ryker*
 DRIVER: *George Taylor*
 CUSTOMER:

FORM #
51079

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attc fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING


PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142724
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DA
		0600095 001	32-50263		09/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTMNATED SOIL	AM-0011		TRAILER GROSS	91,860	
			TARE	34,400	08:53 SEP-19
			*NET	57,460	
			TOTAL	28.735T	08:53 SEP-19

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	301		100	000516-215	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51083

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142727
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0500099		32-50263		09/19/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	104,200	09:23 SEP-19
			TARE	38,600	
			*NET	65,600	
			TOTAL	32.80ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	253		100	000516-216	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
51086

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att. fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SL	142728
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DA
0600099		32-50263			09/19 101
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	94,560	09:25 SEP-19 09:26 SEP-19
			TARE	34,920	
			*NET	59,640	
			TOTAL	29,825T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	258		100	000516-217	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *Wad L*
DRIVER: *Shane R Mc...*
CUSTOMER:

FORM #
51087

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

all be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142737
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/19/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	101,200	
			TARE	34,600	10:14 SEP-19
			*NET	66,600	10:15 SEP-19
			TOTAL	33.30ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	608		100	000516-216	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
51096

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, all fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142740
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099		32-50263		09/11 001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,660	
			TARE	34,900	10:28 SEP-15
			*NET	77,760	
			TOTAL	38.88ST	10:29 SEP-15

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	B1		100	000516-219	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51099

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142744
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/19/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,480	
			TARE	39,100	10:40 SEP-19
			*NET	58,380	
			TOTAL	29.195T	10:41 SEP-19

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	4		100	000516-220	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *Dryden*

DRIVER: *George S. Taylor*

CUSTOMER:

FORM #
51103

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att. fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SL	142748
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP D
0600099		32-50263			09/11/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	95,440	
			TARE	34,400	11:12 SEP-19
			*NET	61,040	
			TOTAL	30.525T	11:13 SEP-19

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		301	301		100	000516-221	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
51107

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

i 1
PAGE OF

SHIPPED TO (CONIGNED TO) EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE 98108 (0) -		SOLD TO EMERALD CONSTRUCTION		SHIPPED FROM SLI	BILL OF LADING NO. 142752
CUSTOMER NO. 0520095	CUSTOMER PURCHASE ORDER NO. 32-50263	SEE B/L NO.	SHIP DATE 09/19/2001		
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,720	
			TARE	38,680	11:46 SEP-19
			*NET	65,040	
			TOTAL	32.52ST	11:46 SEP-19

CARRIER PICKUP	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
		1	253		100	200516-222	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
D. Ryker

DRIVER:
S. K. Ryan

CUSTOMER:

FORM #
51110

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO) EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		SOLD TO EMERALD CONSTRUCTION		SHIPPED FROM SEA	BILL OF LADING NO. 142754
CUSTOMER NO. 001	CUSTOMER PURCHASE ORDER NO. 32-00253	SEE B/L NO.	SHIP DATE 057 2010		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,460	11:55 SEP-1 11:56 SEP-1
			TARE	34,920	
			*NET	64,540	
			TOTAL	32.27ST	

CARRIER PICKUP	CARRIER CODE	TRUCK 0	TRAILER 258	PUP	TRANS CODE 100	ORDER NO. 0000515-223	CUSTOMER REQUIRED DELIVERY
-------------------	--------------	------------	----------------	-----	-------------------	--------------------------	----------------------------

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:
------------------------	-----------------	------------------	--------------	---

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
51112

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____


In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.

9/19/01



R. Ryker

FROM



BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE 98108 (0)		EMERALD CONSTRUCTION		SL	142759
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099		32-50263			09/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,540	
			TARE	34,600	12:22 SEP-19
			*NET	64,940	
			TOTAL	32.475T	12:23 SEP-19

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	605		100	000516-224	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *R. Ryker*

DRIVER: *Jay Corney*

CUSTOMER: _____

FORM #
51116

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO) EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		SOLD TO EMERALD CONSTRUCTION		SHIPPED FROM BLI	BILL OF LADING NO. 142761
CUSTOMER NO. 001	CUSTOMER PURCHASE ORDER NO. 32-50263	SEE B/L NO.	SHIP D 0971		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	107,820	12:38 SEP-19
			TARE	34,900	
			*NET	72,920	12:39 SEP-19
			TOTAL	36.46ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	B1		100	000516-225	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
Wade Mean
DRIVER:
[Signature]
CUSTOMER:

FORM #
51118

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO) EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY ATTLE 98108 (0) -		SOLD TO EMERALD CONSTRUCTION		SHIPPED FROM SLU	BILL OF LADING NO. 142764
CUSTOMER NO. 0600099 001		CUSTOMER PURCHASE ORDER NO. 32-50263		SEE B/L NO.	SHIP DATE 09/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	90,520	13:12 SEP-19
			TARE	39,100	
			*NET	51,420	
			TOTAL	25.71ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	4		100	000516-226	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *D. Ryke*
DRIVER: *Robert Taylor*
CUSTOMER:

FORM #
51120

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO) EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		SOLD TO EMERALD CONSTRUCTION		SHIPPED FROM SLU	BILL OF LADING NO. 142759
CUSTOMER NO. 0620095		CUSTOMER PURCHASE ORDER NO. 32-50263		SEE B/L NO.	SHIP D 09/1 2011

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	96,480	13:27 SEP-19 13:27 SEP-19
			TARE	34,400	
			*NET	62,080	
			TOTAL	31.045T	

CARRIER PICKUP	CARRIER CODE	TRUCK	TRAILER 301	PUP	TRANS CODE 100	ORDER NO. 000516-227	CUSTOMER REQUIRED DELIVERY
-------------------	--------------	-------	----------------	-----	-------------------	-------------------------	----------------------------

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:
------------------------	-----------------	------------------	--------------	---

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
51124

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING



PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO) EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE 98108 (0)		SOLD TO EMERALD CONSTRUCTION		SHIPPED FROM SLL	BILL OF LADING NO. 142771
CUSTOMER NO. 0600099	CUSTOMER PURCHASE ORDER NO. 001	32-50263	SEE B/L NO.	SHIP DATE 09/19/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	106,060	13:56 SEP-19 13:56 SEP-19
			TARE	38,680	
			*NET	67,380	
			TOTAL	33.698T	

CARRIER PICKUP	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
		0	253		100	000516-220	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: 
DRIVER: 
CUSTOMER:

FORM #
51126

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



*9/20/01
Brd. day*

FROM

*Per Sale Order
Job order
Reversed by
Pat. Parkinson
from sle*

BILL OF LADING NUMBER

SEATTLE PLANT (WEST)

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO) MILES SAND & GRAVEL <i>Emerald Construction</i>		SOLD TO MILES SAND & GRAVEL CO. INC.		SHIPPED FROM SLE	BILL OF LADING NO. 142773
CUSTOMER NO. 600099-01 006 600099-01		CUSTOMER PURCHASE ORDER NO. 32-50263		SEE B/L NO.	SHIP DATE 09/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
TYPE I-II BULK <i>AM 001</i>	1N-0001		TRAILER GROSS	96,980	14:08 SEP-19 14:09 SEP-19
			TARE	34,920	
			*NET	62,060	
			TOTAL	31.03ST	

CARRIER PICKUP	CARRIER CODE	TRUCK 1	TRAILER 258	PUP	TRANS CODE 110	ORDER NO. <i>516</i> 000006-377	CUSTOMER REQUIRED DELIVERY
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

TYPE I-II CEMENT CONFORMS WITH ASTM C-150
PER MILL CERT NUMBER S-1-01-05

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
51127

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

ORIGINAL

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, all fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142777
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099		32-50263			09/19/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,280	
			TARE	34,600	14:46 SEP-19
			*NET	64,680	
			TOTAL	32.345T	14:47 SEP-19

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		EOB	EOB		100	000516-229	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
DRIVER: *Jay Casey*
CUSTOMER:

FORM #
51131

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142779
CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE		
060099001	32-50263		09/19/2001		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	107,020	14:58 SEP-19 14:59 SEP-19
			TARE	34,900	
			*NET	72,120	
			TOTAL	36.06ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	B1		100	000516-230	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
51133

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attn fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142782
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE BL NO.	SHIP D
		0600099 001	32-50263		09/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,860	15:40 SEP-19 15:41 SEP-19
			TARE	39,100	
			*NET	59,760	
			TOTAL	29.88ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-231	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51135

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY ATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142783
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	96,920	15:42 SEP-19 15:43 SEP-19
			TARE	34,400	
			*NET	62,520	
			TOTAL	31.26ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	301		100	000516-232	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
51136

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142834
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D
		0600099 001	32-50263		09/2... 001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	102,020	
			TARE	38,600	10:05 SEP-20
			*NET	63,420	
			TOTAL	31.715T	10:06 SEP-20

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	253		100	000516-233	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
51182

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper: _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142837
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/20/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	96,180	10:31 SEP-20
			TARE	35,100	
			*NET	61,080	
			TOTAL	30.54ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	258		100	000516-234	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: *Steve & Wain*
CUSTOMER: _____

FORM #
51185

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 ()		EMERALD CONSTRUCTION		SLI	142851
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/20/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	95,800	13:18 SEP-20
			TARE	35,100	
			*NET	60,780	
			TOTAL	30,395T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		258	258		100	000516-235	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
51198

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 143 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142852
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/20/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	106,520	
			TARE	38,600	13:19 SEP-20
			*NET	67,920	
			TOTAL	33.96ST	13:19 SEP-20

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	253		100	000516-236	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
51199

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attor fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142862
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099		32-50263		09/20/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,160	16:01 SEP-20
			TARE	35,100	
			*NET	64,060	
			TOTAL	32.03ST	
					16:02 SEP-20

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		258	258		100	000516-237	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51207

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	142863
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099		32-50263			09/20/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 97,920	
			TARE 38,600	15:05 SEP-20
			*NET 59,320	
			TOTAL 29.66ST	16:06 SEP-20

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		253	253		100	000516-238	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51208

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		511	142888
CUSTOMER NO. 0500095		CUSTOMER PURCHASE ORDER NO. 32-50253		SEE B/L NO.	SHIP I 0572 001
		001			

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,980 #	
			TARE	39,100 #	07:37 SEP-21
			*NET	64,880	
			TOTAL	32,445T	07:38 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	4		100	000516-239	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *D. Ryker*

DRIVER: *Steve Taylor*

CUSTOMER: _____

FORM #
51233

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION 106 COMSTOCK 43 EAST MARGINAL WAY SEATTLE WA 98108 (0) --		EMERALD CONSTRUCTION		SLL	142890
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/21/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	115,700	
			TARE	38,600	08:00 SEP-21
			*NET	77,100	
			TOTAL	38.55ST	08:01 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	253		100	000516-240	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *D. Ryker*

DRIVER: *S. K. De...*

CUSTOMER:

FORM #
51235

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLU	142894
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D	
0600099		32-50263		05/21/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	99,320	
			TARE	34,600	08:30 SEP-21
			*NET	64,720	
			TOTAL	32.36ST	08:31 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	508		100	000515-241	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Paul Me*
DRIVER: *Jay Cory*
CUSTOMER: _____

FORM #
51238

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 43 EAST MARGINAL WAY ATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142895
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099001		32-50263		09/21/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,160	
			TARE	39,500	
			*NET	60,660	08:34 SEP-21
			TOTAL	30.33ST	08:35 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	271		100	000516-242	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
51239

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) --		EMERALD CONSTRUCTION		SLI	142896
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/8 001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	101,020	08:37 SEP-21 08:37 SEP-21
			TARE	35,100	
			*NET	65,920	
			TOTAL	32.96ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	258		100	000516-243	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
51240

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7743 EAST MARGINAL WAY ATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142899
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/21/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,180	08:54 SEP-21 08:54 SEP-21
			TARE	34,400	
			*NET	63,780	
			TOTAL	31.89ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	301		100	000516-244	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
51243

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.

LAFARGE
CORPORATION
DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

[Handwritten Signature]

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SL	142911
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/21/00	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONFINATED SOIL	AM-001		TRAILER GROSS 94,760 TARE 38,680 *NET 56,080	10:08 SEP-21
			TOTAL 28,045T	10:09 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-245	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
51254

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142917
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/21/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	105,620	10:34 SEP-21
			TARE	38,600	
			*NET	67,220	
			TOTAL	33.61ST	10:34 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	253		100	000516-247	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51260

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142919
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D/
		0600099 001	32-50263		09/21/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,820	
			TARE	39,500	10:36 SEP-21
			*NET	61,320	
			TOTAL	30.66ST	10:36 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	271		100	000516-248	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: *Shane R. [Signature]*
CUSTOMER: _____

FORM #
51262

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 343 EAST MARGINAL WAY EATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142921
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/21/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	91,960	
			TARE	35,100	10:47 SEP-21
			*NET	56,860	
			TOTAL	28.435T	10:48 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		258	258		100	000516-249	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
51264

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142925
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D/
		0600099 001	32-50263		09/21/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	91,440	
			TARE	34,400	
			*NET	57,040	11:34 SEP-21
			TOTAL	28.525T	11:34 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		01	301		100	000516-250	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
51268

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142934
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/21/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 88,380 TARE 38,680 *NET 49,700	12:33 SEP-21
			TOTAL 24,858T	12:34 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-251	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
 DRIVER: _____
 CUSTOMER: _____

FORM #
51276

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142936
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP D
0600099		32-50263			09/21/001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	103,220	
			TARE	38,600	12:57 SEP-21
			*NET	64,620	
			TOTAL	32.31ST	12:58 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	253		100	000516-252	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
51277

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142938
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/21/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,000	13:36 SEP-21
			TARE	35,100	
			*NET	61,900	
			TOTAL	30.95ST	13:36 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	258		100	000516-253	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
51279

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 ()		EMERALD CONSTRUCTION		SLL	142940
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D/	
060099		32-50263		09/21 101	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	112,400	13:50 SEP-21
			TARE	39,500	
			*NET	72,900	
			TOTAL	36.45ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		271	271		100	000516-254	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
 DRIVER: *Shane R. M.*
 CUSTOMER: _____

FORM #
51281

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	142943
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099		32-50263			09/21/2001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	92,740	14:04 SEP-21
			TARE	34,400	
			*NET	58,340	
			TOTAL	29.175T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	301		100	000516-255	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
51284

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLU	142949
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP I
0600039		32-50263			09/2 001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,480	14:59 SEP-2: 14:59 SEP-2:
			TARE	37,800	
			*NET	60,680	
			TOTAL	30.34ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		17	17		100	000516-256	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51289

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

a Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142953
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SHIP DATE	
0600099001		32-50263		09/21/2001	
				LOAD TIME/DATE	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	92,920	15:26 SEP-21
			TARE	38,680	
			*NET	54,240	15:28 SEP-21
			TOTAL	27.125T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-257	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
51292

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	142954
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DA
		0600099	32-50263		09/21/2001
		001			

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,340	
			TARE	38,600	15:30 SEP-21
			*NET	61,740	
			TOTAL	30,875T	15:31 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		253	253		100	000516-258	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
51293

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	142955
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		060099 001	32-50263		09/21/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	95,420	
			TARE	35,100	
			*NET	60,320	15:53 SEP-21
			TOTAL	30,165T	15:54 SEP-21

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		258	258		100	000516-259	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
51294

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION.

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, atty fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	143014
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D
		0600099	32-50263		0972 201
		001			

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	95,160	
			TARE	35,100	
			*NET	60,060	08:39 SEP-24
			TOTAL	30.035T	08:39 SEP-24
PICKUP	0	258		100 000516-260	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: *Ruby Oaker*
CUSTOMER: _____

FORM #
51355

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	14301E
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600059		32-50263		09/24/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	105,460	08:42 SEP-24 08:43 SEP-24
			TARE	38,600	
			*NET	66,860	
			TOTAL	33,435	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	253		100	00051E-261	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER:

FORM #
51356

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	143042
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DA
		060099 001	32-50263		09/24/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	104,840	
			TARE	38,600	11:25 SEP-24
			*NET	66,240	
			TOTAL	33.12ST	11:25 SEP-24

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	253		100	000516-262	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *D. Ryker*

DRIVER: *J. Kelly*

CUSTOMER: _____

FORM #
51379

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.

LAFARGE
CORPORATION
DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

D. Ryker

FROM

[]
BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7743 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	143046
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/24/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	101,940	11:45 SEP-24 11:46 SEP-24
			TARE	35,100	
			*NET	66,840	
			TOTAL	33,429T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP	143046		258		100	000516-263	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *D. Ryker*

DRIVER:

CUSTOMER: *Koby Calkin*

FORM #
51383

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM

ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO) EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		SOLD TO EMERALD CONSTRUCTION		SHIPPED FROM SEATTLE	BILL OF LADING NO. 143063
CUSTOMER NO. 001	CUSTOMER PURCHASE ORDER NO. 32-5425	SEE B/L NO.	SHIP TO 001		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	106,060	
			TARE	38,600	13:40 SEP-24
			*NET	67,460	
			TOTAL	33,739T	13:41 SEP-24

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANSIT ORDER NO: 264	CUSTOMER REQUIRED DELIVERY
---------	--------------	-------	---------	-----	-----------------------	----------------------------

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:
------------------------	-----------------	------------------	--------------	---

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
51399

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING.

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 43 EAST MARGINAL WAY ATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	143071
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099001		32-50263		09/24/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	92,240	
			TARE	35,100	
			*NET	57,140	14:39 SEP-24
			TOTAL	28.579T	14:39 SEP-24

CARRIER	CARRIER CODE	258TRUCK	258TRAILER	PUP	TRANSIT CODE	ORDER NO. 258	CUSTOMER REQUIRED DELIVERY
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:
 #258

CUSTOMER:

FORM #
51405

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	143075
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600093 001		32-50263			09/24/01

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,340	16:08 SEP-24 16:08 SEP-24
			TARE	38,600	
			*NET	61,740	
			TOTAL	30.87ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		253	253		100	000516-266	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
51409

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
PORT OF SEATTLE PETER RESSLER (S-00307341) P.O. BOX 98727 SEATTLE WA 98168-0727 (0) -		PORT OF SEATTLE		SL	143073
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600259	S-00307341		09/24/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	59,780	14:45 SEP-24
			TARE	27,700	
			*NET	32,080	
			TOTAL	16.045T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		58	58		100	000510-054	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
51407

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE 1 OF 1

SEATTLE CO-PROCESSING		SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION CUSTOMER NO. 0600099 001		CUSTOMER PURCHASE ORDER NO. 32-50263		SLI	143097
				SEE B/L NO.	SHIP D/ 09/25/2001		

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,780	07:19 SEP-25 07:20 SEP-25
			TARE	39,100	
			*NET	58,680	
			TOTAL	29.34ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	4		100	000516-267	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM # 1429

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
 ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
 BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7743 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	143099
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/25/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	92,980	07:58 SEP-25
			TARE	35,320	
			*NET	57,660	
			TOTAL	28.83ST	07:59 SEP-25

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	272		100	000516-268	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
 DRIVER: _____
 CUSTOMER: _____

FORM #
51431

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM

ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	143107
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DA
		0600099 001	32-50263		09/25/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	105,280	
			TARE	39,740	
			*NET	65,540	08:50 SEP-25
			TOTAL	32.775T	08:51 SEP-25

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	IS		100	000516-269	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Dryden*

DRIVER: *[Signature]*

CUSTOMER: *[Signature]*

FORM #
51438

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper: _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 343 EAST MARGINAL WAY. SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	143117
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/25/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	91,420	09:41 SEP-25 09:42 SEP-25
			TARE	38,700	
			*NET	52,720	
			TOTAL	26.36ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-270	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
51446

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SL	143119
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DA
		0600099 001	32-50263		09/25/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	79,100	
			TARE	35,320	10:07 SEP-25
			*NET	43,780	
			TOTAL	21.895T	10:08 SEP-25

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	272		100	000516-271	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
51448

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	143127
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/25/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	94,960	
			TARE	39,740	11:07 SEP-25
			*NET	55,220	
			TOTAL	27.61ST	11:08 SEP-25

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	I6		100	000516-272	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
01455

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	143136
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DA	
0600099 001		32-50263		09/25/00	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	93,700	12:06 SEP-25
			TARE	38,700	
			*NET	55,000	
			TOTAL	27.50ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-273	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
51463

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	143138
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		09/25/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	90,200	12:12 SEP-25 12:13 SEP-25
			TARE	35,320	
			*NET	54,880	
			TOTAL	27.44ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		272	272		100	000516-274	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
51465

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98148 (0) -		EMERALD CONSTRUCTION		SLL	143144
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D/	
0600099		32-50263		09/25, 2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	102,960	
			TARE	39,740	
			*NET	63,220	13:34 SEP-25
			TOTAL	31.61ST	13:35 SEP-25

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		6	16		100	000516-275	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
51470

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		BILL	143152
CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE		
0600099	32-50263		09/25/2001		
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,120	14:19 SEP-25 14:19 SEP-25
			TARE	38,700	
			*NET	59,420	
			TOTAL	29.71ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	4		100	000516-278	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: *George S. Taylor*
CUSTOMER: _____

FORM #
51477

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, all fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	143153
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600299		32-50263		09/20/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	89,540	14:25 SEP-25 14:26 SEP-25
			TARE	35,320	
			*NET	54,220	
			TOTAL	27.11ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		272	272		100	000516-277	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
51478

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	143188
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/26/2001

PRODUCT #	DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
	CONTAMINATED SOIL	AM-0011		TRAILER GROSS 84,980 TARE 35,320 *NET 49,660 TOTAL 24,83ST	08:29 SEP-26 08:29 SEP-26

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	272		100	000516-278	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
51510

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify, and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE OF

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 () -		EMERALD CONSTRUCTION		SLI	143195
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
060099		32-50263		09/26/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	90,480	09:37 SEP-26 09:38 SEP-26
			TARE	38,600	
			*NET	51,880	
			TOTAL	25.94ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	252		100	000516-279	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]* #25

CUSTOMER: _____

FORM #
51514

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify, and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 () -		EMERALD CONSTRUCTION		SLI	143196
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		09/26/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	66,420	09:44 SEP-26 09:44 SEP-26
			TARE	35,100	
			*NET	31,320	
			TOTAL	15.665T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	258		100	000516-280	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *DRyber*

DRIVER: *Brian Young*

CUSTOMER:

FORM #
51515

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	143215
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		09/26 001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	96,340	12:48 SEP-26 12:48 SEP-26
			TARE	35,320	
			*NET	61,020	
			TOTAL	30.515T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		272	272		100	000516-281	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
51531

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

**STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE**

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98109 (0)		EMERALD CONSTRUCTION		SLI	143227
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			09/26/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	93,580	15:44 SEP-26 15:46 SEP-26
			TARE	35,320	
			*NET	58,260	
			TOTAL	29,138T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		272	272		100	000516-283	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
51542

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attc fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees, in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	143291
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP D/
0600099 001		32-50263			09/27/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	94,060	
			TARE	35,320	11:56 SEP-27
			*NET	58,740	11:57 SEP-27
			TOTAL	29.37ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		272	272		100	000516-284	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
DRIVER:
CUSTOMER:

FORM #
51602

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	143314
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
01600099 001		32-50263		09/27/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	92,240	14:45 SEP-27 14:45 SEP-27
			TARE	35,320	
			*NET	56,920	
			TOTAL	28.465T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		272	272		100	000516-285	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
 DRIVER: _____
 CUSTOMER: _____

FORM #
51622

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attn fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

SEATTLE CO-PROCESSING

BILL OF LADING NUMBER

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	143388
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D/	
0600099		32-50263		09/21/01	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	69,720	
			TARE	35,320	11:32 SEP-28
			*NET	34,400	
			TOTAL	17.20ST	11:33 SEP-28

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	272		100	000518-286	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *D. Ryker*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
51685

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

((
((
((
FROM
((
((

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION 700 COMSTOCK 43 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	143919
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			10/09/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,320	08:43 OCT-09 08:43 OCT-09
			TARE	38,600	
			*NET	60,720	
			TOTAL	30.365T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	252		100	000516-287	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *Shane R M [Signature]*
CUSTOMER:

FORM #
52876

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att. fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) --		EMERALD CONSTRUCTION		SLL	143921
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DA
		0600099 001	32-50263		10/09/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SDIL	AM-0011		TRAILER GROSS	87,820	08:57 OCT-09 08:57 OCT-09
			TARE	35,100	
			*NET	52,720	
			TOTAL	26.36ST ✓	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	258		100	000516-288	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
Dryden

DRIVER:
Sam Young

CUSTOMER:

FORM #
52878

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	143924 ✓
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060009001		32-50263			10/09/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,920	09:12 OCT-05
			TARE	38,600	
			*NET	60,320	
			TOTAL	30.165T ✓	09:12 OCT-05

PICKUP 0 253 100 000516-289

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *Wade Shuman*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
52881

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, all fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	143939
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D
		0600099 001	32-50263		10/09/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LAB			LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	114,660		
			TARE	38,600		10:57 OCT-05
			*NET	76,060		10:58 OCT-05
			TOTAL	38.03ST		

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	252		100	000516-290	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *Shane R. W.*

CUSTOMER: _____

FORM #
52893

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE OF

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
SEATTLE CO-PROCESSING					
EMERALD CONSTRUCTION E COMSTOCK 7343 EAST MARGINAL WAY SEATTLE		CUSTOMER NO. EMERALD	CONSTRUCTION	SLI	143941
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		0600099			

PRODUCT DESCRIPTION	PRODUCT CODE	SILQ	TRAILER GROSS	TARE	*NET	TOTAL	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		95,780	35,100	60,680	30,345	11:13 OCT-09
							11:14 OCT-09

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED: 0014516-291			
PICKUP	258	0006					

SHIPPER:
K. W. [Signature]

DRIVER:
Bun Yang

CUSTOMER:

FORM #
52895

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, at fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE OF

SHIPPED TO (CONIGNED TO) SEATTLE CO PROCESSING			SOLD TO			SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98148			CUSTOMER NO. EMERALD	CONSTRUCTION	SLI	14394	SHIP
PRODUCT DESCRIPTION			PRODUCT CODE	SILO	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	LOAD TIME DATE
CONTAMINATED SOIL			AM-0011		001 32-50263		11:35 OCT-09
					LBS		11:36 OCT-09
					TRAILER GROSS 101,280		
					TARE 38,600		
					*NET 62,680		
					TOTAL 31.34ST		

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED
PICKUP	0	253		000115-002

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
52897

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

all be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE OF

SHIPPED TO (CONSIGNEE TO) SEATTLE CO PROCESSING		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE		CUSTOMER NO. EMERALD	CONSTRUCTION	SLI	143949
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	

PRODUCT DESCRIPTION CONTAMINATED SOIL	PRODUCT CODE AM-0011	SILO	001	32-50263	LBS	TRAILER GROSS 107,300 TARE 38,600 *NET 68,700 TOTAL 34,395	LOAD TIME/DATE 13:07 OCT-09 13:07 OCT-09
--	-------------------------	------	-----	----------	-----	---	--

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
RAIL ROUTE DESCRIPTION PICKUP		RAIL ROUTE CODE	TRAILER SEAL NO. 232	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED 100 000516-293		

SHIPPER: *[Signature]*
DRIVER: *Shane R M*
CUSTOMER:

FORM #
52901

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CD-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	143952
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DA
		0600095 001	32-50263		10/09/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS.		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,640	
			TARE	35,100	13:22 OCT-09
			*NET	63,540	
			TOTAL	31.77ST	13:22 OCT-09

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	258		100	000516-294	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:

CUSTOMER:

FORM #
52903

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[] []
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION 106 COMSTOCK 343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SL	143958
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0500099 001		32-50263			10/09/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS			LOAD TIME/DATE
CONTAMINATED SOIL	AM-0013		TRAILER GROSS	111,940		
			TARE	38,600		
			*NET	73,340	14:04 OCT-09	
			TOTAL	36.675T	14:04 OCT-09	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	253		100	000516-295	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:

FORM #
52907

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	143965
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DA
		0600099 001	32-50263		10/09/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTMNATED SOIL	AM--0011		TRAILER GROSS	113,200	
			TARE	38,600	15:24 OCT-09
			*NET	74,600	
			TOTAL	37.305T	15:25 OCT-09

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		252	252		100	000516-296	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: *Shane R M*
CUSTOMER: _____

FORM #
52912

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	144024 ✓
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		10/10/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTINATED SOIL	AM-0011		TRAILER GROSS	115,700	12:01 OCT-10 12:02 OCT-10
			TARE	38,100	
			*NET	77,600	
			TOTAL	38,805 ✓	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		22	22		100	000516-297	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
K. NCC

DRIVER:
[Signature]

CUSTOMER:

FORM #
52970

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE. USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attr fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 () -		EMERALD CONSTRUCTION		SLL	144025
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D/
		0600099 001	32-50253		10/10/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	108,140	
			TARE	38,600	12:05 OCT-10
			*NET	69,540	
			TOTAL	34.77ST	12:06 OCT-10

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		21	21		100	000516-298	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
52971

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch, to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	144028 ✓
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0500095 001	32-50263		10/10/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	100,820	
			TARE	38,100	14:01 OCT-10
			*NET	62,720	14:02 OCT-10
			TOTAL	31.365T ✓	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	22		100	000516-299	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *D. Ryker*

DRIVER: *[Signature]*

CUSTOMER:

FORM #
52974

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM

ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, atto fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SL	144030
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DA
		0600299 001	32-50263		10/10/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	96,940	
			TARE	38,600	14:08 OCT-10
			*NET	58,340	
			TOTAL	29,179	14:09 OCT-10

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	21		100	000516-300	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Dryber*

DRIVER: *Ken P*

CUSTOMER:

FORM #
52976

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

PAGE OF

SEATTLE CO-PROCESSING SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION 1E COMSTOCK 143 EAST MARGINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION CUSTOMER NO. 01600099		ELL	144058
		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
		001	32-58263	10/11/2001	
PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LOAD TIME/DATE		

CONTAMINATED SOIL	AM-0011		LBS		
			TRAILER GROSS	101,700	
			TARE	39,600	
			*NET	63,100	08:12 OCT-11
			TOTAL	31.55ST	08:12 OCT-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP							
RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:			

SHIPPER:
[Signature]
DRIVER:
[Signature]
CUSTOMER:

FORM #
53002

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, all fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLL	144063
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D	
060099 001		32-50263		10/11/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	90,820	09:15 OCT-11
			TARE	35,100	
			*NET	55,720	
			TOTAL	27.86ST	09:16 OCT-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	258		100	000516-302	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Wade Allen*
DRIVER: *S. Usher*
CUSTOMER: _____

FORM #
53007

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	144071 REPRINTED
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		10/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	96,580	
			TARE	38,600	10:33 OCT-11
			*NET	57,980	
			TOTAL	28,995T	10:34 OCT-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	252		100	000516-303	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
53015

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attc fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		BLI	144078
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D.	
0600099		32-50263		10/11/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	90,860	11:26 OCT-11
			TARE	35,100	
			*NET	55,760	
			TOTAL	27.88ST	11:26 OCT-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	258		100	000516-304	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
53020

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

**STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE**

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

RECURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY ATTLE 98108 (0)		EMERALD CONSTRUCTION		SLI	144086
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		060099 001	32-50263		10/11/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	101,080	
			TARE	38,600	
			*NET	62,480	12:40 OCT-11
			TOTAL	31,245T	12:41 OCT-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	252		100	000516-305	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *Bob Mean*

DRIVER: *Steve R Mc*

CUSTOMER:

**FORM #
53026**

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, all fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	144096
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP D
0600099		32-50263			10/11/001
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS	LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS 97,300 TARE 38,500 *NET 58,800	15:07 OCT-11
			TOTAL 29.40ST	15:07 OCT-11

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		252	252		100	000516-306	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
53036

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

*10/16/01
shipment mod.
dry*

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	144196
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		10/11/01 10-15-2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	95,320	<i>Approx 13:00 H</i> 09:50 OCT-15 09:50 OCT-15
			TARE	35,100	
			*NET	60,220	
			TOTAL	30.11ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	258		100	000516-307	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

*Computers are down from 1:00pm
approx 50 minutes.*

SHIPPER:
DRIVER:
CUSTOMER:

FORM #
53131

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att. fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	144249
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600039	32-50263		10/16/2001
		001			

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	93,500	09:04 OCT-16 09:05 OCT-16
			TARE	38,500	
			*NET	55,000	
			TOTAL	27.50ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	252		100	000516-300	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:
[Signature]

DRIVER:
Shane R M

CUSTOMER:

FORM #
53180

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION CUSTOMER NO. 0600099 001 32-50263		SLL 1	44727
			CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
					10/24/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL AM-0011			TRAILER GROSS	101,100	
			TARE	39,200	
			*NET	61,900	13:08 OCT-24
			TOTAL	30.95ST	13:09 OCT-24

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP	0		253		170	000516-328	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER:

FORM #
53664

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation service contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation and to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, also fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper: _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	144252
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE BL NO.	SHIP DATE
0600099 001		32-50263			10/16/01

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-001		TRAILER GROSS	82,400	09:15 OCT-16 09:16 OCT-16
			TARE	35,480	
			*NET	46,920	
			TOTAL	23.46ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	1		100	000516-309	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM # 53181

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

ORIGINAL

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLT	144253
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			10/16/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	88,320	09:23 OCT-16 09:23 OCT-16
			TARE	38,100	
			*NET	50,220	
			TOTAL	25.11ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	CM4		100	002516-310	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
53183

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	144274
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		10/16/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	99,520	11:42 OCT-16 11:42 OCT-16
			TARE	38,500	
			*NET	61,020	
			TOTAL	30,515T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	252		100	000516-311	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:
Shane R Mares

CUSTOMER:

FORM #
53199

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	144276
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0500099 001		32-50263			10/16/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	81,800	
			TARE	35,400	12:03 OCT-16
			*NET	46,400	
			TOTAL	23.205T	12:04 OCT-16

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	1		100	000516-312	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER:

FORM #
53201

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CG-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	144278
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0500099 001		32-50263			10/16/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,180	12:18 OCT-16 12:18 OCT-16
			TARE	38,100	
			*NET	59,080	
			TOTAL	29.54ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	CM4		1000	000516-313	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER: _____

FORM #
53203

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	144285
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099	32-50263		10/16/2001
		001			

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	111,060	14:33 OCT-16 14:34 OCT-16
			TARE	38,500	
			*NET	72,560	
			TOTAL	36.28ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		516	252		100	000516-314	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____

DRIVER: _____

CUSTOMER: *Shane R. Maires*

FORM #
53208

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted; marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLI	144286
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099 001		32-50263		10/16/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	88,820	14:39 OCT-16
			TARE	35,840	
			*NET	52,980	
			TOTAL	26.49ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		1	1		100	000516-315	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
53209

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY ATTLE 98108 (0)		EMERALD CONSTRUCTION		SLI	144287
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		10/16/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,400	14:53 OCT-16
			TARE	38,100	
			*NET	62,300	
			TOTAL	31.15ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		4	CM4		100	000516-316	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
53210

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO) EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		SOLD TO EMERALD CONSTRUCTION CUSTOMER NO. 0500293 001		SHIPPED FROM	BILL OF LADING NO. 107454
CUSTOMER PURCHASE ORDER NO. 0500293			SEE B/L NO.	SHIP I 107454 001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	97,540	11:58 OCT-15
			TARE	40,800	
			*NET	56,740	
			TOTAL	28,375T	

CARRIER PUDRA	CARRIER CODE 75	TRUCK	75	TRAILER	PUP	TRANS CODE 240	ORDER NO. 2402110-317	CUSTOMER REQUIRED DELIVERY
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:			

SHIPPER:
[Signature]

DRIVER:
[Signature]

CUSTOMER:
McCann #75

FORM #
53362

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

**STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE**

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper: _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		ELL	144465
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0600099 001	32-50263		10/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO			LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	LBS	
			TARE	104,580	
			*NET	41,660	12:13 OCT-19
			TOTAL	62,920	12:13 OCT-19
PICKUP	0	22		31.46ST	
				100 000516-318	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
53363

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att. fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



DEPARTMENT 228
PO BOX C-34935
SEATTLE WA 98124-1935
PHONE: 1-800-477-0100

FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	144468
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP D.	
0600099		32-50263		10/19/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0013		TRAILER GROSS	105,060	
			TARE	40,600	12:27 OCT-19
			*NET	64,460	
			TOTAL	32.236T	12:20 OCT-19

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	10		100	000516-319	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
53366

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	144479
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			10/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	109,380	14:29 OCT-19 14:29 OCT-19
			TARE	40,600	
			*NET	68,780	
			TOTAL	34,395T	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	10		100	000516-320	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: *[Signature]*

FORM #
53376

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att. fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	144480
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600090001		32-50263		10/19/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	100,380	14:30 OCT-19 14:30 OCT-19
			TARE	40,780	
			*NET	59,600	
			TOTAL	29.80ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	75		100	000516-321	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*

DRIVER: *[Signature]*

CUSTOMER:

FORM #
53377

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

**STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE**

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It will be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (8)		EMERALD CONSTRUCTION		SLI	144481
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
0600099 001		32-50263			10/19/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	107,020	14:31 OCT-19 14:32 OCT-19
			TARE	41,660	
			*NET	65,360	
			TOTAL	32.68ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	22		100	000516-322	

RAIL ROUTE DESCRIPTION	RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:

SHIPPER: *[Signature]*
 DRIVER: *[Signature]*
 CUSTOMER:

FORM #
53378

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.
 THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILD

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		SLI	144584
		CUSTOMER NO.	CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE
		0500099 001	32-50263		10/23/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	110,060	
			TARE	39,200	09:41 OCT-23
			*NET	70,860	
			TOTAL	35.43ST	09:42 OCT-23

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		253	253		100	000516-323	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
53475

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLU	144613
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		32-50263		10/23/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	98,700	
			TARE	39,200	11:54 OCT-23
			*NET	59,500	
			TOTAL	29,755T	11:54 OCT-23

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		253	253		100	000516-324	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
53504

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0) -		EMERALD CONSTRUCTION		BLI	144636
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600093		32-50263		10/23/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	108,340	14:16 OCT-23 14:16 OCT-23
			TARE	39,200	
			*NET	69,140	
			TOTAL	34.57ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		253	253		100	000516-325	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: _____
DRIVER: _____
CUSTOMER: _____

FORM #
53526

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It be Carrier(s) duty to verify the weight of the shipment and, Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7347 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SL	144705
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DATE
060099		32-50263			10/24/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	89,540	10:58 OCT-24
			TARE	35,100	
			*NET	54,440	
			TOTAL	27.22ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP	0	258			1000	00516-327	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *[Signature]*
DRIVER: *[Signature]*
CUSTOMER: _____

FORM #
53647

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARGINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	144705
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0500099		32-50263		10/24/2001	
001					

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	92,420	
			TARE	39,200	
			*NET	53,220	10:55 OCT-24
			TOTAL	26.61ST	10:56 OCT-24

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP	0		253		100	000516-326	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER: _____

FORM #
53646

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

all be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

[]
BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7 EAST MARGINAL WAY SEATTLE WA 98108 () -		EMERALD CONSTRUCTION		SL	144731
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600099		001 32-50263		10/24/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		TRAILER GROSS	93,000	
			TARE	35,100	
			*NET	57,900	13:35 OCT-24
			TOTAL	28.995T	13:35 OCT-24

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP	0	258			100	000516-329	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER: *Paul M.*

DRIVER: *Brian Young*

CUSTOMER:

FORM #
53667

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, att fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONIGNED TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 7343 EAST MARSINAL WAY SEATTLE WA 98108 (0)		EMERALD CONSTRUCTION		SLL	144793
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.		SEE B/L NO.	SHIP DA
0600099 001		32-50263			10/25/2001

PRODUCT DESCRIPTION	PRODUCT CODE	SILO	LBS		LOAD TIME/DATE
CONTMNATED SOIL	AM-0011		TRAILER GROSS	102,580	16:14 OCT-24 08:30 OCT-25
			TARE	39,200	
			*NET	63,380	
			TOTAL	31.69ST	

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		253	253		100	000516-330	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:

DRIVER:

CUSTOMER:

FORM #
53723

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION

STRAIGHT BILL OF LADING - SHORT FORM
ORIGINAL - NOT NEGOTIABLE

Received subject to the terms and provisions of any written transportation services contract between the Carrier(s) transporting this shipment and Lafarge Corporation (Shipper) on the date of issue of this Bill of Lading, the property described hereon, in apparent good order, except as noted, marked, consigned and destined as set forth hereon, which said Carrier(s) agrees to carry with reasonable dispatch to the destination designated hereon. Shipper agrees and warrants that such shipments contain no Class A or B explosives, hazardous or dangerous material, unless specified in writing on the face hereof, and that the articles described hereon are properly described and are in proper condition for transportation according to applicable laws and regulations.

It shall be Carrier(s) duty to verify the weight of the shipment and Carrier(s) agree to indemnify and hold harmless Shipper from and against any loss cost or expense (including, but not limited to, attorney's fees) arising from or relating to Carrier(s) transportation of a load that exceeds the maximum allowable weight.

NON-RECOURSE: If Shipper signs this provision, Shipper shall not be liable for freight charges and Carrier shall not deliver this shipment without advance receipt of payment of all shipping and related charges.

Signature of Shipper _____

In case of any dispute between the parties hereto resulting in legal action, the prevailing party in said action shall be entitled to reasonable attorney's fees in addition to costs and disbursements to be awarded by the clerk of the court therein.



FROM

BILL OF LADING NUMBER

SEATTLE CO-PROCESSING

PAGE 1 OF 1

SHIPPED TO (CONSIGNEE TO)		SOLD TO		SHIPPED FROM	BILL OF LADING NO.
EMERALD CONSTRUCTION JOE COMSTOCK 43 EAST MARINAL WAY SEATTLE WA 98108		EMERALD CONSTRUCTION		SLL	144795
CUSTOMER NO.		CUSTOMER PURCHASE ORDER NO.	SEE B/L NO.	SHIP DATE	
0600039 001		32-50263		10/25/2001	

PRODUCT DESCRIPTION	PRODUCT CODE	SILO				LOAD TIME/DATE
CONTAMINATED SOIL	AM-0011		LBS			
			TRAILER GROSS	74,450		08:41 OCT-25
			TARE	38,500		
			*NET	35,950		
			TOTAL	17.99ST		08:41 OCT-25

CARRIER	CARRIER CODE	TRUCK	TRAILER	PUP	TRANS CODE	ORDER NO.	CUSTOMER REQUIRED DELIVERY
PICKUP		0	252		100	000516-331	
RAIL ROUTE DESCRIPTION		RAIL ROUTE CODE	TRAILER SEAL NO.	PUP SEAL NO.	RECEIVED IN GOOD ORDER EXCEPT AS NOTED:		

SHIPPER:
[Signature]
DRIVER:

CUSTOMER:
[Signature]


FORM #
53724

Freshly mixed cement, mortars, grout or concrete may cause injuries, including burns, to skin and eyes. Avoid contact with skin and wash exposed areas with water. If any cement or cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention.

THIS WARNING SHOULD BE CONVEYED TO ALL PERSONS WHO MAY PURCHASE, USE OR COME IN CONTACT WITH CEMENT AND CEMENT MIXTURES.

KEEP OUT OF REACH OF CHILDREN.

SHIPPING LOCATION



Ms. Linda Dawson
Maul Foster & Alongi
17171 Bothell Way N.E.
Seattle, WA 98155

January 14, 2002

Subject: Demolished Asphalt Disposal Location and recycled Use for
Material taken from Unocal's Former Edmonds Terminal

Dear Ms. Dawson:

As part of the demolition package for the Unocal Project, asphalt was disposed of at CSR's Everett facility. It Emerald Services, Inc (ESI) understanding that CSR crushes the material and mixes it with crushed concrete.

Additionally, it is ESI's understanding that this material is crushed to a WSDOT specification in order to be re-used as roadbed aggregate.

Should you have questions regarding the above information, please feel free to contact me at (206) 832-3036 and I will do my best to complete this work as soon as possible.

Weight tickets received from CSR upon delivery of broken asphalt, only identify the material (broken asphalt), and the respective weigh in tons.

Sincerely,
Emerald Services, Inc.

Joe Comstock

Joe Comstock
Division Construction Manager



WPLE-7349
32-50263

Plant # 1875 Ticket # 40742

Customer # 3062552	Sold To EMERALD SERVICES INC	Date 9/17/2001
Job 32-50263	Delivery Address 104th & Pine Edmonds Ferry EVERETT, WA 98203	Project #
P. O. # 32-50263	Instructions 104th & Pine Edmonds Ferry	Due Time
Zone		Leave Plant 11:09:59 AM

Order # 8732364	Truck # 56765	Driver/Hauler PSS21, PUGET SOUND SOIL	Leave Job	Arrive Plant
-----------------	---------------	--	-----------	--------------

Load Quantity	Cumulative Quantity	Order Quantity	Product	PRODUCT DESCRIPTION	UNIT	AMOUNT
31.29	2 Loads 65.85 Ton	1184344	OTHER MATERIAL DUMPED BY ASPHALT			
			Gross Tare Net	47,196KG 41,380 Lb 62,580 Lb		18,770Kg 22,385 Kg

SUB-TOTAL	TAX	TICKET TOTAL	ORDER TOTAL
-----------	-----	--------------	-------------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.
 All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X Kau
 CUSTOMER SIGNATURE

849734

CUSTOMER COPY



WPE-1349

32 50263

Customer # 3062552	Sold To EMERALD SERVICES INC	Plant # 1575	Ticket # 7324
Job 32-50263	Delivery Address 104th & Pine Edmonds Ferry EVERETT, WA 98203	Project #	Date 9/17/2001
P.O.# 32-50263	Instructions 104th & Pine Edmonds Ferry		Time Batched
Zone		Leave Plant 9:30:25 AM	Arrive Job

Order # 8752364	Truck # 56706	Driver/Hauler P521, PUGET SOUND SOIL	Leave Job	Arrive Plant	
Load Quantity	Cumulative Quantity	WEIGHT	Tare Net	PRODUCT DESCRIPTION	AMOUNT
34.56	1 Load 34.56 Ton	1184344	41,380 Lb 69,120 Lb	OTHER MATERIAL DUMPED BY ASPHALT	

SUB-TOTAL	TAX	TICKET TOTAL	ORDER TOTAL
-----------	-----	--------------	-------------

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature in of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property; buildings; sidewalks; drive-ways; curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X *[Signature]*
 CUSTOMER SIGNATURE

849694



WPE-1348
32-50763

REPRINT Plant # 1075 Ticket # 75243790

Customer # 3062552	Sold To EMERALD SERVICES INC	Date 9/26/2001
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds	Time Batched
Zone		Due Time
	Leave Plant 12:52:10 PM	Arrive Job

Order # 187524	Truck # 205175	Driver/Hauler C253, CEDAR GROVE	Leave Job	Arrive Plant 2:24:37 PM
----------------	----------------	------------------------------------	-----------	----------------------------

Load Qty	Cumulative Qty	Weight	Tare Net	PRODUCT DESCRIPTION	AMOUNT
27.22	27.22 Ton	1 Load	1197157	ASPHALT DUMPED BY TON, NO	

SUB-TOTAL	TAX	TICKET TOTAL	ORDER TOTAL
-----------	-----	--------------	-------------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X [Signature]
 CUSTOMER SIGNATURE

843753



Customer # 3062552	Sold To EMERALD SERVICES INC	Plant # 1875	Ticket # 7524375
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475	Date 9/26/200
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds		Time Batched
Zone		Leave Plant 12:55:39 PM	Arrive Job

Order # 187524	Truck # 2029	Driver/Hauler C258, CEDAR GROVE	Leave Job	Arrive Plant 4:19 PM
----------------	--------------	------------------------------------	-----------	-------------------------

Load Quantity	Cumulative Quantity	Ordered	Weight	Tare Net	PRODUCT DESCRIPTION	Unit	AMOUNT
22.47	49.63	2 Loads	49.63 Ton	1197157	ASPHALT DUMPED BY TON, NO		
					35,280 Lb	16,003Kg	
					44,940 Lb	20,385 Kg	

SUB-TOTAL	TAX	TICKET TOTAL	ORDER TOTAL
-----------	-----	--------------	-------------

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)

Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.

SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X Brian Young
 CUSTOMER SIGNATURE

843755

CUSTOMER COPY



Customer # 3162552	Sold To EMERALD SERVICES INC	Plant # 1A75	Ticket # 75243852
Job	Delivery Address	Date	
Project #	Project #	Time Batched	
Zone #	Zone #	Leave Plant	Arrive Job

Order # 18752476	Truck # 2051753	Driver/Hauler G253, CEDAR GROVE	Leave Job	Arrive Plant
---------------------	--------------------	------------------------------------	-----------	--------------

QUANTITY		PRODUCT DESCRIPTION		WEIGHT	
26.13	3 Loads 70.82 Ton	1197157 ASPHALT DUMPED BY TON, NO	Gross 91,300 Lb Tare 39,040 Lb Net 52,260 Lb	41,413 Kg 17,708 Kg 23,705 Kg	

SUB-TOTAL	TAX	TICKET TOTAL	GRAND TOTAL
-----------	-----	--------------	-------------

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)

Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.

SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE

LOAD RECEIVED BY:
 X [Signature]
 CUSTOMER SIGNATURE

846641

CUSTOMER COPY

CSR Associated

Customer # 3062552 Job	Sold To EMERALD SERVICES INC Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Plant # 1875	Ticket # 75243062
Unocal P.O.#	Unocal Instructions	Project # 40240475	Date 01/25/2001 Time Batched
Unocal	Unocal 11720 Unocal rd Edmonds	Leave Plant	Arrive Job 3:30:10 PM

Order # 18752476	Truck # 2029762	Driver/Hauler C258, CEDAR GROVE	Leave Job	Arrive Plant
---------------------	--------------------	------------------------------------	-----------	--------------

Load #	Quantity	Description	Gross	Tare	Net	Weight
26.45	4 Loads 102.27 Ton	1197157 ASPHALT DUMPED BY TON, NO	98,100 Lb	35,280 Lb	52,900 Lb	39,998Kg 16,003Kg 23,995 Kg

SUB-TOTAL	TAX	TRUCK FEE	ORDER TOTAL
-----------	-----	--------------	----------------

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X Ray Jones
 CUSTOMER SIGNATURE

846644



Customer # 3062552	Sold To EMERALD SERVICES INC	Plant # 1875	Ticket # 75244335
Job	Delivery Address	Date 01/12/01	
Unocal P.O.#	Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475	Time Batched
Unocal Zone	Unocal 11720 Unocal rd Edmonds	Due Time	
		Leave Plant	Arrive Job
		9:34:45 AM	


Order # 18752476	Truck # 2029762	Driver/Hauler C258, CEDAR GROVE	Leave Job	Arrive Plant
---------------------	--------------------	------------------------------------	-----------	--------------

		PRODUCTION DESCRIPTION		AMOUNT	
30.34	1 Load 30.34 Ton	Gross Tare Net	95,960 Lb 35,200 Lb 60,680 Lb	43,527Kg 16,003Kg 27,524 Kg	
		1197157 ASPHALT DUMPED BY TON, NO			

SUB-TOTAL	TAX	NET TOTAL	GRAND TOTAL
-----------	-----	-----------	-------------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as an additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X 
 CUSTOMER SIGNATURE

846910



Plant # 1875 Ticket # 75244339


Customer # 3062552	Sold To EMERALD SERVICES INC	Date 10/1/2000	
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475	Time Batched
P.O.# Unocal	Instructions Unocal 11720 Unocal rd Edmonds	Due Time	
Zone		Leave Plant 9:50:02 AM	Arrive Job

Order # 1875247	Truck # 205175	Driver/Hauler C253, CEDAR GROVE	Leave Job	Arrive Plant
-----------------	----------------	------------------------------------	-----------	--------------

QUANTITY	UNIT	DESCRIPTION	TARE	NET	WEIGHT	AMOUNT
33.70	2 Loads 64.04 Ton	1197157 ASPHALT DUMPED BY TON, NO	39,040 Lb	67,400 Lb	17,708 Kg 30,572 Kg	

SUB-TOTAL TAX TICKET TOTAL ORDER TOTAL

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.
 LOAD RECEIVED BY:
 X CUSTOMER SIGNATURE 

844006



Plant # 1875 Ticket # 75244359

Customer # 3062552	Sold To EMERALD SERVICES INC	Project # 40240475	Date 0/1/2001
Job	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Time Batched	
Unocal P.O.#	Instructions	Due Time	
Unocal	Unocal 11720 Unocal rd Edmonds	Leave Plant 10:42:56 AM	Arrive Job

Order # 18752476	Truck # 2029718	Driver/Hauler C252, CEDAR GROVE	Leave Job	Arrive Plant
---------------------	--------------------	------------------------------------	-----------	--------------

QTY	UNIT	DESCRIPTION	WEIGHT	AMOUNT
25.03	3 Loads 89.07 Ton	MANUAL WEIGHT 1197157 ASPHALT DUMPED BY TON, NO	Gross 89,400 Lb Tare 39,340 Lb Net 50,060 Lb 40,552Kg 17,845Kg 22,707 Kg	

SUB-TOTAL	TAX	TOTAL	TOTAL
-----------	-----	-------	-------

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE...

LOAD RECEIVED BY:
 X [Signature]
 CUSTOMER SIGNATURE

846920



Plant #	Ticket #
1875	75244

Customer # 3062552	Sold To EMERALD SERVICES INC	Date 07/1/2001
Job	Delivery Address	Time Batched
Unocal P.O.#	Unocal 11720 Unocal rd Edmonds Instructions	Project # 40240475
Unocal	Unocal 11720 Unocal rd Edmonds	Due Time
		Leave Plant
		Arrive Job
11:32:27 AM		

Order # 18752476	Truck # 2029762	Driver/Hauler 0258, CEDAR BROVE	Leave Job	Arrive Plant
---------------------	--------------------	------------------------------------	-----------	--------------

Quantity	Unit	Weight	PRODUCT DESCRIPTION	AMOUNT
30.60	4 Loads	119.67 Ton	1197157 ASPHALT DUMPED BY TON, NO	
		Gross	96,480 Lb	43,763Kg
		Tare	35,280 Lb	16,003Kg
		Net	61,200 Lb	27,760 Kg

SUB-TOTAL	TAX	TICKET TOTAL	ORDER TOTAL
-----------	-----	--------------	-------------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X [Signature]
 CUSTOMER SIGNATURE

846929



Plant # 1875 Ticket # 75244416

Customer # 3062552	Sold To EMERALD SERVICES INC		Date 10/1/200
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475	Time Batched
P.O.# Unocal	Instructions Unocal 11720 Unocal rd Edmonds		Due Time
Zone		Leave Plant 12:38:30 PM	Arrive Job

Order # 187524	Truck # 76 2051733	Driver/Hauler C253, CEDAR GROVE	Leave Job	Arrive Plant
-------------------	-----------------------	------------------------------------	-----------	--------------

			PRODUCT DESCRIPTION		AMOUNT
		Gross	95,860 Lb	43,482Kg	
		Tare	39,040 Lb	17,708Kg	
		Net	56,820 Lb	25,773 Kg	
28.41	5 Loads 149.08 Ton	1197157	ASPHALT DUMPED BY TON, NO		

SUB-TOTAL	TAX	TICKET TOTAL	ORDER TOTAL
-----------	-----	--------------	-------------

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.


All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY
 X CUSTOMER SIGNATURE 

844050



Customer # 3062552	Sold To EMERALD SERVICES INC	Plant # 1875	Ticket # 75244414
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475	Date 0/1/2001
P.O.#	Instructions		Time Batched
Unocal Zone	Unocal 11720 Unocal rd Edmonds		Due Time
		Leave Plant 1:00:25 PM	Arrive Job

Order # 18752476	Truck # 2029718	Driver/Hauler C252, CEDAR GROVE	Leave Job	Arrive Plant
---------------------	--------------------	------------------------------------	-----------	--------------

QUANTITY	UNIT	PRODUCT DESCRIPTION	AMOUNT
29.36	6 Loads 177.44 Ton	1137157 ASPHALT DUMPED BY TON, NO	
		Gross 98,060 Lb Tare 39,340 Lb Net 58,720 Lb	44,480 Kg 17,845 Kg 26,635 Kg

SUB-TOTAL	TAX	TICKET TOTAL	ORDER TOTAL
-----------	-----	--------------	-------------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.
 LOAD RECEIVED BY:
 X Steve [Signature]
 CUSTOMER SIGNATURE

846943



Customer #	Sold To	Plant #	Ticket #
3062552	EMERALD SERVICES INC	1875	7524436
Job	Delivery Address	Project #	Date
Unocal	11720 Unocal rd Edmonds	40240475	01112001
Unocal	EVERETT, WA 98203		Time Batched
Unocal	11720 Unocal rd Edmonds	Leave Plant	Arrive Job
2:23:37 PM			

Order #	Truck #	Driver/Hauler	Leave Job	Arrive Plant
18752476	2029762	C258, CEDAR GROVE		
PRODUCT DESCRIPTION				AMOUNT
27.84	7 Loads 205.28 Ton	1197157 ASPHALT DUMPED BY TON, NO		
		Gross 90,960 Lb Tare 35,280 Lb Net 55,680 Lb	41,259Kg 16,003Kg 25,256 Kg	

SUB-TOTAL **TAX** **TOTAL**

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.


All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X 
 CUSTOMER SIGNATURE

816557



Plant # 1875 Ticket # 75
Date 10/1/200

Customer # 3062552	Sold To EMERALD SERVICES INC		Project # 40240475
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203		Time Batched
P. O. # Unocal	Instructions		Due Time
Zone Unocal	Unocal 11720 Unocal rd Edmonds		Leave Plant 2:46:50 PM


Order # 18752476	Truck # 2051753	Driver/Hauler	C253, CEDAR GROVE	Leave Job	Arrive Plant
------------------	-----------------	---------------	-------------------	-----------	--------------

Quantity	Unit	DESCRIPTION	AMOUNT
28.54	8 Loads 233.02 Ton	1197157 ASPHALT DUMPED BY TON, NO	
Gross		56,120 Lb	43,600Kg
Tare		39,040 Lb	17,708Kg
Net		57,080 Lb	25,891 Kg

SUB-TOTAL TAX ORDER TOTAL

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X CUSTOMER SIGNATURE 
 844069

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.
 All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.
 Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.
 A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

CSR Associated

						Plant # 1875	Ticket # 75244450	
Customer # 1062552	Sold To EMERALD SERVICES INC						Date 8/1/2001	
Job	Delivery Address 11720 Unocal rd Edmonds EVERETT, WA 98203						Project # 40240475	Time Batched
Proposal	Instructions						Due Time	
Unocal	Unocal 11720 Unocal rd Edmonds						Leave Plant	Arrive Job

3:10:14 PM

Order # 18752476	Truck # 2029718	Driver/Hauler	CR52, CEDAR GROVE	Leave Job	Arrive Plant
---------------------	--------------------	---------------	-------------------	-----------	--------------

									PRODUCT DESCRIPTION	AMOUNT
28.83	9 Loads 062.65 Ton	1197157	Gross 97,000 Lb Tare 39,340 Lb Net 57,660 Lb	43,999Kg 17,845Kg 26,154 Kg					ASPHALT DUMPED BY TON, NO	

SUB TOTAL	TAX	TOTAL	TOTAL
-----------	-----	-------	-------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.
 All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.
 Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.
 A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY
 X Name K. M. Jowers
 CUSTOMER SIGNATURE

816565



Customer #	Sold To	Plant #	Ticket #
7062552	EMERALD SERVICES INC	1875	75244523
Job	Delivery Address	Project #	Date
Unocal	11720 Unocal rd Edmonds EVERETT, WA 98203	48240475	01/15/2001
Unocal	Unocal 11720 Unocal rd Edmonds	Leave Plant	Arrive Job
			9:33:14 AM

Order #	Truck #	Driver/Hauler	Leave Job	Arrive Plant
18752476	2023718	C252, CEDAR GROVE		

		PRODUCT DESCRIPTION		AMOUNT
27.89	1 Load 07.89 Ton	Gross Tare Net	95,120 Lb 39,340 Lb 55,780 Lb	43,145Kg 17,845Kg 25,302 Kg
		1197157	ASPHALT DUMPED BY TON, NO	

SUB-TOTAL	TAX	TOTAL	ORDER TOTAL
-----------	-----	-------	-------------

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.


All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY
 X 
 CUSTOMER SIGNATURE

816589



Plant # 1A75 Ticket # 75244592

Customer # 2062552 Job	Sold To EMERALD SERVICES INC	Date 8/24/2001
Project # 40240475	Delivery Address 11720 Unocal rd Edmonds EVERETT, WA 98203	Time Batched
Zone # Unocal	Leave Plant	Arrive Job

12:07:24 PM

Order # 18752476	Truck # 2029710	Driver/Hauler C252, CEDAR GROVE	Leave Job	Arrive Plant
---------------------	--------------------	------------------------------------	-----------	--------------

Quantity	Unit	Product Description	Gross	Tare	Net
32.22	2 Loads 60.11 Ton	1197157 ASPHALT DUMPED BY TON, NO	103,780 Lb	39,340 Lb	64,440 Lb
			47,074Kg	17,845Kg	29,230 Kg

SUB-TOTAL	TAX	TICKET #	CARRIER TOTAL
-----------	-----	----------	---------------

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)

Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.

SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY

X Shane K. Ma
CUSTOMER SIGNATURE

816609



Customer #	Sold To	Plant #	Ticket #
2062552	EMERALD SERVICES INC	1975	75244
Job	Delivery Address	Project #	Date
Proval	Instructions 11720 Unocal rd Edmonds EVERETT, WA 98203	40240475	8/2/2001
Zonecal	Unocal 11720 Unocal rd Edmonds	Leave Plant	Arrive Job
			2:13:36 PM

Order #	Truck #	Driver/Hauler	Leave Job	Arrive Plant
18752476	2029718	C252, CEDAR GROVE		

		PRODUCT DESCRIPTION		AMOUNT	
30.87	3 Loads 90.98 Ton	Gross Tare Net	101,080 Lb. 39,340 Lb. 61,740 Lb.	45,850Kg 17,845Kg 28,005 Kg	1197157 ASPHALT DUMPED BY TON, NO

SUB-TOTAL	TAX	NOV	TOTAL
-----------	-----	-----	-------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.
 LOAD RECEIVED BY:
 X Heane R M
 CUSTOMER SIGNATURE

816622



Associated

Plant # 1875 Ticket # 752446 '5

Customer # 3062552	Sold To EMERALD SERVICES INC		Date 10/2/200
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475	Time Batched
P.O.# Unocal	Instructions Unocal 11720 Unocal rd Edmonds		Due Time
Zone Unocal	Leave Plant 4:30:58 PM		Arrive Job

Order # 187524	Truck # 76	Driver/Hauler 2029718	C252, CEDAR GROVE	Leave Job	Arrive Plant
-------------------	---------------	--------------------------	-------------------	-----------	--------------

QUANTITY	DESCRIPTION	AMOUNT
30.15	4 Loads 121.13 Ton 1197157 ASPHALT DUMPED BY TON, NO	45,196Kg 17,845Kg 27,352 Kg

INSTRUCTION

SUB-TOTAL TAX TOTAL

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X Shane R. Myers
 CUSTOMER SIGNATURE

844230



Plant # 1875 Ticket # 7521

Customer # 0062552	Sold To EMERALD SERVICES INC		Date 10/19/2001
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203		Project # 40240475
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds		Time Batched
Zone			Due Time
		Leave Plant 9:18:10 AM	Arrive Job

Order # 18752476	Truck # 2056766	Driver/Hauler PSS21, PUGET SOUND SOIL	Leave Job	Arrive Plant
------------------	-----------------	--	-----------	--------------

			PRODUCT DESCRIPTION	AMOUNT
28.11	Load 29.11 Ton	1184344	OTHER MATERIAL DUMPED BY	
		Gross	37,600 Lb 44,271Kg	
		Tare	41,380 Lb 18,770Kg	
		Net	56,220 Lb 25,501 Kg	

SUB-TOTAL	TAX	TOTAL	TOTAL
-----------	-----	-------	-------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X [Signature]
 CUSTOMER SIGNATURE

829789

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.
 All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.
 Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.
 A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.



Plant # 1875 Ticket # 75248304

Customer # 062552	Sold To EMERALD SERVICES INC		Date 10/19/200
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edms=EVERETT, WA 98203	Project # 40240475	Time Batched
P.O.# Unocal	Instructions Unocal 11720 Unocal rd Edms		Due Time
Zone		Leave Plant 9:41:25 AM	Arrive Job

Order # 18752478	Truck # 2031379	Driver/Hauler GM75, GARY MCCANN	Leave Job	Arrive Plant
------------------	-----------------	---------------------------------	-----------	--------------

			PRODUCT DESCRIPTION	AMOUNT
		Gross	92,000 Lb	41,731Kg
		Tare	41,290 Lb	18,724Kg
		Net	50,720 Lb	23,006 Kg
25.36	1 Load	1197157	ASPHALT DUMPED BY TON, NO	
	25.36 Ton			

SUB-TOTAL	TAX	TOTAL	ORDER TOTAL
-----------	-----	-------	-------------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED


The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY: 
 X CUSTOMER SIGNATURE

829797

CUSTOMER COPY



Plant # 1875 Ticket # 752

Customer # 3062552	Sold To EMERALD SERVICES INC		Date 10/19/200
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475	Time Batched
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds		Due Time
Zone		Leave Plant 9:51:14 AM	Arrive Job

Order # 1875247	Truck # 202988	Driver/Hauler NT10, WOOD TRUCKING	Leave Job	Arrive Plant
-----------------	----------------	--------------------------------------	-----------	--------------

		PROBID DESCRIPTION		AMOUNT
30.68	2 Loads 50.78 Ton	MANUAL WEIGHT	Gross 102,120 Lb	46,321Kg
			Tare 40,760 Lb	18,489Kg
			Net 61,360 Lb	27,833 Kg
		1184344 OTHER MATERIAL DUMPED BY		

SUB-TOTAL	TAX	NET GROSS TOTAL	ORDER TOTAL
-----------	-----	-----------------	-------------

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE. MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X _____
 CUSTOMER SIGNATURE

829799



Plant # 18 Ticket # 73240669

Customer # 4062552	Sold To EMERALD SERVICES INC	Date 10/22/2001
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds	Time Batched
Zone		Leave Plant 8:57:54 AM
		Arrive Job

Order # 1875247	Truck # 202988	Driver/Hauler	WT10, WOOD TRUCKING	Leave Job	Arrive Job 8:13 AM
-----------------	----------------	---------------	---------------------	-----------	--------------------

			PRODUCT DESCRIPTION	AMOUNT
32.71	1 Load 32.71 Ton	1184344	OTHER MATERIAL DUMPED BY	
		Tare	41,040 Lb	18,616 Kg
		Net	65,420 Lb	29,674 Kg

SUB TOTAL TAX SIGNATURE TOTAL

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURBLINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature as of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property; buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X _____
 CUSTOMER SIGNATURE

830045

CUSTOMER COPY



Plant # 10 Ticket # 752

Customer # 3067552	Sold To EMERGO SERVICES INC		Date 10/22/2000
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40249475	Time Batched
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds		Due Time
Zone		Leave Plant 3:09:47 AM	Arrive Job

Order # 1875247	Truck # 203137	Driver/Hauler GM75, GARY MCCANN	Leave Job	Arrive Plant
-----------------	----------------	------------------------------------	-----------	--------------

		PRODUCT DESCRIPTION		AMOUNT
		Fare	41,200 Lb 18,724Kg	
		Net	59,660 Lb 27,062 Kg	
29.03	Load 29.03 Ton	1197157	ASPHALT DUMPED BY TON, NO	

SUB-TOTAL	TAX	TOTAL	TOTAL
-----------	-----	-------	-------

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X [Signature]
 CUSTOMER SIGNATURE

830052



Plant # 1875 Ticket # 7524860

Customer # 3002032	Sold To EMERALD SERVICES INC		Date 10/22/2008
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475	Time Batched
P.O.# Unocal	Instructions Unocal 11720 Unocal rd Edmonds		Due Time
Zone		Leave Plant 9:14:46 AM	Arrive Job

Order # 1075247	Truck # 300579	Driver/Hauler P5621, PUGET SOUND SUTL	Leave Job	Arrive Plant
-----------------	----------------	--	-----------	--------------

		PRODUCTION DESCRIPTIONS		AMOUNT	
30.05	2 Loads 65.56 Tons	1104344	OTHER MATERIAL DUMPED BY		
		Tare	41,300 Lb	18,770Kg	
		Net	65,700 Lb	29,801 Kg	

SUB-TOTAL TAX TOTAL TOTAL

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X CUSTOMER SIGNATURE [Signature] 830054



Plant # 1075 Ticket # 752

Customer # 3062552	Sold To EMERALD SERVICES INC	Date 10/22/2009
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds	Due Time
Zone		Leave Plant 10:59:00 AM Arrive Job

Order # 197524	Truck # 242984	Driver/Hauler WILLIAMS, WOOD TRUCKING	Leave Job	Arrive Plant
----------------	----------------	--	-----------	--------------

QUANTITY	UNIT	PRODUCT DESCRIPTION	AMOUNT
31.38	3 Loads 76.54 Ton	1104344 OTHER MATERIAL DUMPED BY	
		Tare 41,040 Lb 18,616 Kg	
		Net 62,760 Lb 28,468 Kg	

SUB-TOTAL TAX TOTAL CREDIT TOTAL

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:

X _____
 CUSTOMER SIGNATURE

830090



Plant # 10 Ticket # 75248756

Customer # 3947552	Sold To EMERALD SERVICES INC	Date 10/22/2001
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds	Due Time
Zone		Leave Plant 11:10:16 AM

Order # 187524	Truck # 20313	Driver/Hauler GM75, GARY MCCANN	Leave Job	Arrive Plant
----------------	---------------	------------------------------------	-----------	--------------

QUANTITY	UNIT	DESCRIPTION	AMOUNT
28.06	7 Loads 57.00 Ton	1197157 ASPHALT DUMPED BY TON, NO	
		Tare 41,200 Lb	18,724 Kg
		Net 56,120 Lb	25,456 Kg

SUB-TOTAL TAX TOTAL ORDER TOTAL

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED _____

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.
 All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.
 Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.
 A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.
 LOAD RECEIVED BY: _____
 X _____
 CUSTOMER SIGNATURE

830093

CUSTOMER COPY



Plant # 1075 Ticket # 7524

Customer # 0062552	Sold To EMERALD SERVICES INC		Date 10/22/2001
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475	Time Batched
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds		Due Time
Zone		Leave Plant 11:24:21 AM	Arrive Job

Order # 187524	Truck # 285674	Driver/Hauler PSS01, PUGET SOUND SOIL	Leave Job	Arrive Plant
----------------	----------------	--	-----------	--------------

QUANTITY	UNIT	PRODUCT DESCRIPTION	WEIGHT	AMOUNT
4 Loads	1.99.42 Tons	1184344 OTHER MATERIAL DUMPED BY	Tare 41,380 Lb Net 67,100 Lb	18,770 Kg 30,436 Kg

SUB-TOTAL	TAX	TOTAL	ORDER TOTAL
-----------	-----	-------	-------------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 X [Signature]
 CUSTOMER SIGNATURE

830096

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.
 All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.
 Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.
 A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

CSR Associated

Plant # 1075 Ticket # 75248817

Customer # 3962552	Sold To EMERALD SERVICES INC	Date 10/22/2001
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds	Due Time
Zone		Leave Plant 12:54:46 PM

Order # 107524	Truck # 293137	Driver/Hauler G175, GARY MCCANN	Leave Job	Arrive Plant
----------------	----------------	------------------------------------	-----------	--------------

QUANTITY	UNIT	TARE	NET	PRODUCT DESCRIPTION	AMOUNT
20.58	3 Loads 86.67 Ton		41,280 Lb 57,160 Lb	1197157 ASPHALT DUMPED BY TON, NO	18,724Kg 25,928 Kg

SUB TOTAL TAX TOTAL

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

(Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED _____

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 CUSTOMER SIGNATURE _____ 830126



Plant # 18 Ticket # 752

Customer # 0162352	Sold To EMERALD SERVICES INC		Date 10/22/2000
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98003	Project # 40240475	Time Batched
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds		Due Time
Zone		Leave Plant 1:11:06 PM	Arrive Job

Order # 1875247	Truck # 202989	Driver/Hauler WTLO, WOOD TRUCKING	Leave Job	Arrive Plant
-----------------	----------------	--------------------------------------	-----------	--------------

QUANTITY	UNIT	DESCRIPTION	PRODUCT DESCRIPTION	AMOUNT
33.48	5 Loads 163.37 Ton	1184344 OTHER MATERIAL DUMPED BY	Tare 41,040 Lb 18,616Kg Net 66,960 Lb 30,373 Kg	

SUB-TOTAL TAX TOTAL ORDER TOTAL

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.
 All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.
 Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.
 A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.
 LOAD RECEIVED BY:
 X WLOH
 CUSTOMER SIGNATURE

830130



Plant # 10 Ticket # 7524902

Customer # 000552	Sold To EMERALD SERVICES INC	Date 10/22/2001
Job Unocal	Delivery Address Unocal 11720 Unocal rd Edmonds EVERETT, WA 98203	Project # 40240475
P. O. # Unocal	Instructions Unocal 11720 Unocal rd Edmonds	Time Batched
Zone		Leave Plant 1:19:03 PM

Order # 187524	Truck # 205670	Driver/Hauler PSS21, PUGET SOUND SOLL	Leave Job	Arrive Plant
----------------	----------------	--	-----------	--------------

			PRODUCT DESCRIPTION	QUANTITY	WEIGHT
32.05	6 Loads 196.02 ton	1184344	OTHER MATERIAL DUMPED BY		
			Tare	41,380 Lb	18,770 Kg
			Net	64,100 Lb	29,076 Kg

SUB-TOTAL TAX TOTAL TOTAL

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY: [Signature]

X _____
 CUSTOMER SIGNATURE

830131

CUSTOMER COPY



Customer #		Sold To		Plant #	Ticket #
Job		Delivery Address		Project #	Time Balance
P. O. #	Instructions	Zone		Leave Plant	Arrive Job

Order #	Truck #	Driver/Hauler	Leave Job	Arrive Plant
---------	---------	---------------	-----------	--------------

QTY	UNIT	DESCRIPTION	AMOUNT
30.61	4 Loads	1197157 ASPHALT DUMPED BY TON, NO	

SUBTOTAL	TAX	TOTAL
----------	-----	-------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.

LOAD RECEIVED BY:
 CUSTOMER SIGNATURE

830159

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.

All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.

Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.

A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.



Plant #	Ticket #
	1075 75240 00
Customer #	Sold To
Job	Delivery Address
P.O. #	Instructions
Zone	Leave Plant
	Arrive Job

Order #	Truck #	Driver/Hauler	Leave Job	Arrive Plant
1875	2476	2079904		
WOOD, WOOD TRUCKING				

QUANTITY		PRODUCT DESCRIPTION		WEIGHT	
31.40	7 Loads	1184344 OTHER MATERIAL DUMPED BY			
	287.92 Ton				
		Gross	103,040 Lb	47,102 Kg	
		Tare	41,040 Lb	18,616 Kg	
		Net	62,000 Lb	28,486 Kg	

SUB-TOTAL	TAX	TOTAL	TOTAL
-----------	-----	-------	-------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.
 LOAD RECEIVED BY: W.A.S.
 X _____
 CUSTOMER SIGNATURE 830169

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.
 All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.
 Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.
 A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

CUSTOMER COPY



Customer #	Sold To	Plant #	Ticket #
3062556	EMERALD SERVICES INC		1075
Job	Delivery Address	Project #	Date
Unocal	Unocal 11720 Unocal rd Edmonds		10/24/90
P. O. #	Instructions		Due Time
Unocal	Unocal 11720 Unocal rd Edmonds	43248475	
Zone		Leave Plant	Arrive Job
Unocal	Unocal 11720 Unocal rd Edmonds		10:30:30 PM

Order #	Truck #	Driver/Hauler	Leave Job	Arrive Plant
1875	2476	295971A		

		PRODUCT DESCRIPTION		AMOUNT
	Gross	83,060 Lb	37,676 kg	
	Tare	39,340 Lb	17,845 kg	
	Net	43,720 Lb	19,831 kg	
21.86	1 Load	1184344 OTHER MATERIAL DUMPED BY		

SUB-TOTAL	TAX	ORDER TOTAL
-----------	-----	-------------

PROPERTY DAMAGE RELEASE (TO BE SIGNED IF DELIVERY IS TO BE MADE INSIDE CURB LINE)
 Dear Customer: The driver of this truck is presenting this RELEASE to you for your signature is of the opinion that the size and weight of his truck may possibly cause damage to the premises and/or adjacent property if he places the material in this load where you desire it. It is our wish to help you in every way that we can, but in order to do this, the driver is requesting that you sign this RELEASE relieving him and this supplier from any responsibility from any damage that may occur to the premises and/or adjacent property, buildings, sidewalks, drive-ways, curbs, etc. by the delivery of this material and that you also agree to help him remove mud from the wheels of his vehicle so that he will not litter the public street. Further, as additional consideration, the undersigned agrees to indemnify and hold harmless the driver of this truck and this supplier for any and all damage to the premises and/or adjacent property which may be claimed by anyone to have arisen out of delivery of this order.
 SIGNED

The undersigned promises to pay all costs, including reasonable attorney's fees, incurred in collecting any sums owed.
 All accounts not paid within 30 days of delivery will bear interest at the rate of 18% per annum.
 Not Responsible for Reactive Aggregate or Color Quality. No Claim Allowed Unless Made at Time Material is Delivered.
 A \$40.00 Service Charge and Loss of the Cash Discount will be collected on all Returned Checks.

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE AND SUPPLIER WILL NOT BE RESPONSIBLE FOR ANY DAMAGE CAUSED WHEN DELIVERING INSIDE CURB LINE.
 LOAD RECEIVED BY:
 X Sham
 CUSTOMER SIGNATURE

830384

APPENDIX F
PRODUCT/GROUNDWATER SHIPMENTS DOCUMENTATION



RECEIVED
JAN 14 2002
BY: 9077.01.04

Ms. Linda Dawson
Maul Foster & Alongi
17171 Bothell Way N.E.
Seattle, WA 98155

January 14, 2002

Subject: Free Product Removal from Vacuum Truck Deliveries to
Emerald Service's Airport Way Recycling Facilities

Dear Ms. Dawson:

Emerald Services, Inc (ESI) has on 5 occasions taken "spot checks" regarding oil percentages obtained from random loads disposed at ESI's Airport Way Facility. The following gives a breakdown of those "spot checks":

<i>Bill of Lading & Gallonage Record</i>	Date	Ticket No.	Total QTY	Total Oil QTY	Total %
Truck Numbers #184/ 354	9/10/01	10862	5000	178 gals.	3.6
Truck Numbers Dispose Clean Soil	9/19/01	105591424 8	5000	181	3.6
Truck & Dispose Class 1&2 PCS	10/02/01	14248	5542	200	3.6
Truck Number	11/13/01	07072	2000	70	3.5
TOTALS			17,542	629	3.575

Based on the above percentages and volumes accounted for, ESI believes 2524 gallons of free product was recovered during the work occurring from September 2001 through November 2001.

Should you have questions regarding the above information, please feel free to contact me at (206) 832-3036 and I will do my best to complete this work as soon as possible.

Sincerely,
Emerald Services, Inc.

Joe Comstock

Joe Comstock
Division Construction Manager



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

10862

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>UNOCAL</u>		CONTACT	JOB # <u>32-50263</u>		
ADDRESS <u>Edmonds</u>		PHONE#	LOAD # <u>1</u>		
CITY, STATE, ZIP <u>WA</u>			DATE <u>9/10/01</u>		
CARRIER <u>Emerald Services</u>		PHONE#	DOCUMENT # <u>10862</u>		
CONSIGNEE <u>Emerald Petroleum</u>		CONTACT	TRUCK # <u>229181</u>		
ADDRESS <u>1500 Airport Way So.</u>		PHONE#	PRODUCT TYPE <u>Liq</u>		
CITY, STATE, ZIP <u>Seattle WA</u>			EST. GALLONS <u>5000</u>		
HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	WASTE WATER - NON HAZ		11	5000
	B				
	C				
	D				

A. WPQ # _____ DISP. CODE: _____ C. WPQ # _____ DISP. CODE: G01501
 WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____

WASH OUT: YES () NO ()

TIME IN _____ TIME OUT _____

E. WATER 5000 GALLONS LOCATION L-811 TEST ac, pH = 7.4 DISP. CODE WIP-A

F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____

_____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT

G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____

HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR. Part 261 or 40 CFR Part 761.

UNOCAL
 SHIPPER (PRINT NAME)
 X Sam Dickman
 CARRIER - DRIVER 1 (PRINT NAME)
 X _____
 CARRIER - DRIVER 2 (PRINT NAME)
 X EMERALD Petroleum
 CONSIGNEE (PRINT NAME)
WYSLICH KOSTEPEWIKI

X [Signature]
 SIGNATURE
 X [Signature]
 SIGNATURE
 X _____
 SIGNATURE
 X [Signature]
 SIGNATURE

DATE: 9/10/01
 DATE: 9/10/01
 DATE: _____
 DATE: 9/10/01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

13963

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>Unocal</u>		CONTACT	JOB # <u>32-56363</u>		
ADDRESS <u>11726 Unoco Rd</u>		PHONE#	LOAD # <u>1</u>		
CITY, STATE, ZIP <u>Edmonds WA</u>			DATE <u>9-12-01</u>		
CARRIER <u>BST</u>		PHONE#	DOCUMENT #		
CONSIGNEE <u>EPS</u>		CONTACT	TRUCK # <u>184-354</u>		
ADDRESS <u>1500 Airport way</u>		PHONE#	PRODUCT TYPE <u>Liq</u>		
CITY, STATE, ZIP <u>Seattle WA</u>			EST. GALLONS <u>5000</u>		
HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>Non hazardous liquid</u>	<u>1</u>	<u>π</u>	<u>4563</u>
	B				
	C				
	D	<u>45" = 4563 gal</u>			

A. WPQ # _____ DISP. CODE: G-02905 C. WPQ # _____ DISP. CODE: _____
 WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES () NO (X)
 TIME IN _____ TIME OUT 15:05pm
 E. WATER 4563 GALLONS LOCATION L-P TEST OK PH 7.4 DISP. CODE WTP-1
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR. Part 261 or 40 CFR Part 761.

X Unocal SHIPPER (PRINT NAME) X [Signature] SIGNATURE DATE: 9/12/01
 X Scott Uike CARRIER - DRIVER 1 (PRINT NAME) X Scott Uike SIGNATURE DATE: 9-12-01
 X _____ CARRIER - DRIVER 2 (PRINT NAME) X _____ SIGNATURE DATE: _____
 X KED. CONSIGNEE (PRINT NAME) X [Signature] SIGNATURE DATE: 9-12-01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

13713

BILL OF LADING AND GALLONAGE TICKET

58263

SHIPPER/GENERATOR <u>UNOCAI</u>		CONTACT	JOB # <u>32-50365</u>		
ADDRESS <u>EDmonds WA</u>		PHONE#	LOAD # <u>1</u>		
CITY, STATE, ZIP <u>WA</u>			DATE <u>9 13 01</u>		
CARRIER <u>FBI</u>		PHONE#	DOCUMENT # <u>18713</u>		
CONSIGNEE <u>FPS</u>		CONTACT	TRUCK # <u>184/354</u>		
ADDRESS <u>1000 Airport Way S.</u>		PHONE#	PRODUCT TYPE <u>LIO</u>		
CITY, STATE, ZIP <u>Seattle WA</u>			EST. GALLONS <u>4949</u>		
HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>Non Hazardous</u>		<u>T2</u>	<u>4949</u>
	B	<u>Oily Water</u>			
	C				
	D				

A. WPQ # 60050+ 602905 DISP. CODE: _____ C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____

WASH OUT: YES () NO ()

TIME IN _____ TIME OUT _____

E. WATER 4949 GALLONS LOCATION Lgrt TEST PH 7.3 DISP. CODE WTP-A

F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____

_____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT

G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____

HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR Part 261 or 40 CFR Part 761.

X Unocai
 SHIPPER (PRINT NAME)
Stan Hickman
 CARRIER - DRIVER 1 (PRINT NAME)
 X _____
 CARRIER / DRIVER 2 (PRINT NAME)
Felix Quijano
 CONSIGNEE (PRINT NAME)

X [Signature]
 SIGNATURE
 X [Signature]
 SIGNATURE
 X [Signature]
 SIGNATURE
 X [Signature]
 SIGNATURE

DATE: 9/13/01
 DATE: 9/13/01
 DATE: _____
 DATE: 9/13/01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

10590

BILL OF LADING AND GALLONAGE TICKET

50263

SHIPPER/GENERATOR <u>Unicol</u>		CONTACT	JOB # <u>32-50368</u>		
ADDRESS		PHONE#	LOAD # <u>1</u>		
CITY, STATE, ZIP <u>Edmonds WA</u>			DATE <u>9.13.01</u>		
CARRIER <u>Emerald Services</u>		PHONE#	DOCUMENT #		
CONSIGNEE <u>F.P.S</u>		CONTACT	TRUCK # <u>727</u>		
ADDRESS <u>1500 Airport way</u>		PHONE#	PRODUCT TYPE <u>oil & H₂O</u>		
CITY, STATE, ZIP <u>Seattle WA</u>			EST. GALLONS <u>3,000</u>		
HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>Non-Haz Liquid</u>	<u>1</u>	<u>T.Y</u>	<u>3,000</u>
	B	<u>oil & H₂O</u>			
	C				
	D				

A. WPQ # _____ DISP. CODE: 600501 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

WASH OUT: YES () NO () DUMP DELAY TIME _____
 TIME IN _____ TIME OUT _____
 E. WATER 3000 GALLONS LOCATION L-PIT TEST PH 8.7.3 DISP. CODE WTPA
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____% SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR Part 261 or 40 CFR Part 761.

X Unicol
 SHIPPER (PRINT NAME)
 X Steve Dyett
 CARRIER - DRIVER 1 (PRINT NAME)
 X William S. [Signature]
 CARRIER - DRIVER 2 (PRINT NAME)
 X [Signature]
 CONSIGNEE (PRINT NAME)
 X [Signature]
 SIGNATURE
 DATE: 9/13/01
 DATE: 9-13-01
 DATE: 9/13/01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

10591

BILL OF LADING AND GALLONAGE TICKET

50263

SHIPPER/GENERATOR <i>Unical</i>		CONTACT	JOB # <i>32-50363</i>
ADDRESS		PHONE#	LOAD # <i>2</i>
CITY, STATE, ZIP <i>Edmonds</i>			DATE <i>9-13-01</i>
CARRIER <i>Emerald Services</i>		PHONE#	DOCUMENT #
CONSIGNEE <i>E.P.S.</i>		CONTACT	TRUCK # <i>777</i>
ADDRESS <i>1500 Airport Way S</i>		PHONE#	PRODUCT TYPE <i>oil H2O</i>
CITY, STATE, ZIP <i>Seattle Wa</i>			EST. GALLONS <i>3000</i>

HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<i>Non-Haz Liquid</i>	<i>1</i>	<i>TIT</i>	<i>3,000</i>
	B	<i>oil H2O</i>			
	C				
	D				

A. WPQ # _____ DISP. CODE: *G00501* C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES () NO ()
 TIME IN _____ TIME OUT _____
 E. WATER *3000* GALLONS LOCATION *L-PIT* TEST *OK 7.1* DISP. CODE *WTP-A*
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 761.

X *Unical*
 SHIPPER (PRINT NAME)
 X *Steve Dygert*
 CARRIER - DRIVER 1 (PRINT NAME)
 X _____
 CARRIER - DRIVER 2 (PRINT NAME)
 X *Harry Ambrose*
 CONSIGNEE (PRINT NAME)
 X *[Signature]*
 SIGNATURE
 X *[Signature]*
 SIGNATURE
 X *[Signature]*
 SIGNATURE
 DATE: *9/13/01*
 DATE: *9-13-01*
 DATE: _____
 DATE: *9-13-01*



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

13965

BILL OF LADING AND GALLONAGE TICKET

50263

SHIPPER/GENERATOR <u>Unocal</u>		CONTACT	JOB # <u>32-50363</u>		
ADDRESS <u>11720 Unoco Rd</u>		PHONE#	LOAD #		
CITY, STATE, ZIP <u>Edmonds</u>			DATE <u>9-13-01</u>		
CARRIER <u>BSI</u>		PHONE#	DOCUMENT #		
CONSIGNEE <u>EPS</u>		CONTACT	TRUCK # <u>1794</u>		
ADDRESS <u>1600 Airport way</u>		PHONE#	PRODUCT TYPE <u>Liq</u>		
CITY, STATE, ZIP <u>Seattle wa</u>			EST. GALLONS		
HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>Non hazardous liquid</u>	<u>1</u>	<u>TT</u>	<u>2855</u>
	B				
	C				
	D	<u>58" = 2855 gal</u>			

A. WPQ # _____ DISP. CODE: 602905 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES () NO () TIME IN 1515 TIME OUT 15:50
 E. WATER 2855 GALLONS LOCATION L-Pet TEST OK 7.3 DISP. CODE WTP-A
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 761.

X Unocal SHIPPER (PRINT NAME) X [Signature] SIGNATURE DATE: 9/13/01
 X Scott Ulke CARRIER - DRIVER 1 (PRINT NAME) X Scott Ulke SIGNATURE DATE: 9-13-01
 X _____ CARRIER - DRIVER 2 (PRINT NAME) X _____ SIGNATURE DATE: _____
 X [Signature] CONSIGNEE (PRINT NAME) X [Signature] SIGNATURE DATE: 9/13/01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

10559

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>UNOCAL</u>		CONTACT	JOB # <u>30-50263</u>
ADDRESS		PHONE#	LOAD # <u>01</u>
CITY, STATE, ZIP <u>EDMONDS WA</u>			DATE <u>9/19/01</u>
CARRIER <u>EMERALD SERVICES</u>		PHONE#	DOCUMENT # <u>—</u>
CONSIGNEE <u>E.P.S.</u>		CONTACT	TRUCK # <u>184/354</u>
ADDRESS <u>1500 AIRPORT WY. S.</u>		PHONE#	PRODUCT TYPE
CITY, STATE, ZIP <u>SEATTLE WA</u>			EST. GALLONS

HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>NON-HAZARDOUS LIQUID N.O.S.</u>	<u>1</u>	<u>TT</u>	<u>5036</u>
	B				
	C				
	D	<u>50" 5036</u>			

A. WPQ # _____ DISP. CODE: 600507 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES () NO ()
 TIME IN 1455 TIME OUT 1525
 E. WATER 5036 GALLONS LOCATION L-PIT TEST OK PH 8.1 DISP. CODE WT10-A
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR Part 261 or 40 CFR Part 761.

X UNOCAL SHIPPER (PRINT NAME) DATE: 9/19/01
 X R. RASHOE CARRIER - DRIVER 1 (PRINT NAME) DATE: 9/19/01
 X WILLIAM DENISE CONSIGNEE (PRINT NAME) DATE: 9/19/01

X [Signature] SIGNATURE
 X [Signature] SIGNATURE
 X [Signature] SIGNATURE
 X [Signature] SIGNATURE



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

14127

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>UNOCAL</u>	CONTACT	JOB # <u>32-50263</u>
ADDRESS <u>?</u>	PHONE#	LOAD # <u>01</u>
CITY, STATE, ZIP <u>EDMONDS, WA.</u>		DATE <u>9/25/01</u>
CARRIER <u>EMERALD SERVICES</u>	PHONE#	DOCUMENT # <u>-</u>
CONSIGNEE <u>E.P.S.</u>	CONTACT	TRUCK # <u>184/354</u>
ADDRESS <u>1500 AIRPORT WY. S.</u>	PHONE#	PRODUCT TYPE <u>L</u>
CITY, STATE, ZIP <u>SEATTLE, WA</u>		EST. GALLONS <u>-</u>

HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	NON-HAZARDOUS LIQUID N.O.S	1	TT	4762
	B	GROUND WATER			
	C				
	D	47" = 4762			

A. WPQ # _____ DISP. CODE: 003905 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES () NO ()
 TIME IN 1320 TIME OUT 1340
 E. WATER 4762 GALLONS LOCATION L-81T TEST ok, pH=7.1 DISP. CODE WTP-12
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____% SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 761.

X Unocal
 SHIPPER (PRINT NAME)
J. Kasler
 CARRIER - DRIVER 1 (PRINT NAME)
 X _____
 CARRIER - DRIVER 2 (PRINT NAME)
 X Wojciech Kosciuszko
 CONSIGNEE (PRINT NAME)

X [Signature]
 SIGNATURE
 X [Signature]
 SIGNATURE
 X _____
 SIGNATURE
 X Wojciech Kosciuszko
 SIGNATURE

DATE: 9/25/01
 DATE: 9/25/01
 DATE: _____
 DATE: 9/25/01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

14179

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>UNICA1</u>		CONTACT <u>N/A</u>	JOB # <u>32 50263</u>		
ADDRESS <u>Edmonds</u>		PHONE#	LOAD # <u>1</u>		
CITY, STATE, ZIP <u>WASH</u>			DATE <u>10 2 01</u>		
CARRIER <u>EMERALD SERVICE</u>		PHONE#	DOCUMENT # <u>14179</u>		
CONSIGNEE <u>EMERALD PERTE.</u>		CONTACT <u>N/A</u>	TRUCK # <u>184/359</u>		
ADDRESS <u>1500 Airport Way S</u>		PHONE#	PRODUCT TYPE <u>Liq</u>		
CITY, STATE, ZIP <u>SEATTLE, WASH.</u>			EST. GALLONS <u>5120</u>		
HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>Non-hazardous</u>		<u>TT</u>	<u>5120</u>
	B	<u>old water</u>			
	C				
	D	<u>51 inch</u>			

A. WPQ # 900501 DISP. CODE: _____ C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

WASH OUT: YES () NO ()
 DUMP DELAY TIME _____
 TIME IN _____ TIME OUT _____
 E. WATER 5120 GALLONS LOCATION Lq Pit TEST OK PH 7.0 DISP. CODE WTRA
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR. Part 261 or 40 CFR Part 761.

X SHIPPER (PRINT NAME) Peter Price SIGNATURE [Signature] DATE: _____
 CARRIER - DRIVER 1 (PRINT NAME) _____ SIGNATURE [Signature] DATE: 10/2/01
 CARRIER - DRIVER 2 (PRINT NAME) _____ SIGNATURE _____ DATE: _____
 CONSIGNEE (PRINT NAME) _____ SIGNATURE [Signature] DATE: 10/2/01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

14248

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>Unical</u>		CONTACT <u>N/A</u>	JOB # <u>32-50263</u>		
ADDRESS <u>Edmonds</u>		PHONE#	LOAD # <u>3</u>		
CITY, STATE, ZIP <u>Wash.</u>			DATE <u>10/2/01</u>		
CARRIER <u>EMERALD SERVICES</u>		PHONE#	DOCUMENT # <u>14248</u>		
CONSIGNEE <u>Emerald Petroleum</u>		CONTACT <u>N/A</u>	TRUCK # <u>184/354</u>		
ADDRESS <u>1500 Airport Way S.</u>		PHONE#	PRODUCT TYPE <u>Liq.</u>		
CITY, STATE, ZIP <u>Seattle, Wash</u>			EST. GALLONS <u>0</u>		
HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>Non-Hazardious</u>		<u>TT</u>	<u>5542</u>
	B	<u>oil-water</u>			
	C				
	D	<u>58 inch</u>			

A. WPQ # 200501 DISP. CODE: _____ C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

WASH OUT: YES () NO ()
 DUMP DELAY TIME _____
 TIME IN 1520 TIME OUT 1640
 E. WATER 5542 GALLONS LOCATION Lg Pit TEST OK 6.9 DISP. CODE WTP-A
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 761.

X SHIPPER (PRINT NAME) Peter Trice SIGNATURE Peter Trice DATE: _____
 CARRIER - DRIVER 1 (PRINT NAME) _____ SIGNATURE _____ DATE: 10/2/01
 X CARRIER - DRIVER 2 (PRINT NAME) _____ SIGNATURE _____ DATE: _____
 X CONSIGNEE (PRINT NAME) EMERALD SIGNATURE [Signature] DATE: 10/2/01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

14249

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR	Unical	CONTACT	N/A	JOB #	32-50263
ADDRESS	Edmonds	PHONE#		LOAD #	2
CITY, STATE, ZIP	Wash			DATE	10/2/01
CARRIER	EMERALD SERVICES	PHONE#		DOCUMENT #	14249
CONSIGNEE	EMERALD Part.	CONTACT	N/A	TRUCK #	184/354
ADDRESS	1500 Airport Way S.	PHONE#		PRODUCT TYPE	liq
CITY, STATE, ZIP	Seattle, Wash			EST. GALLONS	

HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	Non-hazardous		TT	5120
	B	oil-water			
	C				
	D	51 inch			

A. WPQ # G00501 DISP. CODE: _____ C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES () NO () TIME IN 1230 TIME OUT _____
 E. WATER: 5120 GALLONS LOCATION L-pit TEST PH 6.9 DISP. CODE WTPA
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR Part 261 or 40 CFR Part 761.

X _____
 SHIPPER (PRINT NAME) Peter Price X Peter Price DATE: _____
 CARRIER - DRIVER 1 (PRINT NAME) SIGNATURE DATE: 10/2/01
 X _____
 CARRIER - DRIVER 2 (PRINT NAME) X Peter Price DATE: _____
 SIGNATURE DATE: _____
 X William Denike X _____ DATE: 10/2/01
 CONSIGNEE (PRINT NAME) SIGNATURE DATE: _____



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

14328

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>UNOCAL EDMONDS</u>		CONTACT <u>Joe Constock</u>	JOB # <u>32-50263</u>
ADDRESS		PHONE# <u>N/A</u>	LOAD # <u>1</u>
CITY, STATE, ZIP <u>EDMONDS WA</u>			DATE <u>OCT 9, 2001</u>
CARRIER <u>ESI</u>		PHONE#	DOCUMENT # <u>14328</u>
CONSIGNEE <u>EPS</u>		CONTACT	TRUCK # <u>184-354</u>
ADDRESS <u>1500 AIRPORT WAY S</u>		PHONE#	PRODUCT TYPE <u>LIP</u>
CITY, STATE, ZIP <u>SEATTLE</u>			EST. GALLONS <u>5120</u>

HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>Non Haz. Oily WATER</u>			<u>5120</u>
	B				
	C				
	D				

A. WPQ # _____ DISP. CODE: 600501 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES () NO () TIME IN 0945 TIME OUT 1
 E. WATER 5120 GALLONS LOCATION Lg Pt TEST OK PH&2 DISP. CODE WTRP
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____% SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR. Part 261 or 40 CFR Part 761.

X UNOCAL
 SHIPPER (PRINT NAME)
 X MALIK NUGURUKA
 CARRIER - DRIVER 1 (PRINT NAME)
 X _____
 CARRIER 2 (PRINT NAME)
 X FATE QUSMUNNO
 CONSIGNEE (PRINT NAME)
 X _____
 SIGNATURE
 X Mali
 SIGNATURE
 X _____
 SIGNATURE
 DATE: 10/9/01
 DATE: 10-9-2001
 DATE: _____
 DATE: 10/9/01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

14330

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>UNOCAL</u>		CONTACT	JOB # <u>30 50263</u>		
ADDRESS <u>Edmonds</u>		PHONE#	LOAD # <u>1</u>		
CITY, STATE, ZIP <u>WA</u>			DATE <u>10 9 01</u>		
CARRIER <u>ESI</u>		PHONE#	DOCUMENT # <u>14330</u>		
CONSIGNEE <u>ERS</u>		CONTACT	TRUCK # <u>184/354</u>		
ADDRESS <u>1500 Airport Way Sd</u>		PHONE#	PRODUCT TYPE <u>Liq</u>		
CITY, STATE, ZIP <u>Seattle WA</u>			EST. GALLONS <u>5120</u>		
HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>NON Hazdr Dours</u>		<u>TT</u>	<u>5120</u>
	B	<u>oily water</u>			
	C				
	D				

A. WPQ # _____ DISP. CODE: 900501 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES () NO () TIME IN 1530 TIME OUT _____
 E. WATER 5120 GALLONS LOCATION Lq Pit TEST PH6.8 DISP. CODE WTR-A
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 761.

X Tami Novak SHIPPER (PRINT NAME) DATE: _____
 X Sam Hickman CARRIER - DRIVER 1 (PRINT NAME) SIGNATURE DATE: 10 9 01
 X _____ CARRIER - DRIVER 2 (PRINT NAME) SIGNATURE DATE: _____
 X Pat Quismundo CONSIGNEE (PRINT NAME) SIGNATURE DATE: 10/9/01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

14046

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>UNOCAL</u>		CONTACT	JOB # <u>32-50263</u>		
ADDRESS <u>104th & UNOCO</u>		PHONE#	LOAD #		
CITY, STATE, ZIP <u>EDMONDS, WA</u>			DATE <u>10-23-01</u>		
CARRIER <u>ESI</u>		PHONE#	DOCUMENT #		
CONSIGNEE <u>EPS</u>		CONTACT	TRUCK # <u>184/354</u>		
ADDRESS <u>1500 AIRPORT WAY SO</u>		PHONE#	PRODUCT TYPE <u>L</u>		
CITY, STATE, ZIP <u>SEATTLE, WA</u>			EST. GALLONS		
HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	NON HAZARDOUS LIQUID		π	4460
	B	COILY WATER			
	C				
	D	44" = 4460			

A. WPQ # _____ DISP. CODE: 600501 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES () NO () TIME IN _____ TIME OUT _____
 E. WATER 4460 GALLONS LOCATION 19th St TEST OR PH. 60 DISP. CODE WTR-A
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 761.

X COLIN WRIGHT SHIPPER (PRINT NAME) X Colin Wright SIGNATURE DATE: 10-23-01
Steve Price CARRIER - DRIVER 1 (PRINT NAME) X Steve Price SIGNATURE DATE: 10-23-01
 X _____ CARRIER - DRIVER 2 (PRINT NAME) X _____ SIGNATURE DATE: _____
 X EPS CONSIGNEE (PRINT NAME) X _____ SIGNATURE DATE: 10/23/01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

10833

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>UNOCAL</u>		CONTACT	JOB # <u>32-50263</u>		
ADDRESS <u>EDMONDS</u>		PHONE#	LOAD # <u>1</u>		
CITY, STATE, ZIP <u>WA</u>			DATE <u>10/24/01</u>		
CARRIER <u>E.C.S.T</u>		PHONE#	DOCUMENT #		
CONSIGNEE <u>E.P.S</u>		CONTACT	TRUCK # <u>779</u>		
ADDRESS <u>1508 AIRPORT WY</u>		PHONE#	PRODUCT TYPE <u>L</u>		
CITY, STATE, ZIP			EST. GALLONS <u>627</u>		
HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>NON HAZARDOUS liquid</u>	<u>1</u>	<u>TT</u>	<u>627</u>
	B				
	C				
	D				

A. WPQ # _____ DISP. CODE: E00501 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES (x) NO () TIME IN 10:40 TIME OUT 11:11
 E. WATER 627 GALLONS LOCATION Lg Pit TEST OK PH 6.0 DISP. CODE WTPA
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 761.

X UNOCAL
 SHIPPER (PRINT NAME)
 X DAN DOYLE
 CARRIER - DRIVER 1 (PRINT NAME)
 X PETE CRISMONO
 CONSIGNEE (PRINT NAME)
 X [Signature]
 SIGNATURE
 X [Signature]
 SIGNATURE
 X [Signature]
 SIGNATURE
 DATE: 10/24/01
 DATE: 10/24/01
 DATE: 10/24/01



7343 EAST MARGINAL WAY SOUTH
SEATTLE, WASHINGTON 98108
(206) 832-3000
FAX: (206) 832-3030
24 HOUR EMERGENCY PHONE: 1-800-424-9300

13716

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>UNOCA</u>		CONTACT	JOB # <u>3250263</u>
ADDRESS <u>Edmond</u>		PHONE#	LOAD # <u>1</u>
CITY, STATE, ZIP <u>WA</u>			DATE <u>10 24 01</u>
CARRIER <u>ESI</u>		PHONE#	DOCUMENT #
CONSIGNEE <u>ESF</u>		CONTACT	TRUCK # <u>157354</u>
ADDRESS <u>1500 Airport WA So.</u>		PHONE#	PRODUCT TYPE <u>LIQ</u>
CITY, STATE, ZIP <u>Seattle</u>			EST. GALLONS <u>4000</u> <u>4000</u>

HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>NON HAZARDOUS</u>			<u>4000</u> <u>4000</u>
	B	<u>WATER</u>			
	C				
	D				

A. WPQ # 600501 DISP. CODE: _____ C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

WASH OUT: YES () NO () DUMP DELAY TIME _____
 TIME IN 1600 TIME OUT 1805
 E. WATER 4000 GALLONS LOCATION L-PT TEST OK PH6.7 DISP. CODE WTP-A
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALB SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR Part 261 or 40 CFR Part 761.

X Sam Hobson X Sam Hobson DATE: _____
 SHIPPER (PRINT NAME) SIGNATURE
 X _____ X Sam Hobson DATE: 10 24 01
 DRIVER - DRIVER 1 (PRINT NAME) SIGNATURE
 X _____ X _____ DATE: _____
 CARRIER - DRIVER 2 (PRINT NAME) SIGNATURE
 X Tracey Umovest X May White DATE: 10-24-01
 CONSIGNEE (PRINT NAME) SIGNATURE



7343 EAST MARGINAL WAY SOUTH SEATTLE, WASHINGTON 98108 (206) 832-3000 FAX: (206) 832-3030 24 HOUR EMERGENCY PHONE: 1-800-424-9300

10064

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR Unocal CONTACT JOB # 32-50263 ADDRESS PHONE# LOAD # 1 CITY, STATE, ZIP Edmonds WA DATE 10-23-01 CARRIER EST. PHONE# DOCUMENT # CONSIGNEE Robanco CONTACT TRUCK # 79 ADDRESS 3rd ave + Jordan PHONE# PRODUCT TYPE Sol CITY, STATE, ZIP Seattle WA EST. GALLONS 1000

A. WPQ # DISP. CODE: C. WPQ # DISP. CODE: B. WPQ # DISP. CODE: D. WPQ # DISP. CODE:

DISPOSAL

DUMP DELAY TIME WASH OUT: YES () NO () TIME IN TIME OUT E. WATER GALLONS LOCATION TEST DISP. CODE F. SOLIDS GALLONS LOCATION TEST DISP. CODE % SUSPENDED SOLIDS BY CENTRIFUGE + GALS SEDIMENT G. OIL/DIESEL/GAS GALLONS LOCATION TEST DISP. CODE HOC'S PCB'S B.S.&W. API LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 761.

X Unocal SHIPPER (PRINT NAME) X Scott Ulke DRIVER - DRIVER 1 (PRINT NAME) CARRIER - DRIVER 2 (PRINT NAME) X CONSIGNEE (PRINT NAME)

X [Signature] SIGNATURE X Scott Ulke SIGNATURE X SIGNATURE X SIGNATURE

DATE: 10/23/01 DATE: 10-23-01 DATE: DATE:



7343 EAST MARGINAL WAY SOUTH SEATTLE, WASHINGTON 98108 (206) 832-3000 FAX: (206) 832-3030 24 HOUR EMERGENCY PHONE: 1-800-424-9300

10836

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR UNOCAL ADDRESS EDMONDS CITY, STATE, ZIP WA WA CARRIER E.C.S.I. CONSIGNEE E.P.S. ADDRESS 1500 AIRPORT WY SO CITY, STATE, ZIP SEA WA

A. WPQ # _____ DISP. CODE: E00501 C. WPQ # _____ DISP. CODE: _____ B. J# _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

WASH OUT: YES (X) NO () TIME IN 07:15 TIME OUT _____ E. WATER 715 GALLONS LOCATION F-P15 TEST OK 9.8 DISP. CODE WPA F. SOLIDS 248 GALLONS LOCATION F-P15 TEST OK DISP. CODE NES 25 (238 GALS.) % SUSPENDED SOLIDS BY CENTRIFUGE + 10 GALS SEDIMENT G. OIL/DIESEL/GAS TRUCK GALLONS LOCATION _____ TEST _____ DISP. CODE _____ HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 781.

X UNOCAL SHIPPER (PRINT NAME) DAN DOYLE DRIVER 1 (PRINT NAME) X CARRIER - DRIVER 2 (PRINT NAME) X CONSIGNEE (PRINT NAME)

X [Signature] SIGNATURE X [Signature] SIGNATURE X [Signature] SIGNATURE X [Signature] SIGNATURE

DATE: 10/25/01 DATE: 10/25/01 DATE: DATE: 10-26-01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

15001

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>Unocal</u>		CONTACT	JOB # <u>32-50263</u>
ADDRESS <u>Edmonds Facility</u>		PHONE#	LOAD # <u>2</u>
CITY, STATE, ZIP <u>Edmonds WA</u>			DATE <u>11-8-01</u>
CARRIER <u>ESTJ</u>		PHONE#	DOCUMENT # <u>15001</u>
CONSIGNEE <u>ESP</u>		CONTACT <u>Rick</u>	TRUCK # <u>735</u>
ADDRESS <u>1500 Airport Way</u>		PHONE# <u>832-3000</u>	PRODUCT TYPE <u>5</u>
CITY, STATE, ZIP <u>Seattle WA 98108</u>			EST. GALLONS <u>2,000</u>

HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>Non-Hazardous Solids</u>		<u>TT</u>	
	B				
	C				
	D				

A. WPQ # _____ DISP. CODE: 603204 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

WASH OUT: YES () NO () DUMP DELAY TIME _____
 TIME IN 4:30 p.m. TIME OUT 5:30 p.m.
 E. WATER _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 F. SOLIDS 4.36 Tons GALLONS LOCATION F Pit TEST O.K. DISP. CODE NRS
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 761.

X N/A SHIPPER (PRINT NAME) X _____ SIGNATURE DATE: 11-8-01
 X Jeremy Campbell CARRIER - DRIVER (PRINT NAME) X _____ SIGNATURE DATE: 11-8-01
 X _____ CARRIER - DRIVER 2 (PRINT NAME) X _____ SIGNATURE DATE: _____
 X R.D. CONSIGNEE (PRINT NAME) X Rick J. Dancy SIGNATURE DATE: 11-8-01



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

15002

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>Unocal</u>		CONTACT	JOB # <u>32-50263</u>
ADDRESS		PHONE#	LOAD # <u>1</u>
CITY, STATE, ZIP <u>Edmonds WA</u>			DATE <u>11-8-01</u>
CARRIER <u>EST</u>		PHONE# <u>832-3000</u>	DOCUMENT # <u>15002</u>
CONSIGNEE <u>ESF</u>		CONTACT <u>Rick</u>	TRUCK # <u>725</u>
ADDRESS <u>1500 Airport Wy</u>		PHONE#	PRODUCT TYPE <u>5</u>
CITY, STATE, ZIP <u>Seattle WA 98108</u>			EST. GALLONS <u>2000</u>

HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>Non-Hazardous Liquid/Solids</u>		<input checked="" type="checkbox"/>	
	B				
	C				
	D				

A. WPQ # _____ DISP. CODE: G032001 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

WASH OUT: YES NO () _____
 DUMP DELAY TIME _____
 TIME IN 12:45 p.m. TIME OUT 1:30
 E. WATER 9.86 Tons ~~GALLONS~~ LOCATION P-31 TEST OK PH 8.2 DISP. CODE ~~WAC 173-303~~ NRS
 F. SOLIDS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 _____ % SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N

Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR, Part 261 or 40 CFR Part 761.

X Unocal
 SHIPPER (PRINT NAME)
Jeremy Campbell
 CARRIER - DRIVER 1 (PRINT NAME)
 X _____
 CARRIER - DRIVER 2 (PRINT NAME)
 X William R. Deniko
 CONSIGNEE (PRINT NAME)
 X _____
 SIGNATURE
 X _____
 SIGNATURE
 X _____
 SIGNATURE
 DATE: 11/8/01
 DATE: 11/8/01
 DATE: _____
 DATE: 11/8/01

Time 18:10:41 Date 11/08/01

104252

3215 4TH AVE. S.
SEATTLE WA 98134

Axles 1 2 3

13740 lb

19820 lb

0 lb

Total 33560 lb

Standard Fee

Time 13:35:47 Date 11/08/01

ID

CN 104237

3215 4TH AVE. S.
SEATTLE WA 98134

Axles 1 2 3

13340 lb

39940 lb

0 lb

Total 53280 lb

Standard Fee

53280
33560

19720

9.86 tons



7343 EAST MARGINAL WAY SOUTH
 SEATTLE, WASHINGTON 98108
 (206) 832-3000
 FAX: (206) 832-3030
 24 HOUR EMERGENCY PHONE: 1-800-424-9300

07072

BILL OF LADING AND GALLONAGE TICKET

SHIPPER/GENERATOR <u>UNOCAL</u>		CONTACT	JOB # <u>32-50263</u>
ADDRESS <u>11720 UNOCO RD</u>		PHONE#	LOAD # <u>1</u>
CITY, STATE, ZIP <u>EDMONDS WA.</u>			DATE <u>11/13/01</u>
CARRIER <u>EC.SI</u>		PHONE#	DOCUMENT #
CONSIGNEE <u>E.P.S</u>		CONTACT	TRUCK # <u>735</u>
ADDRESS <u>1500 AIRPORT WY SO</u>		PHONE#	PRODUCT TYPE <u>L/S</u>
CITY, STATE, ZIP <u>SEA WA.</u>			EST. GALLONS

HM	ITEM #	U.S. DOT DESCRIPTION	#	TYPE	QTY.
	A	<u>NON HAZARDOUS LIQUID</u>	<u>1</u>	<u>TT</u>	<u>2000</u>
	B				
	C				
	D				

A. WPQ # _____ DISP. CODE: B00501 C. WPQ # _____ DISP. CODE: _____
 B. WPQ # _____ DISP. CODE: _____ D. WPQ # _____ DISP. CODE: _____

DISPOSAL

DUMP DELAY TIME _____
 WASH OUT: YES NO ()
 TIME IN 9:58 TIME OUT 10:27
 E. WATER 1975 GALLONS LOCATION F-AT TEST OK pH 8.7 DISP. CODE WTP-A
 F. SOLIDS 25 GALLONS LOCATION F-PIT TEST OK DISP. CODE URS
 _____% SUSPENDED SOLIDS BY CENTRIFUGE + _____ GALS SEDIMENT
 G. OIL/DIESEL/GAS _____ GALLONS LOCATION _____ TEST _____ DISP. CODE _____
 HOC'S _____ PCB'S _____ B.S.&W. _____ API _____ LAB: Y / N


Shipper's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway, vessel and rail according to applicable international and national government regulations and this material is not regulated as a hazardous waste in accordance with WAC 173-303, 40 CFR. Part 261 or 40 CFR Part 761.

X UNOCAL
 SHIPPER (PRINT NAME)
DAN DOYLE
 CARRIER - DRIVER 1 (PRINT NAME)
 X _____
 CARRIER - DRIVER 2 (PRINT NAME)
 X Justin Lohel
 CONSIGNEE (PRINT NAME)

X [Signature]
 SIGNATURE
 X Dan Doyle
 SIGNATURE
 X _____
 SIGNATURE
 X [Signature]
 SIGNATURE

DATE: _____
 DATE: 11/13/01
 DATE: _____
 DATE: 11-13-01

APPENDIX G
DATA VALIDATION AND LABORATORY REPORTS





EcoChem, Inc.

Environmental Science and Chemistry

DATA VALIDATION REPORT

**Unocal Edmonds – Former Bulk Storage
Maul Foster & Alongi, Inc. Project No. 9077.01.04/3**

Prepared for:

Maul Foster & Alongi, Inc.
17171 Bothell Way NE, #264
Seattle, Washington 98155

Prepared by:

EcoChem, Inc.
405 Westland Building
100 South King Street
Seattle, Washington 98104-2885

EcoChem Project Number: C18705-9

January 14, 2002

Approved for Release:

Chris Ransom
Project Manager
EcoChem, Inc.

Introduction

Basis for the Data Validation

This report summarizes the results of cursory (Level II) data validation performed on soil and water samples for the Unocal Edmonds project.

Samples were analyzed by North Creek Analytical and Sequoia Analytical. Analytical methods and EcoChem project chemists are listed below.

Analysis	Method	Primary Review	Secondary Review
Volatile Petroleum Products	NWTPH-Gx	Chris Ransom	Alison Hagee
Semivolatile Petroleum Products	NWTPH-Dx	Chris Ransom	Alison Hagee
BTEX	EPA 8021B	Chris Ransom	Alison Hagee
Polynuclear Aromatic Hydrocarbons (PAH)	EPA 8270 SIM	Chris Ransom	Alison Hagee
Total Suspended Solids (TSS)	EPA 160.2	Chris Ransom	Alison Hagee

The data validation is based on the quality control (QC) criteria documented in the methods listed above and *National Functional Guidelines for Organic and Inorganic Data Review* (USEPA 1994).

Data Qualifier Definitions are located in **Appendix A**. **Appendix B** contains the Qualified Data Summary Table.

SAMPLE INDEX

CLIENT: Maul Foster and Alongi, Inc.
PROJECT NAME: Unocal Edmonds Former Bulk Storage
ECO-CHEM PROJECT No.: C18705-9

Sample ID	Lab ID	Matrix
EX-B-1-5	B110610-01	Soil
EX-B-2-5	B110610-02	Soil
EX-B-3-5	B110610-03	Soil
EX-B-4-5	B110610-04	Soil
EX-B-5-5	B110610-05	Soil
EX-B-6-5	B110610-06	Soil
EX-B-7-5	B110610-07	Soil
EX-B-8-5	B110610-08	Soil
EX-B-9-5	B110610-09	Soil
EX-B-10-5	B110610-10	Soil
EX-A-1-4.5	B110610-11	Soil
EX-A-2-4.5	B110610-12	Soil
EX-A-2-4.5RE1	B110610-12RE1	Soil
EX-A-3-4.5	B110610-13	Soil
EX-A-4-4.5	B110610-14	Soil
EX-A-5-4.5	B110610-15	Soil
EX-A-6-4.5	B110610-16	Soil
EX-A-7-4.5	B110610-17	Soil
EX-A-8-4.5	B110610-18	Soil
EX-A-9-4.5	B110610-19	Soil
EX-A-10-4.5	B110610-20	Soil
EX-A-11-4.5	B110610-21	Soil
MW-D1-0901	B110610-22	Rinsate

Sample ID	Lab ID	Matrix
TP-4-1001	B1J0125-01	Water
TP-5-1001	B1J0125-02	Water
TP-6-1001	B1J0125-03	Water
TP-7-1001	B1J0125-04	Water
TP-8-1001	B1J0125-05	Water
TP-9-1001	B1J0125-06	Water
TP-10-1001	B1J0125-07	Water
TP-11-1001	B1J0125-08	Water
TP-12-1001	B1J0125-09	Water
TP-13-1001	B1J0125-10	Water
TP-14-1001	B1J0125-11	Water
TP-15-1001	B1J0125-12	Water
TP-16-1001	B1J0125-13	Water
TP-17B-1001	B1J0125-14	Water
TP-18-1001	B1J0125-15	Water
TP-19-1001	B1J0125-16	Water
TP-20-1001	B1J0125-17	Water

LEVEL II DATA VALIDATION REPORT
Volatile Petroleum Products by Method NWTPH-Gx
Semivolatile Petroleum Products by Method NWTPH-Dx
BTEX by EPA Method 8021B
Polynuclear Aromatic Hydrocarbons (PAH) by EPA Method 8270 SIM
Total Suspended Solids by EPA Method 160.2
Matrix: Soil and Water
SDG Numbers: B1I0610 and B1J0125

Analytical data for 21 soil samples, 17 water samples, and one field blank were reviewed using quality control (QC) criteria documented in the analytical method and *National Functional Guidelines for Organic and Inorganic Data Review* (USEPA, 1994). The samples were collected September 27 and October 2, 2001 and were analyzed by North Creek Analytical, Inc., Bothell, WA and Sequoia Analytical, Petaluma, CA. A complete listing of samples reviewed is given in the **Sample Index**.

I. COMPLETENESS

All contract-required deliverables were submitted by the laboratory. The laboratory followed contract-required corrective action processes, and anomalies were discussed in the case narrative.

II. TECHNICAL DATA VALIDATION

The QC requirements that were reviewed are listed below.

- * Technical Holding Times and Sample Receipt Conditions
- * Blanks (Method and Field)
- * Laboratory Control Sample
- * Surrogate Compounds
- * Matrix Spike/Matrix Spike Duplicates (MS/MSD)
- Laboratory Duplicates
- Field Duplicates
- * Sample Results

Those items marked with an asterisk (*) did not meet all specified QC criteria and are discussed below. QC items not marked with an asterisk meet all QC criteria. Qualified data are listed in the Qualified Data Summary Table in **Appendix B**.

Technical Holding Times and Sample Receipt Conditions

B1I0610

PAH

Sample EX-A-2-4.5 (RE1) was re-extracted 7 days past the 14-day holding time criterion. The sample was originally extracted within the holding time, but was re-extracted and re-analyzed due to surrogate recovery value less than 10%. The original results were qualified do-not-report (DNR-13). The re-extraction results were qualified as estimated (J/UJ-1) to indicate a potential low bias.

NWTPH-Dx

Sample EX-B-1-5 RE1 was re-extracted 5 days past the 14-day holding time criterion. The sample was originally extracted within the holding time, but was re-extracted and re-analyzed due to a surrogate recovery outlier. The result from the original analysis was used and the results from the re-extraction were qualified do-not-report (DNR-1).

B1J0125

NWTPH-G & BTEX

All three VOA containers for sample TP-13-1001 contained headspace. The NWTPH-G and BTEX results for this sample were all non-detects; reporting limits were qualified as estimated (UJ-2) to indicate a potential low bias.

NWTPH-Dx

The samples were re-extracted 7 days past the 14-day holding time criterion. The samples were originally extracted within the holding time, but were re-extracted and re-analyzed due to laboratory control sample duplicate recovery outliers. The result from the original analysis was used and the results from the re-extraction were qualified do-not-report (DNR-1).

Blanks

B1I0610

One rinsate blank, MW-D1-0901, was submitted with this SDG. There were no positive results reported for this sample. Due to an extraction error by the laboratory, there are no NWTPH-Dx results reported for this sample, as there was insufficient sample remaining for re-extraction.

Laboratory Control Samples

B1J0125

NWTPH-Dx

The percent recovery (%R) value for diesel (39.4%) in the laboratory control sample duplicate (LCSD) was less than the lower control limit of 75%. The laboratory control sample (LCS) result was acceptable; therefore no action was taken based on the LCSD %R outlier.

B1L0610

PAH

The %R value for fluorene (73%) in the LCS for batch 1J08018 was less than the lower control limit of 75%. The LCSD result was acceptable; therefore no action was taken based on the LCS %R outlier.

The %R values for chrysene (73%) and indeno(1,2,3-cd)pyrene (73%) in the LCS for batch 1J08027 were less than the lower control limit of 75%. The LCSD results were acceptable, therefore no action was taken based on the LCS %R outliers.

The %R values for indeno(1,2,3-cd)pyrene (64% & 58%) in the LCS/LCSD for batch 1J18001 were less than the lower control limit of 75%. The reporting limit for this compound in the associated sample (EX-A-2-4.5 RE) was qualified as estimated (UJ-10) to indicate a potential low bias.

Surrogate Recovery

B1I0610

NWTPH-G

The 4-BFB %R values on the FID detector for Samples EX-B-9-5 (165%) and EX-A-5-4.5 (174%) were greater than the upper control limit of 147%. The reported gasoline range hydrocarbon results for these samples were qualified as estimated (J-13) to indicate a potential high bias.

BTEX

The 4-BFB %R value on the PID detector for Sample EX-A-8-4.5 (163%) was greater than the upper control limit of 123%. The BTEX results for this sample were all positive and were qualified as estimated (J-13) to indicate a potential high bias.

NWTPH-Dx

The 2-FBP %R value for Sample EX-B-1-5 (182%) was greater than the upper control limit of 150%. The diesel range organic result for this sample was qualified as estimated (J-13) to indicate a potential high bias.

In addition, the octacosane %R value for this sample (45.4%) was less than the lower control limit of 50%. The reporting limit for the Lube Oil range hydrocarbons was qualified as estimated (UJ-13) to indicate a potential low bias.

Matrix Spike and Matrix Spike Duplicate

B1I0610

NWTPH-G

The matrix spike/matrix spike duplicate (MS/MSD) %R values for gasoline range hydrocarbons (71.2% & 70%) were less than the lower control limit of 75%. The parent sample was not in this SDG; therefore no action was taken.

PAH

The MS/MSD %R values for chrysene (71% & 71%) and indeno(1,2,3-cd)pyrene (71% & 71%) in batch 1J08018 were less than the lower control limit of 75%. The reporting limits for these compounds in the parent sample, EX-B-7-5, were qualified as estimated (UJ-8) to indicate a potential low bias.

The MS/MSD %R values for indeno(1,2,3-cd)pyrene (46% & 62%) in batch 1J08027 were less than the lower control limit of 75%. The reporting limit for this compound in the parent sample, EX-A-11-4.5, was qualified as estimated (UJ-8) to indicate a potential low bias.

The MS/MSD %R values for indeno(1,2,3-cd)pyrene (70% & 64%) in batch 1J18001 were less than the lower control limit of 75%. The parent sample was not in this SDG; therefore no action was taken.

The MS/MSD %R values for fluorene (410% & 350%) in batch 1J03030 were greater than the upper control limit of 125%. The parent sample was not in this SDG; therefore no action was taken.

Field Duplicates

B1I0610

Two field duplicate pairs (EX-A-3-4.5/EX-A-11-4.5 and EX-B-8-5/EX-B-10-5) were submitted with this SDG. All relative percent difference (RPD) values were less than the control limit of 50% for sample results greater than 5x the reporting limit.

Sample Results

The laboratory flagged several sample results for gasoline range hydrocarbons "G-01" to indicate that the reported results for the gasoline range were primarily due to overlap for the diesel range hydrocarbon pattern. The results for these data were qualified as estimated (J-14) to indicate a potential high bias. The laboratory flagged several BTEX results "I-06" to indicate that the concentration reported may be artificially elevated due to coeluting compounds or components. These BTEX results were qualified as estimated (J-14) to indicate a potential high bias.

For Samples EX-B-1-5 in SDG B1I0610 and TP-19-1001 in SDG B1J0125, there was a significant difference between the results from the original NWTPH-Dx analyses and the results of the re-extractions. For both of these samples, the re-extractions were performed outside of the holding time and were qualified as do-not-report (DNR-1). The reported diesel results from the

original analyses were qualified as estimated (J-9) based on the lack of precision for these analyses.

III. OVERALL ASSESSMENT

As was determined by this evaluation, the laboratory followed the specified analytical methods. The MS/MSD, laboratory duplicate, and field duplicate RPD values indicated acceptable precision. Accuracy was also acceptable, as demonstrated by the surrogate, MS/MSD, and laboratory control sample recovery results, with the exceptions previously noted.

Data were qualified because of exceeded holding times, headspace in VOA vials, matrix interference, poor agreement between original results and results from re-extractions and MS/MSD, surrogate, and laboratory control sample recovery outliers.

Data were qualified as do-not-report (DNR) to indicate which values should be used from multiple reported results and should not be used for any purpose.

All other data, as qualified, are acceptable for use.



EcoChem, Inc.

Environmental Science and Chemistry

APPENDIX A DATA QUALIFIER DEFINITIONS

DATA VALIDATION QUALIFIER CODES

National Functional Guidelines

The following definitions provide brief explanations of the qualifiers assigned to results in the data review process.

U	The analyte was analyzed for, but was not detected above the reported sample quantitation limit.
J	The analyte was positively identified; the associated numerical value is the approximate concentration of the analyte in the sample.
N	The analysis indicates the presence of an analyte for which there is presumptive evidence to make a "tentative identification".
NJ	The analysis indicates the presence of an analyte that has been "tentatively identified" and the associated numerical value represents its approximate concentration.
UJ	The analyte was not detected above the reported sample quantitation limit. However, the reported quantitation limit is approximate and may or may not represent the actual limit of quantitation necessary to accurately and precisely measure the analyte in the sample.
R	The sample results are rejected due to serious deficiencies in the ability to analyze the sample and meet quality control criteria. The presence or absence of the analyte cannot be verified.

The following is an EcoChem qualifier that may also be assigned in the data review process:

DNR	Do-not-report. Duplicate results exist due to reanalyses. This result should not be reported.
-----	---

DATA QUALIFIER REASON CODES

1	Holding Times
2	Sample Preservation
3	Sample Custody
4	Missing Deliverables
5A	Calibration (initial)
5B	Calibration (continuing)
6	Field Blanks
7	Laboratory Blanks
8	Matrix Spike
9	Precision (Duplicate, or Matrix Spike Duplicate)
10	Laboratory Control Sample
11	Detection Limit
12	Standards
13	Surrogates
14	Other
15	Furnace QC
16	ICP Serial Dilution
17	Chemical Recoveries
18	Trip Blanks
19	Internal Standards
20	Linear Range Exceeded
21	Potential False Positives



EcoChem, Inc.

Environmental Science and Chemistry

APPENDIX B
DATA QUALIFIER SUMMARY TABLE

QUALIFIED DATA SUMMARY TABLE
SDGs B110610 and B1J0125

Field ID	Analysis	Method	Analyte	Conc.	Units	Qualifier	Reason Code
EX-B-1-5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	1950	mg/kg	J	14
EX-B-1-5	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	1570	mg/kg	J	9,13
EX-B-1-5	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	125	mg/kg	UJ	13
EX-B-1-5RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	3740	mg/kg	DNR	1
EX-B-1-5RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	219	mg/kg	DNR	1
EX-B-2-5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	112	mg/kg	J	14
EX-B-2-5	BTEX	8021B	Xylenes	0.23	mg/kg	J	14
EX-B-3-5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	66.6	mg/kg	J	14
EX-B-5-5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	2020	mg/kg	J	14
EX-B-5-5	BTEX	8021B	Xylenes	2.46	mg/kg	J	14
EX-B-6-5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	1560	mg/kg	J	14
EX-B-6-5	BTEX	8021B	Xylenes	7.05	mg/kg	J	14
EX-B-7-5	PAH	8270 SIM	Chrysene	0.01	mg/kg	UJ	8
EX-B-7-5	PAH	8270 SIM	Indeno(1,2,3-cd)pyrene	0.01	mg/kg	UJ	8
EX-B-9-5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	146	mg/kg	J	13,14
EX-A-2-4.5	PAH	8270 SIM	Acenaphthene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Acenaphthylene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Anthracene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Benzo(a)anthracene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Benzo(a)pyrene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Benzo(b)fluoranthene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Benzo(g,h,i)perylene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Benzo(k)fluoranthene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Chrysene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Dibenz(a,h)anthracene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Fluoranthene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Fluorene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Indeno(1,2,3-cd)pyrene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	1-Methylnaphthalene	0.0051	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	2-Methylnaphthalene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Naphthalene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Phenanthrene	ND	mg/kg	DNR	13
EX-A-2-4.5	PAH	8270 SIM	Pyrene	ND	mg/kg	DNR	13
EX-A-2-4.5RE1	PAH	8270 SIM	Acenaphthene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Acenaphthylene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Anthracene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Benzo(a)anthracene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Benzo(a)pyrene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Benzo(b)fluoranthene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Benzo(g,h,i)perylene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Benzo(k)fluoranthene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Chrysene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Dibenz(a,h)anthracene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Fluoranthene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Fluorene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Indeno(1,2,3-cd)pyrene	0.01	mg/kg	UJ	1,10
EX-A-2-4.5RE1	PAH	8270 SIM	1-Methylnaphthalene	0.014	mg/kg	J	1
EX-A-2-4.5RE1	PAH	8270 SIM	2-Methylnaphthalene	0.0037	mg/kg	J	1
EX-A-2-4.5RE1	PAH	8270 SIM	Naphthalene	0.01	mg/kg	UJ	1

QUALIFIED DATA SUMMARY TABLE
SDGs B1I0610 and B1J0125

Field ID	Analysis	Method	Analyte	Conc.	Units	Qualifier	Reason Code
EX-A-2-4.5RE1	PAH	8270 SIM	Phenanthrene	0.01	mg/kg	UJ	1
EX-A-2-4.5RE1	PAH	8270 SIM	Pyrene	0.01	mg/kg	UJ	1
EX-A-5-4.5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	363	mg/kg	J	13,14
EX-A-6-4.5	BTEX	8021B	Benzene	1.36	mg/kg	J	14
EX-A-7-4.5	BTEX	8021B	EthylBenzene	0.0628	mg/kg	J	14
EX-A-7-4.5	BTEX	8021B	Xylenes	0.123	mg/kg	J	14
EX-A-8-4.5	BTEX	8021B	Benzene	1.62	mg/kg	J	13
EX-A-8-4.5	BTEX	8021B	Toluene	0.231	mg/kg	J	13,14
EX-A-8-4.5	BTEX	8021B	EthylBenzene	3.94	mg/kg	J	13,14
EX-A-8-4.5	BTEX	8021B	Xylenes	3.39	mg/kg	J	13,14
EX-A-9-4.5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	13.2	mg/kg	J	14
EX-A-10-4.5	BTEX	8021B	Toluene	0.0596	mg/kg	J	14
EX-A-11-4.5	PAH	8270 SIM	Indeno(1,2,3-cd)pyrene	0.01	mg/kg	UJ	8
TP-4-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	ND	mg/L	DNR	1
TP-4-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-5-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	ND	mg/L	DNR	1
TP-5-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-6-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	ND	mg/L	DNR	1
TP-6-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-7-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	2.59	mg/L	DNR	1
TP-7-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-8-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	0.534	mg/L	DNR	1
TP-8-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-9-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	ND	mg/L	DNR	1
TP-9-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-10-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	0.848	mg/L	DNR	1
TP-10-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-11-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	0.989	mg/L	DNR	1
TP-11-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-12-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	1.37	mg/L	DNR	1
TP-12-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-13-1001	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	50	ug/L	UJ	2
TP-13-1001	BTEX	8021B	Benzene	0.5	ug/L	UJ	2
TP-13-1001	BTEX	8021B	Toluene	0.5	ug/L	UJ	2
TP-13-1001	BTEX	8021B	EthylBenzene	0.5	ug/L	UJ	2
TP-13-1001	BTEX	8021B	Xylenes	0.5	ug/L	UJ	2
TP-13-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	0.699	mg/L	DNR	1
TP-13-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-14-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	ND	mg/L	DNR	1
TP-14-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-15-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	0.269	mg/L	DNR	1
TP-15-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-16-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	0.726	mg/L	DNR	1
TP-16-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-17B-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	ND	mg/L	DNR	1
TP-17B-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-18-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	4.6	mg/L	DNR	1
TP-18-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-19-1001	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	1.57	mg/L	J	9

QUALIFIED DATA SUMMARY TABLE
SDGs B1I0610 and B1J0125

Field ID	Analysis	Method	Analyte	Conc.	Units	Qualifier	Reason Code
TP-19-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	22.8	mg/L	DNR	1
TP-19-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1
TP-20-1001RE1	TPH	NWTPH-Dx	Diesel Range Hydrocarbons	0.543	mg/L	DNR	1
TP-20-1001RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	ND	mg/L	DNR	1



EcoChem, Inc.

Environmental Science and Chemistry

DATA VALIDATION REPORT

Unocal Edmonds - Terminal
Maul Foster & Alongi, Inc. Project No. 9077.01.04/3

Prepared for:

Maul Foster & Alongi, Inc.
17171 Bothell Way NE, #264
Seattle, Washington 98155


Prepared by:

EcoChem, Inc.
405 Westland Building
100 South King Street
Seattle, Washington 98104-2885

EcoChem Project Number: C18705-8

December 5, 2001

Approved for Release:


Chris Ransom
Project Manager
EcoChem, Inc.

Introduction

Basis for the Data Validation

This report summarizes the results of cursory (Level II) data validation performed on soil samples for the Unocal Edmonds project.

Samples were analyzed by North Creek Analytical. Analytical methods and EcoChem project chemists are listed below.

Analysis	Method	Primary Review	Secondary Review
Volatile Petroleum Products	NWTPH-Gx	Mark Brindle	Chris Ransom
Semivolatile Petroleum Products	NWTPH-Dx	Mark Brindle	Chris Ransom
BTEX	EPA 8021B	Mark Brindle	Chris Ransom
Polynuclear Aromatic Hydrocarbons (PAH)	EPA 8270 SIM	Mark Brindle	Chris Ransom
Total Organic Carbon (TOC)	EPA 9060	Mark Brindle	Chris Ransom

The data validation is based on the quality control (QC) criteria documented in the methods listed above and *National Functional Guidelines for Organic and Inorganic Data Review* (USEPA 1994).

Data Qualifier Definitions are located in **Appendix A**. **Appendix B** contains the Qualified Data Summary Table.

LEVEL II DATA VALIDATION REPORT
Volatile Petroleum Products by Method NWTPH-Gx
Semivolatile Petroleum Products by Method NWTPH-Dx
BTEX by EPA Method 8021B
Polynuclear Aromatic Hydrocarbons (PAH) by EPA Method 8270 SIM
Total Organic Carbon by EPA Method 9060 modified
Matrix: Soil
SDG Numbers: B1I0340, B1J0473, B1I0530 and B1I0558

Analytical data for 33 soil field samples were reviewed using quality control (QC) criteria documented in the analytical method and *National Functional Guidelines for Organic and Inorganic Data Review* (USEPA, 1994). The samples were collected September 18, 25, and 26, and October 16, 2001 and were analyzed by North Creek Analytical, Inc. (NCA). A complete listing of samples reviewed is given in the **Sample Index**.

I. COMPLETENESS

All contract-required deliverables were submitted by the laboratory. The laboratory followed contract-required corrective action processes, and anomalies were discussed in the case narrative.

II. TECHNICAL DATA VALIDATION

The QC requirements that were reviewed are listed below.

- * Technical Holding Times and Sample Receipt Conditions
Blanks (Method and Field)
- * Laboratory Control Sample
Surrogate Compounds
- * Matrix Spike/Matrix Spike Duplicates (MS/MSD)
Laboratory Duplicates
- * Field Duplicates
- * Sample Results

Those items marked with an asterisk (*) did not meet all specified QC criteria and are discussed below. QC items not marked with an asterisk meet all QC criteria. Qualified data are listed in the Qualified Data Summary Table in **Appendix B**.

Technical Holding Times and Sample Receipt Conditions

B1I0340

The cooler temperature upon receipt at the laboratory (22.5 °C) was greater than the required 4°C ± 2 °C. No action was taken as the samples were received 1 hour after sampling.

B1I0530

The cooler temperature upon receipt at the laboratory (10.9 °C) was greater than the required $4^{\circ}\text{C} \pm 2^{\circ}\text{C}$. The sample results were judged to be not significantly affected by the non-compliant temperature, therefore no action was taken.

B1I0558

NWTPH-Dx

Samples EX-D-2-3.5RE1, EX-D-4-3.5RE1 and EX-D-7-3.5RE1 were re-extracted 6 days past the 14-day holding time criterion. The samples were originally extracted within holding time, but were re-extracted and re-analyzed due to surrogate outliers. The original results were qualified do-not-report (DNR). The re-extraction results were qualified as estimated (J/UJ-1) to indicate a potential low bias.

Matrix Spike and Matrix Spike Duplicate

B1I0340

NWTPH-G

The matrix spike/matrix spike duplicate (MS/MSD) percent recovery values (%R) for gasoline range hydrocarbons (54.8%/60.9%) were less than the lower control limit of 75%. The GRO result in the parent sample (EX-C-3-4) was qualified as estimated (J-8) to indicate a potential low bias.

BTEX

The MS/MSD %R values for ethyl benzene (65.8%/66.4%) and total xylenes (64.3%/64.9%) were less than the lower control limit of 75%. The parent sample was not in this SDG; therefore no action was taken.

PAH

The MS/MSD %R values for fluorene (170%/170%) were greater than the upper control limit of 125%. The parent sample was not in this SDG; therefore no action was taken.

B1I0530

PAH

The MS/MSD %R values for fluorene (410%/350%) were greater than the upper control limit of 125%. The fluorene result in the parent sample (TP-13-5-E) was qualified as estimated (J-8) to indicate a potential high bias.

B1I0558

PAH

The MS/MSD %R values for chrysene (71%/71%) and indeno(1,2,3-cd)pyrene (71%/71%) were less than the lower control limit of 75%. The parent sample was not in this SDG; therefore no action was taken.

B1J0473

NWTPH-G

The MS %R value for gasoline range hydrocarbons (71.2%) was less than the lower control limit of 75%. The MSD and LCS values were acceptable; therefore no action was taken.

BTEX

The MS/MSD %R values for benzene (68.3%/69.9%) were less than the lower control limit of 75%. The parent sample was not in this SDG; therefore no action was taken.

PAH

The MS/MSD %R values for indeno(1,2,3-cd)pyrene (61%/52%) were less than the lower control limit of 75%. The parent sample was not in this SDG; therefore no action was taken.

Laboratory Control Sample

B1I0558

PAH

The blank spike (BS) % R value for fluorene (73%) was less than the lower control limit of 75%. The reported fluorene results in all samples were positive and were qualified as estimated (J-10) to indicate a potential low bias.

B1J0473

PAH

The blank spike/blank spike duplicate (BS/BSD) %R values for indeno(1,2,3-cd)pyrene (73%/61%) and the BSD %R value for chrysene (64%) were less than the lower control limit of 75%. The reporting limits for the compounds in the associated samples were qualified as estimated (UJ-10) to indicate a potential low bias.

Field Duplicates

B1I0340

One field duplicate set (EX-C-1-4 and EX-C-5-4) was submitted with this SDG. All relative percent difference (RPD) values were less than the control limit of 50% for sample results greater than 5x the reporting limit with the following exceptions:

BTEX: The RPD value for total xylenes (50.9%) was greater than the control limit. The total xylenes results for these samples were qualified as estimated (J-9).

PAH: The RPD value for 1-methylnaphthalene (52.2%) was greater than the control limit. The 1-methylnaphthalene results for these samples were qualified as estimated (J-9). Chrysene was detected in Sample EX-C-1-4 but not detected in Sample EX-C-5-4. The difference between the detected result and the reporting limit (RL) was greater than 2x the RL. The chrysene results for these samples were qualified as estimated, (J/UJ-9).

B1I0558

Two field duplicate sets (TP-18-5.8-S and TP-22-5.8-S) and (EX-D-4-3.5 and EX-D-7-3.5) were submitted with this SDG. All RPD values were less than the control limit of 50% for sample results greater than 5x the reporting limit with the following exception:

BTEX: The RPD value for ethylbenzene (52.6%) was greater than the control limit for field duplicate pair TP-18-5.8S/TP-22-5.8-S. The ethylbenzene results for these samples were qualified as estimated (J-9).

Sample Results

The laboratory flagged several sample results for gasoline range hydrocarbons "G-01" to indicate that the reported results for the gasoline range were primarily due to overlap for the diesel range hydrocarbon pattern. The results for these data were qualified as estimated (J-14) to indicate a potential high bias. The laboratory flagged several BTEX results "I-06" to indicate that the concentration reported may be artificially elevated due to coeluting compounds or components. These BTEX results were qualified as estimated (J-14) to indicate a potential high bias.

III. OVERALL ASSESSMENT

As was determined by this evaluation, the laboratory followed the specified analytical methods. The MS/MSD, laboratory duplicate, and field duplicate RPD values indicated acceptable precision, with the noted exceptions. Accuracy was also acceptable, as demonstrated by the surrogate, MS/MSD, and laboratory control sample recovery results, with the exceptions previously noted.

Data were qualified do-not-report (DNR) to indicate which values should be used from multiple reported results and should not be used for any purpose.

Data were qualified because of matrix interference and surrogate recovery, laboratory control sample recovery, and field duplicate precision outliers.

All data, as qualified, are acceptable for use.



EcoChem, Inc.

Environmental Science and Chemistry

APPENDIX A DATA QUALIFIER DEFINITIONS

DATA QUALIFIER REASON CODES

1	Holding Times
2	Sample Preservation
3	Sample Custody
4	Missing Deliverables
5A	Calibration (initial)
5B	Calibration (continuing)
6	Field Blanks
7	Laboratory Blanks
8	Matrix Spike
9	Precision (Duplicate, or Matrix Spike Duplicate)
10	Laboratory Control Sample
11	Detection Limit
12	Standards
13	Surrogates
14	Other
15	Furnace QC
16	ICP Serial Dilution
17	Chemical Recoveries
18	Trip Blanks
19	Internal Standards
20	Linear Range Exceeded
21	Potential False Positives



EcoChem, Inc.

Environmental Science and Chemistry

APPENDIX B
QUALIFIED DATA SUMMARY TABLE

QUALIFIED DATA SUMMARY TABLE
SDGs B110340, B1J0473, B110558 and B110530

Field ID	Analysis	Method	Analyte	Conc.	Units	Qualifier	Reason Code
EX-C-1-4	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	147	mg/kg	J	14
EX-C-1-4	BTEX	8021B	Xylenes (total)	1.01	mg/kg	J	9
EX-C-1-4	PAH	8270 SIM	Chrysene	1.3	mg/kg	J	9
EX-C-1-4	PAH	8270 SIM	1-Methylnaphthalene	1.7	mg/kg	J	9
EX-C-2-4	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	257	mg/kg	J	14
EX-C-3-4	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	11	mg/kg	J	8,14
EX-C-4-4	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	139	mg/kg	J	14
EX-C-5-4	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	163	mg/kg	J	14
EX-C-5-4	BTEX	8021B	Xylenes (total)	1.7	mg/kg	J	9
EX-C-5-4	PAH	8270 SIM	Chrysene	0.040	mg/kg	UJ	9
EX-C-5-4	PAH	8270 SIM	1-Methylnaphthalene	2.9	mg/kg	J	9
EX-A-7A-4.5	PAH	8270 SIM	Chrysene	0.20	mg/kg	UJ	10
EX-A-7A-4.5	PAH	8270 SIM	Indeno(1,2,3-cd)pyrene	0.2	mg/kg	UJ	10
EX-A-8A-4.5	PAH	8270 SIM	Chrysene	0.1	mg/kg	UJ	10
EX-A-8A-4.5	PAH	8270 SIM	Indeno(1,2,3-cd)pyrene	0.1	mg/kg	UJ	10
EX-A-9A-4.5	PAH	8270 SIM	Chrysene	0.01	mg/kg	UJ	10
EX-A-9A-4.5	PAH	8270 SIM	Indeno(1,2,3-cd)pyrene	0.01	mg/kg	UJ	10
TP-18-5.8-S	BTEX	8021B	Benzene	0.734	mg/kg	J	14
TP-18-5.8-S	BTEX	8021B	Ethylbenzene	2.28	mg/kg	J	9,14
TP-18-5.8-S	BTEX	8021B	Xylenes (total)	5.27	mg/kg	J	14
TP-18-5.8-S	PAH	8270 SIM	Fluorene	5.8	mg/kg	J	10
TP-19-5.8-S	BTEX	8021B	Ethylbenzene	0.557	mg/kg	J	14
TP-19-5.8-S	BTEX	8021B	Xylenes (total)	2.36	mg/kg	J	14
TP-19-5.8-S	PAH	8270 SIM	Fluorene	5.6	mg/kg	J	10
TP-22-5.8-S	BTEX	8021B	Ethylbenzene	1.33	mg/kg	J	9,14
TP-22-5.8-S	BTEX	8021B	Xylenes (total)	3.58	mg/kg	J	14
TP-22-5.8-S	PAH	8270 SIM	Fluorene	6.9	mg/kg	J	10
TP-20-5.8-E	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	51.6	mg/kg	J	14
TP-20-5.8-E	PAH	8270 SIM	Fluorene	0.54	mg/kg	J	10
EX-D-1-3.5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	76.1	mg/kg	J	14
EX-D-1-3.5	PAH	8270 SIM	Fluorene	0.4	mg/kg	J	10
EX-D-2-3.5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	11	mg/kg	J	14
EX-D-2-3.5	PAH	8270 SIM	Fluorene	0.064	mg/kg	J	10
EX-D-2-3.5	TPH	NWTPH-Dx	Diesel Range Organics	955	mg/kg	DNR	
EX-D-2-3.5	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	275	mg/kg	DNR	
EX-D-2-3.5RE1	TPH	NWTPH-Dx	Diesel Range Organics	766	mg/kg	J	1
EX-D-2-3.5RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	198	mg/kg	J	1
EX-D-3-3.5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	64.3	mg/kg	J	14
EX-D-3-3.5	PAH	8270 SIM	Fluorene	0.68	mg/kg	J	10
EX-D-4-3.5	TPH	NWTPH-Dx	Diesel Range Organics	11.7	mg/kg	DNR	
EX-D-4-3.5	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	25 U	mg/kg	DNR	
EX-D-4-3.5RE1	TPH	NWTPH-Dx	Diesel Range Organics	68.3	mg/kg	J	1,9
EX-D-4-3.5RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	25 U	mg/kg	UJ	1
EX-D-4-3.5	PAH	8270 SIM	Fluorene	0.0022	mg/kg	J	10
EX-D-5-3.5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	8.93	mg/kg	J	14
EX-D-5-3.5	PAH	8270 SIM	Fluorene	0.071	mg/kg	J	10
EX-D-6-3.5	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	104	mg/kg	J	14
EX-D-6-3.5	BTEX	8021B	Ethylbenzene	0.219	mg/kg	J	14
EX-D-6-3.5	PAH	8270 SIM	Fluorene	0.82	mg/kg	J	10

*

*

QUALIFIED DATA SUMMARY TABLE
SDGs B1I0340, B1J0473, B1I0558 and B1I0530

Field ID	Analysis	Method	Analyte	Conc.	Units	Qualifier	Reason Code
EX-D-7-3.5	TPH	NWTPH-Dx	Diesel Range Organics	105	mg/kg	DNR	
EX-D-7-3.5	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	36.6	mg/kg	DNR	
EX-D-7-3.5RE1	TPH	NWTPH-Dx	Diesel Range Organics	125	mg/kg	J	1,9
EX-D-7-3.5RE1	TPH	NWTPH-Dx	Lube Oil Range Hydrocarbons	43.6	mg/kg	J	1
EX-D-7-3.5	PAH	8270 SIM	Fluorene	0.0022	mg/kg	J	10
TP-11-5-S	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	54.9	mg/kg	J	14
TP-12-5-S	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	698	mg/kg	J	14
TP-12-5-S	BTEX	8021B	Ethylbenzene	3.12	mg/kg	J	14
TP-12-5-S	BTEX	8021B	Xylenes (total)	3.21	mg/kg	J	14
TP-12-5-S	PAH	8270 SIM	Fluorene	5.8	mg/kg	J	8
TP-13-5-E	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	2180	mg/kg	J	14
TP-14-5-E	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	399	mg/kg	J	14
TP-14-5-E	BTEX	8021B	Benzene	0.0446	mg/kg	J	14
TP-14-5-E	BTEX	8021B	Toluene	0.0965	mg/kg	J	14
TP-15-5-E	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	703	mg/kg	J	14
TP-16-5.8-N	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	1400	mg/kg	J	14
TP-17-5.8-S	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	1280	mg/kg	J	14
TP-5-4.5-S	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	105	mg/kg	J	14
TP-6-4.5-E	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	561	mg/kg	J	14
TP-7-4.5-S	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	153	mg/kg	J	14
TP-8-4.5-E	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	611	mg/kg	J	14
TP-8-4.5-E	BTEX	8021B	Benzene	0.27	mg/kg	J	14
TP-9-5-N	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	1180	mg/kg	J	14
TP-9-5-N	BTEX	8021B	Benzene	0.212	mg/kg	J	14
TP-10-5-S	TPH	NWTPH-Gx	Gasoline Range Hydrocarbons	2180	mg/kg	J	14

✖




Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

08 October 2001

Linda Dawson
Maul Foster & Alongi-Seattle
17171 Bothell Way NE #264
Seattle, WA/USA 98155

RE: Former Bulk Storage of Edmonds



Enclosed are the results of analyses for samples received by the laboratory on 09/21/01 17:05. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Scott A. Woerman
Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network

Stock pile A + B



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
SP-A1-10-1-5	B1I0457-01	Soil	09/21/01 15:00	09/21/01 17:05
SP-A1-20-7-10	B1I0457-02	Soil	09/21/01 15:00	09/21/01 17:05
SP-A1-67-7-8	B1I0457-03	Soil	09/21/01 15:00	09/21/01 17:05
SP-A1-93-5-23	B1I0457-04	Soil	09/21/01 15:00	09/21/01 17:05
SP-A1-124-6-17	B1I0457-05	Soil	09/21/01 15:00	09/21/01 17:05
SP-A1-147-4-30	B1I0457-06	Soil	09/21/01 15:00	09/21/01 17:05
SP-A1-162-2-3	B1I0457-07	Soil	09/21/01 15:00	09/21/01 17:05
SP-A1-188-1-7	B1I0457-08	Soil	09/21/01 15:00	09/21/01 17:05
SP-A1-220-5-25	B1I0457-09	Soil	09/21/01 15:00	09/21/01 17:05
SP-A1-235-7-27	B1I0457-10	Soil	09/21/01 15:00	09/21/01 17:05
SP-A1-255-3-4	B1I0457-11	Soil	09/21/01 15:00	09/21/01 17:05
SP-B1-5-1-10	B1I0457-12	Soil	09/20/01 13:00	09/21/01 17:05
SP-B1-28-2-2	B1I0457-13	Soil	09/20/01 13:00	09/21/01 17:05
SP-B1-63-6-18	B1I0457-14	Soil	09/20/01 13:00	09/21/01 17:05
SP-B1-83-3-4	B1I0457-15	Soil	09/20/01 13:00	09/21/01 17:05
SP-B1-99-12-9	B1I0457-16	Soil	09/20/01 13:00	09/21/01 17:05
SP-B1-112-5-8	B1I0457-17	Soil	09/20/01 13:00	09/21/01 17:05
SP-B1-131-13-12	B1I0457-18	Soil	09/20/01 13:00	09/21/01 17:05
SP-B1-197-1-17	B1I0457-19	Soil	09/20/01 13:00	09/21/01 17:05
SP-B1-219-5-6	B1I0457-20	Soil	09/20/01 13:00	09/21/01 17:05
SP-B1-266-2-20	B1I0457-21	Soil	09/21/01 13:00	09/21/01 17:05
TP-1-3.5	B1I0457-22	Soil	09/21/01 10:00	09/21/01 17:05
TP-2-4	B1I0457-23	Soil	09/21/01 10:00	09/21/01 17:05
TP-3-4	B1I0457-24	Soil	09/21/01 10:00	09/21/01 17:05

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-A1-10-1-5 (B110457-01) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	346	5.00	mg/kg dry	1	1125028	09/25/01	09/26/01	NWTPH-Gx/8021B	
Benzene	0.245	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	0.713	0.0500	"	"	"	"	"	"	
Xylenes (total)	5.65	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	171 %	50-147			"	"	"	"	S-04
Surrogate: 4-BFB (PID)	97.7 %	54-123			"	"	"	"	
SP-A1-20-7-10 (B110457-02) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	248	20.0	mg/kg dry	4	1125028	09/25/01	09/27/01	NWTPH-Gx/8021B	
Benzene	0.195	0.120	"	"	"	"	"	"	
Toluene	ND	0.200	"	"	"	"	"	"	
Ethylbenzene	2.20	0.200	"	"	"	"	"	"	
es (total)	5.61	0.400	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	190 %	50-147			"	"	"	"	S-04
Surrogate: 4-BFB (PID)	105 %	54-123			"	"	"	"	
SP-A1-67-7-8 (B110457-03) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	33.4	5.00	mg/kg dry	1	1125028	09/25/01	09/26/01	NWTPH-Gx/8021B	G-01
Benzene	0.0303	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	0.221	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	101 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	89.6 %	54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting		Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		Limit								
SP-A1-93-5-23 (B1I0457-04) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05										
Gasoline Range Hydrocarbons	10.5	5.00		mg/kg dry	1	1125028	09/25/01	09/26/01	NWTPH-Gx/8021B	
Benzene	0.0485	0.0300		"	"	"	"	"	"	
Toluene	ND	0.0500		"	"	"	"	"	"	
Ethylbenzene	ND	0.0500		"	"	"	"	"	"	
Xylenes (total)	0.153	0.100		"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	93.4 %	50-147				"	"	"	"	
Surrogate: 4-BFB (PID)	85.3 %	54-123				"	"	"	"	
SP-A1-124-6-17 (B1I0457-05) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05										
Gasoline Range Hydrocarbons	7.40	5.00		mg/kg dry	1	1125028	09/25/01	09/26/01	NWTPH-Gx/8021B	
Benzene	0.0352	0.0300		"	"	"	"	"	"	
Toluene	ND	0.0500		"	"	"	"	"	"	
Ethylbenzene	ND	0.0500		"	"	"	"	"	"	
Xylenes (total)	0.116	0.100		"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	94.8 %	50-147				"	"	"	"	
Surrogate: 4-BFB (PID)	87.2 %	54-123				"	"	"	"	
SP-A1-147-4-30 (B1I0457-06) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05										
Gasoline Range Hydrocarbons	34.1	5.00		mg/kg dry	1	1125028	09/25/01	09/26/01	NWTPH-Gx/8021B	
Benzene	ND	0.0300		"	"	"	"	"	"	
Toluene	ND	0.0500		"	"	"	"	"	"	
Ethylbenzene	ND	0.0500		"	"	"	"	"	"	
Xylenes (total)	0.344	0.100		"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	110 %	50-147				"	"	"	"	
Surrogate: 4-BFB (PID)	93.6 %	54-123				"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-A1-162-2-3 (B110457-07) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	286	5.00	mg/kg dry	1	1125028	09/25/01	09/26/01	NWTPH-Gx/8021B	
Benzene	0.0865	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	0.120	0.0500	"	"	"	"	"	"	I-06
Xylenes (total)	24.7	0.500	"	5	"	"	09/27/01	"	
Surrogate: 4-BFB (FID)	124 %	50-147			"	"	09/26/01	"	
Surrogate: 4-BFB (PID)	91.2 %	54-123			"	"	"	"	
SP-A1-188-1-7 (B110457-08) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	909	20.0	mg/kg dry	4	1125028	09/25/01	09/26/01	NWTPH-Gx/8021B	
Benzene	0.203	0.120	"	"	"	"	"	"	
Toluene	0.838	0.200	"	"	"	"	"	"	I-06
Ethylbenzene	0.886	0.200	"	"	"	"	"	"	
Xylenes (total)	60.3	2.00	"	20	"	"	09/27/01	"	
Surrogate: 4-BFB (FID)	%	50-147			"	"	09/26/01	"	S-02
Surrogate: 4-BFB (PID)	119 %	54-123			"	"	"	"	
SP-A1-220-5-25 (B110457-09) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	27.0	5.00	mg/kg dry	1	1125028	09/25/01	09/26/01	NWTPH-Gx/8021B	
Benzene	0.0357	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	0.155	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	99.1 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	90.5 %	54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-A1-235-7-27 (B110457-10) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	29.8	5.00	mg/kg dry	1	1125028	09/25/01	09/27/01	NWTPH-Gx/8021B	G-01
Benzene	0.0335	0.0300	"	"	"	"	"	"	"
Toluene	ND	0.0500	"	"	"	"	"	"	"
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	"
Xylenes (total)	0.220	0.100	"	"	"	"	"	"	"
Surrogate: 4-BFB (FID)	101 %	50-147			"	"	"	"	"
Surrogate: 4-BFB (PID)	91.1 %	54-123			"	"	"	"	"
SP-A1-255-3-4 (B110457-11) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	38.7	5.00	mg/kg dry	1	1125028	09/25/01	09/27/01	NWTPH-Gx/8021B	
Benzene	0.0581	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	0.450	0.0500	"	"	"	"	"	"	
Xylenes (total)	2.52	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	98.4 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	89.2 %	54-123			"	"	"	"	
SP-B1-5-1-10 (B110457-12) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	25.6	5.00	mg/kg dry	1	1125028	09/25/01	09/27/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	114 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	96.2 %	54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-B1-28-2-2 (B110457-13) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	7.44	5.00	mg/kg dry	1	1125028	09/25/01	09/26/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	94.0 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	93.5 %	54-123			"	"	"	"	
SP-B1-63-6-18 (B110457-14) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	92.5	10.0	mg/kg dry	2	1125028	09/25/01	09/27/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0600	"	"	"	"	"	"	
Toluene	ND	0.100	"	"	"	"	"	"	
Ethylbenzene	ND	0.100	"	"	"	"	"	"	
Xylenes (total)	0.280	0.200	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	158 %	50-147			"	"	"	"	S-04
Surrogate: 4-BFB (PID)	104 %	54-123			"	"	"	"	
SP-B1-83-3-4 (B110457-15) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	2020	100	mg/kg dry	20	1125028	09/25/01	09/26/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.600	"	"	"	"	"	"	
Toluene	ND	1.00	"	"	"	"	"	"	
Ethylbenzene	ND	1.00	"	"	"	"	"	"	
Xylenes (total)	11.4	2.00	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	%	50-147			"	"	"	"	S-01
Surrogate: 4-BFB (PID)	%	54-123			"	"	"	"	S-01

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

SP-B1-99-12-9 (B110457-16) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Gasoline Range Hydrocarbons	62.1	10.0	mg/kg dry	2	1125028	09/25/01	09/27/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0600	"	"	"	"	"	"	
Toluene	ND	0.100	"	"	"	"	"	"	
Ethylbenzene	ND	0.100	"	"	"	"	"	"	
Xylenes (total)	0.420	0.200	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	153 %	50-147			"	"	"	"	S-04
Surrogate: 4-BFB (PID)	101 %	54-123			"	"	"	"	

SP-B1-112-5-8 (B110457-17) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Gasoline Range Hydrocarbons	33.1	5.00	mg/kg dry	1	1125028	09/25/01	09/27/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	0.182	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	114 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	96.3 %	54-123			"	"	"	"	

SP-B1-131-13-12 (B110457-18) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Gasoline Range Hydrocarbons	39.1	5.00	mg/kg dry	1	1125028	09/25/01	09/27/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	0.251	0.100	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	119 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	97.7 %	54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network

Page 7 of 44



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

SP-B1-197-1-17 (B110457-19) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Gasoline Range Hydrocarbons	31.5	5.00	mg/kg dry	1	1125028	09/25/01	09/27/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	103 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	91.1 %	54-123			"	"	"	"	

SP-B1-219-5-6 (B110457-20) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Gasoline Range Hydrocarbons	10.9	5.00	mg/kg dry	1	1126020	09/26/01	09/27/01	NWTPH-Gx/8021B	
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	87.7 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	91.0 %	54-123			"	"	"	"	

SP-B1-266-2-20 (B110457-21) Soil Sampled: 09/21/01 13:00 Received: 09/21/01 17:05

Gasoline Range Hydrocarbons	20.8	5.00	mg/kg dry	1	1126020	09/26/01	09/27/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	77.2 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	86.6 %	54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network

Page 8 of 44



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
TP-1-3.5 (B110457-22) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	68.0	5.00	mg/kg dry	1	1126020	09/26/01	09/27/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	0.0730	0.0500	"	"	"	"	"	"	I-06
Xylenes (total)	0.156	0.100	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	103 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	86.8 %	54-123			"	"	"	"	
TP-2-4 (B110457-23) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	151	20.0	mg/kg dry	4	1126020	09/26/01	09/28/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.120	"	"	"	"	"	"	
Toluene	ND	0.200	"	"	"	"	"	"	
Ethylbenzene	0.257	0.200	"	"	"	"	"	"	
Xylenes (total)	ND	0.400	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	141 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	97.1 %	54-123			"	"	"	"	
TP-3-4 (B110457-24) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
Gasoline Range Hydrocarbons	86.4	5.00	mg/kg dry	1	1126020	09/26/01	09/27/01	NWTPH-Gx/8021B	G-01
Benzene	0.0602	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	0.193	0.0500	"	"	"	"	"	"	
Xylenes (total)	0.674	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	99.1 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	85.6 %	54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-A1-10-1-5 (B1I0457-01) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	1340	110	mg/kg dry	11	1I26025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	345	275	"	"	"	"	"	"	
Surrogate: 2-FBP	80.3 %	50-150			"	"	"	"	
Surrogate: Octacosane	112 %	50-150			"	"	"	"	
SP-A1-20-7-10 (B1I0457-02) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	963	110	mg/kg dry	11	1I26025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	394	275	"	"	"	"	"	"	
Surrogate: 2-FBP	66.9 %	50-150			"	"	"	"	
Surrogate: Octacosane	77.7 %	50-150			"	"	"	"	
SP-A1-67-7-8 (B1I0457-03) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	227	10.0	mg/kg dry	1	1I26025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	147	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	77.0 %	50-150			"	"	"	"	
Surrogate: Octacosane	86.2 %	50-150			"	"	"	"	
SP-A1-93-5-23 (B1I0457-04) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	159	10.0	mg/kg dry	1	1I26025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	182	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	77.1 %	50-150			"	"	"	"	
Surrogate: Octacosane	94.0 %	50-150			"	"	"	"	
SP-A1-124-6-17 (B1I0457-05RE1) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	64.9	10.0	mg/kg dry	1	1I28010	09/28/01	09/30/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	38.1	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	57.9 %	50-150			"	"	"	"	
Surrogate: Octacosane	68.4 %	50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-A1-147-4-30 (B1I0457-06RE1) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	604	10.0	mg/kg dry	1	1128010	09/28/01	09/30/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	363	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	97.3 %	50-150			"	"	"	"	
Surrogate: Octacosane	112 %	50-150			"	"	"	"	
SP-A1-162-2-3 (B1I0457-07) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	615	110	mg/kg dry	11	1126025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	300	275	"	"	"	"	"	"	
Surrogate: 2-FBP	59.3 %	50-150			"	"	"	"	
Surrogate: Octacosane	86.6 %	50-150			"	"	"	"	
SP-A1-188-1-7 (B1I0457-08) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	1140	110	mg/kg dry	11	1126025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	281	275	"	"	"	"	"	"	
Surrogate: 2-FBP	81.3 %	50-150			"	"	"	"	
Surrogate: Octacosane	76.1 %	50-150			"	"	"	"	
SP-A1-220-5-25 (B1I0457-09RE1) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	80.9	10.0	mg/kg dry	1	1128010	09/28/01	09/30/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	45.2	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	58.3 %	50-150			"	"	"	"	
Surrogate: Octacosane	62.7 %	50-150			"	"	"	"	
SP-A1-235-7-27 (B1I0457-10) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	251	50.0	mg/kg dry	5	1126025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	139	125	"	"	"	"	"	"	
Surrogate: 2-FBP	65.9 %	50-150			"	"	"	"	
Surrogate: Octacosane	86.2 %	50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9280
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-A1-255-3-4 (B110457-11) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	155	50.0	mg/kg dry	5	1126025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND	125	"	"	"	"	"	"	
Surrogate: 2-FBP	51.5 %	50-150			"	"	"	"	
Surrogate: Octacosane	77.6 %	50-150			"	"	"	"	
SP-B1-5-1-10 (B110457-12) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	386	30.0	mg/kg dry	3	1126025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	360	75.0	"	"	"	"	"	"	
Surrogate: 2-FBP	67.7 %	50-150			"	"	"	"	
Surrogate: Octacosane	85.3 %	50-150			"	"	"	"	
SP-B1-28-2-2 (B110457-13) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	112	10.0	mg/kg dry	1	1126025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	176	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	70.8 %	50-150			"	"	"	"	
Surrogate: Octacosane	85.7 %	50-150			"	"	"	"	
SP-B1-63-6-18 (B110457-14) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	204	50.0	mg/kg dry	5	1126025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	177	125	"	"	"	"	"	"	
Surrogate: 2-FBP	61.4 %	50-150			"	"	"	"	
Surrogate: Octacosane	82.4 %	50-150			"	"	"	"	
SP-B1-83-3-4 (B110457-15) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	825	50.0	mg/kg dry	5	1126025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND	125	"	"	"	"	"	"	
Surrogate: 2-FBP	128 %	50-150			"	"	"	"	
Surrogate: Octacosane	81.6 %	50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-B1-99-12-9 (B110457-16) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	892	50.0	mg/kg dry	5	1126025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	278	125	"	"	"	"	"	"	
Surrogate: 2-FBP	83.1 %	50-150			"	"	"	"	
Surrogate: Octacosane	92.0 %	50-150			"	"	"	"	
SP-B1-112-5-8 (B110457-17RE1) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	164	10.0	mg/kg dry	1	1128010	09/28/01	09/30/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	72.9	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	59.6 %	50-150			"	"	"	"	
Surrogate: Octacosane	61.0 %	50-150			"	"	"	"	
SP-B1-131-13-12 (B110457-18RE1) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	322	10.0	mg/kg dry	1	1128010	09/28/01	09/30/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	111	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	56.6 %	50-150			"	"	"	"	
Surrogate: Octacosane	64.0 %	50-150			"	"	"	"	
SP-B1-197-1-17 (B110457-19RE1) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	196	10.0	mg/kg dry	1	1128010	09/28/01	09/30/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	93.7	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	63.4 %	50-150			"	"	"	"	
Surrogate: Octacosane	64.3 %	50-150			"	"	"	"	
SP-B1-219-5-6 (B110457-20) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	36.7	10.0	mg/kg dry	1	1126025	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	67.6 %	50-150			"	"	"	"	
Surrogate: Octacosane	75.1 %	50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-B1-266-2-20 (B110457-21) Soil Sampled: 09/21/01 13:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	192	10.0	mg/kg dry	1	1126026	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	220	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	71.1 %	50-150			"	"	"	"	
Surrogate: Octacosane	83.9 %	50-150			"	"	"	"	
TP-1-3.5 (B110457-22) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	2890	110	mg/kg dry	11	1126026	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	938	275	"	"	"	"	"	"	
Surrogate: 2-FBP	143 %	50-150			"	"	"	"	
Surrogate: Octacosane	100 %	50-150			"	"	"	"	
TP-2-4 (B110457-23) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	5800	410	mg/kg dry	41	1126026	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	1920	1020	"	"	"	"	"	"	
Surrogate: 2-FBP	%	50-150			"	"	"	"	S-01
Surrogate: Octacosane	%	50-150			"	"	"	"	S-01
TP-3-4 (B110457-24) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
Diesel Range Hydrocarbons	5000	410	mg/kg dry	41	1126026	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	1830	1020	"	"	"	"	"	"	
Surrogate: 2-FBP	%	50-150			"	"	"	"	S-01
Surrogate: Octacosane	%	50-150			"	"	"	"	S-01

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-A1-10-1-5 (B110457-01) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Acenaphthene	0.11	0.050	mg/kg dry	5	1127033	09/27/01	10/04/01	8270-SIM	
Acenaphthylene	0.063	0.050	"	"	"	"	"	"	
Anthracene	ND	0.050	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.050	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.050	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.050	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.050	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.050	"	"	"	"	"	"	
Chrysene	0.066	0.050	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.050	"	"	"	"	"	"	
Fluoranthene	0.055	0.050	"	"	"	"	"	"	
Fluorene	0.37	0.050	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.050	"	"	"	"	"	"	
1-Methylnaphthalene	4.2	0.050	"	"	"	"	"	"	
2-Methylnaphthalene	5.4	0.050	"	"	"	"	"	"	
Naphthalene	0.68	0.050	"	"	"	"	"	"	
Phenanthrene	0.75	0.050	"	"	"	"	"	"	
Pyrene	0.12	0.050	"	"	"	"	"	"	

Surrogate: p-Terphenyl-d14 100 % 30-150 " " " "

SP-A1-20-7-10 (B110457-02) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Acenaphthene	ND	0.20	mg/kg dry	20	1127033	09/27/01	10/03/01	8270-SIM	
Acenaphthylene	ND	0.20	"	"	"	"	"	"	
Anthracene	ND	0.20	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.20	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.20	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.20	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.20	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.20	"	"	"	"	"	"	
Chrysene	ND	0.20	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.20	"	"	"	"	"	"	
Fluoranthene	ND	0.20	"	"	"	"	"	"	
Fluorene	0.48	0.20	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.20	"	"	"	"	"	"	
1-Methylnaphthalene	6.7	0.20	"	"	"	"	"	"	
2-Methylnaphthalene	12	0.20	"	"	"	"	"	"	
Naphthalene	3.3	0.20	"	"	"	"	"	"	
Phenanthrene	1.1	0.20	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

SP-A1-20-7-10 (B110457-02) Soil **Sampled: 09/21/01 15:00** **Received: 09/21/01 17:05**

Pyrene	0.20	0.20	mg/kg dry	20	1127033	09/27/01	10/03/01	8270-SIM	
Surrogate: p-Terphenyl-d14	100 %	30-150			"	"	"	"	

SP-A1-67-7-8 (B110457-03) Soil **Sampled: 09/21/01 15:00** **Received: 09/21/01 17:05**

Acenaphthene	ND	0.010	mg/kg dry	1	1127033	09/27/01	10/02/01	8270-SIM	
Acenaphthylene	ND	0.010	"	"	"	"	"	"	
Anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010	"	"	"	"	"	"	
Chrysene	ND	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010	"	"	"	"	"	"	
Fluorene	ND	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.082	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.10	0.010	"	"	"	"	"	"	
Naphthalene	0.046	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.010	"	"	"	"	"	"	
Pyrene	0.041	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	89 %	30-150			"	"	"	"	

SP-A1-93-5-23 (B110457-04) Soil **Sampled: 09/21/01 15:00** **Received: 09/21/01 17:05**

Acenaphthene	ND	0.010	mg/kg dry	1	1127033	09/27/01	10/02/01	8270-SIM	
Acenaphthylene	ND	0.010	"	"	"	"	"	"	
Anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010	"	"	"	"	"	"	
Chrysene	ND	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.010	"	"	"	"	"	"	
Fluorene	ND	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-A1-93-5-23 (B110457-04) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
1-Methylnaphthalene	0.019	0.010	mg/kg dry	1	1127033	09/27/01	10/02/01	8270-SIM	
2-Methylnaphthalene	0.023	0.010	"	"	"	"	"	"	
Naphthalene	0.020	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.010	"	"	"	"	"	"	
Pyrene	0.017	0.010	"	"	"	"	"	"	
<i>Surrogate: p-Terphenyl-d14</i>	94 %	30-150			"	"	"	"	
SP-A1-124-6-17 (B110457-05) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Acenaphthene	ND	0.010	mg/kg dry	1	1127033	09/27/01	10/02/01	8270-SIM	
Acenaphthylene	ND	0.010	"	"	"	"	"	"	
Anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010	"	"	"	"	"	"	
Chrysene	ND	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.010	"	"	"	"	"	"	
Fluorene	ND	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.030	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.022	0.010	"	"	"	"	"	"	
Naphthalene	0.015	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.010	"	"	"	"	"	"	
Pyrene	0.034	0.010	"	"	"	"	"	"	
<i>Surrogate: p-Terphenyl-d14</i>	89 %	30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting		Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		Limit								
SP-A1-147-4-30 (B110457-06) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05										
Acenaphthene	ND	0.010		mg/kg dry	1	1127033	09/27/01	10/02/01	8270-SIM	
Acenaphthylene	ND	0.010		"	"	"	"	"	"	
Anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010		"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010		"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010		"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010		"	"	"	"	"	"	
Chrysene	ND	0.010		"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010		"	"	"	"	"	"	
Fluoranthene	ND	0.010		"	"	"	"	"	"	
Fluorene	ND	0.010		"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010		"	"	"	"	"	"	
1-Methylnaphthalene	0.028	0.010		"	"	"	"	"	"	
2-Methylnaphthalene	0.025	0.010		"	"	"	"	"	"	
Naphthalene	0.017	0.010		"	"	"	"	"	"	
Phenanthrene	ND	0.010		"	"	"	"	"	"	
Pyrene	0.12	0.010		"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	82 %	30-150								

SP-A1-162-2-3 (B110457-07) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05										
Acenaphthene	ND	0.050		mg/kg dry	5	1127033	09/27/01	10/04/01	8270-SIM	
Acenaphthylene	ND	0.050		"	"	"	"	"	"	
Anthracene	ND	0.050		"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.050		"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.050		"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.050		"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.050		"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.050		"	"	"	"	"	"	
Chrysene	ND	0.050		"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.050		"	"	"	"	"	"	
Fluoranthene	ND	0.050		"	"	"	"	"	"	
Fluorene	0.14	0.050		"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.050		"	"	"	"	"	"	
1-Methylnaphthalene	1.8	0.050		"	"	"	"	"	"	
2-Methylnaphthalene	2.7	0.050		"	"	"	"	"	"	
Naphthalene	1.1	0.050		"	"	"	"	"	"	
Phenanthrene	0.28	0.050		"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

SP-A1-162-2-3 (B110457-07) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05

Pyrene	0.057	0.050	mg/kg dry	5	1I27033	09/27/01	10/04/01	8270-SIM	
Surrogate: p-Terphenyl-d14	110 %	30-150			"	"	"	"	

SP-A1-188-1-7 (B110457-08) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05

Acenaphthene	ND	0.20	mg/kg dry	20	1I27033	09/27/01	10/04/01	8270-SIM	
Acenaphthylene	ND	0.20	"	"	"	"	"	"	
Anthracene	ND	0.20	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.20	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.20	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.20	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.20	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.20	"	"	"	"	"	"	
Chrysene	ND	0.20	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.20	"	"	"	"	"	"	
Fluoranthene	ND	0.20	"	"	"	"	"	"	
Fluorene	0.33	0.20	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.20	"	"	"	"	"	"	
1-Methylnaphthalene	5.3	0.20	"	"	"	"	"	"	
2-Methylnaphthalene	9.6	0.20	"	"	"	"	"	"	
Naphthalene	5.9	0.20	"	"	"	"	"	"	
Phenanthrene	0.49	0.20	"	"	"	"	"	"	
Pyrene	ND	0.20	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	110 %	30-150			"	"	"	"	

SP-A1-220-5-25 (B110457-09) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05

Acenaphthene	ND	0.010	mg/kg dry	1	1I27033	09/27/01	10/02/01	8270-SIM	
Acenaphthylene	ND	0.010	"	"	"	"	"	"	
Anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010	"	"	"	"	"	"	
Chrysene	ND	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.010	"	"	"	"	"	"	
Fluorene	0.028	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting		Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		Limit								
SP-A1-220-5-25 (B1I0457-09) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05										
1-Methylnaphthalene	0.051	0.010		mg/kg dry	1	1127033	09/27/01	10/02/01	8270-SIM	
2-Methylnaphthalene	0.047	0.010		"	"	"	"	"	"	
Naphthalene	0.029	0.010		"	"	"	"	"	"	
Phenanthrene	ND	0.010		"	"	"	"	"	"	
Pyrene	0.031	0.010		"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	110 %	30-150				"	"	"	"	
SP-A1-235-7-27 (B1I0457-10) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05										
Acenaphthene	0.016	0.010		mg/kg dry	1	1J02042	10/02/01	10/04/01	8270-SIM	
Acenaphthylene	ND	0.010		"	"	"	"	"	"	
Anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010		"	"	"	"	"	"	
B (b) fluoranthene	0.011	0.010		"	"	"	"	"	"	
B (ghi) perylene	ND	0.010		"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010		"	"	"	"	"	"	
Chrysene	0.021	0.010		"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010		"	"	"	"	"	"	
Fluoranthene	ND	0.010		"	"	"	"	"	"	
Fluorene	0.046	0.010		"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010		"	"	"	"	"	"	
1-Methylnaphthalene	0.055	0.010		"	"	"	"	"	"	
2-Methylnaphthalene	0.037	0.010		"	"	"	"	"	"	
Naphthalene	ND	0.010		"	"	"	"	"	"	
Phenanthrene	0.045	0.010		"	"	"	"	"	"	
Pyrene	0.024	0.010		"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	78 %	30-150				"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting		Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		Limit								
SP-A1-255-3-4 (B110457-11) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05										
Acenaphthene	ND	0.010		mg/kg dry	1	1J02042	10/02/01	10/04/01	8270-SIM	
Acenaphthylene	ND	0.010		"	"	"	"	"	"	
Anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010		"	"	"	"	"	"	
Benzo (b) fluoranthene	0.013	0.010		"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010		"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010		"	"	"	"	"	"	
Chrysene	0.021	0.010		"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010		"	"	"	"	"	"	
Fluoranthene	ND	0.010		"	"	"	"	"	"	
Fluorene	ND	0.010		"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010		"	"	"	"	"	"	
1-Methylnaphthalene	0.016	0.010		"	"	"	"	"	"	
2-Methylnaphthalene	0.022	0.010		"	"	"	"	"	"	
Naphthalene	ND	0.010		"	"	"	"	"	"	
Phenanthrene	ND	0.010		"	"	"	"	"	"	
Pyrene	0.024	0.010		"	"	"	"	"	"	
<i>Surrogate: p-Terphenyl-d14</i>	100 %	30-150				"	"	"	"	

SP-B1-5-1-10 (B110457-12) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05										
Acenaphthene	ND	0.010		mg/kg dry	1	1J02042	10/02/01	10/06/01	8270-SIM	
Acenaphthylene	ND	0.010		"	"	"	"	"	"	
Anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) anthracene	0.014	0.010		"	"	"	"	"	"	
Benzo (a) pyrene	0.012	0.010		"	"	"	"	"	"	
Benzo (b) fluoranthene	0.014	0.010		"	"	"	"	"	"	
Benzo (ghi) perylene	0.014	0.010		"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010		"	"	"	"	"	"	
Chrysene	0.021	0.010		"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010		"	"	"	"	"	"	
Fluoranthene	0.015	0.010		"	"	"	"	"	"	
Fluorene	ND	0.010		"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010		"	"	"	"	"	"	
1-Methylnaphthalene	ND	0.010		"	"	"	"	"	"	
2-Methylnaphthalene	0.010	0.010		"	"	"	"	"	"	
Naphthalene	ND	0.010		"	"	"	"	"	"	
Phenanthrene	0.042	0.010		"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

SP-B1-5-1-10 (B1I0457-12) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Pyrene	0.040	0.010	mg/kg dry	1	1J02042	10/02/01	10/06/01	8270-SIM	
Surrogate: p-Terphenyl-d14	82 %	30-150			"	"	"	"	

SP-B1-28-2-2 (B1I0457-13) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Acenaphthene	ND	0.010	mg/kg dry	1	1J02042	10/02/01	10/06/01	8270-SIM	
Acenaphthylene	ND	0.010	"	"	"	"	"	"	
Anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	0.016	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010	"	"	"	"	"	"	
Chrysene	ND	0.010	"	"	"	"	"	"	
Fluorene (a,h) anthracene	ND	0.010	"	"	"	"	"	"	
Fluorene	ND	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.040	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.079	0.010	"	"	"	"	"	"	
Naphthalene	0.054	0.010	"	"	"	"	"	"	
Phenanthrene	0.018	0.010	"	"	"	"	"	"	
Pyrene	0.017	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	78 %	30-150			"	"	"	"	

SP-B1-63-6-18 (B1I0457-14) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Acenaphthene	ND	0.010	mg/kg dry	1	1J02042	10/02/01	10/04/01	8270-SIM	
Acenaphthylene	ND	0.010	"	"	"	"	"	"	
Anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010	"	"	"	"	"	"	
Chrysene	ND	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.010	"	"	"	"	"	"	
Fluorene	ND	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-B1-63-6-18 (B1I0457-14) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
1-Methylnaphthalene	ND	0.010	mg/kg dry	1	1J02042	10/02/01	10/04/01	8270-SIM	
2-Methylnaphthalene	ND	0.010	"	"	"	"	"	"	"
Naphthalene	ND	0.010	"	"	"	"	"	"	"
Phenanthrene	ND	0.010	"	"	"	"	"	"	"
Pyrene	ND	0.010	"	"	"	"	"	"	"
Surrogate: p-Terphenyl-d14	89 %	30-150			"	"	"	"	"
SP-B1-83-3-4 (B1I0457-15) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Acenaphthene	ND	0.010	mg/kg dry	1	1J02042	10/02/01	10/04/01	8270-SIM	
Acenaphthylene	ND	0.010	"	"	"	"	"	"	"
Anthracene	ND	0.010	"	"	"	"	"	"	"
Benzo (a) anthracene	ND	0.010	"	"	"	"	"	"	"
Benzo (a) pyrene	ND	0.010	"	"	"	"	"	"	"
Benzo (b) fluoranthene	ND	0.010	"	"	"	"	"	"	"
Benzo (ghi) perylene	ND	0.010	"	"	"	"	"	"	"
Benzo (k) fluoranthene	ND	0.010	"	"	"	"	"	"	"
Chrysene	ND	0.010	"	"	"	"	"	"	"
Dibenz (a,h) anthracene	ND	0.010	"	"	"	"	"	"	"
Fluoranthene	ND	0.010	"	"	"	"	"	"	"
Fluorene	0.075	0.010	"	"	"	"	"	"	"
Indeno (1,2,3-cd) pyrene	ND	0.010	"	"	"	"	"	"	"
1-Methylnaphthalene	0.039	0.010	"	"	"	"	"	"	"
2-Methylnaphthalene	0.034	0.010	"	"	"	"	"	"	"
Naphthalene	ND	0.010	"	"	"	"	"	"	"
Phenanthrene	0.013	0.010	"	"	"	"	"	"	"
Pyrene	0.012	0.010	"	"	"	"	"	"	"
Surrogate: p-Terphenyl-d14	94 %	30-150			"	"	"	"	"

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting		Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		Limit								
SP-B1-99-12-9 (B110457-16) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05										
Acenaphthene	ND	0.010		mg/kg dry	1	1J02042	10/02/01	10/06/01	8270-SIM	
Acenaphthylene	ND	0.010		"	"	"	"	"	"	
Anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010		"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010		"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010		"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010		"	"	"	"	"	"	
Chrysene	0.030	0.010		"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010		"	"	"	"	"	"	
Fluoranthene	0.011	0.010		"	"	"	"	"	"	
Fluorene	ND	0.010		"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010		"	"	"	"	"	"	
1-yl naphthalene	ND	0.010		"	"	"	"	"	"	
2-yl naphthalene	ND	0.010		"	"	"	"	"	"	
Naphthalene	ND	0.010		"	"	"	"	"	"	
Phenanthrene	0.013	0.010		"	"	"	"	"	"	
Pyrene	0.040	0.010		"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	72 %	30-150				"	"	"	"	

SP-B1-112-5-8 (B110457-17) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05										
Acenaphthene	ND	0.010		mg/kg dry	1	1J02042	10/02/01	10/06/01	8270-SIM	
Acenaphthylene	ND	0.010		"	"	"	"	"	"	
Anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010		"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010		"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010		"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010		"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010		"	"	"	"	"	"	
Chrysene	0.015	0.010		"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010		"	"	"	"	"	"	
Fluoranthene	ND	0.010		"	"	"	"	"	"	
Fluorene	ND	0.010		"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010		"	"	"	"	"	"	
1-Methylnaphthalene	ND	0.010		"	"	"	"	"	"	
2-Methylnaphthalene	ND	0.010		"	"	"	"	"	"	
Naphthalene	ND	0.010		"	"	"	"	"	"	
Phenanthrene	0.014	0.010		"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

SP-B1-112-5-8 (B1I0457-17) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Pyrene	0.026	0.010	mg/kg dry	1	1J02042	10/02/01	10/06/01	8270-SIM	
Surrogate: p-Terphenyl-d14	72 %	30-150			"	"	"	"	

SP-B1-131-13-12 (B1I0457-18) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Acenaphthene	ND	0.010	mg/kg dry	1	1J02042	10/02/01	10/04/01	8270-SIM	
Acenaphthylene	ND	0.010	"	"	"	"	"	"	
Anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010	"	"	"	"	"	"	
Chrysene	0.031	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.010	"	"	"	"	"	"	
Fluorene	ND	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.016	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.018	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.010	"	"	"	"	"	"	
Pyrene	0.040	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	78 %	30-150			"	"	"	"	

SP-B1-197-1-17 (B1I0457-19) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Acenaphthene	ND	0.010	mg/kg dry	1	1J02042	10/02/01	10/06/01	8270-SIM	
Acenaphthylene	0.016	0.010	"	"	"	"	"	"	
Anthracene	0.014	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	0.054	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	0.036	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	0.058	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	0.033	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	0.014	0.010	"	"	"	"	"	"	
Chrysene	0.15	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010	"	"	"	"	"	"	
Fluoranthene	0.033	0.010	"	"	"	"	"	"	
Fluorene	ND	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	0.018	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

SP-B1-197-1-17 (B1I0457-19) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

1-Methylnaphthalene	0.028	0.010	mg/kg dry	1	IJ02042	10/02/01	10/06/01	8270-SIM	
2-Methylnaphthalene	0.024	0.010	"	"	"	"	"	"	
Naphthalene	0.013	0.010	"	"	"	"	"	"	
Phenanthrene	0.11	0.010	"	"	"	"	"	"	
Pyrene	0.14	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	76 %	30-150							

SP-B1-219-5-6 (B1I0457-20) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05

Acenaphthene	ND	0.010	mg/kg dry	1	IJ02042	10/02/01	10/06/01	8270-SIM	
Acenaphthylene	ND	0.010	"	"	"	"	"	"	
Anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.010	"	"	"	"	"	"	
Chrysene	ND	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.010	"	"	"	"	"	"	
Fluorene	ND	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	ND	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	ND	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.010	"	"	"	"	"	"	
Pyrene	ND	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	82 %	30-150							

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Reporting		Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
	Result	Limit							
SP-B1-266-2-20 (B110457-21) Soil Sampled: 09/21/01 13:00 Received: 09/21/01 17:05									
Acenaphthene	ND	0.010	mg/kg dry	1	1J02042	10/02/01	10/06/01	8270-SIM	
Acenaphthylene	ND	0.010	"	"	"	"	"	"	"
Anthracene	ND	0.010	"	"	"	"	"	"	"
Benzo (a) anthracene	0.013	0.010	"	"	"	"	"	"	"
Benzo (a) pyrene	0.013	0.010	"	"	"	"	"	"	"
Benzo (b) fluoranthene	0.020	0.010	"	"	"	"	"	"	"
Benzo (ghi) perylene	0.021	0.010	"	"	"	"	"	"	"
Benzo (k) fluoranthene	ND	0.010	"	"	"	"	"	"	"
Chrysene	0.028	0.010	"	"	"	"	"	"	"
Dibenz (a,h) anthracene	ND	0.010	"	"	"	"	"	"	"
Fluoranthene	0.015	0.010	"	"	"	"	"	"	"
Fluorene	ND	0.010	"	"	"	"	"	"	"
Indeno (1,2,3-cd) pyrene	ND	0.010	"	"	"	"	"	"	"
1-Methylnaphthalene	ND	0.010	"	"	"	"	"	"	"
2-Methylnaphthalene	ND	0.010	"	"	"	"	"	"	"
Naphthalene	ND	0.010	"	"	"	"	"	"	"
Phenanthrene	0.020	0.010	"	"	"	"	"	"	"
Pyrene	0.030	0.010	"	"	"	"	"	"	"
Surrogate: p-Terphenyl-d14	72 %	30-150			"	"	"	"	"

TP-1-3.5 (B110457-22) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
Acenaphthene	0.28	0.050	mg/kg dry	5	1J02042	10/02/01	10/06/01	8270-SIM	
Acenaphthylene	0.094	0.050	"	"	"	"	"	"	"
Anthracene	0.34	0.050	"	"	"	"	"	"	"
Benzo (a) anthracene	0.16	0.050	"	"	"	"	"	"	"
Benzo (a) pyrene	0.055	0.050	"	"	"	"	"	"	"
Benzo (b) fluoranthene	ND	0.050	"	"	"	"	"	"	"
Benzo (ghi) perylene	ND	0.050	"	"	"	"	"	"	"
Benzo (k) fluoranthene	ND	0.050	"	"	"	"	"	"	"
Chrysene	0.29	0.050	"	"	"	"	"	"	"
Dibenz (a,h) anthracene	ND	0.050	"	"	"	"	"	"	"
Fluoranthene	0.17	0.050	"	"	"	"	"	"	"
Fluorene	0.94	0.050	"	"	"	"	"	"	"
Indeno (1,2,3-cd) pyrene	ND	0.050	"	"	"	"	"	"	"
1-Methylnaphthalene	1.6	0.050	"	"	"	"	"	"	"
2-Methylnaphthalene	0.17	0.050	"	"	"	"	"	"	"
Naphthalene	ND	0.050	"	"	"	"	"	"	"
Phenanthrene	2.4	0.050	"	"	"	"	"	"	"

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.908.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

TP-1-3.5 (B110457-22) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05

Pyrene	0.47	0.050	mg/kg dry	5	1J02042	10/02/01	10/06/01	8270-SIM	
Surrogate: p-Terphenyl-d14	85 %	30-150			"	"	"	"	

TP-2-4 (B110457-23) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05

Acenaphthene	0.67	0.25	mg/kg dry	25	1J02042	10/02/01	10/06/01	8270-SIM	
Acenaphthylene	0.32	0.25	"	"	"	"	"	"	
Anthracene	0.86	0.25	"	"	"	"	"	"	
Benzo (a) anthracene	0.62	0.25	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.25	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.25	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.25	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.25	"	"	"	"	"	"	
Chrysene	1.3	0.25	"	"	"	"	"	"	
Fluorene (a,h) anthracene	ND	0.25	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.25	"	"	"	"	"	"	
1-Methylnaphthalene	6.3	0.25	"	"	"	"	"	"	
2-Methylnaphthalene	6.6	0.25	"	"	"	"	"	"	
Naphthalene	ND	0.25	"	"	"	"	"	"	
Phenanthrene	8.8	0.25	"	"	"	"	"	"	
Pyrene	2.0	0.25	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	84 %	30-150			"	"	"	"	

TP-3-4 (B110457-24) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05

Acenaphthene	0.50	0.050	mg/kg dry	5	1J02042	10/02/01	10/04/01	8270-SIM	
Acenaphthylene	0.16	0.050	"	"	"	"	"	"	
Anthracene	0.43	0.050	"	"	"	"	"	"	
Benzo (a) anthracene	0.97	0.050	"	"	"	"	"	"	
Benzo (a) pyrene	0.064	0.050	"	"	"	"	"	"	
Benzo (b) fluoranthene	0.12	0.050	"	"	"	"	"	"	
Benzo (ghi) perylene	0.071	0.050	"	"	"	"	"	"	
Benzo (k) fluoranthene	0.12	0.050	"	"	"	"	"	"	
Chrysene	0.92	0.050	"	"	"	"	"	"	
Dibenz (a,h) anthracene	0.12	0.050	"	"	"	"	"	"	
Fluoranthene	0.52	0.050	"	"	"	"	"	"	
Fluorene	1.3	0.050	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.050	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
TP-3-4 (B110457-24) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
1-Methylnaphthalene	3.3	0.050	mg/kg dry	5	1J02042	10/02/01	10/04/01	8270-SIM	
2-Methylnaphthalene	2.7	0.050	"	"	"	"	"	"	
Naphthalene	0.38	0.050	"	"	"	"	"	"	
Phenanthrene	4.5	0.050	"	"	"	"	"	"	
Pyrene	0.97	0.050	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	89 %	30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Physical Parameters by APHA/ASTM/EPA Methods
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-A1-10-1-5 (B1I0457-01) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	90.5	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-A1-20-7-10 (B1I0457-02) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	92.6	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-A1-67-7-8 (B1I0457-03) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	92.5	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-A1-93-5-23 (B1I0457-04) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	90.8	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-A1-124-6-17 (B1I0457-05) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	95.0	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-A1-147-4-30 (B1I0457-06) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	95.5	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-A1-162-2-3 (B1I0457-07) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	92.7	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-A1-188-1-7 (B1I0457-08) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	93.1	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-A1-220-5-25 (B1I0457-09) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	92.9	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

**Physical Parameters by APHA/ASTM/EPA Methods
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-A1-235-7-27 (B1I0457-10) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	93.7	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-A1-255-3-4 (B1I0457-11) Soil Sampled: 09/21/01 15:00 Received: 09/21/01 17:05									
Dry Weight	93.7	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-B1-5-1-10 (B1I0457-12) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Dry Weight	96.0	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-B1-28-2-2 (B1I0457-13) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Dry Weight	92.5	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-B1-63-6-18 (B1I0457-14) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Dry Weight	92.9	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-B1-83-3-4 (B1I0457-15) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Dry Weight	91.5	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-B1-99-12-9 (B1I0457-16) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Dry Weight	93.7	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-B1-112-5-8 (B1I0457-17) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Dry Weight	93.6	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	
SP-B1-131-13-12 (B1I0457-18) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Dry Weight	92.4	1.00	%	1	1I25049	09/25/01	09/26/01	BSOPSPL003R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Physical Parameters by APHA/ASTM/EPA Methods
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-B1-197-1-17 (B1I0457-19) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Dry Weight	95.9	1.00	%	1	1I26001	09/25/01	09/26/01	BSOPSPL003R07	
SP-B1-219-5-6 (B1I0457-20) Soil Sampled: 09/20/01 13:00 Received: 09/21/01 17:05									
Dry Weight	94.4	1.00	%	1	1I26001	09/25/01	09/26/01	BSOPSPL003R07	
SP-B1-266-2-20 (B1I0457-21) Soil Sampled: 09/21/01 13:00 Received: 09/21/01 17:05									
Dry Weight	94.1	1.00	%	1	1I26001	09/25/01	09/26/01	BSOPSPL003R07	
TP-1-3.5 (B1I0457-22) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
Dry Weight	84.1	1.00	%	1	1I26001	09/25/01	09/26/01	BSOPSPL003R07	
TP-2-4 (B1I0457-23) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
Dry Weight	88.7	1.00	%	1	1I26001	09/25/01	09/26/01	BSOPSPL003R07	
TP-3-4 (B1I0457-24) Soil Sampled: 09/21/01 10:00 Received: 09/21/01 17:05									
Weight	88.9	1.00	%	1	1I26001	09/25/01	09/26/01	BSOPSPL003R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I25028: Prepared 09/25/01 Using EPA 5030B (MeOH)

Blank (1I25028-BLK1)

Gasoline Range Hydrocarbons	ND	5.00	mg/kg							
Benzene	ND	0.0300	"							
Toluene	ND	0.0500	"							
Ethylbenzene	ND	0.0500	"							
Xylenes (total)	ND	0.100	"							
Surrogate: 4-BFB (FID)	3.88		"	4.00		97.0	50-147			
Surrogate: 4-BFB (PID)	3.79		"	4.00		94.8	54-123			

LCS (1I25028-BS1)

Gasoline Range Hydrocarbons	22.8	5.00	mg/kg	25.0		91.2	80-120			
Surrogate: 4-BFB (FID)	3.94		"	4.00		98.5	50-147			

LCS (1I25028-BS2)

Benzene	0.435	0.0300	mg/kg	0.500		87.0	80-120			
Toluene	0.477	0.0500	"	0.500		95.4	80-120			
Ethylbenzene	0.500	0.0500	"	0.500		100	80-120			
Xylenes (total)	1.55	0.100	"	1.50		103	80-120			
Surrogate: 4-BFB (PID)	3.78		"	4.00		94.5	54-123			

LCS Dup (1I25028-BSD1)

Gasoline Range Hydrocarbons	24.0	5.00	mg/kg	25.0		96.0	80-120	5.13	40	
Surrogate: 4-BFB (FID)	4.08		"	4.00		102	50-147			

LCS Dup (1I25028-BSD2)

Benzene	0.463	0.0300	mg/kg	0.500		92.6	80-120	6.24	40	
Toluene	0.500	0.0500	"	0.500		100	80-120	4.71	40	
Ethylbenzene	0.531	0.0500	"	0.500		106	80-120	6.01	40	
Xylenes (total)	1.65	0.100	"	1.50		110	80-120	6.25	40	
Surrogate: 4-BFB (PID)	3.91		"	4.00		97.8	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9280
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I25028: Prepared 09/25/01 Using EPA 5030B (MeOH)

Matrix Spike (1I25028-MS1)

Source: B1I0316-01

Gasoline Range Hydrocarbons	26.9	5.00	mg/kg dry	27.5	ND	97.8	53-120			
Surrogate: 4-BFB (FID)	4.39		"	4.40		99.8	50-147			

Matrix Spike (1I25028-MS2)

Source: B1I0457-03

Benzene	0.497	0.0300	mg/kg dry	0.541	0.0303	86.3	64-130			
Toluene	0.510	0.0500	"	0.541	ND	90.2	66-130			
Ethylbenzene	0.570	0.0500	"	0.541	ND	97.0	72-130			
Xylenes (total)	1.78	0.100	"	1.62	0.221	96.2	73-130			
Surrogate: 4-BFB (PID)	3.94		"	4.32		91.2	54-123			

Matrix Spike Dup (1I25028-MSD1)

Source: B1I0316-01

Gasoline Range Hydrocarbons	24.8	5.00	mg/kg dry	27.5	ND	90.2	53-120	8.12	40	
Surrogate: 4-BFB (FID)	4.28		"	4.40		97.3	50-147			

Matrix Spike Dup (1I25028-MSD2)

Source: B1I0457-03

Benzene	0.490	0.0300	mg/kg dry	0.541	0.0303	85.0	64-130	1.42	40	
Toluene	0.508	0.0500	"	0.541	ND	89.8	66-130	0.393	40	
Ethylbenzene	0.563	0.0500	"	0.541	ND	95.7	72-130	1.24	40	
Xylenes (total)	1.79	0.100	"	1.62	0.221	96.9	73-130	0.560	40	
Surrogate: 4-BFB (PID)	3.93		"	4.32		91.0	54-123			

Batch 1I26020: Prepared 09/26/01 Using EPA 5030B (MeOH)

Blank (1I26020-BLK1)

Gasoline Range Hydrocarbons	ND	5.00	mg/kg							
Benzene	ND	0.0300	"							
Toluene	ND	0.0500	"							
Ethylbenzene	ND	0.0500	"							
Xylenes (total)	ND	0.100	"							
Surrogate: 4-BFB (FID)	3.42		"	4.00		85.5	50-147			
Surrogate: 4-BFB (PID)	3.72		"	4.00		93.0	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I26020: Prepared 09/26/01 Using EPA 5030B (MeOH)

LCS (1I26020-BS1)

Gasoline Range Hydrocarbons	22.9	5.00	mg/kg	25.0		91.6	80-120			
Surrogate: 4-BFB (FID)	3.68		"	4.00		92.0	50-147			

LCS (1I26020-BS2)

Benzene	0.464	0.0300	mg/kg	0.500		92.8	80-120			
Toluene	0.484	0.0500	"	0.500		96.8	80-120			
Ethylbenzene	0.499	0.0500	"	0.500		99.8	80-120			
Xylenes (total)	1.53	0.100	"	1.50		102	80-120			
Surrogate: 4-BFB (PID)	3.70		"	4.00		92.5	54-123			

LCS Dup (1I26020-BSD1)

Gasoline Range Hydrocarbons	21.5	5.00	mg/kg	25.0		86.0	80-120	6.31	40	
Surrogate: 4-BFB (FID)	3.42		"	4.00		85.5	50-147			

LCS Dup (1I26020-BSD2)

Benzene	0.463	0.0300	mg/kg	0.500		92.6	80-120	0.216	40	
Toluene	0.479	0.0500	"	0.500		95.8	80-120	1.04	40	
Ethylbenzene	0.498	0.0500	"	0.500		99.6	80-120	0.201	40	
Xylenes (total)	1.53	0.100	"	1.50		102	80-120	0.00	40	
Surrogate: 4-BFB (PID)	3.71		"	4.00		92.8	54-123			

Matrix Spike (1I26020-MS1)

Source: B1I0340-03

Gasoline Range Hydrocarbons	26.3	5.00	mg/kg dry	27.9	11.0	54.8	53-120			
Surrogate: 4-BFB (FID)	3.82		"	4.47		85.5	50-147			

Matrix Spike (1I26020-MS2)

Source: B1I0457-24

Benzene	0.484	0.0300	mg/kg dry	0.562	0.0602	75.4	64-130			
Toluene	0.485	0.0500	"	0.562	ND	78.3	66-130			
Ethylbenzene	0.563	0.0500	"	0.562	0.193	65.8	72-130			Q-02
Xylenes (total)	1.76	0.100	"	1.69	0.674	64.3	73-130			Q-02
Surrogate: 4-BFB (PID)	3.78		"	4.50		84.0	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1126020: Prepared 09/26/01 Using EPA 5030B (MeOH)										
Matrix Spike Dup (1126020-MSD1)										
Source: B110340-03										
Gasoline Range Hydrocarbons	28.0	5.00	mg/kg dry	27.9	11.0	60.9	53-120	6.26	40	
Surrogate: 4-BFB (FID)	3.78		"	4.47		84.6	50-147			
Matrix Spike Dup (1126020-MSD2)										
Source: B110457-24										
Benzene	0.485	0.0300	mg/kg dry	0.562	0.0602	75.6	64-130	0.206	40	
Toluene	0.493	0.0500	"	0.562	ND	79.7	66-130	1.64	40	
Ethylbenzene	0.566	0.0500	"	0.562	0.193	66.4	72-130	0.531	40	Q-02
Xylenes (total)	1.77	0.100	"	1.69	0.674	64.9	73-130	0.567	40	Q-02
Surrogate: 4-BFB (PID)	3.78		"	4.50		84.0	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I26025: Prepared 09/26/01 Using EPA 3550B

Blank (1I26025-BLK1)

Diesel Range Hydrocarbons	ND	10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND	25.0	"							
Surrogate: 2-FBP	7.51		"	10.7		70.2	50-150			
Surrogate: Octacosane	8.50		"	10.7		79.4	50-150			

LCS (1I26025-BS1)

Diesel Range Hydrocarbons	62.1	10.0	mg/kg	66.7		93.1	50-150			
Surrogate: 2-FBP	10.3		"	10.7		96.3	50-150			

LCS Dup (1I26025-BSD1)

Diesel Range Hydrocarbons	60.0	10.0	mg/kg	66.7		90.0	50-150	3.44	50	
Surrogate: 2-FBP	8.15		"	10.7		76.2	50-150			

Duplicate (1I26025-DUP1)

Source: B110457-04

Diesel Range Hydrocarbons	149	10.0	mg/kg dry		159			6.49	50	
Lube Oil Range Hydrocarbons	187	25.0	"		182			2.71	50	
Surrogate: 2-FBP	9.37		"	11.7		80.1	50-150			
Surrogate: Octacosane	10.6		"	11.7		90.6	50-150			

Batch 1I26026: Prepared 09/26/01 Using EPA 3550B

Blank (1I26026-BLK1)

Diesel Range Hydrocarbons	ND	10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND	25.0	"							
Surrogate: 2-FBP	7.78		"	10.7		72.7	50-150			
Surrogate: Octacosane	8.54		"	10.7		79.8	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I26026: Prepared 09/26/01 Using EPA 3550B

LCS (1I26026-BS1)

Diesel Range Hydrocarbons	55.9	10.0	mg/kg	66.7		83.8	50-150			
Surrogate: 2-FBP	8.05		"	10.7		75.2	50-150			

LCS Dup (1I26026-BSD1)

Diesel Range Hydrocarbons	57.4	10.0	mg/kg	66.7		86.1	50-150	2.65	50	
Surrogate: 2-FBP	7.89		"	10.7		73.7	50-150			

Duplicate (1I26026-DUP1)

Source: B1I0457-22

Diesel Range Hydrocarbons	2610	110	mg/kg dry		2890			10.2	50	
Lube Oil Range Hydrocarbons	835	275	"		938			11.6	50	
Surrogate: 2-FBP	18.3		"	12.7		144	50-150			
Surrogate: Octacosane	15.3		"	12.7		120	50-150			

Batch 1I28010: Prepared 09/28/01 Using EPA 3545

Blank (1I28010-BLK1)

Diesel Range Hydrocarbons	ND	10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND	25.0	"							
Surrogate: 2-FBP	7.97		"	10.7		74.5	50-150			
Surrogate: Octacosane	8.30		"	10.7		77.6	50-150			

LCS (1I28010-BS1)

Diesel Range Hydrocarbons	56.6	10.0	mg/kg	66.7		84.9	50-150			
Surrogate: 2-FBP	8.29		"	10.7		77.5	50-150			

LCS Dup (1I28010-BSD1)

Diesel Range Hydrocarbons	59.6	10.0	mg/kg	66.7		89.4	50-150	5.16	50	
Surrogate: 2-FBP	8.49		"	10.7		79.3	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1128010: Prepared 09/28/01 Using EPA 3545

Duplicate (1128010-DUP1)

Source: B110515-01

Diesel Range Hydrocarbons	ND	10.0	mg/kg dry		ND			43.7	50	
Lube Oil Range Hydrocarbons	ND	25.0	"		ND			6.07	50	
Surrogate: 2-FBP	7.95		"	11.4		69.7	50-150			
Surrogate: Octacosane	8.24		"	11.4		72.3	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network

Page 39 of 44



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I27033: Prepared 09/27/01 Using EPA 3550B

Blank (1I27033-BLK1)

Acenaphthene	ND	0.010	mg/kg							
Acenaphthylene	ND	0.010	"							
Anthracene	ND	0.010	"							
Benzo (a) anthracene	ND	0.010	"							
Benzo (a) pyrene	ND	0.010	"							
Benzo (b) fluoranthene	ND	0.010	"							
Benzo (ghi) perylene	ND	0.010	"							
Benzo (k) fluoranthene	ND	0.010	"							
Chrysene	ND	0.010	"							
Dibenz (a,h) anthracene	ND	0.010	"							
Fluoranthene	ND	0.010	"							
Fluorene	ND	0.010	"							
Indeno (1,2,3-cd) pyrene	ND	0.010	"							
1-Methylnaphthalene	ND	0.010	"							
2-Methylnaphthalene	ND	0.010	"							
Naphthalene	ND	0.010	"							
Phenanthrene	ND	0.010	"							
Pyrene	ND	0.010	"							
Surrogate: p-Terphenyl-d14	2.0		"	1.7		120	30-150			

LCS (1I27033-BS1)

Chrysene	0.30	0.010	mg/kg	0.33		91	10-125			
Fluorene	0.33	0.010	"	0.33		100	11-116			
Indeno (1,2,3-cd) pyrene	0.32	0.010	"	0.33		97	10-147			
Surrogate: p-Terphenyl-d14	2.0		"	1.7		120	30-150			

LCS Dup (1I27033-BSD1)

Chrysene	0.31	0.010	mg/kg	0.33		94	10-125	3.3	28	
Fluorene	0.32	0.010	"	0.33		97	11-116	3.1	32	
Indeno (1,2,3-cd) pyrene	0.30	0.010	"	0.33		91	10-147	6.5	34	
Surrogate: p-Terphenyl-d14	1.9		"	1.7		110	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I27033: Prepared 09/27/01 Using EPA 3550B

Matrix Spike (1I27033-MS1)

Source: B1I0457-01

Chrysene	0.40	0.050	mg/kg dry	0.37	0.066	90	10-125			
Fluorene	1.0	0.050	"	0.37	0.37	170	10-154			Q-01
Indeno (1,2,3-cd) pyrene	0.43	0.050	"	0.37	ND	120	10-144			
Surrogate: p-Terphenyl-d14	2.2		"	1.8		120	30-150			

Matrix Spike Dup (1I27033-MSD1)

Source: B1I0457-01

Chrysene	0.40	0.050	mg/kg dry	0.37	0.066	90	10-125	0.0	28	
Fluorene	1.0	0.050	"	0.37	0.37	170	10-154	0.0	32	Q-01
Indeno (1,2,3-cd) pyrene	0.46	0.050	"	0.37	ND	120	10-144	6.7	47	
Surrogate: p-Terphenyl-d14	2.3		"	1.8		130	30-150			

Batch 1J02042: Prepared 10/02/01 Using EPA 3550B

Blank (1J02042-BLK1)

Acenaphthene	ND	0.010	mg/kg							
Acenaphthylene	ND	0.010	"							
Anthracene	ND	0.010	"							
Benzo (a) anthracene	ND	0.010	"							
Benzo (a) pyrene	ND	0.010	"							
Benzo (b) fluoranthene	ND	0.010	"							
Benzo (ghi) perylene	ND	0.010	"							
Benzo (k) fluoranthene	ND	0.010	"							
Chrysene	ND	0.010	"							
Dibenz (a,h) anthracene	ND	0.010	"							
Fluoranthene	ND	0.010	"							
Fluorene	ND	0.010	"							
Indeno (1,2,3-cd) pyrene	ND	0.010	"							
1-Methylnaphthalene	ND	0.010	"							
2-Methylnaphthalene	ND	0.010	"							
Naphthalene	ND	0.010	"							
Phenanthrene	ND	0.010	"							
Pyrene	ND	0.010	"							
Surrogate: p-Terphenyl-d14	1.6		"	1.7		94	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/08/01 21:02

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J02042: Prepared 10/02/01 Using EPA 3550B

LCS (1J02042-BS1)

Chrysene	0.24	0.010	mg/kg	0.33		73	10-125			
Fluorene	0.26	0.010	"	0.33		79	11-116			
Indeno (1,2,3-cd) pyrene	0.26	0.010	"	0.33		79	10-147			
Surrogate: p-Terphenyl-d14	1.5		"	1.7		88	30-150			

LCS Dup (1J02042-BSD1)

Chrysene	0.25	0.010	mg/kg	0.33		76	10-125	4.1	28	
Fluorene	0.25	0.010	"	0.33		76	11-116	3.9	32	
Indeno (1,2,3-cd) pyrene	0.24	0.010	"	0.33		73	10-147	8.0	34	
Surrogate: p-Terphenyl-d14	1.6		"	1.7		94	30-150			

Matrix Spike (1J02042-MS1)

Source: B110457-18

Chrysene	0.27	0.010	mg/kg dry	0.36	0.031	66	10-125			
Fluorene	0.29	0.010	"	0.36	ND	81	10-154			
Indeno (1,2,3-cd) pyrene	0.25	0.010	"	0.36	ND	69	10-144			
Surrogate: p-Terphenyl-d14	1.7		"	1.8		94	30-150			

Matrix Spike Dup (1J02042-MSD1)

Source: B110457-18

Chrysene	0.27	0.010	mg/kg dry	0.36	0.031	66	10-125	0.0	28	
Fluorene	0.28	0.010	"	0.36	ND	78	10-154	3.5	32	
Indeno (1,2,3-cd) pyrene	0.27	0.010	"	0.36	ND	75	10-144	7.7	47	
Surrogate: p-Terphenyl-d14	1.4		"	1.8		78	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Physical Parameters by APHA/ASTM/EPA Methods - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I25049: Prepared 09/25/01 Using Dry Weight

Blank (1I25049-BLK1)

Dry Weight	100	1.00	%							
------------	-----	------	---	--	--	--	--	--	--	--

Batch 1I26001: Prepared 09/25/01 Using Dry Weight

Blank (1I26001-BLK1)

Dry Weight	100	1.00	%							
------------	-----	------	---	--	--	--	--	--	--	--



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/08/01 21:02
--	--	-----------------------------

Notes and Definitions

- G-01 Results reported for the gas range are primarily due to overlap from diesel range hydrocarbons.
- I-06 The analyte concentration may be artificially elevated due to coeluting compounds or components.
- Q-01 The spike recovery for this QC sample is outside of established control limits. Review of associated batch QC indicates the recovery for this analyte does not represent an out-of-control condition for the batch.
- Q-02 The spike recovery for this QC sample is outside of NCA established control limits due to sample matrix interference.
- S-01 The surrogate recovery for this sample is not available due to sample dilution required from high analyte concentration and/or matrix interferences.
- S-02 The surrogate recovery for this sample cannot be accurately quantified due to interference from coeluting organic compounds present in the sample.
- S-04 The surrogate recovery for this sample is outside of established control limits due to a sample matrix effect.
- S-06 The recovery of this surrogate is outside control limits due to sample dilution required from high analyte concentration and/or matrix interferences.
- DET Analyte DETECTED
- Analyte NOT DETECTED at or above the reporting limit
- NK Not Reported
- dry Sample results reported on a dry weight basis
- RPD Relative Percent Difference

Scott A. Woerman, Project Manager



UNOCAL CHAIN OF CUSTODY REPORT

310457

18939 120th Avenue N.E., Suite 101, Bothell, WA 98011-9508 (206) 481-9200 FAX 485-2992
 East 11115 Montgomery, Suite B, Spokane, WA 99206-4779 (509) 924-9200 FAX 924-9290
 9405 S.W. Nimbus Avenue, Beaverton, OR 97008-7132 (503) 643-9200 FAX 644-2202

UNOCAL INFORMATION

Facility Number: Unocal Edmonds Terminal

Site Address: 11720 Unoco Road

City, State, ZIP: Edmonds, 98020

Site Release Number:

Unocal Manager: Mark Bearley

CERT INFO: (check one) Evaluation Remediation Detection Demolition Closure Miscellaneous

CONSULTANT INFORMATION

Firm: Maul Foster & Alonzi Project Number: 9077.001.004

Address: 17171 Bothell Way NE, #264
Seattle, 98155

Phone: 425-744-1489 Fax: 744-0919

Project Manager: L. Dawson

Sample Collection by: R. Dyer

Chain of Custody Record #:

Quality Assurance Data Level:
 A B

A: Standard Summary
Per site QAM
 B: Standard + Chromatograms

Laboratory Turnaround Days:
 10 5 3 2 1

SAMPLE IDENTIFICATION	SAMPLING DATE / TIME	MATRIX (W,S,O)	# OF CONTAINERS
1. SP-A1-10-1-5	9-21-01/1500	S	1
2. SP-A1-20-7-10			
3. SP-A1-67-7-8			
4. SP-A1-93-5-23			
5. SP-A1-124-6-17			
6. SP-A1-147-4-30			
7. SP-A1-162-2-3			
8. SP-A1-188-1-7			
9. SP-A1-220-5-25			
10. SP-A1-235-7-27			

Oregon Washington Hydrocarbon Methods NWTPH

TPH-HCID	TPH-Gas	BTEX (EPA 8020 Mod.) TPH-Gas + BTEX <u>NW</u>	TPH-Diesel Extended <u>NW</u>	TPH-418.1	Halogen Volatiles (EPA 8010)	Aromatic Volatiles (EPA 8020)	Pesticides/PCBs or PCBs Only	GC/MS Volatiles (EPA 8240/8260)	GC/MS SemiVol. (EPA 8270)	PAHs by HPLC (EPA 8310)	Lead	Total or Dissolved TCLP Metals (8)	PAHs ⁶
		X	X										X
		X	X										X
		X	X										X
		X	X										X
		X	X										X
		X	X										X
		X	X										X
		X	X										X
		X	X										X

NWTPH + PAHs
BTEX

NCA SAMPLE NUMBER
-01
-02
-03
-04
-05
-06
-07
-08
-09
-10

Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
<u>[Signature]</u>	<u>MFA</u>	<u>9-21-01 1700</u>	<u>[Signature]</u>	<u>NCA</u>	<u>9/21/01 1705</u>

Final Report Approval

Were all requested results provided? yes no Define

Were results within requested turnaround? yes no "No"

Final Approval Signature: _____ on back

Firm: _____

Comments: @ silicagel cleanup on NWTPH
PAHs by 8270 SIM, incl. -lan-2 Met... naphthalene
 Distribution: White - Laboratory Yellow - Consultant Photocopy - Unocal



ica™
North Creek Analytical, Inc.
Environmental Laboratory Network
www.ncalabs.com

11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8223
East 11115 Montgomery, Suite B, Spokane, WA 98206-4776
9405 S.W. Nimbus Avenue, Beaverton, OR 97008-7132
20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711

(425) 420-9200 FAX 420-9210
(509) 924-9200 24-9290
(503) 906-9200 06-9210
(541) 383-9310 FAX 382-7588



UNOCAL CHAIN OF CUSTODY REPORT

BIT0457

UNOCAL INFORMATION	
Facility Number:	Unocal Edmonds Terminal
Site Address:	11720 Unoco Road
City, State, ZIP:	Edmonds, 98020
Site Release Number:	
Unocal Manager:	Mark Bearley
CERT INFO: (check one)	<input type="checkbox"/> Evaluation <input checked="" type="checkbox"/> Remediation
	<input type="checkbox"/> Detection <input type="checkbox"/> Demolition <input type="checkbox"/> Closure <input type="checkbox"/> Miscellaneous

CONSULTANT INFORMATION	
Firm:	Mani Foster + Alongi Project# 9077.001.004
Address:	17171 Bothell Way NE, #264 Seattle 98155
Phone:	425-744-1489 Fax: 744-0919
Project Manager:	L. Dawson
Sample Collection by:	R. Dyer

Chain of Custody Record #:
Quality Assurance Data Level: <input type="checkbox"/> A <input checked="" type="checkbox"/> B A: Standard Summary per Site QA B: Standard + Chromatograms
Laboratory Turnaround Days: <input checked="" type="checkbox"/> 10 <input type="checkbox"/> 5 <input type="checkbox"/> 3 <input type="checkbox"/> 2 <input type="checkbox"/> 1

SAMPLE IDENTIFICATION	SAMPLING DATE / TIME	MATRIX (W,S,O)	# OF CONTAINERS
1. SP-A1-255-3-4	9/21-01/1500	S	1
2. SP-B1-5-1-10	9-20-01/1300	S	1
3. SP-B1-28-2-2			
4. SP-B1-63-6-18			
5. SP-B1-83-3-4			
6. SP-B1-99-12-9			
7. SP-B1-112-5-8			
8. SP-B1-131-13-12			
9. SP-B1-197-1-17			
10. SP-B1-219-5-6			

<input type="radio"/> OR <input type="radio"/> WA <input type="radio"/> AK <input checked="" type="radio"/> NW Series													
TPH-HCID	TPH-Gas	BTEX EPA 8021 Mod.	TPH-Gas + BTEX (a)	TPH-Diesel	TPH-Diesel Extended	TPH-Diesel-Ext w/SG Cleanup	Halogen Volatiles EPA 8021	Pesticides/PCBs or PCBs Only	GC/MS Volatiles EPA 8260	GC/MS SemiVol. EPA 8270	PAHs: EPA 8270 SIM or 8310	Lead:	Total or Dissolved TCLP or RCRA Metals (8)
		X	X	X	X	X					PAHs (b)		X
		X	X	X	X	X							X
		X	X	X	X	X							X
		X	X	X	X	X							X
		X	X	X	X	X							X
		X	X	X	X	X							X
		X	X	X	X	X							X
		X	X	X	X	X							X
		X	X	X	X	X							X
		X	X	X	X	X							X

PAHs	NWTPH + BTEX
NCA SAMPLE NUMBER	
	-11
	-12
	-13
	-14
	-15
	-16
	-17
	-18
	-19
	-20

Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
1. <i>[Signature]</i>	MFA	9-21-01: 1700	<i>[Signature]</i>	NEA	9/21/01 1705
2.					w/ 4.5
3.					

Final Report Approval		
Were all requested results provided?	<input type="checkbox"/> yes <input type="checkbox"/> no	Define
Were results within requested turnaround?	<input type="checkbox"/> yes <input type="checkbox"/> no	"No"
Final Approval Signature:		on back
Firm:	Date:	



BIO457

UNOCAL CHAIN OF CUSTODY REPORT

UNOCAL INFORMATION

Facility Number: Unocal Edmonds Terminal

Site Address: 11720 Unoco Road

City, State, ZIP: Edmonds, WA 98020

Site Release Number:

Unocal Manager: Mark Beasley

CERT INFO: (check one) Evaluation Remediation
 Detection Demolition Closure Miscellaneous

CONSULTANT INFORMATION

Firm: Maul Foster & Alangi Project # 9077.001.004

Address: 17171 Bothell Way NE #264
Seattle 98155

Phone: 425-744-1489 Fax: 744-0919

Project Manager: L. Dawson

Sample Collection by: R. Dyer

Chain of Custody Record #:

Quality Assurance Data Level:
 A B
A: Standard Summary
Per site QA
B: Standard + Chromatograms

Laboratory Turnaround Days:
 10 5 3 2 1

SAMPLE IDENTIFICATION	SAMPLING DATE/TIME	MATRIX (W.S.O)	# OF CONTAINERS
1. SP-BI-266-2-20	9-21-01/1302	S	1
2.			
3.			
4. TP-1-3.5	9/21-01/1000	S	1
5. TP-2-4	9-21-01/1002	S	1
6. TP-3-4	9-21-01/1000	S	1
7. SP-BI-126-3-9	9/21/01 1400	S	1
8.			
9.			
10.			

		<input type="checkbox"/> OR	<input type="checkbox"/> WA	<input type="checkbox"/> AK	<input checked="" type="checkbox"/> NW Series														
TPH-HCID	TPH-Gas	BTEX EPA 8021 Mod.	TPH-Gas + BTEX (4)	TPH-Diesel	TPH-Diesel Extended	TPH-Diesel-Ext. w/SG Cleanup	Halogen. Volatiles EPA 8021	Pesticides/PCBs or PCBs Only	GC/MS Volatiles EPA 8260	GC/MS Semivols. EPA 8270	PAH's: 8270 SIM or 8310	Lead:	Total or Dissolved TCLP or RCRA Metals (8)	PAHs (6)					
			X		X									X					
			X		X									X					
			X		X									X					
			X		X									X					

PAHs
TP's TPH+BTEX

MWTPH+BTEX

NCA SAMPLE NUMBER

-21

-22

-23

-24

-25

Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
1. <u>[Signature]</u>	<u>MFA</u>	<u>9-21-01-1700</u>	<u>[Signature]</u>	<u>NCA</u>	<u>9/21/01 1705</u>
2.					
3.					

Final Report Approval

Were all requested results provided? yes no Define

Were results within requested turnaround? yes no "No" on back

Final Approval Signature: _____

Firm: _____



UNOCAL CHAIN OF CUSTODY REPORT

UNOCAL INFORMATION	
Facility Number: <i>Unocal Edmonds Terminal</i>	
Site Address: <i>11720 Unocal Road</i>	
City, State, ZIP: <i>Edmonds, 98020</i>	
Site Release Number:	
Unocal Manager: <i>Mark Beasley</i>	
CERT INFO: (check one) <input type="checkbox"/> Evaluation <input checked="" type="checkbox"/> Remediation	
<input type="checkbox"/> Detection <input type="checkbox"/> Demolition <input type="checkbox"/> Closure <input type="checkbox"/> Miscellaneous	

CONSULTANT INFORMATION	
Firm: <i>Maul Foster & Longi</i>	Project # <i>9077.001.007</i>
Address: <i>17171 Bothell Way NE #264</i>	
<i>Seattle 98155</i>	
Phone: <i>425-444-1489</i>	Fax: <i>744-0919</i>
Project Manager: <i>L. Dawson</i>	
Sample Collection by: <i>R. Dyer</i>	

Chain of Custody Record #:
Quality Assurance Data Level: <input type="checkbox"/> A <input checked="" type="checkbox"/> B A: Standard Summary <i>Per Site QA</i> B: Standard + Chromatograms
Laboratory Turnaround Days: <input checked="" type="checkbox"/> 10 <input type="checkbox"/> 5 <input checked="" type="checkbox"/> 3 <input type="checkbox"/> 2 <input type="checkbox"/> 1

SAMPLE IDENTIFICATION	SAMPLING DATE/TIME	MATRIX (W,S,O)	# OF CONTAINERS
1. <i>SP-B1-266-2-20</i>	<i>9-21-01/1300</i>	<i>S</i>	<i>1</i>
2.			
3.			
4. <i>TP-1-3.5</i>	<i>9/21-01/1000</i>	<i>S</i>	<i>1</i>
5. <i>TP-2-4</i>	<i>9-21-01/1000</i>	<i>S</i>	<i>1</i>
6. <i>TP-3-4</i>	<i>9-21-01/1000</i>	<i>S</i>	<i>1</i>
7.			
8.			
9.			
10.			

○ OR ○ WA ○ AK <input checked="" type="checkbox"/> NW Series														
TPH-HCID	TPH-Gas	BTEX EPA 8021 Mod.	TPH-Gas + BTEX	TPH-Diesel	TPH-Diesel Extended	TPH-Diesel-Ext w/SG Cleanup	Halogen Volatiles EPA 8021	Pesticides/PCBs or PCBs Only	GC/MS Volatiles EPA 8260	GC/MS Semi Vols. EPA 8270	PAH's: 8270 SIM or 8310	Lead: Total or Dissolved	TCLP or RCRA Metals (8)	
			X		X								X	21
			X		X								X	22
			X		X								X	23
			X		X								X	24

PAHs *NW TPH + BTEX*
TP's TPH + BTEX

NCA SAMPLE NUMBER


Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
1. <i>[Signature]</i>	<i>MFA</i>	<i>9-21-01-1700</i>	<i>[Signature]</i>	<i>NCA</i>	<i>9/21/01 1705</i>
2.					
3.					

Final Report Approval		
Were all requested results provided?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	Define
Were results within requested turnaround?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	"No"
Final Approval Signature: _____		on back
Firm: _____	Date: _____	



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

20 September 2001



Linda Dawson
Maul Foster & Alongi-Seattle
17171 Bothell Way NE #264
Seattle, WA/USA 98155
RE: Former Bulk Storage of Edmonds

Enclosed are the results of analyses for samples received by the laboratory on 09/07/01 17:15. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Scott A. Woerman
Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network

stockpile C



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
SP-C1-46-3-2	B1I0109-01	Soil	09/07/01 15:00	09/07/01 17:15
SP-C1-68-4-2	B1I0109-02	Soil	09/07/01 15:00	09/07/01 17:15
SP-C1-92-6-4	B1I0109-03	Soil	09/07/01 15:00	09/07/01 17:15
SP-C1-114-5-2	B1I0109-04	Soil	09/07/01 15:00	09/07/01 17:15
SP-C1-124-6-4	B1I0109-05	Soil	09/07/01 15:00	09/07/01 17:15
SP-C1-155-7-4	B1I0109-06	Soil	09/07/01 15:00	09/07/01 17:15
rinsate	B1I0109-07	Water	09/07/01 14:02	09/07/01 17:15

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 09/20/01 10:02
--	--	-----------------------------

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-C1-46-3-2 (B1I0109-01) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Gasoline Range Hydrocarbons	74.9	5.00	mg/kg dry	1	1110036	09/10/01	09/12/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	80.5 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	82.5 %	54-123			"	"	"	"	
SP-C1-68-4-2 (B1I0109-02) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Gasoline Range Hydrocarbons	ND	5.00	mg/kg dry	1	1110036	09/10/01	09/10/01	NWTPH-Gx/8021B	
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	81.8 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	83.4 %	54-123			"	"	"	"	
SP-C1-92-6-4 (B1I0109-03) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Gasoline Range Hydrocarbons	91.6	5.00	mg/kg dry	1	1110036	09/10/01	09/13/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	0.110	0.100	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	85.4 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	84.1 %	54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-C1-114-5-2 (B1I0109-04) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Gasoline Range Hydrocarbons	121	5.00	mg/kg dry	1	1I10036	09/10/01	09/13/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	0.101	0.100	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	84.7 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	77.7 %	54-123			"	"	"	"	
SP-C1-124-6-4 (B1I0109-05) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Gasoline Range Hydrocarbons	31.8	5.00	mg/kg dry	1	1I10036	09/10/01	09/13/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	79.0 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	78.4 %	54-123			"	"	"	"	
SP-C1-155-7-4 (B1I0109-06) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Gasoline Range Hydrocarbons	34.8	5.00	mg/kg dry	1	1I10036	09/10/01	09/13/01	NWTPH-Gx/8021B	G-01
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	82.4 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	79.7 %	54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
rinsate (B110109-07) Water Sampled: 09/07/01 14:02 Received: 09/07/01 17:15									
Gasoline Range Hydrocarbons	ND	50.0	ug/l	1	1112009	09/12/01	09/12/01	NWTPH-Gx/8021B	
Benzene	ND	0.500	"	"	"	"	"	"	
Toluene	ND	0.500	"	"	"	"	"	"	
Ethylbenzene	ND	0.500	"	"	"	"	"	"	
Xylenes (total)	ND	1.00	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	96.5 %	62-139			"	"	"	"	
Surrogate: 4-BFB (PID)	96.9 %	62-125			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-C1-46-3-2 (B110109-01) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Diesel Range Hydrocarbons	3590	210	mg/kg dry	21	1111008	09/11/01	09/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	1310	525	"	"	"	"	"	"	
Surrogate: 2-FBP	119 %	50-150			"	"	"	"	
Surrogate: Octacosane	%	50-150			"	"	"	"	S-01
SP-C1-68-4-2 (B110109-02) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Diesel Range Hydrocarbons	141	10.0	mg/kg dry	1	1111008	09/11/01	09/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	139	25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	72.4 %	50-150			"	"	"	"	
Surrogate: Octacosane	89.6 %	50-150			"	"	"	"	
SP-C1-92-6-4 (B110109-03) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Diesel Range Hydrocarbons	3540	410	mg/kg dry	41	1111008	09/11/01	09/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	1340	1020	"	"	"	"	"	"	
Surrogate: 2-FBP	110 %	50-150			"	"	"	"	
Surrogate: Octacosane	%	50-150			"	"	"	"	S-01
SP-C1-114-5-2 (B110109-04) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Diesel Range Hydrocarbons	3150	210	mg/kg dry	21	1111008	09/11/01	09/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	1160	525	"	"	"	"	"	"	
Surrogate: 2-FBP	105 %	50-150			"	"	"	"	
Surrogate: Octacosane	106 %	50-150			"	"	"	"	
SP-C1-124-6-4 (B110109-05) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Diesel Range Hydrocarbons	2800	410	mg/kg dry	41	1111008	09/11/01	09/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND	1020	"	"	"	"	"	"	
Surrogate: 2-FBP	93.2 %	50-150			"	"	"	"	
Surrogate: Octacosane	%	50-150			"	"	"	"	S-01

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-C1-155-7-4 (B1I0109-06) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Diesel Range Hydrocarbons	2440	410	mg/kg dry	41	1111008	09/11/01	09/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND	1020	"	"	"	"	"	"	
Surrogate: 2-FBP	%	50-150			"	"	"	"	S-01
Surrogate: Octacosane	111 %	50-150			"	"	"	"	
rinsate (B1I0109-07) Water Sampled: 09/07/01 14:02 Received: 09/07/01 17:15									
Diesel Range Hydrocarbons	ND	0.250	mg/l	1	1108004	09/08/01	09/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND	0.500	"	"	"	"	"	"	
Surrogate: 2-FBP	65.0 %	50-150			"	"	"	"	
Surrogate: Octacosane	64.3 %	50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 09/20/01 10:02
--	--	-----------------------------

Polynuclear Aromatic Compounds by GC/MS with Selected Ion Monitoring
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

SP-C1-46-3-2 (B110109-01) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15

1-Methylnaphthalene	0.0661	0.0100	mg/kg dry	1	1117027	09/17/01	09/19/01	EPA 8270 Mod	
2-Methylnaphthalene	0.0535	0.0100	"	"	"	"	"	"	
Acenaphthene	0.0825	0.0100	"	"	"	"	"	"	
Acenaphthylene	ND	0.0100	"	"	"	"	"	"	
Anthracene	0.0684	0.0100	"	"	"	"	"	"	
Benzo (a) anthracene	0.113	0.0100	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0100	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0100	"	"	"	"	"	"	
Benzo (ghi) perylene	0.0483	0.0100	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0100	"	"	"	"	"	"	
Chrysene	0.268	0.0100	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0100	"	"	"	"	"	"	
Fluoranthene	0.132	0.0100	"	"	"	"	"	"	
Fluorene	0.127	0.0100	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0100	"	"	"	"	"	"	
Naphthalene	ND	0.0100	"	"	"	"	"	"	
Phenanthrene	0.698	0.0100	"	"	"	"	"	"	
Pyrene	0.300	0.0100	"	"	"	"	"	"	
Surrogate: 2-FBP	112 %	13-140			"	"	"	"	
Surrogate: Nitrobenzene-d5	114 %	10-136			"	"	"	"	
Surrogate: p-Terphenyl-d14	87.6 %	30-150			"	"	"	"	

SP-C1-68-4-2 (B110109-02) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15

1-Methylnaphthalene	ND	0.0100	mg/kg dry	1	1117027	09/17/01	09/19/01	EPA 8270 Mod	
2-Methylnaphthalene	ND	0.0100	"	"	"	"	"	"	
Acenaphthene	ND	0.0100	"	"	"	"	"	"	
Acenaphthylene	ND	0.0100	"	"	"	"	"	"	
Anthracene	ND	0.0100	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0100	"	"	"	"	"	"	
Benzo (a) pyrene	0.0310	0.0100	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0100	"	"	"	"	"	"	
Benzo (ghi) perylene	0.0166	0.0100	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0100	"	"	"	"	"	"	
Chrysene	ND	0.0100	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0100	"	"	"	"	"	"	
Fluoranthene	0.0108	0.0100	"	"	"	"	"	"	
Fluorene	ND	0.0100	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	0.0346	0.0100	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Polynuclear Aromatic Compounds by GC/MS with Selected Ion Monitoring
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-C1-68-4-2 (B1I0109-02) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Naphthalene	ND	0.0100	mg/kg dry	1	1117027	09/17/01	09/19/01	EPA 8270 Mod	
Phenanthrene	ND	0.0100	"	"	"	"	"	"	
Pyrene	0.0159	0.0100	"	"	"	"	"	"	
Surrogate: 2-FBP	113 %	13-140			"	"	"	"	
Surrogate: Nitrobenzene-d5	97.8 %	10-136			"	"	"	"	
Surrogate: p-Terphenyl-d14	107 %	30-150			"	"	"	"	
SP-C1-92-6-4 (B1I0109-03) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
1-Methylnaphthalene	0.0843	0.0100	mg/kg dry	1	1117027	09/17/01	09/19/01	EPA 8270 Mod	
2-Methylnaphthalene	0.0655	0.0100	"	"	"	"	"	"	
Acenaphthene	0.100	0.0100	"	"	"	"	"	"	
Acenaphthylene	ND	0.0100	"	"	"	"	"	"	
Anthracene	0.0617	0.0100	"	"	"	"	"	"	
o (a) anthracene	0.144	0.0100	"	"	"	"	"	"	
o (a) pyrene	0.138	0.0100	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0100	"	"	"	"	"	"	
Benzo (ghi) perylene	0.0632	0.0100	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0100	"	"	"	"	"	"	
Chrysene	0.296	0.0100	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0100	"	"	"	"	"	"	
Fluoranthene	0.100	0.0100	"	"	"	"	"	"	
Fluorene	0.141	0.0100	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0100	"	"	"	"	"	"	
Naphthalene	ND	0.0100	"	"	"	"	"	"	
Phenanthrene	0.768	0.0100	"	"	"	"	"	"	
Pyrene	0.366	0.0100	"	"	"	"	"	"	
Surrogate: 2-FBP	128 %	13-140			"	"	"	"	
Surrogate: Nitrobenzene-d5	113 %	10-136			"	"	"	"	
Surrogate: p-Terphenyl-d14	97.3 %	30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Polynuclear Aromatic Compounds by GC/MS with Selected Ion Monitoring
North Creek Analytical - Bothell

Analyte	Result	Reporting		Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		Limit								

SP-C1-114-5-2 (B1I0109-04) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15

1-Methylnaphthalene	0.0768	0.0100	mg/kg dry	1	1117027	09/17/01	09/19/01	EPA 8270 Mod		
2-Methylnaphthalene	0.0709	0.0100	"	"	"	"	"	"	"	"
Acenaphthene	0.0585	0.0100	"	"	"	"	"	"	"	"
Acenaphthylene	ND	0.0100	"	"	"	"	"	"	"	"
Anthracene	0.0717	0.0100	"	"	"	"	"	"	"	"
Benzo (a) anthracene	0.128	0.0100	"	"	"	"	"	"	"	"
Benzo (a) pyrene	ND	0.0100	"	"	"	"	"	"	"	"
Benzo (b) fluoranthene	ND	0.0100	"	"	"	"	"	"	"	"
Benzo (ghi) perylene	ND	0.0100	"	"	"	"	"	"	"	"
Benzo (k) fluoranthene	ND	0.0100	"	"	"	"	"	"	"	"
Chrysene	0.278	0.0100	"	"	"	"	"	"	"	"
Dibenz (a,h) anthracene	ND	0.0100	"	"	"	"	"	"	"	"
Fluoranthene	ND	0.0100	"	"	"	"	"	"	"	"
Fluorene	0.129	0.0100	"	"	"	"	"	"	"	"
Indeno (1,2,3-cd) pyrene	ND	0.0100	"	"	"	"	"	"	"	"
Naphthalene	ND	0.0100	"	"	"	"	"	"	"	"
Phenanthrene	0.662	0.0100	"	"	"	"	"	"	"	"
Pyrene	0.344	0.0100	"	"	"	"	"	"	"	"
Surrogate: 2-FBP	131 %	13-140			"	"	"	"	"	"
Surrogate: Nitrobenzene-d5	111 %	10-136			"	"	"	"	"	"
Surrogate: p-Terphenyl-d14	94.0 %	30-150			"	"	"	"	"	"

SP-C1-124-6-4 (B1I0109-05) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15

1-Methylnaphthalene	0.347	0.0100	mg/kg dry	1	1117027	09/17/01	09/19/01	EPA 8270 Mod		
2-Methylnaphthalene	0.371	0.0100	"	"	"	"	"	"	"	"
Acenaphthene	0.113	0.0100	"	"	"	"	"	"	"	"
Acenaphthylene	ND	0.0100	"	"	"	"	"	"	"	"
Anthracene	0.0724	0.0100	"	"	"	"	"	"	"	"
Benzo (a) anthracene	0.140	0.0100	"	"	"	"	"	"	"	"
Benzo (a) pyrene	ND	0.0100	"	"	"	"	"	"	"	"
Benzo (b) fluoranthene	ND	0.0100	"	"	"	"	"	"	"	"
Benzo (ghi) perylene	ND	0.0100	"	"	"	"	"	"	"	"
Benzo (k) fluoranthene	ND	0.0100	"	"	"	"	"	"	"	"
Chrysene	0.317	0.0100	"	"	"	"	"	"	"	"
Dibenz (a,h) anthracene	ND	0.0100	"	"	"	"	"	"	"	"
Fluoranthene	0.132	0.0100	"	"	"	"	"	"	"	"
Fluorene	0.360	0.0100	"	"	"	"	"	"	"	"
Indeno (1,2,3-cd) pyrene	ND	0.0100	"	"	"	"	"	"	"	"

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Polynuclear Aromatic Compounds by GC/MS with Selected Ion Monitoring
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-C1-124-6-4 (B1I0109-05) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Naphthalene	0.0205	0.0100	mg/kg dry	1	1117027	09/17/01	09/19/01	EPA 8270 Mod	
Phenanthrene	1.37	0.0100	"	"	"	"	"	"	
Pyrene	0.365	0.0100	"	"	"	"	"	"	
Surrogate: 2-FBP	124 %	13-140			"	"	"	"	
Surrogate: Nitrobenzene-d5	105 %	10-136			"	"	"	"	
Surrogate: p-Terphenyl-d14	104 %	30-150			"	"	"	"	
SP-C1-155-7-4 (B1I0109-06) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
1-Methylnaphthalene	0.796	0.0500	mg/kg dry	5	1117027	09/17/01	09/19/01	EPA 8270 Mod	
2-Methylnaphthalene	0.544	0.0500	"	"	"	"	"	"	
Acenaphthene	0.237	0.0500	"	"	"	"	"	"	
Acenaphthylene	0.0767	0.0500	"	"	"	"	"	"	
Anthracene	0.223	0.0500	"	"	"	"	"	"	
o (a) anthracene	0.157	0.0500	"	"	"	"	"	"	
o (a) pyrene	0.201	0.0500	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0500	"	"	"	"	"	"	
Benzo (ghi) perylene	0.0548	0.0500	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0500	"	"	"	"	"	"	
Chrysene	0.427	0.0500	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0500	"	"	"	"	"	"	
Fluoranthene	0.241	0.0500	"	"	"	"	"	"	
Fluorene	0.654	0.0500	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	0.172	0.0500	"	"	"	"	"	"	
Naphthalene	ND	0.0500	"	"	"	"	"	"	
Phenanthrene	2.13	0.0500	"	"	"	"	"	"	
Pyrene	0.625	0.0500	"	"	"	"	"	"	
Surrogate: 2-FBP	114 %	13-140			"	"	"	"	
Surrogate: Nitrobenzene-d5	100 %	10-136			"	"	"	"	
Surrogate: p-Terphenyl-d14	104 %	30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588


Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 09/20/01 10:02
--	--	-----------------------------

Physical Parameters by APHA/ASTM/EPA Methods
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-C1-46-3-2 (B1I0109-01) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Dry Weight	89.7	1.00	%	1	1I12028	09/12/01	09/13/01	BSOPSPL003R07	
SP-C1-68-4-2 (B1I0109-02) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Dry Weight	92.5	1.00	%	1	1I12028	09/12/01	09/13/01	BSOPSPL003R07	
SP-C1-92-6-4 (B1I0109-03) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Dry Weight	88.6	1.00	%	1	1I12028	09/12/01	09/13/01	BSOPSPL003R07	
SP-C1-114-5-2 (B1I0109-04) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Dry Weight	91.2	1.00	%	1	1I12028	09/12/01	09/13/01	BSOPSPL003R07	
SP-C1-124-6-4 (B1I0109-05) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Dry Weight	91.2	1.00	%	1	1I12028	09/12/01	09/13/01	BSOPSPL003R07	
SP-C1-155-7-4 (B1I0109-06) Soil Sampled: 09/07/01 15:00 Received: 09/07/01 17:15									
Dry Weight	91.3	1.00	%	1	1I12028	09/12/01	09/13/01	BSOPSPL003R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I10036: Prepared 09/10/01 Using EPA 5030B (MeOH)

Blank (1I10036-BLK1)

Gasoline Range Hydrocarbons	ND	5.00	mg/kg							
Benzene	ND	0.0300	"							
Toluene	ND	0.0500	"							
Ethylbenzene	ND	0.0500	"							
Xylenes (total)	ND	0.100	"							
Surrogate: 4-BFB (FID)	3.46		"	4.00		86.5	50-147			
Surrogate: 4-BFB (PID)	3.84		"	4.00		96.0	54-123			

LCS (1I10036-BS1)

Gasoline Range Hydrocarbons	22.9	5.00	mg/kg	25.0		91.6	80-120			
Surrogate: 4-BFB (FID)	3.62		"	4.00		90.5	50-147			

(1I10036-BS2)

Benzene	0.456	0.0300	mg/kg	0.500		91.2	80-120			
Toluene	0.486	0.0500	"	0.500		97.2	80-120			
Ethylbenzene	0.509	0.0500	"	0.500		102	80-120			
Xylenes (total)	1.55	0.100	"	1.50		103	80-120			
Surrogate: 4-BFB (PID)	3.58		"	4.00		89.5	54-123			

LCS Dup (1I10036-BSD1)

Gasoline Range Hydrocarbons	23.3	5.00	mg/kg	25.0		93.2	80-120	1.73	40	
Surrogate: 4-BFB (FID)	3.66		"	4.00		91.5	50-147			

LCS Dup (1I10036-BSD2)

Benzene	0.447	0.0300	mg/kg	0.500		89.4	80-120	1.99	40	
Toluene	0.473	0.0500	"	0.500		94.6	80-120	2.71	40	
Ethylbenzene	0.498	0.0500	"	0.500		99.6	80-120	2.18	40	
Xylenes (total)	1.51	0.100	"	1.50		101	80-120	2.61	40	
Surrogate: 4-BFB (PID)	3.53		"	4.00		88.2	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I10036: Prepared 09/10/01 Using EPA 5030B (MeOH)

Matrix Spike (1I10036-MS1) Source: B1I0125-01

Gasoline Range Hydrocarbons	24.1	5.00	mg/kg dry	27.2	ND	88.6	53-120			
Surrogate: 4-BFB (FID)	3.84		"	4.36		88.1	50-147			

Matrix Spike (1I10036-MS2) Source: B1I0109-02

Benzene	0.481	0.0300	mg/kg dry	0.541	ND	88.9	64-130			
Toluene	0.520	0.0500	"	0.541	ND	96.1	66-130			
Ethylbenzene	0.546	0.0500	"	0.541	ND	99.6	72-130			
Xylenes (total)	1.67	0.100	"	1.62	ND	101	73-130			
Surrogate: 4-BFB (PID)	3.73		"	4.33		86.1	54-123			

Matrix Spike Dup (1I10036-MSD1) Source: B1I0125-01

Gasoline Range Hydrocarbons	23.9	5.00	mg/kg dry	27.2	ND	87.9	53-120	0.833	40	
Surrogate: 4-BFB (FID)	3.76		"	4.36		86.2	50-147			

Matrix Spike Dup (1I10036-MSD2) Source: B1I0109-02

Benzene	0.473	0.0300	mg/kg dry	0.541	ND	87.4	64-130	1.68	40	
Toluene	0.509	0.0500	"	0.541	ND	94.1	66-130	2.14	40	
Ethylbenzene	0.537	0.0500	"	0.541	ND	97.9	72-130	1.66	40	
Xylenes (total)	1.58	0.100	"	1.62	ND	95.5	73-130	5.54	40	
Surrogate: 4-BFB (PID)	3.75		"	4.33		86.6	54-123			

Batch 1I12009: Prepared 09/12/01 Using EPA 5030B (P/T)

Blank (1I12009-BLK1)

Gasoline Range Hydrocarbons	ND	50.0	ug/l							
Benzene	ND	0.500	"							
Toluene	ND	0.500	"							
Ethylbenzene	ND	0.500	"							
Xylenes (total)	ND	1.00	"							
Surrogate: 4-BFB (FID)	43.6		"	48.0		90.8	62-139			
Surrogate: 4-BFB (PID)	46.5		"	48.0		96.9	62-125			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I12009: Prepared 09/12/01 Using EPA 5030B (P/T)

LCS (1I12009-BS1)

Gasoline Range Hydrocarbons	505	50.0	ug/l	500		101	80-120			
Benzene	6.09	0.500	"	6.01		101	80-120			
Toluene	33.7	0.500	"	36.1		93.4	80-120			
Ethylbenzene	8.85	0.500	"	8.37		106	80-120			
Xylenes (total)	41.2	1.00	"	42.0		98.1	80-120			
Surrogate: 4-BFB (FID)	48.2		"	48.0		100	62-139			
Surrogate: 4-BFB (PID)	43.7		"	48.0		91.0	62-125			

LCS Dup (1I12009-BSD1)

Gasoline Range Hydrocarbons	519	50.0	ug/l	500		104	80-120	2.73	25	
Benzene	6.18	0.500	"	6.01		103	80-120	1.47	40	
ne	33.8	0.500	"	36.1		93.6	80-120	0.296	40	
benzene	8.90	0.500	"	8.37		106	80-120	0.563	40	
Xylenes (total)	41.9	1.00	"	42.0		99.8	80-120	1.68	40	
Surrogate: 4-BFB (FID)	48.4		"	48.0		101	62-139			
Surrogate: 4-BFB (PID)	43.8		"	48.0		91.2	62-125			

Source: B1I0106-22

Matrix Spike (1I12009-MS1)

Gasoline Range Hydrocarbons	484	50.0	ug/l	500	ND	92.9	70-130			
Benzene	6.92	0.500	"	6.01	1.20	95.2	80-120			
Toluene	35.9	0.500	"	36.1	4.07	88.2	75-117			
Ethylbenzene	8.99	0.500	"	8.37	ND	101	80-120			
Xylenes (total)	42.6	1.00	"	42.0	2.29	96.0	80-120			
Surrogate: 4-BFB (FID)	46.8		"	48.0		97.5	62-139			
Surrogate: 4-BFB (PID)	44.7		"	48.0		93.1	62-125			

Source: B1I0106-22

Matrix Spike Dup (1I12009-MSD1)

Gasoline Range Hydrocarbons	501	50.0	ug/l	500	ND	96.3	70-130	3.45	25	
Benzene	7.00	0.500	"	6.01	1.20	96.5	80-120	1.15	40	
Toluene	36.6	0.500	"	36.1	4.07	90.1	75-117	1.93	40	
Ethylbenzene	9.14	0.500	"	8.37	ND	103	80-120	1.65	40	
Xylenes (total)	43.3	1.00	"	42.0	2.29	97.6	80-120	1.63	40	
Surrogate: 4-BFB (FID)	47.7		"	48.0		99.4	62-139			
Surrogate: 4-BFB (PID)	44.6		"	48.0		92.9	62-125			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I08004: Prepared 09/08/01 Using zz 3520C/600 Series

Blank (1I08004-BLK1)

Diesel Range Hydrocarbons	ND	0.250	mg/l							
Lube Oil Range Hydrocarbons	ND	0.500	"							
Surrogate: 2-FBP	0.227		"	0.320		70.9	50-150			
Surrogate: Octacosane	0.231		"	0.320		72.2	50-150			

LCS (1I08004-BS1)

Diesel Range Hydrocarbons	1.70	0.250	mg/l	2.00		85.0	50-150			
Surrogate: 2-FBP	0.248		"	0.320		77.5	50-150			

LCS Dup (1I08004-BSD1)

Diesel Range Hydrocarbons	1.76	0.250	mg/l	2.00		88.0	50-150	3.47	50	
Surrogate: 2-FBP	0.270		"	0.320		84.4	50-150			

Batch 1I11008: Prepared 09/11/01 Using EPA 3550B

Blank (1I11008-BLK1)

Diesel Range Hydrocarbons	ND	10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND	25.0	"							
Surrogate: 2-FBP	10.1		"	10.7		94.4	50-150			
Surrogate: Octacosane	9.10		"	10.7		85.0	50-150			

LCS (1I11008-BS1)

Diesel Range Hydrocarbons	97.0	10.0	mg/kg	66.7		145	50-150			
Surrogate: 2-FBP	11.1		"	10.7		104	50-150			

LCS Dup (1I11008-BSD1)

Diesel Range Hydrocarbons	64.8	10.0	mg/kg	66.7		97.2	50-150	39.8	50	
Surrogate: 2-FBP	11.0		"	10.7		103	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 09/20/01 10:02

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I11008: Prepared 09/11/01 Using EPA 3550B

Duplicate (1I11008-DUP1)

Source: B1I0109-01

Diesel Range Hydrocarbons	3840	210	mg/kg dry		3590			6.73	50	
Lube Oil Range Hydrocarbons	1400	525	"		1310			6.64	50	
Surrogate: 2-FBP	14.0		"	11.9		118	50-150			
Surrogate: Octacosane	0.00		"	11.9			50-150			S-01

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 403, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 09/20/01 10:02
--	--	-----------------------------

Polynuclear Aromatic Compounds by GC/MS with Selected Ion Monitoring - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I17027: Prepared 09/17/01 Using EPA 3550B

Blank (1I17027-BLK1)

1-Methylnaphthalene	ND	0.0100	mg/kg							
2-Methylnaphthalene	ND	0.0100	"							
Acenaphthene	ND	0.0100	"							
Acenaphthylene	ND	0.0100	"							
Anthracene	ND	0.0100	"							
Benzo (a) anthracene	ND	0.0100	"							
Benzo (a) pyrene	ND	0.0100	"							
Benzo (b) fluoranthene	ND	0.0100	"							
Benzo (ghi) perylene	ND	0.0100	"							
Benzo (k) fluoranthene	ND	0.0100	"							
Chrysene	ND	0.0100	"							
Dibenz (a,h) anthracene	ND	0.0100	"							
Fluoranthene	ND	0.0100	"							
Fluorene	ND	0.0100	"							
Indeno (1,2,3-cd) pyrene	ND	0.0100	"							
Naphthalene	ND	0.0100	"							
Phenanthrene	ND	0.0100	"							
Pyrene	ND	0.0100	"							
Surrogate: 2-FBP	1.62		"	1.67		97.0	13-140			
Surrogate: Nitrobenzene-d5	1.66		"	1.67		99.4	10-136			
Surrogate: p-Terphenyl-d14	1.79		"	1.67		107	30-150			

LCS (1I17027-BS1)

Chrysene	0.297	0.0100	mg/kg	0.333		89.2	51-124			
Fluorene	0.282	0.0100	"	0.333		84.7	35-141			
Indeno (1,2,3-cd) pyrene	0.251	0.0100	"	0.333		75.4	27-148			
Surrogate: 2-FBP	1.54		"	1.67		92.2	13-140			
Surrogate: Nitrobenzene-d5	1.60		"	1.67		95.8	10-136			
Surrogate: p-Terphenyl-d14	1.64		"	1.67		98.2	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle, WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 09/20/01 10:02
--	---	------------------------------------

Polynuclear Aromatic Compounds by GC/MS with Selected Ion Monitoring - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	--------	-----	-----------	-------

Batch 1I17027: Prepared 09/17/01 Using EPA 3550B

LCS Dup (1I17027-BSD1)

Chrysene	0.312	0.0100	mg/kg	0.333		93.7	51-124	4.93	28	
Fluorene	0.274	0.0100	"	0.333		82.3	35-141	2.88	32	
Indeno (1,2,3-cd) pyrene	0.251	0.0100	"	0.333		75.4	27-148	0.00	34	
Surrogate: 2-FBP	1.45		"	1.67		86.8	13-140			
Surrogate: Nitrobenzene-d5	1.61		"	1.67		96.4	10-136			
Surrogate: p-Terphenyl-d14	1.74		"	1.67		104	30-150			

Matrix Spike (1I17027-MS1)

Source: B1I0109-04

Chrysene	0.546	0.0100	mg/kg dry	0.366	0.278	73.2	15-147			
Fluorene	0.599	0.0100	"	0.366	0.129	128	21-153			
Indeno (1,2,3-cd) pyrene	0.376	0.0100	"	0.366	ND	103	10-179			
Surrogate: 2-FBP	2.25		"	1.83		123	13-140			
Surrogate: Nitrobenzene-d5	2.22		"	1.83		121	10-136			
Surrogate: p-Terphenyl-d14	1.82		"	1.83		99.5	30-150			

Matrix Spike Dup (1I17027-MSD1)

Source: B1I0109-04

Chrysene	0.477	0.0100	mg/kg dry	0.366	0.278	54.4	15-147	13.5	37	
Fluorene	0.556	0.0100	"	0.366	0.129	117	21-153	7.45	38	
Indeno (1,2,3-cd) pyrene	0.391	0.0100	"	0.366	ND	107	10-179	3.91	53	
Surrogate: 2-FBP	2.30		"	1.83		126	13-140			
Surrogate: Nitrobenzene-d5	2.12		"	1.83		116	10-136			
Surrogate: p-Terphenyl-d14	1.66		"	1.83		90.7	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 09/20/01 10:02
--	--	-----------------------------

**Physical Parameters by APHA/ASTM/EPA Methods - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I12028: Prepared 09/12/01 Using Dry Weight

Blank (1I12028-BLK1)

Dry Weight	100	1.00	%							
------------	-----	------	---	--	--	--	--	--	--	--

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588


Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 09/20/01 10:02
---	---	------------------------------------

Notes and Definitions

- G-01 Results reported for the gas range are primarily due to overlap from diesel range hydrocarbons.
- I-06 The analyte concentration may be artificially elevated due to coeluting compounds or components.
- S-01 The surrogate recovery for this sample is not available due to sample dilution required from high analyte concentration and/or matrix interferences.
- DET Analyte DETECTED
- ND Analyte NOT DETECTED at or above the reporting limit
- NR Not Reported
- dry Sample results reported on a dry weight basis
- RPD Relative Percent Difference

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

UNOCAL INFORMATION

Facility Number: Unocal Edmonds Terminal

Site Address: 11720 Unocal Road

City, State, ZIP: Edmonds, 98020

Site Release Number:

Unocal Manager: Mark Bravley

CERT INFO: (check one) Evaluation Remediation

Detection Demolition Closure Miscellaneous

CONSULTANT INFORMATION

Firm: MVA Foster + Alangi Project Number: 9077.001.004

Address: 17171 Bothell Way NE #264
Seattle 98155

Phone: 425-744-1489 Fax: 425-744-0919

Project Manager: L Dawson

Sample Collection by: Randy Dyer

Chain of Custody Record #:

Quality Assurance Data Level:
 A B

A: Standard Summary
Per Site QAPP
 B: ~~Standard + Chromatograms~~

Laboratory Turnaround Days:
 10 5 3 2 1

SAMPLE IDENTIFICATION	SAMPLING DATE / TIME	MATRIX (W,S,O)	# OF CONTAINERS
1. <u>SP-C1-46-3-2</u>	<u>9-7-01/1500</u>	<u>S</u>	<u>1</u>
2. <u>SP-C1-68-4-2</u>	<u> </u>	<u> </u>	<u> </u>
3. <u>SP-C1-92-6-4</u>	<u> </u>	<u> </u>	<u> </u>
4. <u>SP-C1-114-5-2</u>	<u> </u>	<u> </u>	<u> </u>
5. <u>SP-C1-124-6-4</u>	<u> </u>	<u> </u>	<u> </u>
6. <u>SP-C1-155-7-4</u>	<u> </u>	<u> </u>	<u> </u>
7.			
8. <u>kinsate</u>	<u>9/7/01/1400</u>	<u>W</u>	<u>3</u>
9.			
10.			

Oregon Washington Hydrocarbon Methods - 7 NWTPH

TPH-HCID	TPH-Gas	BTEX (EPA 8020 Mod.)	TPH-Gas + BTEX NW	TPH-Diesel	TPH-Diesel Extended NW	TPH-418.1	Halogen. Volatiles (EPA 8010)	Aromatic Volatiles (EPA 8020)	Pesticides/PCBs or PCBs Only	GC/MS Volatiles (EPA 8240/8260)	GC/MS SemiVol. (EPA 8270)	PAHs by HPLC (EPA 8310)	Lead	Total or Dissolved	TCLP Metals (6)	PAHs
			X		X											X
			X		X											X
			X		X											X
			X		X											X
			X		X											X
			X		X											X
			X		X											X
			X		X											X
			X		X											X
			X		X											X

PAHs TPH + BTEX

NCA SAMPLE NUMBER

-01

-02

-03

-04

-05

-06

-07

Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
1. <u>[Signature]</u>	<u>MFA</u>	<u>9-7-00 17:15</u>	<u>[Signature]</u>	<u>PCA</u>	<u>9/7/01 17:15</u>
2.					
3.					

Final Report Approval

Were all requested results provided? yes no Define

Were results within requested turnaround? yes no "No"

Final Approval Signature: _____ on back

Firm: _____ Date: _____



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

02 October 2001

RECEIVED
 OCT 12 2001
 BY: 9077.01.04

Linda Dawson
 Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle, WA/USA 98155

RE: Former Bulk Storage of Edmonds

Enclosed are the results of analyses for samples received by the laboratory on 09/20/01 16:00. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

S. Woerman

Scott A. Woerman
 Project Manager

*stockpile
 D
 finals*



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/02/01 22:38
--	--	-----------------------------

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
SP-D1-102-1-1	B1I0413-01	Soil	09/20/01 10:30	09/20/01 16:00
SP-D1-113-3-2	B1I0413-02	Soil	09/20/01 10:15	09/20/01 16:00
SP-D1-104-5-2	B1I0413-03	Soil	09/20/01 11:00	09/20/01 16:00
SP-D1-172-6-2	B1I0413-04	Soil	09/20/01 11:00	09/20/01 16:00
SP-D1-207-9-4	B1I0413-05	Soil	09/20/01 11:00	09/20/01 16:00
SP-D1-241-9-4	B1I0413-06	Soil	09/20/01 11:00	09/20/01 16:00

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/02/01 22:38

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-D1-102-1-1 (B110413-01) Soil Sampled: 09/20/01 10:30 Received: 09/20/01 16:00									
Gasoline Range Hydrocarbons	17.2	5.00	mg/kg dry	1	1124028	09/24/01	09/25/01	NWTPH-Gx/8021B	G-01
Benzene	0.0371	0.0300	"	"	"	"	"	"	"
Toluene	ND	0.0500	"	"	"	"	"	"	"
Ethylbenzene	0.0692	0.0500	"	"	"	"	"	"	"
Xylenes (total)	0.339	0.100	"	"	"	"	"	"	"
Surrogate: 4-BFB (FID)	93.8 %	50-147			"	"	"	"	"
Surrogate: 4-BFB (PID)	88.4 %	54-123			"	"	"	"	"
SP-D1-113-3-2 (B110413-02) Soil Sampled: 09/20/01 10:15 Received: 09/20/01 16:00									
Gasoline Range Hydrocarbons	24.7	5.00	mg/kg dry	1	1124028	09/24/01	09/25/01	NWTPH-Gx/8021B	G-01
Benzene	0.0322	0.0300	"	"	"	"	"	"	"
Toluene	ND	0.0500	"	"	"	"	"	"	"
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	"
Xylenes (total)	0.149	0.100	"	"	"	"	"	"	"
Surrogate: 4-BFB (FID)	96.1 %	50-147			"	"	"	"	"
Surrogate: 4-BFB (PID)	87.0 %	54-123			"	"	"	"	"
SP-D1-104-5-2 (B110413-03) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Gasoline Range Hydrocarbons	ND	5.00	mg/kg dry	1	1124028	09/24/01	09/25/01	NWTPH-Gx/8021B	
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	90.4 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	89.7 %	54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/02/01 22:38
--	--	-----------------------------

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-D1-172-6-2 (B110413-04) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Gasoline Range Hydrocarbons	6.65	5.00	mg/kg dry	1	1124028	09/24/01	09/25/01	NWTPH-Gx/8021B	
Benzene	0.0400	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	0.123	0.0500	"	"	"	"	"	"	
Xylenes (total)	0.516	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	89.6 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	87.0 %	54-123			"	"	"	"	
SP-D1-207-9-4 (B110413-05) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Gasoline Range Hydrocarbons	ND	5.00	mg/kg dry	1	1124028	09/24/01	09/25/01	NWTPH-Gx/8021B	
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	91.6 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	88.6 %	54-123			"	"	"	"	
SP-D1-241-9-4 (B110413-06) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Gasoline Range Hydrocarbons	ND	5.00	mg/kg dry	1	1124028	09/24/01	09/25/01	NWTPH-Gx/8021B	
Benzene	ND	0.0300	"	"	"	"	"	"	
Toluene	ND	0.0500	"	"	"	"	"	"	
Ethylbenzene	ND	0.0500	"	"	"	"	"	"	
Xylenes (total)	ND	0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	92.5 %	50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	91.3 %	54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the c. custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/02/01 22:38

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-D1-102-1-1 (B110413-01) Soil Sampled: 09/20/01 10:30 Received: 09/20/01 16:00									
Diesel Range Hydrocarbons	807	55.0	mg/kg dry	11	1125021	09/25/01	09/25/01	NWTPH-Dx	D-06
Lube Oil Range Hydrocarbons	406	138	"	"	"	"	"	"	"
Surrogate: 2-FBP	78.2 %	50-150			"	"	"	"	"
Surrogate: Octacosane	94.9 %	50-150			"	"	"	"	"
SP-D1-113-3-2 (B110413-02) Soil Sampled: 09/20/01 10:15 Received: 09/20/01 16:00									
Diesel Range Hydrocarbons	1650	105	mg/kg dry	21	1125021	09/25/01	09/25/01	NWTPH-Dx	D-06
Lube Oil Range Hydrocarbons	526	262	"	"	"	"	"	"	"
Surrogate: 2-FBP	103 %	50-150			"	"	"	"	"
Surrogate: Octacosane	87.8 %	50-150			"	"	"	"	"
SP-D1-104-5-2 (B110413-03) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Diesel Range Hydrocarbons	995	105	mg/kg dry	21	1125021	09/25/01	09/25/01	NWTPH-Dx	D-06
Oil Range Hydrocarbons	553	262	"	"	"	"	"	"	"
Surrogate: 2-FBP	85.2 %	50-150			"	"	"	"	"
Surrogate: Octacosane	100 %	50-150			"	"	"	"	"
SP-D1-172-6-2 (B110413-04) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Diesel Range Hydrocarbons	468	25.0	mg/kg dry	5	1125021	09/25/01	09/25/01	NWTPH-Dx	D-06
Lube Oil Range Hydrocarbons	240	62.5	"	"	"	"	"	"	"
Surrogate: 2-FBP	74.6 %	50-150			"	"	"	"	"
Surrogate: Octacosane	96.5 %	50-150			"	"	"	"	"
SP-D1-207-9-4 (B110413-05) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Diesel Range Hydrocarbons	866	55.0	mg/kg dry	11	1125021	09/25/01	09/25/01	NWTPH-Dx	D-06
Lube Oil Range Hydrocarbons	475	138	"	"	"	"	"	"	"
Surrogate: 2-FBP	76.0 %	50-150			"	"	"	"	"
Surrogate: Octacosane	94.7 %	50-150			"	"	"	"	"

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/02/01 22:38

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-D1-241-9-4 (B110413-06) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Diesel Range Hydrocarbons	832	55.0	mg/kg dry	11	1125021	09/25/01	09/25/01	NWTPH-Dx	D-06
Lube Oil Range Hydrocarbons	456	138	"	"	"	"	"	"	"
Surrogate: 2-FBP	75.6 %	50-150			"	"	"	"	
Surrogate: Octacosane	102 %	50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/02/01 22:38

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

SP-D1-102-1-1 (B110413-01) Soil Sampled: 09/20/01 10:30 Received: 09/20/01 16:00

Acenaphthene	ND	0.050	mg/kg dry	5	1127033	09/27/01	09/30/01	8270-SIM	
Acenaphthylene	ND	0.050	"	"	"	"	"	"	
Anthracene	ND	0.050	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.050	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.050	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.050	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.050	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.050	"	"	"	"	"	"	
Chrysene	ND	0.050	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.050	"	"	"	"	"	"	
Fluoranthene	ND	0.050	"	"	"	"	"	"	
Fluorene	ND	0.050	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.050	"	"	"	"	"	"	
1-Methylnaphthalene	ND	0.050	"	"	"	"	"	"	
2-Methylnaphthalene	0.058	0.050	"	"	"	"	"	"	
Naphthalene	0.051	0.050	"	"	"	"	"	"	
Phenanthrene	ND	0.050	"	"	"	"	"	"	
Pyrene	ND	0.050	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	100 %	30-150			"	"	"	"	

SP-D1-113-3-2 (B110413-02) Soil Sampled: 09/20/01 10:15 Received: 09/20/01 16:00

Acenaphthene	ND	0.020	mg/kg dry	2	1127033	09/27/01	10/02/01	8270-SIM	
Acenaphthylene	ND	0.020	"	"	"	"	"	"	
Anthracene	ND	0.020	"	"	"	"	"	"	
Benzo (a) anthracene	0.056	0.020	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.020	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.020	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.020	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.020	"	"	"	"	"	"	
Chrysene	0.066	0.020	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.020	"	"	"	"	"	"	
Fluoranthene	0.050	0.020	"	"	"	"	"	"	
Fluorene	0.042	0.020	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.020	"	"	"	"	"	"	
1-Methylnaphthalene	ND	0.020	"	"	"	"	"	"	
2-Methylnaphthalene	0.022	0.020	"	"	"	"	"	"	
Naphthalene	ND	0.020	"	"	"	"	"	"	
Phenanthrene	0.027	0.020	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/02/01 22:38
--	--	-----------------------------

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Reporting		Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
	Result	Limit							

SP-D1-113-3-2 (B1I0413-02) Soil Sampled: 09/20/01 10:15 Received: 09/20/01 16:00

Pyrene	0.11	0.020	mg/kg dry	2	1127033	09/27/01	10/02/01	8270-SIM	
Surrogate: p-Terphenyl-d14	110 %	30-150			"	"	"	"	

SP-D1-104-5-2 (B1I0413-03) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00

Acenaphthene	ND	0.020	mg/kg dry	2	1127033	09/27/01	09/30/01	8270-SIM	
Acenaphthylene	ND	0.020	"	"	"	"	"	"	
Anthracene	ND	0.020	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.020	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.020	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.020	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.020	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.020	"	"	"	"	"	"	
Chrysene	ND	0.020	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.020	"	"	"	"	"	"	
Fluoranthene	ND	0.020	"	"	"	"	"	"	
Fluorene	ND	0.020	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.020	"	"	"	"	"	"	
1-Methylnaphthalene	ND	0.020	"	"	"	"	"	"	
2-Methylnaphthalene	ND	0.020	"	"	"	"	"	"	
Naphthalene	ND	0.020	"	"	"	"	"	"	
Phenanthrene	ND	0.020	"	"	"	"	"	"	
Pyrene	0.10	0.020	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	110 %	30-150			"	"	"	"	

SP-D1-172-6-2 (B1I0413-04) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00

Acenaphthene	ND	0.020	mg/kg dry	2	1127033	09/27/01	09/30/01	8270-SIM	
Acenaphthylene	ND	0.020	"	"	"	"	"	"	
Anthracene	ND	0.020	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.020	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.020	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.020	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.020	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.020	"	"	"	"	"	"	
Chrysene	ND	0.020	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.020	"	"	"	"	"	"	
Fluoranthene	ND	0.020	"	"	"	"	"	"	
Fluorene	ND	0.020	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.020	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/02/01 22:38

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----------------	-------	----------	-------	----------	----------	--------	-------

SP-D1-172-6-2 (B1I0413-04) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00

1-Methylnaphthalene	ND	0.020	mg/kg dry	2	1127033	09/27/01	09/30/01	8270-SIM	
2-Methylnaphthalene	ND	0.020	"	"	"	"	"	"	
Naphthalene	ND	0.020	"	"	"	"	"	"	
Phenanthrene	ND	0.020	"	"	"	"	"	"	
Pyrene	ND	0.020	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	94 %	30-150			"	"	"	"	

SP-D1-207-9-4 (B1I0413-05) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00

Acenaphthene	ND	0.020	mg/kg dry	2	1127033	09/27/01	09/30/01	8270-SIM	
Acenaphthylene	ND	0.020	"	"	"	"	"	"	
Anthracene	ND	0.020	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.020	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.020	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.020	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.020	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.020	"	"	"	"	"	"	
Chrysene	ND	0.020	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.020	"	"	"	"	"	"	
Fluoranthene	ND	0.020	"	"	"	"	"	"	
Fluorene	ND	0.020	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.020	"	"	"	"	"	"	
1-Methylnaphthalene	0.037	0.020	"	"	"	"	"	"	
2-Methylnaphthalene	0.027	0.020	"	"	"	"	"	"	
Naphthalene	ND	0.020	"	"	"	"	"	"	
Phenanthrene	0.23	0.020	"	"	"	"	"	"	
Pyrene	0.16	0.020	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	100 %	30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/02/01 22:38

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-D1-241-9-4 (B110413-06) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Acenaphthene	ND	0.020	mg/kg dry	2	1127033	09/27/01	09/30/01	8270-SIM	
Acenaphthylene	ND	0.020	"	"	"	"	"	"	
Anthracene	ND	0.020	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.020	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.020	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.020	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.020	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.020	"	"	"	"	"	"	
Chrysene	ND	0.020	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.020	"	"	"	"	"	"	
Fluoranthene	ND	0.020	"	"	"	"	"	"	
Fluorene	ND	0.020	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.020	"	"	"	"	"	"	
1-Methylnaphthalene	0.039	0.020	"	"	"	"	"	"	
2-Methylnaphthalene	0.035	0.020	"	"	"	"	"	"	
Naphthalene	ND	0.020	"	"	"	"	"	"	
Phenanthrene	0.41	0.020	"	"	"	"	"	"	
Pyrene	0.20	0.020	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	94 %	30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/02/01 22:38

Physical Parameters by APHA/ASTM/EPA Methods
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-D1-102-1-1 (B110413-01) Soil Sampled: 09/20/01 10:30 Received: 09/20/01 16:00									
Dry Weight	91.2	1.00	%	1	1124037	09/24/01	09/25/01	BSOPSPLO03R07	
SP-D1-113-3-2 (B110413-02) Soil Sampled: 09/20/01 10:15 Received: 09/20/01 16:00									
Dry Weight	92.7	1.00	%	1	1124037	09/24/01	09/25/01	BSOPSPLO03R07	
SP-D1-104-5-2 (B110413-03) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Dry Weight	93.1	1.00	%	1	1124037	09/24/01	09/25/01	BSOPSPLO03R07	
SP-D1-172-6-2 (B110413-04) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Dry Weight	94.4	1.00	%	1	1124037	09/24/01	09/25/01	BSOPSPLO03R07	
SP-D1-207-9-4 (B110413-05) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Dry Weight	93.4	1.00	%	1	1124037	09/24/01	09/25/01	BSOPSPLO03R07	
SP-D1-241-9-4 (B110413-06) Soil Sampled: 09/20/01 11:00 Received: 09/20/01 16:00									
Weight	93.6	1.00	%	1	1124037	09/24/01	09/25/01	BSOPSPLO03R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/02/01 22:38

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I24028: Prepared 09/24/01 Using EPA 5030B (MeOH)

Blank (1I24028-BLK1)

Gasoline Range Hydrocarbons	ND	5.00	mg/kg							
Benzene	ND	0.0300	"							
Toluene	ND	0.0500	"							
Ethylbenzene	ND	0.0500	"							
Xylenes (total)	ND	0.100	"							
Surrogate: 4-BFB (FID)	3.80		"	4.00		95.0	50-147			
Surrogate: 4-BFB (PID)	3.72		"	4.00		93.0	54-123			

LCS (1I24028-BS1)

Gasoline Range Hydrocarbons	23.5	5.00	mg/kg	25.0		94.0	80-120			
Surrogate: 4-BFB (FID)	4.08		"	4.00		102	50-147			

LCS (1I24028-BS2)

Benzene	0.433	0.0300	mg/kg	0.500		86.6	80-120			
Toluene	0.473	0.0500	"	0.500		94.6	80-120			
Ethylbenzene	0.503	0.0500	"	0.500		101	80-120			
Xylenes (total)	1.57	0.100	"	1.50		105	80-120			
Surrogate: 4-BFB (PID)	3.76		"	4.00		94.0	54-123			

LCS Dup (1I24028-BSD1)

Gasoline Range Hydrocarbons	24.9	5.00	mg/kg	25.0		99.6	80-120	5.79	40	
Surrogate: 4-BFB (FID)	4.17		"	4.00		104	50-147			

LCS Dup (1I24028-BSD2)

Benzene	0.443	0.0300	mg/kg	0.500		88.6	80-120	2.28	40	
Toluene	0.483	0.0500	"	0.500		96.6	80-120	2.09	40	
Ethylbenzene	0.510	0.0500	"	0.500		102	80-120	1.38	40	
Xylenes (total)	1.58	0.100	"	1.50		105	80-120	0.635	40	
Surrogate: 4-BFB (PID)	3.73		"	4.00		93.2	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/02/01 22:38

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I24028: Prepared 09/24/01 Using EPA 5030B (MeOH)

Matrix Spike (1I24028-MS1)

Source: B1I0378-21

Gasoline Range Hydrocarbons	28.7	5.00	mg/kg dry	28.3	5.54	81.8	53-120			
Surrogate: 4-BFB (FID)	3.82		"	4.53		84.3	50-147			

Matrix Spike (1I24028-MS2)

Source: B1I0413-03

Benzene	0.448	0.0300	mg/kg dry	0.537	ND	83.4	64-130			
Toluene	0.494	0.0500	"	0.537	ND	92.0	66-130			
Ethylbenzene	0.526	0.0500	"	0.537	ND	98.0	72-130			
Xylenes (total)	1.62	0.100	"	1.61	ND	101	73-130			
Surrogate: 4-BFB (PID)	3.92		"	4.29		91.4	54-123			

Matrix Spike Dup (1I24028-MSD1)

Source: B1I0378-21

Gasoline Range Hydrocarbons	29.2	5.00	mg/kg dry	28.3	5.54	83.6	53-120	1.73	40	
Surrogate: 4-BFB (FID)	4.10		"	4.53		90.5	50-147			

Matrix Spike Dup (1I24028-MSD2)

Source: B1I0413-03

Benzene	0.455	0.0300	mg/kg dry	0.537	ND	84.7	64-130	1.55	40	
Toluene	0.499	0.0500	"	0.537	ND	92.9	66-130	1.01	40	
Ethylbenzene	0.537	0.0500	"	0.537	ND	100	72-130	2.07	40	
Xylenes (total)	1.65	0.100	"	1.61	ND	102	73-130	1.83	40	
Surrogate: 4-BFB (PID)	3.81		"	4.29		88.8	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network

Page 12 of 17



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/02/01 22:38
--	--	-----------------------------

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I25021: Prepared 09/25/01 Using EPA 3550B

Blank (1I25021-BLK1)

Diesel Range Hydrocarbons	ND	5.00	mg/kg							
Lube Oil Range Hydrocarbons	ND	12.5	"							
Surrogate: 2-FBP	7.38		"	10.7		69.0	50-150			
Surrogate: Octacosane	8.35		"	10.7		78.0	50-150			

LCS (1I25021-BS1)

Diesel Range Hydrocarbons	51.4	5.00	mg/kg	66.7		77.1	50-150			
Surrogate: 2-FBP	7.23		"	10.7		67.6	50-150			

LCS Dup (1I25021-BSD1)

Diesel Range Hydrocarbons	55.1	5.00	mg/kg	66.7		82.6	50-150	6.95	50	
Surrogate: 2-FBP	8.01		"	10.7		74.9	50-150			

Duplicate (1I25021-DUP1)

Source: B110413-04

Diesel Range Hydrocarbons	425	25.0	mg/kg dry		468			9.63	50	
Lube Oil Range Hydrocarbons	245	62.5	"		240			2.06	50	
Surrogate: 2-FBP	9.33		"	11.3		82.6	50-150			
Surrogate: Octacosane	10.9		"	11.3		96.5	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network

Page 13 of 17



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 10/02/01 22:38

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1127033: Prepared 09/27/01 Using EPA 3550B

Blank (1127033-BLK1)

Acenaphthene	ND	0.010	mg/kg							
Acenaphthylene	ND	0.010	"							
Anthracene	ND	0.010	"							
Benzo (a) anthracene	ND	0.010	"							
Benzo (a) pyrene	ND	0.010	"							
Benzo (b) fluoranthene	ND	0.010	"							
Benzo (ghi) perylene	ND	0.010	"							
Benzo (k) fluoranthene	ND	0.010	"							
Chrysene	ND	0.010	"							
Dibenz (a,h) anthracene	ND	0.010	"							
Fluoranthene	ND	0.010	"							
Indeno (1,2,3-cd) pyrene	ND	0.010	"							
1-Methylnaphthalene	ND	0.010	"							
2-Methylnaphthalene	ND	0.010	"							
Naphthalene	ND	0.010	"							
Phenanthrene	ND	0.010	"							
Pyrene	ND	0.010	"							
<i>Surrogate: p-Terphenyl-d14</i>	2.0		"	1.7		120	30-150			

LCS (1127033-BS1)

Chrysene	0.30	0.010	mg/kg	0.33		91	10-125			
Fluorene	0.33	0.010	"	0.33		100	11-116			
Indeno (1,2,3-cd) pyrene	0.32	0.010	"	0.33		97	10-147			
<i>Surrogate: p-Terphenyl-d14</i>	2.0		"	1.7		120	30-150			

LCS Dup (1127033-BS1)

Chrysene	0.31	0.010	mg/kg	0.33		94	10-125	3.3	28	
Fluorene	0.32	0.010	"	0.33		97	11-116	3.1	32	
Indeno (1,2,3-cd) pyrene	0.30	0.010	"	0.33		91	10-147	6.5	34	
<i>Surrogate: p-Terphenyl-d14</i>	1.9		"	1.7		110	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network

Page 14 of 17



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/02/01 22:38
--	--	-----------------------------

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I27033: Prepared 09/27/01 Using EPA 3550B

Matrix Spike (1I27033-MS1)

Source: B110457-01

Chrysene	0.40	0.050	mg/kg dry	0.37		110	10-125			
Fluorene	1.0	0.050	"	0.37		270	10-154			
Indeno (1,2,3-cd) pyrene	0.43	0.050	"	0.37		120	10-144			
<i>Surrogate: p-Terphenyl-d14</i>	2.2		"	1.8		120	30-150			

Matrix Spike Dup (1I27033-MSD1)

Source: B110457-01

Chrysene	0.40	0.050	mg/kg dry	0.37		110	10-125	0.0	28	
Fluorene	1.0	0.050	"	0.37		270	10-154	0.0	32	
Indeno (1,2,3-cd) pyrene	0.46	0.050	"	0.37		120	10-144	6.7	47	
<i>Surrogate: p-Terphenyl-d14</i>	2.3		"	1.8		130	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network

Page 15 of 17



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/02/01 22:38
--	--	-----------------------------

**Physical Parameters by APHA/ASTM/EPA Methods - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I24037: Prepared 09/24/01 Using Dry Weight

Blank (1I24037-BLK1)

Dry Weight	100	1.00	%							
------------	-----	------	---	--	--	--	--	--	--	--

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 10/02/01 22:38
--	--	-----------------------------

Notes and Definitions

- D-06 The sample chromatographic pattern does not resemble the fuel standard used for quantitation.
- G-01 Results reported for the gas range are primarily due to overlap from diesel range hydrocarbons.
- DET Analyte DETECTED
- ND Analyte NOT DETECTED at or above the reporting limit
- NR Not Reported
- dry Sample results reported on a dry weight basis
- RPD Relative Percent Difference



UNOCAL CHAIN OF CUSTODY REPORT B110213

18939 120th Avenue N.E., Suite 101, Bothell, WA 98011-9508 (206) 481-9200 FAX 485-2992
 East 11115 Montgomery, Suite B, Spokane, WA 99206-4779 (509) 924-9200 1 4-9290
 9405 S.W. Nimbus Avenue, Beaverton, OR 97008-7132 (503) 643-9200 FAX 4-2202

UNOCAL INFORMATION

Facility Number: Unocal Edmonds Terminal
 Site Address: 11720 Unoco Road
 City, State, ZIP: Edmonds, 98020

Site Release Number:
 Unocal Manager: Mark Brearley

CERT INFO: (check one) Evaluation Remediation
 Detection Demolition Closure Miscellaneous

CONSULTANT INFORMATION

Firm: Mani Foster & Alongi Project Number: 9077.001.004
 Address: 17171 Bothell Way NE, #264
Seattle, 98155

Phone: 425-744-1489 Fax: 425-744-0919

Project Manager: L. Dawson
 Sample Collection by: R. Dyer

Chain of Custody Record #:

Quality Assurance Data Level:
 A B
 A: Standard Summary
Per Site Q App
 B: Standard + Chromatograms

Laboratory Turnaround Days:
 10 5 3 2 1

SAMPLE IDENTIFICATION	SAMPLING DATE / TIME	MATRIX (W,S,O)	# OF CONTAINERS
1. SP-D1-102-1-1	9/20/01/1030	S	1
2. SP-D1-113-3-2	9-20-01/1015	S	1
3. SP-D1-104-5-2	9-20-01/1100	S	1
4. SP-D1-172-6-2	9-20-01/1100	S	1
5. SP-D1-207-9-4	9-20-01/1100	S	1
6. SP-D1-241-9-4	9-20-01/1100	S	1
7.			
8.			
9.			
10.			

Oregon Washington Hydrocarbon Methods → NWTPH

TPH-ACID	TPH-Gas	BTEX (EPA 8020 Mod.)	TPH-Gas + BTEX ^(A)	TPH-Diesel ^(B)	TPH-Diesel Extended ^(B)	TPH-418.1	Halogen Volatiles (EPA 8010)	Aromatic Volatiles (EPA 8020)	Pesticides/PCBs or PCBs Only	GC/MS Volatiles (EPA 8240/8260)	GC/MS Semi-Volat. (EPA 8270)	PAHs by HPLC (EPA 8310)	Lead:	Total or Dissolved TCLP Metals (B)	PAHs ^(C)
			X	X	X										X
			X	X	X										X
			X	X	X										X
			X	X	X										X
			X	X	X										X
			X	X	X										X

PAHs TPH + BTEX

NCA SAMPLE NUMBER

- 01
 - 02
 - 03
 - 04
 - 05
 - 06

Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
<u>[Signature]</u>	<u>NCA</u>	<u>9/20/01 14:20</u>	<u>[Signature]</u>	<u>NCA</u>	<u>9/20/01 14:20</u>
<u>[Signature]</u>	<u>NCA</u>	<u>9/20/01 16:00</u>	<u>[Signature]</u>	<u>NCA</u>	<u>9/20/01 16:00</u>

Final Report Approval

Were all requested results provided? yes no Define

Were results within requested turnaround? yes no "No"

Final Approval Signature: _____ on back

Firm: _____ Date: _____

Comments: PAHs by 8270 SIM, incl. 1+2-methylnaphthalene
(B) Silica cleanup


Distribution: White - Laboratory Yellow - Consultant Photocopy - Unocal

18.2° W/0



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

27 November 2001



Linda Dawson
Maul Foster & Alongi-Seattle
17171 Bothell Way NE #264
Seattle, WA/USA 98155
RE: Former Bulk Storage of Edmonds

Enclosed are the results of analyses for samples received by the laboratory on 09/27/01 15:15. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Scott A. Woerman
Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

Case Narrative for B1I0610

Client: Maul Foster & Alongi - Seattle
Project Manager: Linda Dawson
Project Name: Former Bulk Storage of Edmonds
Project Number: 9077.001.004

1.0 DESCRIPTION OF CASE

Twenty-one soil samples and one water sample were submitted on September 27, 2001, for one or all of the following analyses: Volatile Petroleum Products and BTEX by NWTPH-Gx/EPA 8021B, Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up and Polynuclear Aromatic Hydrocarbons by EPA 8270-SIM.

2.0 COMMENTS ON SAMPLE RECEIPT

The samples were received on September 27, 2001 and logged in on September 29, 2001 at a temperature of 3.1°C. No anomalies were associated with sample receipt.

3.0 PREPARATION AND ANALYSIS

Volatile Petroleum Products and BTEX by NWTPH-Gx/EPA 8021B

No anomalies or discrepancies were associated with this analysis other than those already qualified in the data.

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up

No results are reported for sample MW-D1-0901 as every sample associated with laboratory batch 1J03015 was inadvertently spiked with diesel analyte. No additional volume was available with which to re-extract and re-analyze the sample.

The surrogate recoveries for 2-FBP and Octacosane fell outside of their established QC limits in sample EX-B-1-5. The sample was re-analyzed to confirm the results before being sent back for re-extraction and re-analysis. Both the initial and re-extract results are reported as the re-extraction and re-analysis took place outside of the EPA recommended holding time. The results should be considered as estimated values.

No additional anomalies or discrepancies were associated with this analysis other than those already qualified in the data.

Polynuclear Aromatic Hydrocarbons by EPA 8270-SIM

The surrogate, p-Terphenyl-d14, yielded a recovery outside of its established QC limit in sample EX-A-3-4.5. The sample was re-analyzed to confirm the result before being sent back for re-extraction and re-analysis. Both the initial and re-extract results are reported as the re-extraction and re-analysis took place outside of the EPA recommended holding time. The results should be considered as estimated values.

No additional anomalies or discrepancies were associated with this analysis other than those already qualified in the data.



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

"I certify that this data package is in compliance with the Contract both technically and for completeness, other than the conditions detailed above. Release of the data in this hard copy data package has been authorized by the Laboratory Director, as verified by the following signature."

Scott A. Woerman
Project Manager
North Creek Analytical - Bothell



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory	Laboratory ID	Matrix	Date Sampled	Date Received
EX-B-1-5	North Creek Analytical - Bothell	B1I0610-01	Soil	09/27/01 10:00	09/27/01 15:15
EX-B-2-5	North Creek Analytical - Bothell	B1I0610-02	Soil	09/27/01 10:00	09/27/01 15:15
EX-B-3-5	North Creek Analytical - Bothell	B1I0610-03	Soil	09/27/01 10:00	09/27/01 15:15
EX-B-4-5	North Creek Analytical - Bothell	B1I0610-04	Soil	09/27/01 10:00	09/27/01 15:15
EX-B-5-5	North Creek Analytical - Bothell	B1I0610-05	Soil	09/27/01 10:00	09/27/01 15:15
EX-B-6-5	North Creek Analytical - Bothell	B1I0610-06	Soil	09/27/01 10:00	09/27/01 15:15
EX-B-7-5	North Creek Analytical - Bothell	B1I0610-07	Soil	09/27/01 10:00	09/27/01 15:15
EX-B-8-5	North Creek Analytical - Bothell	B1I0610-08	Soil	09/27/01 10:00	09/27/01 15:15
EX-B-9-5	North Creek Analytical - Bothell	B1I0610-09	Soil	09/27/01 10:00	09/27/01 15:15
EX-B-10-5	North Creek Analytical - Bothell	B1I0610-10	Soil	09/27/01 10:00	09/27/01 15:15
EX-A-1-4.5	North Creek Analytical - Bothell	B1I0610-11	Soil	09/27/01 11:00	09/27/01 15:15
EX-A-2-4.5	North Creek Analytical - Bothell	B1I0610-12	Soil	09/27/01 11:00	09/27/01 15:15
EX-A-3-4.5	North Creek Analytical - Bothell	B1I0610-13	Soil	09/27/01 11:00	09/27/01 15:15
EX-A-4-4.5	North Creek Analytical - Bothell	B1I0610-14	Soil	09/27/01 11:00	09/27/01 15:15
EX-A-5-4.5	North Creek Analytical - Bothell	B1I0610-15	Soil	09/27/01 11:00	09/27/01 15:15
EX-A-6-4.5	North Creek Analytical - Bothell	B1I0610-16	Soil	09/27/01 11:00	09/27/01 15:15
EX-A-7-4.5	North Creek Analytical - Bothell	B1I0610-17	Soil	09/27/01 11:00	09/27/01 15:15
EX-A-8-4.5	North Creek Analytical - Bothell	B1I0610-18	Soil	09/27/01 11:00	09/27/01 15:15
EX-A-9-4.5	North Creek Analytical - Bothell	B1I0610-19	Soil	09/27/01 11:00	09/27/01 15:15
EX-A-10-4.5	North Creek Analytical - Bothell	B1I0610-20	Soil	09/27/01 11:00	09/27/01 15:15
EX-A-11-4.5	North Creek Analytical - Bothell	B1I0610-21	Soil	09/27/01 11:00	09/27/01 15:15
MW-D1-0901	North Creek Analytical - Bothell	B1I0610-22	Water	09/27/01 12:00	09/27/01 15:15

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-1-5 (B1I0610-01) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	1950		50.0	mg/kg dry	10	1J03019	10/03/01	10/09/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.300	"	"	"	"	"	"	
Toluene	ND		0.500	"	"	"	"	"	"	
Ethylbenzene	3.35		0.500	"	"	"	"	"	"	
Xylenes (total)	7.79		1.00	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	S-01
Surrogate: 4-BFB (PID)	%		54-123			"	"	"	"	S-01
EX-B-2-5 (B1I0610-02) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	112		5.00	mg/kg dry	1	1J03019	10/03/01	10/09/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	0.230		0.100	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	S-02
Surrogate: 4-BFB (PID)	109 %		54-123			"	"	"	"	
EX-B-3-5 (B1I0610-03) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	66.6		5.00	mg/kg dry	1	1J03019	10/03/01	10/09/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	119 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	90.4 %		54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-4-5 (B1I0610-04) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	ND		5.00	mg/kg dry	1	1J03019	10/03/01	10/04/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	87.2 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	77.5 %		54-123			"	"	"	"	
EX-B-5-5 (B1I0610-05) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	2020		100	mg/kg dry	20	1J03019	10/03/01	10/09/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.600	"	"	"	"	"	"	
Toluene	ND		1.00	"	"	"	"	"	"	
Ethylbenzene	1.10		1.00	"	"	"	"	"	"	
Xylenes (total)	2.46		2.00	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	%		54-123			"	"	"	"	S-01
EX-B-6-5 (B1I0610-06) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	1560		25.0	mg/kg dry	5	1J03019	10/03/01	10/09/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.150	"	"	"	"	"	"	
Toluene	ND		0.250	"	"	"	"	"	"	
Ethylbenzene	1.34		0.250	"	"	"	"	"	"	
Xylenes (total)	7.05		0.500	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	S-01
Surrogate: 4-BFB (PID)	%		54-123			"	"	"	"	S-01

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----	-----------------	-------	----------	-------	----------	----------	--------	-------

EX-B-7-5 (B110610-07) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15

Gasoline Range Hydrocarbons	ND		5.00	mg/kg dry	1	1J04028	10/04/01	10/05/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	87.7 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	88.0 %		54-123			"	"	"	"	

EX-B-8-5 (B110610-08) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15

Gasoline Range Hydrocarbons	ND		5.00	mg/kg dry	1	1J04028	10/04/01	10/05/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	86.8 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	92.2 %		54-123			"	"	"	"	

EX-B-9-5 (B110610-09) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15

Gasoline Range Hydrocarbons	146		5.00	mg/kg dry	1	1J04028	10/04/01	10/09/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.286		0.0500	"	"	"	"	"	"	
Xylenes (total)	1.48		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	165 %		50-147			"	"	"	"	S-04
Surrogate: 4-BFB (PID)	109 %		54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----	-----------------	-------	----------	-------	----------	----------	--------	-------

EX-B-10-5 (B1I0610-10) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15

Gasoline Range Hydrocarbons	ND		5.00	mg/kg dry	1	1J04028	10/04/01	10/05/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	84.1 %		50-147							
Surrogate: 4-BFB (PID)	88.2 %		54-123							

EX-A-1-4.5 (B1I0610-11) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15

Gasoline Range Hydrocarbons	ND		5.00	mg/kg dry	1	1J04028	10/04/01	10/06/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	82.3 %		50-147							
Surrogate: 4-BFB (PID)	86.1 %		54-123							

EX-A-2-4.5 (B1I0610-12) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15

Gasoline Range Hydrocarbons	ND		5.00	mg/kg dry	1	1J04028	10/04/01	10/06/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	83.0 %		50-147							
Surrogate: 4-BFB (PID)	85.3 %		54-123							

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-3-4.5 (B1I0610-13) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	ND		5.00	mg/kg dry	1	1J04028	10/04/01	10/06/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	81.3 %		50-147							
Surrogate: 4-BFB (PID)	84.9 %		54-123							
EX-A-4-4.5 (B1I0610-14) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	9.41		5.00	mg/kg dry	1	1J04028	10/04/01	10/09/01	NWTPH-Gx/ 8021B	
Benzene	0.343		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	0.431		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	79.7 %		50-147							
Surrogate: 4-BFB (PID)	80.4 %		54-123							
EX-A-5-4.5 (B1I0610-15) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	363		5.00	mg/kg dry	1	1J04028	10/04/01	10/09/01	NWTPH-Gx/ 8021B	G-01
Benzene	0.0681		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.551		0.0500	"	"	"	"	"	"	
Xylenes (total)	1.44		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	174 %		50-147							S-04
Surrogate: 4-BFB (PID)	97.8 %		54-123							

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-6-4.5 (B110610-16) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	2060		100	mg/kg dry	20	1J04028	10/04/01	10/09/01	NWTPH-Gx/ 8021B	I-06
Benzene	1.36		0.600	"	"	"	"	"	"	
Toluene	ND		1.00	"	"	"	"	"	"	
Ethylbenzene	17.1		1.00	"	"	"	"	"	"	
Xylenes (total)	126		2.00	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	S-01
Surrogate: 4-BFB (PID)	%		54-123			"	"	"	"	S-01
EX-A-7-4.5 (B110610-17) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	15.1		5.00	mg/kg dry	1	1J04028	10/04/01	10/09/01	NWTPH-Gx/ 8021B	
Benzene	0.0783		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.0628		0.0500	"	"	"	"	"	"	I-06
Xylenes (total)	0.123		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	88.6 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	80.2 %		54-123			"	"	"	"	
EX-A-8-4.5 (B110610-18) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	791		20.0	mg/kg dry	4	1J04028	10/04/01	10/09/01	NWTPH-Gx/ 8021B	
Benzene	1.62		0.120	"	"	"	"	"	"	
Toluene	0.231		0.200	"	"	"	"	"	"	I-06
Ethylbenzene	3.94		0.200	"	"	"	"	"	"	I-06
Xylenes (total)	3.39		0.400	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	S-02
Surrogate: 4-BFB (PID)	163 %		54-123			"	"	"	"	S-04

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----	-----------------	-------	----------	-------	----------	----------	--------	-------

EX-A-9-4.5 (B1I0610-19) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15

Gasoline Range Hydrocarbons	13.2		5.00	mg/kg dry	1	1J04028	10/04/01	10/09/01	NWTPH-Gx/ 8021B	G-01
Benzene	0.109		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	0.256		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	79.1 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	81.9 %		54-123			"	"	"	"	

EX-A-10-4.5 (B1I0610-20) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15

Gasoline Range Hydrocarbons	129		5.00	mg/kg dry	1	1J04028	10/04/01	10/09/01	NWTPH-Gx/ 8021B	
Benzene	1.31		0.0300	"	"	"	"	"	"	
Toluene	0.0596		0.0500	"	"	"	"	"	"	I-06
Ethylbenzene	0.365		0.0500	"	"	"	"	"	"	
Xylenes (total)	0.566		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	110 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	75.1 %		54-123			"	"	"	"	

EX-A-11-4.5 (B1I0610-21) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15

Gasoline Range Hydrocarbons	ND		5.00	mg/kg dry	1	1J04028	10/04/01	10/09/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	83.6 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	86.9 %		54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network

Page 8 of 47



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
MW-D1-0901 (BIH0610-22) Water Sampled: 09/27/01 12:00 Received: 09/27/01 15:15										
Gasoline Range Hydrocarbons	ND		50.0	ug/l	1	1J10004	10/10/01	10/10/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.500	"	"	"	"	"	"	
Toluene	ND		0.500	"	"	"	"	"	"	
Ethylbenzene	ND		0.500	"	"	"	"	"	"	
Xylenes (total)	ND		1.00	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	95.2 %		62-139			"	"	"	"	
Surrogate: 4-BFB (PID)	95.8 %		62-125			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-1-5 (B1I0610-01) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	1570		50.0	mg/kg dry	5	1J05042	10/05/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		125	"	"	"	"	"	"	
Surrogate: 2-FBP	182 %		50-150			"	"	"	"	X
Surrogate: Octacosane	45.4 %		50-150			"	"	"	"	X
EX-B-1-5 (B1I0610-01RE1) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	3740		210	mg/kg dry	21	1J16038	10/16/01	10/20/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	219		25.0	"	1	"	"	10/19/01	"	D-10
Surrogate: 2-FBP	%		50-150			"	"	10/20/01	"	S-01
Surrogate: Octacosane	114 %		50-150			"	"	10/19/01	"	
EX-B-2-5 (B1I0610-02) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	153		10.0	mg/kg dry	1	1J05042	10/05/01	10/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	79.9 %		50-150			"	"	"	"	
Surrogate: Octacosane	79.7 %		50-150			"	"	"	"	
EX-B-3-5 (B1I0610-03) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	174		10.0	mg/kg dry	1	1J05042	10/05/01	10/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	74.1 %		50-150			"	"	"	"	
Surrogate: Octacosane	73.7 %		50-150			"	"	"	"	
EX-B-4-5 (B1I0610-04) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	ND		10.0	mg/kg dry	1	1J05042	10/05/01	10/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	72.2 %		50-150			"	"	"	"	
Surrogate: Octacosane	81.4 %		50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-5-5 (B110610-05) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	692		10.0	mg/kg dry	1	1J05042	10/05/01	10/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	95.7 %		50-150			"	"	"	"	
Surrogate: Octacosane	80.9 %		50-150			"	"	"	"	
EX-B-6-5 (B110610-06) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	848		10.0	mg/kg dry	1	1J05042	10/05/01	10/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	47.0		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	94.9 %		50-150			"	"	"	"	
Surrogate: Octacosane	81.3 %		50-150			"	"	"	"	
EX-B-7-5 (B110610-07) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	96.9		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	41.1		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	79.4 %		50-150			"	"	"	"	
Surrogate: Octacosane	86.9 %		50-150			"	"	"	"	
EX-B-8-5 (B110610-08) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	ND		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	92.9 %		50-150			"	"	"	"	
Surrogate: Octacosane	103 %		50-150			"	"	"	"	
EX-B-9-5 (B110610-09) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	1850		110	mg/kg dry	11	1J08026	10/08/01	10/15/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		275	"	"	"	"	"	"	
Surrogate: 2-FBP	118 %		50-150			"	"	"	"	
Surrogate: Octacosane	104 %		50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-10-5 (B1I0610-10) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	13.3		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	81.6 %		50-150			"	"	"	"	
Surrogate: Octacosane	88.5 %		50-150			"	"	"	"	
EX-A-1-4.5 (B1I0610-11) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	25.1		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	35.5		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	83.3 %		50-150			"	"	"	"	
Surrogate: Octacosane	90.6 %		50-150			"	"	"	"	
EX-A-2-4.5 (B1I0610-12) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	ND		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	77.7 %		50-150			"	"	"	"	
Surrogate: Octacosane	84.2 %		50-150			"	"	"	"	
EX-A-3-4.5 (B1I0610-13) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	ND		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	80.8 %		50-150			"	"	"	"	
Surrogate: Octacosane	86.6 %		50-150			"	"	"	"	
EX-A-4-4.5 (B1I0610-14) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	116		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	218		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	85.2 %		50-150			"	"	"	"	
Surrogate: Octacosane	94.5 %		50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-5-4.5 (B1I0610-15) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	1320		110	mg/kg dry	11	1J08026	10/08/01	10/15/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	1040		275	"	"	"	"	"	"	
Surrogate: 2-FBP	113 %		50-150			"	"	"	"	
Surrogate: Octacosane	136 %		50-150			"	"	"	"	
EX-A-6-4.5 (B1I0610-16) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	2830		210	mg/kg dry	21	1J08026	10/08/01	10/15/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	1790		525	"	"	"	"	"	"	
Surrogate: 2-FBP	236 %		50-150			"	"	"	"	S-06
Surrogate: Octacosane	245 %		50-150			"	"	"	"	S-06
EX-A-7-4.5 (B1I0610-17) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	383		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	360		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	101 %		50-150			"	"	"	"	
Surrogate: Octacosane	107 %		50-150			"	"	"	"	
EX-A-8-4.5 (B1I0610-18) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	1130		30.0	mg/kg dry	3	1J08026	10/08/01	10/15/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	150		75.0	"	"	"	"	"	"	
Surrogate: 2-FBP	138 %		50-150			"	"	"	"	
Surrogate: Octacosane	101 %		50-150			"	"	"	"	
EX-A-9-4.5 (B1I0610-19) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	56.6		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	30.1		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	78.6 %		50-150			"	"	"	"	
Surrogate: Octacosane	84.3 %		50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-10-4.5 (B1I0610-20) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	172		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	63.8		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	84.0 %		50-150			"	"	"	"	
Surrogate: Octacosane	87.0 %		50-150			"	"	"	"	
EX-A-11-4.5 (B1I0610-21) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Diesel Range Hydrocarbons	ND		10.0	mg/kg dry	1	1J08026	10/08/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	90.7 %		50-150			"	"	"	"	
Surrogate: Octacosane	97.5 %		50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-1-5 (B110610-01) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Acenaphthene	ND	0.035	0.25	mg/kg dry	25	1J03030	10/03/01	10/09/01	8270-SIM	
Acenaphthylene	ND	0.020	0.25	"	"	"	"	"	"	
Anthracene	0.13	0.040	0.25	"	"	"	"	"	"	J
Benzo (a) anthracene	ND	0.028	0.25	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.028	0.25	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.030	0.25	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.020	0.25	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.040	0.25	"	"	"	"	"	"	
Chrysene	ND	0.040	0.25	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.035	0.25	"	"	"	"	"	"	
Fluoranthene	ND	0.025	0.25	"	"	"	"	"	"	
Fluorene	1.3	0.028	0.25	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.048	0.25	"	"	"	"	"	"	
1-Methylnaphthalene	17	0.028	0.25	"	"	"	"	"	"	
2-Methylnaphthalene	10	0.020	0.25	"	"	"	"	"	"	
Naphthalene	ND	0.035	0.25	"	"	"	"	"	"	
Phenanthrene	1.9	0.030	0.25	"	"	"	"	"	"	
Pyrene	0.11	0.0025	0.25	"	"	"	"	"	"	J
Surrogate: p-Terphenyl-d14	79 %		30-150							

EX-B-2-5 (B110610-02) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15

Acenaphthene	0.013	0.0014	0.010	mg/kg dry	1	1J03030	10/03/01	10/09/01	8270-SIM	
Acenaphthylene	0.011	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	0.052	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.095	0.0011	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.015	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	0.056	0.0012	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-2-5 (B1I0610-02) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Pyrene	ND	0.00010	0.010	mg/kg dry	1	1J03030	10/03/01	10/09/01	8270-SIM	
Surrogate: p-Terphenyl-d14	94 %		30-150			"	"	"	"	
EX-B-3-5 (B1I0610-03) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J03030	10/03/01	10/09/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Fluorene	0.014	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.017	0.0011	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	ND	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	0.025	0.0012	0.010	"	"	"	"	"	"	
Pyrene	0.0036	0.00010	0.010	"	"	"	"	"	"	J
Surrogate: p-Terphenyl-d14	89 %		30-150			"	"	"	"	
EX-B-4-5 (B1I0610-04) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J03030	10/03/01	10/09/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----	-----------------	-------	----------	-------	----------	----------	--------	-------

EX-B-4-5 (B110610-04) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15

1-Methylnaphthalene	ND	0.0011	0.010	mg/kg dry	1	1J03030	10/03/01	10/09/01	8270-SIM	
2-Methylnaphthalene	ND	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.0012	0.010	"	"	"	"	"	"	
Pyrene	ND	0.00010	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	100 %		30-150			"	"	"	"	

EX-B-5-5 (B110610-05) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15

Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J03030	10/03/01	10/09/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	0.018	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.043	0.0011	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.039	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	0.12	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.0012	0.010	"	"	"	"	"	"	
Pyrene	ND	0.00010	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	94 %		30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-6-5 (B1I0610-06) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Acenaphthene	0.036	0.0014	0.010	mg/kg dry	1	1J03030	10/03/01	10/09/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	J
Benzo (a) anthracene	0.0036	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	J
Chrysene	0.0073	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	J
Fluoranthene	0.0051	0.0010	0.010	"	"	"	"	"	"	
Fluorene	0.081	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	1.3	0.0011	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.55	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	0.089	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	0.091	0.0012	0.010	"	"	"	"	"	"	
Pyrene	0.012	0.00010	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	45 %		30-150							

EX-B-7-5 (B1I0610-07) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J08018	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	J
Anthracene	0.0035	0.0016	0.010	"	"	"	"	"	"	J
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	J
Benzo (a) pyrene	0.0021	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	J
Benzo (ghi) perylene	0.0042	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	J
1-Methylnaphthalene	0.0064	0.0011	0.010	"	"	"	"	"	"	J
2-Methylnaphthalene	0.0021	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.0012	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----	-----------------	-------	----------	-------	----------	----------	--------	-------

EX-B-7-5 (B1I0610-07) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15

Pyrene	ND	0.00010	0.010	mg/kg dry	1	1J08018	10/08/01	10/12/01	8270-SIM	
Surrogate: p-Terphenyl-d14	72 %		30-150			"	"	"	"	

EX-B-8-5 (B1I0610-08) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15

Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J08018	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	ND	0.0011	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	ND	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.0012	0.010	"	"	"	"	"	"	
Pyrene	ND	0.00010	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	83 %		30-150			"	"	"	"	

EX-B-9-5 (B1I0610-09) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15

Acenaphthene	0.051	0.0070	0.050	mg/kg dry	5	1J08018	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	0.023	0.0040	0.050	"	"	"	"	"	"	J
Anthracene	ND	0.0080	0.050	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0055	0.050	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0055	0.050	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0060	0.050	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.0040	0.050	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0080	0.050	"	"	"	"	"	"	
Chrysene	ND	0.0080	0.050	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0070	0.050	"	"	"	"	"	"	
Fluoranthene	ND	0.0050	0.050	"	"	"	"	"	"	
Fluorene	0.17	0.0055	0.050	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0095	0.050	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-9-5 (B1I0610-09) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
1-Methylnaphthalene	1.6	0.0055	0.050	mg/kg dry	5	1J08018	10/08/01	10/12/01	8270-SIM	
2-Methylnaphthalene	1.6	0.0040	0.050	"	"	"	"	"	"	
Naphthalene	0.35	0.0070	0.050	"	"	"	"	"	"	
Phenanthrene	0.31	0.0060	0.050	"	"	"	"	"	"	
Pyrene	0.035	0.00050	0.050	"	"	"	"	"	"	J
Surrogate: p-Terphenyl-d14	80 %		30-150			"	"	"	"	
EX-B-10-5 (B1I0610-10) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J08018	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	0.0028	0.0011	0.010	"	"	"	"	"	"	J
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	0.0028	0.0016	0.010	"	"	"	"	"	"	J
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.0056	0.0011	0.010	"	"	"	"	"	"	J
2-Methylnaphthalene	ND	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	0.0070	0.0012	0.010	"	"	"	"	"	"	J
Pyrene	0.0049	0.00010	0.010	"	"	"	"	"	"	J
Surrogate: p-Terphenyl-d14	89 %		30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-1-4.5 (B1I0610-11) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J08018	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.0051	0.0011	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	ND	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.0012	0.010	"	"	"	"	"	"	
Pyrene	ND	0.00010	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	100 %		30-150			"	"	"	"	

EX-A-2-4.5 (B1I0610-12) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J08018	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.0051	0.0011	0.010	"	"	"	"	"	"	J
2-Methylnaphthalene	ND	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.0012	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9230
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-2-4.5 (B110610-12) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										X
Pyrene	ND	0.00010	0.010	mg/kg dry	1	1J08018	10/08/01	10/12/01	8270-SIM	
Surrogate: p-Terphenyl-d14	6.7 %		30-150			"	"	"	"	

EX-A-2-4.5 (B110610-12RE1) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										Q-29
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J18001	10/18/01	10/22/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
1,2,3,4-dibenz(a,h)anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.014	0.0011	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.0037	0.00080	0.010	"	"	"	"	"	"	J
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.0012	0.010	"	"	"	"	"	"	
Pyrene	ND	0.00010	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	100 %		30-150			"	"	"	"	

EX-A-3-4.5 (B110610-13) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J08018	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting		Dilution	Batch	Prepared	Analyzed	Method	Notes
			Limit	Units						
EX-A-3-4.5 (B110610-13) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
1-Methylnaphthalene	0.0052	0.0011	0.010	mg/kg dry	1	1J08018	10/08/01	10/12/01	8270-SIM	J
2-Methylnaphthalene	ND	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.0012	0.010	"	"	"	"	"	"	
Pyrene	ND	0.00010	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	89 %		30-150							
EX-A-4-4.5 (B110610-14) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J08018	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	0.0032	0.0011	0.010	"	"	"	"	"	"	J
Benzo (a) pyrene	0.0064	0.0011	0.010	"	"	"	"	"	"	J
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	0.0072	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	0.0032	0.0010	0.010	"	"	"	"	"	"	J
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	0.0040	0.0019	0.010	"	"	"	"	"	"	J
1-Methylnaphthalene	0.0072	0.0011	0.010	"	"	"	"	"	"	J
2-Methylnaphthalene	0.0040	0.00080	0.010	"	"	"	"	"	"	J
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	0.0024	0.0012	0.010	"	"	"	"	"	"	J
Pyrene	0.0064	0.00010	0.010	"	"	"	"	"	"	J
Surrogate: p-Terphenyl-d14	90 %		30-150							

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-5-4.5 (B110610-15) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	0.072	0.0070	0.050	mg/kg dry	5	1J08027	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	ND	0.0040	0.050	"	"	"	"	"	"	
Anthracene	0.14	0.0080	0.050	"	"	"	"	"	"	
Benzo (a) anthracene	0.098	0.0055	0.050	"	"	"	"	"	"	
Benzo (a) pyrene	0.057	0.0055	0.050	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0060	0.050	"	"	"	"	"	"	
Benzo (ghi) perylene	0.030	0.0040	0.050	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0080	0.050	"	"	"	"	"	"	
Chrysene	0.16	0.0080	0.050	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0070	0.050	"	"	"	"	"	"	
Fluoranthene	0.057	0.0050	0.050	"	"	"	"	"	"	
Fluorene	0.22	0.0055	0.050	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0095	0.050	"	"	"	"	"	"	
1-Methylnaphthalene	0.34	0.0055	0.050	"	"	"	"	"	"	
2-Methylnaphthalene	0.43	0.0040	0.050	"	"	"	"	"	"	
Naphthalene	ND	0.0070	0.050	"	"	"	"	"	"	
Phenanthrene	0.60	0.0060	0.050	"	"	"	"	"	"	
Pyrene	0.35	0.00050	0.050	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	95 %		30-150							

EX-A-6-4.5 (B110610-16) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	0.21	0.0070	0.050	mg/kg dry	5	1J08027	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	0.11	0.0040	0.050	"	"	"	"	"	"	
Anthracene	ND	0.0080	0.050	"	"	"	"	"	"	
Benzo (a) anthracene	0.12	0.0055	0.050	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0055	0.050	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0060	0.050	"	"	"	"	"	"	
Benzo (ghi) perylene	0.057	0.0040	0.050	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0080	0.050	"	"	"	"	"	"	
Chrysene	0.24	0.0080	0.050	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0070	0.050	"	"	"	"	"	"	
Fluoranthene	0.14	0.0050	0.050	"	"	"	"	"	"	
Fluorene	0.71	0.0055	0.050	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0095	0.050	"	"	"	"	"	"	
1-Methylnaphthalene	5.7	0.0055	0.050	"	"	"	"	"	"	
2-Methylnaphthalene	8.1	0.0040	0.050	"	"	"	"	"	"	
Naphthalene	4.2	0.0070	0.050	"	"	"	"	"	"	
Phenanthrene	1.1	0.0060	0.050	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-6-4.5 (B110610-16) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Pyrene	0.44	0.00050	0.050	mg/kg dry	5	1J08027	10/08/01	10/12/01	8270-SIM	
Surrogate: p-Terphenyl-d14	90 %		30-150			"	"	"	"	
EX-A-7-4.5 (B110610-17) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	0.0026	0.0014	0.010	mg/kg dry	1	1J08027	10/08/01	10/12/01	8270-SIM	J
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	0.0051	0.0016	0.010	"	"	"	"	"	"	J
Benzo (a) anthracene	0.014	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	0.013	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	0.012	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	0.039	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	0.011	0.0010	0.010	"	"	"	"	"	"	
Fluorene	0.0094	0.0011	0.010	"	"	"	"	"	"	J
Indeno (1,2,3-cd) pyrene	0.0051	0.0019	0.010	"	"	"	"	"	"	J
1-Methylnaphthalene	0.020	0.0011	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.020	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	0.014	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	0.048	0.0012	0.010	"	"	"	"	"	"	
Pyrene	0.067	0.00010	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	86 %		30-150			"	"	"	"	
EX-A-8-4.5 (B110610-18) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	0.11	0.014	0.10	mg/kg dry	10	1J08027	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	0.062	0.0080	0.10	"	"	"	"	"	"	J
Anthracene	0.080	0.016	0.10	"	"	"	"	"	"	J
Benzo (a) anthracene	0.035	0.011	0.10	"	"	"	"	"	"	J
Benzo (a) pyrene	0.035	0.011	0.10	"	"	"	"	"	"	J
Benzo (b) fluoranthene	ND	0.012	0.10	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.0080	0.10	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.016	0.10	"	"	"	"	"	"	
Chrysene	0.053	0.016	0.10	"	"	"	"	"	"	J
Dibenz (a,h) anthracene	ND	0.014	0.10	"	"	"	"	"	"	
Fluoranthene	0.053	0.010	0.10	"	"	"	"	"	"	J
Fluorene	0.59	0.011	0.10	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.019	0.10	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-8-4.5 (B1I0610-18) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
1-Methylnaphthalene	6.4	0.011	0.10	mg/kg dry	10	1J08027	10/08/01	10/12/01	8270-SIM	
2-Methylnaphthalene	11	0.0080	0.10	"	"	"	"	"	"	
Naphthalene	0.88	0.014	0.10	"	"	"	"	"	"	
Phenanthrene	0.96	0.012	0.10	"	"	"	"	"	"	
Pyrene	0.14	0.0010	0.10	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	91 %		30-150			"	"	"	"	
EX-A-9-4.5 (B1I0610-19) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	0.0044	0.0014	0.010	mg/kg dry	1	1J08027	10/08/01	10/12/01	8270-SIM	J
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	0.015	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	0.018	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	0.0088	0.0011	0.010	"	"	"	"	"	"	J
Benzo (b) fluoranthene	0.0061	0.0012	0.010	"	"	"	"	"	"	J
Benzo (ghi) perylene	0.0044	0.00080	0.010	"	"	"	"	"	"	J
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	0.032	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	0.012	0.0010	0.010	"	"	"	"	"	"	
Fluorene	0.020	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.025	0.0011	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.044	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	0.061	0.0012	0.010	"	"	"	"	"	"	
Pyrene	0.057	0.00010	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	77 %		30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-10-4.5 (B110610-20) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	0.036	0.0028	0.020	mg/kg dry	2	1J08027	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	0.022	0.0016	0.020	"	"	"	"	"	"	
Anthracene	0.018	0.0032	0.020	"	"	"	"	"	"	J
Benzo (a) anthracene	0.022	0.0022	0.020	"	"	"	"	"	"	
Benzo (a) pyrene	0.022	0.0022	0.020	"	"	"	"	"	"	
Benzo (b) fluoranthene	0.024	0.0024	0.020	"	"	"	"	"	"	
Benzo (ghi) perylene	0.014	0.0016	0.020	"	"	"	"	"	"	J
Benzo (k) fluoranthene	ND	0.0032	0.020	"	"	"	"	"	"	
Chrysene	0.036	0.0032	0.020	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0028	0.020	"	"	"	"	"	"	
Fluoranthene	0.038	0.0020	0.020	"	"	"	"	"	"	
Fluorene	0.097	0.0022	0.020	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	0.010	0.0038	0.020	"	"	"	"	"	"	J
1-Methylnaphthalene	1.1	0.0022	0.020	"	"	"	"	"	"	
2-Methylnaphthalene	1.8	0.0016	0.020	"	"	"	"	"	"	
Naphthalene	0.38	0.0028	0.020	"	"	"	"	"	"	
Phenanthrene	0.12	0.0024	0.020	"	"	"	"	"	"	
Pyrene	0.089	0.00020	0.020	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	84 %		30-150							

EX-A-11-4.5 (B110610-21) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J08027	10/08/01	10/12/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.0052	0.0011	0.010	"	"	"	"	"	"	J
2-Methylnaphthalene	ND	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	ND	0.0012	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

**Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-11-4.5 (B110610-21) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Pyrene	ND	0.00010	0.010 mg/kg dry		1	1J08027	10/08/01	10/12/01	8270-SIM	
Surrogate: p-Terphenyl-d14	100 %		30-150			"	"	"	"	

Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Physical Parameters by APHA/ASTM/EPA Methods
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-1-5 (B1I0610-01) Soil	Sampled: 09/27/01 10:00 Received: 09/27/01 15:15									
Dry Weight	89.5		1.00	%	1	1J04007	10/04/01	10/05/01	BSOPSPLO0 3R07	
EX-B-2-5 (B1I0610-02) Soil	Sampled: 09/27/01 10:00 Received: 09/27/01 15:15									
Dry Weight	89.5		1.00	%	1	1J04007	10/04/01	10/05/01	BSOPSPLO0 3R07	
EX-B-3-5 (B1I0610-03) Soil	Sampled: 09/27/01 10:00 Received: 09/27/01 15:15									
Dry Weight	91.4		1.00	%	1	1J04007	10/04/01	10/05/01	BSOPSPLO0 3R07	
EX-B-4-5 (B1I0610-04) Soil	Sampled: 09/27/01 10:00 Received: 09/27/01 15:15									
Dry Weight	90.1		1.00	%	1	1J04003	10/04/01	10/04/01	BSOPSPLO0 3R07	
EX-B-5-5 (B1I0610-05) Soil	Sampled: 09/27/01 10:00 Received: 09/27/01 15:15									
Dry Weight	92.1		1.00	%	1	1J04007	10/04/01	10/05/01	BSOPSPLO0 3R07	
EX-B-6-5 (B1I0610-06) Soil	Sampled: 09/27/01 10:00 Received: 09/27/01 15:15									
Dry Weight	91.5		1.00	%	1	1J04007	10/04/01	10/05/01	BSOPSPLO0 3R07	
EX-B-7-5 (B1I0610-07) Soil	Sampled: 09/27/01 10:00 Received: 09/27/01 15:15									
Dry Weight	94.4		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPLO0 3R07	
EX-B-8-5 (B1I0610-08) Soil	Sampled: 09/27/01 10:00 Received: 09/27/01 15:15									
Dry Weight	94.5		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPLO0 3R07	
EX-B-9-5 (B1I0610-09) Soil	Sampled: 09/27/01 10:00 Received: 09/27/01 15:15									
Dry Weight	85.1		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPLO0 3R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Physical Parameters by APHA/ASTM/EPA Methods
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-B-10-5 (B1I0610-10) Soil Sampled: 09/27/01 10:00 Received: 09/27/01 15:15										
Dry Weight	94.8		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	
EX-A-1-4.5 (B1I0610-11) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	91.0		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	
EX-A-2-4.5 (B1I0610-12) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	90.8		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	
EX-A-3-4.5 (B1I0610-13) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	90.0		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	
EX-A-4-4.5 (B1I0610-14) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	83.5		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	
EX-A-5-4.5 (B1I0610-15) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	88.4		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	
EX-A-6-4.5 (B1I0610-16) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	81.4		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	
EX-A-7-4.5 (B1I0610-17) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	78.4		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	
EX-A-8-4.5 (B1I0610-18) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	75.3		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

**Physical Parameters by APHA/ASTM/EPA Methods
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-9-4.5 (B1I0610-19) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	76.0		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	
EX-A-10-4.5 (B1I0610-20) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	65.5		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	
EX-A-11-4.5 (B1I0610-21) Soil Sampled: 09/27/01 11:00 Received: 09/27/01 15:15										
Dry Weight	90.2		1.00	%	1	1J06009	10/06/01	10/08/01	BSOPSPL00 3R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J03019: Prepared 10/03/01 Using EPA 5030B (MeOH)

Blank (1J03019-BLK1)

Gasoline Range Hydrocarbons	ND		5.00	mg/kg							
Benzene	ND		0.0300	"							
Toluene	ND		0.0500	"							
Ethylbenzene	ND		0.0500	"							
Xylenes (total)	ND		0.100	"							
Surrogate: 4-BFB (FID)	3.69			"	4.00		92.2	50-147			
Surrogate: 4-BFB (PID)	3.39			"	4.00		84.8	54-123			

LCS (1J03019-BS1)

Gasoline Range Hydrocarbons	24.6		5.00	mg/kg	25.0		98.4	80-120			
Surrogate: 4-BFB (FID)	4.47			"	4.00		112	50-147			

LCS (1J03019-BS2)

Benzene	0.532		0.0300	mg/kg	0.500		106	80-120			
Toluene	0.564		0.0500	"	0.500		113	80-120			
Ethylbenzene	0.563		0.0500	"	0.500		113	80-120			
Xylenes (total)	1.71		0.100	"	1.50		114	80-120			
Surrogate: 4-BFB (PID)	3.63			"	4.00		90.8	54-123			

LCS Dup (1J03019-BSD1)

Gasoline Range Hydrocarbons	24.7		5.00	mg/kg	25.0		98.8	80-120	0.406	40	
Surrogate: 4-BFB (FID)	4.41			"	4.00		110	50-147			

LCS Dup (1J03019-BSD2)

Benzene	0.520		0.0300	mg/kg	0.500		104	80-120	2.28	40	
Toluene	0.543		0.0500	"	0.500		109	80-120	3.79	40	
Ethylbenzene	0.549		0.0500	"	0.500		110	80-120	2.52	40	
Xylenes (total)	1.66		0.100	"	1.50		111	80-120	2.97	40	
Surrogate: 4-BFB (PID)	3.55			"	4.00		88.8	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J03019: Prepared 10/03/01 Using EPA 5030B (MeOH)

Matrix Spike (1J03019-MS1)					Source: B1J0028-01						
Gasoline Range Hydrocarbons	25.9		5.00 mg/kg dry	29.6	ND	87.5	53-120				
Surrogate: 4-BFB (FID)	4.92		"	4.74		104	50-147				

Matrix Spike (1J03019-MS2)					Source: B1I0610-04						
Benzene	0.528		0.0300 mg/kg dry	0.555	ND	95.1	64-130				
Toluene	0.561		0.0500 "	0.555	ND	101	66-130				
Ethylbenzene	0.560		0.0500 "	0.555	ND	101	72-130				
Xylenes (total)	1.70		0.100 "	1.67	ND	102	73-130				
Surrogate: 4-BFB (PID)	3.31		"	4.44		74.5	54-123				

Matrix Spike Dup (1J03019-MSD1)					Source: B1J0028-01						
Gasoline Range Hydrocarbons	26.6		5.00 mg/kg dry	29.6	ND	89.9	53-120	2.67	40		
Surrogate: 4-BFB (FID)	4.81		"	4.74		101	50-147				

Matrix Spike Dup (1J03019-MSD2)					Source: B1I0610-04						
Benzene	0.524		0.0300 mg/kg dry	0.555	ND	94.4	64-130	0.760	40		
Toluene	0.550		0.0500 "	0.555	ND	99.1	66-130	1.98	40		
Ethylbenzene	0.554		0.0500 "	0.555	ND	99.8	72-130	1.08	40		
Xylenes (total)	1.68		0.100 "	1.67	ND	101	73-130	1.18	40		
Surrogate: 4-BFB (PID)	3.54		"	4.44		79.7	54-123				

Batch 1J04028: Prepared 10/04/01 Using EPA 5030B (MeOH)

Blank (1J04028-BLK1)											
Gasoline Range Hydrocarbons	ND		5.00 mg/kg								
Benzene	ND		0.0300 "								
Toluene	ND		0.0500 "								
Ethylbenzene	ND		0.0500 "								
Xylenes (total)	ND		0.100 "								
Surrogate: 4-BFB (FID)	3.55		"	4.00		88.8	50-147				
Surrogate: 4-BFB (PID)	3.70		"	4.00		92.5	54-123				

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J04028: Prepared 10/04/01 Using EPA 5030B (MeOH)

LCS (1J04028-BS1)

Gasoline Range Hydrocarbons	23.9		5.00	mg/kg	25.0		95.6	80-120			
Surrogate: 4-BFB (FID)	3.94			"	4.00		98.5	50-147			

LCS (1J04028-BS2)

Benzene	0.449		0.0300	mg/kg	0.500		89.8	80-120			
Toluene	0.489		0.0500	"	0.500		97.8	80-120			
Ethylbenzene	0.503		0.0500	"	0.500		101	80-120			
Xylenes (total)	1.53		0.100	"	1.50		102	80-120			
Surrogate: 4-BFB (PID)	3.75			"	4.00		93.8	54-123			

LCS Dup (1J04028-BSD1)

Gasoline Range Hydrocarbons	24.0		5.00	mg/kg	25.0		96.0	80-120	0.418	40	
Surrogate: 4-BFB (FID)	3.78			"	4.00		94.5	50-147			

LCS Dup (1J04028-BSD2)

Benzene	0.450		0.0300	mg/kg	0.500		90.0	80-120	0.222	40	
Toluene	0.488		0.0500	"	0.500		97.6	80-120	0.205	40	
Ethylbenzene	0.505		0.0500	"	0.500		101	80-120	0.397	40	
Xylenes (total)	1.53		0.100	"	1.50		102	80-120	0.00	40	
Surrogate: 4-BFB (PID)	3.74			"	4.00		93.5	54-123			

Matrix Spike (1J04028-MS1)

Source: B110570-11

Gasoline Range Hydrocarbons	24.6		5.00	mg/kg dry	26.7	ND	92.1	53-120			
Surrogate: 4-BFB (FID)	3.89			"	4.28		90.9	50-147			

Matrix Spike (1J04028-MS2)

Source: B110610-07

Benzene	0.468		0.0300	mg/kg dry	0.530	ND	85.9	64-130			
Toluene	0.517		0.0500	"	0.530	ND	93.5	66-130			
Ethylbenzene	0.529		0.0500	"	0.530	ND	97.7	72-130			
Xylenes (total)	1.61		0.100	"	1.59	ND	98.0	73-130			
Surrogate: 4-BFB (PID)	3.79			"	4.24		89.4	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network

Page 34 of 47



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J04028: Prepared 10/04/01 Using EPA 5030B (MeOH)

Matrix Spike Dup (1J04028-MSD1)

Source: B110570-11

Gasoline Range Hydrocarbons	23.8		5.00 mg/kg dry		26.7	ND	89.1	53-120	3.31	40	
Surrogate: 4-BFB (FID)	3.81			"	4.28		89.0	50-147			

Matrix Spike Dup (1J04028-MSD2)

Source: B110610-07

Benzene	0.462		0.0300 mg/kg dry		0.530	ND	84.8	64-130	1.29	40	
Toluene	0.503		0.0500	"	0.530	ND	90.8	66-130	2.75	40	
Ethylbenzene	0.528		0.0500	"	0.530	ND	97.5	72-130	0.189	40	
Xylenes (total)	1.59		0.100	"	1.59	ND	96.7	73-130	1.25	40	
Surrogate: 4-BFB (PID)	3.85			"	4.24		90.8	54-123			

Batch 1J10004: Prepared 10/10/01 Using EPA 5030B (P/T)

Blank (1J10004-BLK1)

Gasoline Range Hydrocarbons	ND		50.0	ug/l							
Benzene	ND		0.500	"							
Toluene	ND		0.500	"							
Ethylbenzene	ND		0.500	"							
Xylenes (total)	ND		1.00	"							
Surrogate: 4-BFB (FID)	42.7			"	48.0		89.0	62-139			
Surrogate: 4-BFB (PID)	44.9			"	48.0		93.5	62-125			

LCS (1J10004-BS1)

Gasoline Range Hydrocarbons	500		50.0	ug/l	500		100	80-120			
Surrogate: 4-BFB (FID)	49.5			"	48.0		103	62-139			

LCS (1J10004-BS2)

Benzene	8.37		0.500	ug/l	10.0		83.7	80-120			
Toluene	8.76		0.500	"	10.0		87.6	80-120			
Ethylbenzene	8.99		0.500	"	10.0		89.9	80-120			
Xylenes (total)	27.5		1.00	"	30.0		91.7	80-120			
Surrogate: 4-BFB (PID)	45.3			"	48.0		94.4	62-125			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J10004: Prepared 10/10/01 Using EPA 5030B (P/T)

LCS Dup (1J10004-BSD1)

Gasoline Range Hydrocarbons	485		50.0	ug/l	500		97.0	80-120	3.05	25	
Surrogate: 4-BFB (FID)	49.7			"	48.0		104	62-139			

LCS Dup (1J10004-BSD2)

Benzene	8.28		0.500	ug/l	10.0		82.8	80-120	1.08	40	
Toluene	8.58		0.500	"	10.0		85.8	80-120	2.08	40	
Ethylbenzene	8.83		0.500	"	10.0		88.3	80-120	1.80	40	
Xylenes (total)	26.9		1.00	"	30.0		89.7	80-120	2.21	40	
Surrogate: 4-BFB (PID)	45.6			"	48.0		95.0	62-125			

Matrix Spike (1J10004-MS1)

Source: B1J0127-01

Gasoline Range Hydrocarbons	908		50.0	ug/l	500	552	71.2	70-130			
Surrogate: 4-BFB (FID)	65.5			"	48.0		136	62-139			

Matrix Spike (1J10004-MS2)

Source: B1J0055-03

Benzene	8.49		0.500	ug/l	10.0	ND	83.3	80-120			
Toluene	8.68		0.500	"	10.0	ND	85.1	75-117			
Ethylbenzene	8.82		0.500	"	10.0	ND	88.2	80-120			
Xylenes (total)	25.3		1.00	"	30.0	ND	84.3	80-120			
Surrogate: 4-BFB (PID)	45.7			"	48.0		95.2	62-125			

Matrix Spike Dup (1J10004-MSD1)

Source: B1J0127-01

Gasoline Range Hydrocarbons	902		50.0	ug/l	500	552	70.0	70-130	0.663	25	
Surrogate: 4-BFB (FID)	64.9			"	48.0		135	62-139			

Matrix Spike Dup (1J10004-MSD2)

Source: B1J0055-03

Benzene	8.72		0.500	ug/l	10.0	ND	85.6	80-120	2.67	40	
Toluene	8.90		0.500	"	10.0	ND	87.3	75-117	2.50	40	
Ethylbenzene	9.02		0.500	"	10.0	ND	90.2	80-120	2.24	40	
Xylenes (total)	25.9		1.00	"	30.0	ND	86.3	80-120	2.34	40	
Surrogate: 4-BFB (PID)	46.0			"	48.0		95.8	62-125			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J05042: Prepared 10/05/01 Using EPA 3545

Blank (1J05042-BLK1)

Diesel Range Hydrocarbons	ND		10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND		25.0	"							
Surrogate: 2-FBP	9.94			"	10.7		92.9	50-150			
Surrogate: Octacosane	10.9			"	10.7		102	50-150			

LCS (1J05042-BS1)

Diesel Range Hydrocarbons	60.6		10.0	mg/kg	66.7		90.9	50-150			
Surrogate: 2-FBP	8.94			"	10.7		83.6	50-150			

LCS Dup (1J05042-BSD1)

Diesel Range Hydrocarbons	62.0		10.0	mg/kg	66.7		93.0	50-150	2.28	50	
Surrogate: 2-FBP	11.5			"	10.7		107	50-150			

Duplicate (1J05042-DUP1)

Source: B110558-07

Diesel Range Hydrocarbons	3980		210	mg/kg dry		4390			9.80	50	
Lube Oil Range Hydrocarbons	1220		525	"		1390			13.0	50	
Surrogate: 2-FBP	8.50			"	11.7		72.6	50-150			
Surrogate: Octacosane	10.4			"	11.7		88.9	50-150			

Batch 1J08026: Prepared 10/08/01 Using EPA 3550B

Blank (1J08026-BLK1)

Diesel Range Hydrocarbons	ND		10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND		25.0	"							
Surrogate: 2-FBP	9.58			"	10.7		89.5	50-150			
Surrogate: Octacosane	10.6			"	10.7		99.1	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J08026: Prepared 10/08/01 Using EPA 3550B

LCS (1J08026-BS1)

Diesel Range Hydrocarbons	57.3		10.0	mg/kg	66.7		85.9	50-150			
Surrogate: 2-FBP	11.0			"	10.7		103	50-150			

LCS Dup (1J08026-BSD1)

Diesel Range Hydrocarbons	63.0		10.0	mg/kg	66.7		94.5	50-150	9.48	50	
Surrogate: 2-FBP	10.5			"	10.7		98.1	50-150			

Duplicate (1J08026-DUP1) Source: B110610-21

Diesel Range Hydrocarbons	ND		10.0	mg/kg dry		ND				50	
Lube Oil Range Hydrocarbons	ND		25.0	"		ND			42.2	50	
Surrogate: 2-FBP	11.5			"	11.8		97.5	50-150			
Surrogate: Octacosane	12.4			"	11.8		105	50-150			

Batch 1J16038: Prepared 10/16/01 Using EPA 3550B

Blank (1J16038-BLK1)

Diesel Range Hydrocarbons	ND		10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND		25.0	"							
Surrogate: 2-FBP	8.21			"	10.7		76.7	50-150			
Surrogate: Octacosane	9.61			"	10.7		89.8	50-150			

LCS (1J16038-BS1)

Diesel Range Hydrocarbons	48.4		10.0	mg/kg	66.7		72.6	50-150			
Surrogate: 2-FBP	8.58			"	10.7		80.2	50-150			

LCS Dup (1J16038-BSD1)

Diesel Range Hydrocarbons	69.5		10.0	mg/kg	66.7		104	50-150	35.8	50	
Surrogate: 2-FBP	9.06			"	10.7		84.7	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J16038: Prepared 10/16/01 Using EPA 3550B

Duplicate (1J16038-DUP1)

Source: B110558-11RE1

Diesel Range Hydrocarbons	87.2		10.0 mg/kg dry			125			35.6	50	
Lube Oil Range Hydrocarbons	29.7		25.0	"		43.6			37.9	50	
Surrogate: 2-FBP	8.93			"	11.8		75.7	50-150			
Surrogate: Octacosane	12.2			"	11.8		103	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network

Page 39 of 47



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J03030: Prepared 10/03/01 Using EPA 3550B

Blank (1J03030-BLK1)

Acenaphthene	ND	0.0014	0.010	mg/kg							
Acenaphthylene	ND	0.00080	0.010	"							
Anthracene	ND	0.0016	0.010	"							
Benzo (a) anthracene	ND	0.0011	0.010	"							
Benzo (a) pyrene	ND	0.0011	0.010	"							
Benzo (b) fluoranthene	ND	0.0012	0.010	"							
Benzo (ghi) perylene	ND	0.00080	0.010	"							
Benzo (k) fluoranthene	ND	0.0016	0.010	"							
Chrysene	ND	0.0016	0.010	"							
Dibenz (a,h) anthracene	ND	0.0014	0.010	"							
Fluorene	ND	0.0010	0.010	"							
Fluorene	ND	0.0011	0.010	"							
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"							
1-Methylnaphthalene	ND	0.0011	0.010	"							
2-Methylnaphthalene	ND	0.00080	0.010	"							
Naphthalene	ND	0.0014	0.010	"							
Phenanthrene	ND	0.0012	0.010	"							
Pyrene	ND	0.00010	0.010	"							

Surrogate: p-Terphenyl-d14 1.4 " 1.7 82 30-150

LCS (1J03030-BS1)

Chrysene	0.28	0.0016	0.010	mg/kg	0.33		85	10-125			
Fluorene	0.27	0.0011	0.010	"	0.33		82	11-116			
Indeno (1,2,3-cd) pyrene	0.25	0.0019	0.010	"	0.33		76	10-147			

Surrogate: p-Terphenyl-d14 1.4 " 1.7 82 30-150

LCS Dup (1J03030-BSD1)

Chrysene	0.29	0.0016	0.010	mg/kg	0.33		88	10-125	3.5	28	
Fluorene	0.28	0.0011	0.010	"	0.33		85	11-116	3.6	32	
Indeno (1,2,3-cd) pyrene	0.25	0.0019	0.010	"	0.33		76	10-147	0.0	34	

Surrogate: p-Terphenyl-d14 1.4 " 1.7 82 30-150

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J03030: Prepared 10/03/01 Using EPA 3550B

Matrix Spike (1J03030-MS1)

Source: B110530-03

Chrysene	0.66	0.16	1.0 mg/kg dry	0.37	0.37	78	10-125				J
Fluorene	7.3	0.11	1.0 "	0.37	5.8	410	10-154				Q-03
Indeno (1,2,3-cd) pyrene	0.37	0.19	1.0 "	0.37	ND	100	10-144				J
Surrogate: p-Terphenyl-d14	1.5		"	1.8		83	30-150				

Matrix Spike Dup (1J03030-MSD1)

Source: B110530-03

Chrysene	0.66	0.16	1.0 mg/kg dry	0.37	0.37	78	10-125	0.0	28		J
Fluorene	7.1	0.11	1.0 "	0.37	5.8	350	10-154	2.8	32		Q-03
Indeno (1,2,3-cd) pyrene	0.29	0.19	1.0 "	0.37	ND	78	10-144	24	47		J
Surrogate: p-Terphenyl-d14	1.5		"	1.8		83	30-150				

Batch 1J08018: Prepared 10/08/01 Using EPA 3550B

Blank (1J08018-BLK1)

Acenaphthene	ND	0.0014	0.010 mg/kg								
Acenaphthylene	ND	0.00080	0.010 "								
Anthracene	ND	0.0016	0.010 "								
Benzo (a) anthracene	ND	0.0011	0.010 "								
Benzo (a) pyrene	ND	0.0011	0.010 "								
Benzo (b) fluoranthene	ND	0.0012	0.010 "								
Benzo (ghi) perylene	ND	0.00080	0.010 "								
Benzo (k) fluoranthene	ND	0.0016	0.010 "								
Chrysene	ND	0.0016	0.010 "								
Dibenz (a,h) anthracene	ND	0.0014	0.010 "								
Fluoranthene	ND	0.0010	0.010 "								
Fluorene	ND	0.0011	0.010 "								
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010 "								
1-Methylnaphthalene	ND	0.0011	0.010 "								
2-Methylnaphthalene	ND	0.00080	0.010 "								
Naphthalene	ND	0.0014	0.010 "								
Phenanthrene	ND	0.0012	0.010 "								
Pyrene	ND	0.00010	0.010 "								
Surrogate: p-Terphenyl-d14	1.3		"	1.7		76	30-150				

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J08018: Prepared 10/08/01 Using EPA 3550B

LCS (1J08018-BS1)

Chrysene	0.28	0.0016	0.010	mg/kg	0.33		85	10-125			
Fluorene	0.24	0.0011	0.010	"	0.33		73	11-116			
Indeno (1,2,3-cd) pyrene	0.26	0.0019	0.010	"	0.33		79	10-147			
Surrogate: p-Terphenyl-d14	1.2			"	1.7		71	30-150			

LCS Dup (1J08018-BSD1)

Chrysene	0.27	0.0016	0.010	mg/kg	0.33		82	10-125	3.6	28	
Fluorene	0.26	0.0011	0.010	"	0.33		79	11-116	8.0	32	
Indeno (1,2,3-cd) pyrene	0.28	0.0019	0.010	"	0.33		85	10-147	7.4	34	
Surrogate: p-Terphenyl-d14	1.3			"	1.7		76	30-150			

Spike (1J08018-MS1)

Source: B110610-07

Chrysene	0.25	0.0016	0.010	mg/kg dry	0.35	ND	71	10-125			
Fluorene	0.32	0.0011	0.010	"	0.35	ND	91	10-154			
Indeno (1,2,3-cd) pyrene	0.25	0.0019	0.010	"	0.35	ND	71	10-144			
Surrogate: p-Terphenyl-d14	1.3			"	1.8		72	30-150			

Matrix Spike Dup (1J08018-MSD1)

Source: B110610-07

Chrysene	0.25	0.0016	0.010	mg/kg dry	0.35	ND	71	10-125	0.0	28	
Fluorene	0.31	0.0011	0.010	"	0.35	ND	89	10-154	3.2	32	
Indeno (1,2,3-cd) pyrene	0.25	0.0019	0.010	"	0.35	ND	71	10-144	0.0	47	
Surrogate: p-Terphenyl-d14	1.3			"	1.8		72	30-150			

Batch 1J08027: Prepared 10/08/01 Using EPA 3550B

Blank (1J08027-BLK1)

Acenaphthene	ND	0.0014	0.010	mg/kg							
Acenaphthylene	ND	0.00080	0.010	"							
Anthracene	ND	0.0016	0.010	"							
Benzo (a) anthracene	ND	0.0011	0.010	"							
Benzo (a) pyrene	ND	0.0011	0.010	"							
Benzo (b) fluoranthene	ND	0.0012	0.010	"							
Benzo (ghi) perylene	ND	0.00080	0.010	"							
Benzo (k) fluoranthene	ND	0.0016	0.010	"							

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J08027: Prepared 10/08/01 Using EPA 3550B

Blank (1J08027-BLK1)

Chrysene	ND	0.0016	0.010	mg/kg							
Dibenz (a,h) anthracene	ND	0.0014	0.010	"							
Fluoranthene	ND	0.0010	0.010	"							
Fluorene	ND	0.0011	0.010	"							
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"							
1-Methylnaphthalene	ND	0.0011	0.010	"							
2-Methylnaphthalene	ND	0.00080	0.010	"							
Naphthalene	ND	0.0014	0.010	"							
Phenanthrene	ND	0.0012	0.010	"							
Pyrene	ND	0.00010	0.010	"							

Surrogate: p-Terphenyl-d14 1.6 " 1.7 94 30-150

LCS (1J08027-BS1)

Chrysene	0.24	0.0016	0.010	mg/kg	0.33		73	10-125			
Fluorene	0.24	0.0011	0.010	"	0.33		73	11-116			
Indeno (1,2,3-cd) pyrene	0.26	0.0019	0.010	"	0.33		79	10-147			

Surrogate: p-Terphenyl-d14 1.3 " 1.7 76 30-150

LCS Dup (1J08027-BSD1)

Chrysene	0.28	0.0016	0.010	mg/kg	0.33		85	10-125	15	28	
Fluorene	0.27	0.0011	0.010	"	0.33		82	11-116	12	32	
Indeno (1,2,3-cd) pyrene	0.26	0.0019	0.010	"	0.33		79	10-147	0.0	34	

Surrogate: p-Terphenyl-d14 1.4 " 1.7 82 30-150

Matrix Spike (1J08027-MS1)

Source: B110610-21

Chrysene	0.29	0.0016	0.010	mg/kg dry	0.37	ND	78	10-125			
Fluorene	0.30	0.0011	0.010	"	0.37	ND	81	10-154			
Indeno (1,2,3-cd) pyrene	0.17	0.0019	0.010	"	0.37	ND	46	10-144			

Surrogate: p-Terphenyl-d14 1.7 " 1.8 94 30-150

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/27/01 12:45

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J08027: Prepared 10/08/01 Using EPA 3550B

Matrix Spike Dup (1J08027-MSD1)

Source: B110610-21

Chrysene	0.30	0.0016	0.010	mg/kg dry	0.37	ND	81	10-125	3.4	28	
Fluorene	0.31	0.0011	0.010	"	0.37	ND	84	10-154	3.3	32	
Indeno (1,2,3-cd) pyrene	0.23	0.0019	0.010	"	0.37	ND	62	10-144	30	47	
Surrogate: p-Terphenyl-d14	1.7			"	1.8		94	30-150			

Batch 1J18001: Prepared 10/18/01 Using EPA 3550B

Blank (1J18001-BLK1)

Accenaphthene	ND	0.0014	0.010	mg/kg							
Accenaphthylene	ND	0.00080	0.010	"							
Anthracene	ND	0.0016	0.010	"							
B(a) anthracene	ND	0.0011	0.010	"							
B(a) pyrene	ND	0.0011	0.010	"							
Benzo (b) fluoranthene	ND	0.0012	0.010	"							
Benzo (ghi) perylene	ND	0.00080	0.010	"							
Benzo (k) fluoranthene	ND	0.0016	0.010	"							
Chrysene	ND	0.0016	0.010	"							
Dibenz (a,h) anthracene	ND	0.0014	0.010	"							
Fluoranthene	ND	0.0010	0.010	"							
Fluorene	ND	0.0011	0.010	"							
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"							
1-Methylnaphthalene	ND	0.0011	0.010	"							
2-Methylnaphthalene	ND	0.00080	0.010	"							
Naphthalene	ND	0.0014	0.010	"							
Phenanthrene	ND	0.0012	0.010	"							
Pyrene	ND	0.00010	0.010	"							
Surrogate: p-Terphenyl-d14	1.5			"	1.7		88	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J18001: Prepared 10/18/01 Using EPA 3550B

LCS (1J18001-BS1)

Chrysene	0.28	0.0016	0.010	mg/kg	0.33		85	10-125			
Fluorene	0.28	0.0011	0.010	"	0.33		85	11-116			
Indeno (1,2,3-cd) pyrene	0.21	0.0019	0.010	"	0.33		64	10-147			
Surrogate: p-Terphenyl-d14	1.6			"	1.7		94	30-150			

LCS Dup (1J18001-BSD1)

Chrysene	0.27	0.0016	0.010	mg/kg	0.33		82	10-125	3.6	28	
Fluorene	0.27	0.0011	0.010	"	0.33		82	11-116	3.6	32	
Indeno (1,2,3-cd) pyrene	0.19	0.0019	0.010	"	0.33		58	10-147	10	34	
Surrogate: p-Terphenyl-d14	1.6			"	1.7		94	30-150			

Matrix Spike (1J18001-MS1)

Source: B1J0215-19

Chrysene	0.27	0.0016	0.010	mg/kg wet	0.33	ND	82	10-125			
Fluorene	0.27	0.0011	0.010	"	0.33	ND	82	10-154			
Indeno (1,2,3-cd) pyrene	0.23	0.0019	0.010	"	0.33	ND	70	10-144			
Surrogate: p-Terphenyl-d14	1.5			"	1.7		88	30-150			

Matrix Spike Dup (1J18001-MSD1)

Source: B1J0215-19

Chrysene	0.27	0.0016	0.010	mg/kg wet	0.33	ND	82	10-125	0.0	28	
Fluorene	0.26	0.0011	0.010	"	0.33	ND	79	10-154	3.8	32	
Indeno (1,2,3-cd) pyrene	0.21	0.0019	0.010	"	0.33	ND	64	10-144	9.1	47	
Surrogate: p-Terphenyl-d14	1.4			"	1.7		82	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

Physical Parameters by APHA/ASTM/EPA Methods - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1J04003: Prepared 10/04/01 Using Dry Weight											
Blank (1J04003-BLK1)											
Dry Weight	100		1.00	%							
Batch 1J04007: Prepared 10/04/01 Using Dry Weight											
Blank (1J04007-BLK1)											
Dry Weight	100		1.00	%							
Batch 1J06009: Prepared 10/06/01 Using Dry Weight											
Blank (1J06009-BLK1)											
Dry Weight	100		1.00	%							

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/27/01 12:45
--	--	-----------------------------

Notes and Definitions

- D-10 The heavy oil range organics present are due to hydrocarbons eluting primarily in the diesel range.
- G-01 Results reported for the gas range are primarily due to overlap from diesel range hydrocarbons.
- I-06 The analyte concentration may be artificially elevated due to coeluting compounds or components.
- J Estimated value.
- Q-03 The percent recovery for this QC spike sample cannot be accurately calculated due to the high concentration of analyte already present in the sample.
- Q-29 This sample was prepared outside of the method established holding time.
- S-01 The surrogate recovery for this sample is not available due to sample dilution required from high analyte concentration and/or matrix interferences.
- S-02 The surrogate recovery for this sample cannot be accurately quantified due to interference from coeluting organic compounds present in the sample.
- S-04 The surrogate recovery for this sample is outside of established control limits due to a sample matrix effect.
- S-06 The recovery of this surrogate is outside control limits due to sample dilution required from high analyte concentration and/or matrix interferences.
- X See case narrative.
- DET Analyte DETECTED
- ND Analyte NOT DETECTED at or above the reporting limit
- NR Not Reported
- dry Sample results reported on a dry weight basis
- RPD Relative Percent Difference

UNOCAL CHAIN OF CUSTODY REPORT

UNOCAL INFORMATION	
Facility Number:	Unocal Edmonds Terminal
Site Address:	11720 Unoco Road
City, State, ZIP:	Edmonds 98020
Site Release Number:	
Unocal Manager:	Mark Bearley
CERT INFO: (check one)	<input type="checkbox"/> Evaluation <input checked="" type="checkbox"/> Remediation <input type="checkbox"/> Detection <input type="checkbox"/> Demolition <input type="checkbox"/> Closure <input type="checkbox"/> Miscellaneous

CONSULTANT INFORMATION	
Firm:	Maui Foster & Alangi
Project#	9077, 001, 004
Address:	17171-Bothell Way NE. #267 Seattle, 98155
Phone:	744-1489
Fax:	744-0919
Project Manager:	L. Dawson
Sample Collection by:	R. Dyer

Chain of Custody Record #:

BIBI0610

Quality Assurance Data Level:

A B

A: Standard Summary
B: Standard + Chromatograms

Laboratory Turnaround Days:

10	5	3	2	1
----	---	---	---	---

Unocal STB
T/A

SAMPLE IDENTIFICATION	SAMPLING DATE/TIME	MATRIX (W,S,O)	# OF CONTAINERS
1. EX-B-1-5	9/27/01/1000	S	1
2. EX-B-2-5			
3. EX-B-3-5			
4. EX-B-4-5			
5. EX-B-5-5			
6. EX-B-6-5			
7. EX-B-7-5			
8. EX-B-8-5			
9. EX-B-9-5			
10. EX-B-10-5			

	OR	WA	AK	NW Series
TPH-HCID				
TPH-Gas				
BTEX				
EPA 8021 Mod.				
TPH-Gas + BTEX				
TPH-Diesel				
TPH-Diesel Extended				
TPH-Diesel-Ext. w/SG Cleanup				
Halogen. Volatiles EPA 8021				
Pesticides/PCBs or PCBs Only				
GC/MS Volatiles EPA 8260				
GC/MS SemiVolts. EPA 8270				
PAHs: EPA 8270 SIM or 8310				
Lead:				
Total or Dissolved TCLP or RCRA Metals (B)				
PAHs				

NCA SAMPLE NUMBER	
BIBI0610 - 01	01
	02
	03
	04
	05
	06
	07
	08
	09
	10

Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
1. <i>Abena Kuren</i>	NCA	9/27/01 15:15	<i>[Signature]</i>	NCA	9/27/01 13:00
2. <i>[Signature]</i>	NCA	9/27/01 15:15	<i>[Signature]</i>	NCA	9/27/01 15:15
3. <i>[Signature]</i>					

Final Report Approval

Were all requested results provided? yes no Define

Were results within requested turnaround? yes no "No" on back

Final Approval Signature: _____

Firm: _____ Date: _____



UNOCAL CHAIN OF CUSTODY REPORT

UNOCAL INFORMATION	
Facility Number:	Unocal Edmonds Terminal
Site Address:	11720 Unoco Road
City, State, ZIP:	Edmonds 98020
Site Release Number:	
Unocal Manager:	Mark Brearley
CERT INFO: (check one)	<input type="checkbox"/> Evaluation <input checked="" type="checkbox"/> Remediation <input type="checkbox"/> Detection <input type="checkbox"/> Demolition <input type="checkbox"/> Closure <input type="checkbox"/> Miscellaneous

CONSULTANT INFORMATION	
Firm:	Mani Foster & Alangi Project# 9077.001.004
Address:	17171 Bothell Way NE. #264 Seattle 98155
Phone:	744-1489
Fax:	744-0919
Project Manager:	L. Dawson
Sample Collection by:	R. Dyer

Chain of Custody Record #:

B10610

Quality Assurance Data Level:

A B

A: Standard Summary
Per Site QA
B: Standard + Chromatograms

Laboratory Turnaround Days:

10 5 3 2 1

SEE T/A

SAMPLE IDENTIFICATION	SAMPLING DATE/TIME	MATRIX (W,S,O)	# OF CONTAINERS
1. EX-A-1-4.5	9-27-01/1100	S	1
2. EX-A-2-4.5			
3. EX-A-3-4.5			
4. EX-A-4-4.5			
5. EX-A-5-4.5			
6. EX-A-6-4.5			
7. EX-A-7-4.5			
8. EX-A-8-4.5			
9. EX-A-9-4.5			
10. EX-A-10-4.5			

<input type="radio"/> OR <input type="radio"/> WA <input type="radio"/> AK <input checked="" type="radio"/> NW Series													
TPH-HCID	TPH-Gas	BTEX EPA 8021 Mod.	TPH-Gas + BTEX	TPH-Diesel	TPH-Diesel Extended	TPH-Diesel-Ext. w/SG Cleanup	Halogen. Volatiles EPA 8021	Pesticides/PCBs or PCBs Only	GC/MS Volatiles EPA 8260	GC/MS Semi Vols. EPA 8270	PAH's: EPA 8270 SIM or 8310	Lead:	Total or Dissolved TCLP or RCRA Metals (8)
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>
			<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>								<input checked="" type="checkbox"/>

NCA SAMPLE NUMBER
B10610-011
12
13
14
15
16
17
18
19
20

Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
1. [Signature]	NCA	9/27/01 15:05	[Signature]	NCA	9/27/01 15:05
2. [Signature]	NCA	9/27/01 15:15	[Signature]	NCA	9/27/01 15:15
3.					

Final Report Approval

Were all requested results provided? yes no Define

Were results within requested turnaround? yes no "No" on back

Final Approval Signature: _____

Firm: _____

Page 2 of 2
Rev. UNO3.3, 2/99

Comments: acid
① PAHs by 8270 SIM, incl 1 and 2-Me naphthalene

Distribution: White - Laboratory Yellow - Consultant Photocopy - Unocal


W/O 3.1



caTM
 North Creek Analytical, Inc.
 Environmental Laboratory Network
 www.ncalabs.com

11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8223
 East 11115 Montgomery, Suite B, Spokane, WA 98206-4776
 9405 S.W. Nimbus Avenue, Beaverton, OR 97008-7132
 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711

(425) 420-9200 FAX 420-9210
 (509) 924-9200 F/ -9290
 (503) 906-9200 F/ -9210
 (541) 383-9310 FAX 382-7588



UNOCAL CHAIN OF CUSTODY REPORT

UNOCAL INFORMATION

Facility Number: Unocal Edmonds Terminal
 Site Address: 11720 Unoco Road
 City, State, ZIP: Edmonds. 98020
 Site Release Number:
 Unocal Manager: Mark Bearley
 CERT INFO: (check one) Evaluation Remediation
 Detection Demolition Closure Miscellaneous

CONSULTANT INFORMATION

Firm: Man/Forest & Alongi Project# 9077.001.007
 Address: 17171 Bothell Way NE #264
Seattle 98155
 Phone: 744-1489 Fax: 744-0919
 Project Manager: L. Dawson
 Sample Collection by: R. Dyer

Chain of Custody Record #:
B110610
 Quality Assurance Data Level:
 A B
 A: Standard Summary
Per Site CPA
 B: Standard Chromatograms
 Laboratory Turnaround Days:
 10 5 3 2 1
Std T/A

SAMPLE IDENTIFICATION	SAMPLING DATE / TIME	MATRIX (W,S,O)	# OF CONTAINERS
1. <u>EX-A-11-4.5</u>	<u>9-27-01/1100</u>	<u>S</u>	<u>1</u>
2. <u>MW-DT-0901</u>	<u>9-27-01/1200</u>	<u>W</u>	<u>4</u>
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

	<input type="checkbox"/> OR	<input type="checkbox"/> WA	<input type="checkbox"/> AK	<input checked="" type="checkbox"/> NW Series
TPH-HCID				
TPH-Gas				
BTEX				
EPA 8021 Mod.				
TPH-Gas + BTEX				
TPH-Diesel				
TPH-Diesel <u>acid</u>				
TPH-Diesel <u>5/1100</u>				
TPH-Diesel-Ext. <u>cleaning</u>				
w/SG Cleanup				
Halogen. Volatiles				
EPA 8021				
Pesticides/PCBs or PCBs Only				
GC/MS Volatiles				
EPA 8260				
GC/MS SemiVols.				
EPA 8270				
PAH's: 8270 SIM or 8310				
Lead:				
Total or Dissolved TCLP or RCRA Metals (8)				
				<u>PAHs</u>

NCA SAMPLE NUMBER
B110610-222
22

Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
1. <u>Aura Lauren</u>	<u>NCA</u>	<u>9/27/01 15:15</u>	<u>[Signature]</u>	<u>NCA</u>	<u>9/27/01 13:25</u>
2. <u>[Signature]</u>	<u>NCA</u>	<u>9/27/01 15:15</u>	<u>[Signature]</u>	<u>NCA</u>	<u>9/27/01 15:15</u>
3.					

Final Report Approval

Were all requested results provided? yes no Define

Were results within requested turnaround? yes no "No" on back

Final Approval Signature: _____ Date: _____

Comments: @ PAHs by 8270 SIM, incl. 1- and 2- Methyl naphthalene
 Distribution: White - Laboratory Yellow - Consultant Photocopy - Unocal
 v/o 3.1




Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

20 November 2001

Linda Dawson
Maul Foster & Alongi-Seattle
17171 Bothell Way NE #264
Seattle, WA/USA 98155

RE: Former Bulk Storage of Edmonds



Enclosed are the results of analyses for samples received by the laboratory on 10/17/01 15:45. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Scott A. Woerman
Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

Case Narrative for B1J0473

Client: Maul Foster & Alongi - Seattle
Project Manager: Linda Dawson
Project Name: Former Bulk Storage of Edmonds
Project Number: 9077.001.004

1.0 DESCRIPTION OF CASE

Three soil samples were submitted on October 17, 2001, for one or all of the following analyses: Volatile Petroleum Products and BTEX by NWTPH-Gx/EPA 8021B, Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up and Polynuclear Aromatic Hydrocarbons by EPA 8270-SIM.

2.0 COMMENTS ON SAMPLE RECEIPT

The samples were received and logged in on October 17, 2001 at a temperature of 2.8°C. No anomalies were associated with sample receipt.

3.0 PREPARATION AND ANALYSIS

Volatile Petroleum Products and BTEX by NWTPH-Gx/EPA 8021B

No anomalies or discrepancies were associated with this analysis other than those already qualified in the data.

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up

No anomalies or discrepancies were associated with this analysis.

Polynuclear Aromatic Hydrocarbons by EPA 8270-SIM

No anomalies or discrepancies were associated with this analysis.

"I certify that this data package is in compliance with the Contract both technically and for completeness, other than the conditions detailed above. Release of the data in this hard copy data package has been authorized by the Laboratory Director, as verified by the following signature."

Scott A. Woerman
Project Manager
North Creek Analytical - Bothell



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.01.04
 Project Manager: Linda Dawson


Reported:
 11/20/01 13:28

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory	Laboratory ID	Matrix	Date Sampled	Date Received
EX-A-7A-4.5	North Creek Analytical - Bothell	B1J0473-01	Soil	10/16/01 14:10	10/17/01 15:45
EX-A-8A-4.5	North Creek Analytical - Bothell	B1J0473-02	Soil	10/16/01 14:14	10/17/01 15:45
EX-A-9A-4.5	North Creek Analytical - Bothell	B1J0473-03	Soil	10/16/01 14:18	10/17/01 15:45

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.01.04
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:28

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-7A-4.5 (B1J0473-01) Soil Sampled: 10/16/01 14:10 Received: 10/17/01 15:45										
Gasoline Range Hydrocarbons	1460		100 mg/kg dry		20	1J26016	10/26/01	10/27/01	NWTPH-Gx/ 8021B	
Benzene	1.32		0.600	"	"	"	"	"	"	
Toluene	ND		1.00	"	"	"	"	"	"	
Ethylbenzene	11.4		1.00	"	"	"	"	"	"	
Xylenes (total)	31.4		2.00	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	S-01
Surrogate: 4-BFB (PID)	%		54-123			"	"	"	"	S-01
EX-A-8A-4.5 (B1J0473-02) Soil Sampled: 10/16/01 14:14 Received: 10/17/01 15:45										
Gasoline Range Hydrocarbons	918		100 mg/kg dry		20	1J26016	10/26/01	10/27/01	NWTPH-Gx/ 8021B	
Benzene	3.13		0.600	"	"	"	"	"	"	
Toluene	1.11		1.00	"	"	"	"	"	"	
Ethylbenzene	12.8		1.00	"	"	"	"	"	"	
Xylenes (total)	69.8		2.00	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	S-01
Surrogate: 4-BFB (PID)	169 %		54-123			"	"	"	"	S-06
EX-A-9A-4.5 (B1J0473-03) Soil Sampled: 10/16/01 14:18 Received: 10/17/01 15:45										
Gasoline Range Hydrocarbons	19.4		5.00 mg/kg dry		1	1J26016	10/26/01	10/27/01	NWTPH-Gx/ 8021B	
Benzene	0.141		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.0641		0.0500	"	"	"	"	"	"	
Xylenes (total)	0.129		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	94.1 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	88.2 %		54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.01.04
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:28

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-7A-4.5 (B1J0473-01) Soil Sampled: 10/16/01 14:10 Received: 10/17/01 15:45										
Diesel Range Hydrocarbons	1770		110 mg/kg dry		11	1J24030	10/24/01	10/28/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		275	"	"	"	"	"	"	
Surrogate: 2-FBP	137 %		50-150			"	"	"	"	
Surrogate: Octacosane	89.3 %		50-150			"	"	"	"	
EX-A-8A-4.5 (B1J0473-02) Soil Sampled: 10/16/01 14:14 Received: 10/17/01 15:45										
Diesel Range Hydrocarbons	985		50.0 mg/kg dry		5	1J24030	10/24/01	10/28/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		125	"	"	"	"	"	"	
Surrogate: 2-FBP	116 %		50-150			"	"	"	"	
Surrogate: Octacosane	95.0 %		50-150			"	"	"	"	
EX-A-9A-4.5 (B1J0473-03) Soil Sampled: 10/16/01 14:18 Received: 10/17/01 15:45										
Diesel Range Hydrocarbons	ND		10.0 mg/kg dry		1	1J24030	10/24/01	10/28/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	81.3 %		50-150			"	"	"	"	
Surrogate: Octacosane	92.1 %		50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.01.04
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:28

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting		Dilution	Batch	Prepared	Analyzed	Method	Notes
			Limit	Units						
EX-A-7A-4.5 (B1J0473-01) Soil Sampled: 10/16/01 14:10 Received: 10/17/01 15:45										
Acenaphthene	0.23	0.028	0.20	mg/kg dry	20	1J26024	10/26/01	11/06/01	8270-SIM	
Acenaphthylene	ND	0.016	0.20	"	"	"	"	"	"	
Anthracene	ND	0.032	0.20	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.022	0.20	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.022	0.20	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.024	0.20	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.016	0.20	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.032	0.20	"	"	"	"	"	"	
Chrysene	ND	0.032	0.20	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.028	0.20	"	"	"	"	"	"	
Fluoranthene	0.065	0.020	0.20	"	"	"	"	"	"	J
Fluorene	1.0	0.022	0.20	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.038	0.20	"	"	"	"	"	"	
1-Methylnaphthalene	6.1	0.022	0.20	"	"	"	"	"	"	
2-Methylnaphthalene	12	0.016	0.20	"	"	"	"	"	"	
Naphthalene	5.0	0.028	0.20	"	"	"	"	"	"	
Phenanthrene	1.4	0.024	0.20	"	"	"	"	"	"	
Pyrene	0.16	0.0020	0.20	"	"	"	"	"	"	J
Surrogate: p-Terphenyl-d14	90 %		30-150			"	"	"	"	

EX-A-8A-4.5 (B1J0473-02) Soil Sampled: 10/16/01 14:14 Received: 10/17/01 15:45

Acenaphthene	0.19	0.014	0.10	mg/kg dry	10	1J26024	10/26/01	11/06/01	8270-SIM	
Acenaphthylene	0.079	0.0080	0.10	"	"	"	"	"	"	J
Anthracene	ND	0.016	0.10	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.011	0.10	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.011	0.10	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.012	0.10	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.0080	0.10	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.016	0.10	"	"	"	"	"	"	
Chrysene	ND	0.016	0.10	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.014	0.10	"	"	"	"	"	"	
Fluoranthene	0.044	0.010	0.10	"	"	"	"	"	"	J
Fluorene	0.66	0.011	0.10	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.019	0.10	"	"	"	"	"	"	
1-Methylnaphthalene	7.2	0.011	0.10	"	"	"	"	"	"	
2-Methylnaphthalene	12	0.0080	0.10	"	"	"	"	"	"	
Naphthalene	6.0	0.014	0.10	"	"	"	"	"	"	
Phenanthrene	1.4	0.012	0.10	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.01.04
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:28

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-8A-4.5 (B1J0473-02) Soil Sampled: 10/16/01 14:14 Received: 10/17/01 15:45										
Pyrene	0.15	0.0010	0.10	mg/kg dry	10	1J26024	10/26/01	11/06/01	8270-SIM	
Surrogate: <i>p</i> -Terphenyl- <i>d</i> 14	95 %		30-150			"	"	"	"	
EX-A-9A-4.5 (B1J0473-03) Soil Sampled: 10/16/01 14:18 Received: 10/17/01 15:45										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J26024	10/26/01	11/04/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	ND	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.078	0.0011	0.010	"	"	"	"	"	"	J
2-Methylnaphthalene	0.087	0.00080	0.010	"	"	"	"	"	"	J
Naphthalene	0.011	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	0.0044	0.0012	0.010	"	"	"	"	"	"	
Pyrene	0.0044	0.00010	0.010	"	"	"	"	"	"	
Surrogate: <i>p</i> -Terphenyl- <i>d</i> 14	82 %		30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.01.04 Project Manager: Linda Dawson	Reported: 11/20/01 13:28
--	--	-----------------------------

**Physical Parameters by APHA/ASTM/EPA Methods
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-A-7A-4.5 (B1J0473-01) Soil	Sampled: 10/16/01 14:10 Received: 10/17/01 15:45									
Dry Weight	81.4		1.00	%	1	1J22014	10/22/01	10/23/01	BSOPSPL00 3R07	
EX-A-8A-4.5 (B1J0473-02) Soil	Sampled: 10/16/01 14:14 Received: 10/17/01 15:45									
Dry Weight	75.7		1.00	%	1	1J22014	10/22/01	10/23/01	BSOPSPL00 3R07	
EX-A-9A-4.5 (B1J0473-03) Soil	Sampled: 10/16/01 14:18 Received: 10/17/01 15:45									
Dry Weight	76.2		1.00	%	1	1J22014	10/22/01	10/23/01	BSOPSPL00 3R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.01.04
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:28

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J26016: Prepared 10/26/01 Using EPA 5030B (MeOH)

Blank (1J26016-BLK1)

Gasoline Range Hydrocarbons	ND		5.00	mg/kg							
Benzene	ND		0.0300	"							
Toluene	ND		0.0500	"							
Ethylbenzene	ND		0.0500	"							
Xylenes (total)	ND		0.100	"							
Surrogate: 4-BFB (FID)	3.54			"	4.00		88.5	50-147			
Surrogate: 4-BFB (PID)	3.66			"	4.00		91.5	54-123			

LCS (1J26016-BS1)

Gasoline Range Hydrocarbons	22.5		5.00	mg/kg	25.0		90.0	80-120			
Surrogate: 4-BFB (FID)	3.72			"	4.00		93.0	50-147			

LCS (1J26016-BS2)

Benzene	0.439		0.0300	mg/kg	0.500		87.8	80-120			
Toluene	0.476		0.0500	"	0.500		95.2	80-120			
Ethylbenzene	0.495		0.0500	"	0.500		99.0	80-120			
Xylenes (total)	1.50		0.100	"	1.50		100	80-120			
Surrogate: 4-BFB (PID)	3.66			"	4.00		91.5	54-123			

LCS Dup (1J26016-BSD1)

Gasoline Range Hydrocarbons	25.1		5.00	mg/kg	25.0		100	80-120	10.9	40	
Surrogate: 4-BFB (FID)	3.77			"	4.00		94.2	50-147			

LCS Dup (1J26016-BSD2)

Benzene	0.447		0.0300	mg/kg	0.500		89.4	80-120	1.81	40	
Toluene	0.473		0.0500	"	0.500		94.6	80-120	0.632	40	
Ethylbenzene	0.495		0.0500	"	0.500		99.0	80-120	0.00	40	
Xylenes (total)	1.51		0.100	"	1.50		101	80-120	0.664	40	
Surrogate: 4-BFB (PID)	3.43			"	4.00		85.8	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.01.04 Project Manager: Linda Dawson	Reported: 11/20/01 13:28
--	--	-----------------------------

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J26016: Prepared 10/26/01 Using EPA 5030B (MeOH)

Matrix Spike (1J26016-MS1)		Source: B1J0574-01									
Gasoline Range Hydrocarbons	28.0		5.00 mg/kg dry		37.0	ND	71.2	53-120			
Surrogate: 4-BFB (FID)	4.40			"	5.92		74.3	50-147			


Matrix Spike (1J26016-MS2)		Source: B1J0574-18									
Benzene	0.499		0.0300 mg/kg dry		0.731	ND	68.3	64-130			
Toluene	0.561		0.0500	"	0.731	ND	76.7	66-130			
Ethylbenzene	0.582		0.0500	"	0.731	ND	79.6	72-130			
Xylenes (total)	1.76		0.100	"	2.19	ND	80.4	73-130			
Surrogate: 4-BFB (PID)	4.47			"	5.85		76.4	54-123			

Matrix Spike Dup (1J26016-MSD1)		Source: B1J0574-01									
Gasoline Range Hydrocarbons	35.8		5.00 mg/kg dry		37.0	ND	92.3	53-120	24.5	40	
Surrogate: 4-BFB (FID)	4.86			"	5.92		82.1	50-147			

Matrix Spike Dup (1J26016-MSD2)		Source: B1J0574-18									
Benzene	0.511		0.0300 mg/kg dry		0.731	ND	69.9	64-130	2.38	40	
Toluene	0.577		0.0500	"	0.731	ND	78.9	66-130	2.81	40	
Ethylbenzene	0.607		0.0500	"	0.731	ND	83.0	72-130	4.21	40	
Xylenes (total)	1.84		0.100	"	2.19	ND	84.0	73-130	4.44	40	
Surrogate: 4-BFB (PID)	4.59			"	5.85		78.5	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.01.04 Project Manager: Linda Dawson	Reported: 11/20/01 13:28
--	--	-----------------------------

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1J24030: Prepared 10/24/01 Using EPA 3550B											
Blank (1J24030-BLK1)											
Diesel Range Hydrocarbons	ND		10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND		25.0	"							
Surrogate: 2-FBP	10.2			"	10.7		95.3	50-150			
Surrogate: Octacosane	9.94			"	10.7		92.9	50-150			
LCS (1J24030-BS1)											
Diesel Range Hydrocarbons	56.6		10.0	mg/kg	66.7		84.9	50-150			
Surrogate: 2-FBP	9.72			"	10.7		90.8	50-150			
LCS Dup (1J24030-BSD1)											
Diesel Range Hydrocarbons	58.4		10.0	mg/kg	66.7		87.6	50-150	3.13	50	
Surrogate: 2-FBP	10.2			"	10.7		95.3	50-150			
Duplicate (1J24030-DUP1) Source: B1J0583-07											
Diesel Range Hydrocarbons	ND		10.0	mg/kg dry		ND			22.0	50	
Lube Oil Range Hydrocarbons	ND		25.0	"		ND			33.4	50	
Surrogate: 2-FBP	10.8			"	12.5		86.4	50-150			
Surrogate: Octacosane	10.5			"	12.5		84.0	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.01.04
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:28

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J26024: Prepared 10/26/01 Using EPA 3550B

Blank (1J26024-BLK1)

Acenaphthene	ND	0.0014	0.010	mg/kg							
Acenaphthylene	ND	0.00080	0.010	"							
Anthracene	ND	0.0016	0.010	"							
Benzo (a) anthracene	ND	0.0011	0.010	"							
Benzo (a) pyrene	ND	0.0011	0.010	"							
Benzo (b) fluoranthene	ND	0.0012	0.010	"							
Benzo (ghi) perylene	ND	0.00080	0.010	"							
Benzo (k) fluoranthene	ND	0.0016	0.010	"							
Chrysene	ND	0.0016	0.010	"							
Dibenz (a,h) anthracene	ND	0.0014	0.010	"							
Fluoranthene	ND	0.0010	0.010	"							
Fluorene	ND	0.0011	0.010	"							
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"							
1-Methylnaphthalene	ND	0.0011	0.010	"							
2-Methylnaphthalene	ND	0.00080	0.010	"							
Naphthalene	ND	0.0014	0.010	"							
Phenanthrene	ND	0.0012	0.010	"							
Pyrene	ND	0.00010	0.010	"							
<i>Surrogate: p-Terphenyl-d14</i>	<i>1.5</i>			"	<i>1.7</i>		<i>88</i>	<i>30-150</i>			

LCS (1J26024-BS1)

Chrysene	0.25	0.0016	0.010	mg/kg	0.33		76	10-125			
Fluorene	0.26	0.0011	0.010	"	0.33		79	11-116			
Indeno (1,2,3-cd) pyrene	0.24	0.0019	0.010	"	0.33		73	10-147			
<i>Surrogate: p-Terphenyl-d14</i>	<i>1.3</i>			"	<i>1.7</i>		<i>76</i>	<i>30-150</i>			

LCS Dup (1J26024-BSD1)

Chrysene	0.21	0.0016	0.010	mg/kg	0.33		64	10-125	17	28	
Fluorene	0.24	0.0011	0.010	"	0.33		73	11-116	8.0	32	
Indeno (1,2,3-cd) pyrene	0.20	0.0019	0.010	"	0.33		61	10-147	18	34	
<i>Surrogate: p-Terphenyl-d14</i>	<i>1.2</i>			"	<i>1.7</i>		<i>71</i>	<i>30-150</i>			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.01.04
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:28

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J26024: Prepared 10/26/01 Using EPA 3550B

Matrix Spike (1J26024-MS1)

Source: B1J0455-06

Chrysene	0.29	0.016	0.10mg/kg wet		0.33	ND	88	10-125			
Fluorene	0.26	0.011	0.10	"	0.33	ND	79	10-154			
Indeno (1,2,3-cd) pyrene	0.20	0.019	0.10	"	0.33	ND	61	10-144			
Surrogate: p-Terphenyl-d14	1.7			"	1.7		100	30-150			

Matrix Spike Dup (1J26024-MSD1)

Source: B1J0455-06

Chrysene	0.23	0.016	0.10mg/kg wet		0.33	ND	70	10-125	23	28	
Fluorene	0.25	0.011	0.10	"	0.33	ND	76	10-154	3.9	32	
Indeno (1,2,3-cd) pyrene	0.17	0.019	0.10	"	0.33	ND	52	10-144	16	47	
Surrogate: p-Terphenyl-d14	1.4			"	1.7		82	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588


Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.01.04 Project Manager: Linda Dawson	Reported: 11/20/01 13:28
--	--	-----------------------------

Physical Parameters by APHA/ASTM/EPA Methods - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1J22014: Prepared 10/22/01 Using Dry Weight											
Blank (1J22014-BLK1)											
Dry Weight	99.8		1.00	%							

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.01.04 Project Manager: Linda Dawson	Reported: 11/20/01 13:28
--	--	-----------------------------


Notes and Definitions

- J Estimated value.
- S-01 The surrogate recovery for this sample is not available due to sample dilution required from high analyte concentration and/or matrix interferences.
- S-06 The recovery of this surrogate is outside control limits due to sample dilution required from high analyte concentration and/or matrix interferences.
- DET Analyte DETECTED
- ND Analyte NOT DETECTED at or above the reporting limit
- NR Not Reported
- dry Sample results reported on a dry weight basis
- RPD Relative Percent Difference

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager



UNOCAL CHAIN OF CUSTODY REPORT 3100473

UNOCAL INFORMATION	
Facility Number: <u>Unocal Edmonds Terminal</u>	
Site Address: <u>11720 Unoco rd.</u>	
City, State, ZIP: <u>Edmonds, WA 98020</u>	
Site Release Number:	
Unocal Manager: <u>Mark Brearley</u>	
CERT INFO: (check one) <input type="checkbox"/> Evaluation <input checked="" type="checkbox"/> Remediation	
<input type="checkbox"/> Detection <input type="checkbox"/> Demolition <input type="checkbox"/> Closure <input type="checkbox"/> Miscellaneous	

CONSULTANT INFORMATION	
Firm: <u>Maul, Foster, + Alorgi</u>	Project# <u>9077.01.04</u>
Address: <u>17171 Bothell Way NE #264</u> <u>Seattle, WA 98155</u>	
Phone: <u>425-744-1489</u>	Fax: <u>744-0919</u>
Project Manager: <u>L. Dawson</u>	
Sample Collection by: <u>S. Anderson</u>	

Chain of Custody Record #:
Quality Assurance Data Level: <input type="checkbox"/> A <input checked="" type="checkbox"/> B A: Standard Summary <u>Per Site QA PP</u> B: Standard + Chromatograms
Laboratory Turnaround Days: <input type="checkbox"/> 10 <input type="checkbox"/> 5 <input type="checkbox"/> 3 <input type="checkbox"/> 2 <input type="checkbox"/> 1 <u>5-7/1A</u>

SAMPLE IDENTIFICATION	SAMPLING DATE/TIME	MATRIX (W,S,O)	# OF CONTAINERS	<input type="checkbox"/> OR <input type="checkbox"/> WA <input type="checkbox"/> AK <input checked="" type="checkbox"/> NW Series														NCA SAMPLE NUMBER		
				TPH-HCID	TPH-Gas	BTEX EPA 8021 Mod.	TPH-Gas + BTEX	TPH-Diesel	TPH-Diesel Extended	TPH-Diesel-Ext. w/SG Cleanup	Halogen. Volatiles EPA 8021	Pesticides/PCBs or PCBs Only	GC/MS Volatiles EPA 8260	GC/MS Semi Vols. EPA 8270	PAH's: 8270 SIM or 8310	Lead: Total or Dissolved TCLP or RCRA Metals (8)	PAH's (8)			
1. <u>Ex-A-7A-4.5</u>	<u>10-16-01 14:10</u>	<u>S</u>	<u>2</u>			X		X										X		<u>-01</u>
2. <u>Ex-A-8A-4.5</u>	<u>10-16-01 14:14</u>	<u>S</u>	<u>2</u>			X		X										X		<u>-02</u>
3. <u>Ex-A-9A-4.5</u>	<u>10-16-01 14:18</u>	<u>S</u>	<u>2</u>			X		X										X		<u>-03</u>
4.																				
5.																				
6.																				
7.																				
8.																				
9.																				
10.																				

Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
1. <u>Anna Lauer</u>	<u>NCA</u>	<u>10-17-01</u>	<u>Buell</u>	<u>NCA</u>	<u>10-17-01 14:45</u>
2. <u>Buell</u>		<u>10-17-01 15:45</u>	<u>Buell</u>		<u>10/17/01 15:45</u>
3.					

Final Report Approval	
Were all requested results provided?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no Define
Were results within requested turnaround?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no "No"
Final Approval Signature: _____ on back	
Firm: _____	Date: _____



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

20 November 2001

Linda Dawson
Maul Foster & Alongi-Seattle
17171 Bothell Way NE #264
Seattle, WA/USA 98155

RECEIVED
NOV 20 2001
BY: 9077.01.04

RE: Former Bulk Storage of Edmonds

Enclosed are the results of analyses for samples received by the laboratory on 09/18/01 15:40. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Scott A. Woerman
Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

Case Narrative for B1I0340

Client: Maul Foster & Alongi - Seattle
Project Manager: Linda Dawson
Project Name: Former Bulk Storage of Edmonds
Project Number: 9077.001.004

1.0 DESCRIPTION OF CASE

Five soil samples were submitted on September 18, 2001, for one or all of the following analyses: Volatile Petroleum Products and BTEX by NWTPH-Gx/EPA 8021B, Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up and Polynuclear Aromatic Hydrocarbons by EPA 8270-SIM.

2.0 COMMENTS ON SAMPLE RECEIPT

The samples were received and logged in on September 18, 2001 at a temperature of 22.5 °C. No anomalies were associated with sample receipt.

3.0 PREPARATION AND ANALYSIS

Volatile Petroleum Products and BTEX by NWTPH-Gx/EPA 8021B

No anomalies or discrepancies were associated with this analysis other than those already qualified in the data.

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up

No anomalies or discrepancies were associated with this analysis other than those already qualified in the data.

Polynuclear Aromatic Hydrocarbons by EPA 8270-SIM

No anomalies or discrepancies were observed while conducting this analysis.

"I certify that this data package is in compliance with the Contract both technically and for completeness, other than the conditions detailed above. Release of the data in this hard copy data package has been authorized by the Laboratory Director, as verified by the following signature."

Scott A. Woerman
Project Manager
North Creek Analytical - Bothell



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588


Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:46
--	--	-----------------------------

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory	Laboratory ID	Matrix	Date Sampled	Date Received
EX-C-1-4	North Creek Analytical - Bothell	B1I0340-01	Soil	09/18/01 14:00	09/18/01 15:40
EX-C-2-4	North Creek Analytical - Bothell	B1I0340-02	Soil	09/18/01 14:00	09/18/01 15:40
EX-C-3-4	North Creek Analytical - Bothell	B1I0340-03	Soil	09/18/01 14:00	09/18/01 15:40
EX-C-4-4	North Creek Analytical - Bothell	B1I0340-04	Soil	09/18/01 14:00	09/18/01 15:40
EX-C-5-4	North Creek Analytical - Bothell	B1I0340-05	Soil	09/18/01 14:00	09/18/01 15:40

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:46
--	--	-----------------------------

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-C-1-4 (B1I0340-01) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Gasoline Range Hydrocarbons	147		10.0 mg/kg dry		2	1126020	09/26/01	09/27/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0600	"	"	"	"	"	"	
Toluene	ND		0.100	"	"	"	"	"	"	
Ethylbenzene	0.169		0.100	"	"	"	"	"	"	
Xylenes (total)	1.01		0.200	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	89.7 %		50-147		"	"	"	"	"	
Surrogate: 4-BFB (PID)	77.7 %		54-123		"	"	"	"	"	
EX-C-2-4 (B1I0340-02) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Gasoline Range Hydrocarbons	257		5.00 mg/kg dry		1	1126020	09/26/01	09/27/01	NWTPH-Gx/ 8021B	G-01
Benzene	0.0721		0.0300	"	"	"	"	"	"	
Toluene	0.806		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.612		0.0500	"	"	"	"	"	"	
Xylenes (total)	4.96		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	101 %		50-147		"	"	"	"	"	
Surrogate: 4-BFB (PID)	82.3 %		54-123		"	"	"	"	"	
EX-C-3-4 (B1I0340-03) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Gasoline Range Hydrocarbons	11.0		5.00 mg/kg dry		1	1126020	09/26/01	09/26/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	79.2 %		50-147		"	"	"	"	"	
Surrogate: 4-BFB (PID)	84.8 %		54-123		"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:46

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-C-4-4 (B110340-04) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Gasoline Range Hydrocarbons	139		5.00	mg/kg dry	1	1126020	09/26/01	09/27/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	0.0810		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.133		0.0500	"	"	"	"	"	"	
Xylenes (total)	0.982		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	95.9 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	91.3 %		54-123			"	"	"	"	
EX-C-5-4 (B110340-05) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Gasoline Range Hydrocarbons	163		5.00	mg/kg dry	1	1126020	09/26/01	09/27/01	NWTPH-Gx/ 8021B	G-01
Benzene	0.0315		0.0300	"	"	"	"	"	"	
Toluene	0.155		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.275		0.0500	"	"	"	"	"	"	
Xylenes (total)	1.70		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	87.9 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	80.7 %		54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle: 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane: East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland: 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend: 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:46

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-C-1-4 (B1I0340-01) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Diesel Range Hydrocarbons	35100		2010	mg/kg dry	201	1I26026	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	10900		5020	"	"	"	"	"	"	
Surrogate: 2-FBP	%		50-150			"	"	"	"	S-01
Surrogate: Octacosane	%		50-150			"	"	"	"	S-01
EX-C-2-4 (B1I0340-02) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Diesel Range Hydrocarbons	30000		2010	mg/kg dry	201	1I26026	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	8520		5020	"	"	"	"	"	"	
Surrogate: 2-FBP	%		50-150			"	"	"	"	S-01
Surrogate: Octacosane	%		50-150			"	"	"	"	S-01
EX-C-3-4 (B1I0340-03) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Diesel Range Hydrocarbons	53.1		0.993	mg/kg dry	1	1I26026	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	16.1		2.48	"	"	"	"	"	"	
Surrogate: 2-FBP	81.3 %		50-150			"	"	"	"	
Surrogate: Octacosane	85.6 %		50-150			"	"	"	"	
EX-C-4-4 (B1I0340-04) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Diesel Range Hydrocarbons	16300		2010	mg/kg dry	201	1I26026	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		5020	"	"	"	"	"	"	
Surrogate: 2-FBP	%		50-150			"	"	"	"	S-01
Surrogate: Octacosane	%		50-150			"	"	"	"	S-01
EX-C-5-4 (B1I0340-05) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Diesel Range Hydrocarbons	23900		2010	mg/kg dry	201	1I26026	09/26/01	09/27/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	7000		5020	"	"	"	"	"	"	
Surrogate: 2-FBP	%		50-150			"	"	"	"	S-01
Surrogate: Octacosane	%		50-150			"	"	"	"	S-01

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:46

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----	-----------------	-------	----------	-------	----------	----------	--------	-------

EX-C-1-4 (B1I0340-01) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40

Acenaphthene	ND	0.035	0.25	mg/kg dry	25	1127033	09/27/01	09/30/01	8270-SIM	
Acenaphthylene	ND	0.020	0.25	"	"	"	"	"	"	
Anthracene	ND	0.040	0.25	"	"	"	"	"	"	
Benzo (a) anthracene	0.24	0.028	0.25	"	"	"	"	"	"	J
Benzo (a) pyrene	ND	0.028	0.25	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.030	0.25	"	"	"	"	"	"	
Benzo (ghi) perylene	0.12	0.020	0.25	"	"	"	"	"	"	J
Benzo (k) fluoranthene	ND	0.040	0.25	"	"	"	"	"	"	
Chrysene	1.3	0.040	0.25	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.035	0.25	"	"	"	"	"	"	
Fluoranthene	ND	0.025	0.25	"	"	"	"	"	"	
Fluorene	ND	0.028	0.25	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.048	0.25	"	"	"	"	"	"	
1-Methylnaphthalene	1.7	0.028	0.25	"	"	"	"	"	"	
2-Methylnaphthalene	2.4	0.020	0.25	"	"	"	"	"	"	
Naphthalene	0.89	0.035	0.25	"	"	"	"	"	"	
Phenanthrene	1.4	0.030	0.25	"	"	"	"	"	"	
Pyrene	1.5	0.0025	0.25	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	120 %		30-150			"	"	"	"	

EX-C-2-4 (B1I0340-02) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40

Acenaphthene	ND	0.035	0.25	mg/kg dry	25	1127033	09/27/01	09/30/01	8270-SIM	
Acenaphthylene	ND	0.020	0.25	"	"	"	"	"	"	
Anthracene	ND	0.040	0.25	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.028	0.25	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.028	0.25	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.030	0.25	"	"	"	"	"	"	
Benzo (ghi) perylene	0.45	0.020	0.25	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.040	0.25	"	"	"	"	"	"	
Chrysene	ND	0.040	0.25	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.035	0.25	"	"	"	"	"	"	
Fluoranthene	ND	0.025	0.25	"	"	"	"	"	"	
Fluorene	6.9	0.028	0.25	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.048	0.25	"	"	"	"	"	"	
1-Methylnaphthalene	25	0.028	0.25	"	"	"	"	"	"	
2-Methylnaphthalene	39	0.020	0.25	"	"	"	"	"	"	
Naphthalene	8.3	0.035	0.25	"	"	"	"	"	"	
Phenanthrene	15	0.030	0.25	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:46

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-C-2-4 (B1I0340-02) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Pyrene	3.0	0.0025	0.25	mg/kg dry	25	1I27033	09/27/01	09/30/01	8270-SIM	
Surrogate: p-Terphenyl-d14	86 %		30-150			"	"	"	"	
EX-C-3-4 (B1I0340-03) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Acenaphthene	ND	0.0028	0.020	mg/kg dry	2	1I27033	09/27/01	09/30/01	8270-SIM	
Acenaphthylene	ND	0.0016	0.020	"	"	"	"	"	"	
Anthracene	ND	0.0032	0.020	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0022	0.020	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0022	0.020	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0024	0.020	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.0016	0.020	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0032	0.020	"	"	"	"	"	"	
Chrysene	ND	0.0032	0.020	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0028	0.020	"	"	"	"	"	"	
Fluoranthene	ND	0.0020	0.020	"	"	"	"	"	"	
Fluorene	0.10	0.0022	0.020	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0038	0.020	"	"	"	"	"	"	
1-Methylnaphthalene	0.15	0.0022	0.020	"	"	"	"	"	"	
2-Methylnaphthalene	0.17	0.0016	0.020	"	"	"	"	"	"	
Naphthalene	ND	0.0028	0.020	"	"	"	"	"	"	
Phenanthrene	0.42	0.0024	0.020	"	"	"	"	"	"	
Pyrene	0.047	0.00020	0.020	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	100 %		30-150			"	"	"	"	
EX-C-4-4 (B1I0340-04) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Acenaphthene	ND	0.035	0.25	mg/kg dry	25	1I27033	09/27/01	09/30/01	8270-SIM	
Acenaphthylene	ND	0.020	0.25	"	"	"	"	"	"	
Anthracene	ND	0.040	0.25	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.028	0.25	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.028	0.25	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.030	0.25	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.020	0.25	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.040	0.25	"	"	"	"	"	"	
Chrysene	ND	0.040	0.25	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.035	0.25	"	"	"	"	"	"	
Fluoranthene	ND	0.025	0.25	"	"	"	"	"	"	
Fluorene	8.1	0.028	0.25	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.048	0.25	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:46

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----	-----------------	-------	----------	-------	----------	----------	--------	-------

EX-C-4-4 (B110340-04) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40

1-Methylnaphthalene	21	0.028	0.25	mg/kg dry	25	1I27033	09/27/01	09/30/01	8270-SIM	
2-Methylnaphthalene	30	0.020	0.25	"	"	"	"	"	"	
Naphthalene	ND	0.035	0.25	"	"	"	"	"	"	
Phenanthrene	25	0.030	0.25	"	"	"	"	"	"	
Pyrene	ND	0.0025	0.25	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	110 %		30-150			"	"	"	"	

EX-C-5-4 (B110340-05) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40

Acenaphthene	ND	0.035	0.25	mg/kg dry	25	1I27033	09/27/01	09/30/01	8270-SIM	
Acenaphthylene	ND	0.020	0.25	"	"	"	"	"	"	
Anthracene	ND	0.040	0.25	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.028	0.25	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.028	0.25	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.030	0.25	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.020	0.25	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.040	0.25	"	"	"	"	"	"	
Chrysene	ND	0.040	0.25	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.035	0.25	"	"	"	"	"	"	
Fluoranthene	ND	0.025	0.25	"	"	"	"	"	"	
Fluorene	ND	0.028	0.25	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.048	0.25	"	"	"	"	"	"	
1-Methylnaphthalene	2.9	0.028	0.25	"	"	"	"	"	"	
2-Methylnaphthalene	3.1	0.020	0.25	"	"	"	"	"	"	
Naphthalene	1.4	0.035	0.25	"	"	"	"	"	"	
Phenanthrene	ND	0.030	0.25	"	"	"	"	"	"	
Pyrene	ND	0.0025	0.25	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	120 %		30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:46

**Physical Parameters by APHA/ASTM/EPA Methods
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-C-1-4 (B1I0340-01) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Dry Weight	84.2		1.00	%	1	1I27005	09/27/01	09/28/01	BSOPSPLO0 3R07	
EX-C-2-4 (B1I0340-02) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Dry Weight	80.6		1.00	%	1	1I27005	09/27/01	09/28/01	BSOPSPLO0 3R07	
EX-C-3-4 (B1I0340-03) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Dry Weight	89.6		1.00	%	1	1I27005	09/27/01	09/28/01	BSOPSPLO0 3R07	
EX-C-4-4 (B1I0340-04) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Dry Weight	91.1		1.00	%	1	1I27005	09/27/01	09/28/01	BSOPSPLO0 3R07	
EX-C-5-4 (B1I0340-05) Soil Sampled: 09/18/01 14:00 Received: 09/18/01 15:40										
Dry Weight	83.2		1.00	%	1	1I27005	09/27/01	09/28/01	BSOPSPLO0 3R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:46
--	--	-----------------------------

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I26020: Prepared 09/26/01 Using EPA 5030B (MeOH)

Blank (1I26020-BLK1)

Gasoline Range Hydrocarbons	ND		5.00	mg/kg							
Benzene	ND		0.0300	"							
Toluene	ND		0.0500	"							
Ethylbenzene	ND		0.0500	"							
Xylenes (total)	ND		0.100	"							
Surrogate: 4-BFB (FID)	3.42			"	4.00		85.5	50-147			
Surrogate: 4-BFB (PID)	3.72			"	4.00		93.0	54-123			

LCS (1I26020-BS1)

Gasoline Range Hydrocarbons	22.9		5.00	mg/kg	25.0		91.6	80-120			
Surrogate: 4-BFB (FID)	3.68			"	4.00		92.0	50-147			

LCS (1I26020-BS2)

Benzene	0.464		0.0300	mg/kg	0.500		92.8	80-120			
Toluene	0.484		0.0500	"	0.500		96.8	80-120			
Ethylbenzene	0.499		0.0500	"	0.500		99.8	80-120			
Xylenes (total)	1.53		0.100	"	1.50		102	80-120			
Surrogate: 4-BFB (PID)	3.70			"	4.00		92.5	54-123			

LCS Dup (1I26020-BSD1)

Gasoline Range Hydrocarbons	21.5		5.00	mg/kg	25.0		86.0	80-120	6.31	40	
Surrogate: 4-BFB (FID)	3.42			"	4.00		85.5	50-147			

LCS Dup (1I26020-BSD2)

Benzene	0.463		0.0300	mg/kg	0.500		92.6	80-120	0.216	40	
Toluene	0.479		0.0500	"	0.500		95.8	80-120	1.04	40	
Ethylbenzene	0.498		0.0500	"	0.500		99.6	80-120	0.201	40	
Xylenes (total)	1.53		0.100	"	1.50		102	80-120	0.00	40	
Surrogate: 4-BFB (PID)	3.71			"	4.00		92.8	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.806.9200 fax 503.806.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:46

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I26020: Prepared 09/26/01 Using EPA 5030B (MeOH)

Matrix Spike (1I26020-MS1)

Source: B1I0340-03

Gasoline Range Hydrocarbons	26.3		5.00 mg/kg dry		27.9	11.0	54.8	53-120			
Surrogate: 4-BFB (FID)	3.82			"	4.47		85.5	50-147			

Matrix Spike (1I26020-MS2)

Source: B1I0457-24

Benzene	0.484		0.0300 mg/kg dry		0.562	0.0602	75.4	64-130			
Toluene	0.485		0.0500	"	0.562	ND	78.3	66-130			
Ethylbenzene	0.563		0.0500	"	0.562	0.193	65.8	72-130			Q-02
Xylenes (total)	1.76		0.100	"	1.69	0.674	64.3	73-130			Q-02
Surrogate: 4-BFB (PID)	3.78			"	4.50		84.0	54-123			

Matrix Spike Dup (1I26020-MSD1)

Source: B1I0340-03

Gasoline Range Hydrocarbons	28.0		5.00 mg/kg dry		27.9	11.0	60.9	53-120	6.26	40	
Surrogate: 4-BFB (FID)	3.78			"	4.47		84.6	50-147			

Matrix Spike Dup (1I26020-MSD2)

Source: B1I0457-24

Benzene	0.485		0.0300 mg/kg dry		0.562	0.0602	75.6	64-130	0.206	40	
Toluene	0.493		0.0500	"	0.562	ND	79.7	66-130	1.64	40	
Ethylbenzene	0.566		0.0500	"	0.562	0.193	66.4	72-130	0.531	40	Q-02
Xylenes (total)	1.77		0.100	"	1.69	0.674	64.9	73-130	0.567	40	Q-02
Surrogate: 4-BFB (PID)	3.78			"	4.50		84.0	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:46

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I26026: Prepared 09/26/01 Using EPA 3550B

Blank (1I26026-BLK1)

Diesel Range Hydrocarbons	ND		10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND		25.0	"							
Surrogate: 2-FBP	7.78			"	10.7		72.7	50-150			
Surrogate: Octacosane	8.54			"	10.7		79.8	50-150			

LCS (1I26026-BS1)

Diesel Range Hydrocarbons	55.9		10.0	mg/kg	66.7		83.8	50-150			
Surrogate: 2-FBP	8.05			"	10.7		75.2	50-150			

LCS Dup (1I26026-BSD1)

Diesel Range Hydrocarbons	57.4		10.0	mg/kg	66.7		86.1	50-150	2.65	50	
Surrogate: 2-FBP	7.89			"	10.7		73.7	50-150			

Duplicate (1I26026-DUP1)

Source: B110457-22

Diesel Range Hydrocarbons	2610		110	mg/kg dry		2890			10.2	50	
Lube Oil Range Hydrocarbons	835		275	"		938			11.6	50	
Surrogate: 2-FBP	18.3			"	12.7		144	50-150			
Surrogate: Octacosane	15.3			"	12.7		120	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woernman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:46

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I27033: Prepared 09/27/01 Using EPA 3550B

Blank (1I27033-BLK1)

Acenaphthene	ND	0.0014	0.010	mg/kg							
Acenaphthylene	ND	0.00080	0.010	"							
Anthracene	ND	0.0016	0.010	"							
Benzo (a) anthracene	ND	0.0011	0.010	"							
Benzo (a) pyrene	ND	0.0011	0.010	"							
Benzo (b) fluoranthene	ND	0.0012	0.010	"							
Benzo (ghi) perylene	ND	0.00080	0.010	"							
Benzo (k) fluoranthene	ND	0.0016	0.010	"							
Chrysene	ND	0.0016	0.010	"							
Dibenz (a,h) anthracene	ND	0.0014	0.010	"							
Fluoranthene	ND	0.0010	0.010	"							
Fluorene	ND	0.0011	0.010	"							
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"							
1-Methylnaphthalene	ND	0.0011	0.010	"							
2-Methylnaphthalene	ND	0.00080	0.010	"							
Naphthalene	ND	0.0014	0.010	"							
Phenanthrene	ND	0.0012	0.010	"							
Pyrene	ND	0.00010	0.010	"							

Surrogate: p-Terphenyl-d14	2.0			"	1.7		120	30-150			
----------------------------	-----	--	--	---	-----	--	-----	--------	--	--	--

LCS (1I27033-BS1)

Chrysene	0.30	0.0016	0.010	mg/kg	0.33		91	10-125			
Fluorene	0.33	0.0011	0.010	"	0.33		100	11-116			
Indeno (1,2,3-cd) pyrene	0.32	0.0019	0.010	"	0.33		97	10-147			

Surrogate: p-Terphenyl-d14	2.0			"	1.7		120	30-150			
----------------------------	-----	--	--	---	-----	--	-----	--------	--	--	--

LCS Dup (1I27033-BSD1)

Chrysene	0.31	0.0016	0.010	mg/kg	0.33		94	10-125	3.3	28	
Fluorene	0.32	0.0011	0.010	"	0.33		97	11-116	3.1	32	
Indeno (1,2,3-cd) pyrene	0.30	0.0019	0.010	"	0.33		91	10-147	6.5	34	

Surrogate: p-Terphenyl-d14	1.9			"	1.7		110	30-150			
----------------------------	-----	--	--	---	-----	--	-----	--------	--	--	--

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the terms of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:46
--	--	-----------------------------

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I27033: Prepared 09/27/01 Using EPA 3550B

Matrix Spike (1I27033-MS1)				Source: B1I0457-01							
Chrysene	0.40	0.0080	0.050 mg/kg dry	0.37	0.066	90	10-125				
Fluorene	1.0	0.0055	0.050 "	0.37	0.37	170	10-154				Q-01
Indeno (1,2,3-cd) pyrene	0.43	0.0095	0.050 "	0.37	ND	120	10-144				
Surrogate: p-Terphenyl-d14	2.2		"	1.8		120	30-150				

Matrix Spike Dup (1I27033-MSD1)				Source: B1I0457-01							
Chrysene	0.40	0.0080	0.050 mg/kg dry	0.37	0.066	90	10-125	0.0	28		
Fluorene	1.0	0.0055	0.050 "	0.37	0.37	170	10-154	0.0	32		Q-01
Indeno (1,2,3-cd) pyrene	0.46	0.0095	0.050 "	0.37	ND	120	10-144	6.7	47		
Surrogate: p-Terphenyl-d14	2.3		"	1.8		130	30-150				

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:46
--	--	-----------------------------

**Physical Parameters by APHA/ASTM/EPA Methods - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1I27005: Prepared 09/27/01 Using Dry Weight

Blank (1I27005-BLK1)

Dry Weight	100		1.00	%							
------------	-----	--	------	---	--	--	--	--	--	--	--

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

**North Creek Analytical, Inc.
 Environmental Laboratory Network**



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588


Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:46
--	--	-----------------------------

Notes and Definitions

- G-01 Results reported for the gas range are primarily due to overlap from diesel range hydrocarbons.
- J Estimated value.
- Q-01 The spike recovery for this QC sample is outside of established control limits. Review of associated batch QC indicates the recovery for this analyte does not represent an out-of-control condition for the batch.
- Q-02 The spike recovery for this QC sample is outside of NCA established control limits due to sample matrix interference.
- S-01 The surrogate recovery for this sample is not available due to sample dilution required from high analyte concentration and/or matrix interferences.
- DET Analyte DETECTED
- ND Analyte NOT DETECTED at or above the reporting limit
- NR Not Reported
- dry Sample results reported on a dry weight basis
- RPD Relative Percent Difference

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
Environmental Laboratory Network

BIO340

UNOCAL CHAIN OF CUSTODY REPORT

420-9200

UNOCAL INFORMATION

Facility Number: Unocal Edmonds Terminal

Site Address: 11720 Unoco Road

City, State, ZIP: Edmonds, WA 98020

Site Release Number:

Unocal Manager: Mark Breakley

CERT INFO: (check one) Evaluation Remediation Detection Demolition Closure Miscellaneous

CONSULTANT INFORMATION

Firm: Maul Foster & Alongi (MFA) Project Number: 9077.001.004

Address: 17171 Bothell Way NE #264
Seattle, 98155

Phone: (425) 744-1489 Fax: (425) 744-0919

Project Manager: Li Dawson

Sample Collection by: Randy Dyer

Chain of Custody Record #:

Quality Assurance Data Level:
 A B

A: Standard Summary
 Per Site QAPP
 B: Standard + Chromatograms

Laboratory Turnaround Days:
 10 5 3 2 1

Oregon Washington Hydrocarbon Methods MWTPH

TPH-HCID	TPH-Gas	BTEX (EPA 8020 Mod.)	TPH-Gas + BTEX (EPA 8020)	TPH-Diesel Extended (EPA 818.1)	Halogen. Volatiles (EPA 8010)	Aromatic Volatiles (EPA 8020)	Pesticides/PCBs or PCBs Only	GC/MS Volatiles (EPA 8240/8260)	GC/MS SemiVols. (EPA 8270)	PAHs by HPLC (EPA 8310)	Lead:	Total or Dissolved TCLP Metals (8)	PAH (2)
		X	X	X									X
		X	X	X									X
		X	X	X									X
		X	X	X									X
		X	X	X									X

SAMPLE IDENTIFICATION	SAMPLING DATE / TIME	MATRIX (W,S,O)	# OF CONTAINERS
1. EX-C-1-4	9/18/01 - 1400	S	1
2. EX-C-2-4	"	S	1
3. EX-C-3-4	"	S	1
4. EX-C-4-4	"	S	1
5. EX-C-5-4	"	S	1
6.			
7.			
8.			
9.			
10.			

NCA SAMPLE NUMBER
-01
-02
-03
-04
-05

	Relinquished by	Firm:	Date & Time	Received by:	Firm:	Date & Time
1.	<u>Randy Dyer</u>	<u>MFA</u>	<u>9/18/01</u>	<u>Randy Dyer</u>	<u>NCA</u>	<u>9/18/01 15:10</u>
2.	<u>[Signature]</u>	<u>NCA</u>	<u>9/18/01 15:40</u>	<u>[Signature]</u>	<u>NCA</u>	<u>9-18-01 15:40</u>
3.						

Final Report Approval

Were all requested results provided? yes no Define

Were results within requested turnaround? yes no "No"

Final Approval Signature: _____ on back

Firm: _____

Comments: PAHs by 8270 SIM, incl. 1- and 2-m. Inaphthalene

Distribution: White - Laboratory Yellow - Consultant Photocopy - Unocal

Samples were not @2-6C Upon Receipt


22-5° W/D



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

20 November 2001

Linda Dawson
Maul Foster & Alongi-Seattle
17171 Bothell Way NE #264
Seattle, WA/USA 98155



RE: Former Bulk Storage of Edmonds

Enclosed are the results of analyses for samples received by the laboratory on 09/26/01 17:55. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Scott A. Woerman
Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
425.420.9200 fax 425.420.9210
Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
509.924.9200 fax 509.924.9290
Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
503.906.9200 fax 503.906.9210
Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
541.383.9310 fax 541.382.7588

Case Narrative for B1I0558

Client: Maul Foster & Alongi - Seattle
Project Manager: Linda Dawson
Project Name: Former Bulk Storage of Edmonds
Project Number: 9077.001.004

1.0 DESCRIPTION OF CASE

Eleven soil samples were submitted on September 26, 2001, for one or all of the following analyses: Volatile Petroleum Products and BTEX by NWTPH-Gx/EPA 8021B, Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up and Polynuclear Aromatic Hydrocarbons by EPA 8270-SIM.

2.0 COMMENTS ON SAMPLE RECEIPT

The samples were received on September 25, 2001 and logged in on September 26, 2001 at a temperature of 10.9°C. No anomalies were associated with sample receipt.

3.0 PREPARATION AND ANALYSIS

Volatile Petroleum Products and BTEX by NWTPH-Gx/EPA 8021B

No anomalies or discrepancies were associated with this analysis other than those already qualified in the data.

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up


The surrogate, 2-FBP, fell outside of its established QC limits in samples EX-D-2-3.5 and EX-D-7-3.5. In addition to 2-FBP, the surrogate Octacosane fell outside of its established QC limits in sample EX-D-4-3.5. As a consequence, the samples were re-extracted and re-analyzed, but were done so outside of the EPA's recommended holding time. Both the initial and re-extract data are reported as a result.

No additional anomalies or discrepancies were associated with this analysis other than those already qualified in the data.

Polynuclear Aromatic Hydrocarbons by EPA 8270-SIM

No anomalies or discrepancies were associated with this analysis.

"I certify that this data package is in compliance with the Contract both technically and for completeness, other than the conditions detailed above. Release of the data in this hard copy data package has been authorized by the Laboratory Director, as verified by the following signature."


Scott A. Woerman
Project Manager
North Creek Analytical - Bothell



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory	Laboratory ID	Matrix	Date Sampled	Date Received
TP-18-5.8-S	North Creek Analytical - Bothell	B1I0558-01	Soil	09/25/01 10:00	09/26/01 17:55
TP-19-5.8-S	North Creek Analytical - Bothell	B1I0558-02	Soil	09/25/01 10:00	09/26/01 17:55
TP-22-5.8-S	North Creek Analytical - Bothell	B1I0558-03	Soil	09/25/01 10:00	09/26/01 17:55
TP-20-5.8-E	North Creek Analytical - Bothell	B1I0558-04	Soil	09/26/01 10:00	09/26/01 17:55
EX-D-1-3.5	North Creek Analytical - Bothell	B1I0558-05	Soil	09/26/01 10:00	09/26/01 17:55
EX-D-2-3.5	North Creek Analytical - Bothell	B1I0558-06	Soil	09/26/01 12:00	09/26/01 17:55
EX-D-3-3.5	North Creek Analytical - Bothell	B1I0558-07	Soil	09/26/01 12:00	09/26/01 17:55
EX-D-4-3.5	North Creek Analytical - Bothell	B1I0558-08	Soil	09/26/01 12:00	09/26/01 17:55
EX-D-5-3.5	North Creek Analytical - Bothell	B1I0558-09	Soil	09/26/01 12:00	09/26/01 17:55
EX-D-6-3.5	North Creek Analytical - Bothell	B1I0558-10	Soil	09/26/01 12:00	09/26/01 17:55
EX-D-7-3.5	North Creek Analytical - Bothell	B1I0558-11	Soil	09/26/01 12:00	09/26/01 17:55

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.


 Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
TP-18-5.8-S (B110558-01) Soil Sampled: 09/25/01 10:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	1590		100	mg/kg dry	20	1J02038	10/02/01	10/06/01	NWTPH-Gx/ 8021B	
Benzene	0.734		0.600	"	"	"	"	"	"	I-06
Toluene	ND		1.00	"	"	"	"	"	"	
Ethylbenzene	2.28		1.00	"	"	"	"	"	"	I-06
Xylenes (total)	5.27		2.00	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	S-01
Surrogate: 4-BFB (PID)	190 %		54-123			"	"	"	"	S-06
TP-19-5.8-S (B110558-02) Soil Sampled: 09/25/01 10:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	687		50.0	mg/kg dry	10	1J02038	10/02/01	10/06/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.300	"	"	"	"	"	"	
Toluene	ND		0.500	"	"	"	"	"	"	
Ethylbenzene	0.557		0.500	"	"	"	"	"	"	I-06
Xylenes (total)	2.36		1.00	"	"	"	"	"	"	6
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	S-01
Surrogate: 4-BFB (PID)	144 %		54-123			"	"	"	"	S-06
TP-22-5.8-S (B110558-03) Soil Sampled: 09/25/01 10:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	1160		100	mg/kg dry	20	1J02038	10/02/01	10/06/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.600	"	"	"	"	"	"	
Toluene	ND		1.00	"	"	"	"	"	"	
Ethylbenzene	1.33		1.00	"	"	"	"	"	"	I-06
Xylenes (total)	3.58		2.00	"	"	"	"	"	"	I-06
Surrogate: 4-BFB (FID)	%		50-147			"	"	"	"	S-01
Surrogate: 4-BFB (PID)	189 %		54-123			"	"	"	"	S-06

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety. of

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:33
--	--	-----------------------------

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
TP-20-5.8-E (B1I0558-04) Soil Sampled: 09/26/01 10:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	51.6		5.00	mg/kg dry	1	1J02038	10/02/01	10/06/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	78.1 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	87.8 %		54-123			"	"	"	"	
EX-D-1-3.5 (B1I0558-05) Soil Sampled: 09/26/01 10:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	76.1		5.00	mg/kg dry	1	1J02038	10/02/01	10/06/01	NWTPH-Gx/ 8021B	G-01
Benzene	0.352		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.565		0.0500	"	"	"	"	"	"	
Xylenes (total)	0.534		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	85.9 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	85.9 %		54-123			"	"	"	"	
EX-D-2-3.5 (B1I0558-06) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	11.0		5.00	mg/kg dry	1	1J02038	10/02/01	10/06/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	84.6 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	88.9 %		54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

North Creek Analytical, Inc.
 Environmental Laboratory Network

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-D-3-3.5 (B1I0558-07) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	64.3		5.00	mg/kg dry	1	1J02038	10/02/01	10/04/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	0.0560		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.0518		0.0500	"	"	"	"	"	"	
Xylenes (total)	0.138		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	94.1 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	90.6 %		54-123			"	"	"	"	
EX-D-4-3.5 (B1I0558-08) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	7.11		5.00	mg/kg dry	1	1J02038	10/02/01	10/04/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	0.240		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.0973		0.0500	"	"	"	"	"	"	
Xylenes (total)	0.488		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	87.0 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	89.7 %		54-123			"	"	"	"	
EX-D-5-3.5 (B1I0558-09) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	8.93		5.00	mg/kg dry	1	1J02038	10/02/01	10/06/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	76.8 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	80.3 %		54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-D-6-3.5 (B110558-10) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	104		5.00	mg/kg dry	1	1J02038	10/02/01	10/06/01	NWTPH-Gx/ 8021B	G-01
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	0.219		0.0500	"	"	"	"	"	"	I-06
Xylenes (total)	0.950		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	119 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	94.4 %		54-123			"	"	"	"	
EX-D-7-3.5 (B110558-11) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Gasoline Range Hydrocarbons	ND		5.00	mg/kg dry	1	1J02038	10/02/01	10/06/01	NWTPH-Gx/ 8021B	
Benzene	ND		0.0300	"	"	"	"	"	"	
Toluene	ND		0.0500	"	"	"	"	"	"	
Ethylbenzene	ND		0.0500	"	"	"	"	"	"	
Xylenes (total)	ND		0.100	"	"	"	"	"	"	
Surrogate: 4-BFB (FID)	85.3 %		50-147			"	"	"	"	
Surrogate: 4-BFB (PID)	93.9 %		54-123			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
TP-18-5.8-S (B1I0558-01) Soil Sampled: 09/25/01 10:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	13600		410	mg/kg dry	41	1J05042	10/05/01	10/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	1240		1020	"	"	"	"	"	"	
Surrogate: 2-FBP	%		50-150			"	"	"	"	S-01
Surrogate: Octacosane	95.0 %		50-150			"	"	"	"	
TP-19-5.8-S (B1I0558-02) Soil Sampled: 09/25/01 10:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	12300		410	mg/kg dry	41	1J05042	10/05/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	1130		1020	"	"	"	"	"	"	
Surrogate: 2-FBP	%		50-150			"	"	"	"	S-01
Surrogate: Octacosane	82.8 %		50-150			"	"	"	"	
TP-22-5.8-S (B1I0558-03) Soil Sampled: 09/25/01 10:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	11100		410	mg/kg dry	41	1J05042	10/05/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	1370		1020	"	"	"	"	"	"	
Surrogate: 2-FBP	%		50-150			"	"	"	"	S-01
Surrogate: Octacosane	81.0 %		50-150			"	"	"	"	
TP-20-5.8-E (B1I0558-04) Soil Sampled: 09/26/01 10:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	5030		410	mg/kg dry	41	1J05042	10/05/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		1020	"	"	"	"	"	"	
Surrogate: 2-FBP	134 %		50-150			"	"	"	"	
Surrogate: Octacosane	83.2 %		50-150			"	"	"	"	
EX-D-1-3.5 (B1I0558-05) Soil Sampled: 09/26/01 10:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	2940		210	mg/kg dry	21	1J05042	10/05/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	851		525	"	"	"	"	"	"	
Surrogate: 2-FBP	97.7 %		50-150			"	"	"	"	
Surrogate: Octacosane	82.4 %		50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-D-2-3.5 (B1I0558-06) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	955		50.0 mg/kg dry		5	1J05042	10/05/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	275		125	"	"	"	"	"	"	
Surrogate: 2-FBP	48.4 %		50-150			"	"	"	"	X
Surrogate: Octacosane	80.7 %		50-150			"	"	"	"	
EX-D-2-3.5 (B1I0558-06RE1) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55 Q-29										
Diesel Range Hydrocarbons	766		10.0 mg/kg dry		1	1J16038	10/16/01	10/19/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	198		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	68.7 %		50-150			"	"	"	"	
Surrogate: Octacosane	97.4 %		50-150			"	"	"	"	
EX-D-3-3.5 (B1I0558-07) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	4390		210 mg/kg dry		21	1J05042	10/05/01	10/13/01	NWTPH-Dx	
Oil Range Hydrocarbons	1390		525	"	"	"	"	"	"	
Surrogate: 2-FBP	135 %		50-150			"	"	"	"	
Surrogate: Octacosane	80.1 %		50-150			"	"	"	"	
EX-D-4-3.5 (B1I0558-08) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	11.7		10.0 mg/kg dry		1	1J05042	10/05/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	%		50-150			"	"	"	"	X
Surrogate: Octacosane	%		50-150			"	"	"	"	X
EX-D-4-3.5 (B1I0558-08RE1) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55 Q-29										
Diesel Range Hydrocarbons	68.3		10.0 mg/kg dry		1	1J16038	10/16/01	10/20/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	ND		25.0	"	"	"	"	"	"	
Surrogate: 2-FBP	82.4 %		50-150			"	"	"	"	
Surrogate: Octacosane	106 %		50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

**Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-D-5-3.5 (B1I0558-09) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	254		10.0 mg/kg dry		1	1J05042	10/05/01	10/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	214		25.0 "		"	"	"	"	"	
Surrogate: 2-FBP	56.9 %		50-150			"	"	"	"	
Surrogate: Octacosane	86.6 %		50-150			"	"	"	"	
EX-D-6-3.5 (B1I0558-10) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	712		10.0 mg/kg dry		1	1J05042	10/05/01	10/12/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	291		25.0 "		"	"	"	"	"	
Surrogate: 2-FBP	110 %		50-150			"	"	"	"	
Surrogate: Octacosane	112 %		50-150			"	"	"	"	
EX-D-7-3.5 (B1I0558-11) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	105		10.0 mg/kg dry		1	1J05042	10/05/01	10/13/01	NWTPH-Dx	
Lube Oil Range Hydrocarbons	36.6		25.0 "		"	"	"	"	"	
Surrogate: 2-FBP	46.3 %		50-150			"	"	"	"	X
Surrogate: Octacosane	75.3 %		50-150			"	"	"	"	
EX-D-7-3.5 (B1I0558-11RE1) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Diesel Range Hydrocarbons	125		10.0 mg/kg dry		1	1J16038	10/16/01	10/19/01	NWTPH-Dx	Q-29
Lube Oil Range Hydrocarbons	43.6		25.0 "		"	"	"	"	"	
Surrogate: 2-FBP	75.3 %		50-150			"	"	"	"	
Surrogate: Octacosane	110 %		50-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
TP-18-5.8-S (B1I0558-01) Soil Sampled: 09/25/01 10:00 Received: 09/26/01 17:55										
Acenaphthene	1.5	0.14	1.0	mg/kg dry	100	1J08018	10/08/01	10/11/01	8270-SIM	
Acenaphthylene	0.60	0.080	1.0	"	"	"	"	"	"	J
Anthracene	1.1	0.16	1.0	"	"	"	"	"	"	J
Benzo (a) anthracene	0.82	0.11	1.0	"	"	"	"	"	"	J
Benzo (a) pyrene	ND	0.11	1.0	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.12	1.0	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.080	1.0	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.16	1.0	"	"	"	"	"	"	
Chrysene	1.1	0.16	1.0	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.14	1.0	"	"	"	"	"	"	
Fluoranthene	0.52	0.10	1.0	"	"	"	"	"	"	J
Fluorene	5.8	0.11	1.0	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.19	1.0	"	"	"	"	"	"	
1-Methylnaphthalene	60	0.11	1.0	"	"	"	"	"	"	
2-Methylnaphthalene	110	0.080	1.0	"	"	"	"	"	"	
Naphthalene	0.75	0.14	1.0	"	"	"	"	"	"	J
Phenanthrene	13	0.12	1.0	"	"	"	"	"	"	
Pyrene	1.9	0.010	1.0	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	84 %		30-150			"	"	"	"	

TP-19-5.8-S (B1I0558-02) Soil Sampled: 09/25/01 10:00 Received: 09/26/01 17:55										
Acenaphthene	1.4	0.070	0.50	mg/kg dry	50	1J08018	10/08/01	10/10/01	8270-SIM	
Acenaphthylene	0.80	0.040	0.50	"	"	"	"	"	"	
Anthracene	ND	0.080	0.50	"	"	"	"	"	"	J
Benzo (a) anthracene	0.29	0.055	0.50	"	"	"	"	"	"	J
Benzo (a) pyrene	0.15	0.055	0.50	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.060	0.50	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.040	0.50	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.080	0.50	"	"	"	"	"	"	
Chrysene	0.51	0.080	0.50	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.070	0.50	"	"	"	"	"	"	
Fluoranthene	0.55	0.050	0.50	"	"	"	"	"	"	
Fluorene	5.6	0.055	0.50	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.095	0.50	"	"	"	"	"	"	
1-Methylnaphthalene	41	0.055	0.50	"	"	"	"	"	"	
2-Methylnaphthalene	46	0.040	0.50	"	"	"	"	"	"	
Naphthalene	0.62	0.070	0.50	"	"	"	"	"	"	
Phenanthrene	8.3	0.060	0.50	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
TP-19-5.8-S (B1I0558-02) Soil Sampled: 09/25/01 10:00 Received: 09/26/01 17:55										
Pyrene	0.84	0.0050	0.50	mg/kg dry	50	1J08018	10/08/01	10/10/01	8270-SIM	
Surrogate: p-Terphenyl-d14	78 %		30-150			"	"	"	"	
TP-22-5.8-S (B1I0558-03) Soil Sampled: 09/25/01 10:00 Received: 09/26/01 17:55										
Acenaphthene	1.8	0.14	1.0	mg/kg dry	100	1J08018	10/08/01	10/11/01	8270-SIM	
Acenaphthylene	ND	0.080	1.0	"	"	"	"	"	"	
Anthracene	ND	0.16	1.0	"	"	"	"	"	"	
Benzo (a) anthracene	0.31	0.11	1.0	"	"	"	"	"	"	J
Benzo (a) pyrene	ND	0.11	1.0	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.12	1.0	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.080	1.0	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.16	1.0	"	"	"	"	"	"	
Chrysene	0.69	0.16	1.0	"	"	"	"	"	"	J
Dibenz (a,h) anthracene	ND	0.14	1.0	"	"	"	"	"	"	
Fluoranthene	0.31	0.10	1.0	"	"	"	"	"	"	J
Fluorene	6.9	0.11	1.0	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.19	1.0	"	"	"	"	"	"	
1-Methylnaphthalene	62	0.11	1.0	"	"	"	"	"	"	
2-Methylnaphthalene	100	0.080	1.0	"	"	"	"	"	"	
Naphthalene	0.85	0.14	1.0	"	"	"	"	"	"	J
Phenanthrene	10	0.12	1.0	"	"	"	"	"	"	
Pyrene	0.85	0.010	1.0	"	"	"	"	"	"	J
Surrogate: p-Terphenyl-d14	79 %		30-150			"	"	"	"	
TP-20-5.8-E (B1I0558-04) Soil Sampled: 09/26/01 10:00 Received: 09/26/01 17:55										
Acenaphthene	0.31	0.014	0.10	mg/kg dry	10	1J08018	10/08/01	10/11/01	8270-SIM	
Acenaphthylene	ND	0.0080	0.10	"	"	"	"	"	"	
Anthracene	0.25	0.016	0.10	"	"	"	"	"	"	
Benzo (a) anthracene	0.62	0.011	0.10	"	"	"	"	"	"	
Benzo (a) pyrene	0.54	0.011	0.10	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.012	0.10	"	"	"	"	"	"	
Benzo (ghi) perylene	0.19	0.0080	0.10	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.016	0.10	"	"	"	"	"	"	
Chrysene	0.84	0.016	0.10	"	"	"	"	"	"	
Dibenz (a,h) anthracene	0.15	0.014	0.10	"	"	"	"	"	"	
Fluoranthene	0.25	0.010	0.10	"	"	"	"	"	"	
Fluorene	0.54	0.011	0.10	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	0.078	0.019	0.10	"	"	"	"	"	"	J

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
TP-20-5.8-E (B1I0558-04) Soil Sampled: 09/26/01 10:00 Received: 09/26/01 17:55										
1-Methylnaphthalene	ND	0.011	0.10	mg/kg dry	10	1J08018	10/08/01	10/11/01	8270-SIM	
2-Methylnaphthalene	ND	0.0080	0.10	"	"	"	"	"	"	
Naphthalene	ND	0.014	0.10	"	"	"	"	"	"	
Phenanthrene	ND	0.012	0.10	"	"	"	"	"	"	
Pyrene	2.7	0.0010	0.10	"	"	"	"	"	"	
Surrogate: <i>p</i> -Terphenyl-d14	83 %		30-150			"	"	"	"	
EX-D-1-3.5 (B1I0558-05) Soil Sampled: 09/26/01 10:00 Received: 09/26/01 17:55										
Acenaphthene	0.080	0.0028	0.020	mg/kg dry	2	1J08018	10/08/01	10/11/01	8270-SIM	
Acenaphthylene	ND	0.0016	0.020	"	"	"	"	"	"	
Anthracene	ND	0.0032	0.020	"	"	"	"	"	"	
Benzo (a) anthracene	0.080	0.0022	0.020	"	"	"	"	"	"	
Benzo (a) pyrene	0.052	0.0022	0.020	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0024	0.020	"	"	"	"	"	"	
Benzo (ghi) perylene	0.043	0.0016	0.020	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0032	0.020	"	"	"	"	"	"	
Chrysene	0.26	0.0032	0.020	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0028	0.020	"	"	"	"	"	"	
Fluoranthene	ND	0.0020	0.020	"	"	"	"	"	"	
Fluorene	0.40	0.0022	0.020	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0038	0.020	"	"	"	"	"	"	
1-Methylnaphthalene	0.93	0.0022	0.020	"	"	"	"	"	"	
2-Methylnaphthalene	0.48	0.0016	0.020	"	"	"	"	"	"	
Naphthalene	0.21	0.0028	0.020	"	"	"	"	"	"	
Phenanthrene	0.61	0.0024	0.020	"	"	"	"	"	"	
Pyrene	0.56	0.00020	0.020	"	"	"	"	"	"	
Surrogate: <i>p</i> -Terphenyl-d14	90 %		30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-D-2-3.5 (B1I0558-06) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Acenaphthene	0.012	0.0028	0.020	mg/kg dry	2	1J08018	10/08/01	10/11/01	8270-SIM	J
Acenaphthylene	ND	0.0016	0.020	"	"	"	"	"	"	
Anthracene	0.051	0.0032	0.020	"	"	"	"	"	"	
Benzo (a) anthracene	0.038	0.0022	0.020	"	"	"	"	"	"	
Benzo (a) pyrene	0.020	0.0022	0.020	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0024	0.020	"	"	"	"	"	"	
Benzo (ghi) perylene	0.013	0.0016	0.020	"	"	"	"	"	"	J
Benzo (k) fluoranthene	ND	0.0032	0.020	"	"	"	"	"	"	
Chrysene	0.084	0.0032	0.020	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0028	0.020	"	"	"	"	"	"	
Fluoranthene	0.046	0.0020	0.020	"	"	"	"	"	"	
Fluorene	0.064	0.0022	0.020	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.0038	0.020	"	"	"	"	"	"	
1-Methylnaphthalene	0.020	0.0022	0.020	"	"	"	"	"	"	
2-Methylnaphthalene	0.016	0.0016	0.020	"	"	"	"	"	"	J
Naphthalene	ND	0.0028	0.020	"	"	"	"	"	"	
Phenanthrene	0.22	0.0024	0.020	"	"	"	"	"	"	
Pyrene	0.13	0.00020	0.020	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	94 %		30-150			"	"	"	"	

EX-D-3-3.5 (B1I0558-07) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Acenaphthene	0.16	0.035	0.25	mg/kg dry	25	1J08018	10/08/01	10/10/01	8270-SIM	J
Acenaphthylene	ND	0.020	0.25	"	"	"	"	"	"	
Anthracene	0.22	0.040	0.25	"	"	"	"	"	"	J
Benzo (a) anthracene	0.13	0.028	0.25	"	"	"	"	"	"	J
Benzo (a) pyrene	ND	0.028	0.25	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.030	0.25	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.020	0.25	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.040	0.25	"	"	"	"	"	"	
Chrysene	0.37	0.040	0.25	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.035	0.25	"	"	"	"	"	"	
Fluoranthene	0.16	0.025	0.25	"	"	"	"	"	"	J
Fluorene	0.68	0.028	0.25	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.048	0.25	"	"	"	"	"	"	
1-Methylnaphthalene	1.4	0.028	0.25	"	"	"	"	"	"	
2-Methylnaphthalene	1.2	0.020	0.25	"	"	"	"	"	"	
Naphthalene	0.11	0.035	0.25	"	"	"	"	"	"	J
Phenanthrene	2.1	0.030	0.25	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-D-3-3.5 (B110558-07) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Pyrene	0.57	0.0025	0.25 mg/kg dry		25	1J08018	10/08/01	10/10/01	8270-SIM	
Surrogate: p-Terphenyl-d14	83 %		30-150			"	"	"	"	
EX-D-4-3.5 (B110558-08) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Acenaphthene	ND	0.0014	0.010 mg/kg dry		1	1J08018	10/08/01	10/11/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	0.0030	0.0011	0.010	"	"	"	"	"	"	J
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	0.0030	0.0016	0.010	"	"	"	"	"	"	J
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	J
Fluorene	0.0022	0.0011	0.010	"	"	"	"	"	"	J
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-Methylnaphthalene	0.016	0.0011	0.010	"	"	"	"	"	"	
2-Methylnaphthalene	0.016	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	J
Phenanthrene	0.0067	0.0012	0.010	"	"	"	"	"	"	J
Pyrene	0.0067	0.00010	0.010	"	"	"	"	"	"	J
Surrogate: p-Terphenyl-d14	68 %		30-150			"	"	"	"	
EX-D-5-3.5 (B110558-09) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Acenaphthene	0.018	0.0014	0.010 mg/kg dry		1	1J08018	10/08/01	10/11/01	8270-SIM	
Acenaphthylene	0.047	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	0.034	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	0.025	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	0.025	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	0.10	0.0016	0.010	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	0.071	0.0011	0.010	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	0.020	0.0019	0.010	"	"	"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

North Creek Analytical, Inc.
 Environmental Laboratory Network

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:33
--	--	-----------------------------

**Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
---------	--------	-----	-----------------	-------	----------	-------	----------	----------	--------	-------

EX-D-5-3.5 (B1I0558-09) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55

1-Methylnaphthalene	0.065	0.0011	0.010	mg/kg dry	1	1J08018	10/08/01	10/11/01	8270-SIM	
2-Methylnaphthalene	0.052	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	0.018	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	0.23	0.0012	0.010	"	"	"	"	"	"	
Pyrene	0.11	0.00010	0.010	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	75 %		30-150			"	"	"	"	

EX-D-6-3.5 (B1I0558-10) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55

Acenaphthene	0.21	0.035	0.25	mg/kg dry	25	1J08018	10/08/01	10/10/01	8270-SIM	J
Acenaphthylene	0.097	0.020	0.25	"	"	"	"	"	"	J
Anthracene	0.54	0.040	0.25	"	"	"	"	"	"	
Benzo (a) anthracene	0.19	0.028	0.25	"	"	"	"	"	"	J
Benzo (a) pyrene	0.078	0.028	0.25	"	"	"	"	"	"	J
Benzo (b) fluoranthene	ND	0.030	0.25	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.020	0.25	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.040	0.25	"	"	"	"	"	"	
Chrysene	0.37	0.040	0.25	"	"	"	"	"	"	
Dibenz (a,h) anthracene	ND	0.035	0.25	"	"	"	"	"	"	
Fluoranthene	0.25	0.025	0.25	"	"	"	"	"	"	
Fluorene	0.82	0.028	0.25	"	"	"	"	"	"	
Indeno (1,2,3-cd) pyrene	ND	0.048	0.25	"	"	"	"	"	"	
1-Methylnaphthalene	2.5	0.028	0.25	"	"	"	"	"	"	
2-Methylnaphthalene	3.0	0.020	0.25	"	"	"	"	"	"	
Naphthalene	0.47	0.035	0.25	"	"	"	"	"	"	
Phenanthrene	2.3	0.030	0.25	"	"	"	"	"	"	
Pyrene	0.72	0.0025	0.25	"	"	"	"	"	"	
Surrogate: p-Terphenyl-d14	79 %		30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:33
--	--	-----------------------------

**Polynuclear Aromatic Hydrocarbons by GC/MS-SIM
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-D-7-3.5 (B110558-11) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Acenaphthene	ND	0.0014	0.010	mg/kg dry	1	1J08018	10/08/01	10/11/01	8270-SIM	
Acenaphthylene	ND	0.00080	0.010	"	"	"	"	"	"	
Anthracene	ND	0.0016	0.010	"	"	"	"	"	"	
Benzo (a) anthracene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (a) pyrene	ND	0.0011	0.010	"	"	"	"	"	"	
Benzo (b) fluoranthene	ND	0.0012	0.010	"	"	"	"	"	"	
Benzo (ghi) perylene	ND	0.00080	0.010	"	"	"	"	"	"	
Benzo (k) fluoranthene	ND	0.0016	0.010	"	"	"	"	"	"	
Chrysene	0.0029	0.0016	0.010	"	"	"	"	"	"	J
Dibenz (a,h) anthracene	ND	0.0014	0.010	"	"	"	"	"	"	
Fluoranthene	ND	0.0010	0.010	"	"	"	"	"	"	
Fluorene	0.0022	0.0011	0.010	"	"	"	"	"	"	J
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"	"	"	"	"	"	
1-methyl-naphthalene	0.014	0.0011	0.010	"	"	"	"	"	"	
2-methyl-naphthalene	0.015	0.00080	0.010	"	"	"	"	"	"	
Naphthalene	ND	0.0014	0.010	"	"	"	"	"	"	
Phenanthrene	0.010	0.0012	0.010	"	"	"	"	"	"	
Pyrene	0.0081	0.00010	0.010	"	"	"	"	"	"	J
Surrogate: p-Terphenyl-d14	78 %		30-150			"	"	"	"	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:33
--	--	-----------------------------

**Physical Parameters by APHA/ASTM/EPA Methods
North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
TP-18-5.8-S (B1I0558-01) Soil	Sampled: 09/25/01 10:00 Received: 09/26/01 17:55									
Dry Weight	89.0		1.00	%	1	1J03016	10/03/01	10/04/01	BSOPSPL00 3R07	
TP-19-5.8-S (B1I0558-02) Soil	Sampled: 09/25/01 10:00 Received: 09/26/01 17:55									
Dry Weight	91.2		1.00	%	1	1J03016	10/03/01	10/04/01	BSOPSPL00 3R07	
TP-22-5.8-S (B1I0558-03) Soil	Sampled: 09/25/01 10:00 Received: 09/26/01 17:55									
Dry Weight	86.4		1.00	%	1	1J03016	10/03/01	10/04/01	BSOPSPL00 3R07	
TP-20-5.8-E (B1I0558-04) Soil	Sampled: 09/26/01 10:00 Received: 09/26/01 17:55									
Dry Weight	94.2		1.00	%	1	1J03016	10/03/01	10/04/01	BSOPSPL00 3R07	
EX-D-1-3.5 (B1I0558-05) Soil	Sampled: 09/26/01 10:00 Received: 09/26/01 17:55									
Dry Weight	81.4		1.00	%	1	1J03016	10/03/01	10/04/01	BSOPSPL00 3R07	
EX-D-2-3.5 (B1I0558-06) Soil	Sampled: 09/26/01 12:00 Received: 09/26/01 17:55									
Dry Weight	92.2		1.00	%	1	1J03016	10/03/01	10/04/01	BSOPSPL00 3R07	
EX-D-3-3.5 (B1I0558-07) Soil	Sampled: 09/26/01 12:00 Received: 09/26/01 17:55									
Dry Weight	91.2		1.00	%	1	1J03016	10/03/01	10/04/01	BSOPSPL00 3R07	
EX-D-4-3.5 (B1I0558-08) Soil	Sampled: 09/26/01 12:00 Received: 09/26/01 17:55									
Dry Weight	89.7		1.00	%	1	1J03016	10/03/01	10/04/01	BSOPSPL00 3R07	
EX-D-5-3.5 (B1I0558-09) Soil	Sampled: 09/26/01 12:00 Received: 09/26/01 17:55									
Dry Weight	83.7		1.00	%	1	1J03016	10/03/01	10/04/01	BSOPSPL00 3R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

**Physical Parameters by APHA/ASTM/EPA Methods
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
EX-D-6-3.5 (B1I0558-10) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Dry Weight	85.7		1.00	%	1	1J03016	10/03/01	10/04/01	BSOPSPLO0 3R07	
EX-D-7-3.5 (B1I0558-11) Soil Sampled: 09/26/01 12:00 Received: 09/26/01 17:55										
Dry Weight	90.7		1.00	%	1	1J03017	10/03/01	10/04/01	BSOPSPLO0 3R07	

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

**Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J02038: Prepared 10/02/01 Using EPA 5030B (MeOH)

Blank (1J02038-BLK1)

Gasoline Range Hydrocarbons	ND		5.00	mg/kg							
Benzene	ND		0.0300	"							
Toluene	ND		0.0500	"							
Ethylbenzene	ND		0.0500	"							
Xylenes (total)	ND		0.100	"							
Surrogate: 4-BFB (FID)	3.04			"	4.00		76.0	50-147			
Surrogate: 4-BFB (PID)	3.57			"	4.00		89.2	54-123			

LCS (1J02038-BS1)

Gasoline Range Hydrocarbons	21.5		5.00	mg/kg	25.0		86.0	80-120			
Surrogate: 4-BFB (FID)	3.43			"	4.00		85.8	50-147			

LCS (1J02038-BS2)

Benzene	0.485		0.0300	mg/kg	0.500		97.0	80-120			
Toluene	0.518		0.0500	"	0.500		104	80-120			
Ethylbenzene	0.530		0.0500	"	0.500		106	80-120			
Xylenes (total)	1.61		0.100	"	1.50		107	80-120			
Surrogate: 4-BFB (PID)	3.63			"	4.00		90.8	54-123			

LCS Dup (1J02038-BSD1)

Gasoline Range Hydrocarbons	21.2		5.00	mg/kg	25.0		84.8	80-120	1.41	40	
Surrogate: 4-BFB (FID)	3.32			"	4.00		83.0	50-147			

LCS Dup (1J02038-BSD2)

Benzene	0.480		0.0300	mg/kg	0.500		96.0	80-120	1.04	40	
Toluene	0.501		0.0500	"	0.500		100	80-120	3.34	40	
Ethylbenzene	0.521		0.0500	"	0.500		104	80-120	1.71	40	
Xylenes (total)	1.59		0.100	"	1.50		106	80-120	1.25	40	
Surrogate: 4-BFB (PID)	3.63			"	4.00		90.8	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager

North Creek Analytical, Inc.
 Environmental Laboratory Network



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Volatile Petroleum Products and BTEX by NWTPH-Gx and EPA 8021B - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J02038: Prepared 10/02/01 Using EPA 5030B (MeOH)

Matrix Spike (1J02038-MS1)

Source: B1I0424-03

Gasoline Range Hydrocarbons	26.9		5.00 mg/kg dry		28.8	ND	84.2	53-120			
Surrogate: 4-BFB (FID)	3.92		"		4.61		85.0	50-147			

Matrix Spike (1J02038-MS2)

Source: B1I0558-07

Benzene	0.487		0.0300 mg/kg dry		0.548	ND	84.3	64-130			
Toluene	0.490		0.0500	"	0.548	0.0560	79.2	66-130			
Ethylbenzene	0.541		0.0500	"	0.548	0.0518	89.3	72-130			
Xylenes (total)	1.63		0.100	"	1.64	0.138	91.0	73-130			
Surrogate: 4-BFB (PID)	3.84		"		4.38		87.7	54-123			

Matrix Spike Dup (1J02038-MSD1)

Source: B1I0424-03

Gasoline Range Hydrocarbons	25.2		5.00 mg/kg dry		28.8	ND	78.3	53-120	6.53	40	
Surrogate: 4-BFB (FID)	3.73		"		4.61		80.9	50-147			

Matrix Spike Dup (1J02038-MSD2)

Source: B1I0558-07

Benzene	0.512		0.0300 mg/kg dry		0.548	ND	88.9	64-130	5.01	40	
Toluene	0.521		0.0500	"	0.548	0.0560	84.9	66-130	6.13	40	
Ethylbenzene	0.586		0.0500	"	0.548	0.0518	97.5	72-130	7.99	40	
Xylenes (total)	1.75		0.100	"	1.64	0.138	98.3	73-130	7.10	40	
Surrogate: 4-BFB (PID)	4.24		"		4.38		96.8	54-123			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

North Creek Analytical, Inc.
Environmental Laboratory Network

Page 19 of 25

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J05042: Prepared 10/05/01 Using EPA 3545

Blank (1J05042-BLK1)

Diesel Range Hydrocarbons	ND		10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND		25.0	"							
Surrogate: 2-FBP	9.94			"	10.7		92.9	50-150			
Surrogate: Octacosane	10.9			"	10.7		102	50-150			

LCS (1J05042-BS1)

Diesel Range Hydrocarbons	60.6		10.0	mg/kg	66.7		90.9	50-150			
Surrogate: 2-FBP	8.94			"	10.7		83.6	50-150			

LCS Dup (1J05042-BSD1)

Diesel Range Hydrocarbons	62.0		10.0	mg/kg	66.7		93.0	50-150	2.28	50	
Surrogate: 2-FBP	11.5			"	10.7		107	50-150			

Duplicate (1J05042-DUP1)

Source: B110558-07

Diesel Range Hydrocarbons	3980		210	mg/kg dry		4390			9.80	50	
Lube Oil Range Hydrocarbons	1220		525	"		1390			13.0	50	
Surrogate: 2-FBP	8.50			"	11.7		72.6	50-150			
Surrogate: Octacosane	10.4			"	11.7		88.9	50-150			

Batch 1J16038: Prepared 10/16/01 Using EPA 3550B

Blank (1J16038-BLK1)

Diesel Range Hydrocarbons	ND		10.0	mg/kg							
Lube Oil Range Hydrocarbons	ND		25.0	"							
Surrogate: 2-FBP	8.21			"	10.7		76.7	50-150			
Surrogate: Octacosane	9.61			"	10.7		89.8	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Semivolatile Petroleum Products by NWTPH-Dx with Acid/Silica Gel Clean-up - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1J16038: Prepared 10/16/01 Using EPA 3550B											
LCS (1J16038-BS1)											
Diesel Range Hydrocarbons	48.4		10.0	mg/kg	66.7		72.6	50-150			
Surrogate: 2-FBP	8.58			"	10.7		80.2	50-150			
LCS Dup (1J16038-BSD1)											
Diesel Range Hydrocarbons	69.5		10.0	mg/kg	66.7		104	50-150	35.8	50	
Surrogate: 2-FBP	9.06			"	10.7		84.7	50-150			
Duplicate (1J16038-DUP1) Source: B1I0558-11RE1											
Diesel Range Hydrocarbons	87.2		10.0	mg/kg dry		125			35.6	50	
Lube Oil Range Hydrocarbons	29.7		25.0	"		43.6			37.9	50	
Surrogate: 2-FBP	8.93			"	11.8		75.7	50-150			
Surrogate: Octacosane	12.2			"	11.8		103	50-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:33
--	--	-----------------------------

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J08018: Prepared 10/08/01 Using EPA 3550B

Blank (1J08018-BLK1)

Acenaphthene	ND	0.0014	0.010	mg/kg							
Acenaphthylene	ND	0.00080	0.010	"							
Anthracene	ND	0.0016	0.010	"							
Benzo (a) anthracene	ND	0.0011	0.010	"							
Benzo (a) pyrene	ND	0.0011	0.010	"							
Benzo (b) fluoranthene	ND	0.0012	0.010	"							
Benzo (ghi) perylene	ND	0.00080	0.010	"							
Benzo (k) fluoranthene	ND	0.0016	0.010	"							
Chrysene	ND	0.0016	0.010	"							
Dibenz (a,h) anthracene	ND	0.0014	0.010	"							
Fluoranthene	ND	0.0010	0.010	"							
Fluorene	ND	0.0011	0.010	"							
Indeno (1,2,3-cd) pyrene	ND	0.0019	0.010	"							
1-Methylnaphthalene	ND	0.0011	0.010	"							
2-Methylnaphthalene	ND	0.00080	0.010	"							
Naphthalene	ND	0.0014	0.010	"							
Phenanthrene	ND	0.0012	0.010	"							
Pyrene	ND	0.00010	0.010	"							

Surrogate: p-Terphenyl-d14	1.3			"	1.7		76	30-150			
----------------------------	-----	--	--	---	-----	--	----	--------	--	--	--

LCS (1J08018-BS1)

Chrysene	0.28	0.0016	0.010	mg/kg	0.33		85	10-125			
Fluorene	0.24	0.0011	0.010	"	0.33		73	11-116			
Indeno (1,2,3-cd) pyrene	0.26	0.0019	0.010	"	0.33		79	10-147			

Surrogate: p-Terphenyl-d14	1.2			"	1.7		71	30-150			
----------------------------	-----	--	--	---	-----	--	----	--------	--	--	--

LCS Dup (1J08018-BSD1)

Chrysene	0.27	0.0016	0.010	mg/kg	0.33		82	10-125	3.6	28	
Fluorene	0.26	0.0011	0.010	"	0.33		79	11-116	8.0	32	
Indeno (1,2,3-cd) pyrene	0.28	0.0019	0.010	"	0.33		85	10-147	7.4	34	

Surrogate: p-Terphenyl-d14	1.3			"	1.7		76	30-150			
----------------------------	-----	--	--	---	-----	--	----	--------	--	--	--

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle
 17171 Bothell Way NE #264
 Seattle WA/USA, 98155

Project: Former Bulk Storage of Edmonds
 Project Number: 9077.001.004
 Project Manager: Linda Dawson

Reported:
 11/20/01 13:33

Polynuclear Aromatic Hydrocarbons by GC/MS-SIM - Quality Control
North Creek Analytical - Bothell

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J08018: Prepared 10/08/01 Using EPA 3550B

Matrix Spike (1J08018-MS1) **Source: B1I0610-07**

Chrysene	0.25	0.0016	0.010 mg/kg dry		0.35	ND	71	10-125			
Fluorene	0.32	0.0011	0.010	"	0.35	ND	91	10-154			
Indeno (1,2,3-cd) pyrene	0.25	0.0019	0.010	"	0.35	ND	71	10-144			
Surrogate: p-Terphenyl-d14	1.3			"	1.8		72	30-150			

Matrix Spike Dup (1J08018-MSD1) **Source: B1I0610-07**

Chrysene	0.25	0.0016	0.010 mg/kg dry		0.35	ND	71	10-125	0.0	28	
Fluorene	0.31	0.0011	0.010	"	0.35	ND	89	10-154	3.2	32	
Indeno (1,2,3-cd) pyrene	0.25	0.0019	0.010	"	0.35	ND	71	10-144	0.0	47	
Surrogate: p-Terphenyl-d14	1.3			"	1.8		72	30-150			

North Creek Analytical - Bothell

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:33
--	--	-----------------------------

**Physical Parameters by APHA/ASTM/EPA Methods - Quality Control
 North Creek Analytical - Bothell**

Analyte	Result	MDL	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
---------	--------	-----	-----------------	-------	-------------	---------------	------	-------------	-----	-----------	-------

Batch 1J03016: Prepared 10/03/01 Using Dry Weight

Blank (1J03016-BLK1)

Dry Weight	100		1.00	%							
------------	-----	--	------	---	--	--	--	--	--	--	--

Batch 1J03017: Prepared 10/03/01 Using Dry Weight

Blank (1J03017-BLK1)

Dry Weight	100		1.00	%							
------------	-----	--	------	---	--	--	--	--	--	--	--

Scott A. Woerman, Project Manager



Seattle 11720 North Creek Pkwy N, Suite 400, Bothell, WA 98011-8244
 425.420.9200 fax 425.420.9210
 Spokane East 11115 Montgomery, Suite B, Spokane, WA 99206-4776
 509.924.9200 fax 509.924.9290
 Portland 9405 SW Nimbus Avenue, Beaverton, OR 97008-7132
 503.906.9200 fax 503.906.9210
 Bend 20332 Empire Avenue, Suite F-1, Bend, OR 97701-5711
 541.383.9310 fax 541.382.7588

Maul Foster & Alongi-Seattle 17171 Bothell Way NE #264 Seattle WA/USA, 98155	Project: Former Bulk Storage of Edmonds Project Number: 9077.001.004 Project Manager: Linda Dawson	Reported: 11/20/01 13:33
--	--	-----------------------------

Notes and Definitions

- G-01 Results reported for the gas range are primarily due to overlap from diesel range hydrocarbons.
- I-06 The analyte concentration may be artificially elevated due to coeluting compounds or components.
- J Estimated value.
- Q-29 This sample was prepared outside of the method established holding time.
- S-01 The surrogate recovery for this sample is not available due to sample dilution required from high analyte concentration and/or matrix interferences.
- S-06 The recovery of this surrogate is outside control limits due to sample dilution required from high analyte concentration and/or matrix interferences.
- X See case narrative.
- DET Analyte DETECTED
- ND Analyte NOT DETECTED at or above the reporting limit
- NR Not Reported
- Sample results reported on a dry weight basis
- RPD Relative Percent Difference


 Scott A. Woerman, Project Manager



UNOCAL CHAIN OF CUSTODY REPORT

B110550

UNOCAL INFORMATION	
Facility Number:	Unocal Edmond Terminal
Site Address:	11720 UNOCO Road
City, State, ZIP:	Edmonds 98020
Site Release Number:	
Unocal Manager:	Mark Bearley
CERT INFO: (check one)	<input type="checkbox"/> Evaluation <input checked="" type="checkbox"/> Remediation <input type="checkbox"/> Detection <input type="checkbox"/> Demolition <input type="checkbox"/> Closure <input type="checkbox"/> Miscellaneous

CONSULTANT INFORMATION	
Firm:	Mani Foster + Alangi Project# 9077.001.004
Address:	17171 Bothell Way NE. #264 Seattle, 98155
Phone:	744-1489 Fax: 744-0919
Project Manager:	L. Dawson
Sample Collection by:	R. Dyer

Chain of Custody Record #:

Quality Assurance Data Level:
 A B
 A: Standard Summary
 per site QA
 B: Standard + Chromatograms

Laboratory Turnaround Days:
 10 5 3 2 1
 SED T/A

SAMPLE IDENTIFICATION	SAMPLING DATE / TIME	MATRIX (W,S,O)	# OF CON-TAINERS
1. TP-18-5.8-S	9-25-01/1000	S	1
2. TP-19-5.8-S	9-25-01/1000	S	1
3. TP-22-5.8-S	9-25-01/1000	S	1
4. TP-20-5.8-E	9-26-01/1000	S	1
5. EX-D-1-3.5	9-26-01/1000	S	1
6. EX-D-2-3.5	9-26-01/1200	S	1
7. EX-D-3-3.5	9-26-01/1200	S	1
8. EX-D-4-3.5	9-26-01/1200	S	1
9. EX-D-5-3.5	9-26-01/1200	S	1
10. EX-D-6-3.5	9-26-01/1200	S	1

○ OR ○ WA ○ AK <input checked="" type="checkbox"/> NW Series													
TPH-HCID	TPH-Gas	BTEX EPA 8021 Mod.	TPH-Gas + BTEX	TPH-Diesel	TPH-Diesel Extended	TPH-Diesel-Ext. w/SG Cleanup	Halogen. Volatiles EPA 8021	Pesticides/PCBs or PCBs Only	GC/MS Volatiles EPA 8260	GC/MS SemiVols. EPA 8270	PAHs: 8270 SIM or 8310	Lead:	Total or Dissolved TCLP or RCRA Metals (6)
			X		X								PAHs (6)
			X		X								X
			X		X								X
			X		X								X
			X		X								X
			X		X								X
			X		X								X
			X		X								X
			X		X								X
			X		X								X

TPH + BTEX

PAHs

NCA SAMPLE NUMBER
01
02
03
04
05
06
07
08
09
10

Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
1. [Signature]	MFA	9/26/01 4:00pm	[Signature]	NOA	9/26/01 16:00
2. [Signature]	NCA	9/26/01 17:55	[Signature]	FORJUE	9/26/01 17:55
3.					

Final Report Approval

Were all requested results provided? yes no Define

Were results within requested turnaround? yes no "No" on back

Final Approval Signature: [Signature]

Firm: W/O S.Y.



UNOCAL CHAIN OF CUSTODY REPORT BLOSSB

UNOCAL INFORMATION	
Facility Number:	Unocal Edmonds Terminal
Site Address:	11720 Unoco Road
City, State, ZIP:	Edmonds 98020
Site Release Number:	
Unocal Manager:	Mark Bearley
CERT INFO: (check one)	<input type="checkbox"/> Evaluation <input checked="" type="checkbox"/> Remediation <input type="checkbox"/> Detection <input type="checkbox"/> Demolition <input type="checkbox"/> Closure <input type="checkbox"/> Miscellaneous

CONSULTANT INFORMATION	
Firm:	Maul Foster + Alangi Project# 9077.001.004
Address:	17171 Bothell Way NE #264 Seattle, 98155
Phone:	(425) 744-1489 Fax: 744-0919
Project Manager:	L. Dawson
Sample Collection by:	R. Dyer

Chain of Custody Record #:

Quality Assurance Data Level:
 A B
 A: Standard Summary
 B: Standard + Chromatograms
per site QA

Laboratory Turnaround Days:
 10 5 3 2 1
SKD T/A

SAMPLE IDENTIFICATION	SAMPLING DATE / TIME	MATRIX (W,S,O)	# OF CONTAINERS
1. EX-D-7-3.5	9-26-01/1200	LS	1
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

	<input type="radio"/> OR	<input type="radio"/> WA	<input type="radio"/> AK	<input checked="" type="radio"/> NW Series
TPH-HCID				
TPH-Gas				
BTEX				
EPA 8021 Mod				
TPH-Gas + BTEX				
TPH-Diesel				
TPH-Diesel Extended				
TPH-Diesel-Ext. w/SG Cleanup				
Halogen Volatiles EPA 8021				
Pesticides/PCBs or PCBs Only				
GC/MS Volatiles EPA 8260				
GC/MS SemiVol. EPA 8270				
PAH's: 8270 SIM or 8310				
Lead: Total or Dissolved				
TCLP or RCRA Metals (8)				
PAHs				

PAHs TPH + BTEX

NCA SAMPLE NUMBER
- 11

	Relinquished by:	Firm:	Date & Time	Received by:	Firm:	Date & Time
1.	<i>[Signature]</i>	MFA	9/26/01 4:00pm	<i>[Signature]</i>	NCA	9/26/01 16:00
2.	<i>[Signature]</i>	NCA	9/26/01 17:55	<i>[Signature]</i>	NCA	9/26/01 17:55
3.						

Final Report Approval

Were all requested results provided? yes no Define

Were results within requested turnaround? yes no "No" on back

Final Approval Signature: *[Signature]*

Firm: _____ Date: _____