

SERVICE RECORD

RECEIVED

FAMILY NAME.....

MAY 30 1996
Recorded by _____ Title _____

Date	NOTES	DEPT. OF ECOLOGY
3/27/96	yard at the time of visitation. Staining of the soil was not visible at this time. Gary told Mr. McAllister that he will be sending this file to DOE for final determination.	MJS
4/30/96	Note: Soils mentioned 8/18/95 that were excavated from the drainage / creek area on the west side of the property are still covered with a tarp in a pile on the SE side of the property.	MJS
5/15/96	T.C. with Nancy Wold. Gave her update on site. Indicated I would be forwarding file to Ecology for a final determination. Ms. Wold upset that it did not seem fair that some auto wrecking yards are listed and others are not. I indicated we visited sites via complaint investigation and did not inspect all auto wrecking yards in the county.	BSF
5/22/96	T.C. with Gail Colburn. Will send copy of file for a determination on site listing.	BSF

SERVICE RECORD

FAMILY NAME Flary Auto & Truck

Date	NOTES	Recorded by	Title
1/14/96	Left message with message machine for Nancy Wold, requested that she contact me for an update of on Flary Auto Property.	ASJ/K	
1/31/96	TC with Nancy Wold. Talked about Flary Auto property. Talked about our visits and some of the issues. Discussed the contaminated soil problem and soil sink routes. She indicated that an uncle ran an auto parts factory from 1950 - 1972 and that they operated some time of ignition in July of 1973 - to Sept of 1984 Mr. McCallister has operated on property since 1984. We talked about where contamination would come from and I indicated fluids from radiators, condensers, etc., and crushing operations. Radiators in the past were stored inside because of value. I indicating we would be visiting property in March and then forwarding information to Ecology for a determination on whether site should be tested.	ASJ/K	
3/20/96	TC with Mr. McAllister - told him we have scheduled a CB for 3/27 & would see him then	MDS	
3/27/96	Visited site with Gary Hamada. Mr. McAllister showed us the area where he kept his paperwork, the garage area where totes were used as 2 nd containment & under cover to contain waste such as oil & antifreeze. We also walked the perimeter of the yard, we did not see batteries, drums or other containers out in the		

SERVICE RECORD

FAMILY NAME.....

Date	NOTES	Recorded by	Title
9/27/95	<p>Spoke w/Mr. McAllister. He said that his visit with ^{Bob Write} resulted in installing down spouts on the roof, french drains, so that the water would go into the runoff area. He also said that Mr. Write told him not to put an underground pipe in for surface water but just to leave the runoff area as is. I asked Mr. McAllister if he had a copy of the SLEPs on wrecking yards - he does - I also told him that at this point I have a concern about the area where cars are being crushed since it is done on soil. He said that all the cars are completely drained before they are crushed - this is a requirement of Pete Gundie (800) 444 21344, the man who owns the crusher. Mr. McAllister also told me that he is paid \$70/ton for the auto bodies and he is docked \$18./ton if there is a "wet" car. I asked him what they do when automotive fluids are released in the crushing process. He told me that there is a low point in the crusher and the put carpet there to catch any auto. fluids. Then the carpet is allowed to dry & thrown away.</p> <p>(B) March 19, 1996</p>		

SERVICE RECORD

FAMILY NAME.....

Date	NOTES	Recorded by	Title
3/18/95 cont.	<p>At the time of visitation all containers were labeled. Also at this time there were no batteries or containers on the grounds with the exception of those in totes under the roof. The area where the stream ran through the property has been cleared of all vehicles and approximately 2 cubic yards of soil had been removed from the surface of this stream then placed on a tarp on the ^{south} east side of the property and covered with a tarp. Jeff advised Mr. McAllister that Rabanco/Rubatino would pick this up after it is tested. Mr. McAllister said that Bob Write w/ DOE will come out & advise him on the water situation (stream & surface water) and at that time Mr. McAllister will ask Bob Write his opinion on diverting the water from surface through a pipe underground and connecting it w/ the pipes on both the North & South sides of the property. The crusher had been removed as well as the drums in this area, however, there is still sheer on the puddles and the area doesn't have a concrete pad for future use. I will call Mr. McAllister on this concern and ask him if he has contacted Scott Lamb at DOE for a technical visit appointment.</p>	MS	

HO-5 Everett Iron & Metals takes radiators
Mr. McAllister is keeping all receipts. MS

SERVICE RECORD

FAMILY NAME.....

Date	NOTES	Recorded by	Title
8/11/95	Spoke with Mr. McAllister. He said that he has been working on the requests in the letter all week and will meet with us on Aug. 18 th at 10:30 (at my request). He said on the oil - he has hired vintage oil to take it and has kept the receipts he is not taking it to Scheck's or Al's anymore. He has hired Cool-Rite to remove the Freon from the vehicles when he has about 30 to do they will come out. He gives or sells his antifreeze to Car Connection and they use it in their vehicles. He asked where to get his waste labels - I told him I would send him 10 for now and give him the 800 number of 3 order places. Will do CB		
8/18/95	Visited site. Mr. McAllister took us around the entire yard. Concerning wastes: oil is put into their tank and when full he calls Vintage Oil. The antifreeze is given to the car connection for use in their vehicles. The gas is used in vehicles on site and employee vehicles. The batteries are picked up by Interstate Storage. Mr. McAllister has purchased totes to store drums and other waste in.	WJS with Jeff Defenbach	
	cont.		

SERVICE RECORD

FAMILY NAME.....

Date	NOTES	Recorded by	Title
7/11/95	<p>Guy - Jerry was out of town. Taking waste oil to Shucks 5 gallons at a time - told him that was not for businesses.</p> <p>Roof is up & went up ~ 6 weeks or 3 months ago. ~ 12 ft. concrete layered under roof - soil moved out beyond roof. 20 ft rocks beyond roof & concrete.</p> <p>Took photos of area - batteries stored outside. Staining around entire site → refer to photos.</p> <p>Looked at area around back (east) took photos gas, oil & other fluids kept in 55-gallon drums near the crusher - oil in puddles (photos). Strong odor of gas.</p> <p>Antifreeze & transmission fluid & oils are drained. Brake fluid is not drained at this time. Crusher is kept in approximately the same area every time cars are crushed. See photos. Talk to Jerry or Reg (MRW) & Vendor list. Will send letter to owner & 2nd letter to Mr. M^{ac}Allister</p>		

SERVICE RECORD

FAMILY NAME.....

SERVICE RECORD

FAMILY NAME.....

Date	NOTES	Recorded by	Title
2/23/95	Bob Wright spoke with Mr. McAllister about getting a SWPPP permit - he told Mr. McAllister that he needed to get this application in within 2 weeks. Gary spoke with Mr. McAllister on possibly doing a site clean-up and he will be in touch with him on those requirements. I will send a letter, in addition to Gary's, discussing current practices and requirements of MRCW regulations.	MS	
3/3/95	T.C. with Scott Lamb - Ecology. Gail Colburn had discussed Fleury Auto and he would be willing to meet with Mr. McAllister to give technical assistance on his facility. I stated that I would contact McAllister and inform him of technical assistance option. He Scott will contact us when he hears from McAllister.	2/1/1	
3/6/95	T.C. with Jerry McAllister. He will contact Scott Lamb (Bob) for technical assistance.	2/1/1	
3/16/95	Left message for Scott Lamb, D.O.E.	2/1/1	
3/14/95	T.C. with Scott Lamb. Has not been contacted by McAllister.	2/1/1	

743-3120
355-0554I LUV USED, INC. dba
Fleury Auto & Truck Parts13303 Hwy 99 S.
Everett, WA 98204

Jerry & Patti McAllister

SERVICE RECORD

FAMILY NAME.....

Date	NOTES	Recorded by	Title
1/7/95 cont.	puddles around the yard and there was also sheen in the surface water running in the yard. May speak with Bob Wright about this.	MS	
2/6/95	Spoke to with Bob Wright on Fleurys. He said Als next door, has a discharge permit but Fleurys doesn't as of yet. Will visit site with Bob Wright 2/15/95. MS		
2/9/95	Received another call (anonymous complaint) concerning Fleurys practices. Caller stated that he knew SHD visited site and heard via ^{current} employee that nothing was found during the inspection. MS		
2/17/95	Received a new complaint from a customer of Fleurys - it was left anonymously - they said that while there a radiator line was cut and fluid was allowed to go onto the ground; also there was a lot of oil on the ground as well.	MS	
2/23/95	Visited site with Gary Hanack, Bob Wright DCE. With the recent rain, there was quite a bit of mud in the muddy area directly adjacent (south) of the concrete pad where cars are parked. There was a very strong odor of antifreeze and oil. On the east side of the pad there was a lot of liquid that appeared to have been dumped oil and/or other oil products.		
	(Have photos attached)		