

CHRISTINE O. GREGOIRE
Director



STATE OF WASHINGTON

DEPARTMENT OF ECOLOGY

4350-150th Ave. N.E. • Redmond, Washington 98052-5301 • (206) 867-7000

August 21, 1990

Western Gear
2100 W. Marine View Dr.
Everett, WA 98201

Re: EARLY NOTICE LETTER
East Waterway Site #N-31-5011-000

Dear Sir/Madam:

I am writing to send you information the Department of Ecology has gathered regarding the above-referenced property. Under the Model Toxics Control Act (Chapter 70.105D RCW) Ecology maintains a database of known or suspected contaminated sites. Based on available information and an inspection performed on March 7, 1990, we have added the above-referenced property to our database.

Enclosed is a computer print-out summarizing information which we believe reflects the current status of this site. We are making every effort to ensure that we have accurate information. I encourage you to carefully review this report. If you have any corrections, please send them and any supporting material to me at the above address. A legend, location description and map have also been enclosed to help you interpret this report.

Please note that inclusion in the database **does not** mean that Ecology has determined you are a potentially liable person under the Model Toxics Control Act or that action is needed at this time. We will be conducting a more detailed inspection of this property, including testing for possible contamination, at a future time. After that, we will be better able to assess whether action will be needed and to establish a priority for this work.

It is Ecology's policy to work cooperatively with persons to accomplish prompt and effective cleanups. However, due to limited resources and requirements in state law, we are not always able to provide requested assistance in a timely manner. Cooperating with the department in planning or conducting remedial cleanup action is not admission of guilt or liability. If you decide to proceed with an independent




Western Gear
August 21, 1990
Page 2

cleanup, please be aware to adhere to the requirements in state law. Please contact me for a copy of Chapter 70.105D RCW (The Model Toxics Control Act) and the implementing regulations, Chapter 173-340 WAC, which detail these requirements.

If you have any questions regarding this letter you may call me at (206)867-7209. Thank you in advance for your cooperation.

Sincerely,



Louise Bardy
Site Information Coordinator
Toxics Cleanup Program (TCP)

Enclosures

LB:lb

cc: Mike Gallagher, Supervisor, TCP

CHRISTINE O. GREGOIRE
Director



R

STATE OF WASHINGTON

DEPARTMENT OF ECOLOGY

4350-150th Ave. N.E. • Redmond, Washington 98052-5301 • (206) 867-7000

August 21, 1990

The Honorable Pete Kinch
Mayor of Everett
3002 Wetmore
Everett, WA 98201

Re: EARLY NOTICE LETTER
East Waterway Site #N-31-5011-000

Dear Mayor Kinch:

I am writing to send you information the Department of Ecology has gathered regarding the above-referenced property. Under the Model Toxics Control Act (Chapter 70.105D RCW) Ecology maintains a database of known or suspected contaminated sites. Based on available information and an inspection performed on March 7, 1990, we have added the above-referenced property to our database.

Enclosed is a computer print-out summarizing information which we believe reflects the current status of this site. We are making every effort to ensure that we have accurate information. I encourage you to carefully review this report. If you have any corrections, please send them and any supporting material to me at the above address. A legend, location description and map have also been enclosed to help you interpret this report.

Please note that inclusion in the database **does not** mean that Ecology has determined you are a potentially liable person under the Model Toxics Control Act or that action is needed at this time. We will be conducting a more detailed inspection of this property, including testing for possible contamination, at a future time. After that, we will be better able to assess whether action will be needed and to establish a priority for this work.

It is Ecology's policy to work cooperatively with persons to accomplish prompt and effective cleanups. However, due to limited resources and requirements in state law, we are not always able to provide requested assistance in a timely manner. Cooperating with the department in planning or conducting remedial cleanup action is not admission of guilt or liability. If you decide to proceed with an independent




Mayor Kinch
August 21, 1990
Page 2

cleanup, please be aware to adhere to the requirements in state law. Please contact me for a copy of Chapter 70.105D RCW (The Model Toxics Control Act) and the implementing regulations, Chapter 173-340 WAC, which detail these requirements.

If you have any questions regarding this letter you may call me at (206)867-7209. Thank you in advance for your cooperation.

Sincerely,



Louise Bardy
Site Information Coordinator
Toxics Cleanup Program (TCP)

Enclosures

LB:lb

cc: Mike Gallagher, Supervisor, TCP

CHRISTINE O. GREGOIRE
Director



(R)

STATE OF WASHINGTON

DEPARTMENT OF ECOLOGY

4350-150th Ave. N.E. • Redmond, Washington 98052-5301 • (206) 867-7000

August 21, 1990

Weyerhaeuser
101 E. Marine View Dr.
Everett, WA 98201

Re: EARLY NOTICE LETTER
East Waterway Site #N-31-5011-000

Dear Sir/Madam:

I am writing to send you information the Department of Ecology has gathered regarding the above-referenced property. Under the Model Toxics Control Act (Chapter 70.105D RCW) Ecology maintains a database of known or suspected contaminated sites. Based on available information and an inspection performed on March 7, 1990, we have added the above-referenced property to our database.

Enclosed is a computer print-out summarizing information which we believe reflects the current status of this site. We are making every effort to ensure that we have accurate information. I encourage you to carefully review this report. If you have any corrections, please send them and any supporting material to me at the above address. A legend, location description and map have also been enclosed to help you interpret this report.

Please note that inclusion in the database does not mean that Ecology has determined you are a potentially liable person under the Model Toxics Control Act or that action is needed at this time. We will be conducting a more detailed inspection of this property, including testing for possible contamination, at a future time. After that, we will be better able to assess whether action will be needed and to establish a priority for this work.

It is Ecology's policy to work cooperatively with persons to accomplish prompt and effective cleanups. However, due to limited resources and requirements in state law, we are not always able to provide requested assistance in a timely manner. Cooperating with the department in planning or conducting remedial cleanup action is not admission of guilt or liability. If you decide to proceed with an independent



Weyerhaeuser
August 21, 1990
Page 2

cleanup, please be aware to adhere to the requirements in state law. Please contact me for a copy of Chapter 70.105D RCW (The Model Toxics Control Act) and the implementing regulations, Chapter 173-340 WAC, which detail these requirements.

If you have any questions regarding this letter you may call me at (206)867-7209. Thank you in advance for your cooperation.

Sincerely,

Louise Bardy
Louise Bardy
Site Information Coordinator
Toxics Cleanup Program (TCP)

Enclosures

LB:lb

cc: Mike Gallagher, Supervisor, TCP

CHRISTINE O. GREGOIRE
Director



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

4350-150th Ave. N.E. • Redmond, Washington 98052-5301 • (206) 867-7000

August 21, 1990

Mr. Dennis Gregoire
Port of Everett
1700 W. Marine View Dr.
Everett, WA 98201

Re: EARLY NOTICE LETTER
East Waterway Site #N-31-5011-000

Dear Mr. Gregoire:

I am writing to send you information the Department of Ecology has gathered regarding the above-referenced property. Under the Model Toxics Control Act (Chapter 70.105D RCW) Ecology maintains a database of known or suspected contaminated sites. Based on available information and an inspection performed on March 7, 1990, we have added the above-referenced property to our database.

Enclosed is a computer print-out summarizing information which we believe reflects the current status of this site. We are making every effort to ensure that we have accurate information. I encourage you to carefully review this report. If you have any corrections, please send them and any supporting material to me at the above address. A legend, location description and map have also been enclosed to help you interpret this report.

Please note that inclusion in the database does not mean that Ecology has determined you are a potentially liable person under the Model Toxics Control Act or that action is needed at this time. We will be conducting a more detailed inspection of this property, including testing for possible contamination, at a future time. After that, we will be better able to assess whether action will be needed and to establish a priority for this work.


It is Ecology's policy to work cooperatively with persons to accomplish prompt and effective cleanups. However, due to limited resources and requirements in state law, we are not always able to provide requested assistance in a timely manner. Cooperating with the department in planning or conducting remedial cleanup action is not admission of guilt or liability. If you decide to proceed with an independent

Mr. Gregoire
August 21, 1990
Page 2

cleanup, please be aware to adhere to the requirements in state law. Please contact me for a copy of Chapter 70.105D RCW (The Model Toxics Control Act) and the implementing regulations, Chapter 173-340 WAC, which detail these requirements.

If you have any questions regarding this letter you may call me at (206)867-7209. Thank you in advance for your cooperation.

Sincerely,



Louise Bardy
Site Information Coordinator
Toxics Cleanup Program (TCP)

Enclosures

LB:lb

cc: Mike Gallagher, Supervisor, TCP

CHRISTINE O. GREGOIRE
Director



(R)

STATE OF WASHINGTON

DEPARTMENT OF ECOLOGY

4350-150th Ave. N.E. • Redmond, Washington 98052-5301 • (206) 867-7000

August 21, 1990

Ms. Ann Bailey
Scott Paper
P.O. Box 925
Everett, WA 98206

Re: EARLY NOTICE LETTER
East Waterway Site #N-31-5011-000

Dear Ms. Bailey:

I am writing to send you information the Department of Ecology has gathered regarding the above-referenced property. Under the Model Toxics Control Act (Chapter 70.105D RCW) Ecology maintains a database of known or suspected contaminated sites. Based on available information and an inspection performed on March 7, 1990, we have added the above-referenced property to our database.

Enclosed is a computer print-out summarizing information which we believe reflects the current status of this site. We are making every effort to ensure that we have accurate information. I encourage you to carefully review this report. If you have any corrections, please send them and any supporting material to me at the above address. A legend, location description and map have also been enclosed to help you interpret this report.

Please note that inclusion in the database **does not** mean that Ecology has determined you are a potentially liable person under the Model Toxics Control Act or that action is needed at this time. We will be conducting a more detailed inspection of this property, including testing for possible contamination, at a future time. After that, we will be better able to assess whether action will be needed and to establish a priority for this work.


It is Ecology's policy to work cooperatively with persons to accomplish prompt and effective cleanups. However, due to limited resources and requirements in state law, we are not always able to provide requested assistance in a timely manner. Cooperating with the department in planning or conducting remedial cleanup action is not admission of guilt or liability. If you decide to proceed with an independent

Ms. Bailey
August 21, 1990
Page 2

cleanup, please be aware to adhere to the requirements in state law. Please contact me for a copy of Chapter 70.105D RCW (The Model Toxics Control Act) and the implementing regulations, Chapter 173-340 WAC, which detail these requirements.

If you have any questions regarding this letter you may call me at (206)867-7209. Thank you in advance for your cooperation.

Sincerely,


Louise Bardy
Site Information Coordinator
Toxics Cleanup Program (TCP)

Enclosures

LB:lb

cc: Mike Gallagher, Supervisor, TCP

CHRISTINE O. GREGOIRE
Director



2

STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

4350-150th Ave. N.E. • Redmond, Washington 98052-5301 • (206) 867-7000

August 21, 1990

Mr. V.L. Vasaitis, P.E.
EFA NW
3505 Anderson Hill Rd.
Silverdale, WA 98383

Re: EARLY NOTICE LETTER
East Waterway Site #N-31-5011-000

Dear Mr. Vasaitis:

I am writing to send you information the Department of Ecology has gathered regarding the above-referenced property. Under the Model Toxics Control Act (Chapter 70.105D RCW) Ecology maintains a database of known or suspected contaminated sites. Based on available information and an inspection performed on March 7, 1990, we have added the above-referenced property to our database.

Enclosed is a computer print-out summarizing information which we believe reflects the current status of this site. We are making every effort to ensure that we have accurate information. I encourage you to carefully review this report. If you have any corrections, please send them and any supporting material to me at the above address. A legend, location description and map have also been enclosed to help you interpret this report.

Please note that inclusion in the database does not mean that Ecology has determined you are a potentially liable person under the Model Toxics Control Act or that action is needed at this time. We will be conducting a more detailed inspection of this property, including testing for possible contamination, at a future time. After that, we will be better able to assess whether action will be needed and to establish a priority for this work.


It is Ecology's policy to work cooperatively with persons to accomplish prompt and effective cleanups. However, due to limited resources and requirements in state law, we are not always able to provide requested assistance in a timely manner. Cooperating with the department in planning or conducting remedial cleanup action is not admission of guilt or liability. If you decide to proceed with an independent

Mr. Vasaitis
August 21, 1990
Page 2

cleanup, please be aware to adhere to the requirements in state law. Please contact me for a copy of Chapter 70.105D RCW (The Model Toxics Control Act) and the implementing regulations, Chapter 173-340 WAC, which detail these requirements.

If you have any questions regarding this letter you may call me at (206)867-7209. Thank you in advance for your cooperation.

Sincerely,



Louise Bardy
Site Information Coordinator
Toxics Cleanup Program (TCP)

Enclosures

LB:lb

cc: Mike Gallagher, Supervisor, TCP

CHRISTINE O. GREGGIRE
Director



STATE OF WASHINGTON

DEPARTMENT OF ECOLOGY

4350-150th Ave. N.E. • Redmond, Washington 98052-5301 • (206) 867-7000

August 30, 1990

Bucyrus Erie
P.O. Box 500
South Milwaukee, WI 53172

Re: EARLY NOTICE LETTER FOR EAST WATERWAY SITE
Formerly Western Gear Property
2100 W. Marine View Dr., Everett, WA

Dear Gentleman/Madam:

I am writing to send you information the Department of Ecology has gathered regarding the above-referenced property. Under the Model Toxics Control Act (Chapter 70.105D RCW) Ecology maintains a database of known or suspected contaminated sites. Based on available information and an inspection performed on March 7, 1990, we have added the above-referenced property to our database.

Enclosed is a computer print-out summarizing information which we believe reflects the current status of this site. We are making every effort to ensure that we have accurate information. I encourage you to carefully review this report. If you have any corrections, please send them and any supporting material to me at the above address. A legend, location description and map have also been enclosed to help you interpret this report.

Please note that inclusion in the database **does not** mean that Ecology has determined you are a potentially liable person under the Model Toxics Control Act or that action is needed at this time. We will be conducting a more detailed inspection of this property, including testing for possible contamination, at a future time. After that, we will be better able to assess whether action will be needed and to establish a priority for this work.

It is Ecology's policy to work cooperatively with persons to accomplish prompt and effective cleanups. However, due to limited resources and requirements in state law, we are not always able to provide requested assistance in a timely manner. Cooperating with the department in planning or conducting remedial cleanup action is not admission of guilt or liability. If you decide to proceed with an independent




Bucyrus Erie
August 30, 1990
Page 2

cleanup, please be aware to adhere to the requirements in state law. Please contact me for a copy of Chapter 70.105D RCW (The Model Toxics Control Act) and the implementing regulations, Chapter 173-340 WAC, which detail these requirements.

If you have any questions regarding this letter you may call me at (206)867-7209. Thank you in advance for your cooperation.

Sincerely,



Louise Bardy
Site Information Coordinator
Toxics Cleanup Program (TCP)

Enclosures

LB:lb

cc: Mike Gallagher, Supervisor, TCP