### **BNSF Railway Skykomish**

S H A R P
Go to site contamination history

SHARP Report — Part 1 of 2

• SHARP first SHARP		v2024.04.29	Ecology	Info
<ul> <li>SHARP rating</li> </ul>	Low		ERTS	SHARP it
<ul> <li>SHARP date</li> </ul>	08/28/2025		CSID	34
<ul><li>EJFlagged?</li></ul>	🛇 - No Override		FSID	2104
<ul> <li>LD confidence level</li> </ul>	low		VCP	SHARP it
<ul> <li>Cleanup milestone</li> </ul>	cleanup implementation		UST ID	SHARP it
• SHARPster	Tanner Bushnell		LUST ID	SHARP it

This section is blank if this	is the first SHARP
-------------------------------	--------------------

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	D4	medium	multiple chemical types	<b>✓</b>
Groundwater	C3	high	risk to off-site people	$\otimes$
Surface water	D4	high	climate change impacts	✓
Sediment	D4	high	plant/animal tissue data	$\Diamond$
Soil	C1	high		

#### Location and land use info

SE Of Int Of 5th St N & Railroad Ave, Skykomish, King County, 98288

Primary parcel 2626119017

Land use transportation
Responsible unit NWRO

#### Sources reviewed

BNSF Railway Skykomish - Progress Report - 2nd Quarter 2025, 7/15/25
BNSF Railway Skykomish - 2023 Annual Long-Term Monitoring Report, 5/22/2024
BNSF Railway Skykomish - 2023 Annual Hydraulic Control and Containment System
Operations Report, 5/22/24

Primary census tract	Associated census tracts
53033032800	SHARP it

#### Local demographics comments

# **BNSF Railway Skykomish** EJScreen not available Source/source area description ASTs, USTs, petroleum conveyance infrastructure, and maintenance areas on the railyard are the sources of contamination. **Soil comments** no comments **Groundwater comments** no comments

## **Surface water comments**

no comments

# **BNSF Railway Skykomish**



Sediment comments	
no comments	
Indoor air comments	
no comments	
Additional factors comments no comments	
no comments	
Site history	Go to to
The site is a former railway maintenace and fueling facility. Historical activities incldued refueling and	
maintaining locomotives and operating an electrical substation.	

BNSF Railway Skykomish	
	SHARP
Overflow - Site contamination and cleanup history	
	Cabaal
rkemaining contamination is primarily located on the railyard parcel listed above and the Skykomish.	SCHOOL
Remaining contamination is primarily located on the railyard parcel listed above and the Skykomish parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume under	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	
parcel 5060800005. Much of the town is still under a Restrictive Covenant, although the plume unde	

1	BNSF Railway Skykomish	SHARP

**BNSF Railway Skykomish** 

34 BNSF Railway Skykomish 20250828

**First SHARP** 

**SHARP** rating — Low

SHARP Report — Part 2 of 2

Conceptual site model 08/28/2025





