4919 Tiger Oil 24th Avenue and West Nob Hill 20250925


First SHARP

SHARP rating — Medium

SHARP Report — Part 2 of 2

Conceptual site model 09/25/2025







SHARP Report — Part 1 of 2

Go to site contamination history

• SHARP first SHARP		v2024.04.29	Ecology	/ Info
 SHARP rating 	Medium		ERTS	none
 SHARP date 	09/25/2025		CSID	4919
EJFlagged?	🛇 - Overridden		FSID	469
 LD confidence level 	low		VCP	none
 Cleanup milestone 	site hazard assessment		UST ID	9858
• SHARPster	Monahan		LUST ID	5560

SHARP Media	Scores	Confidence	Additional Factors	
Indoor air	A2	medium	multiple chemical types	~
Groundwater	C1	high	risk to off-site people	✓
Surface water	D4	medium	climate change impacts	✓
Sediment	D4	high	plant/animal tissue data	\otimes
Soil	C1	high		

Location and land use info

2312 West Nob Hill Boulevard, Yakima, Yakima County, 98902

Primary parcel SHARP it
Land use commercial
Responsible unit CRO

Sources reviewed			



	SHÄRP
Primary census tract	Associated census tracts
53077001000	
Local demographics co	mmonte
	resent on the WTN website, including high unemployment, various education
	d low English speaking population rates.
lactors, high poverty rates, an	d low Eligibil speaking population rates.
0	
Source/source area des	·
	an underground product line impacted soils and groundwater at ths site.
_	soline petroleum hydrocarbons and BTEX. In the early 2020s, additional
	discovered at the site. These include halogenated volatile organic compounds;
	hloride. Subsequent investigations revealed that these are coming from an off-site
source west of the Tiger Oil pr	operty.
Soil comments	
no comments	
Groundwater comments	
no comments	,



	SIIAKI
Surface water comments	
no comments	
Sediment comments	
no comments	
Indoor air comments	
no comments	
Additional factors comments	
no comments	
no comments	



Site history <u>Go to t</u>	op
Site was used as a bulk petroleum fuel distributing site until the release in 1982. Shortly after the release, the	
site ceased operating as a bulk fuel distributor. It is currently a vacant lot covered with gravel.	



Overflow -	· Site contamination and cleanup history
No overflow	