

Musa, Donna K. (ECY)

From: Musa, Donna K. (ECY)
Sent: Thursday, December 12, 2013 11:25 AM
To: 'toni@wedenengineering.com'
Subject: Ecology Determination of No Further Action - Pilot Travel Center 583 Surface Spill
Attachments: Pilot Travel Center 583 ISIS summary.pdf

Hi Toni,

Attached is the database summary showing the status of the independent remediation performed at the Pilot Travel Center 583 (1678 Main Street, Ferndale) after the discovery of the diesel spill on February 7, 2013.

Ecology has determined that no further action is necessary (at the Initial Investigation stage) due to independent remediation. The Spill Cleanup Report provided by Whatcom Environmental (dated 10/16/13) provides sufficient documentation that this cleanup was conducted to MTCA Method A cleanup levels for unrestricted land use.

You may access additional information about the site cleanup here:

<https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=12261>

To view the documentation Ecology has available electronically, on the right-hand side of the page, click on [View Electronic Documents](#).

Please let me know if you have any questions!

Sincerely,

Donna Musa
Initial Investigation / Site Hazard Assessment Coordinator
Regional Facility Site / ISIS Database Coordinator
NWRO Toxics Cleanup Program, WA Dept of Ecology
3190 160th Ave SE, Bellevue WA 98008
Phone: 425-649-7136
Fax: 425-649-7098
donna.musa@ecy.wa.gov