

COORDINATOR: DAVID HOVIK

UNIQUE RECORD #: N6769

REGION: N

DATE/TIME REC'D: 11/06/91

16:00:40

REPORT TYPE: INITIAL

REPORTER'S NAME: HARRY BUSH

BUSINESS NAME:

BISON ENVIRONMENTAL

ADDRESS:

WA

BEST TIME

OR ANONYMOUS:

TO CALL:

WORK PHONE: (206)-838-7261 EXT.

HOME PHONE:

DETAILS ON INCIDENT:

COUNTY: KING

NEAREST CITY: SEATTLE

WATERWAY:

WRIA #:

LOCATION: *[Handwritten signature]*

WEATHER: UNKNOWN

TIDE:

DETAILS ON ALLEGED VIOLATOR:

NAME & ADDRESS:

LIDLAW TRANS

13523 LAKE CITY WAY NE

SEATTLE

WA 98125

CONTACT'S NAME:

STEVEN WILSON

PHONE NUMBER AND EXT:

(206)-365-7300

VEHICLE INFORMATION:

DESCRIPTION OF CONTAMINANT: (PROVIDED BY REPORTER)

MEDIUM: SOIL

MATERIAL: OIL/PETROLEUM

OTHER: PETROLEUM

QUANTITY: UNK

SOURCE: UST/LUST

COMMENTS: REMOVING 15K DIESEL TANK. LOTS IN HOLE FROM OVERFILL. TANK HAD GASOLINE YEARS AGO. LOTS OF GASOLINE IN SOIL. ABOUT 40 FT DOWNGRADE FROM STORMGRATE. BUT ANOTHER GRATE DOWNGRADE FROM TANK. HAVING SAMPLES ANALYZED. WHEN REPORT IS BACK WILL BEGIN REMEDIATING.

Diesel tank removed on 11/5/91 -; On 11/4/91 - Vacuum truck removed tank contents; on 11/12/91 - Vacuum truck removed 3700 gallons. On Wed 11/6/91 pumped 700 gallons.

REFERRED TO PROGRAM: HWICP

SECTION HEAD: GALLAGHER

EXTERNAL REFERRAL? (Y/N): N

IF EXTERNAL. WHAT AGENCY: _____

INVESTIGATION COMPLETED? (Y/N): *NY*
IF YES. COMPLETE SECOND PAGE OF FORM.

INTERNAL REFERRAL INFORMATION:

NAME OF STAFF PERSON: *Annette Petrie*

DATE RECEIVED: *11/12/91*
DATE INVESTIGATED: *11/13/91*
DATE COMPLETED: *11/13/91*

ACTION TAKEN: *site inspection*
CAUSE OF INCIDENT: *UST*
IMPACT: *soil*

LUST: *Y*

NONPOINT: (UNK. GW. SW) POINT: (UNK. SW. PRETMT)

ACTUAL VIOLATOR INFORMATION:

NAME: *same*

CONTACT:

ADDRESS:

CITY:

HOME:

WORK:

ACTUAL CONTAMINANT:

MEDIUM: *soil*

MATERIAL: *petroleum*

QUANTITY: *unknown*

SOURCE: *UST*

OTHER:

ENFORCEMENT SENSITIVE? (Y/N): *N*

CROSS-REFERENCES TO OTHER SYSTEMS: *LUST*

OTHER RELEVANT INFORMATION:

*Lee Morse is the contractor - Lee or Steve are contacts.
Harry Bush has been taking samples during tank removal & cleanup.
450 tons of contaminated soil went to Sterling
Asphalt.
Installed new tank on 11/12/91. Hole is partially backfilled.*