

ENVIRONMENTAL HEALTH DIVISION

3020 Rucker Avenue, Suite 104 Everett, WA 98201-3900 425.339.5250 FAX: 425.339.5254 Deaf/Hard of Hearing: 425.339.5252 (TTY)

· Healthy Lifestyles, Healthy Communities -

January 9, 2006

Helmuth K. Schlueter P. O. Box 40 Duvall, Washington 98019

Subject:

Site Hazard Assessment – Schleuter Property

Latitude: 47°49' 13.19"

Longitude: 122°12' 42.08"

Facility ID: 2886743

Section 18 Township 27N Range 5E

ERTS: 545943

Dear Mr. Schueter:

The Snohomish Health District has completed the Site Hazard Assessment (SHA) of the Scheuter (Schlueter) Property site, as required under the Model Toxics Control Act. This site's hazard ranking, an estimation of the potential threat to human health and/or the environment relative to all other Washington State sites assessed at this time, has been determined to be a 4, where 1 represents the highest relative risk and 5 the lowest.

For your information, the Department of Ecology (Ecology) will be publishing the results of this, and other recently assessed sites in the *February 22, 2006, Special Issue of the Site Register*. The site hazard ranking will be used in conjunction with other site-specific considerations in determining Ecology's priority for future actions.

Please contact me at 425.339.5250 if you have any questions relating to the SHA of your site. If you have any inquiries/comments about the site scoring/ranking process, please call Michael Spencer at 360.407.7195. For inquiries regarding any further activities at your site now that it is on Ecology's Hazardous Sites List, please call Louise Bardy at 425.649.7000.

Sincerely,

Geoffrey W. Crofoot, R.S.

Environmental Health Specialist Solid Waste and Toxics Section

GWC:sei

Enclosures

cc: Michael Spencer, Department of Ecology Louise Bardy, TCP - NWRO