

---

## 13.0 REFERENCES

- Adamson, D.T., T.M. McGuire, C.J. Newell, and H. Stroo. 2011. "Sustained Treatment: Implications for Treatment Timescales Associated with Source-Depletion Technologies." *Remediation Journal* 21 (2):27-50. doi: 10.1002/rem.20280.
- AFCEE. 2004. Principles and Practices of Enhanced Anaerobic Bioremediation of Chlorinated Solvents. Air Force Center for Environmental Excellence. August.
- AGI. 1996a. Closure Plan Supplement - 17-07 Acid Waste Hold Tank, WAD 041337130. March.
- AGI. 1996b. Closure Plan Supplement - 17-07 Cyanide Waste Hold Tank, WAD 041337130. March.
- AGI. 1996c. Final Closure Report, RCRA Acid and Cyanide Tank Closures, 17-07 Building, BCAG-Fabrication Division, Auburn, Washington. AGI Technologies. November 1.
- AGI. 1996d. Soil and Groundwater Assessment Acid Scrubber Drain Line Leak, 17-07 Building, BCAG-Fabrication Division, Auburn, Washington. AGI Technologies. November 8.
- AGI. 1997a. Soil and Groundwater Assessment, Aerator Tank, Wastewater Pretreatment Plant BCAG - Fabrication Division, Auburn, Washington. July 18.
- AGI. 1997b. Letter: Summary Report Soil and Groundwater Characterization Rinsewater Release from Vault, Auburn, Washington. From Peter Barry and Martin Carlson, AGI Technologies, to Jeanette Ramos, Manager Environmental Affairs, The Boeing Company. December 11.
- AGI. 1998a. Summary Report - Soil Characterization Rinsewater Release at Wastewater Pretreatment Plant, Auburn, Washington. March.
- AGI. 1998b. Letter: Summary Report Former Waste Pile Soil Investigation Southwest of Building 17-64. From AGI Technologies, to Ken Macnair, Boeing Commercial Airplane Group, The Boeing Company. July 13.
- AGI. 1999a. Soil Assessment Conducted During Trench Excavation for Oily Waste Pipe Replacement, Wastewater Pretreatment Plant, Building 17-15, Boeing Commercial Airplanes Group, Auburn Facility, Auburn, Washington. November 8.
- AGI. 1999b. Soil Characterization Summary Report, Existing Oily Waste Piping, West Building 17-07 to Wastewater Treatment Plant, Auburn, Washington. May 5.
- AGI. 1999c. Soil Characterization Summary Report, New Oily Waste Pipe Location, West of Building 17-07 to Wastewater Treatment Plant, Auburn, Washington. October 26.
- AGI. 1999d. Letter: Summary Report Pit and Sump Inspection (SWMU S-08), Pit and Sump SAU45-017, Paint Booth 4, Building 17-45, Boeing Commercial Airplane Group, Auburn Facility, Auburn, Washington. From David Dawson and Peter Barry, AGI Technologies, to Kennedy Macnair, Boeing Commercial Airplane Group, The Boeing Company. October 21.

- AGI. 1999e. Letter: Summary Report Soil Characterization Release from Secondary Containment Rinse-Water Transfer Pipe (Building 17-68), Auburn, Washington. From David Dawson and Martin Carlson, AGI Technologies, to Kennedy Macnair, Boeing Commercial Airplane Group, The Boeing Company. October 1.
- AGI. 2000. Final: Summary Report, RCRA SWMU S-15 Sump Inspection Program, Boeing Commercial Airplanes Group, Auburn Facility, Auburn, Washington.
- AMTEST. 1993. Boeing Commercial Airplane Group, Spray Painting Booths, Building 17-45 Transfer, Capture, and Removal Efficiencies, Auburn, Washington. Am Test-Air Quality, Inc. October 6 and 30.
- AMTEST. 1996. Source Emission Evaluation, Boeing Commercial Airplane Group, Spray Painting Booths, Building 17-45, Auburn, Washington. Am Test-Air Quality, Inc. May 22-24.
- Ballapragada, B.S., H.D. Stensel, J.A. Puhakka, and J.F. Ferguson. 1997. "Effect of Hydrogen on Reductive Dechlorination of Chlorinated Ethenes." *Environmental Science & Technology* 31:1728-1734.
- Beneteau, K.M., R. Aravena, and S.K. Frape. 1999. "Isotopic Characterization of Chlorinated Solvents - Laboratory and Field Results." *Organic Geochemistry* 30 (8 part 1):739-753. doi: 10.1016/S0146-6380(99)00057-1.
- Boeing. 1976a. Facilities Engineering Report R-17-05-4-90 Vapor Degreaser, Shop A-3280. The Boeing Company. October 29.
- Boeing. 1976b. Facilities Engineering Report R-17-07-4-87, Vapor Degreaser, Shop A-3250. The Boeing Company.
- Boeing. 1985a. Boeing Commercial Airplane Company Fabrication Division Sludge Pile Delisting Petition. The Boeing Company. November.
- Boeing. 1985b. Letter: Groundwater Monitoring Parameters, Sludge Pile Monitoring Wells, Boeing Auburn Facility. From K.J. Kinzer, The Boeing Company, to George Hofer, US Environmental Protection Agency. June 17.
- Boeing. 1986a. Boeing Auburn North Lagoon Closure Report and Engineer's Certification. The Boeing Company.
- Boeing. 1986b. RCRA Part B Permit Application. Publication No. EPA 530 SW-84-004. US Environmental Protection Agency. November 21.
- Boeing. 1987a. Letter: Boeing Auburn Notification of Intent to Submit a Request for a Variance from 40 CFR 264.193, Tank Secondary Containment Requirements. From The Boeing Company, to Roger Fuentes, The Environmental Protection Agency. January 6.
- Boeing. 1987b. Letter: North Lagoon Closure Report and Engineering Certification. From D.I. Peterson, The Boeing Company, to John Conroy, Washington State Department of Ecology. July 2.

- 
- Boeing. 1990a. Letter: Notification of Intent to Remove Underground Storage Tanks (UST). From R M Love, The Boeing Company, to Thorn Lufkin, Washington State Department of Ecology. July 18.
- Boeing. 1990b. Letter: Solid Waste Disposal Plan for the Boeing Auburn Plant. From R.M. Love, The Boeing Company, to W.C. Swofford, Seattle-King County Department of Health. June 12.
- Boeing. 1993. Independent Cleanup Action, Fuel Island, 17-64 Building, Boeing, Auburn. The Boeing Company. May.
- Boeing. 1994. Letter: Report of Release Pursuant to WAC 173-340-300(2), 17-05 Building, Boeing-Auburn Site. From H.F. Alsid, The Boeing Company, to Northwest Regional Office, Washington State Department of Ecology. July 12.
- Boeing. 1995a. Letter: Discovery and Remediation of Small Fuel Oil Spills. From Hal Asid, The Boeing Company, to Dean Yasuda, Washington State Department of Ecology. February 23.
- Boeing. 1995b. Letter: Initial Notification Report and Removal of Two Batch Vapor Degreaser Units from Buildings 17-05 and 17-07. From Jenette Ramos, The Boeing Company, to Chris Hall, US Environmental Protection Agency. August 21.
- Boeing. 1995c. Letter: Internal Correspondence: Removal of Phillips Vapor Degreaser, Building 17-07. From Charley Austin, The Boeing Company, to T.Ortega and N.Currie, The Boeing Company. December 15.
- Boeing. 1995d. Letter: Notice of Construction (NOC) No. 3614 - Equipment Deletion for the Degreasers in Buildings 17-12 and 17-68. From H F Alsid, The Boeing Company, to Abigail C Lee, Air Pollution Engineer, Puget Sound Clean Air Agency. February 14.
- Boeing. 1995e. Letter: Proposal to Address Lead and Cadmium in Soil Adjacent to the 17-07 Building, Alkaline Waste Tank Closure and Boeing's Auburn, Washington Facility. From Jenette Ramos, The Boeing Company, to Julie Sellick, Washington State Department of Ecology. July 28.
- Boeing. 1996. Letter: Closure of the Acid and Cyanide Waste Holding Tanks, Building 17-07, Boeing, Auburn, Washington. From Jenette Ramos, The Boeing Company, to Dean Yasuda, Washington State Department of Ecology. December 17.
- Boeing. 2003a. Letter: MTCA Release Notification, 17-15 Building Wastewater Pretreatment Plan, Boeing Auburn Facility. From Edward Cierebiej, The Boeing Company, to Steven Bremer, Toxics Cleanup Program, Washington State Department of Ecology. June 10.
- Boeing. 2003b. Letter: Part A Permit Application for Boeing Commercial Airplanes, Fabrication Division - Auburn Plant, WAD041337130. From James Bet, The Boeing Company, to Robin Harrover, Washington State Department of Ecology. February 21.
- Boeing. 2003c. Letter: Proposed Property Transfer of Auburn North Parcel to YMCA - November Groundwater Sample Results. From James Bet, The Boeing Company, to Robin Harrover, Washington State Department of Ecology. January 14.

- 
- Boeing. 2004a. Letter: Dangerous Waste Permit Application, Part A Form for Boeing Commercial Airplanes, Fabrication Division - Auburn Plant, WAD041337130. From James Bet, The Boeing Company, to Robin Harrover, Washington State Department of Ecology. June 15.
- Boeing. 2004b. Letter: Sentry Well Groundwater Results - June 2004, Boeing Commercial Airplanes, Fabrication Division - Auburn Plant. G-1241-JNB-154. From The Boeing Company, to John Walsh, City of Pacific. September 10.
- Bradley, P.M, and F.H. Chapelle. 1999a. "Methane as a Product of Chloroethene Biodegradation under Methanogenic Conditions." *Environmental Science & Technology* 33 (4):653-656. doi: 10.1021/es981027+.
- Bradley, P.M, and F.H. Chapelle. 1999b. "Role for Acetotrophic Methanogens in Methanogenic Biodegradation of Vinyl Chloride." *Environmental Science & Technology* 33 (19):3473-3476. doi: 10.1021/es990395q.
- Bradley, P.M, and F.H. Chapelle. 2000. "Acetogenic Microbial Degradation of Vinyl Chloride." *Environmental Science & Technology* 34 (13):2761-2763. doi: 10.1021/es991371m.
- Carollo Engineers. 2015. City of Auburn Comprehensive Water Plan. October.
- CDM. 2000. Soil Assessment Conducted During Preliminary Construction of Chemical Tanker Transfer Station, Building 17-07, Boeing Commercial Airplanes Group, Auburn Facility, Auburn, Washington. Camp Dresser & McKee. December 20.
- CDM. 2001a. PCB Cleanup Report, G&L Post Mill Machine Pit, 17-10 Building, Auburn, Washington. December 12.
- CDM. 2001b. Soil Removal and Sampling, Electrical Trench West of Former G&L Post Mill Machine, Building 17-10, Column 3, Boeing Commercial Airplanes Group/Auburn Facility, Auburn, Washington. November 8.
- CDM. 2001c. Summary Report: Pretreatment Plant Clarifier Tank Release, Soil Investigation/Cleanup, BCAG Auburn, Washington. October 9.
- CDM. 2003a. Letter: Assessment and Verification Sampling, Wastewater Pre-Treatment Plant Sump Closure Building 17-15, Boeing Commercial Airplanes, Auburn Facility, Auburn, Washington. From Alan Carey, Camp Dresser & McKee, Inc., to Kennedy Macnair, Boeing Commercial Airplanes, The Boeing Company. April 8.
- CDM. 2003b. Summary Report, Cleanup and Groundwater Sampling, Building 17-15, Boeing Commercial Airplanes, Auburn Facility, Auburn, Washington. June 10.
- CDM. 2003c. Letter: Summary Report, Soil Cleanup and Groundwater Sampling, Building 17-15, Boeing Commercial Airplanes/Auburn Facility, Auburn, Washington. From Alan Carey, to James Bet, The Boeing Company. June 10.
- CDM. 2004. Summary Report, Soil Cleanup, South Substation, Boeing Commercial Airplanes/Auburn Facility, Auburn Washington. April 30.

- 
- Chambers, L.W., and J.M. Bahr. 1992. "Tracer Test Evaluation of a Drainage Ditch Capture Zone." *Ground Water* 30 (5):667-675. doi: 10.1111/j.1745-6584.1992.tb01552.x.
- Chapelle, F.H. 1996. Identifying Redox Conditions that Favor the Natural Attenuation of Chlorinated Ethenes in Contaminated Ground-Water Systems. Publication No. EPA/540/R-96/509. US Environmental Protection Agency.
- Charlton & Leach. 1995. Independent Remedial Action Report, The Boeing Company Government Canal Site, Final Report. Charlton & Leach, Inc. January 11.
- ChemRisk. 1992. Risk Assessment for Boeing Government Canal. August 24.
- City of Auburn. 1993. Solid Waste Disposal Agreement between Boeing Auburn Fabrication Division; RST Disposal, Inc.; and the City of Auburn. February 25.
- City of Auburn. 1997. Amendment to the Solid Waste Disposal Agreement between Boeing Auburn Fabrication Division; RST Disposal, Inc.; and the City of Auburn. August 15.
- City of Pacific. 2008. Water System Plan. February.
- Dames & Moore. 1985. Characterization of Site Geology and Hydrogeology and Proposed Detection Monitoring Program, Auburn Facility, Auburn, Washington. August 30.
- Dames & Moore. 1986. Letter: Groundwater Monitoring Near the North and South Lagoons. From Paul W. Agrid, to Hal Alsid, The Boeing Company. June 18.
- Dames & Moore. 1987a. Burn Pit/Tank Area Soil Sampling and Analysis Report. July 17.
- Dames & Moore. 1987b. Report of Site Contamination Assessment and Geotechnical Investigation Proposed Sheet Metal Fabrication Building 17-45, Boeing Auburn Plant, Auburn, Washington. Dames & Moore. July 10.
- Dames & Moore. 1988a. Boeing Auburn Fabrication Division Rinse Water Treatment Plant Phase II, North Lagoon Closure Final Closure Certification Report. September 26.
- Dames & Moore. 1988b. South Lagoon Closure Report and Engineer's Certification, Boeing Auburn Fabrication Division. November.
- Dames & Moore. 1988c. Supplemental Report: USTs, March 1988 Ground-Water Monitoring and May 1988 Resampling. June 27.
- Devlin, J.F. 2003. "A Spreadsheet Method of Estimating Best-Fit Hydraulic Gradients Using Head Data from Multiple Wells." *Ground Water* 41 (3):316-320.
- Dragovich, J.D., P.T. Pringle, and T.J. Walsh. 1994. "Extent and Geometry of the Mid-Holocene Osceola Mudflow in the Puget Lowlands: Implications for Holocene Sedimentation and Paleogeography." *Washington Geology* 22 (3):3-26.

- 
- Driscoll, Fletcher G. 1986. *Groundwater and Wells*. 2nd ed. St. Paul, MN: Johnson Filtration Systems, Inc.
- E.S.P. 1998. Sump Management Pilot Study Summary Report. Engineering Support Personnel, Inc. April 6.
- Ecology. 1989. Approval of BCA Prevention of Significant Deterioration, Application, and Attachments. Washington State Department of Ecology. April 24.
- Ecology. 1991. Solid and Hazardous Waste Program Inspection Report. Washington State Department of Ecology. June 19.
- Ecology. 1994a. Letter: Ecology Acceptance of Certification of Clean Closure of the 17-05 Building 40,000 Gallon Waste Hold Tank. From Julie Sellick, Supervisor Hazardous Waste and Toxics Reduction Section, Washington State Department of Ecology, to Jeff Kellett, Boeing Commercial Airplane Group, The Boeing Company. August 4.
- Ecology. 1994b. Natural Background Soil Metals Concentrations in Washington State. Publication No. 94-115. Washington State Department of Ecology. October.
- Ecology. 1995. Letter: Ecology Review, Geoenvironmental Services, Government Canal Remedial Excavation, Algona, Washington. From Mary K O'Herron, Environmental Specialist, Toxics Cleanup Program, State of Washington Department of Ecology, to Paul Johansen, The Boeing Company. April 17.
- Ecology. 1997. Letter: Ecology Acceptance of Certification of Clean Closure of the 17-07 Building, 2000 Gallon Waste Cyanide and 2000 Gallon Waste Acid Underground Storage Tanks (USTs) at the Boeing Auburn Facility - WAD 041337130. From Julie Sellick, State of Washington Department of Ecology, to Jeanette Ramos, The Boeing Company. January 13.
- Ecology. 2002a. Agreed Order No. 01HWTRNR-3345, In the Matter of Remedial Action by: the Boeing Company and The Potentially Liable Parties. State of Washington Department of Ecology. May 15.
- Ecology. 2002b. Letter: Letter of Determination and transmittal of Final Agreed Order No. 01HWTRNR-3345 and Stipulated Amendment No. 1 to the Agreed Order, WAD041337130. From Robin Harrover, Hazardous Waste and Toxics Reduction Program, State of Washington Department of Ecology, to James Bet, SSG Environmental Remediation, The Boeing Company. September 5.
- Ecology. 2003a. Letter: Ecology Approval of the Boeing Company's Permit Modification to Revise Part A of the RCRA Permit Application for the Boeing Commercial Airplanes, Fabrication Division - Auburn Plant, WAD041337130. From Julie Sellick, Washington State Department of Ecology, to James Bet, The Boeing Company. February 27.
- Ecology. 2003b. Letter: Proposed Property Transfer of Boeing Commercial Airplane Group - Auburn North Parcel to the YMCA of Greater Seattle. From Robin Harrover, Washington State Department of Ecology, to James Bet, The Boeing Company. February 3.

- Ecology. 2004a. Letter: Determination for SWMUs and AOCs within or near the Area I Property Boundary. From Robin Harrover, Washington State Department of Ecology, to James Bet, The Boeing Company. April 24.
- Ecology. 2004b. Implementation Memorandum #5, Collecting and Preparing Soil Samples for VOC Analysis. Publication No. 04-09-87. Washington State Department of Ecology. June.
- Ecology. 2004c. Letter: Letter of Determination for SWMUs and AOCs within or near the Area 1 Property Boundary based on Ecology review of the expedited Area 1 Remedial Investigation Report and Supplemental Area 1 Remedial Investigation Report, Boeing Commercial Airplanes Group, Fabrication Division - Auburn Plant, WAD041337130. From PG Robin Harrover, PHg, Hazardous Waste and Toxics Reduction Program, State of Washington Department of Ecology, to James Bet, Environmental Affairs, The Boeing Company. April 29.
- Ecology. 2005. State Dangerous Waste Permit, Modified Agreed Order, and Modified Interim Action Work Plan Available for Public Review and Comment. Washington State Department of Ecology. December.
- Ecology. 2006a. Letter: Finalization of State of Washington Dangerous Waste Management Permit for Corrective Action No. WAD041337130 and First Amended Agreed Order No. 01HWTRNR-3345 for Continued Implementation of a Remedial Investigation/Feasibility Study at the Boeing Commercial Airplanes, Fabrication Division - Auburn Plant. From Robin Harrover, Washington State Department of Ecology, to Kirk Thomson and Steve Campbell, The Boeing Company. February 21.
- Ecology. 2006b. First Amended Agreed Order No. 01HWTRNR-3345; In the Matter of Remedial Action by: The Boeing Company and AMB Property Corporation, to The Potentially Liable Parties. State of Washington Department of Ecology. April 7.
- Ecology. 2007a. Letter: Review and Comment Regarding the Document: Agency Review, Remedial Investigation Report, Boeing Auburn Fabrication Division Facility, Auburn, Washington; Prepared for Boeing by Landau Associates; September 10, 2005 (WAD041337130). From LG Robin Harrover, LHg, Hazardous Waste and Toxics Reduction Program, Washington State Department of Ecology, to Mr. James Bet, Environment, Safety, and Health - Remediation, The Boeing Company. August 13.
- Ecology. 2007b. "Toxics Cleanup Program Tools & Resources, Assessing Risk/Establishing Cleanup Levels, Workbook Tools for Calculating Cleanup Levels for Individual Substances and TPH." Washington State Department of Ecology.  
<http://www.ecy.wa.gov/programs/tcp/tools/toolmain.html>.
- Ecology. 2008. Letter: Review and Comment Regarding the Document: Revised Agency Review Draft Remedial Investigation Report, Boeing Auburn Fabrication Division Facility, Auburn, Washington WAD041337130. From Robin Harrover, Hazardous Waste Specialist, Washington State Department of Ecology, to James Bet, Environmental Affairs, The Boeing Company. April 16.
- Ecology. 2009a. Guidance for Evaluating Soil Vapor Intrusion in Washington State: Investigation and Remedial Action. Publication No. 09-09-047. Washington State Department of Ecology. October.

- 
- Ecology. 2009b. Letter: Review and Comment Regarding the Document: 2nd Revised Ecology Review Draft Remedial Investigation Report, April 10, 2009, Boeing Auburn Fabrication Division Facility, Auburn, Washington WAD041337130. From LG Robin Harrover, LHg, Hazardous Waste Specialist, Hazardous Waste and Toxics Reduction Program, to James Bet, Environmental Affairs, The Boeing Company. June 19.
- Ecology. 2012a. Letter: Ecology Comment and Approval Letter for the Report: Technical Memorandum, Agency Review Draft - Proposed Cleanup Levels and Screening Levels, Remedial Investigation Vapor Intrusion Assessments, Boeing Auburn Facility WAD041337130. From LHG Robin Harrover, Hazardous Waste and Toxics Reduction Program, Washington State Department of Ecology, to James Bet, Environmental Affairs, The Boeing Company. November 28.
- Ecology. 2012b. Letter: Ecology Comments Regarding the Spring and Fall 2011 Remedial Investigation Data Summary Reports; Prepared for Boeing by Landau Associates March 1, 2012 and May 17, 2012 (respectively); WAD041337130. From Robin Harrover, Hazardous Waste and Toxics Reduction Program, Washington State Department of Ecology, to James Bet, Environmental Affairs, The Boeing Company. August 31.
- Ecology. 2013. Letter: Ecology Review and Approval of Site-Specific Surface Water Screening Levels for Evaluation of the Yard and Ditch SW Sampling in Residential North Algona; FSID #2018, CSID #5049, and WAD041337130. From Robin Harrover LHG, Northwest Regional Office, Washington State Department of Ecology, to James Bet, EHS Remediation Group, The Boeing Company. November 22.
- Ecology. 2014. Letter: Ecology Comments Regarding the Draft Technical Memorandum: July 2013 Surface Water Investigation, Boeing Auburn Facility, Auburn, Washington; FS ID #2018; CS ID #5049; EPA ID #WAD041337130. From Robin Harrover, Hazardous Waste and Toxics Reduction Program, Washington State Department of Ecology, to James Bet, Environmental Affairs, The Boeing Company. January 23, 2014.
- Ecology. 2015. "Cleanup Levels and Risk Calculations (CLARC)." Washington State Department of Ecology. <https://fortress.wa.gov/ecy/clarc/CLARCHome.aspx>.
- Ecology. 2016. Letter: Ecology Comment regarding the Draft Remedial Investigation Report, Boeing Auburn Facility, Auburn, WA; prepared for The Boeing Company by Landau Associates; August 5, 2016; FS #2018; CS #5049; EPA WAD041337130. From Robin Harrover LHG, Hazardous Waste and Toxics Reduction Program, State of Washington Department of Ecology, to James Bet, Environmental Affairs, The Boeing Company. November 9.
- EPA. 1992. Inspection Report, Boeing Commercial Airplane Group, Auburn. US Environmental Protection Agency. August 14.
- EPA. 1997. Exposure Factors Handbook (1997 Final Report). Publication No. EPA/600/P-95/002F a-c. US Environmental Protection Agency. August.
- EPA. 2005. Letter: PCB Hydraulic System Remedial Plan Approval. From Scott Downey, Manager, Pesticides and Toxics Unit, U.S. Environmental Protection Agency, to Peter Weickmann, Auburn Site Environmental Manager, The Boeing Company. August 26.

- 
- EPA. 2008. A Guide for Assessing Biodegradation and Source Identification of Organic Ground Water Contaminants using Compound Specific Isotope Analysis (CSIA). Publication No. EPA 600/R-08/148. National Risk Management Research Laboratory Office of Research and Development, December.
- EPI. 2005. Environmental Site Review, Boeing Auburn - Area 1, 700 15th Street SW, Auburn, Washington 98002. Environmental Partners, Inc. July 27.
- ERT. 1988. Prevention of Significant Deterioration Permit Application for the New Sheet Metal Center - Final Report. September.
- ESP. 1998. Final: Sump Management Pilot Study Summary Report. Engineering Support Personnel, Inc. April 6.
- Fetter, C.W. 1993. *Contaminant Hydrogeology*. 4th ed. Upper Saddle River, NJ: Prentice-Hall, Inc.
- Fetter, C.W. 2001. *Applied Hydrogeology*. 4th ed. Englewood Cliffs, NJ: Prentice-Hall, Inc.
- Freeze, R.A., and J.A. Cherry. 1979. *Groundwater*. Englewood Cliffs, NJ: Prentice-Hall, Inc.
- G-Logics. 2009. Groundwater Sampling, January 2009, Commercial Property, 401 Lunch Road, Auburn, Washington. January 26.
- GeoEngineers. 1986. Report: Phase I Site Assessment Report BCAG Auburn Facility Auburn, Washington for The Boeing Company. GeoEngineers, Inc. December 12.
- GeoEngineers. 1991a. Removal of Underground Sumps. October 21.
- GeoEngineers. 1991b. Report of Geoenvironment Services, Subsurface Assessment, Two Underground Storage Tanks near Building 17-06, Auburn, Washington. May 23.
- GeoEngineers. 1991c. Report of Geoenvironmental Services Building 17-35 Removal of Underground Sumps AU-34 and AU-35, Boeing Fabrication Division Auburn, Washington for The Boeing Company. October 31.
- GeoEngineers. 1991d. Report: Sump Tank Removal and Replacement Building 17-29, Auburn, Washington. May 23.
- GeoEngineers. 1992a. Phase II Investigation Government Canal, King and Pierce Counties, Washington. October 7.
- GeoEngineers. 1992b. Report of Geoenvironmental Services, Drilling Additional Soil Borings, Building 17-06, Boeing Fabrication Division, Auburn, Washington. April 6.
- GeoEngineers. 1992c. Report of Geoenvironmental Services, Removal of Underground Methyl Ethyl Ketone Storage Tank (Tank AU-18), Boeing Fabrication Division, Auburn, Washington. April 7.
- GeoEngineers. 1995. Report Geoenvironmental Services Government Canal Remedial Excavation, Algona, Washington. January 19.

- 
- GeoEngineers. 1997. Site Characterization Report, 17-29 Titanium Bailing Area, Auburn, WA. June 24.
- GeoEngineers. 2005. Technical Memorandum: AMB-Boeing Auburn Vapor Intrusion. October 5.
- Geomatrix. 2003a. Area 1 Property Transfer Work Plan, Boeing Auburn Plant, Auburn, Washington. November.
- Geomatrix. 2003b. Remedial Investigation Work Plan, Boeing Auburn Plant, Auburn, Washington. Geomatrix Consultants. October.
- Geomatrix. 2004. Area 5 Property Transfer SWMU/AOC Summary and Evaluation, Boeing Auburn Plant, Auburn, Washington. Geomatrix Consultants. February 11.
- Geomatrix. 2006. 17-34 Closure Supporting Documentation. January.
- Harrover, Robin. 2003. "Re: Draft Push Probe Investigation Work Plan, YMCA Parcel, Boeing Auburn Facility." Washington State Department of Ecology. February 13.
- Hart Crowser. 1986a. Auburn Hazardous Waste Storage Facility Potential Contamination Assessment, Auburn, Washington. Hart Crowser & Associates, Inc. May 15.
- Hart Crowser. 1986b. Letter: Sump and Contaminated Soil Removal Hazardous Waste Storage Facility, Auburn, Washington. From Russell Prior and Mark Utting, Hart Crowser, Inc., to Dave Smukowski and Steve Tochko, BE & C Engineers. July 11.
- Hart Crowser. 1987. Letter: Auburn Plant, Building 17-52 Battery Wash Pad Assessment. From Hart Crowser, Inc., to Roger Fuentes, The Boeing Company. November 2.
- Jacob, C.L., C.N. Venot, E.F. Weber, C.M. Bach, and J.N. Bet. 2010. Implications of Complete Reductive Dechlorination Persisting Years after Electron Donor Injection - Two Case Studies. May.
- Kennedy/Jenks. 1985. Study to Replace Auburn Waste Treatment Plant Lagoons with Above Ground Storage, The Boeing Commercial Airplane Co. Fabrication Division. Kennedy/Jenks Consultants. August.
- Kennedy/Jenks. 1991. Technical Report, Preliminary Subsurface Investigation Rinsewater Treatment Plant, Boeing Auburn. Kennedy/Jenks Consultants. November.
- Kennedy/Jenks. 1992a. Compliance Monitoring Report, Regulated Material Storage Facility, Construction Site, Boeing Auburn. October.
- Kennedy/Jenks. 1992b. Letter: Transmittal of Laboratory Analysis Reports, Building 17-03 Subsurface Investigation BECE No. 0071; WOR No. AUB-A-92466-245. From Susan Roth, Kennedy/Jenks Consultants, to Jeff Kellett, Boeing Commercial Airplane Group, The Boeing Company. November 13.
- Kennedy/Jenks. 1993a. Closure Report - Alkaline Waste Hold Tank 17-07 Building, Boeing Auburn. Kennedy/Jenks Consultants. December 30.

- 
- Kennedy/Jenks. 1993b. Environmental Compliance Monitoring Report, Rinse Water Treatment Plant Technical Report. January.
- Kennedy/Jenks. 1993c. Independent Remedial Action: 17-66 Building East Construction Site, Boeing Auburn. October.
- Kennedy/Jenks. 1993d. Letter: Observation, Sampling, and Testing 17-08 Building Acid Sump Removal, Boeing Commercial Airplane Group - Auburn, Washington. From Thomas Morin and John Norris, Kennedy/Jenks Consultants, to Mike Reeve, Boeing Commercial Airplane Group, The Boeing Company. July 14.
- Kennedy/Jenks. 1993e. Letter: Report of Independent Cleanup Action Telephone Utility Trench Excavation Regulated Material Storage Facility Construction Site, Boeing Auburn. From Eric Chapman and John Norris, Kennedy/Jenks Consultants, to Michael Reeve, Chemical Process Engineer, The Boeing Company. May 19.
- Kennedy/Jenks. 1993f. Letter: Soil Sampling and Analytical Results Building 17-07 Aqueous Degreaser Pit Excavation, Boeing Auburn. From John Norris and Melissa Papworth, Kennedy/Jenks Consultants, to Mel Johnson, Boeing Commercial Airplane Group, The Boeing Company. February 1.
- Kennedy/Jenks. 1993g. Technical Report, Environmental Monitoring Report 17-03 Building Demolition, Boeing Auburn. Kennedy/Jenks Consultants. January.
- Kennedy/Jenks. 1994a. 17-08 Building Environmental Response Action, Boeing Auburn, K/J 936019.02. February 22.
- Kennedy/Jenks. 1994b. Closure Report Waste Hold Tank 17-05 Building. Kennedy/Jenks Consultants. June 17.
- Kennedy/Jenks. 1994c. Environmental Services, 17-02 and 17-05 Building Decontamination and Demolition Project, Boeing Auburn. May.
- Kennedy/Jenks. 1994d. Fact Summary - Former Metalbond Tanklines Degreaser Area, 17-05 Building, Boeing, Auburn. June 23.
- Kennedy/Jenks. 1994e. Final Closure Report Alkaline Waste Hold Tank 17-07 Building, Boeing Auburn. Kennedy/Jenks Consultants. September 14.
- Kennedy/Jenks. 1994f. Hydrogeologic Investigation, Rinsewater Treatment Plant Area. January.
- Kennedy/Jenks. 1994g. Letter: Proposal for Consulting Services, 17-05 Building Former Metalbond Tankline Degreaser Area Site Investigation and Remedial Action Planning, Boeing Auburn. From John Norris and Edward Kistner, Kennedy/Jenks Consultants, to Joan McGilton, Environmental Projects, The Boeing Company. May 2.
- Kennedy/Jenks. 1994h. Results of Site Characterization Study for 17-07 Building Alkaline Waste Hold Tank Closure, Boeing Auburn. Kennedy/Jenks Consultants. May 23.

- 
- Kennedy/Jenks. 1994i. Supplemental Closure Report Alkaline Waste Hold Tank 17-07 Building, Boeing Auburn. Kennedy/Jenks Consultants. July 20.
- Kennedy/Jenks. 1994j. Technical Report Hydrogeologic Investigation Regulated Material Storage Facility, Boeing Auburn. Kennedy/Jenks Consultants. January.
- Kennedy/Jenks. 1995. Technical Report, Hydrogeologic Investigation Building 17-05, Boeing Auburn. Kennedy/Jenks Consultants. February.
- Kennedy/Jenks. 1996a. Letter: Proposal for Professional Services Building 17-05 Area Hydrogeologic Characterization and Contaminant Source Identification. From John Norris and Melissa Papworth, Kennedy/Jenks Consultants, to Scott Cleary, Boeing Commercial Airplane Group, The Boeing Company. August 15.
- Kennedy/Jenks. 1996b. Subsurface Investigation, Building 17-07 Plating Shop Degreaser Area, Boeing Auburn. May.
- Kennedy/Jenks. 1996c. Technical Report, 1995 Hydrogeologic Investigations and Summary Report, Boeing Auburn. May.
- Kennedy/Jenks. 1997a. Building 17-03/17-05 Chrome Waste Piping Investigation, Boeing Auburn - Final. May.
- Kennedy/Jenks. 1997b. Final Report - Building 17-05 Vapor Degreaser Removal, Boeing Auburn. Kennedy/Jenks Consultants. April.
- Kennedy/Jenks. 1997c. Letter: Summary of Building 17-05 Area Characterization Activities in 1996/1997, Boeing Auburn. From John Norris, Kennedy/Jenks Consultants, to Ken Macnair, Boeing Commercial Airplane Group, The Boeing Company. January 31.
- Kennedy/Jenks. 1997d. Technical Report, Building 17-05 Area Hydrogeologic Characterization, Boeing Auburn. Kennedy/Jenks Consultants. May.
- Kennedy/Jenks/Chilton. 1989. Underground Storage Tank History, Boeing Commercial Fabrication Division, Auburn Site. April.
- Kueper, B.H., H.F. Stroo, C.M. Vogel, and C.H. Ward. 2014. *Chlorinated Solvent Source Zone Remediation*. New York, NY: Springer.
- LAI. 1990. Building 17-10 Soil Excavation Monitoring, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. July 18.
- LAI. 2001a. G&L Post Mill Remedial Investigation, Boeing Auburn Building 17-10, Boeing Auburn Site, Auburn, Washington. Landau Associates, Inc. December 20.
- LAI. 2001b. Phase II Environmental Site Assessment, Boeing Auburn South Site, Auburn, Washington. Landau Associates, Inc. December 20.

- 
- LAI. 2002a. Ecology Review - Report, Building 17-52 Battery Wash Pad, Former Boeing Auburn South Site, Auburn, Washington. Landau Associates, Inc. November 25.
- LAI. 2002b. Letter Report: Hydraulic Spill Confirmation Sampling, former Boeing Auburn South Site, Auburn, Washington. Landau Associates, Inc. December 11.
- LAI. 2002c. Investigation of the Boeing Auburn South Site and Sale of the South Site to the Safeway Corporation. Landau Associates, Inc.
- LAI. 2003a. Report: Former 17-56 and 17-58 Buildings, Limited Soil Cleanup Actions, Former Boeing Auburn South Site, Auburn, Washington. Landau Associates, Inc. January 14.
- LAI. 2003b. Letter: Two Hydraulic Oil Spill Cleanups and Confirmation Sampling, Former 17-58 Building, Former Boeing Auburn South Site, Auburn, Washington. From Eric Weber, Landau Associates, Inc., to Ken MacNair, January 14.
- LAI. 2004a. Draft: Area 1 Remedial Investigation Report, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. January 30.
- LAI. 2004b. Interim Remedial Action Work Plan, Boeing Auburn Area 1 700 15th Street SW, Auburn, Washington. Landau Associates, Inc. May 7.
- LAI. 2004c. Draft: Interim Remedial Action, Boeing Auburn Area 1 (Building 17-05), 700 15th Street SW, Auburn, Washington. Landau Associates, Inc. December 20.
- LAI. 2004d. Memorandum: Soil Excavation Near Area of Concern A-01. From Eric Weber, Landau Associates, Inc., to James Bet and Ken MacNair, The Boeing Company. May 3.
- LAI. 2004e. Memorandum: Summary of Initial Results: Building 17-06 Boeing Auburn Facility Remedial Investigation Auburn, Washington. From Clint Jacob and Eric Weber, Landau Associates, Inc., to Ken MacNair and Jim Bet, The Boeing Company. October 8.
- LAI. 2004f. Draft: Supplemental Area 1 Remedial Investigation Report, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. March 10.
- LAI. 2005a. Draft: Agency Review Remedial Investigation Report, Boeing Auburn Fabrication Division Facility, Auburn, Washington. Landau Associates, Inc. September 19.
- LAI. 2005b. Memorandum: Boeing Auburn Area 1 - Additional Investigation Results. From Jim Swartz and Eric Weber, Landau Associates, Inc., to Jim Bet and Ken Macnair, The Boeing Company. September 14.
- LAI. 2005c. Memorandum: Boeing Auburn Area 1 - Chrome Line and Elevator Shaft Update. From Jim Swartz and Eric Weber, Landau Associates, Inc., to Jim Bet and Ken Macnair, The Boeing Company, October 3.
- LAI. 2005d. Cleanup Action Report, Building 17-05 Elevator Shaft, Boeing Auburn Fabrication Division Facility, Auburn, Washington. Landau Associates, Inc. October 27.

- 
- LAI. 2005e. Memorandum: Interim Groundwater Monitoring, Boeing Auburn Facility, Auburn, Washington. From Clint Jacob and Eric Weber, Landau Associates, Inc., to Jim Bet and Ken Macnair, The Boeing Company, March 29.
- LAI. 2005f. Draft (2nd Report): Interim Remedial Action, Boeing Auburn Area I (Building 17-05) 700 15th Street SW, Auburn, Washington. Landau Associates, Inc. June 7.
- LAI. 2005g. Draft: Supplement to Final Interim Remedial Action Work Plan. Landau Associates, Inc. October 11.
- LAI. 2006a. Building 17-10 TPH Discovery and Cleanup, Auburn, Washington. Landau Associates, Inc. December 8.
- LAI. 2006b. Memorandum: Perimeter Road Memorandum. From Jennifer Olson and Eric Weber, Landau Associates, Inc., to Jim Bet, The Boeing Company. June 20.
- LAI. 2006c. Report 17-07 Mill Foundations Soil Cleanup - Boeing Auburn, Auburn, Washington. The Boeing Company. November 1.
- LAI. 2006d. Memorandum: Soil Investigation and Removal Near the 17-05 Autoclave Former Building 17-05, Boeing Auburn Facility. From Eric Weber and Jennifer Olson, Landau Associates, Inc., to Jim Bet, The Boeing Company, August 21.
- LAI. 2007a. Memorandum: Boeing Auburn Area 1 - Removal of Former Chromium Pipelines. From Eric Weber and Jennifer Wynkoop, Landau Associates, Inc., to Jim Bet, The Boeing Company, May 22.
- LAI. 2007b. Draft Memorandum: Former Area 1 Well Abandonment. From Eric Weber and Jennifer Olson, Landau Associates, Inc., to Jim Bet, The Boeing Company, February 8.
- LAI. 2007c. Revised Agency Review Draft Remedial Investigation Report, Boeing Auburn Fabrication Division Facility, Auburn, Washington. Landau Associates, Inc. December 28.
- LAI. 2008a. Interim Remedial Action Boeing Auburn Area 1, Auburn, Washington. Landau Associates, Inc. April 22.
- LAI. 2008b. Draft: Supplemental Remedial Investigation Work Plan, Auburn Fabrication Division, Auburn, Washington. Landau Associates, Inc. August 20.
- LAI. 2009a. Memorandum: Building 17-06 Chip Handling System Recommendations and Proposed Scope of Work for Leak Repair and Prevention. From Jennifer Wynkoop and Eric Weber, Landau Associates, Inc., to Jim Bet and Jim Swortz, The Boeing Company. May 21.
- LAI. 2009b. Memorandum: Building 17-06 Chip Handling System Summary of System Operation and Recommendations for Leak Evaluation and Prevention, Boeing Auburn Plant, Washington. From Jennifer Wynkoop Clint Jacob, and Eric Weber, Landau Associates, Inc., to Jim Bet and Jim Swortz, The Boeing Company, January 7.

- 
- LAI. 2009c. Memorandum: First Addendum to the 2nd Revised Ecology Review Draft Remedial Investigation Report, Boeing Auburn Fabrication Division Facility, Auburn, Washington. From Eric Weber, Landau Associates, Inc., to Jim Bet, The Boeing Company, December 16.
- LAI. 2009d. 2nd Revised Draft: Remedial Investigation Report, Boeing Auburn Fabrication Division Facility, Auburn, Washington. Landau Associates, Inc. April 10.
- LAI. 2010a. Memorandum: Boeing Auburn Building 17-07 TCE Source Evaluation. From Lauren McIntire and Eric Weber, Landau Associates, Inc., to Jim Bet, The Boeing Company, July 19.
- LAI. 2010b. Memorandum: Building 17-06 Sump SAU06-52 Cleaning Inspection. From Lauren McIntire and Eric Weber, Landau Associates, Inc., to Jim Bet and Jim Swortz, The Boeing Company, October 15.
- LAI. 2010c. Memorandum: Critical Area/Wellhead Protection Ordinance Review. From LG Eric Weber, Landau Associates, Inc., to Jim Bet, The Boeing Company, April 14.
- LAI. 2010d. Letter: Report of Historic Release at the Wastewater Pretreatment Plant, Boeing Auburn Fabrication Division Facility, Auburn, Washington. From Jennifer Wynkoop, Landau Associates, Inc., to Robin Harrover, Washington State Department of Transportation. February 10.
- LAI. 2010e. Letter: Status Report: No. 29, October 2009 through December 2009 Activity Period, Boeing Commercial Airplane Group, Auburn Plant, WAD 041337130, RCRA Corrective Action Agreed Order No. 01HWTRNR-3345. From Eric Weber, Landau Associates, Inc., to Robin Harrover, Washington State Department of Ecology. January 15.
- LAI. 2010f. Letter: Status Report: No. 30, January through March 2010 Activity Period, Boeing Commercial Airplane Group, Auburn Plant, WAD 041337130, RCRA Corrective Action Agreed Order No. 01HWTRNR-3345. From Eric F. Weber, Landau Associates, Inc., to Robin Harrover, Washington State Department of Ecology. April 15.
- LAI. 2010g. Summer 2010 Remedial Investigation Report, Boeing Auburn Fabrication Division Facility, Auburn, Washington. Landau Associates, Inc. November 19.
- LAI. 2011a. Memorandum: Building 17-06 Sump Cleaning Inspection and Repairs, Boeing Auburn Facility, Auburn, Washington. From Jennifer Wynkoop and Lauren McIntire, Landau Associates, Inc., to Jim Bet and Jim Swortz, The Boeing Company, July 27.
- LAI. 2011b. Memorandum: Historical Practices: Employee Interviews, Boeing Auburn Plant, Auburn, Washington. From Jennifer Wynkoop, Landau Associates, to Jim Bet and Jim Swortz, Robin Harrover, and Ben Farrell, The Boeing Company, Washington State Department of Ecology, and Tetra Tech, respectively, September 13.
- LAI. 2012a. Draft: 2011 Fall Remedial Investigation Data Report, Boeing Auburn Fabrication Division, Auburn, Washington. Landau Associates, Inc. May 17.
- LAI. 2012b. Draft Memorandum: Proposed Cleanup Levels and Screening Levels, Remedial Investigation Vapor Intrusion Assessments, Boeing Auburn Facility, Auburn, Washington. From

---

Lauren McIntire and Chip Halbert, Landau Associates, Inc., to Jim Bet, The Boeing Company. September 4.

LAI. 2012c. Draft: Spring 2011 Remedial Investigation Data Summary Report, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. March 1.

LAI. 2012d. Letter: Status Report: No 39, April through June 2012 Activity Period, Boeing Commercial Airplane Group, Auburn Plant, WAD 041337130, RCRA Corrective Action Agreed Order No. 01HWTRNR-3345. From Eric F. Weber, Landau Associates, Inc., to Robin Harrover, Washington State Department of Ecology. July 17.

LAI. 2012e. Letter: Status Report: No. 40, July through September 2012 Activity Period, Boeing Auburn Facility, WAD 041337130, RCRA Corrective Action Agreed Order No. 01HWTRNR-3345. From Eric Weber, Landau Associates, Inc., to Robin Harrover, Northwest Regional Office, Washington State Department of Ecology. October 15.

LAI. 2012f. Memorandum: Surface Water Investigation, Boeing Auburn Facility, Auburn, Washington. From Sarah Weeks and Jennifer Wynkoop, Landau Associates, Inc., to James Bet, The Boeing Company, August 8.

LAI. 2012g. Draft: Vapor Intrusion Assessment, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. May 16.

LAI. 2013a. Algona Residential Neighborhood Vapor Intrusion Assessment Work Plan, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. June 13.

LAI. 2013b. Letter: Indoor Air Sampling Results, Junior Achievement Building, Auburn, Washington. From Jennifer Wynkoop, Landau Associates, Inc., to David Moore, Junior Achievement. October 16.

LAI. 2013c. Letter: Indoor Air Sampling Results, YMCA Building, Auburn, Washington. From Jennifer Wynkoop, Landau Associates, Inc., to Jason Berry, YMCA. October 16.

LAI. 2013d. Memorandum: Screening Levels for Yard and Ditch Surface Water, Boeing Auburn Plant, Auburn, Washington. From Chip Halbert and Jennifer Wynkoop, Landau Associates, Inc., to James Bet, The Boeing Company. December 13.

LAI. 2013e. Memorandum: Sewer Worker Exposure Assessment and Sewer Air Sampling Results, Boeing Auburn Facility, Auburn, Washington. From Chip Halbert and Jennifer Wynkoop, Landau Associates, Inc., to James Bet, The Boeing Company, October 16.

LAI. 2013f. Letter: Status Report No. 43, April through June 2013 Activity Period, Boeing Auburn Facility, WAD 041337130, RCRA Corrective Action Agreed Order No. 01HWTRNR-3345. From Jennifer Wynkoop, Landau Associates, Inc., to Robin Harrover, Northwest Regional Office, Washington State Department of Ecology. July 15.

LAI. 2013g. Final: Work Plan, Direct-Push Probe Investigation Winter 2013, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. March 21.

- 
- LAI. 2014a. Memorandum: Algona Neighborhood Direct-Push Boring Investigation, Boeing Auburn Facility, Auburn, Washington. From Jennifer Wynkoop and Eric Weber, Landau Associates, Inc., to Jim Bet, The Boeing Company, February 13.
- LAI. 2014b. Memorandum: Algona Neighborhood Ditch Sampling Investigation, Boeing Auburn Facility, Auburn, Washington. From Jennifer Wynkoop and Sarah Fees, Landau Associates, Inc., to Jim Bet, The Boeing Company, June 19.
- LAI. 2014c. Memorandum: Algona Neighborhood Yard Sampling Investigation, Boeing Auburn Facility, Auburn, Washington. From Sarah Fees and Jennifer Wynkoop, Landau Associates, Inc., to Jim Bet, The Boeing Company, September 25.
- LAI. 2014d. Algona Residential Vapor Intrusion Assessment Summary Report, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. September 30.
- LAI. 2014e. Memorandum: Chicago Avenue Ditch Over-Water Air Investigation August 2014, Boeing Auburn Facility, Auburn, Washington. From Sarah Fees and Jennifer Wynkoop, Landau Associates, Inc., to James Bet, The Boeing Company, November 25.
- LAI. 2014f. Letter: Indoor Air and Sub-Slab Soil Vapor Sampling Results. From Jennifer Wynkoop, Landau Associates, Inc., to Jason Berry, YMCA. June 24.
- LAI. 2014g. Memorandum: July 2013 Surface Water Investigation, Boeing Auburn Facility, Auburn, Washington. From Sarah Fees and Jennifer Wynkoop, Landau Associates, Inc., to James Bet, The Boeing Company, June 19.
- LAI. 2014h. Memorandum: March 2014 Utility Tunnel Groundwater Intrusion Investigation and Analytical Results, Boeing Auburn Facility, Auburn, Washington. From Jennifer Wynkoop, Landau Associates, Inc., to Jim Bet, The Boeing Company, September 19.
- LAI. 2014i. Memorandum: Private Well Survey, Boeing Auburn Facility, Auburn, Washington. From Sarah Fees and Eric Weber, Landau Associates, Inc., to Jim Bet, The Boeing Company, December 16.
- LAI. 2014j. Supplemental Remedial Investigation Data Summary Report, Fall 2012 to Fall 2013, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. December 19.
- LAI. 2014k. Memorandum: T-8 Boring on the Auburn 400 Corporate Park Property, Boeing Auburn Project, Auburn, Washington. From Jennifer Wynkoop and Sarah Fees, Landau Associates, Inc., to James Bet, The Boeing Company, February 10.
- LAI. 2015a. 2014 Algona Groundwater Investigation Report, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. March 26.
- LAI. 2015b. 2014 Surface Water Investigation Report, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. September 24.
- LAI. 2015c. Natural Attenuation Assessment Report, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. November 13.

- 
- LAI. 2015d. Letter: Status Report No 51: April Through June 2015 Activity Period, Boeing Auburn Facility, WAD 041337130, RCRA Corrective Action Agreed Order No. 01HWTRNR-3345. From Jennifer Wynkoop, Landau Associates, Inc., to Robin Harrover, Washington State Department of Ecology. July 15.
- LAI. 2015e. Surface Water Monitoring Work Plan, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. August 28.
- LAI. 2016a. 2015 Groundwater Investigation Report, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. June 16.
- LAI. 2016b. Draft Memorandum: 2015 Surface Water Investigation, Boeing Auburn Facility, Auburn, Washington. From Nicholas Dosch and Jennifer Wynkoop, Landau Associates, Inc., to Robin Harrover and Neal Hines, Washington State Department of Ecology, July 20.
- LAI. 2016c. 2015 Tier I Commercial Vapor Intrusion Assessment Report, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. February 8.
- LAI. 2016d. 2015 Tier II Commercial Vapor Intrusion Assessment Report, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. June 15.
- LAI. 2016e. Draft Quality Assurance Project Plan, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. March 4.
- LAI. 2016f. Draft Sampling and Analysis Plan, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. March 4.
- LAI. 2016g. Fall 2014 Auburn Groundwater Investigation, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. August 4.
- LAI. 2016h. Groundwater Modeling Report, Boeing Auburn Facility, Auburn, Washington. May 2.
- LAI. 2016i. Draft Memorandum: Investigation History and Status of Petroleum Releases, Building 17-06 Chip Collection and Briquetter Systems, Boeing Auburn Facility. From Jennifer Wynkoop, Landau Associates, Inc., to James Bet, The Boeing Company, January 6.
- LAI. 2016j. Report: Phase I Environmental Site Assessment, Fletcher Property, 16305 126th Avenue SE, Renton, Washington. Landau Associates. January 26.
- LAI. 2016k. Memorandum: Phase VII Interim Groundwater Monitoring Program, Boeing Auburn Facility, Auburn, Washington. From Jennifer Wynkoop and Sarah Fees, Landau Associates, Inc., to Robin Harrover and Neal Hines, Washington State Department of Ecology. June 21.
- LAI. 2016l. Vapor Intrusion Evaluation and Assessment Approach, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. April 21.
- LAI. 2017a. 2016 Tier II Commercial Vapor Intrusion Report for the Los Cabos Property, Boeing Auburn Facility, Auburn, Washington. Landau Associates, Inc. January 31.

- 
- LAI. 2017b. Status Report No. 57, October through December 2016 Activity Period, Boeing Auburn Facility, WAD 041337130, RCRA Corrective Action Agreed Order No. 01HWTRNR-3345, Auburn, Washington. Landau Associates, Inc. January 16.
- Major, D.W., E. Cox, D. Ellis, E. Lutz, C. Acheson, and P. Hadley. 2003. "Accelerated Bioremediation of Chlorinated Solvents." The Seventh International In Situ and On-Site Bioremediation Symposium, Orlando, FL, June 2-5.
- Montgomery, John H. 2000. *Third Edition, Groundwater Chemicals Desk Reference*. CRC Lewis Publishers.
- Niswonger, RG, S Panday, and M Ibaraki. 2011. MODFLOW-NWT, A Newton Formulation for MODFLOW-2005. U.S. Geological Survey.
- Norton. 1985. Engineering Report - Final Report, Soil Sampling and Priority Analysis, Auburn Underground Storage Tanks, Boeing Contract No. BECE(HWM) 85-01. Norton Corrosion Limited, Inc. November 30.
- Pankow, J.F., and J.A. Cherry. 1996. *Dense Chlorinated Solvents and Other DNAPLs in Groundwater: History, Behavior, and Remediation*. Portland, OR: Waterloo Press.
- Peck, Ralph B., Walter E. Hanson, and Thomas H. Thornburn. 1974. *Foundation Engineering*. 2nd ed. New York: John Wiley & Sons.
- PGG. 1996. 1996 Preliminary Hydrogeologic Characterization, City of Auburn. Pacific Groundwater Group. October 28.
- PGG. 1998. Summary of 1997 Hydrogeologic Investigations, City of Auburn. Pacific Groundwater Group. January 15.
- PGG. 1999. 1999 Hydrogeologic Characterization Report, City of Auburn, Volume 1. Pacific Groundwater Group.
- PGG. 2000. Groundwater Model, Construction and Calibration, City of Auburn. Pacific Groundwater Group. July.
- SECOR. 1996a. Preliminary Subsurface Assessment Investigation, 17-10 Building, G&L Post Mill, Boeing Commercial Airplane Group, Auburn, Washington. July 17.
- SECOR. 1996b. Preliminary Subsurface Investigation 17-06 Building, Briquetting Machines, BCAG, Auburn, Washington. September 9.
- Sleep, B.E., A.J. Brown, and B.S. Lollar. 2005. "Long-Term Tetrachloroethene Degradation Sustained by Endogenous Cell Decay." *Journal of Environmental Engineering and Science* 4 (1):11-17. doi: 10.1139/s04-038.
- Swortz, J. 2007a. "Re: 17-07 Vapor Degreasers." James Swortz, The Boeing Company. December 20.
- Swortz, J. 2007b. "Re: 17-08 UST." James Swortz, The Boeing Company. December 21.

- 
- Swortz, J. 2007c. "Re: G&L Post Mill Follow-up." James Swortz, The Boeing Company. December 20.
- Swortz, J. 2008. "Re: 17-07 Vapor Degreasers." James Swortz, The Boeing Company. May 7.
- Tank Tech. 1997. Letter: Tank Tightness of Tank No. TAU-31 and TAU-32, Diesel and Gasoline Service, Respectively. From George Roni and Lee G. Connel, to John Gieber, The Boeing Company. January 8.
- Tetra Tech. 1991. Boeing Auburn: Drainage Assessment. Tetra Tech, Inc. November 25.
- Tetra Tech. 1992. Boeing Auburn Government Canal Drainage System - Preliminary Assessment. Tetra Tech, Inc. February 10.
- Tetra Tech. 1998. The Boeing Company Auburn Fabrication Division Auburn, Washington, Resource Conservation and Recovery Act Facility Assessment, Final Conclusions and Recommendation. June 19.
- URS. 2003a. Letter: Proposed YMCA Property Transfer Investigation, Boeing Auburn Facility. From David Haddock, URS Corporation, to James Bet, Shared Services Group, Safety, Health, and Environmental Affairs, The Boeing Company. February 25.
- URS. 2003b. Push Probe Investigation Work Plan, North Portion (YMCA Parcel), Boeing Auburn Facility. URS Corporation. February 12.
- URS. 2003c. Letter: Semi-Annual Groundwater Monitoring Report: November 2002, Boeing Auburn, Washington Facility. From Roy Elliot, URS Corporation, to James Bet, The Boeing Company. March 5.
- Vogel, T.M., C.S. Criddle, and P.L. McCarty. 1987. "Transformations of Halogenated Aliphatic Compounds." *Environmental Science & Technology* 21 (8):722-736.
- Vogel, T.M., and P.L. McCarty. 1985. "Biotransformation of Tetrachloroethylene to Trichloroethylene, Dichloroethylene, Vinyl Chloride, and Carbon Dioxide under Methanogenic Conditions." *Applied Environmental Microbiology* 49:1080-1083.
- WDOH. 2007. "Arsenic Detections in Washington Public Water Supplies." Washington State Department of Health. <http://www.doh.wa.gov/Portals/1/documents/4200/arsenic.pdf>.
- WDOH. 2011. Health Consultation Report, Evaluation of Groundwater Contamination, Boeing Commercial Airlines Fabrication Division, Auburn, King County, Washington. Washington State Department of Health. November 3.
- WDOH. 2012. Health Consultation, Evaluation of Groundwater Contamination, Boeing Commercial Airlines Fabrication Division, Auburn, King County, Washington. Washington State Department of Health. January 4.
- WDOH. 2013. Letter: Health Consultation, Boeing Commercial Airplane Fabrication Division, Auburn Plant Exposures to Surface Water in Chicago Avenue Ditch and Government Canal, Algona, King

---

County, Washington. From Rhonda S. Kaetzel, Toxicologist, Health Assessor, Washington State Department of Health, to Mayor David Hill, City of Algona. March 28.

- WDOH. 2014a. "Group B Public Water Systems." Washington State Department of Health.  
<http://www.doh.wa.gov/CommunityandEnvironment/DrinkingWater/WaterSystemAssistance/GroupB>.
- WDOH. 2014b. Health Consultation, Boeing Commercial Airplane Fabrication Division, Auburn Plant Exposures to Surface Water Seasonal Sampling 2013, Algona, King County, Washington. Washington State Department of Health. August 15.
- WDOH. 2014c. Health Consultation, City of Algona - 2013 Residential Indoor Air Results, Boeing Commercial Airplanes Fabrication Division, Auburn, King County, Washington. Washington State Department of Health. January 16.
- WDOH. 2016. "Division of Environmental Health Office of Drinking Water, Find Water Systems." Washington State Department of Health.  
<https://fortress.wa.gov/doh/eh/portal/odw/si/Disclaimer.aspx?Page=FindWaterSystem.aspx>.
- Weston. 1997. Closure Certification Building 17-06, 66,000-Gallon Waste Hold Tank, Boeing - Auburn Facility, Auburn, Washington. January.
- Weston. 1999. Report of Substantive Closure Activities for Building 17-34 Container Storage Unit, Boeing Auburn Facility, Auburn, Washington. Roy F. Weston, Inc. November 23.
- Wiedemeier. 2004. Multiple Lines of Evidence Used to Evaluate Natural Attenuation and Enhanced Remediation of Chlorinated Solvents. T.H. Wiedemeier & Associates. December 31.
- Williams, E.B. 1981. "Fundamental Concepts of Well Design." *Ground Water* 19 (5):527-542. doi: 10.1111/j.1745-6584.1981.tb03504.x.
- Woodward-Clyde. 1997. Subsurface Investigation of Building 17-34 North Bay. September 10.
- Woodward-Clyde. 1998a. Letter: Soil Characterization Summary Report - Building 17-45 Spray Booth #3 Pit - Auburn, Washington. From Tim Syverson and Gary Dupuy, to Kennedy Macnair, Environmental Engineer, The Boeing Company. October 9.
- Woodward-Clyde. 1998b. Letter: Summary Report - Soil Characterization Building 17-07 Former Scrubber #4 - Auburn, Washington. From to Kennedy Macnair, Environmental Engineer, The Boeing Company. July 17.
- Woodward-Clyde. 1998c. Letter: Summary Report - Soil Characterization Rinsewater Release at Wastewater Pretreatment Plan - Auburn, Washington. From Tim Syverson and Geoff Compeau, to Kennedy Macnair, Environmental Engineer, The Boeing Company. March 30.
- Zheng, C., K.R. Bradbury, and M.P. Anderson. 1988. "Role of Interceptor Ditches in Limiting the Spread of Contaminants in Ground Water." *Ground Water* 26 (6):734-742. doi: 10.1111/j.1745-6584.1988.tb00424.x.