



Seep (2004)
not visible →

Notes: 1. Seeps 1 to 5 mapped
7/14/08

Seep not visible
(2004)

D4D
8/6/08

NOTE

1. INTERIM ACTIONS AREAS A, B, AND D SHOWN ARE CONSERVATIVE ESTIMATES BASED ON SAMPLING RESULTS.

2. Seeps 1 and 3 were sampled in 2004. A single composite sample was analyzed for HClD, SVOCs, and Metals

LEGEND

- MW ⊕ PROPOSED MONITORING WELL
- PROPOSED CONFIRMATION SOIL SIDEWALL SAMPLE LOCATION
- ▲ PROPOSED CONFIRMATION SOIL BOTTOM SAMPLE LOCATION
- INTERIM ACTION AREA FOOTPRINT
- GROUNDWATER CONCENTRATIONS EXCEEDED MTCA CLEANUP LEVELS
- SOIL CONCENTRATIONS EXCEED MTCA CLEANUP LEVELS
- SOIL AND GROUNDWATER CONCENTRATIONS EXCEED MTCA CLEANUP LEVELS



Figure 7
Solid Wood Incorporated Site
(West Bay Park)
Olympia, Washington
Interim Action Areas