



STATE OF WASHINGTON  
DEPARTMENT OF ECOLOGY

*Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000  
711 for Washington Relay Service • Persons with a speech disability can call (877) 833-6341*

**STATE ENVIRONMENTAL POLICY ACT  
DETERMINATION OF NONSIGNIFICANCE**

Date of Issuance: January 15, 2021

Lead agency: Department of Ecology, Hazardous Waste and Toxics Reduction, Northwest Regional Office, Corrective Action Unit

Agency Contact: Paul Bianco, paul.bianco@ecy.wa.gov, (425) 649-7253

Permit Number: Not Applicable

Description of proposal:

A cleanup action conducted under the Model Toxics Control Act (MTCA). The cleanup action includes removals and excavation, soil vapor extraction, dynamic groundwater recirculation, groundwater extraction, and monitoring of soil, groundwater, and vapors to achieve cleanup levels. The cleanup action will address on-site and off-site contamination resulting from plant operations.

Location of proposal: Boeing Everett Facility, 3003 W. Casino Road, Everett, Washington 98203  
Township, Range, Section: T 28 N, R 04 E, and portions of the following sections: Section 3 (SE ¼), Section 10 (E ½), Section 11 (SW ¼), Section 14 (SW ¼), and Section 15 (NE ¼)

---

Applicant/Proponent:

Deborah Taege  
The Boeing Company  
deborah.a.taege@boeing.com  
(818) 720-5575  
Bldg. 10-20, MC 9U4-26  
Renton, WA 98055-1409

---

Ecology has determined that this proposal will not have a probable significant adverse impact on the environment. An environmental impact statement (EIS) is not required under RCW

DETERMINATION OF NONSIGNIFICANCE

Page 2 of 2

January 14, 2021

43.21C.030(2)(c). We have reviewed the attached Environmental Checklist. This is available at: <https://apps.ecology.wa.gov/gsp/CleanupSiteDocuments.aspx?csid=4534>

This determination is based on the following findings and conclusions:

The cleanup action areas north of Highway 526 are located on the Boeing Everett Facility North Complex, except the Powder Mill Gulch site, which extends north of the Boeing Everett Facility into forested open space portions of the City of Everett Lot 9 property and commercial properties (Powder Mill Business Center and Seaway Center). The cleanup action areas south of Highway 526 on the Boeing Everett Facility South Complex are bordered by Paine Field, industrial, and commercial land uses. Adjacent land uses include industrial, commercial, residential, and forested open space uses.

Overall, the proposed remedial actions will result in improvements to ground and surface waters on lands adjacent to the cleanup action areas, including Powder Mill Gulch, but will have no effect on current land uses on nearby or adjacent properties.

All work will be performed under Ecology approved plans with temporary erosion and sediment control (TESC) measures installed and maintained by the contractor throughout the duration of construction to stabilize work areas and limit soil erosion. Restoration planting will be performed after completion of construction as required by the City of Everett.

The comment period for this DNS corresponds with the comment period on the Corrective Action Plan which will end on March 26, 2021.

Responsible official:

Raman Iyer  
Section Manager  
Department of Ecology, Northwest Regional Office  
3190 160th Ave SE  
Bellevue, WA 98008-5452  
425-649-7053

Signature  Date January 14, 2021

This SEPA decision may be appealed in conjunction with an appeal on the underlying agency action. In this case, the permit, rule amendment, plan, order or other may be appealed by the applicable citation and summary of timeline.