

Cleanup Site Details

Cleanup Site ID: 11589 Facility/Site ID: 615198 UST ID: N/A Site Page **Site Documents** View Map

Cleanup Site Name: Spokane River Metals Myrtle Point **Glossary**

Alternate Names: SPOKANE RIVER METALS, Spokane River Metals Barker Road North, Spokane River Metals Barker Road South, Spokane River Metals Flora Road, Spokane River Metals Harvard Road, Spokane River Metals Island Complex, Spokane River Metals Islands Lagoon,

Spokane River Metals Murray Road, Spokane River Metals Myrtle Point, Spokane River Metals Starr Road

LOCATION

Address: SPOKANE RIVER City: SPOKANE **Zip Code:** 99027 County: Spokane

Congressional District: 5 Latitude: 47.68348 Longitude: -117.11165 **WRIA:** 57 Legislative District: 4 TRS: 25N 45E 9

DETAIL

Status: Cleanup Complete-Active NFA Received? No Is PSI site? No

O&M/Monitoring

NFA Reason:

Past VCP? No

Cleanup Site ID: 11589

Statute: MTCA **NFA Date:** **Current VCP? Brownfield?** No

No

Site Manager: Dowling, Brendan

Responsible Unit:

N/A

N/A

Active Institutional Control?

No

CLEANUP UNITS

Site Rank: N/A

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SPOKANE RIVER METALS MYRTLE POINT	Sediment	Awaiting Cleanup	EA	Dowling, Brendan	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type R	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-------------------	----------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals - Other				С		

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above RB - Remediated-Below S - Suspected R - Remediated

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		12/1/1999

Toxics Cleanup Program Report Generated: 7/1/2025 Page 1 of 1