

Cleanup Site Details

Cleanup Site ID: 16582

Cleanup Site ID: 16582 **Facility/Site ID:** 57044 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Rainier Trail & Memorial Field [Glossary](#)
Alternate Names: Lower Issaquah Valley PFAS, Rainier Trail, Rainier Trail & Memorial Field

LOCATION

Address: 135 E SUNSET WAY **City:** ISSAQUAH **Zip Code:** 98027 **County:** King
Latitude: 47.52970 **Longitude:** -122.03468 **WRIA:** 8 **Legislative District:** 5 **Congressional District:** 8 **TRS:** 24N 6E 34

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Carp, Brett **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Rainier Trail & Memorial Field	Upland	Cleanup Started	NW	Carp, Brett	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Per- and polyfluoroalkyl substances (PFAS)	C	C				
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/25/2016
Initial Investigation / Federal Preliminary Assessment	Completed		1/21/2022
Early Notice Letter(s)	Completed		4/14/2022
Remedial Investigation and/or FS Work Plan	In Process	1/1/2024	
Order/Decree/Amendment	Planned	2/26/2024	1/1/1900