

## Cleanup Site Details

Cleanup Site ID: 17308

Cleanup Site ID: 17308 Facility/Site ID: 100004576 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Everett Sportsmens Club Area Glossary

Alternate Names: Everett Sportsmens Club Area

LOCATION

Address: 4520 38th St SE City: Everett Zip Code: 98201 County: Snohomish

Latitude: 47.96082 Longitude: -122.16866 WRIA: 7 Legislative District: 44 Congressional District: 1 TRS: 29N 5E 33

**DETAIL** 

Status: Awaiting Cleanup NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

 
 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Everett Sportsmens Club Area
 Upland
 Awaiting Cleanup
 NW
 Northwest Region
 No Process

**ACTIVE INSTITUTIONAL CONTROLS** 

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	С	S	С			

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		11/18/2023
Non-LUST Ind Report Received	Completed		5/23/2024
Initial Investigation / Federal Preliminary Assessment	Completed		4/21/2025
SHARP Assessment	Completed		4/21/2025
Early Notice Letter(s)	Completed		8/11/2025

Toxics Cleanup Program Report Generated: 8/27/2025 Page 1 of 1