

Cleanup Site Details

Cleanup Site ID: 4534

Cleanup Site ID: 4534 Facility/Site ID: 2703 UST ID: 8262 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Boeing Everett

[Glossary](#)

Alternate Names: 40 91 Demolition & Parking, 45 08 Wastewater Treatment Facility Upgrade, 767 Tow Path, Additional Flightline Vehicle Parking, Boeing Bldg 40-56, BOEING CO EVERETT BLDG 40 37, BOEING COMM AIRPLANE GRP EVERETT, BOEING COMMERCIAL AIRPLANE COMPANY, BOEING EVERETT, Boeing Everett 1994, Boeing Everett A, Boeing Everett Bldg 40-30, Boeing Everett Bldg 40-53, Boeing Everett Bldg 40-56, Boeing Everett Bldg 45-52, Boeing Everett Fuel Farm Bldg 45-51 Spill, Boeing Everett Tank EV-48-1, Boeing Flightline Fuel Line, Boeing Flightline Steamline Replacement, Boeing Rail Yard, Boeing Work Position 112, EVERETT FLIGHTLINE EXPANSION, Former Gun Club Area C, LCL Tow Path, New Everett Delivery Center, Parent - BOEING COMMERCIAL AIRPLANE COMPANY

LOCATION

Address: 3003 W CASINO RD **City:** EVERETT **Zip Code:** 98204 **County:** Snohomish
Latitude: 47.91944 **Longitude:** -122.27282 **WRIA:** 7 **Legislative District:** 38 **Congressional District:** 2 **TRS:** 28N 4E 15

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA (RCRA Corrective Action) **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Bianco, Paul **Responsible Unit:** Hazardous Waste **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Boeing Commercial Airplane Company	Sediment	Cleanup Started	NW	Northwest Region	Ecology-supervised or conducted
Boeing Commercial Airplane Company	Upland	Cleanup Started	HWTR	Bianco, Paul	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C	C				
Halogenated Organics	C	C	C	C		
Metals - Other	C					
Metals Priority Pollutants	C	C	S	C		
Non-Halogenated Solvents	C	C	S	S		
Petroleum Products-Unspecified	C	C	S	S		
Polychlorinated biPhenyls (PCB)	S	S	S	C		
Polycyclic Aromatic Hydrocarbons	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 4534

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	In Process	2/12/1997	
Site Hazard Assessment/Federal Site Inspection	Completed		2/18/1997
Hazardous Sites Listing/NPL	Completed		10/15/1997