

Cleanup Site ID: 4534

Cleanup Site Details

Facility/Site ID: 2703 UST ID: 8262 Site Page Site Documents View Map

Cleanup Site ID: 4534

Cleanup Site Name: Boeing Everett Glossary

Alternate Names: 40 91 Demolition & Parking, 45 08 Wastewater Treatment Facility Upgrade, 767 Tow Path, Additional Flightline Vehicle Parking, Boeing Bldg 40-56, BOEING CO EVERETT BLDG 40 37, BOEING COMM AIRPLANE GRP EVERETT, BOEING COMMERCIAL AIRPLANE COMPANY, BOEING EV-176 (Under Parent UST ID 8262), BOEING EV-48 & EV-49 (Under Parent UST ID 8262), BOEING EV-69 (Under Parent UST ID 8262), BOEING EV24 (Under Parent UST ID 8262), BOEING EVERETT, Boeing Everett 1994, Boeing Everett A, Boeing Everett Bldg 40-30, Boeing Everett Bldg 40-53, Boeing Everett Bldg 40-56, Boeing Everett Bldg 45-52, Boeing Everett Fuel Farm Bldg 45-51 Spill, Boeing Everett Tank EV-48-1, Boeing Flightline Fuel Line, Boeing Flightline Steamline Replacement, Boeing Rail Yard, Boeing Work Position 112, BOEINGEV-355 (Under Parent UST ID 8262), EVERETT FLIGHTLINE EXPANSION, Former Gun Club Area C, LCL Tow Path, New Everett Delivery Center, Parent -

BOEING USTIDs: 619998, 620002, 620003, 620004, 6200013)

LOCATION

Address: 3003 W CASINO RD City: EVERETT Zip Code: 98204 County: Snohomish

Latitude: 47.91944 Longitude: -122.27282 WRIA: 7 Legislative District: 38 Congressional District: 2 TRS: 28N 4E 15

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA (RCRA Corrective Action) NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Bianco, Paul Responsible Unit: Hazardous Waste Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Boeing Commercial Airplane Company	Sediment	Cleanup Started	NW	Northwest Region	Ecology-supervised or conducted
Boeing Commercial Airplane Company	Upland	Cleanup Started	HWTR	Bianco, Paul	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	estriction Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	--------------------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Base/Neutral/Acid Organics	С	С					
Halogenated Organics	С	С	С	С			
Metals - Other	С						
Metals Priority Pollutants	С	С	S	С			
Non-Halogenated Solvents	С	С	S	S			
Petroleum Products-Unspecified	С	С	S	S			
Polychlorinated biPhenyls (PCB)	S	S	S	С			
Polycyclic Aromatic Hydrocarbons	С	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

Toxics Cleanup Program Report Generated: 11/11/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Remedial Investigation and/or Feasibility Study	In Process	2/12/1997				
Federal Site Inspection	Completed		2/18/1997			
Hazardous Sites Listing	Completed		10/15/1997			

Cleanup Site ID: 4534