

Cleanup Site Details

Cleanup Site ID: 4891

Cleanup Site ID: 4891	Facility/Site ID: 308	UST ID: 9093	Site Page	Site Documents	View Map
Cleanup Site Name: Richland Horn Rapids Landfill					
Alternate Names: Horn Rapids Landfill, Horn Rapids Landfill LUST, Richland City Landfill, Richland HHW Fire, Richland Horn Rapids Landfill, Richland Landfill					
LOCATION					
Address: 3102 Twin Bridges Rd		City: RICHLAND	Zip Code: 99352	County: Benton	
Latitude: 46.34899	Longitude: -119.33612	WRIA: 40	Legislative District: 8	Congressional District: 4	TRS: 10N 28E 17
DETAIL					
Status: Cleanup Started	NFA Received? No	Is PSI site? No			
Statute: MTCA	NFA Date: N/A	Current VCP? No		Past VCP? No	
Site Rank: N/A	NFA Reason: N/A	Brownfield? No			
Site Manager: Lemond, Luke	Responsible Unit: Solid Waste Program	Active Institutional Control?		No	
CLEANUP UNITS					
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
HORN RAPIDS LANDFILL	Upland	Cleanup Started	SWP	Lemond, Luke	Ecology-supervised or conducted
ACTIVE INSTITUTIONAL CONTROLS					
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County
There are no current Institutional Controls in effect for this site.					
AFFECTED MEDIA & CONTAMINANTS					
MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air
Conventional Contaminants, Inorganic		B			
Halogenated Organics	S	C			
Petroleum-Diesel	C				
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below					
SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
Site Hazard Assessment	Completed	10/22/1987	6/1/1988		
Site Discovery/Release Report Received	Completed		12/17/1998		
Early Notice Letter(s)	Completed		3/6/2000		
Order/Decree/Amendment	In Process	4/19/2016			
Remedial Investigation and/or FS Work Plan	Completed	4/28/2016	4/28/2017		
Remedial Investigation and/or Feasibility Study	In Process	6/9/2017			