

Cleanup Site Details

Cleanup Site ID: 5064

Cleanup Site ID: 5064 Facility/Site ID: 2163 UST ID: 1945 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Kelly Moore Paint Co

[Glossary](#)

Alternate Names: Kelly Moore Paint Co, KELLY MOORE PRESERVATIVE PAINT CO, KELLY-MOORE PAINT CO, PRESERVATIVE PAINT CO, PRESERVATIVE PAINT COMPANY

LOCATION

Address: 5410 AIRPORT WAY S **City:** SEATTLE **Zip Code:** 98108 **County:** King
Latitude: 47.55390 **Longitude:** -122.32102 **WRIA:** 9 **Legislative District:** 11 **Congressional District:** 7 **TRS:** 24N 4E 20

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** Yes **Past VCP?** Yes
Site Rank: 5 - Lowest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Song, Jing **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Preservative Paint Co	Upland	Cleanup Started	NW	Song, Jing	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C				
Benzene	C	C				
Halogenated Organics	C	C				
Lead	C	C				
Metals - Other	C					
Non-Halogenated Solvents	C	C				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				
Petroleum-Other		C				
Polycyclic Aromatic Hydrocarbons	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 5064

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/21/1994
Site Discovery/Release Report Received	Completed		4/21/1994
Site Hazard Assessment/Federal Site Inspection	Completed	8/21/1997	7/15/1998
LUST - Report Received	Completed		8/29/1997
LUST - Site Characterization Report	Completed		6/26/1998
Hazardous Sites Listing/NPL	Completed		8/18/1998
LUST - Report Received	Completed		6/22/2010
VCP Receipt of Plan or Report	Completed		7/22/2010
VCP Opinion on Remedial Investigation Work Plan	Completed	12/8/2010	
LUST - Report Received	Completed		11/15/2013
VCP Opinion on Site Cleanup Plan	Completed	11/15/2013	2/19/2014
LUST - Report Received	Completed		5/13/2014
LUST - Report Received	Completed		5/18/2015
LUST - Report Received	Completed		7/9/2015
LUST - Report Received	Completed		8/11/2015
VCP Opinion on Remedial Investigation	Canceled	8/11/2015	
LUST - Report Received	Completed		2/1/2016
VCP Opinion on Remedial Investigation	Completed	2/1/2016	5/4/2016
LUST - Report Received	Completed		4/6/2017
VCP Opinion on Feasibility Study	Completed	4/6/2017	2/27/2018
LUST - Report Received	Completed		6/18/2018
LUST - Report Received	Completed		10/10/2019
LUST - Report Received	Completed		10/15/2019
VCP Opinion on Remedial Investigation Work Plan	Completed	10/15/2019	11/22/2019
LUST - Report Received	Completed		9/28/2020
LUST - Report Received	Completed		3/25/2022
LUST - Report Received	Completed		5/15/2023