

# Cleanup Site Details

Cleanup Site ID: 6070

Cleanup Site ID: 6070      Facility/Site ID: 43142599      UST ID: 7709      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Gull 274      [Glossary](#)

**Alternate Names:** Gull 274, GULL EXPRESS LANE 274, TESORO 2154, TESORO REFINING & MARKETING CO BLAINE, TESORO SERVICE STATION 62154, Tesoro SS 62154

## LOCATION

**Address:** 530 PEACE PORTAL DR      **City:** BLAINE      **Zip Code:** 98230      **County:** Whatcom  
**Latitude:** 48.99571      **Longitude:** -122.75141      **WRIA:** 1      **Legislative District:** 42      **Congressional District:** 1      **TRS:** 41N 1W 36

## DETAIL

**Status:** No Further Action      **NFA Received?** Yes      **Is PSI site?** Yes  
**Statute:** MTCA      **NFA Date:** 6/22/2010      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** N/A      **NFA Reason:** Voluntary Cleanup Program Review      **Brownfield?** No  
**Site Manager:** Olsen, Russ      **Responsible Unit:** Northwest      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Gull 274 (Tesoro SS 62154)	Upland	No Further Action Required	NW	Olsen, Russ	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	R	R				
Non-Halogenated Solvents	C	C				
Petroleum-Gasoline	R	R				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		1/16/2002
LUST - Report Received	Completed		1/16/2002
LUST - Report Received	Completed		5/21/2002
LUST - Report Received	Completed		7/5/2002
LUST - Report Received	Completed		11/1/2002
LUST - Report Received	Completed		2/24/2003
LUST - Report Received	Completed		4/16/2003

# Cleanup Site Details

Cleanup Site ID: 6070

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
LUST - Report Received	Completed		10/20/2003
LUST - Report Received	Completed		10/21/2003
VCP Opinion on Remedial Investigation Work Plan	Completed	6/23/2004	8/8/2006
LUST - Report Received	Completed		9/23/2004
LUST - Report Received	Completed		2/22/2005
LUST - Report Received	Completed		5/4/2005
LUST - Report Received	Completed		10/31/2005
LUST - Report Received	Completed		10/14/2009
VCP Opinion on Property Cleanup	Completed	10/20/2009	2/8/2010
Reopen Site	Completed		11/6/2009
Site Status Changed to NFA	Completed		6/22/2010
VCP Opinion on Site Cleanup	Completed		6/22/2010