

Cleanup Site Details

Cleanup Site ID: 6085

Cleanup Site ID: 6085 Facility/Site ID: 43737443 UST ID: 4623 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Tri City Battery Goodyear [Glossary](#)

Alternate Names: Top Auto Inc Richland, Tri Cities Battery Inc Richland, Tri City Battery Goodyear, USA Holding Inc DBA Tiremax

LOCATION

Address: 601 GEORGE WASHINGTON WAY City: RICHLAND Zip Code: 99352 County: Benton
Latitude: 46.27385 Longitude: -119.27399 WRIA: 40 Legislative District: 8 Congressional District: 4 TRS: 9N 28E 11

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 2/14/2011 Current VCP? No Past VCP? Yes
Site Rank: 2 - Moderate-High Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Dunbar, Mark Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Tiremax	Upland	No Further Action Required	CE	Dunbar, Mark	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	RB	RB				
Petroleum-Diesel	RB	RB				
Petroleum-Other	RB	RB				
Polychlorinated biPhenyls (PCB)	RB	RB				
Polycyclic Aromatic Hydrocarbons	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		5/17/1995
LUST - Report Received	Completed		5/17/1995
Site Discovery/Release Report Received	Completed		2/9/2006
Initial Investigation / Federal Preliminary Assessment	Completed		3/16/2006
Early Notice Letter(s)	Completed		4/6/2006
Site Hazard Assessment/Federal Site Inspection	Completed	8/29/2007	9/27/2007

Cleanup Site Details

Cleanup Site ID: 6085

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Interim Action	Completed	1/15/2008	10/27/2010
Hazardous Sites Listing/NPL	Completed		2/20/2008
LUST - Site Characterization Report	Completed		11/24/2008
LUST - Report Received	Completed		5/6/2009
LUST - Report Received	Completed		9/22/2009
LUST - Report Received	Completed		12/15/2009
LUST - NFA Determination II or SHA	Completed		10/27/2010
Remove site from Hazardous Sites List	Completed		2/14/2011
Site Status Changed to NFA	Completed		2/14/2011