Cleanup Site Details Cleanup Site ID: 6								
Cleanup Site ID: 6838 Facility/Site ID: 90456792		0456792	<b>UST ID</b> : 12411		Site Pag	e <u>Site Doo</u>	<u>cuments</u>	<u>View Map</u>
Cleanup Site Name: Hampton Lumber Mill Darrington Glossary								
Alternate Names: A&E LLC GOLD HILL QUARRY, GOLD HILL QUARRY, HAMPTON LUMBER DARRINGTON, Hampton Lumber Mill Darrington, HAMPTON LUMBER MILL GOLD HILL QUARR, Hampton Lumber Mills WA Inc, SUMMIT TIMBER CO, SUMMIT TIMBER SAWMILL								
LOCATION								
Address: 46921 SAUK PRAIRIE RDCity: DARRINGTONZip Code: 98241County: Snohomish								omish
Latitude: 48.26061 Longitude:	-121.60020 <b>V</b>	WRIA: 4	Legislative D	istrict:	39 Congress	onal District	: 1 TRS:	
DETAIL								
Status: No Further Action	NFA F	Received?	Yes		ls	PSI site?	No	
Statute: MTCA	NFA D	Date:	2/1/2003		Cu	rrent VCP?	No Past	t VCP? Yes
Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No								
Site Manager: Sato, Brian	Respo	onsible Unit:	Northwest		Ac	tive Institutio	nal Control	<b>?</b> No
CLEANUP UNITS				-				
Cleanup Unit Name	Unit Type	Unit Type Unit		Resp Unit	Unit Manage	r	Current Process	
Summit Timber Co Upland No		No Further A	ction Required	NW	Sato, Brian	Stan	Standard Voluntary Cleanup	
ACTIVE INSTITUTIONAL CONTROL	S							
Instrument Type Restriction Media	Restri	Restrictions/Requirements					cording ounty	Tax Parcel
There are no current Institutional Controls in effect for this site.								
AFFECTED MEDIA & CONTAMINANTS								
Contaminant					MED		<b>A 1</b> ···	Destructo
Petroleum-Other		Soi C	il Ground	water	Surface Water	Sediment	Air	Bedrock
Phenolic Compounds		C						
Key:								
B - Below Cleanup LevelC - Confirmed Above Cleanup LevelRA - Remediated-AboveS - SuspectedR - RemediatedRB - Remediated-Below								
SITE ACTIVITIES								
Activity				Status		Start Date	art Date End Date/ Completion Date	
LUST - Notification				C	Completed		1/18/2002	
VCP Opinion on Interim Action				C	Completed 1/2		2002 2/1/2003	
LUST - Report Received				C	Completed		4/19/2002	
LUST - Report Received				C	Completed		1	/30/2003
Site Status Changed to NFA					Completed 2/1/2003			2/1/2003