

Cleanup Site Details

Cleanup Site ID: 7115

Cleanup Site ID: 7115 Facility/Site ID: 69587682 UST ID: 9534 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: BP Service Station 03158

[Glossary](#)

Alternate Names: BP 031585577, BP Service Station 03158, CIRCLE K 76 2705577, CONOCOPHILLIPS 2705577, EXXON STATION 77134, FRED MEYER 659 FM FUEL, FRED MEYER FUEL #659 TUMWATER, TOSCO FACILITY 05577

LOCATION

Address: 501 TROSPER RD SW **City:** TUMWATER **Zip Code:** 98501 **County:** Thurston
Latitude: 46.99969 **Longitude:** -122.91376 **WRIA:** 13 **Legislative District:** 22 **Congressional District:** 10 **TRS:** 18N 2W 34

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 6/1/2015 **Current VCP?** No **Past VCP?** Yes
Site Rank: 3 - Moderate Risk **NFA Reason:** Voluntary Cleanup Program Review **Brownfield?** No
Site Manager: Middleton, Tom **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BP 03158/EXXON 7-7134	Upland	No Further Action Required	SW	Middleton, Tom	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		12/2/1991
LUST - Report Received	Completed		12/11/1991
Site Characterization	Completed	1/1/1992	12/31/1995
LUST - Report Received	Completed		4/9/1992
O & M	Completed	8/1/1992	3/30/2002
LUST - Report Received	Completed		10/14/1992
LUST - Report Received	Completed		3/8/1993
LUST - Report Received	Completed		7/14/1993
LUST - Report Received	Completed		9/20/1993

Cleanup Site Details

Cleanup Site ID: 7115

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		2/14/1994
LUST - Report Received	Completed		7/22/1994
LUST - Site Characterization Report	Completed		12/1/1995
LUST - Report Received	Completed		2/29/1996
LUST - Report Received	Completed		3/11/1996
LUST - Report Received	Completed		5/20/1996
LUST - Report Received	Completed		7/1/1996
LUST - Report Received	Completed		9/16/1996
LUST - Report Received	Completed		12/6/1996
LUST - Report Received	Completed		2/28/1997
LUST - Report Received	Completed		2/28/1997
LUST - Report Received	Completed		8/29/1997
LUST - Report Received	Completed		11/17/1997
LUST - Report Received	Completed		11/17/1997
LUST - Report Received	Completed		11/17/1997
LUST - Report Received	Completed		2/9/1998
LUST - Report Received	Completed		2/9/1998
LUST - Report Received	Completed		5/5/1998
LUST - Report Received	Completed		9/21/1998
LUST - Report Received	Completed		9/21/1998
LUST - Report Received	Completed		9/21/1998
LUST - Report Received	Completed		9/21/1998
LUST - Report Received	Completed		4/17/2000
LUST - Report Received	Completed		7/30/2002
LUST - Report Received	Completed		8/15/2002
LUST - Report Received	Completed		11/12/2002
LUST - Report Received	Completed		12/2/2002
VCP Opinion on Cleanup Action	Canceled	1/13/2003	
LUST - Report Received	Completed		2/3/2003
LUST - Notification	Completed		5/12/2003
LUST - Site Characterization Report	Completed		6/12/2003
LUST - Report Received	Completed		11/1/2004
Site Hazard Assessment/Federal Site Inspection	Completed	10/20/2006	12/14/2006
Hazardous Sites Listing/NPL	Completed		12/14/2006
LUST - Report Received	Completed		3/21/2007
Toxics Cleanup Program		Report Generated: 5/7/2024	Page 2 of 3

Cleanup Site Details

Cleanup Site ID: 7115

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		5/3/2007
LUST - Report Received	Completed		7/10/2007
LUST - Report Received	Completed		8/8/2007
LUST - Report Received	Completed		9/28/2007
LUST - Report Received	Completed		10/4/2007
LUST - Report Received	Completed		11/19/2007
LUST - Report Received	Completed		2/4/2008
LUST - Report Received	Completed		2/27/2008
LUST - Report Received	Completed		4/16/2008
LUST - Report Received	Completed		5/23/2008
LUST - Report Received	Completed		2/3/2010
LUST - Report Received	Completed		5/20/2010
LUST - Report Received	Completed		12/13/2010
VCP Opinion on Remedial Investigation Work Plan	Completed	1/25/2011	4/19/2011
LUST - Report Received	Completed		3/2/2011
LUST - Report Received	Completed		4/13/2011
LUST - Report Received	Completed		4/19/2012
LUST - Report Received	Completed		4/19/2012
LUST - Report Received	Completed		4/19/2012
VCP Opinion on Remedial Investigation	Completed	2/7/2013	5/8/2013
VCP Opinion on Site Cleanup	Completed	1/22/2015	6/1/2015
LUST - NFA Determination II or SHA	Completed		6/1/2015
LUST - NFA Determination II or SHA	Completed		6/1/2015
Site Status Changed to NFA	Completed		6/1/2015
Remove site from Hazardous Sites List	Completed		7/30/2015