



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

PO Box 47775 • Olympia, Washington 98504-7775 • (360) 407-6300
711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341

June 19, 2020

Donny Schride
General Manager
Rainier Ballistics, LLC
4500 15th Street East
Tacoma, WA 98424

RE: NPDES Permit Number WAR001996

Dear Donny Schride:

Enclosed is the report from the Department of Ecology's recent National Pollutant Discharge Elimination System (NPDES) Industrial Stormwater General Permit (ISGP) Notice of Termination (NOT) inspection conducted at your facility on June 10, 2020.

Please contact me at honor.carpenter@ecy.wa.gov or (360) 485-2701 if you have questions, comments, needs, or concerns.

Sincerely,

Honor Carpenter

Honor Carpenter
Industrial Stormwater Facility Manager
Southwest Regional Office
Water Quality Program

Enclosures: Industrial Stormwater Inspection Report
Photolog

cc: Jesse McCulloch, MW Environmental
Fee Unit, Department of Ecology
Melinda Wilson, Department of Ecology

You must also comply with other applicable requirements in chapter 43.21B RCW and chapter 371-08 WAC.

Address and Location Information:

Street Addresses:

Department of Ecology
Attn: Appeals Processing Desk
300 Desmond Drive SE
Lacey, WA 98503

Mailing Addresses:

Department of Ecology
Attn: Appeals Processing Desk
PO Box 47608
Olympia, WA 98504-7608

Pollution Control Hearings Board (PCHB)
1111 Israel Road SW, Suite 301
Tumwater, WA 98501

Pollution Control Hearings Board
PO Box 40903
Olympia, WA 98504-0903

Latitude and Longitude at northwest corner of the building:
47.244342; -122.367731

Announced
 Unannounced

Name(s) and Signature(s) of Inspector(s) Honor Carpenter <i>Honor Carpenter</i>	Agency/Office/Phone and Fax Numbers Ecology/SWRO (360) 407-6273	Date June 16, 2020
Signature of Management QA Reviewer Steven G. Eberl, P. E. <i>SA G Eberl</i>	Agency/Office/Phone and Fax numbers Ecology/SWRO (360) 407-6293	Date June 19, 2020

Image 1: North side of the former-Rainier Ballistics facility (facing east).



Image 2: Space at the northwest corner of the former-Rainier Ballistics facility appears to be occupied by a new tenant or owner.

