

Site Register

WASHINGTON STATE DEPARTMENT OF ECOLOGY TOXICS CLEANUP PROGRAM



JANUARY 15, 2009

The Site Register is published every two weeks to inform you about public comment periods, public meetings, hearings, and other information related to the study and cleanup of hazardous waste sites under the Model Toxics Control Act, Chapter 70.105D RCW.

You may also find information about public hearings, meetings, workshops, and open public comment periods on Ecology's web page. Go to www.ecy.wa.gov and click on the Public Involvement Calendar.

If you have questions or want to be added to the mailing list (electronic or paper) for the Site Register, contact Linda Thompson at 360/407-6069 or e-mail Ltho461@ecy.wa.gov. Specific regional contacts are listed after each entry.

If you need this publication in an alternate format, please call the Toxics Cleanup Program at 360/407-7170. Persons with hearing loss may call 711 for Washington Relay Service. Persons with a speech disability may call 877/833-6341.

CONTENTS

Formal Cleanups	1
Independent Cleanups	5
Voluntary Cleanup Program	7
Program Publications	9

FORMAL CLEANUPS

Ecology oversees complex cleanup sites to ensure that your health and that of the environment are protected.

GRANT COUNTY

Cenex Supply & Marketing Inc. Rinsate Site, 300 Division Street, Quincy Facility Site ID# 33599645

**Public comment period:
12/19/08 – 1/19/09**

Periodic Review Available to Public

Ecology invites you to review and comment on a document called a periodic review for the Cenex Supply & Marketing Inc., Rinsate site. A periodic review is conducted at least every five years after the initiation of a cleanup action at a site, as required by the Model Toxics Control Act (MTCA). The purposes of the review are to evaluate site conditions after cleanup is considered complete and to ensure protection of human health and the environment.

CHS, Inc., formerly Cenex Harvest States, is the current property owner and the party liable for cleanup at the site. CHS leased the property prior to purchasing it in 2004. The site originally was used as a liquid fertilizer and soil fumigant storage facility.

Investigations identified contamination in groundwater and soil. CHS conducted several cleanup actions to address elevated levels of Volatile Organic Compounds (VOCs) in soil and groundwater. Treatment systems were put in place in 2001 to address the contamination, and monitoring was conducted.

Monitoring within the treatment area indicates VOC levels in soil and

groundwater have declined significantly. However, VOCs in groundwater have not been effectively reduced down gradient of the source area. Additional cleanup actions are necessary to achieve the goals outlined in the final Cleanup Action Plan and to ensure that the VOCs don't continue to migrate down gradient.

Deed restrictions are on the property. They limit the ways that the property may be used and protect the cleanup remedies that have been implemented. Monitoring wells installed in 2007 showed dissolved VOCs in groundwater beyond the original established site boundaries. Deed restrictions should be expanded to cover these areas.

You may review the Periodic Review and associated documents at the following locations:

- Quincy City Hall, Ms. Nancy Schanze, 104 B Street Southwest, Quincy, WA 98848
- Grant County Health District, Mr. Gerald Campbell, 35 First and C Street, Ephrata, WA 98823
- Ecology Eastern Regional Office, 4601 N. Monroe, Spokane WA 99205-1295. (Please call **Kari Johnson** at **509/329-3415** for an appointment.)
- Ecology's website: http://www.ecy.wa.gov/programs/tcp/sites/Cenex_grant_county/cenex_hp.htm

Para asistencia en Espanol Sr Gregory Bohn at 509/454-4174
Если вам нужно помощь по русский, звоните: **Tatyana Bistrevsky** at **509/928-7617**

For more information or to submit written comments, please contact **Mr. Dave George**, Site Manager, at the Ecology address listed above or at **509/329-3520** or e-mail cgeo461@ecy.wa.gov.

KING COUNTY

Bothell Landing at 18120, 18126, 18132 Bothell Way NE and 10001 Woodinville Drive Facility Site ID# 73975762

Bothell Riverside at NE 180th Street & Woodinville Drive Facility Site ID# 53578168

Bothell Paint & Decorating at 18004 & 18005 Bothell Way NE. Facility Site ID# 93536765

**Public comment period:
1/2/09 – 2/2/09**

City of Bothell ~3 Agreed Orders and Public Participation Plans

In December 2008, Ecology and the City of Bothell (Bothell) entered into negotiations for Agreed Orders for these sites. The orders are being negotiated at the initiative of the City of Bothell as part of their due diligence in redeveloping properties acquired for their planned redevelopment of the downtown area (Bothell Crossroads SR 522 Realignment and SR 527 Multiway Boulevard Project). Under the proposed Agreed Orders, Bothell agrees to complete the following actions:

- Prepare a draft Remedial Investigation/ Feasibility Study (RI/FS) Work Plan for each site.
- Perform a RI/FS for each site, which will define the nature, extent, and magnitude of contamination, then identify and evaluate cleanup alternatives.
- Prepare a draft RI/FS report for each site, which will present the results of the investigation and evaluate the cleanup alternatives.
- Prepare a draft Cleanup Action Plan for each site.

Also available in the orders are draft Public Participation Plans that outline and describe the tools that Ecology

will use to inform the public about site activities, and identify opportunities for the community to become involved in this process.

The Bothell Landing site contained two former gasoline service stations. In the course of construction of a park amenity (Rotunda Park), five underground storage tanks (USTs) and approximately 385 tons of petroleum contaminated soil were found and removed in 1998. One of the stations was likely associated with the underground storage tanks. Under the Voluntary Cleanup Program, an Interim No Further Action letter was issued in 2002 for site soils (excluding ground water). The property owner also issued a restrictive covenant for the site in 2002 confirming that petroleum-affected soils and ground water exist at the site. However, Ecology removed the site from the Voluntary Cleanup Program in 2006 due to a lack of activity, and at that time issued a Further Action Determination letter for the Site. In 2007, chlorinated solvents were detected in ground water from an unknown source.

The Bothell Riverside site contained a former gasoline service station. Petroleum-impacted soil, groundwater, and buried solid waste were found on-site. The solid waste included discarded containers of motor oil, anti-freeze, and transmission fluid. Approximately 4,500 yards of petroleum impacted soil were excavated, treated on-site, and returned to the excavation in the early 1990s. The soil that was returned to the excavation may not have met state cleanup standards. A 2008 Phase II Environmental Site Assessment (ESA) documented the presence of petroleum contaminants in the soil as well as chlorinated solvents in the ground water at concentrations of potential regulatory concern.

This Bothell Paint & Decorating site was used by a former sandblasting operation and contained at least one petroleum underground storage tank removed in 1988. A hole was discovered in the UST at the time of removal and petroleum

was observed on water in the excavation when the UST was removed. Metals and petroleum hydrocarbons in soil, and chlorinated solvents and metals in ground water are the primary contaminants of concern at this time. High levels of cadmium and arsenic in soil are among the metals of potential regulatory concern.

The proposed Remedial Investigations will provide additional information to identify the nature and extent of contamination at each site.

The Agreed Order and Public Participation Plans are available for review at the following locations:

- King County Bothell Regional Library, 18215 98th Ave. NE, Bothell, WA 98011
- Bothell City Hall, 18305 101st Ave. NE, Bothell, WA 98011 Hours: Monday - Friday 8 am - 5 pm
- Ecology Northwest Regional Office, 3190 160th Ave. SE, Bellevue, WA 98008-5482. (Please call **Sally Perkins** at **425/649-7190** for an appointment.)
- Bothell Landing - Ecology's website: http://www.ecy.wa.gov/programs/tcp/sites/bothellLand/bothellLanding_hp.html
- Bothell Riverside - Ecology's website: http://www.ecy.wa.gov/programs/tcp/sites/bothellRiv/bothellRiv_hp.html
- Bothell Paint & Decorating - Ecology's website: http://www.ecy.wa.gov/programs/tcp/sites/bothellPaint/bothellPaint_hp.html

For more information or to submit written comments, please contact **Jerome Cruz**, Site Manager, at the Ecology address listed above or at **425/649-7094** or e-mail jeru461@ecy.wa.gov.

Fox Ave Building Site, 6900 Fox Avenue South, Seattle Facility Site ID# 2282

**Public comment period:
12/22/08 – 1/30/09**

Draft Agreed Order and Public Participation Plan Available t

Ecology requests your input on two documents: an Agreed Order and Public Participation Plan (PPP). The documents are for the proposed investigation and cleanup of contamination in the soil and groundwater at the Fox Ave Building site (Site).

This site has been under investigation and cleanup since 1991 under a previous Agreed Order with Ecology. This new Agreed Order is a legal agreement between Ecology and the current property owner, Fox Ave Building, LLC, also known as a Potentially Liable Person (PLP). Under the order the PLP will do an interim cleanup action to control the contamination to the Lower Duwamish Waterway, test technology to address the contamination, find out what data is needed to understand the site, collect air samples to check if air quality in the buildings on the property is contaminated, analyze cleanup alternatives, and create a draft Cleanup Action Plan. The PPP outlines the tools that Ecology will use to inform the public about site activities, and identifies how the community may become involved in this process.

The Fox Ave Building site is located along the east side of the Lower Duwamish Waterway in Seattle, Washington. Contamination at the site is due to industrial use since 1918. Contaminants of concern are:

- Chlorinated solvents
- Petroleum hydrocarbons
- Semi-volatile organic compounds (SVOCs)
- Dioxins and furans

Related documents are available for public review at:

- South Park Library 8604 Eighth Ave S at South Cloverdale St, Seattle **206/615-1688**
- Ecology Northwest Regional Office,

3190 160th Ave. SE, Bellevue, WA 98008-5482. (Please call **Sally Alexander** at **425/649-7239** or **Sally Perkins** at **425/649-7190** for an appointment.)

- Ecology's website: http://www.ecy.wa.gov/programs/tcp/sites/foxAve/foxAve_hp.html.

For more information or to submit written comments, please contact **Sunny Becker**, Site Manager, at the Ecology address listed above or at **425/649-7187** or e-mail hlin461@ecy.wa.gov.

ULTRA Corporation Former Pace National, 500 7th Ave South, Kirkland Facility Site ID# 2159

**Public comment period:
12/19/08 – 1/20/09**

Agreed Order and Public Participation Plan

Ecology is inviting public comment on a proposed Agreed Order, and Public Participation Plan for ULTRA Corporation Former Pace National site. Ecology and ULTRA Corporation entered a legal agreement called an Agreed Order. Under this proposed Agreed Order, ULTRA Corporation agrees to complete the following actions:

- Implement a Work Plan that prepares a Remedial Investigation/Feasibility Study (RI/FS) report, which will present the results of the investigation and evaluate the cleanup alternatives. The work plan will outline the content of the Draft RI and includes a Pilot Test Work Plan for conducting a study of remedial technologies (Pilot Test).
- Prepare a draft Cleanup Action Plan (CAP), which will use the RI/FS information to describe a preferred cleanup action.

The draft Public Participation Plan outlines and describes the tools that Ecology will use to inform the public about site activities, and it identifies

opportunities for the community to become involved in this process.

The following hazardous substances are potential chemicals of concern (COCs) for subsurface soil and groundwater at the site:

- Petroleum hydrocarbons
- Semi-Volatile Organic Compounds
- Chlorinated solvents

The excavations at the site were backfilled with clean fill material and six new wells were installed as part of the performance monitoring program. Also, there has been extensive groundwater monitoring and in general, the concentration of several of the chemicals of concern has decreased.

The proposed Agreed Order and Public Participation Plan are available for review at the following locations:

- King County Public Library – Kirkland, 308 Kirkland Avenue, Kirkland, WA 98033 **425/822-2459**
- Ecology Northwest Regional Office, 3190 160th Ave. SE, Bellevue, WA 98008-5482. (Please call **Sally Perkins** at **425/649-7190** for an appointment.)

- Ecology's website: http://www.ecy.wa.gov/programs/tcp/sites/pace/pace_hp.html

For more information or to submit written comments, please contact **Maura S. O'Brien**, Site Manager, at the Ecology address listed above or at **425/649-7249** or e-mail mobr461@ecy.wa.gov.

PIERCE COUNTY

Superlon Plastics Co., Inc., 2116 Taylor Way, Tacoma Facility Site ID# 2776343

Negotiations for an Agreed Order

Ecology, White Birch, LLC and E.I. DuPont De Nemours and Company have begun negotiations for an Agreed Order to complete a Remedial Investigation and

Feasibility Study at the Superlon Plastics site in Tacoma.

From 1925 to 1951, the property was used to produce and warehouse lead-arsenate pesticides. In 1951, the site was sold and operated as a lumber company and wood treatment facility until 1972. Superlon Plastics purchased the site in 1972 to manufacture plastic piping. The site is still active. Site investigations led to the discovery of several contaminants above state standards in soil, groundwater and standing water. Contaminants include arsenic, cadmium, lead, mercury, gasoline and oil range hydrocarbons, pentachlorophenol, tetrachloroethylene, trichloroethylene, cis-1,2-dichloroethylene, vinyl chloride, and chloromethane.

For more information about this site, please contact **Laura Klasner**, Site Manager, at **360/407-6265** or e-mail **lkl461@ecy.wa.gov** or at Ecology Southwest Regional Office, 300 Desmond Drive, Lacey, WA 98504-7775.

SNOHOMISH COUNTY

US DOJ DEA Yttri-Wozow Site, 9218 171st Ave S.E., Snohomish Facility Site ID# 2833

Public comment period:
12/19/08 – 1/20/09

Proposed Delisting from Hazardous Sites List

Ecology proposes to remove Yttri-Wozow site also known as US DOJ DEA (United States Department of Justice/ Drug Enforcement Administration), from the state's Hazardous Sites List. The Yttri-Wozow property is located at 9218 171st Ave S.E., Snohomish, Washington, 98290.

The area is approximately 2 acres. A former tenant used the property as a junkyard, covert drug lab and salvage storage area. Mr. Randy Yttri was the original owner of the property, which was subsequently transferred to the Wozow family. In 2004, B&R Homes

LLC (B&R) purchased the property and began construction of a single family residence. Construction was halted by regulatory agencies until the site's cleanup status could be determined.

Following a 1994 DEA investigation that found an illegal methamphetamine lab at the property, this site was listed on the state database for Confirmed and Suspected Contaminated Site List. It has been under investigation by regulatory and law enforcement agencies from 1994-2005. The site was also referred for a site hazardous assessment. Based on this assessment this site was given a "5" ranking on the Washington State Hazardous Sites List. This ranking is based on a scale of 1 to 5 where "1" represents the highest relative risk, and "5" represents the lowest relative risk. The site rank is also designed to estimate the potential threat to human health and the environment, relative to all other sites in Washington.

After a 2006 environmental investigation to assess the site, the following materials were removed from the property as part of the cleanup work:

- About 1 ½ tons of metal debris recovered from test pits, 95 tons of solid waste
- 50 buried batteries and about 15 tons of excavated soil from an area where batteries were buried

Ecology has determined that the remediation work of the Yttri-Wozow site meets the substantial requirements of the Model Toxics Control Act (MCTA) and therefore does not pose a threat to human health or the environment. Ecology proposes to remove the site from the Hazardous Sites list and wants your input.

The proposed Agreed Order and Public Participation Plan are available for review at the following locations:

- Ecology Northwest Regional Office, 3190 160th Ave. SE, Bellevue, WA 98008-5482. (Please call **Sally Perkins** at **425/649-7190** for an appointment.)

- Ecology's website: <http://www.ecy.wa.gov/programs/tcp/sites/yttri/yttri.htm>

For more information or to submit written comments, please contact **Russ Olsen**, Voluntary Cleanup Program Unit Supervisor, at the Ecology address listed above or at **425/649-7038** or e-mail **rols461@ecy.wa.gov**.

SPOKANE COUNTY

BNSF Railway Company (BNSF) Parkwater Railyard Site, 5302 East Trent Avenue, Spokane Facility Site ID# 676

Public comment period:
1/12/09 – 2/10/09

Agreed Order Available for Public Comment

Public Meeting: January 13, 2009 from 7-9 p.m.

*Mountain Gear Corporate Office
6021 E. Mansfield
Spokane Valley, WA 99212*

You are invited to review the proposed Agreed Order, attend the public meeting, and provide comments to Ecology. The Washington State Department of Ecology plans to enter into an Agreed Order with BNSF Railway Company (BNSF) to conduct a Remedial Investigation and Feasibility Study at the Parkwater Railyard site. The BNSF Parkwater facility, formerly known as Yardley, is one-half mile south of the Spokane River and lies over the Spokane Valley Rathdrum-Prairie Aquifer in the Spokane Valley. The site is located at 5302 East Trent Avenue in the city of Spokane, Spokane County, Washington.

The Agreed Order is a legal document issued by Ecology. It formalizes the agreement between Ecology and BNSF for the necessary investigations at the site. The purpose of the Remedial Investigation is to gather information to determine where and how much contamination is present in soil and groundwater. The Feasibility Study

will evaluate cleanup alternatives in preparation for a cleanup action.

The site operated as a railyard for nearly 100 years. Operations continue today and include fueling, intermodal operations, and switching of rail cars. In 1990 a petroleum release was discovered during the removal of an underground storage tank believed to contain petroleum. Petroleum constituents consistent with diesel fuel have been detected in soil and groundwater near the locomotive fueling area on the rail yard.

You may review the Agreed Order at the following locations:

- Argonne County Library, 4322 N. Argonne, Spokane, WA 99206
- Spokane Valley Library, 12004 E. Main, Spokane Valley, WA 99216
- Ecology Eastern Regional Office, 4601 N. Monroe, Spokane WA 99205-1295. (Please call **Kari Johnson** at **509/329-3415** for an appointment.)
- Ecology's website: [://www.ecy.wa.gov/programs/tcp/sites/parkwater/railyard_hp.htm](http://www.ecy.wa.gov/programs/tcp/sites/parkwater/railyard_hp.htm)

For more information or to submit written comments, please contact **Ms. Sandra Treccani**, Site Manager, at the Ecology address listed above or at **509/329-3412** or e-mail satr461@ecy.wa.gov.

Para asistencia en Espanol **Richelle Perez** at **360/407-6971**

Если вам нужно помощь по русский, звоните: **Tatyana Bistrevsky** at **509/928-7617**

Liên hệ bằng tiếng Việt, xin liên lạc **360/407-6948**

Progress Elementary, 710 North Progress Road, Spokane Valley Facility Site ID# 1740049

Public comment period:
1/7/09 – 2/6/09

Proposed Removal from Hazardous Sites List

You are invited to comment on the proposed removal of Progress Elementary School from Ecology's Hazardous Sites List. Cleanup at the site was part of Ecology's Area-Wide Soil Contamination Project. The focus of the project was to identify and clean up lead and arsenic on orchard lands that were developed in to properties with high child use.

Pesticides containing a mixture of lead and arsenic were used on orchard lands from 1905 until the late 1940s. In 2005 the Spokane Regional Health District sampled soil at the school because the property was a former orchard land. Results showed lead and arsenic in soil above safe levels allowed by the state.

Several tasks were completed to protect children using the playground. A special man-made geo-textile cover was placed over existing soil or grass to act as a barrier and marker between dirty and clean soils. Clean topsoil was put over the entire site at a thickness of 6 inches. A topsoil nutrient amendment was placed on areas receiving hydroseed or sod. Ground covering was replaced with similar materials; for example, grass removed was replaced with new grass. Gravel and concrete curbing in play areas was removed and replaced. The sprinkler system was adjusted as necessary, and a restrictive covenant, now called an environmental covenant, was established on the property to prevent damage to the protective barrier and limit land uses. The restrictive covenant shows the type and location of contamination on the property. It also protects public health ensuring that the cleanup actions will not be damaged by future activities.

You may review the fact sheet and associated site documents at the following locations:

- Ecology Eastern Regional Office, 4601 N. Monroe, Spokane WA 99205-1295. (Please call **Kari Johnson** at **509/329-3415** for an appointment.)
- Ecology's website: http://www.ecy.wa.gov/programs/tcp/sites/progress_es/progress_es_hp.htm

[wa.gov/programs/tcp/sites/progress_es/progress_es_hp.htm](http://www.ecy.wa.gov/programs/tcp/sites/progress_es/progress_es_hp.htm)

- To learn more about lead and arsenic see Ecology's Dirt Alert brochure at: <http://www.ecy.wa.gov/biblio/0609048.html>

Para asistencia en Espanol **Richelle Perez** at **360/407-6971**

Если вам нужно помощь по русский, звоните: **Tatyana Bistrevsky** at **509/477-3881**

For more information or to submit written comments, please contact **Sandra Treccani**, Site Manager, at the Ecology address listed above or at **509/329-3412** or e-mail satr461@ecy.wa.gov.

INDEPENDENT CLEANUPS

A property owner may conduct an independent cleanup of contamination and submit reports to Ecology. When a property owner applies to Ecology for review of their independent cleanup, the site enters the Voluntary Cleanup Program. After review, Ecology sends a letter to the property owner stating either that additional work is required to be removed from the list of hazardous waste sites or that no further action is needed.

DOUGLAS COUNTY

Central Regional Office Contact: e-mail Rjoh461@ecy.wa or call 509/575-2490

Liberty Tank Lines Spill, SR 17, MP 127, Bridgeport Facility Site ID # 82565711 - Submitted 12/15/08. Report received: October 2008 Groundwater Monitoring & Sampling Event Report.

KING COUNTY

Northwest Regional Office Contact: e-mail Dmus461@ecy.wa or call 425/649-7136

7-Eleven Food Store #2306-26056b,

3302 E Lake Sammamish Pwy SE #100, Issaquah Facility Site ID # 64259867 - Submitted 12/8/08. Report received: Groundwater Status September 2008.

Alaska St Texaco, 3901 SW Alaska St, Seattle Facility Site ID # 39196282 - Submitted 12/7/08. Report received: Prelim. Historic Site Research & Geophysical. Survey Letter Rpt.

Bellevue Northrop Chevron, 13948 NE 20th St, Bellevue Facility Site ID # 6541715 - Submitted 12/8/08. Report received: Groundwater Status February 2008.

Burien 76, 12660 1st Ave S, Burien Facility Site ID # 35395376 - Submitted 12/17/08. Report received: Groundwater Status August 2008.

Chevron 97451, 2626 Bellevue Way NE, Bellevue Facility Site ID # 53482918 - Submitted 12/8/08. Report received: Groundwater Status June 2008; Groundwater Status September 2008.

ConocoPhillips Company-2603142, 2841 S 188th, SeaTac Facility Site ID # 92871162 - Submitted 12/15/08. Report received: Groundwater Status October 2008.

Former Gull 220, 1637 W Meeker Street, Kent Facility Site ID # 51268843 - Submitted 12/11/08. Report received: Groundwater Status October 2008.

Former Unocal 6248, 11845 Des Moines Way S, Seattle Facility Site ID # 66498524 - Submitted 12/12/08. Report received: Groundwater Well & Soil Vapor Probe Install Plan.

SeaTac 76, 16850 International Blvd, SeaTac Facility Site ID # 73251149 - Submitted 12/19/08. Report received: Groundwater Status October 2008.

Smith-Gandy Building, 1100 Olive Way, Seattle Facility Site ID # 11842931 - Submitted 12/24/08. Report received: Remedial Progress Report 7.

Sun Cor Holdings-Copii LLC, 11655 Renton Ave S, Seattle Facility Site ID # 61442182 - Submitted 12/5/08. Report received: Groundwater Status October 2008.

Sunmart 2, 711 N Central Ave, Kent Facility Site ID # 38458226 - Submitted 12/11/08. Report received: Groundwater Status October 2008.

Texaco Star Mart #63-232-272, 18800 Woodinville-Duvall Rd, Woodinville Facility Site ID # 89785828 - Submitted 12/12/08. Report received: Groundwater Status July 2008.

Uhaul Co of Kirkland, 12006 NE 85th Street, Kirkland Facility Site ID # 23174884 - Submitted 12/24/08. Report received: Remedial Feasibility August 2008.

KITSAP COUNTY

Northwest Regional Office Contact:
e-mail Dmus461@ecy.wa or call
425/649-7136

Convenience Retailers #2705402, 1350 Bay Street, Port Orchard Facility Site ID # 85753551 - Submitted 12/17/08. Report received: Groundwater Status July 2008.

Convenience Retailers #2705522, 10023 Old Frontier Rd NW, Silverdale Facility Site ID # 75359597 - Submitted 12/5/08. Report received: Groundwater Status September 2008.

Poulsbo Food Mart 399, 19740 Viking Way Ave NW, Poulsbo Facility Site ID # 68211258 - Submitted 12/5/08. Report received: Groundwater Status May 2008.

LEWIS COUNTY

Southwest Regional Office Contact:
e-mail Kcro461@ecy.wa or call
360/407-6240

Chevron 60096942, 1233 Alder St, Centralia Facility Site ID # 17551864 - Submitted 12/12/08. Report received: 2008 Annual Groundwater Monitoring Rpt.

State Street Texaco, 1349 NW State St, Chehalis Facility Site ID # 47829194 - Submitted 12/5/08. Report received: Groundwater Monitoring Report 3rd Qtr 2008.

PIERCE COUNTY

Southwest Regional Office Contact:
e-mail Kcro461@ecy.wa or call
360/407-6240

Food Mart 345, 8320 Canyon Rd E, Puyallup Facility Site ID # 72868291 - Submitted 12/9/08. Report received: 2nd Q 2008 Groundwater Monitoring.

Texaco Station #63-232-0168, 2325 Meridian E, Edgewood Facility Site ID # 44579441 - Submitted 12/10/08. Report received: 3rd Q 2008 Groundwater Monitoring.

SKAGIT COUNTY

Northwest Regional Office Contact:
e-mail Dmus461@ecy.wa or call
425/649-7136

Petrosun #1155, 17587 State RT 536, Mount Vernon Facility Site ID # 67747518 - Submitted mm/dd/08. Report received: Groundwater Status June 2008

SKAMANIA COUNTY

Southwest Regional Office Contact:

e-mail Kcro461@ecy.wa or call
360/407-6240

**Home Valley Grocery 110, 50151
SR 14, Stevenson Facility Site ID #
35352326** - Submitted 12/5/08. Report
received: 3rd Qtr 2008 Focused Groundwater
Remediation & Monitoring Report.

SNOHOMISH COUNTY

**Northwest Regional Office Contact:
e-mail Dmus461@ecy.wa or call
425/649-7136**

**Jackpot Food Mart Co. 169, 851 N
Broadway, Everett Facility Site ID #
54678156** - Submitted 12/5/08. Report
received: Groundwater Status June 2008.

**Taco Time, 3805 Rucker Ave, Everett
Facility Site ID # 1469239** - Submitted
12/11/08. Report received: Groundwater
Status November 2008.

WHATCOM COUNTY

**Northwest Regional Office Contact:
e-mail Dmus461@ecy.wa or call
425/649-7136**

**Burlington Northern RR Bellingham
North, 2658 Roeder Ave, Bellingham
Facility Site ID # 43966326** - Submitted
12/18/08. Report received: Groundwater
Status October 2008.

VOLUNTARY CLEANUP PROGRAM

Under Ecology's Voluntary Cleanup Program (VCP), a property owner cleaning up a contaminated site pays a fee for Ecology review. When a cleanup is determined to be sufficient, Ecology issues a no further action decision.

CLARK COUNTY

**SW VCP Contact: Scott Rose,
360/407-6347 or e-mail Sros461@ecy.wa.**

**Esquire Cleaners/Macarthur Center,
7615 Mac Arthur Blvd, Vancouver
Facility Site ID # 96459896** - Submitted
12/4/08. Report received: Remedial
Investigation Report. Media contaminated:
Soil and Groundwater. Contaminants:
Halogenated Organic Compounds. Site
status: Independent remedial action in
process.

GRANT COUNTY

**Contact: Patti Carter, 509/329-3522 or
e-mail Paca461@ecy.wa**

**Coulee Hartline School District 151,
410 W Locust, Coulee City Facility
Site ID # 85559561** - Submitted 2/4/08.
Report received: Remedial Investigation
Report. Media contaminated: Soil.
Contaminants: Petroleum Products. Site
status: Completed Opinion Letter. Project
Completed.

KING COUNTY

**NW VCP Contact: Donna Musa,
425/649-7136 or e-mail Dmus461@ecy.wa**

**Texaco Wallingford, 118 NE 45th St,
Seattle Facility Site ID # 4465692** -
Submitted 12/22/08. Media contaminated:
Soil and Groundwater. Contaminants: Metals
– other; Petroleum Products. Site status:
Independent remedial action in process.

**College Street Apartments, 4301 SW
College St, Seattle Facility Site ID
4824752** - Submitted 12/11/08. Report
received: Remedial Investigation Report.
Media contaminated: Soil. Contaminants:
Petroleum Products. Site status: Independent
remedial action in process.

**Kingston Residence, 4727 9th Av NE,
Seattle Facility Site ID # 6518814** -
Submitted 12/10/08. Media contaminated:
Soil and Groundwater. Contaminants:
Petroleum Products. Site status: Independent
remedial action in process.

**Shell Oil Product , 31660 Pacific Hwy
S, Federal Way Facility Site ID #
13539617** - Submitted 12/22/08. Media
contaminated: Soil and Groundwater.
Contaminants: Metals – other Petroleum
Products. Site status: Independent remedial
action in process.

**Shell Station 120877, 210 NE 45th St,
Seattle Facility Site ID # 14577491** -
Submitted 12/22/08. Media contaminated:
Soil and Groundwater. Contaminants:
Petroleum Products; MTBE. Site status:
Independent remedial action in process.

**Texaco Station 120516 , 1133 W
James St, Kent Facility Site ID #
20469999** - Submitted 12/22/08. Media
contaminated: Soil and Groundwater.
Contaminants: Petroleum Products; MTBE.
Site status: Independent remedial action in
process.

**Jackpot Station 305, 16757 Redmond
Way NE, Redmond Facility Site ID #
23164812** - Submitted 12/11/08. Report
received: Interim Action Report. Media
contaminated: Soil. Contaminants: Petroleum
Products. Site status: Independent remedial
action in process.

**SunMart 1, 21449 Pacific Hwy S, Des
Moines Facility Site ID # 35888116** -
Submitted 12/22/08. Media contaminated:
Soil and Groundwater. Contaminants: Metals
– other; Petroleum Products. Site status:
Independent remedial action in process.

**Shell Station 120441, 1013 NE 45th St,
Seattle Facility Site ID # 519941974** -
Submitted 12/22/08. Media contaminated:
Soil and Groundwater. Contaminants:
Petroleum Products; MTBE. Site status:
Independent remedial action in process.

Shell 120930, 22588 84th Ave S, Kent Facility Site ID # 55129449 - Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Metals – other; Petroleum Products. Site status: Independent remedial action in process.

Texaco Station, 511 Dearborn St, Seattle Facility Site ID # 59579759 - Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Petroleum Products; MTBE. Site status: Independent remedial action in process.

Walt's Service Center, 546 Burnett Ave N, Renton Facility Site ID # 62238722 - Submitted 12/11/08. Report received: Interim Action Report. Media contaminated: Soil and Groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide; Petroleum Products; Non-Halogenated Solvents. Site status: Independent remedial action in process.

Shell Oil Products, 13201 SE 272nd St, Kent Facility Site ID # 65688356 - Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Petroleum Products. Site status: Independent remedial action in process.

Shell Station, 2501 NE 75th St, Seattle Facility Site ID # 66383785 - Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Petroleum Products; MTBE. Site status: Independent remedial action in process.

Shell Station, 2424 Beacon Ave, Seattle Facility Site ID # 71317148 - Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Metals – other; Petroleum Products. Site status: Independent remedial action in process.

Shell Station, 17255 Aurora Ave N, Shoreline Facility Site ID # 79631686 - Submitted 12/22/08. Report received: Interim Action Report. Media contaminated: Soil. Contaminants: Metals – other; Petroleum Products. Site status: Independent remedial action in process.

Shell Station, 3100 E Madison St, Seattle Facility Site ID # 80616298 - Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Petroleum Products; MTBE. Site status: Independent remedial action in process.

Juanita Firs Shell, 13701 100th Ave NE, Kirkland Facility Site ID # 92142255 - Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Metals – other; Petroleum Products; MTBE. Site status: Independent remedial action in process.

Texaco 121287, 4605 Fremont Ave N, Seattle Facility Site ID # 94485958 - Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Metals – other; Petroleum Products; MTBE. Site status: Independent remedial action in process.

Surftech Finishes Co Inc, 22436 72nd Ave S, Kent Facility Site ID # 95894611 - Submitted 12/11/08. Media contaminated: Soil and Groundwater. Contaminants: Halogenated Organic Compounds. Site status: Independent remedial action in process.

KITTITAS COUNTY

CR VCP Contact: Frosti Smith, 509/454-7841 or e-mail Fsmi461@ecy.wa.gov

University Auto Center, 100 E University Way, Ellensburg Facility Site ID # 65863261 - Submitted 12/8/08. Media contaminated: Soil and Groundwater. Contaminants: Petroleum Products. Site status: Independent remedial action in process.

MASON COUNTY

SW VCP Contact: Scott Rose, 360/407-6347 or e-mail Sros461@ecy.wa.gov

Sandy's Deli Mart & Gas, NE 120 Hwy 300, Belfair Facility Site ID # 16929485 - Submitted 8/10/06. Report received: Remedial Investigation Work Plan; Remedial Investigation Report. Media contaminated: Soil and Groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide; Petroleum Products; Non-Halogenated Solvents; MTBE. Site status: Completed Opinion Letter. Independent remedial action in process.

PIERCE COUNTY

SW VCP Contact: Scott Rose, 360/407-6347 or e-mail Sros461@ecy.wa.gov

Fife 76, 2002 E 54th Ave, Fife Facility Site ID # 72452584 - Submitted 12/18/08. Report received: title. Media contaminated: Soil and Groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide; Petroleum Products; Non-Halogenated Solvents. Site status: Independent remedial action in process.

Hosmer 76 & Car Wash, 8235 S Hosmer, Tacoma Facility Site ID # 98852274 - Submitted 12/8/08. Report received: Remedial Investigation Report. Media contaminated: Soil and Groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide; Petroleum Products; Non-Halogenated Solvents. Site status: Independent remedial action in process.

SNOHOMISH COUNTY

NW VCP Contact: Donna Musa, 425/649-7136 or e-mail Dmus461@ecy.wa.gov

Shell Station 120839, 19930 44th Ave W, Lynnwood Facility Site ID # 6326863 - Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Metals – other; Petroleum Products. Site status: Independent remedial action in process.

Texaco 121117, 3315 172nd St NE, Arlington Facility Site ID # 8894437 -

Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Petroleum Products. Site status: Independent remedial action in process.

Legion Memorial Golf Course, E Marine View Drive, Everett Facility Site ID # 9311679 -

Submitted 12/8/08. Report received: Cleanup Action Plan. Media contaminated: Soil. Contaminants: EPA Priority Pollutants – metals and cyanide. Site status: Independent remedial action in process.

Texaco 120848, 201 128th St SW, Everett Facility Site ID # 13589449 -

Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Petroleum Products. Site status: Independent remedial action in process.

Shell Station 120562, 1221 Ave D, Snohomish Facility Site ID # 33913433

- Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Metals – other; Petroleum Products. Site status: Independent remedial action in process.

5 Corners Deli Market, 8406 Bowdoin Way, Edmonds Facility Site ID #

64436181 - Submitted 7/24/08. Report received: Final Cleanup Report. Media contaminated: Soil. Contaminants: Petroleum Products. Site status: Completed Consultation.

Texaco Star Mart 3706 Snohomish, 17924 SR 9 SE, Snohomish Facility Site ID # 97719941 -

Submitted 12/22/08. Report received: title. Media contaminated: Soil and Groundwater. Contaminants: Metals – other; Petroleum Products. Site status: Independent remedial action in process.

THURSTON COUNTY

SW VCP Contact: Scott Rose, 360/407-6347 or e-mail Sros461@ecy.wa.gov

Unocal Service Station 0266, 924 Capitol Way, Olympia Facility Site ID # 1439 -

Submitted 5/20/08. Report received: Remedial Investigation Report. Media contaminated: Soil and Groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide; Petroleum Products; Non-Halogenated Solvents; Polynuclear aromatic hydrocarbons (PAH). Site status: Completed Opinion Letter. Independent remedial action in process.

WHATCOM COUNTY

NW VCP Contact: Donna Musa, 425/649-7136 or e-mail Dmus461@ecy.wa.gov

Shell Station 120793, 1811 Main St, Ferndale Facility Site ID # 93697533

- Submitted 12/22/08. Media contaminated: Soil and Groundwater. Contaminants: Metals – other; Petroleum Products; MTBE. Site status: Independent remedial action in process.

TOXICS CLEANUP PROGRAM PUBLICATIONS

Contact: Ann McNeely, 360/407-7205 or e-mail Amcn461@ecy.wa.gov

Residential Heating Oil Tanks
Publication # R-TC-92-117, Date: December 2008

Bothell Landing, Bothell Riverside, & Bothell Paint & Decorating
Publication # 08-09-163, Date: December 2008

Cenex Supply & Marketing Inc. Rinsate Site
Publication # 08-09-030, Date: December 2008

Cenex Supply & Marketing Inc. Sitio Rinsate
Publication # 08-09-030ES, Date: December 2008

Focus on Brownfield Investments
Publication # 08-09-047, Date: December 2008

Fox Avenue Building LLC Site
Publication # 08-09-111, Date: December 2008

Washington Water Power Central Steam Plant Site
Publication # 08-09-051, Date: December 2008

Yttri-Wozow site also known as US DOJ DEA
Publication # 08-09-077, Date: December 2008

ULTRA Corporation Former Pace National Site
Publication # 08-09-162, Date: December 2008
