

Site Register

WASHINGTON STATE DEPARTMENT OF ECOLOGY TOXICS CLEANUP PROGRAM



FEBRUARY 12, 2009

The Site Register is published every two weeks to inform you about public comment periods, public meetings, hearings, and other information related to the study and cleanup of hazardous waste sites under the Model Toxics Control Act, Chapter 70.105D RCW.

You may also find information about public hearings, meetings, workshops, and open public comment periods on Ecology's web page. Go to www.ecy.wa.gov and click on the Public Involvement Calendar.

If you have questions or want to be added to the mailing list (electronic or paper) for the Site Register, contact Linda Thompson at 360/407-6069 or e-mail Ltho461@ecy.wa.gov. Specific regional contacts are listed after each entry.

If you need this publication in an alternate format, please call the Toxics Cleanup Program at 360/407-7170. Persons with hearing loss may call 711 for Washington Relay Service. Persons with a speech disability may call 877/833-6341.

CONTENTS

Formal Cleanups	1
Independent Cleanups	5
Voluntary Cleanup Program	9
Site Hazard Assessments	15
Other Department Notices	15
Program Publications	15

FORMAL CLEANUPS

Ecology oversees complex cleanup sites to ensure that your health and that of the environment are protected.

CLARK COUNTY

**Evergreen Airport, 13800-14144 SE Mill Plain Boulevard, Vancouver
Facility Site ID# 7056386**

**Public comment period:
2/2/09 – 3/2/09**

Proposed Delisting from Hazardous Sites List

Ecology is proposing to remove the Evergreen Airport cleanup site from the Hazardous Sites List. A Hazardous Sites List is a statewide list of contaminated properties. This site was cleaned up under the Voluntary Cleanup Program (VCP). Ecology has reviewed the site cleanup activity and determined that

- The site is no longer a threat to human health or the environment.
- The cleanup actions at the site meet MTCA cleanup standards.
- No further action is needed.

The Evergreen Airport site includes approximately 52 acres and is located at 13800 through 14114 SE Mill Plain Boulevard in Vancouver, WA. The site was formerly used as an airport and contained hangars, office buildings, a runway, control tower and eight additional buildings (leased). It was developed into an airfield in approximately 1945.

Investigations at the site revealed soil contamination at levels above state cleanup standards from gasoline, diesel and heavy oil-range petroleum hydrocarbons and metals (cadmium, chromium and lead). Groundwater was not contaminated.

The site was entered into the VCP program in October 2005. Cleanup actions at the site included excavation of contaminated soil, removal of underground and above-ground storage tanks and piping, and disposal of contaminated soil. Based on sampling results and cleanup activities, Ecology has determined that the site no longer poses a threat to the environment or human health. Ecology has issued a determination of No Further Action and is proposing to remove the site from the Hazardous Sites List. A No Further Action Opinion letter was issued in December 2008.

The Cleanup Action Plan and No Further Action Letter may be reviewed at the locations listed below until March 2, 2009.

- Fort Vancouver Public Library, 1007 E Mill Plain Boulevard, Vancouver, WA 98663. **360/695-1566**
- Ecology Southwest Regional Office, 300 Desmond Drive, Lacey, WA 98504-7775. (By appointment only: Contact **Debbie Nelson** at 360/407-6365 or e-mail **Dene461@ecy.wa.gov**.)
- Ecology's website: http://www.ecy.wa.gov/programs/tcp/sites/evergreen_Air/evgrnAir_hp.html

To submit written comments or technical questions, please contact **Steve Teel**, Site Manager, at the Ecology address listed above or at 360/407-6247 or e-mail stee461@ecy.wa.gov. For public involvement information, please contact **Meg Bommarito**, Public Involvement Coordinator at 360/407-6255 or e-mail Mbom461@ecy.wa.gov.

KITSAP COUNTY

Bainbridge Island landfill, located off NE Vincent Road between Komjima Avenue NE & Fletcher Bay Road NE,

Bainbridge Island Facility Site ID# 2602

Public comment period:
2/13/09 – 3/16/09

Periodic Review

Ecology invites you to comment on the Periodic Review for the Bainbridge Island landfill. A periodic review is conducted at least every five years after the initiation of a cleanup action, as required by the Model Toxics Control Act (MTCA). This is the first periodic review for Bainbridge Island landfill. The purpose of the review is to evaluate site conditions and monitoring data, after cleanup is considered complete, in order to ensure human health and the environment is protected.

Kitsap County acquired the land in 1942 and several parties operated it as a landfill until 1975. The landfill accepted typical domestic waste, tank bottoms from the nearby Wyckoff wood treatment facility, and petroleum products. Refuse was burned at the site until 1968.

In 1992, Ecology listed the site on its Hazardous Sites List with a rank of 1 on the Washington State Hazardous Sites List. This ranking is based on a scale of 1 to 5. According to this scale, "1" represents the highest relative risk, and "5" represents the lowest relative risk. This ranking is designed to estimate the potential threat to human health and the environment, relative to all other sites in Washington State.

Also in 1992, Kitsap County removed, stabilized, and disposed 475 tons of contaminated waste. In 1993, and additional 930 tons of contaminated soils were removed and properly disposed at a permitted facility.

Kitsap County conducted a Remedial Investigation and Feasibility Study (RI/FS) for the cleanup of the landfill in 1996 under an enforcement order by Ecology. The investigation found low levels of volatile organic compounds (VOCs), such as those found in paints and solvents, in the groundwater. The

landfill cover soils and site surface water were also found to be contaminated. The primary medium of concern at the site is groundwater because it is used as an offsite domestic drinking water source.

When contamination was found in nearby drinking water wells, the Washington State Department of Health conducted a series of health consultation reports. The reports concluded no apparent public health hazard exists as a result of exposure to the contamination detected in the domestic wells. The groundwater continues to be monitored.

The selected cleanup action alternative consisted of waste reclamation with a soil cover, monitoring, institutional controls, and monitored natural attenuation. The waste was excavated and sorted by size. All materials larger than 1.5 inches in diameter were disposed offsite in a permitted landfill. Material smaller than 1.5 inches in diameter was left onsite and covered with a soil cap.

Kitsap County Health District (Health District) reviewed the first Five-Year Review Report for Bainbridge Island Landfill, Kitsap County, Washington by CH2M Hill. Here are the findings:

- Vinyl chloride concentrations in groundwater fall below the federal/state maximum contaminant level (MCL) and the Model Toxics Control Act Method A (MTCA-A) cleanup level but exceed the MTCA-B cleanup level.
- The Health District concludes that the results presented in the report indicate that the levels of vinyl chloride are not a significant health risk to persons using groundwater for domestic purposes because the reported concentrations are below the drinking water MCL of 2.0 ug/l. The Health District recommends continued monitoring of wells in accordance with the closure action plan because vinyl chloride continues to be detected.
- The Cleanup Action Plan states monitoring may go for 30 years before groundwater cleanup levels are met.

Ecology recommends that monitoring continue in accordance with the Cleanup Action Plan (CAP) until the concentrations of the contaminants fall below the cleanup levels.

After the 30-day public comment period, Ecology will review all comments received and make recommendations for any suggested changes to the periodic review. If no significant changes are necessary, the periodic review will be considered final.

You may review the periodic review report at:

- Ecology Northwest Regional Office, 3190 160th Ave. SE, Bellevue, WA 98008-5482. (Please call **Sally Perkins** at **425/649-7190** for an appointment.)
- Ecology's website: http://www.ecy.wa.gov/programs/tcp/sites/bil/bil_hp.htm

For more information or to submit written comments, please contact **Ching-Pi Wang**, Site Manager, at the Ecology address listed above or at **425/649-7134** or e-mail cwan461@ecy.wa.gov.

KING COUNTY

Joseph Simon & Sons Kent, 12441 Des Moines Memorial Way, Seattle Facility Site ID# 83334411

Public comment period:
1/30/09 – 3/2/09

Proposed Delisting from Hazardous Sites List

Ecology proposes to remove Joseph Simon & Sons Kent from the state's Hazardous Sites List. The Joseph Simon & Sons Kent site comprises most of a 6.2 acre property divided into two lots located at 917 and 1025 South Central Avenue in Kent, Washington. The Joseph Simon & Sons Kent site was farmland during the 1960s and was later developed as automobile wrecking and metal scrap storage yards. These operations continued until the 1980s.

In 2002, Ecology added the property to the Hazardous Site Listing due to hazardous substances detected in soils. This site was given a “1” ranking on the Washington State Hazardous Sites List. This ranking is based on a scale of 1 to 5 where “1” represents the highest relative risk and “5” represents the lowest relative risk. This ranking is designed to estimate the potential threat to human health and the environment, relative to all other sites in Washington State.

A number of environmental assessments have been conducted at the site. These assessments showed soil contaminated with diesel-and oil-range petroleum hydrocarbons, antimony, arsenic, cadmium, lead, mercury, polycyclic aromatic hydrocarbons, and polychlorinated biphenyls. Sampling and testing also determined that perched ground water was contaminated by diesel-and oil-range petroleum hydrocarbons. Cleanup of the site occurred in 2005. As part of the cleanup, 20,813 tons of contaminated soil were excavated and removed from the property. Almost 300 soil samples were taken during and following the excavation to guide and confirm the cleanup. Ground water monitoring was conducted quarterly for a year in eight wells.

Ecology has determined that the remediation of the Joseph Simon & Sons Kent site meets the substantial requirements of the Model Toxics Control Act and therefore the site no longer poses a threat to human health or the environment. Ecology proposes to remove the site from the Hazardous Sites list and wants your input.

Joseph Simon & Sons Kent documents are available at

- Ecology Northwest Regional Office, 3190 160th Ave. SE, Bellevue, WA 98008-5482. (Please call **Sally Alexander** at 425/649-7239 or **Sally Perkins** at 425/649-7190 for an appointment.)

- Ecology’s website: <http://www.ecy.wa.gov>.

[wa.gov/programs/tcp/sites/jos_simons/jos_sim_hp.htm](http://www.ecy.wa.gov/programs/tcp/sites/jos_simons/jos_sim_hp.htm)

For more information or to submit written comments, please contact **Mark Adams**, Site Manager, at the Ecology address listed above or at 425/649-7107 or e-mail mada461@ecy.wa.gov.

Mike’s Aussie Machine Shop, 12441 Des Moines Memorial Way, Seattle Facility Site ID# 2334

Public comment period:
1/30/09 – 3/2/09

Proposed Delisting from Hazardous Sites List

Ecology proposes to remove Mike’s Aussie Machine Shop from the state’s Hazardous Sites List. The property was added to the Hazardous Site Listing in March 18, 1991 for suspected non-halogenated solvents, petroleum products, and metals in soil and ground water. This site is ranked a “5” on the Washington State Hazardous Sites List. This ranking is based on a scale of 1 to 5. According to this scale, “1” represents the highest relative risk, and “5” represents the lowest relative risk. This ranking is designed to estimate the potential threat to human health and the environment, relative to all other sites in Washington State.

In June 2005, oil, cadmium, and lead contaminated soil was excavated and disposed of offsite. Confirmation sampling showed the remaining soils met state cleanup standards.

Ecology has determined that the remediation work at the Mike’s Aussie Machine Shop site meets the substantial requirements of the state cleanup standards and therefore does not pose a threat to human health or the environment. Ecology proposes to remove the site from the Hazardous Sites list and wants your input.

Mike’s Aussie Machine Shop documents are available at

- Ecology Northwest Regional Office, 3190 160th Ave. SE, Bellevue, WA 98008-5482. (Please call **Sally Alexander** at 425/649-7239 or **Sally Perkins** at 425/649-7190 for an appointment.)

- Ecology’s website: <http://www.ecy.wa.gov/programs/tcp/sites/mikesAussie/machineShop.htm>

For more information or to submit written comments, please contact **Mark Adams**, Site Manager, at the Ecology address listed above or at 425/649-7107 or e-mail mada461@ecy.wa.gov.

PIERCE COUNTY

Sauro’s Cleanerama, 1401 Pacific Ave., Tacoma Facility Site ID# 4339824

Public comment period:
2/12/09 – 3/16/09

Agreed Order for Investigation and Cleanup

Ecology would like your comments on an Agreed Order (legal agreement) with the City of Tacoma for the Sauro’s Cleanerama site. The City of Tacoma recently purchased the property from the Estate of Pete Sauro and plans to clean up and redevelop it.

As part of this agreement, the City of Tacoma will complete a:

- Remedial Investigation to determine the nature and extent of contamination.
- Feasibility Study to look at possible cleanup options.
- Draft Cleanup Action Plan to outline the cleanup strategy.

Cleanup of contaminated soils and groundwater must meet state standards under the Model Toxics Control Act (MTCA), Chapter 70.105D.

Documents are available for public review at:

- Tacoma Public Library, 1102 Tacoma Avenue, Tacoma, WA 98402 **253/591-5666**

- Citizens for a Healthy Bay, 917 Pacific Avenue, Suite 100, Tacoma, WA 98402 **253/383-2429**

- Ecology Southwest Regional Office, 300 Desmond Drive, Lacey, WA 98504-7775. (By appointment only: Contact **Debbie Nelson** at **360/407-6365** or e-mail **Dene461@ecy.wa.gov**.)

- Ecology's website: **www.ecy.wa.gov/programs/tcp/sites/sauros/sauros_hp.htm**.

For more information or to submit written comments, please contact **Marv Coleman**, Site Manager, at the Ecology address listed above or at **360/407-6259** or e-mail **Mcol461@ecy.wa.gov**. For public involvement information, please contact **Hannah Aoyagi**, Public Involvement Coordinator at **360/407-6790** or e-mail **Haoy461@ecy.wa.gov**.

SNOHOMISH COUNTY

Brashler Industrial Park [former Premier Offset Web Sales], 5701 48th Drive NE, Marysville Facility Site ID# 2765

Public comment period:
2/27/09 – 3/30/09

Proposed Delisting from Hazardous Sites List

Ecology proposes to remove Brashler Industrial Park, former Premier Offset Web Sales (Premier Offset Web Sales) from the state's Hazardous Sites List. Brashler Industrial Park operated a machine shop where the majority of the work involves rebuilding old printing presses.

Ecology conducted an initial investigation of the property in 1991, which determined printing press cleaning activities were conducted on the soil outside the building. Soil analysis found that cadmium was the only metal above state standards. Other chemicals of concern were arsenic in soil and groundwater as well as petroleum hydrocarbons in the soil. Based on

these results, the site was added to the Washington State Hazardous Sites List. The site was ranked a "3" on the Washington State Hazardous Sites List. This ranking is based on a scale of 1 to 5. According to this scale, "1" represents the highest relative risk, and "5" represents the lowest relative risk. This ranking is designed to estimate the potential threat to human health and the environment, relative to all other sites in Washington State.

Ecology has determined that the remediation work at the Premier Offset Web Sales site meets the substantive requirements of the Model Toxics Control Act (MTCA) and therefore does not pose a threat to human health or the environment. Ecology proposes to remove the site from the Hazardous Sites list and wants your input.

Premier Offset Web Sales documents are available at:

- Ecology Northwest Regional Office, 3190 160th Ave. SE, Bellevue, WA 98008-5482. (Please call **Sally Perkins** at **425/649-7190** for an appointment.)

- Ecology's website: **http://www.ecy.wa.gov/programs/tcp/sites/premierOffset/premierOffset_hp.html**

For more information or to submit written comments, please contact **Joe Hickey**, Site Manager, at the Ecology address listed above or at **425/649-7202** or e-mail **jhic461@ecy.wa.gov**.

SPOKANE COUNTY

Kaiser Aluminum & Chemical Corporation Heglar Kronquist Site, 10 miles northeast of downtown Spokane in a rural area near the intersection of Heglar and Kronquist Roads in Mead Facility Site ID# 645

Public comment period:
2/9/09 – 3/11/09

Agreed Order for a Remedial Investigation and Feasibility Study

Sampling Results to be Explained at Public Meeting on Tuesday, February 17, 2009 from 7-9 p.m. at Mt. Spokane High School - Atrium, 6015 East Mt. Spokane Park Drive Mead.

Ecology will host a public meeting to discuss the draft Agreed Order that Ecology proposes to enter into with Kaiser Aluminum & Chemical Corporation, LLC. On December 10 and 11, 2008, Ecology and Kaiser sampled 16 residential wells near the Heglar Kronquist site. Preliminary results of this sampling will be presented at the public meeting on February 17, 2009. A representative from the local regional health district will also be at the meeting to answer health-related questions.

The Agreed Order requires Kaiser to conduct a Remedial Investigation and Feasibility Study at the Heglar Kronquist site. It also formalizes the agreement between Ecology and Kaiser to assess the contamination and the need for additional cleanup actions at the site. The purpose of the Remedial Investigation is to gather more information to determine the nature and extent of site-related contamination that may be in soil and groundwater. The Feasibility Study will evaluate cleanup options.

The nearly four-acre site was used as a gravel pit until it was closed in 1969. Kaiser disposed of aluminum black dross from its Trentwood plant at the Heglar site. Black dross is a by-product from processing aluminum materials. The dross disposal was stopped in 1974 because high levels of chloride were found in shallow water supply wells and springs down gradient of the site. Air sampling conducted downwind of the site in 1979 showed elevated levels of several organic compounds. Ammonia also was detected at levels higher than accepted by state laws.

Past site data show that chemicals of concern related to the aluminum dross include: sodium, potassium, aluminum, chloride, fluoride, ammonia, nitrates and nitrites. The Remedial Investigation

will provide additional information to identify the extent and concentration of contaminants at the site.

Kaiser took several steps to address the contamination in 1984 including the installation of a cover designed to protect the dross pile, and they eventually purchased the property. Monitoring that occurred from the early 1980s through 2004 indicated decreasing but still elevated chloride and nitrates in springs downgradient from the site.

Ecology conducted an assessment of the property in 2006 and ranked the site a two on the Hazardous Sites List. The Hazardous Sites List is a record of contaminated sites throughout the state that are ranked on a scale of one to five. One represents the greatest potential threat to human health and the environment; five represents the least potential threat.

Ecology asked the Washington State Department of Health to provide an assessment of the potential health impacts of the site and evaluate the private well testing results. This work has already begun and the health department will provide its findings in a health consultation report. The report is anticipated to be available to the public in late Spring 2009.

For more details you may review the Agreed Order at the following locations:

- North Spokane Public Library, Hawthorne Branch, 44 E. Hawthorne Rd., Spokane WA 99218
- Spokane Public Library, Hillyard Branch, 4005 N. Cook St, Spokane WA 99207
- Ecology Eastern Regional Office, 4601 N. Monroe, Spokane WA 99205-1295. (Please call **Kari Johnson** at **509/329-3415** for an appointment.)
- Ecology's website: http://www.ecy.wa.gov/programs/tcp/sites/heglar/heglar_hp.html

For more information or to submit written comments, please contact

Teresita Bala at the Ecology address listed above or at **509/329-3543** or e-mail **tbal461@ecy.wa.gov**.

Spokane Transit Authority Former Railroad Property, south of the Interstate Fairgrounds, north of Sprague Avenue, east of Havana Street and west of Fancher Road in Spokane Valley Facility Site ID# 2165959

Public comment period:
1/19/09 – 2/17/09

Proposed Delisting from Hazardous Sites List

Ecology invites you to comment on the proposed removal of the Spokane Transit Authority Former Railroad Property site from the Hazardous Sites List. The site is in a commercial and industrial area and is currently vacant.

The Hazardous Sites List is a list of contaminated sites throughout the state that are ranked on a scale of one to five. One represents the greatest potential threat to human health and the environment; five the least potential threat. The site ranked a two.

Union Pacific Railroad owned the site until the 1970s when it was bought by the Chicago Milwaukee Railroad. The site was used for loading and unloading trains, storing automobiles, and as a source of gravel. In 2001 the Spokane Transit Authority purchased the property. Now the site is occasionally used for overflow parking for the fairgrounds.

Environmental assessments conducted on the property in 1998 and 1999 discovered petroleum and arsenic in soil and arsenic in groundwater. An underground storage tank was removed along with an abandoned drywell and sump in the southwest portion of the former shop building area. A total of 194 tons of petroleum-contaminated soil was removed from the site.

Arsenic was also found in soil near a monitoring well (MW2) that had been

installed as part of the environmental assessments. Soil in this area was not removed because it was 45 feet below the ground surface. Groundwater sampling conducted at the site showed arsenic at levels above what is allowed by the state. Additional groundwater monitoring was conducted from October 2007 through June 2008. The results from the last four sets of groundwater samples during these years met cleanup levels. The cleanup work was completed under Ecology's Voluntary Cleanup Program.

Ecology proposes removing the Spokane Transit Authority Former Railroad Property site from the Hazardous Site List based upon the following:

- Review of the cleanup reports.
- Supporting documentation.
- State standards for cleanup of petroleum and arsenic in soil and arsenic in groundwater have been met at the site.

Para asistencia en Español **Richelle Perez** at **360/407-6971**

Если вам нужно помощь по русский, звоните: **Tatyana Bistrevsky** at **509/477-3881**

For more information or to submit written comments, please contact **Ms. Patti Carter** at the Ecology address listed above or at **509/329-3522** or e-mail **paca461@ecy.wa.gov**.

INDEPENDENT CLEANUPS

A property owner may conduct an independent cleanup of contamination and submit reports to Ecology. When a property owner applies to Ecology for review of their independent cleanup, the site enters the Voluntary Cleanup Program. After review, Ecology sends a letter to the property owner stating either that additional work is required to be removed from the list of hazardous waste sites or that no further action is needed.

CHELAN COUNTY

Central Regional Office Contact: e-mail
Rjoh461@ecy.wa or call 509/575-2490

**Unocal Blk Plt 0853, 6 N 5th St,
Wenatchee Facility Site ID # 346**

- Submitted 11/21/08. Report received:
Groundwater Monitoring Report 3rd quarter
2008.

CLARK COUNTY

Southwest Regional Office Contact:
360/407-6300

**Ray Wilson, 600 NE 78th, Vancouver
Facility Site ID # 4864448** - Submitted
1/20/09. Report received: Groundwater
Monitoring Rpt- 4th Qtr 2008.

GRAYS HARBOR COUNTY

Southwest Regional Office Contact:
360/407-6300

**Montesano Quick Stop, 405 S Main St,
Montesano Facility Site ID # 88688912**
- Submitted 1/8/09. Report received: 4th Qtr
2008 Monitoring.

ISLAND COUNTY

Northwest Regional Office Contact:
e-mail Dmus461@ecy.wa or call
425/649-7136

**The Southland Corp. 2306-18255a,
5520 N State Hwy, Oak Harbor Facility
Site ID # 49928544** - Submitted 1/8/09.
Report received: Groundwater Status
September 2008.

KING COUNTY

Northwest Regional Office Contact:
e-mail Dmus461@ecy.wa or call
425/649-7136

Mobil Station 99-NWA Former, 3227

**NE 145th St, Seattle Facility Site ID #
2267** - Submitted 1/21/09. Report received:
Groundwater Status December 2008.

**Louis Dale Erickson, 4557 Brooklyn
Ave, Seattle Facility Site ID # 4819383**
- Submitted 1/7/09. Report received:
Groundwater Status November 2008.

**Friendly Food Mart, 16402 SE 128th,
Renton Facility Site ID # 5127572**
- Submitted 12/31/08. Reports received:
Groundwater Status November 2008;
Subsurface Investigation November 2008.

**Mobil Service Station 19-748, 5100
15th Ave NW, Seattle Facility Site ID
5268606** - Submitted 1/8/09. Report
received: Groundwater Status November
2008.

**Barney & Al's Chevron, 1649 Bellevue
Way SE, Bellevue Facility Site ID
6215454** - Submitted 1/14/09. Report
received: Groundwater Status September
2008.

**Bellevue Northrup Chevron, 13948
NE 20th St, Bellevue Facility Site ID
6541715** - Submitted 1/14/09. Report
received: Groundwater Status August 2008.

**Texaco Station #63-232-0277, 3670
150th Ave SE, Bellevue Facility Site
ID # 11244769** - Submitted 1/13/09. Report
received: Groundwater Status November
2008.

**Convenience Retailers #2705508, 2022
S Puget Dr, Renton Facility Site ID
12692333** - Submitted 1/29/09. Report
received: Groundwater Status October 2008.

**7-Eleven Store 2307-17381p, 9436
Rainier Ave S, Seattle Facility Site ID
13876787** - Submitted 1/8/09. Report
received: Groundwater Status September
2008.

**Circle K No. 1452, 2415 Griffin
Ave, Enumclaw Facility Site ID #
14644972** - Submitted 12/30/08. Reports
received: Groundwater Status August 2008;
Groundwater Status November 2008.

**7-Eleven Store #2307-18553b, 3939
Stone Way N, Seattle, City Facility Site
ID # 15895351** - Submitted 1/15/09. Report
received: Groundwater Status September
2008.

**U-Haul Co of SeaTac, 20024 Pacific
Highway S, Seattle Facility Site ID #
16882249** - Submitted 1/22/09. Reports
received: Groundwater Status December
2008; Groundwater Monitoring Report-June
2008.

**6382, 12805 - 1st Ave S, Seattle
Facility Site ID # 19886142** - Submitted
1/27/09. Report received: Groundwater
Status November 2008.

**Arco #00409/Manual Inc, 13515
Ambaum Blvd SW, Seattle Facility Site
ID # 22483258** - Submitted 1/23/09. Report
received: Groundwater Status July 2008.

**U-Haul Co of Kirkland, 12006 NE
85th Street, Kirkland Facility Site ID
23174884** - Submitted 1/22/09. Report
received: Groundwater Status December
2008.

**7-Eleven Food Store #2307-22866b,
14207 Pacific Hwy S, Tukwila Facility
Site ID # 23544274** - Submitted 1/11/09.
Report received: Groundwater Status
September 2008.

**7-Eleven Store 2307-27390m, 6061
Martin Luther King Way, Seattle
Facility Site ID # 25181548** - Submitted
1/8/09. Report received: Groundwater Status
May 2008.

**Budget Rent A Car System, Inc., 17801
International Blvd, SeaTac Facility**

Site ID # 29143426 - Submitted 1/13/09.
Report received: Groundwater Status
November 2008.

**Arco Facility #05243/Merced Market
Inc, 31855 Pacific Hwy S, Federal Way
Facility Site ID # 29499326** - Submitted
1/23/09. Reports received: Groundwater
Status July 2008; Groundwater Status
September 2008.

**7-Eleven Store 2307-16365c, 6111
24th Ave NW, Seattle Facility Site ID
32622962** - Submitted 1/8/09. Reports
received: Groundwater Status June 2008;
Groundwater Status September 2008.

**Kirkland 76, 12235 NE 116th, Kirkland
Facility Site ID # 32821675** - Submitted
12/31/08. Report received: Groundwater
Status October 2008.

**0355, 159 Denny Way, Seattle Facility
Site ID # 32873776** - Submitted 1/15/09.
Reports received: Groundwater Status July
2008; Groundwater Status October 2008.

**Freemont 76, 4600 Fremont Ave N,
Seattle Facility Site ID # 33185679**
- Submitted 1/5/09. Report received:
Groundwater Status November 2008.

**Stadium Market Northgate, 2143
Northgate Way, Seattle Facility Site ID
33451755** - Submitted 1/12/09. Report
received: Groundwater Status November
2008.

**Jackpot Food Mart 309, 415 Auburn
Way NE, Auburn Facility Site ID #
42261182** - Submitted 1/6/09. Report
received: Groundwater Status June 2008.

**Roxbury Gasoline, 2851 SW Roxbury
St, Seattle Facility Site ID # 44862443**
- Submitted 1/12/09. Report received: Well
Installation November 2008.

**Airport 76/Mini Mart & Deli, 4603 S
188th St, SeaTac Facility Site ID #
45382686** - Submitted 12/31/08. Report
received: Groundwater Status November
2008.

**Sunset BP, 4715 NE Sunset Blvd,
Renton Facility Site ID # 46125333**
- Submitted 1/21/09. Reports received:
Groundwater Status December 2008; Well
Installation November 2008.

**Fred Meyer, Inc., 2041 148th NE,
Bellevue Facility Site ID # 47193443**
- Submitted 1/14/09. Report received:
Groundwater Status June 2008.

**MLK Food Mart & HI Travel, 12911
MLK Jr Way S, Seattle Facility Site
ID # 48796862** - Submitted 1/5/09.
Report received: Soil And Groundwater
Investigation.

**Jem Locke / 7-Eleven # 27482, 14225
Interurban Ave S, Tukwila Facility Site
ID # 54824185** - Submitted 1/11/09. Report
received: Groundwater Status September
2008.

**Broadway Roy 76, 915 E Roy St,
Seattle Facility Site ID # 56827327**
- Submitted 1/14/09. Report received:
Groundwater Status October 2008.

**Arco Facility #00836/Mek Corporation,
11611 NE 8th St, Bellevue Facility Site
ID # 63427923** - Submitted 1/23/09. Report
received: Groundwater Status July 2008.

**Marginal Way Arco, 7200 E Marginal
Way S, Seattle Facility Site ID #
63713485** - Submitted 1/23/09. Report
received: Groundwater Status July 2008.

**King 76, 6056 Martin Luther King Way
S, Seattle Facility Site ID # 64295469**
- Submitted 1/21/09. Report received:
Groundwater Status December 2008.

**7-Eleven 2303-27219, 2202 Auburn
Way N, Auburn, City Facility Site ID
64748872** - Submitted 1/21/09. Report
received: Remediation Progress May 2008;
Groundwater Status September 2008.

**7-Eleven Store 2307-20188e, 13131 SE
240th, Kent Facility Site ID # 66465734**
- Submitted 1/15/09. Report received:
Groundwater Status September 2008.

**7-Eleven Store 2307-14396b, 7215
Sandpoint Way NE, Seattle Facility
Site ID # 69852392** - Submitted 1/8/09.
Report received: Groundwater Status August
2008.

**7-Eleven 2303-17463, 104 SW 312th,
Federal Way Facility Site ID #
73389516** - Submitted 1/8/09. Report
received: Groundwater Status August 2008.

**7-Eleven 2303-17463, 104 SW 312th,
Federal Way Facility Site ID #
73389516** - Submitted 1/11/09. Report
received: Subsurface Investigation April
2008.

**The Southland Corp. 2306-23559b,
2353 140th Ave NE, Bellevue Facility
Site ID # 76437511** - Submitted 1/26/09.
Report received: Groundwater Status
September 2008.

**Unocal 4871, 17606 International
Blvd, Seattle Facility Site ID #
83443263** - Submitted 1/6/09. Reports
received: Groundwater Status August 2008;
Groundwater Status November 2008.

**Old Bellevue Services LLC, 10011
Main St, Bellevue Facility Site ID #
83879769** - Submitted 1/14/09. Report
received: Groundwater Status September
2008.

**Mercer Island Shell, 7833 SE 28th
St, Mercer Island Facility Site ID #
85772269** - Submitted 1/13/09. Report

received: Groundwater Status December 2008.

Sun Cor Holdings-Copii LLC, 2411 76th SE, Mercer Island Facility Site ID # 89773988 - Submitted 1/14/09. Report received: Groundwater Status August 2008.

Scarsella Bros. Inc., 19440 84th Ave S, Kent Facility Site ID # 91349895 - Submitted 1/6/09. Report received: Groundwater Status November 2008.

Budget Rent A Car - Lot 2, 18445 Pacific Hwy S, Seattle Facility Site ID # 91686113 - Submitted 1/8/09. Report received: Groundwater Status October 2008.

Arco Facility #04451/Kaaw, Inc., 10504 Aurora Ave N, Seattle Facility Site ID # 93425596 - Submitted 1/23/09. Report received: Well Abandonment January 2009.

Aurora 76, 8408 Aurora Ave N, Seattle Facility Site ID # 94735647 - Submitted 1/27/09. Report received: Groundwater Status October 2006.

BP 03102, 1960 148th Ave NE, Redmond Facility Site ID # 95497348 - Submitted 1/22/09. Report received: Groundwater Status December 2008.

KITSAP COUNTY

Northwest Regional Office Contact:
e-mail Dmus461@ecy.wa or call 425/649-7136

Jackpot 01-363, 3302 W Hwy #16, Port Orchard Facility Site ID # 1786697 - Submitted 1/6/09. Report received: Subsurface Investigation February 2008.

Poulsbo Imperial, 19559 Viking Ave NW, Poulsbo Facility Site ID # 13524668 - Submitted 1/5/09. Report received: Groundwater Status November 2008.

Charleston Beach BP, 1116 Charleston Beach Rd, Bremerton Facility Site ID # 28366276 - Submitted 1/8/09. Report received: Groundwater Status November 2008.

Convenience Retailers LLC #2705536, 9215 Silverdale Way NW, Silverdale Facility Site ID # 54454413 - Submitted 1/26/09. Report received: Fuel Line Replacement July 2008.

Poulsbo Food Mart 399, 19740 Viking Way Ave NW, Poulsbo Facility Site ID # 68211258 - Submitted 1/15/09. Report received: Groundwater Status September 2008.

Circle K Convenience Store #8882, 9671 Silverdale Way, Silverdale Facility Site ID # 79523271 - Submitted 12/30/08. Report received: Groundwater Status September 2008.

Convenience Retailers #2705402, 1350 Bay Street, Port Orchard Facility Site ID # 85753551 - Submitted 1/14/09. Report received: Groundwater Status October 2008.

Reid Realty, 9564 Silverdale Way, Silverdale Facility Site ID # 87832799 - Submitted 1/8/09. Report received: Groundwater Status September 2008.

Car Wash, 1220 Hildebrand Ln NE, Bainbridge Island Facility Site ID # 96325489 - Submitted 1/23/09. Report received: Groundwater Status October 2008.

VIP Landfill site, 600 Oyster Bay, Bremerton - Submitted 1/27/09. Report received: Letter of Intent.

KITTITAS COUNTY

Central Regional Office Contact: e-mail Rjoh461@ecy.wa or call 509/575-2490

Smitty's 250, 1503 Hwy 97, Ellensburg

Facility Site ID # 62898962 - Submitted 1/7/09. Report received: Initial Site Characterization.

Texaco #63-232-0017, 1510 Canyon Rd, Ellensburg Facility Site ID # 86291644 - Submitted 1/23/09. Report received: Fourth Quarter 2008 Monitoring.

PIERCE COUNTY

Southwest Regional Office Contact:
e-mail Kcro461@ecy.wa or call 360/407-6240

Unocal 5956, 7051 Pacific Ave, Tacoma Facility Site ID # 1368 - Submitted 1/20/09. Report received: 4th Q 2008 Maintenance & Groundwater Sampling.

Texaco Station #63-232-0343, 5602 McKinley Ave, Tacoma Facility Site ID # 18389922 - Submitted 1/6/09. Report received: 3rd Q 2008 Groundwater Monitoring; 4th Q 2008 Groundwater Monitoring.

Texaco Station #63-232-0255, 801 South 56th St, Tacoma Facility Site ID # 28836816 - Submitted 1/6/09. Report received: 3rd Q 2008 Groundwater Monitoring.

Texaco Star Mart #3619, 5115 Olympic Dr NW, Gig Harbor Facility Site ID # 29585983 - Submitted 12/31/08. Report received: 3rd Q 2008 Groundwater Monitoring.

Texaco Station #63-232-1425, 1430 East 72nd St, Tacoma Facility Site ID # 29639496 - Submitted 1/20/09. Report received: 4th Q 2009 Groundwater Monitoring.

Seven Eleven 2324-14469/Closed, 12336 Pacific Hwy SW, Tacoma Facility Site ID # 34768492 - Submitted 1/22/09. Report received: 1st & 2nd Q 2008

Groundwater Monitoring.

Food Mart 345, 8320 Canyon Rd E, Puyallup Facility Site ID # 72868291 -

Submitted 1/26/09. Report received: 3rd Q 2008 Groundwater Monitoring.

Texaco Station #63-232-0500, 5501 20th St E, Fife Facility Site ID #

96352712 - Submitted 1/13/09. Report received: 4th Q 2008 Groundwater Monitoring.

SKAGIT COUNTY

Northwest Regional Office Contact:
e-mail Dmus461@ecy.wa or call
425/649-7136

Jackpot Station 154, 1102 West SR 20, Sedro-Woolley Facility Site ID

6391777 - Submitted 1/9/09. Report received: Groundwater Status June 2008.

Skagit Big Mini Mart, 157 S Burlington Blvd, Burlington Facility Site ID #

25786278 - Submitted 1/5/09. Report received: Groundwater Status May 2008.

Tesoro - 411, 115 W Fir St, Mount Vernon Facility Site ID # 96335388

- Submitted 1/6/09. Reports received: Subsurface Investigation April 2008; Groundwater Status June 2008; Groundwater Status September 2008.

SNOHOMISH COUNTY

Northwest Regional Office Contact:
e-mail Dmus461@ecy.wa or call
425/649-7136

Casino Fuel, 2510 W Casino, Everett Facility Site ID # 9915598 - Submitted

1/14/09. Report received: Decommissioning Report December 2008.

Mountlake Terrace Chevron, 22801 44th Ave W, Mountlake Terrace

Facility Site ID # 34991366 - Submitted 1/23/09. Report received: Groundwater Status November 2008.

Exxon 7-7135, 3015 Everett Ave, Everett Facility Site ID # 78599184

- Submitted 1/22/09. Report received: Groundwater Status December 2008.

7-Eleven Store 2306-21464d, 1215 2nd Ave, Snohomish Facility Site ID

85327563 - Submitted 1/15/09. Report received: Groundwater Status June 2008; Groundwater Status September 2008.

Exxon 7-3674, 16409 20th W, Alderwood Manor Facility Site ID

89674139 - Submitted 1/7/09. Report received: Groundwater Status November 2008.

7-Eleven Food Store 2306-23176-E, 12704 Mukilteo Speedway, Mukilteo Facility Site ID # 91197184 - Submitted

1/11/09. Report received: Groundwater Status September 2008.

Nel/Son Distributing, Inc., 9826 7th Ave SE, Everett Facility Site ID # 97797673

- Submitted 1/23/09. Report received: Groundwater Status October 2008.

STEVENS COUNTY

Eastern Regional Office Contact:
Doug Ladwig, 509/329-3440 or e-mail
dlad461@ecy.wa.gov

Food Mart 025, 750 N Hwy 395, Colville Facility Site ID # 7612479 - Submitted

1/8/09. Report received: Ground Water Monitoring Report Third Quarter, TOC Holding Co.

YAKIMA COUNTY

Central Regional Office Contact: e-mail
Rjoh461@ecy.wa or call 509/575-2490

Unocal Bulk Plant 0766, 511 Lincoln Ave, Sunnyside Facility Site ID #

539 - Submitted 1/20/09. Report received: Quarterly Groundwater Monitoring Report.

VOLUNTARY CLEANUP PROGRAM

Under Ecology's Voluntary Cleanup Program (VCP), a property owner cleaning up a contaminated site pays a fee for Ecology review. When a cleanup is determined to be sufficient, Ecology issues a no further action decision.

BENTON COUNTY

CR VCP Contact: Frosti Smith, 509/454-7841 or e-mail Fsmi461@ecy.wa.gov

Kiona Benton City High School, 1205 Horne Rd, Benton City Facility Site ID # 9129377 - Submitted 9/8/08.

Report received: Final Cleanup Report. Media contaminated: Soil. Contaminants: Petroleum products. Site status: Completed Consultation. Project Completed.

CLALLAM COUNTY

SW VCP Contact: Scott Rose, 360/407-6347 or e-mail Sros461@ecy.wa.gov

Ediz Hook Drum II, Ediz Hook Coast Guard Station, Port Angeles Facility Site ID # 63423475 - Submitted

9/1/98. Reports received: Remedial Investigation Report; Final Cleanup Report. Media contaminated: Soil, sediment and groundwater. Contaminants: Petroleum products. Site status: Completed Opinion Letter. Independent remedial action in process.

CLARK COUNTY

SW VCP Contact: Scott Rose, 360/407-6347 or e-mail Sros461@ecy.wa.gov

Chastain Residence, 228 Phoenix Way, Vancouver Facility Site ID # 2764791 - Submitted 1/28/09. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Tetra Pak, 3125 Thompson Ave, Vancouver Facility Site ID # 34822454 - Submitted 12/19/01. Reports received: Remedial Investigation Report; Remedial Investigation Work Plan. Media contaminated: Soil and groundwater. Contaminants: Halogenated organic compounds, phenolic compounds, dioxin. Site status: Completed Opinion Letter. Independent remedial action in process.

Former Chevron 92097, 7220 NE Hwy 99, Vancouver Facility Site ID # 41626836 - Submitted 1/24/06. Reports received: Remedial Investigation Work Plan; Final Cleanup Report. Media contaminated: Soil and groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide, petroleum products, non-halogenated solvents, MTBE. Site status: Completed Opinion Letter. Independent remedial action in process.

Lil Colonel Drive In, 13309 NE Hwy 99, Vancouver Facility Site ID # 50743515 - Submitted 12/18/06. Reports received: Remedial Investigation Work Plan; Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Halogenated organic compounds, petroleum products, non-halogenated solvents. Site status: Completed Opinion Letter. Independent remedial action in process.

Astro Western Station 607, 13117 NE Hwy 99, Vancouver Facility Site ID # 69431927 - Submitted 12/14/06. Reports received: Remedial Investigation Work Plan; Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide, petroleum products, non-halogenated solvents. Site status: Completed

Opinion Letter. Independent remedial action in process.

COWLITZ COUNTY

SW VCP Contact: Scott Rose, 360/407-6347 or e-mail Sros461@ecy.wa.gov

Ocean Beach Chevron, 3002 Ocean Beach, Longview Facility Site ID # 94989386 - Submitted 3/21/07. Report received: Interim Action Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products, MTBE. Site status: Completed Opinion Letter. Independent remedial action in process.

DOUGLAS COUNTY

CR VCP Contact: Frosti Smith, 509/454-7841 or e-mail Fsmi461@ecy.wa.gov

Hartl Dump, Rock Island Rd, Rock Island Facility Site ID # 1557707 - Submitted 8/24/06. Report received: Final Cleanup Report. Media contaminated: Soil. Contaminants: EPA Priority Pollutants – metals and cyanide, pesticides, petroleum products. Site status: Completed Opinion Letter. Project Completed.

GRANT COUNTY

ER VCP Contact: Patti Carter, 509/329-3522 or e-mail Paca461@ecy.wa.gov

Quincy Alfalfa Company, 901 E Division St, Quincy Facility Site ID # 93674364 - Submitted 6/8/07. Reports received: Interim Action Work Plan; Final Cleanup Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Completed Opinion Letter. Completed Consultation. Project Completed.

GRAYS HARBOR COUNTY

SW VCP Contact: Scott Rose, 360/407-6347 or e-mail Sros461@ecy.wa.gov

City Of Westport Maintenance Yard, 506 Montesano St, Westport Facility Site ID # 14817971 - Submitted 1/26/09. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Halogenated organic compounds, petroleum products. Site status: Independent remedial action in process.

Sams Food Market McCleary, 140 S 3rd St, McCleary Facility Site ID # 22576988 - Submitted 12/20/07. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products, non-halogenated solvents. Site status: Completed Opinion Letter. Independent remedial action in process.

KING COUNTY

NW VCP Contact: Donna Musa, 425/649-7136 or e-mail Dmus461@ecy.wa.gov

General Disposal Corp, 1415 NW Ballard Way, Seattle Facility Site ID # 2122 - Submitted 1/9/09. Report received: Interim Action Report. Media contaminated: Groundwater, Surface Water, Air, Soil. Contaminants: Petroleum products, non-halogenated solvents. Site status: Independent remedial action in process.

Ballard Auto Wrecking, 1515 NW Leary Way, Seattle Facility Site ID # 2346 - Submitted 1/16/09. Report received: Final Cleanup Report. Media contaminated: Soil and groundwater. Contaminants: Halogenated organic compounds, EPA Priority Pollutants – metals and cyanide, polychlorinated biPhenyls (PCBs), petroleum products, non-halogenated solvents. Site status: Independent remedial action in process.

Shell Oil Products Sap 169780, 2756 NE 45th St, Seattle Facility Site ID # 1002463 - Submitted 1/9/09. Media

contaminated: Soil and groundwater.
Contaminants: Petroleum products,
non-halogenated solvents. Site status:
Independent remedial action in process.

**4347 53rd Ave NE, 4347 53rd Ave NE,
Seattle Facility Site ID # 2241425**

- Submitted 1/27/09. Report received:
Cleanup Action Plan. Media contaminated:
Soil. Contaminants: Petroleum products.
Site status: Independent remedial action in
process.

**Fostoria Gardens Building Property,
4501 S 134th St, Tukwila Facility Site
ID # 3270145**

- Submitted 10/22/08. Report
received: Remedial Investigation Work Plan.
Media contaminated: Soil and groundwater.
Contaminants: EPA Priority Pollutants –
metals and cyanide, arsenic. Site status:
Completed Opinion Letter. Independent
remedial action in process.

**Olga & Pakie Plastino, 3253 NE
98th St, Seattle Facility Site ID #
6377448**

- Submitted 1/27/09. Report
received: Remedial Investigation Report.
Media contaminated: Soil, Surface Water,
Groundwater. Contaminants: Petroleum
Products. Site status: Independent remedial
action in process.

**Shell Station 120698, 1520 S 348th St,
Federal Way Facility Site ID # 7546643**

- Submitted 1/22/09. Media contaminated:
Soil and groundwater. Contaminants: Metals
– other, petroleum products. Site status:
Independent remedial action in process.

**Olympic Athletic Club, 5301 Leary Ave
NW, Seattle Facility Site ID # 9958499**

- Submitted 1/13/09. Report received:
Interim Action Report. Media contaminated:
Groundwater. Contaminants: EPA Priority
Pollutants – metals and cyanide, petroleum
products, non-halogenated solvents. Site
status: Independent remedial action in
process.

**Shell Station 121450, 6200 Corson
Ave SW, Seattle Facility Site ID #
11354986**

contaminated: Soil and groundwater.
Contaminants: Petroleum products, MTBE.
Site status: Independent remedial action in
process.

**Lincoln Executive Center Gas Station,
3380 146th Pl SE Bldg, 1, Bellevue
Facility Site ID # 11731557**

- Submitted
1/13/09. Report received: Interim Action
Report. Media contaminated: Soil and
groundwater. Contaminants: Halogenated
organic compounds, EPA Priority Pollutants
– metals and cyanide, petroleum products,
non-halogenated solvents. Site status:
Independent remedial action in process.

**Shell 120956, 23419 Pacific Hwy S, Des
Moines Facility Site ID # 18977197**

- Submitted 1/20/09. Media contaminated: Soil
and groundwater. Contaminants: Petroleum
products. Site status: Independent remedial
action in process.

**Shell Station 120465, 106 148th
Ave SE, Bellevue Facility Site ID #
20948179**

- Submitted 1/20/09. Media
contaminated: Soil and groundwater.
Contaminants: Petroleum products, MTBE.
Site status: Independent remedial action in
process.

**Shell Oil Co NW Market St803 NW
Market St, Seattle Facility Site ID
26173437**

- Submitted 1/9/09. Media
contaminated: Soil and groundwater.
Contaminants: Metals – other, petroleum
products, non-halogenated solvents, MTBE.
Site status: Independent remedial action in
process.

**Texaco 121585, 812 NE 65th St, Seattle
Facility Site ID # 29211653**

- Submitted
1/22/09. Media contaminated: Soil and
groundwater. Contaminants: Metals – other,
petroleum products. Site status: Independent
remedial action in process.

**Shell Station 120677, 15 E Sunset Way,
Issaquah Facility Site ID # 29834827**

- Submitted 1/9/09. Media contaminated: Soil
and groundwater. Contaminants: Petroleum
products. Site status: Independent remedial
action in process.

**Texaco Station 632320049, 5500
15th NW, Seattle Facility Site ID #
32794934**

- Submitted 12/31/08. Media
contaminated: Soil and groundwater.
Contaminants: Metals – other, petroleum
products, MTBE. Site status: Independent
remedial action in process.

**Shell Station 120654, 1439 Auburn Way
N, Auburn Facility Site ID # 34292725**

- Submitted 1/14/09. Media contaminated: Soil
and groundwater. Contaminants: Petroleum
products, MTBE. Site status: Independent
remedial action in process.

**Shell Oil Products US SAP 120764,
17010 International Blvd, SeaTac
Facility Site ID # 35684714**

- Submitted
1/22/09. Media contaminated: Soil and
groundwater. Contaminants: Halogenated
organic compounds, EPA Priority Pollutants
– metals and cyanide, petroleum products,
Polynuclear aromatic hydrocarbons (PAH).
Site status: Independent remedial action in
process.

**Shell Station 120598, 13138 Interurban
Ave S, Tukwila Facility Site ID #
35848934**

- Submitted 1/14/09. Media
contaminated: Soil and groundwater.
Contaminants: Petroleum products, MTBE.
Site status: Independent remedial action in
process.

**Shell Station 121702, 10 Denny Way,
Seattle Facility Site ID # 49674295**

- Submitted 1/14/09. Media contaminated:
Soil and groundwater. Contaminants: Metals
– other, petroleum products. Site status:
Independent remedial action in process.

**Texaco 632320307, 1637 W Meeker
St, Kent Facility Site ID # 51268843**

- Submitted 1/8/09. Media contaminated:
Soil and groundwater. Contaminants: Metals
– other, petroleum products. Site status:
Independent remedial action in process.

**Auto Site Automotive, 11803 Des
Moines Memorial Dr, Seattle Facility
Site ID # 53457146**

- Submitted 1/27/09.
Report received: Interim Action Report.
Media contaminated: Soil. Contaminants:

Petroleum products. Site status: Independent remedial action in process.

Allied Domecq, 2921 Martin Luther King Jr Way S, Seattle Facility Site ID # 56326712 - Submitted 12/31/08.

Media contaminated: Soil and groundwater. Contaminants: Metals – other, petroleum products, non-halogenated solvents. Site status: Independent remedial action in process.

BP Service Station 11049, 13201 100th Ave NE, Kirkland Facility Site ID # 61984217 - Submitted 1/13/09.

Report received: Interim Action Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum Products. Site status: Independent remedial action in process.

Rainier Court, Rainier Ave S, Seattle Facility Site ID # 62285426 - Submitted

6/19/01. Report received: Interim Action Report. Media contaminated: Soil and groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide, Polychlorinated biPhenyls (PCBs), pesticides, petroleum products, Polynuclear aromatic hydrocarbons (PAH). Site status: Completed Opinion Letter. Independent remedial action in process.

Shell Station 120463, 105 S 156th St, Seattle Facility Site ID # 64432537 -

Submitted 1/20/09. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Shell Station 120477, 10801 NE 68th St, Kirkland Facility Site ID # 65747289

- Submitted 1/22/09. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Bellevue Square Project, 727-731 Bellevue Way, Bellevue Facility Site ID # 66913169 - Submitted 2/28/00.

Report received: Remedial Investigation Work Plan. Media contaminated: Soil and groundwater. Contaminants: Petroleum products.

Site status: Completed Opinion Letter. Independent remedial action in process.

Shell Oil Products, 2805 SW Roxbury St, Seattle Facility Site ID # 71459562

- Submitted 1/12/09. Media contaminated: Soil and groundwater. Contaminants: Metals – other, petroleum products. Site status: Independent remedial action in process.

Shell Station 120546, 12001 NE 8th St., Bellevue Facility Site ID # 83922248 -

Submitted 1/20/09. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

KITSAP COUNTY

NW VCP Contact: Donna Musa, 425/649-7136 or e-mail Dmus461@ecy.wa.gov

City Hand Laundry, 1002 4th St, Bremerton Facility Site ID # 9475242

- Submitted 2/4/08. Report received: Interim Action Report. Media contaminated: Soil and groundwater. Contaminants: Halogenated organic compounds. Site status: Completed Consultation.

Time Oil Co Kingston, 10958 Hwy 104 NE, Kingston Facility Site ID # 64282254 - Submitted 2/6/07.

Report received: Interim Action Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum Products. Site status: Completed Opinion Letter. Completed Consultation.

MASON COUNTY

SW VCP Contact: Scott Rose, 360/407-6347 or e-mail Sros461@ecy.wa.gov

Time Oil Co Property 01369, 108 1st N, Shelton Facility Site ID # 24168976 -

Submitted 6/22/06. Reports received: Final Cleanup Report; Remedial Investigation Report; Remedial Investigation Work Plan. Media contaminated: Soil and groundwater. Contaminants: Petroleum Products.

Site status: Completed Opinion Letter. Independent remedial action in process.

Sodhi Chevron, 1730 Olympic Hwy S, Shelton Facility Site ID # 94197779 - Submitted 3/29/05.

Reports received: Interim Action Report; Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide; Petroleum products; Non-halogenated solvents; Polynuclear aromatic hydrocarbons (PAH); MTBE. Site status: Completed Opinion Letter. Independent remedial action in process.

OKANOGAN COUNTY

CR VCP Contact: Frosti Smith, 509/454-7841 or e-mail Fsmi461@ecy.wa.gov

Train Station Mini Mart, 900 E Methow Valley Hwy, Twisp Facility Site ID # 44615567 - Submitted 11/14/08.

Report received: Final Cleanup Report. Media contaminated: Soil. Contaminants: Petroleum Products. Site status: Completed Consultation. Project Completed..

PIERCE COUNTY

SW VCP Contact: Scott Rose, 360/407-6347 or e-mail Sros461@ecy.wa.gov

TPU Moffitt Property, 312 179th Ct E, Spanaway Facility Site ID # 1184997

- Submitted 12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Former William Tell Apartments, 4545 South Cedar Street, Tacoma Facility Site ID # 1678835 - Submitted

12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil. Contaminants: Petroleum products. Site status: Independent remedial action in process.

TPU Bailey Property, 1646 E, Fairbanks, Tacoma Facility Site ID # 2243854 - Submitted 12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

TPU Orchard Park Convalescent Center, 4755 S 48th St , Tacoma Facility Site ID # 2745087 - Submitted 12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

TPU Fonoimoana Property, 24002 86th Ave E, Graham Facility Site ID # 3129766 - Submitted 12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil. Contaminants: Petroleum products. Site status: Independent remedial action in process.

TPU Calypso Apartments, 3201 S 47th St, Tacoma Facility Site ID # 4366524 - Submitted 12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Kanpai Japanese Restaurant, 402 N Meridian, Puyallup Facility Site ID # 5461558 - Submitted 12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products, non-halogenated solvents. Site status: Completed Opinion Letter. Independent remedial action in process.

Tpu Outrigger Apts, 6102 6th Ave , Tacoma Facility Site ID # 5571317 - Submitted 12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Polychlorinated biPhenyls (PCBs), petroleum products. Site status: Independent remedial action in process.

TPU Row Moisieo Property, 8432 S 16th, Tacoma Facility Site ID # 6673670 - Submitted 12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Tpu Autrey Property Westcliff, 5305 87th St Ct W, University Place Facility Site ID # 8153127 - Submitted 12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Tpu Hara Property Westcliff, 8722 53rd St Ct W, University Place Facility Site ID # 8984738 - Submitted 12/24/08. Report received: Remedial Investigation Report. Media contaminated: Soil. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Taco Bell Former Chevron 97376, 5018 Pacific Hwy E, Tacoma Facility Site ID # 20365296 - Submitted 1/12/06. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide, petroleum products, non-halogenated solvents. Site status: Completed Opinion Letter. Independent remedial action in process.

Former Bott Fuel Facility, 7002 Park Ave S, Tacoma Facility Site ID # 33674196 - Submitted 1/7/09. Media contaminated: Soil and groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide, petroleum products, non-halogenated solvents. Site status: Completed Opinion Letter. Independent remedial action in process.

Puyallup Chevron & Food Court, 516 S Meridian, Puyallup Facility Site ID # 62439981 - Submitted 1/3/08. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater.

Contaminants: Petroleum products, non-halogenated solvents. Site status: Completed Opinion Letter. Independent remedial action in process.

Fircrest Village Cleaners, 1105 A Regents Blvd, Fircrest Facility Site ID # 64128162 - Submitted 6/3/08. Report received: Interim Action Work Plan. Media contaminated: Soil and groundwater. Contaminants: Non-halogenated solvents. Site status: Completed Opinion Letter. Independent remedial action in process.

Fife 76, 2002 E 54th Ave, Fife Facility Site ID # 72452584 - Submitted 12/18/08. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide, petroleum products, non-halogenated solvents. Site status: Independent remedial action in process.

Shell Station 121589, 8223 Steilacoom Blvd , Tacoma Facility Site ID # 73992787 - Submitted 8/9/07. Report received: Remedial Investigation Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products, non-halogenated solvents, Polynuclear aromatic hydrocarbons (PAH). Site status: Completed Opinion Letter. Independent remedial action in process.

Shear Trucking, 26719 Sr 410 E, Buckley Facility Site ID # 83113674 - Submitted 12/28/06. Reports received: Remedial Investigation Report; Remedial Investigation Work Plan. Media contaminated: Soil and groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide, petroleum products, phenolic compounds, non-halogenated solvents, Polynuclear aromatic hydrocarbons (PAH); MTBE. Site status: Completed Opinion Letter. Independent remedial action in process.

SKAGIT COUNTY

NW VCP Contact: Donna Musa,

425/649-7136 or e-mail Dmus461@ecy.wa.gov

Texaco Station 630760004, 1712 McMurry, Conway Facility Site ID # 10339322 - Submitted 1/14/09. Media contaminated: Soil and groundwater. Contaminants: Petroleum Products; MTBE. Site status: Independent remedial action in process.

SNOHOMISH COUNTY

NW VCP Contact: Donna Musa, 425/649-7136 or e-mail Dmus461@ecy.wa.gov

Shell Everett 246 2772 2507, 8530 Evergreen Way, Everett Facility Site ID # 30116 - Submitted 1/8/09. Media contaminated: Soil and groundwater. Contaminants: Metals – other; Petroleum products; MTBE. Site status: Independent remedial action in process.

Pacific Commercial Equipment 2, 4717 Bickford Ave, Snohomish Facility Site ID # 1800552 - Submitted 5/11/06. Report received: Final Cleanup Report. Media contaminated: Sediment, Soil, Surface Water. Contaminants: EPA Priority Pollutants – metals and cyanide; Petroleum products; Polynuclear aromatic hydrocarbons (PAH). Site status: Completed Consultation.

Ryder Ate Inc, 2900 112th St Sw Bldg 654, Everett Facility Site ID # 1815283 - Submitted 1/28/09. Report received: Remedial Investigation Report. Media contaminated: Soil. Contaminants: EPA Priority Pollutants – metals and cyanide; Petroleum products; Polynuclear aromatic hydrocarbons (PAH). Site status: Independent remedial action in process.

Snohomish Cnty Used Oil Collect, 11020 19th Ave SE, Everett Facility Site ID # 5195417 - Submitted 12/31/08. Media contaminated: Soil and groundwater. Contaminants: Base/Neutral/Acid Organics; Halogenated organic compounds; petroleum products; non-halogenated solvents;

Polynuclear aromatic hydrocarbons (PAH). Site status: Independent remedial action in process.

Shell 120935, 22802 Bothell Way SE, Bothell Facility Site ID # 53947398 - Submitted 1/14/09. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Jiffy Lube Marysville, 8417 State Ave, Marysville Facility Site ID # 55657475 - Submitted 1/26/09. Report received: Remedial Investigation Report. Media contaminated: Soil. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Texaco Star Mart 3703, 22727 Bothell Everett Hwy, Bothell Facility Site ID # 56626259 - Submitted 1/9/09. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

SPOKANE COUNTY

ER VCP Contact: Patti Carter, 509/329-3522 or e-mail Paca461@ecy.wa.gov

Geiger Heights Housing Area, Grove & Hallet Rd, Spokane Facility Site ID # 21455 - Submitted 1/30/09. Media contaminated: Groundwater, Drinking Water, Soil. Contaminants: Petroleum products. Site status: Independent remedial action in process.

Avista Northeast Combustion Terminal, 8703 North Regal, Spokane Facility Site ID # 6461060 - Submitted 1/16/09. Report received: Remedial Investigation Report. Media contaminated: Soil. Contaminants: Petroleum products. Site status: Independent remedial action in process.

STEVENS COUNTY

ER VCP Contact: Patti Carter, 509/329-3522 or e-mail Paca461@ecy.wa.gov

Peterson Swamp Road, Peterson Swamp Road, Evans Facility Site ID # 2704912 - Submitted 1/27/09. Media contaminated: Soil. Contaminants: EPA Priority Pollutants – metals and cyanide. Site status: Independent remedial action in process.

THURSTON COUNTY

SW VCP Contact: Scott Rose, 360/407-6347 or e-mail Sros461@ecy.wa.gov

Taco Bell/ Former Chevron 96801, 3815 Pacific Ave, Lacey Facility Site ID # 3567929 - Submitted 1/13/08. Report received: Remedial Investigation Work Plan. Media contaminated: Soil and groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide; Petroleum products; Non-halogenated solvents. Site status: Independent remedial action in process.

Maple Lane School, 20311 Old Hwy 9 SW, Centralia Facility Site ID # 63149499 - Submitted 1/8/07. Reports received: Remedial Investigation Report; Final Cleanup Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Completed Opinion Letter. Project Completed.

WALLA WALLA COUNTY

ER VCP Contact: Patti Carter, 509/329-3522 or e-mail Paca461@ecy.wa.gov

Taj Foodmart, 5 W Morton Street, Walla Walla Facility Site ID # 3491851 - Submitted 10/29/08. Report received: Interim Action Work Plan. Media contaminated: Soil and groundwater. Contaminants: EPA Priority Pollutants – metals and cyanide; Petroleum products. Site status: Independent remedial action in process.

Bernies Automotive Center, 412 W Main, Walla Walla Facility Site ID # 54893171 - Submitted 1/27/09. Report received: Interim Action Report. Media contaminated: Soil and groundwater. Contaminants: Petroleum products. Site status: Independent remedial action in process.

WHATCOM COUNTY

NW VCP Contact: Donna Musa, 425/649-7136 or e-mail Dmus461@ecy.wa.gov

Meenderinck Molasses Company, 506 Nooksack Ave, Nooksack Facility Site ID # 13413417 - Submitted 1/8/09. Report received: Interim Action Report. Media contaminated: Soil. Contaminants: Petroleum products. Site status: Independent remedial action in process.

YAKIMA COUNTY

CR VCP Contact: Frosti Smith, 509/454-7841 or e-mail Fsmi461@ecy.wa.gov

Marvin Gardens, Hathaway Ave, Yakima Facility Site ID # 4660794 - Submitted 12/24/08. Report received: Final Cleanup Report. Media contaminated: Soil. Contaminants: EPA Priority Pollutants – metals and cyanide, Arsenic. Site status: Independent remedial action in process.

East Valley Central Middle School Campus, 1900 Beaudry Rd, Yakima Facility Site ID # 66683757 - Submitted 9/8/08. Report received: Final Cleanup Report. Media contaminated: Soil. Contaminants: Petroleum products. Site status: Completed Consultation. Project Completed..

SITE HAZARD ASSESSMENTS

An initial investigation is conducted when a suspected release of hazardous

materials has occurred. If additional work is required, a site hazard assessment may be conducted. These sites are ranked on a scale from 1 to 5, with 1 being the highest risk to human health and the environment. The following sites are scheduled for an assessment.

SKAGIT COUNTY

Contact: Polly Dubbel, Skagit County Health Dept., e-mail pollyd@co.skagit.wa.us or call 360/336-9380.

A Ave Landfill, A Ave & 37th St, Anacortes Facility Site ID # 3094179

Puget Sound Energy Sedro Woolley, 284 Minkler Rd, Sedro Woolley Facility Site ID # 32313154

PSE Lower Baker Switchyard, Baker River Rd, Concrete Facility Site ID # 91913661

PSE Fredonia Generating Facility, 14254 Ovenell Rd, Mount Vernon Facility Site ID # 86666971

OTHER DEPARTMENT NOTICES

Ecology's Toxics Cleanup Program (TCP) has recently updated the following policies and procedures.

Policy 340: Managing TCP's Program Plan. This policy defines roles and responsibilities for managing TCP's program plan. Updates a previous policy.

Policy 550 A: Cost Recovery. This policy provides Ecology employees guidance on recovering remedial action costs under the Model Toxics Control Act. Updates a previous policy in response to State

Auditor recommendations. Ecology will now require payment of invoices within 30 days of issuance of the invoice.

Procedure 550 A: Cost Recovery of State TCP Expenditures. This procedure describes updated procedures for issuing invoices to recover remedial action costs under the Model Toxics Control Act.

Policy 550 B: Tracking Site Activities in the Site Log. This policy has been deleted and replaced by Policy 550 A.

Procedure 550 B: Site Log Procedure. This procedure has been deleted and replaced by Policy 550 A.

To obtain a copy of these and other TCP policies and procedures, go to

- Ecology's Internet web site: <http://www.ecy.wa.gov/programs/tcp/policies/tcppoly.html>
- Contact **Ann McNeely** at **360/407-7205** or e-mail **Amcn461@ecy.wa.gov**

TOXICS CLEANUP PROGRAM PUBLICATIONS

Contact: Ann McNeely, 360/407-7205 or e-mail Amcn461@ecy.wa.gov

Evergreen Airport Publication # 09-09-141, Date: Jan. 2009

Tacoma Smelter Plume - Interim Cleanup Action Plan State Environmental Policy Act (SEPA) Early Scoping Publication # 09-09-121, Date: Jan. 2009

Spokane Transit Authority Former Railroad Property Publication # 09-09-21, Date: Jan. 2009

Joseph Simon & Sons Kent Publication # 09-09-91, Date: Jan. 2009

Mike's Aussie Machine Shop Publication # 09-09-92, Date: Jan. 2009

BNSF Parkwater Railyard Site Publication # 08-09-028, Date: Jan. 2009

Участок Железнодорожной Компании BNSF Publication # 08-09-028RU, Date: Jan. 2009

Progress Elementary School Publication
08-09-152, Date: Jan. 2009

Cost Recovery of State TCP
Expenditures Publication # Policy 550A,
Date: Jan. 2009
